

12/28/2017
4:04:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169426 2008 FORD F250 Pickup, 3/4 Ton, W/Topper, Winch

Workorder: 742286

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0		Labor	Parts	
In Date: 07/31/2007	Close Date: 07/31/2007	Hours	Description	Quantity
- Pre-Delivery Inspection		2.00		
	Parts Charge: 0.00	Labor Charge:	110.00	

Workorder: 833796

Problem: P.M.SERVICE

Meter Reading: 2059		Labor	Parts	
In Date: 02/06/2008	Close Date: 02/15/2008	Hours	Description	Quantity
- Pm Service		2.75	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Shop Supplies			5W20 ENGINE OIL	7.00
			SHOP SUPPLIES	1.00
	Parts Charge: 35.35	Labor Charge:	165.00	

Workorder: 843830

Problem: P.M.SERVICE

Meter Reading: 5203		Labor	Parts	
In Date: 09/05/2008	Close Date: 09/10/2008	Hours	Description	Quantity
- Pm Service		3.25	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Test Drive			G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
- Shop Supplies			5W20 ENGINE OIL	7.00
			1066 WHITE LITHIUM (CRC 05037)	1.00
			SHOP SUPPLIES	1.00
			USED FIREX REFURBED FIRE EXTINGSHERS	1.00
	Parts Charge: 71.45	Labor Charge:	15.00	

Workorder: 935223

Problem: P.M.SERVICE

Meter Reading: 8672		Labor	Parts	
In Date: 03/16/2009	Close Date: 03/23/2009	Hours	Description	Quantity
- Pm Service		4.00	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Install New Decal			SHOP SUPPLIES	1.00
- Service Winch; Rollers Seized Up; Free Rollers & Test			5W20 ENGINE OIL	7.00
- Shop Supplies			31-20 WIPER BLADES 20" BLADE	2.00
	Parts Charge: 50.03	Labor Charge:	240.00	

12/28/2017
4:04:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169426 2008 FORD F250 Pickup, 3/4 Ton, W/Topper, Winch

Workorder: 944098

Problem: P.M.SERVICE

Meter Reading: 12028		Labor		Parts	
In Date: 10/02/2009	Close Date: 10/09/2009	Hours	Description		Quantity
-	P.M.Service	5.25	1372 OIL FILTER FRM PH2 WIX 51372		1.00
-	Service Winch,Test And Lub. Rollers		G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
-	R/R Front Tires,Test Drive		179636492 LT245/75R17 WRANGLER SR-A E		2.00
-	Shop Supplies		TIRE DISPOSAL FEE		2.00
			SHOP SUPPLIES		1.00
			5W20 ENGINE OIL		7.00
Parts Charge:		427.87	Labor Charge:	315.00	

Workorder: 1003135

Problem: P. M.

Meter Reading: 14716		Labor		Parts	
In Date: 03/29/2010	Close Date: 03/31/2010	Hours	Description		Quantity
-	P.M.	5.50	CA10262 AIR FILTER MTC FA1883 WIX 49883		1.00
-	Service Winch & Rollers, Test Winch, Rerap Cable.		1372 OIL FILTER FRM PH2 WIX 51372		1.00
-	Verify, Needs Two Rear Tires. R&R Two Tires, Mount,		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
-	Balance, Add 65 Psi Of N2, Rotate To Front.		TIRE DISPOSAL FEE		2.00
-	Install Sticker On Rear Bumper.		5W20 ENGINE OIL		8.00
-	Shop Supplies		31-20 WIPER BLADES 20" BLADE		2.00
			179636492 LT245/75R17 WRANGLER SR-A E		2.00
			SHOP SUPPLIES		1.00
Parts Charge:		462.49	Labor Charge:	330.00	

Workorder: 1010505

Problem: Plug for tailer needs replacing

Meter Reading: 17709		Labor		Parts	
In Date: 09/23/2010	Close Date: 09/24/2010	Hours	Description		Quantity
-	Repair Damaged Trailer Wiring Connector & Replace	1.50	SHOP SUPPLIES		1.00
-	Trailer Plug. Retest System, Ok.		5404 FEMALE CONNECTOR		1.00
-	Shop Supplies				
Parts Charge:		12.11	Labor Charge:	90.00	

12/28/2017
4:04:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169426 2008 FORD F250 Pickup, 3/4 Ton, W/Topper, Winch

Workorder: 1011249

Problem: P. M. SERVICE

Meter Reading: 17924		Labor		Parts	
In Date: 10/13/2010	Close Date: 10/18/2010	Hours	Description		Quantity
-	P. M. Service.	8.75	G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
-	Verify. Winch Inoperable. Loose Bolts Caused Motor To Stop. Remove Winch, Re-Align, Reinstall, & Test.		5W20 ENGINE OIL		7.00
-	Repair Handle Assy On Driver'S Side Hatch On Topper.		1372 OIL FILTER FRM PH2 WIX 51372		1.00
-	Lube All Hinges, Handles, & Tighten All Inner Fastening Bolts.		SHOP SUPPLIES		1.00
-	Repair Trailer Lights Connection Wires. Verify. Cargo Brake Lights Out On Topper. R&R Two Bulbs.				
-	Shop Supplies				
Parts Charge: 45.97		Labor Charge:	525.00		

Workorder: 1100046

Problem: Truck needs new socket for lights on trailer

Meter Reading: 19145		Labor		Parts	
In Date: 01/03/2011	Close Date: 01/10/2011	Hours	Description		Quantity
-	C/C: Needs New Socket. Replace Damaged Socket For Trailer Lights. Install Bulb On Trailer. Test Lights.	1.50	SHOP SUPPLIES		1.00
-	Shop Supplies		5404 FEMALE CONNECTOR		1.00
Parts Charge: 12.11		Labor Charge:	90.00		

Workorder: 1104310

Problem: P. M. SERVICE

Meter Reading: 20419		Labor		Parts	
In Date: 04/21/2011	Close Date: 04/28/2011	Hours	Description		Quantity
-	P. M. Service.	6.00	SHOP SUPPLIES		1.00
-	Service Winch. Lube Rollers, Cable, Etc.		1372 OIL FILTER FRM PH2 WIX 51372		1.00
-	Lube & Inspect All Hinges & Latches On Topper Cover. Check All Fastening Bolts.		5W20 ENGINE OIL		8.00
-	Nail In R/R Tire. Dismount, Patch, Mount, Balance, Add N2.				
-	Repair Passenger Side Reverse Light.				
-	Shop Supplies				
Parts Charge: 29.63		Labor Charge:	360.00		

12/28/2017
4:04:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169426 2008 FORD F250 Pickup, 3/4 Ton, W/Topper, Winch

Workorder: 1107727

Problem: Left blinker on truck is not working

Meter Reading: 21735		Labor		Parts	
In Date: 07/22/2011	Close Date: 07/28/2011	Hours	Description		Quantity
-	Replace Left Rear Turn Signal Bulb.	0.50	3157 TAIL LIGHT BULBS		1.00
Parts Charge:		0.83	Labor Charge:	30.00	

Workorder: 1111077

Problem: Trailer lights running lights not working

Meter Reading: 22923		Labor		Parts	
In Date: 10/18/2011	Close Date: 10/26/2011	Hours	Description		Quantity
-	Ck Lights, Found Bad Female Connector, & Blown Fuse	2.00	5404 FEMALE CONNECTOR		1.00
	For Trailer Lights. Replace Connector & Blown Fuse.		SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge:		12.10	Labor Charge:	120.00	

Workorder: 1111903

Problem: P. M. SERVICE

Meter Reading: 23161		Labor		Parts	
In Date: 11/04/2011	Close Date: 11/15/2011	Hours	Description		Quantity
-	P. M. Service.	3.75	USED FIREX REFURBED FIRE EXTINGSHERS		1.00
-	Service Winch.		1066 WHITE LITHIUM (CRC 05037)		1.00
-	Shop Supplies		31-20 WIPER BLADES 20" BLADE		2.00
			CA10262 AIR FILTER MTC FA1883 WIX 49883		1.00
			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
			SHOP SUPPLIES		1.00
			5W20 ENGINE OIL		8.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
Parts Charge:		80.30	Labor Charge:	225.00	

12/28/2017
4:04:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169426 2008 FORD F250 Pickup, 3/4 Ton, W/Topper, Winch

Workorder: 1202626

Problem: ck engine light came on and then went off inside light burnt out dome light

Meter Reading: 24649		Labor		Parts	
In Date: 03/16/2012	Close Date: 03/23/2012	Hours	Description		Quantity
- Replace Dome Light Bulb		2.50	SHOP SUPPLIES		1.00
- C/S Ck Engine Light Is On Verify Concern Scan Found Code #P2270 Perform Pinpoint Test And Found Leaking Vacuum Hose On Intake Repair Hose Clear Code And Test Drive					
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	150.00	

Workorder: 1204721

Problem: P. M. SERVICE

Meter Reading: 25772		Labor		Parts	
In Date: 05/18/2012	Close Date: 05/30/2012	Hours	Description		Quantity
- P. M. Service		4.75	1372 OIL FILTER FRM PH2 WIX 51372		1.00
- Service Winch.			5W20 ENGINE OIL		8.00
- Inspect Topper, Check All Fastening Points. Lubricate Latches, Hinges, Etc.			SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		33.86	Labor Charge:	285.00	

Workorder: 1209411

Problem: dead battery had to jump start

Meter Reading: 27876		Labor		Parts	
In Date: 10/02/2012	Close Date: 10/04/2012	Hours	Description		Quantity
- Ck And Replace Bad Battery		0.75	SHOP SUPPLIES		1.00
- Shop Supplies			GROUP 65 BATTERY MTC		1.00
Parts Charge:		147.05	Labor Charge:	45.00	

12/28/2017
4:04:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169426 2008 FORD F250 Pickup, 3/4 Ton, W/Topper, Winch

Workorder: 1211841

Problem: pm, ac in out, ck engine light is on

Meter Reading: 29037		Labor		Parts	Quantity
In Date: 12/07/2012	Close Date: 12/20/2012	Hours	Description		
-	Pm	11.00	179636492 LT245-75R17		2.00
-	Ck Ac Is Not Working Verify Concern Ck System		CORE		1.00
	Pressure Cd And Found Leaking Low Side Shradlet Valve		SHOP SUPPLIES		1.00
	Evacuate Replace Shrater Valve Recharge Leak Test And		TIRE DISPOSAL FEE		2.00
	Test Drive		PH2 OIL FILTER LBF PH		1.00
-	Ck Engine Light Is On Scan And Found Code P2270		NAPA QUART 5W20		8.00
	Perform Pin Point Test And Found Bad 02 Sensor Bank 1		FORD FUEL FILTER		1.00
	Sensor Sensor 2 Replace Sensor Clear Code And Test		CA10262 AIR FILTER MT		1.00
	Drive		USED FIREX REFURBED F		1.00
-	Replace Both Rear Tires And Rotate To The Front		MAC WITE LITHIUM GRES		1.00
-	Service Winch		31-20 WIPER BLADES 20		2.00
-	Shop Supplies		R134A REFRIGERANT		2.00
			E8 A-C OIL R134A A-C		1.00
			CORE		1.00
			O2 SENSOR DOWNSTREAM		1.00
Parts Charge:		664.52	Labor Charge:	660.00	

Workorder: 1301738

Problem: right rear blinker brake light burnt out

Meter Reading: 30038		Labor		Parts	Quantity
In Date: 02/20/2013	Close Date: 02/21/2013	Hours	Description		
-	Ck Tail Light Verify Right Rear Tail Light Out Replace One	0.50	MINIATURE BULB		1.00
	3157 Tail Light Bulb				
Parts Charge:		0.72	Labor Charge:	30.00	

Workorder: 1303675

Problem: need new trailer hitch ball

Meter Reading: 31202		Labor		Parts	Quantity
In Date: 04/15/2013	Close Date: 04/26/2013	Hours	Description		
-	Fabricate And Repair Trailer Hitch	1.00	SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge:		2.00	Labor Charge:	60.00	

12/28/2017
4:04:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169426 2008 FORD F250 Pickup, 3/4 Ton, W/Topper, Winch

Workorder: 1305935

Problem: P. M. Service

Meter Reading: 32104		Labor	Parts	
In Date: 06/14/2013	Close Date: 06/20/2013	Hours	Description	Quantity
- Pm		4.75	NAPAGOLD OIL FILTER	1.00
- Svc Winch			NAPA QUART 5W20	8.00
- Lub Latches And Hinges On Topper Cab Tighten Mounting Bolts			SHOP SUPPLIES	1.00
- Shop Supplies				
Parts Charge: 35.33		Labor Charge: 285.00		

Workorder: 1401298

Problem: rr tail lite

Meter Reading: 35109		Labor	Parts	
In Date: 02/07/2014	Close Date: 02/10/2014	Hours	Description	Quantity
- Ck Tail Light Out Rr Rr Turn Signal Bulb Ck All Lights		0.50	BULB	1.00
Parts Charge: 0.99		Labor Charge: 30.00		

Workorder: 1401598

Problem: pm, wiper blades

Meter Reading: 35236		Labor	Parts	
In Date: 02/19/2014	Close Date: 02/28/2014	Hours	Description	Quantity
- Pm		5.50	SHOP SUPPLIES	1.00
- Replace Both Rear Tires (With Good Used Tires) And Rotate To The Front			USED FIRE X REFURBISHED	1.00
- Svc Winch			WASHER FL	1.00
- Fill All Tires With Nitrogen			NAPAGOLD AIR FILTER	1.00
- Shop Supplies			NAPAGOLD FUEL FILTER	1.00
			NAPAGOLD OIL FILTER	1.00
			NAPA QUART 5W20	8.00
			WIPER BLADE	2.00
Parts Charge: 77.63		Labor Charge: 330.00		

12/28/2017
4:04:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169426 2008 FORD F250 Pickup, 3/4 Ton, W/Topper, Winch

Workorder: 1408122

Problem: pm

Meter Reading: 38191

Labor

Parts

In Date: 08/15/2014

Close Date: 08/25/2014

Hours

Description

Quantity

- Pm	5.75	NAPAGOLD OIL FILTER	1.00
- Svc Winch Lube And Rewrap Cable		NAPA QUART 5W20	8.00
- Inspect Secure Topper On Bed		SHOP SUPPLIES	1.00
- Verify Rr Tie Leaking Rr Valve Stem Dismount Patch			
- Mount Balance Add N2			
- Shop Supplies			

Parts Charge: 36.29

Labor Charge: 345.00

Workorder: 1501644

Problem: P.M.SERVICE,,WINCH CABLE,FLOOR MATS

Meter Reading: 40377

Labor

Parts

In Date: 02/13/2015

Close Date: 03/20/2015

Hours

Description

Quantity

- Pm	9.75	NAPAGOLD FUEL FILTER	1.00
- Replace Complete Floor Mat		WASHER FL	1.00
- Replace Damage Cable And Service Winch		VINYL CABIN FLOOR	1.00
- Shop Supplies		WINCH CABLE FABRICATION	1.00
		SHOP SUPPLIES	1.00
		USED FIRE X REFURBISHED	1.00
		NAPAGOLD OIL FILTER	1.00
		CARPET	1.00
		WIPER BLADE	2.00
		NAPAGOLD AIR FILTER	1.00
		NAPA QUART 5W20	8.00

Parts Charge: 805.67

Labor Charge: 585.00

12/28/2017
4:04:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169426 2008 FORD F250 Pickup, 3/4 Ton, W/Topper, Winch

Workorder: 1509343

Problem: pm

Meter Reading: 42452

In Date: 09/16/2015

Close Date: 09/24/2015

Labor

Hours

Description

Parts

Quantity

- Pm	5.00	NAPAGOLD OIL FILTER	1.00
- Replace Broken Trans Dip Stick		WASHER FLUID CONCENTR	1.00
- Svc Winch		seal	4.00
- Install Hows My Driving Dedcal		ADAPTER FITTING	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		USED FIRE X REFURBISHED	1.00
		NAPA QUART 5W20	8.00
		tube oil	1.00

Parts Charge: 121.23

Labor Charge: 300.00

Workorder: 1600742

Problem: windsheild washer resivore leaking, hook on winch cable came off camper shell struts , light bulb

Meter Reading: 43795

In Date: 01/22/2016

Close Date: 01/29/2016

Labor

Hours

Description

Parts

Quantity

- Remove Winch Cable And Send To Napa For Repair.	3.50	REPAIR CABLE	1.00
Reinstall Winch Cable.		HOOD LIFT SUPPORT	2.00
- Replace Camper Rear Support Struts		SHOP SUPPLIES	1.00
- Repair R/Rear Blinker		BULB	1.00
- Shop Supplies			

Parts Charge: 119.61

Labor Charge: 210.00

Workorder: 1603004

Problem: pm

Meter Reading: 44368

In Date: 03/22/2016

Close Date: 03/30/2016

Labor

Hours

Description

Parts

Quantity

- Pm	4.75	NAPAGOLD FUEL FILTER	1.00
- Svc Winch		NAPAGOLD OIL FILTER	1.00
- Inspect And Svc Topper		NAPA QUART 5W20	8.00
- Shop Supplies		20" WIPER BLADE	2.00
		SHOP SUPPLIES	1.00
		WASHER FLUID CONCENTR	1.00

Parts Charge: 49.37

Labor Charge: 285.00

12/28/2017
4:04:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169426 2008 FORD F250 Pickup, 3/4 Ton, W/Topper, Winch

Workorder: 1609494

Problem: P.M.SERVICE

Meter Reading: 46749		Labor		Parts	
In Date: 09/13/2016	Close Date: 09/30/2016	Hours	Description		Quantity
- Pm Service		8.25	HALOGEN LAMP		2.00
- Replace Both Head Lights.			FREON SR SHOP		3.00
- Check Ac And Found Leaking Schrader Valves. Evacuate			AC VALVE CORE HIGH		1.00
System And Replace Valves. Recharge And Recheck.			CORE		1.00
Ok.			WD40 16OZ AERO CAN		1.00
- Service Winch.			SHOP SUPPLIES		1.00
- Shop Supplies			20" WIPER BLADE		2.00
			NAPAGOLD OIL FILTER		1.00
			WASHER FLUID CONCENTR		1.00
			DRAIN PLUG		1.00
			NAPA QUART 5W20		8.00
			USED FIRE X REFURBISHED		1.00
Parts Charge: 137.32		Labor Charge: 495.00			

Workorder: 1611718

Problem: battery/jump start

Meter Reading: 47394		Labor		Parts	
In Date: 11/15/2016	Close Date: 11/21/2016	Hours	Description		Quantity
- C/C Battery.Test Battery Bad.Replace Battery.Check		0.75	SHOP SUPPLIES		1.00
Charging System.			BATTERY		1.00
- Shop Supplies					
Parts Charge: 126.42		Labor Charge: 45.00			

12/28/2017
4:04:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169426 2008 FORD F250 Pickup, 3/4 Ton, W/Topper, Winch

Workorder: 1702991

Problem: PM Service.Check windshield washer inop.

Meter Reading: 48950		Labor		Parts	
In Date: 03/24/2017	Close Date: 03/31/2017	Hours	Description		Quantity
- Pm Service.		11.25	SHOP SUPPLIES		1.00
- Replace Windshield Washer Pump Motor.			WASHER FLUID CONCENTR		1.00
- Mount And Balance Two Front Tires.			WASHER PUMP		1.00
- Front Brake Job.Cut Rotors And Replace Brake Pads.			TIRE DISPOSAL FEE		2.00
- Service Winch			NAPAGOLD OIL FILTER		1.00
- Shop Supplies			BRAKE PADS		1.00
			20" WIPER BLADE		2.00
			NAPA QUART 5W20		8.00
			179636492 LT245-75R17		2.00
Parts Charge: 662.50		Labor Charge: 675.00			

Workorder: 1708271

Problem: Check engine light on.Trailer harness plug broken

Meter Reading: 50970		Labor		Parts	
In Date: 08/22/2017	Close Date: 08/31/2017	Hours	Description		Quantity
- Replace Trailer Socket		8.50	VALVE		1.00
- Scan And Found Code# P0455 And P0457.Perform Pin			CANNISTER		1.00
Point Test And Found Bad Evapt Canister And			SHOP SUPPLIES		1.00
Valve.Replace Canister Assembly, Purge Valve And Clear			trailer plug		1.00
Codes.					
- Test Drive Before And After Repairs.					
- Shop Supplies					
Parts Charge: 258.64		Labor Charge: 510.00			

Workorder: 1710087

Problem: Transition Prep Charge

Meter Reading: 51376		Labor		Parts	
In Date: 10/16/2017	Close Date: 10/16/2017	Hours	Description		Quantity
- Transition Prep Charge		2.00			
Parts Charge: 0.00		Labor Charge: 0.00			

Total Parts Charges:	4,521.39	Total Labor Charges:	7,940.00	Total Comm. Charges:	0.00
----------------------	-----------------	----------------------	-----------------	----------------------	-------------