

**Palm Beach County Fleet Management
Asset Maintenance History**

10174458 2008 FORD F350 Utility Body, 1 Ton

Workorder: 842492 **Meter:** 0 **In Date:** 08/06/2008 **Closed:** 08/06/2008
Problem: PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 4.00 Labor: 240.00 Parts: 0.00 Total: 240.00
:

Workorder: 933885 **Meter:** 4493 **In Date:** 02/10/2009 **Closed:** 02/12/2009
Problem: RECALL #08B07.P.M SERVICE

- Pm Service

Parts List **Qty**

- To/fr Dealer For Recall #081307

Shop Supplies 1.00

- Tag Lamp Inop.inspect & Test Circuit.trace Problem To Open Ground.repair Ground On Tag Lamp Assy.

7312 Oil Filterfrm Ch9549 Wix 57312 1.00

Cs10263 Fuel Filter (use Cs10263a) 1.00

- Rotate And Nitro Service All Six Tires.

15/40 Oil 15.00

- Shop Supplies

Used Firex Refurbed Fire Extingshers 1.00

Hours 8.00 Labor: 480.00 Parts: 132.12 Total: 612.12
:

Workorder: 939127 **Meter:** 8549 **In Date:** 06/17/2009 **Closed:** 06/22/2009
Problem: INSTALL WIRING FOR COMPUTER.

- Fabricate And Install Wiring Harness For Computer Stand.

Parts List **Qty**

- Shop Supplies

Shop Supplies 1.00

Hours 2.00 Labor: 120.00 Parts: 2.00 Total: 122.00
:

Workorder: 945171 **Meter:** 12030 **In Date:** 10/27/2009 **Closed:** 11/13/2009
Problem: P.M. Service.

- P.m service.

Parts List **Qty**

- Replace missing pintal safety pin & chain.

Shop Supplies 1.00

- Diagnose lights, replace R/r marker lamp base, replace rear center marker lamp bar & rewire as needed.

7312 Oil Filterfrm Ch9549 Wix 57312 1.00

Cs10263 Fuel Filter (use Cs10263a) 1.00

- Repair R/f tire, rotate & balance all six tires.

Ca10270 Air Filter Mtc Fa1886 Wix 49886 1.00

- Shop Supplies

15/40 Oil 15.00

Used Firex Refurbed Fire Extingshers 1.00

31-20 Wiper Blades 20" Blade 2.00

15050r Id Bar Red Model 15 Led 1.00

19721 Base Mount 19 Series 4" Marker Light 1.00

18410 Pintle Pin 1.00

Hours 8.00 Labor: 480.00 Parts: 178.27 Total: 658.27
:

Workorder: 946794 **Meter:** 12115 **In Date:** 12/08/2009 **Closed:** 12/10/2009
Problem: Gas cap missing

- Replace missing fuel cap.

Parts List **Qty**

Fuel Cap 1.00

Hours 0.50 Labor: 30.00 Parts: 18.71 Total: 48.71
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1002057 **Meter:** 14045 **In Date:** 02/26/2010 **Closed:** 03/01/2010
Problem: water indicator light on dash warning message see notes

- Perfrom computer diagnostics, inspect fuel system, remove fuel filter seperator, clean & service, replace primary fuel filter, clear codes & test drive.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	Cs10263 Fuel Filter (use Cs10263a)	1.00
	8c3z9a343a Seal Kit Fuel Filter (ford)	1.00
Hours 2.00	Labor: 120.00	Parts: 85.40
:		Total: 205.40

Workorder: 1006255 **Meter:** 16466 **In Date:** 06/11/2010 **Closed:** 06/28/2010
Problem: P.M.Service.

- P.m. Service.	Parts List	Qty
- Replace and balance and nitro fill all six tires.	Shop Supplies	1.00
- Complete front end alignment.	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- Remove computer stand and all accessories and send to dealer for floor mat replacement(defect,warranty).	Cs10263 Fuel Filter (use Cs10263a)	1.00
- Transport vehicle to dealer for floor mat replacement.	15/40 Oil	15.00
- Shop Supplies	31-20 Wiper Blades 20" Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	7090blk Frt Floor Mats (rubber Queen)	1.00
	179636492 Lt245/75r17 Wrangler Sr-a E	6.00
	Tire Disposal Fee	6.00
Hours 12.50	Labor: 750.00	Parts: 1,291.14
:		Total: 2,041.14

Workorder: 1100372 **Meter:** 20879 **In Date:** 01/10/2011 **Closed:** 01/20/2011
Problem: P.M. Service.

- Perform pm service.	Parts List	Qty
- Fabricate and replace missing hitch pindel pin with new.	Pm-22-a Additive Diesel Fuel (m/craft)	1.00
- Rotate and balance all six tires.	Shop Supplies	1.00
- Shop Supplies	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
	Cs10263 Fuel Filter (use Cs10263a)	1.00
	15/40 Oil	15.00
	31-20 Wiper Blades 20" Blade	2.00
	18410 Pintle Pin	1.00
Hours 6.00	Labor: 360.00	Parts: 106.65
:		Total: 466.65

Workorder: 1100546 **Meter:** 20879 **In Date:** 01/13/2011 **Closed:** 01/19/2011
Problem: reflash canceiver spot 186

- Reflash Canceiver and reprogram	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1107470 **Meter:** 25076 **In Date:** 07/18/2011 **Closed:** 07/26/2011
Problem: Pm service.

- Perform pm service.	Parts List	Qty
- Test and replace failed left alley lamp bulb with new.	Shop Supplies	1.00
- Test starting and charging system both batteries failed load test after recharge.replace both failed batteries with new.	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- Rotate and balance all six tires.	Ca10270 Air Filter Mtc Fa1886 Wix 49886	1.00
- Shop Supplies	3963 Fuel Filter Frm Cs10263a Wix 33963	1.00
	15/40 Oil	15.00
	Used Firex Refurbed Fire Extingshers	1.00
	31-20 Wiper Blades 20" Blade	2.00
	Group 65 Battery (mtc Bxt-65-850)	2.00
	Fxam1 Light Socket Assy (whelen)	1.00
Hours 8.50	Labor: 510.00	Parts: 465.11
:		Total: 975.11

Workorder: 1109365 **Meter:** 26160 **In Date:** 09/01/2011 **Closed:** 09/21/2011
Problem: Check engine light on.

- Test drive and computer diagnose vehicle.p0087 & P2291.replace fuel filter and clean water seperator.perform Pcm update per Tsb 09-18-15.clear codes and test drive.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	8c3z9a343a Seal Kit Fuel Filter (ford)	1.00
	3963 Fuel Filter Frm Cs10263a Wix 33963	1.00
Hours 3.50	Labor: 210.00	Parts: 78.99
:		Total: 288.99

Workorder: 1110148 **Meter:** 26367 **In Date:** 09/22/2011 **Closed:** 10/24/2011
Problem: Check engine light on and no power see notes.

- Transport vehicle to and from dealer for replacing failed high pressure fuel pump with new under factory warranty asper Tsb#11-4-22 and perform recall 11b23 reprogram pcm.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 2.00
:		Total: 122.00

Workorder: 1202230 **Meter:** 29567 **In Date:** 03/05/2012 **Closed:** 03/29/2012
Problem: P.M. service and A/C not cooling.

- Perform pm service and install new steering wheel cover.	Parts List	Qty
- Fabricate and replace missing hitch pindel pin with new.	Shop Supplies	1.00
- Ac performance and leak test.replace failed ac condenser with new.vacume and recharge system to specs with virgin freon and oil.	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- Rotate and balance all six tires.	3963 Fuel Filter Frm Cs10263a Wix 33963	1.00
- Shop Supplies	15/40 Oil	15.00
	Steering Wheel Cover	1.00
	R134a Refrigerant	2.00
	E8 A/c Oil R134a A/c Oil (tsi)	1.00
	31-20 Wiper Blades 20" Blade	2.00
	A/c Condensor	1.00
	18410 Pintle Pin	1.00
Hours 8.50	Labor: 510.00	Parts: 425.87
:		Total: 935.87

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1211459 **Meter:** 35789 **In Date:** 11/28/2012 **Closed:** 12/11/2012
Problem: Pm service and replace damage vise.

	Parts List	Qty
- P.m. Service.		
- Replace missing pintle pin.	15-40 Oil	15.00
- Replace and balance six tires.	Oil Filter	1.00
- Replace broken work vise.	Napagold Fuel Filter	1.00
- Complete wheel alignment.test drive.	31-20 Wiper Blades 20	2.00
- Clean,repack and adjust both front wheel bearings.	Used Firex Refurbed F	1.00
- Make and replace front asset #.	18410 Pintle Pin	1.00
- Shop Supplies	179636492 Lt245-75r17	6.00
	66997 Combo Vise Rigi	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	6.00
Hours 12.75	Labor: 765.00	Parts: 2,219.99
:		Total: 2,984.99

Workorder: 1305473 **Meter:** 40985 **In Date:** 05/31/2013 **Closed:** 06/04/2013
Problem: R/R/I/ Flat

- Tire Service 8100 Forest hill blvd---301.1889 - R/r/i/ Flat			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1306292 **Meter:** 42185 **In Date:** 06/24/2013 **Closed:** 07/10/2013
Problem: P.M. Service.Repair vise.

	Parts List	Qty
- P.m. Service.		
- Replace damaged inop vise.replace missing pintle pin.	15-40 Oil	15.00
- Test battery and charging system.replace both bad batteries.	Napagold Oil Filter	1.00
	Napagold Fuel Filter	1.00
- Replace blower resistor	31-20 Wiper Blades 20	2.00
- Replace left alley lamp	66997 Combo Vise Rigid	1.00
- Resurface rear brake rotors.service and lube rear calipers,flush and bleed system.replace front suspension jounce bumpers.	Pintle Pin W/chain	1.00
	Battery 65	2.00
- Repair right rear tire.rotate and balance all six.	Blower Resistor	1.00
- Shop Supplies	Fxalf1 Alley Light Le	1.00
	Brake Pads	1.00
	1401 Brake Fluid Bra	1.00
	Bumper	2.00
	Slip Plate Spray 12oz	1.00
	Shop Supplies	1.00
Hours 17.25	Labor: 1,035.0	Parts: 1,194.29
:	0	Total: 2,229.29

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1400699 **Meter:** 48775 **In Date:** 01/22/2014 **Closed:** 02/11/2014

Problem: Pm service.Vise inop and check trailer outlet inop.

- P.m. Service.	Parts List	Qty
- Resurface front brake rotors,replace front pads.service and lube front calipers.flush and bleed system.	15-40 Oil	15.00
- Replace and rewire trailer plug.replace right rear marker light.r&r vise and replace broken roll pin.	Napagold Oil Filter	1.00
- Rotate and balnce all six tires.	Fuel Filter Ford Only	1.00
- Shop Supplies	Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Washer FI	1.00
	Brake Pads	1.00
	Brake Cleaner	1.00
	Trailer Conn Socket	1.00
	Pintle Pin W/chain	1.00
	M C Base Mount Kit	1.00
	Shop Supplies	1.00
Hours 13.00	Labor: 780.00	Parts: 269.75
:		Total: 1,049.75

Workorder: 1406275 **Meter:** 53664 **In Date:** 06/26/2014 **Closed:** 07/15/2014

Problem: Pm service.Check wipers inop.Re-position vise.Noise in front tire area.

- Perform pm service.	Parts List	Qty
- Test and replace failed windshield wiper motor assembly with new.install new washer nozzles.replace failed middle ac vent with new.	15-40 Oil	15.00
- Install two new tires to the front wheels.repair flat right rear outer tire.nitrogen fill and balance all four.replace broken hitch pindel pin with new.	Napagold Oil Filter	1.00
- Computer diagnose and monitor fuel pressure.pinpoint test and replace failed fuel pump and conditioning module on frame rail with new.	Napagold Air Filter	1.00
- Diagnose for noise over bumps and replace both failed left and right front body mounts with new.	Wd40 16oz	1.00
- Remove vise.fabricate bracket and reposition vise to different position.	Wiper Blade	2.00
- Perform wheel alignment complete.	Fuel Filter Ford Only	1.00
- Shop Supplies	Washer Nozzle	2.00
	Lt245/75r17 Hankook Tire	2.00
	Pintle Pin W/chain	1.00
	Wiper Motor Assembly	1.00
	Louvre Asy	1.00
	Pedal Pad	1.00
	Stg Wheel Cov - Ford	1.00
	Pump Asy	1.00
	Insulator	2.00
	Insulator	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 18.75	Labor: 1,125.0	Parts: 1,726.05
:	0	Total: 2,851.05

Workorder: 1408235 **Meter:** 54476 **In Date:** 08/19/2014 **Closed:** 08/19/2014

Problem: Tires

- Tire Service 8100 Forest Hill Blvd - Tires			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1408236 **Meter:** 54476 **In Date:** 08/19/2014 **Closed:** 08/19/2014
Problem: service

- Tire Service 8100 forest hill blvd - service

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1500374 **Meter:** 59481 **In Date:** 01/12/2015 **Closed:** 01/30/2015
Problem: Pm service and belt noise.

- P.m. Service.

Parts List **Qty**

- Replace four tires,rotate and balance all six.

15-40 Oil 15.00

- Pressure test and inspect cooling system.replace leaking lower radiator hose,serpentine belt and tensioner.flush and refill system.

Napagold Oil Filter 1.00

Fuel Filter Ford Only 1.00

Wiper Blade 2.00

- Resurface rear brake rotors.replace rear brake pads,service and lube calipers.flush and bleed system.

Lt245/75r17 Hankook Tire 4.00

- Shop Supplies

Serpentine Belt 1.00

Tensioner-heavy Duty 1.00

Curved Radiator Hose 1.00

Peak Global 3.00

Rear Pads 1.00

Curved Radiator Hose 1.00

Shop Supplies 1.00

Tire Disposal Fee 4.00

Hours 16.00 Labor: 960.00 Parts: 1,576.48 Total: 2,536.48
:

Workorder: 1506923 **Meter:** 64310 **In Date:** 07/13/2015 **Closed:** 07/27/2015
Problem: Pm service.Dead battery.

- Pm service.

Parts List **Qty**

- Check starting and charging system.replace both defective batteries.

15-40 Oil 15.00

- Replace one defective cab clearance lamp bulb and one alley lamp bulb.

Napagold Oil Filter 1.00

Fuel Filter Ford Only 1.00

- Perform transmission flush and replace filter.refill transmission fluid.

Wiper Blade 2.00

Used Fire X Refurbished 1.00

- Repair right front tire.rotate and balance all six.

Battery 2.00

- Shop Supplies

Bulb 1.00

Bulb (Mr11-12v) 1.00

Syn-atf Trans Fluid S 20.00

Seal Kit 1.00

Atp Filter 1.00

Shop Supplies 1.00

Hours 12.00 Labor: 720.00 Parts: 590.30 Total: 1,310.30
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1600576 **Meter:** 69009 **In Date:** 01/19/2016 **Closed:** 02/04/2016
Problem: P.M. service check power outlet.

	Parts List	Qty
- Pm service.		
- Replace two tires.rotate and balance all six.	15-40 Oil	15.00
- Replace licence plate bracket with light,clearance light bar,and faulty power outlet.repair broken wire for light bar and two center rear lamps at box switch.	Napagold Oil Filter	1.00
	Fuel Filter Ford Only	1.00
	20" Wiper Blade	2.00
- Replace four defective rear body mounts.replace both left and right upper and lower ball joints.clean and repack both front wheel bearings and replace seals.	179636492 Lt245-75r17	2.00
	Upper Ball Joint	2.00
- Complete front end alignment and road test.	Lower Ball Joint	2.00
- Shop Supplies	License Bracket W/light	1.00
	6 Inch Id Bar Kit	1.00
	Body Mount Kit	4.00
	Wheel Seal - Front Wheel	2.00
	Green Diesel Fuel Cap	1.00
	Soket Pauer Outlet	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 22.00	Labor: 1,320.0	Parts: 1,241.96
:	0	Total: 2,561.96

Workorder: 1607043 **Meter:** 72988 **In Date:** 07/13/2016 **Closed:** 07/29/2016
Problem: P.M. service and trailer plug inop and replace steering wheel cover

	Parts List	Qty
- P.m. Service.		
- Replace four tires,rotate and balance all six.	Exha	1.00
- Replace left side headlamp.	Kq22932df Diesel Inje	1.00
- Replace and rewire corroded trailer plug.install steering wheel cover.	15-40 Oil	30.00
	Napagold Oil Filter	2.00
- Service and clean Egr port and induction system.flush injectors.r&r exhaust particulate and pressure clean.perform forced regen.	Fuel Filter Ford Only	1.00
	20" Wiper Blade	2.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
	179636492 Lt245-75r17	4.00
	Halogen Lamp	1.00
	trailer plug	1.00
	Stg Wheel Cov - Ford	1.00
	Tr416 Valve Stem	4.00
	Diesel Egr Induction Service Kit	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 17.00	Labor: 1,020.0	Parts: 1,751.82
:	0	Total: 2,771.82

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1701978 **Meter:** 79084 **In Date:** 02/27/2017 **Closed:** 03/14/2017

Problem: P.M. service and right rear tire going flat.

- P.m. Service.	Parts List	Qty
- Replace one tail lamp.replace two roof marker bulbs.	Non-chlor Brake Clnr	1.00
- Resurface front and rear brake rotors,replace brake pads.service and lube calipers.flush and bleed system.	Real Suspension Bumpstops	2.00
- Replace worn out rear bump stop.replace missing pintle pin.	Pintle Pin W/clip	1.00
- Test batteries and charging system.replace both bad batteries.	Battery 65	2.00
- Repair right rear outter tire,rotate and balance all six.	15-40 Oil	15.00
- Shop Supplies	Napagold Oil Filter	1.00
	Napagold Air Filter	1.00
	Fuel Filter Ford Only	1.00
	20" Wiper Blade	2.00
	Pedal Pad	1.00
	Wd40 Spr	1.00
	Used Fire X Refurbished	1.00
	4 Led S T T Lamp	2.00
	Bulb	2.00
	Brake Pad	1.00
	Brake Pads	1.00
	Shop Supplies	1.00
Hours 20.75	Labor: 1,245.00	Parts: 794.75
:	0	Total: 2,039.75

Workorder: 1705720 **Meter:** 81316 **In Date:** 06/08/2017 **Closed:** 06/15/2017

Problem: Towed in for no start.

- Diagnose hvac blower operation.replace bad blower motor.	Parts List	Qty
- Diagnose no start,no crank.scan computer pulled codes,u0101and U0115.perform pinpoint test.clear codes ,self test generated code P0231.check lfs greater than 10ohms.replace lfs clear codes and retest.	Blwer Mtr Assy Flan	1.00
- Shop Supplies	Swicth Assy	1.00
	Shop Supplies	1.00
Hours 3.60	Labor: 216.00	Parts: 166.15
:		Total: 382.15

Workorder: 1705725 **Meter:** 81147 **In Date:** 06/08/2017 **Closed:** 06/08/2017

Problem: No start

- Tow From: 6116 New Stead Court, Greenacres Fl To: Lv shop

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1706651 **Meter:** 81741 **In Date:** 07/06/2017 **Closed:** 07/07/2017

Problem: Running Rough

- Tow From: 8100 Forest Hill Blvd, Wpb To: Lv shop

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1706748 **Meter:** 81822 **In Date:** 07/11/2017 **Closed:** 07/20/2017

Problem: Towed in for rattle under truck over bumps.

- Diagnose noise .replace two front shocks.test drive.	Parts List	Qty
- Shop Supplies	Gas Grande Fleet Shoc	2.00
	Shop Supplies	1.00
Hours 1.30	Labor: 78.00	Parts: 115.16
:		Total: 193.16

Workorder: 1711250 **Meter:** 84728 **In Date:** 11/15/2017 **Closed:**

Problem: PM Service

-	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

Workorder: 1712484 **Meter:** 84728 **In Date:** 12/19/2017 **Closed:** 12/19/2017

Problem: Transition Prep Charge

- Transition Prep Charge	Hours 2.00	Labor: 120.00	Parts: 0.00	Total: 120.00
	:			