



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V16430

In Date: 07/18/2008
Close Date: 07/28/2008

Meter Reading: 47.00

Problem?

shoreline ac unit does not work when plugged in. r73

Task performed:

Parts ----- Quantity

1. contacted hallmark for repair.

NO PARTS USED

Workorder: V16588

In Date: 07/25/2008
Close Date: 07/28/2008

Meter Reading: 75.00

Problem?

The seal that seperates the Front Cab from the rear box is coming apart cuasing water from the exterior of the truck to leak inside the front passenger cab and into the A/C unit that is directly under neath it. r73

Task performed:

Parts ----- Quantity

contacted hallmark for repair.

NO PARTS USED

Workorder: V16663

In Date: 07/28/2008
Close Date: 07/31/2008

Meter Reading:

Problem?

siren no longer works R-73

Task performed:

Parts ----- Quantity

drive to stn; MIC keyed up; put in holder; told driver to keep in holder. j

071704214035 GASKET 1 1/2

3

Workorder: V16717

In Date: 07/30/2008
Close Date: 08/01/2008

Meter Reading:

Problem?

seal between main cab and patient compartment is leaking water.R73

Task performed:

Parts ----- Quantity

1. contacted hallmark for warranty repair.

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V16589

In Date: 07/25/2008
Close Date: 08/06/2008

Meter Reading: 75.00

Problem?

Rear passenger A/C vent inside of front CAB is Missing. r73

Task performed:

1. warranty repair by hallmark

Parts

NO PARTS USED

Quantity

Workorder: V16878

In Date: 08/06/2008
Close Date: 08/12/2008

Meter Reading:

Problem?

Lower left rear warning light not working. R73

Task performed:

1 test operation l/r comp tight and r&r light assembly.
2 get all parts used at Pahokee- belle Glade on 08/07/08and charge them out on w/o and restock truck.

Parts

50R03ZCRLIGHT LED RED TIR 6

1

Quantity

Workorder: V16980

In Date: 08/12/2008
Close Date: 08/20/2008

Meter Reading: 119.00

Problem?

AC NOT BLOWING COLD, ALSO BLOWING WHEN FAN IS IN OFF POSITION. R73

Task performed:

check a/c freon level on r73. freon pressure normal.

Parts

NO PARTS USED

Quantity

Workorder: V17145

In Date: 08/19/2008
Close Date: 08/25/2008

Meter Reading: 2,315.00

Problem?

scba seat release on rear passenger behind driver inoperable. R73

Task performed:

1. adjusted scba bracket and replaced missing cable lock

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V17439

In Date: 09/02/2008
Close Date: 09/29/2008

Meter Reading: 168.00

Problem?

replace rear tires

Task performed:

Parts

Quantity

Replace rear tires - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V18535

In Date: 10/23/2008
Close Date: 11/05/2008

Meter Reading: 360.00

Problem?

The seat behind the officer SCBA holder is broke it will not lock the pack in place. R73

Task performed:

Parts

Quantity

Repaired by Hallmark 10/23/08 j

NO PARTS USED

Workorder: V19683

In Date: 12/11/2008
Close Date: 12/12/2008

Meter Reading: 503.00

Problem?

Door open alarm not activating at all. Safety issue. r73

Task performed:

Parts

Quantity

CONTACTED HALLMARK FIRE 12/11/08

NO PARTS USED

Workorder: V19481

In Date: 12/03/2008
Close Date: 12/16/2008

Meter Reading: 467.00

Problem?

While enroute to a call the water/oil alarm went off. It sounded for a few min. and silenced by itself. 12/2/08 r73

Task performed:

Parts

Quantity

Drive to Stn; cln connection; test drive ok. j

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V20352

In Date: 01/14/2009
Close Date: 01/27/2009

Meter Reading: 8,054.00

Problem?

C INSPECTION AND REPAIRS AS NEEDED R73

Task performed:

- 1- clean bay area
- 2- shop meeting.
- C-Inspection
- 2. R/R air dryer & purge valve.
- 3. Tighten door latches.
- 4. R/R wiper blades.
- 5. Cln/unclog evap; had no filter on it.
- 6. Start checking for air leaks.
- 7. Ck/rep air leaks, oil air tanks;, brake lines & air horns.
- j

Parts	Quantity
065624AD-IP DRIER	1
109494CHK VLV KIT AD-IP	1
15W40BSYN OIL BULK QTS	28
1873910C91FUEL STRAINER HORTON	1
1878042C91FUEL FILTER 2008 HORTON	1
46870AIR FILTER	1
5774457744XD OIL FILTER	1
78R539018-2699 A/C FILTER	1
800404USE K022105 PURGE KIT AD-IP-IS	1
91-22WIPER BLADE	2

Workorder: V19815

In Date: 12/17/2008
Close Date: 02/04/2009

Meter Reading:

Problem?

The a/c filters in the pt compartment are very dirty and need to be replaced. R73

Task performed:

- Replaced pat compt A/C filters. j

Parts	Quantity
1500900017000USE 9 X 14 FILTER	3

Workorder: V20228

In Date: 01/08/2009
Close Date: 02/04/2009

Meter Reading: 580.00

Problem?

rear passenger side door, pin is coming out. r73

Task performed:

- Inspected pin; put shotpeen to hinge to try & hold pin.
- j

Parts	Quantity
NO PARTS USED	



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V21270

In Date: 02/23/2009 Meter Reading: 9,377.00

Close Date: 02/24/2009

Problem?

REPAIR AIR HORN AND BACK UP ALARM R73 ON CALL

Task performed:

	<u>Parts</u>	<u>Quantity</u>
Replcd air horn kit & rep screw in _____ alarm. j	1094KIT-AIR HORN-GROVER	1

Workorder: V21512

In Date: 03/03/2009 Meter Reading: 9,948.00

Close Date: 03/16/2009

Problem?

Install long stretcher release rod R73B

Task performed:

	<u>Parts</u>	<u>Quantity</u>
Install stretcher rod & adj; adj stretcher magnets. j	NO PARTS USED	

Workorder: V21726

In Date: 03/12/2009 Meter Reading: 732.00

Close Date: 03/16/2009

Problem?

battery charger for the stretcher battery no longer charges the battery r73

Task performed:

	<u>Parts</u>	<u>Quantity</u>
Travel to Stn; chk charger-ok; btry must be bad; gave Stn extra btry; told to tag out bad btry when found; send in to shop. j	NO PARTS USED	

Workorder: V22212

In Date: 03/31/2009 Meter Reading: 10,927.00

Close Date: 04/07/2009

Problem?

While raining passenger front side compartment leaks. r73

Task performed:

	<u>Parts</u>	<u>Quantity</u>
Reported to Hallmark 3/31/09 j	NO PARTS USED	



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V22178

In Date: 03/30/2009

Meter Reading:

Close Date: 04/17/2009

Problem?

Need brackets mounted for signage. R73B

Task performed:

Parts

Quantity

Installed placard on truck; cln off door & installed. j

NO PARTS USED

Workorder: V22426

In Date: 04/09/2009

Meter Reading: 10,927.00

Close Date: 04/21/2009

Problem?

repair air horn R73

Task performed:

Parts

Quantity

R/R air horn kit. j

1094KIT-AIR HORN-GROVER

1

Workorder: V22920

In Date: 04/29/2009

Meter Reading: 908.00

Close Date: 04/30/2009

Problem?

Shoreline ac unit does not come on. R73B

Task performed:

Parts

Quantity

Breaker was tripped - crew reset 4/30/09 j

NO PARTS USED

Workorder: V23409

In Date: 05/20/2009

Meter Reading: 13,412.00

Close Date: 06/15/2009

Problem?

Low coolant alarm sounding even when coolant is full. Oil in water alarm sounding. (Three consecutive shifts). r 73

Task performed:

Parts

Quantity

cotacted hugo at sta 73 coolant was slightly low was topped off he will contact shop if problem persists. No labor

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V23689

In Date: 06/01/2009
Close Date: 06/22/2009

Meter Reading: 1,009.00

Problem?

Oil in water light/alarm still coming on. Privacy windows still not working. Front compartment on officers side leaks, bottom shelf fill with water.r73

Task performed:

Coolant Leak; Contacted Hallmark for WARRANTY repair. j

Parts

NO PARTS USED

Quantity

Workorder: V24233

In Date: 06/20/2009
Close Date: 06/22/2009

Meter Reading: 1,077.00

Problem?

St 73 and R73B needs Diesel Oil. None available at station

Task performed:

OIL TAKEN TO STA BY DRIVER

Parts

15W40QSYN OIL QT

Quantity

12

Workorder: V23582

In Date: 05/27/2009
Close Date: 06/24/2009

Meter Reading: 1,009.00

Problem?

officers compartment leaking. water on shelf r73

Task performed:

Travel from Stn74 to Stn73.
2. Chkd door gskt - ok; chkd A/C drain hose for plugged condition & blew out both lines - ok; chkd A/C drain pans uper shelf; fnd (2) drill holes; siliconed holes for temp fix.
j

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V24428

In Date: 06/29/2009
Close Date: 07/02/2009

Meter Reading: 14,965.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED R 73

Task performed:

- B-Inspection
- 2. Replcd rear cab A/C filter.
- 3. Replcd filters in pat compt for A/C; had to cut filter material to size because we don't have current filter.
- 4. Replcd accreditation stickr on R/S.
- 5. mod area for fuel right side tank first decal; attached decal.
- 6. Diss LEDs w/condensation; dried lenses & mntng out & put drain holes to help drain moisture.
- 7. Mod rear comp door above bumper to close properly.
- 8. Took oil sample & put some on test paper. j

Parts

Quantity

15W40BSYN OIL BULK QTS	24
1873910C91FUEL STRAINER HORTON	1
1878042C91FUEL FILTER 2008 HORTON	1
5774457744XD OIL FILTER	1
78R539018-2699 A/C FILTER	1

Workorder: V24209

In Date: 06/19/2009
Close Date: 07/08/2009

Meter Reading: 14,629.00

Problem?

nail in L/F tire (outside agency-callaghan tire)

Task performed:

- Nail L/F tire - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V24647

In Date: 07/09/2009
Close Date: 07/17/2009

Meter Reading: 14,965.00

Problem?

compt door wont open r73

Task performed:

- 1. Get parts/tools ness for repair.
- 2. Travel to Stn73 from C/S; travel to C/S from Stn73.
- 3. Tried to get compt door open; lower latch will not release on compt L-1. j

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V24600

In Date: 07/06/2009
Close Date: 07/20/2009

Meter Reading: 14,965.00

Problem?

adjust fast idle r73

Task performed:

Adjust fast idle R73 - Rechten j

Parts

NO PARTS USED

Quantity

Vendor? RECHTIEN

Workorder: V24833

In Date: 07/17/2009
Close Date: 07/21/2009

Meter Reading: 15,398.00

Problem?

horn innop, armrest falling off R73B

Task performed:

1. Rebuild horns.
2. Reinstall arm rest; install backup washers. j

Parts

1094KIT-AIR HORN-GROVER

2

Quantity

Workorder: V24970

In Date: 07/22/2009
Close Date: 07/22/2009

Meter Reading: 1,126.00

Problem?

Rear A/C unit still leaking into compartment. r73b

Task performed:

contacted hallmark for repair

Parts

NO PARTS USED

Quantity

Workorder: V24873

In Date: 07/19/2009
Close Date: 07/23/2009

Meter Reading: 1,126.00

Problem?

A/C unit is leaking into compartment; gear and equipment getting wet. R73

Task performed:

contacted hallmark for warranty repair 7/19

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V25504

In Date: 08/13/2009 Meter Reading: 1,203.00
Close Date: 08/13/2009

Problem?

Shoreline ac doesn't work (note: mod 4 error)

Task performed:	Parts	Quantity
CALLED BOB AT HALLMARK, WILL STOP BY TODAY	NO PARTS USED	

Workorder: V25522

In Date: 08/13/2009 Meter Reading: 1,203.00
Close Date: 08/14/2009

Problem?

ac is not blowing cold R-73

Task performed:	Parts	Quantity
CALLED BOB FROM HALLMARK WILL LOOK AT IT TODAY WHEN HE IS OUT THERE REPAIRING THE A/C AND MODULAR PIN FAILUR	NO PARTS USED	

Workorder: V25495

In Date: 08/12/2009 Meter Reading: 1,203.00
Close Date: 08/25/2009

Problem?

Error message states," Mod 4 Pin 4 fail". Rear A/C unit still leaking into compartment. r73

Task performed:	Parts	Quantity
Unit rep under warranty by Hallmark. j	NO PARTS USED	

Workorder: V25904

In Date: 08/31/2009 Meter Reading: 1,232.00
Close Date: 09/11/2009

Problem?

The auto ejectors will not eject the shoreline that is plugged in to keep the truck running inside the station. They are on the drive side of the truck. Both of them are not working. r73

Task performed:	Parts	Quantity
Ck opn of auto-ejectors; ck connections at ign swtch; ck ok; ck opn-ck ok; asked driver abt problem. j	NO PARTS USED	



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V25776

In Date: 08/25/2009
Close Date: 09/14/2009

Meter Reading: 16,447.00

Problem?

repair a/c r73 charge for filter on warranty repair

Task performed:

Repar A/C R73; charge for filter on WARRANTY repair.
j

Parts

NO PARTS USED

Quantity

Vendor? RECHTIEN INTL

Workorder: V26334

In Date: 09/20/2009
Close Date: 09/29/2009

Meter Reading: 1,251.00

Problem?

OIL LEAKAGE. NOTED OIL ON GROUND AFTER RESCUE SITTING FOR AN HOUR.r73

Task performed:

Rep on W/O 26367 j

Parts

03210072SWITCH DUMP/FLOR LT
FREIGHTSHIPPING CHARGES

Quantity

1
1

Workorder: V26367

In Date: 09/21/2009
Close Date: 09/29/2009

Meter Reading: 1,251.00

Problem?

Oil in water alarm still going off. Oil leaking from right side of engine. r73

Task performed:

Ck for oil leak; fnd oil filter loose; tightened filter; clnd;
ran/ck for leak; ck oil level; ck ok; went to HQ. j

Parts

NO PARTS USED

Quantity

Workorder: V27154

In Date: 10/25/2009
Close Date: 11/02/2009

Meter Reading: 1,379.00

Problem?

broken running board light. the light fastener is broken and the light hangs r73

Task performed:

Travel to Stn73 and secured light under step. j

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V27134

In Date: 10/23/2009
Close Date: 11/20/2009

Meter Reading: 1,379.00

Problem?

the rear a/c is not working when plugged into shoreline to keep the meds cool. The airhorn is not working right only one side work:

Task performed:

1. Went to Stn73; fnd pat A/C 110V not working; condenser fans inop; cld not find any fuse or brkr for fans; poss cntrl unit; returned home.
2. Adj officers side air horn.
3. Adj air horns; add (2) qts trans fluid.
- .4 Fnd (1) bad shoreline plug & reset brkrs; condensor fans not comming on; Hallmark to come out & fix ckt board/module. j

Parts

Quantity

TRANSYND-GGAL CONTAINER TRANS FLUID

1

Workorder: V27314

In Date: 10/31/2009
Close Date: 11/23/2009

Meter Reading: 3,770.00

Problem?

low radiator fluid alarm went off fluid was checked and found to be good. ac blows hot when plugged in. water on gas alarm went R73

Task performed:

Chkd all above issues; NPF. (cooling sys) j

Parts

Quantity

NO PARTS USED

Workorder: V28244

In Date: 12/09/2009
Close Date: 01/08/2010

Meter Reading:

Problem?

drivers side air horn extension tube keeps popping out of base

Task performed:

1. Travel to Stn73 from Stn72; L/F air horn; solder joint brokn; needs new air horn; cldnd/put ___ loctite to see if fit; holds temporarily.
2. Rem air line fittings & mnt bolts; R/R air horn asy; reinstalled all parts; ck ok. j

Parts

Quantity

HRN6681HORN AIR 24" GROVER P/N-1510

1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V28583

In Date: 12/26/2009
Close Date: 01/08/2010

Meter Reading: 1,565.00

Problem?

R73B with water pump leak

Task performed:

Went to IH for parts; went to Stn73; drained rad; rem belt pulley, fender & pump replcd pump; reassembled all parts; filled rad; ran/topped off sys; clnd trk & work area; test drove; ck for leaks; ck ok. j

Parts

Quantity

ALA00350-50 EXTENDED LIFE COOLANT GAL

2

Workorder: V28589

In Date: 12/26/2009
Close Date: 01/08/2010

Meter Reading: 1,565.00

Problem?

R73B driver-side headlight out.

Task performed:

R/R headlight; chk lights ; ck ok. j

Parts

Quantity

9007H9007 BULB ASSY

1

Workorder: V28800

In Date: 01/04/2010
Close Date: 01/26/2010

Meter Reading: 1,565.00

Problem?

Right rear suspension air bag is not inflated possible leak r73

Task performed:

Adjust rear suspension. j

Parts

Quantity

NO PARTS USED

Workorder: V28952

In Date: 01/09/2010
Close Date: 01/27/2010

Meter Reading: 1,565.00

Problem?

truck leaning to left R73

Task performed:

Truck off level; fnd one leveling rod gone; replc/releveled truck; adj both sides. j

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V29427

In Date: 01/25/2010

Meter Reading: 22,282.00

Close Date: 02/05/2010

Problem?

C INSPECTION AND REPAIRS AS NEEDED R73

Task performed:

1. C-Inspection
2. Adj all tire pressures.
3. Replc wiper blades.
4. Replc L/frt of box LED clearance light asy.
5. Cln out road debris frm bat box slides & lube up to free slides; work draw back/forth until free.
6. Rem light ays frm under cab door panels; diss fixture & replc bulbs inside; reassemble & reinstall in panels.
7. Rem cvr & replc bulb in overhead pat area light.
8. Tighten loose compt door hold opens.
9. R/R rear A/C filters.
10. Rem L/rear door panel; take part # fnd on backside to parts dept & order parts.
11. Svc air dryer.
12. Svc trans (filters only); top off fluid.
13. Retorque all u-bolts.
14. R/rear air bag empties out overnight; chk for leaks; fnd one small leak at valve connector; rep; reset ride height to be equal on both sides.
15. 12V pat air inop; C/O sys to locate problem; fnd after following wires that low press switch connector was severely bent over & prongs not making connections w/connector; rep connector & straighten prongs on switch; now all works ok.
16. Replc all eng drive belts.
17. Rep pat area ovrhead slide draws; reglue divider strip & order one that is msng frm other side. j

Parts

Quantity

065624AD-IP DRIER	1
109494CHK VLV KIT AD-IP	1
1501450007750USE 0775145	3
15W40BSYN OIL BULK QTS	30
1847727C1BELT	1
1873910C91FUEL STRAINER HORTON	1
1878042C91FUEL FILTER 2008 HORTON	1
194BULB	10
2506656C124316 WIX CAB A/C FILTER	1
29526898 29548988 TRANS FILTER ALLISON	1
322502BULB PATIENT GH22	1
46870AIR FILTER	1
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
K022105PURGE VALVE AD-IP-IS	1
K060695BELT	1

Workorder: V29022

In Date: 01/11/2010

Meter Reading: 21,764.00

Close Date: 02/08/2010

Problem?

locking mechanism for the oxygen tray broke off. R73

Task performed:

Rep locking mechanism for O2 tank. j

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V28691

In Date: 12/30/2009
Close Date: 02/11/2010

Meter Reading: 1,565.00

Problem?

drivers side front marker light loose...it pops out very easily r73

Task performed:

1. C/O light; did not have one on truck; replc bolt for officers side step.
2. R/R lens; R&I hood strap W/O 29386. j

Parts

Quantity

3561965C1LIGHT	1
50R03ZCRLIGHT LED RED TIR 6	1
5FLANGEC5FLANGEC FLANGE CHROME	1

Workorder: V29386

In Date: 01/24/2010
Close Date: 02/11/2010

Meter Reading: 1,648.00

Problem?

Replace wiper blades. Marker/directional/side amber light on drivers side (front) is broken/cracked. R73

Task performed:

1. R/R wipers.
2. Fnd drivers side t-signal brkn; rem hood strap; R/R lense; ck ok; lense in Batt 7 slot. j

Parts

Quantity

91-22WIPER BLADE	2
------------------	---

Workorder: V29626

In Date: 01/25/2010
Close Date: 03/04/2010

Meter Reading: 22,282.00

Problem?

Finshed repairs R73

Task performed:

Finished repairs R73.

1. Replc R/side forward rub rail that was torn off; replc rub rail end cap on L/side.
2. Replc complete door panel - L/side - rear "cab" (panel insert missing); can only get w/compelte panel.
3. Rep panel insert on R/side; read "cab" only halfway pulling off.
4. In patient area install a new cabinet slide rail; cut length from 6' stock & sec to slide panel; reinstall the one that fell off forward cabinet that was ying on counter. j

Parts

Quantity

02840400END CAP	2
04320004RUBBER EXTRUSION	7
10003748DOOR CAP EXTR	2
3612563C92L/R DOOR PANEL	1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V29409

In Date: 01/25/2010
Close Date: 03/10/2010

Meter Reading: 1,648.00

Problem?

Low coolant alarm going off. Oil/Water alarm going off. Added coolant again. r74

Task performed:

Rep by Rechten Intl j

Parts

Quantity

NO PARTS USED

Workorder: V30359

In Date: 03/01/2010
Close Date: 03/10/2010

Meter Reading: 22,837.00

Problem?

mod 12 pin 5 (rear window frost inverter) alarm keeps going off R73

Task performed:

New inverter for window. j

Parts

Quantity

NO PARTS USED

Workorder: V30358

In Date: 03/01/2010
Close Date: 03/25/2010

Meter Reading: 22,837.00

Problem?

officer side intersection lamp housing busted. R73

Task performed:

Tighten A/C units under truck all loose. j

Parts

Quantity

5TSMACMOUNT 500 TIR SER CHROME

1

Workorder: V30452

In Date: 03/04/2010
Close Date: 03/25/2010

Meter Reading: 22,837.00

Problem?

loose a/c unit r-73B

Task performed:

Already tightened; all bolts on aA/C unit on other ticket.
1. Adj both leveling valves on this unit; also both out of adjustment.
2. Fnd pad coming off; drill/tap hole, isntall new screw & finish . j

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V30789

In Date: 03/17/2010
Close Date: 04/02/2010

Meter Reading: 23,650.00

Problem?

side door to mod does not close all the way because the locking pin keeps coming loose. also there is no "door open" audible alarm when a cab or mod door is open and the truck is in gear. r73

Task performed:

Fnd bottom pin on compt door loose; tighten & chk alldoor alarms. j

Parts

NO PARTS USED

Quantity

Workorder: V30692

In Date: 03/12/2010
Close Date: 04/20/2010

Meter Reading: 23,650.00

Problem?

scba bracket in drivers compartment needs to be lowered. top of pack/hoses rubbing on galvanized cage when opening and closing door. r73

Task performed:

r/R air pack; mov all brackets to fit; reinstalled on door panel. j

Parts

NO PARTS USED

Quantity

Workorder: V31303

In Date: 04/06/2010
Close Date: 04/27/2010

Meter Reading: 24,095.00

Problem?

oil leak, rubber boot torn R73

Task performed:

contacted Hallmark for warranty repair.

Parts

NO PARTS USED

Quantity

C/O; looks like oil cooler leaking a little; tighten bolts; clean up; tighten oil filter & valve core; have crew watch till need svc. j

Workorder: V31526

In Date: 04/14/2010
Close Date: 04/27/2010

Meter Reading: 24,095.00

Problem?

Install moulding around screen R73B

Task performed:

Go to Stn to install molding onscreen mount on truck. j

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V31875

In Date: 04/29/2010 Meter Reading: 25,550.00
Close Date: 05/11/2010

Problem?

replace all 6 tires R73B (outside agency-boulevard tire)

Task performed:

Replace all (6) tires - Boulevard j

Parts

NO PARTS USED

Quantity

Vendor? BOULEVARD TIRE

Workorder: V32603

In Date: 06/02/2010 Meter Reading: 25,550.00
Close Date: 06/08/2010

Problem?

rear door wont stay closed r73

Task performed:

Rear door will not stay closed; cln out latches & lube; full of sand/dirt; bad hose in this compt; ok at this time.
j

Parts

NO PARTS USED

Quantity

Workorder: V32127

In Date: 05/11/2010 Meter Reading: 25,550.00
Close Date: 06/25/2010

Problem?

110 a/c 10-7 r73

Task performed:

Rep wires on this unit; all work ok at this time; blow out dirt; rep wire ends.

Parts

5-20PH1PGK4 CONNECTOR 120V 20A FEMALE
50-1500USE FAN KIT PANCAKE MOTOR DANHARD

Quantity

1
2

Workorder: V33054

In Date: 06/22/2010 Meter Reading: 12,577.40
Close Date: 06/25/2010

Problem?

repair a/c r73

Task performed:

1. R/R cvr panel to tape up A/C line dripping wtr in rear A/C sys shoreline.
2. Replc shoreline plug; pull out wire & damages plug; replc w/new; working ok at this time. j

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V34962

In Date: 09/15/2010 Meter Reading: 30,621.00
Close Date: 09/23/2010

Problem?
repair computer stand R73

Task performed:	Parts	Quantity
Computer not charging - loose connecto in dash; rep wiring. j	NO PARTS USED	

Workorder: V33335

In Date: 07/05/2010 Meter Reading: 12,577.40
Close Date: 09/28/2010

Problem?
priivacy windows in pt compartment not working r73

Task performed:	Parts	Quantity
Privacy windows inop; inverter bad; replc inverter. j	10006527WINDOW INVERTOR	1

Workorder: V34265

In Date: 08/13/2010 Meter Reading: 30,356.00
Close Date: 09/29/2010

Problem?
B INSPECTION AND REPAIRS AS NEEDED R73

Task performed:	Parts	Quantity
B-Inspection	15W40BSYN OIL BULK QTS	30
2. R/R/I leak - valve stem ext replcd.	1872550C91FUEL FITTING CHECK VALVE INT	1
3. Air tires - low.	1873910C91FUEL STRAINER HORTON	1
4. Replc btrys-failed; rerouted cables, put pos to inside.	1878042C91FUEL FILTER 2008 HORTON	1
5. Diff overfull; adj fluid level.	2505420C91L/H WINDOW MOTOR	1
6. Coolant leaks - crimp on clamps; replc crimp on clamps; als svc cooling sys.	2506656C124316 WIX CAB A/C FILTER	1
7. L/R window inop frm drivers control connector; reset control to get window working.	440-44 1/8 IN VALVE EXT	1
8. Air comp intake hose rubbing brkt; sec & insulated hose.	4DA2545W LAMP	1
9. O2 alarm sounds; transducer defective; ordered new sensor; t-shoot sys; fnd problem w/transducer. j	5774457744XD OIL FILTER	1
	78R539018-2699 A/C FILTER	1
	91-22WIPER BLADE	2
	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	3
	DOOR6RED HAZ DOOR	1
	FREIGHTSHIPPING CHARGES	46
	H35SN12BULB	1
	HP-31DBATTERY 950CCA HP-31D	3



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V35216

In Date: 09/27/2010 Meter Reading: 30,983.00
Close Date: 10/27/2010

Problem?

Oil leak. Resubmission of 06 April 2010. Vehicle has been in for PM .Not corrected. Still leaking oil. r73

Task performed:

Parts

Quantity

C/O trk at Stn73; looks to be oil filter leaking under trk;
tighten up; have crew watch it for leaks. j

NO PARTS USED

Workorder: V35562

In Date: 10/12/2010 Meter Reading: 31,331.00
Close Date: 10/28/2010

Problem?

O2 is not getting from the bottle (which is full) to the o2 regulators in the pt compartment.

Task performed:

Parts

Quantity

1. inspect o2 system, check valve and regulator on tank,
check ok, need to go to support services, looks like bad
by pass valve. job

NO PARTS USED

Workorder: V35620

In Date: 10/13/2010 Meter Reading: 31,331.00
Close Date: 10/28/2010

Problem?

Check engine light on. R73B

Task performed:

Parts

Quantity

1. check engine light on, inspect and found a icp code
active, defered to shop for repairs. job

NO PARTS USED

Workorder: V35152

In Date: 09/24/2010 Meter Reading: 30,983.00
Close Date: 10/29/2010

Problem?

the air horns on R-73B are not working and the emergency light on the back box is broken.

Task performed:

Parts

Quantity

1. adjust one of air horns & installed diaphragms in
other, checks ok.
2. need new light cover , acquired at s/s parts and
installed on rescue. job

1094KIT-AIR HORN-GROVER

1

6819634283068-1963428-30 LENS CLR

4



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V35941

In Date: 10/26/2010
Close Date: 11/01/2010

Meter Reading: 32,075.00

Problem?

A INSPECTION AND DEFERED REPAIRS R73

Task performed:

Parts

Quantity

1. C/O rep after return frm Rechten(Intl dealer); road test & set up computer to chk for eng codes.
2. A-Inspection
3. C/O problem w/O2 sys; will dlvr O2 only when in bypass; fnd O2 solenoid on bypass valve inop; power to solenoid ok.
4. Change bottle brkt on O2 bottle to hold in carriage for shorter O2 bottles.
5. Right rear lower brake light flashes when applied; rem light asy & untape wiring to find pattern wire; set up steady burn & retape & reinstall light asy. j

NO PARTS USED

Workorder: V36179

In Date: 11/04/2010
Close Date: 11/18/2010

Meter Reading: 32,180.00

Problem?

officerside dash cover came dislodged, when putting it back in place, a fuse fell out, not sure if it is a spare, electrical seems to be working properly R73

Task performed:

Parts

Quantity

- C/O fuse panel; fnd ___ fuse came out; reinstalled fue & tightene clips to cvr so it is harder to open; ok at this time. j

NO PARTS USED

Workorder: V36018

In Date: 10/28/2010
Close Date: 11/30/2010

Meter Reading: 37,511.00

Problem?

flip up cover cover for shore power outlet broke off. prongs are exposed to elements inside the housing. E73

Task performed:

Parts

Quantity

- (1) TRAVELED TO ST73 TO REPAIR / REPLACE COVER ON SHORE LINE POWER RECEPTACLE ON SIDE OF R73B. FOUND ONE COVER MISSING AND THE OTHER BROKEN. REPLACED BOTH WITH NEW. OK. J.W.

091-3YWCOVER KUSSMAUL AUTO EJECT

2



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V36667

In Date: 11/24/2010
Close Date: 12/03/2010

Meter Reading: 32,978.00

Problem?

WHEN BRAKE IS APPLIED DRIVER REAR STROBE DOES NOT WORK R73

Task performed:

- 1. drive to Stn73; reset TIR 6 lite to ORR.
- 2. R/R pat compt bulb on; C/O light wiring - was ok. j

Parts

F39BXLAMP BULB

Quantity

1

Workorder: V35423

In Date: 10/06/2010
Close Date: 12/22/2010

Meter Reading: 31,331.00

Problem?

Rear passenger side door handle came off while entering the truck. This is the rear exit door to remove the stretcher. r73

Task performed:

- (1) TRAVELED TO ST73 TO REPAIR THE REAR DOOR HANDLE OF R73 THAT HAD COME OFF WHILE ENTERING THE TRUCK. FOUND THE BOLT HOLES THREADS WERE STRIPPED OUT. HAD TO DRILL LARGER HOLES AND RETAPPED NEW THREADS FOR LARGER BOLTS. CHECKED OUT OPERATION OF THE DOOR AFTER THE REPAIR. OK. J.W.

Parts

NO PARTS USED

Quantity

Workorder: V36310

In Date: 11/09/2010
Close Date: 12/22/2010

Meter Reading: 32,180.00

Problem?

replace o2 sensor r73

Task performed:

Parts

0250014702 SOLENOID HORTON
FREIGHTSHIPPING CHARGES

Quantity

1
20

Workorder: V37122

In Date: 12/13/2010
Close Date: 01/04/2011

Meter Reading: 32,180.00

Problem?

rear center marker lights loose r73

Task performed:

- Rep center marker light on rear of truck. j

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V37395

In Date: 12/24/2010 Meter Reading: 33,602.00
Close Date: 01/21/2011

Problem?

rear tire has a leak and is missing air cap R73

Task performed:

Reat tire has a leak & msng air cap - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor? BOULEVARD TIRE

Workorder: V38081

In Date: 01/27/2011 Meter Reading: 32,180.00
Close Date: 02/02/2011

Problem?

both auto eject plugs damaged r73B

Task performed:

Replc both plugs on rescue; (1) ripped out by wires,
other ran over bad; replc both. j

Parts

Quantity

NO PARTS USED

Workorder: V38091

In Date: 01/27/2011 Meter Reading: 35,319.00
Close Date: 02/14/2011

Problem?

the lens on the passenger rear led light cover fell off. needs to be replaced. R73

Task performed:

Installed new light cvr on R/rear 0 ok. j

Parts

Quantity

6819634283068-1963428-30 LENS CLR

1

Workorder: V38261

In Date: 02/03/2011 Meter Reading: 35,319.00
Close Date: 02/14/2011

Problem?

INSTALL 731 SIGNS ON BRAVO UNIT

Task performed:

Take off the band; make all plackards say 731 at this
time. j

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V38545

In Date: 02/15/2011
Close Date: 02/23/2011

Meter Reading: 36,168.00

Problem?

The O2 sensor on the main tank keeps sending a warning alarm stating there is no O2 in the tank. The clip to hold the officers side visor is broke. The the air horns go off at different times. r 73

Task performed:

Installed new Ow sensor on air tank; working ok;
installed clip on right side visor ok; did not find problem
w/air horn. j

Parts

Quantity

AST4000ASENSOR O2 REGULATOR

1

Workorder: V38445

In Date: 02/11/2011
Close Date: 02/28/2011

Meter Reading: 36,044.00

Problem?

Running light bar on top of rear emergency light bar is loose moving around.

Task performed:

C/O - fnd it loose; retap w/double sided tape - ok. j

Parts

Quantity

NO PARTS USED

Workorder: V38560

In Date: 02/16/2011
Close Date: 02/28/2011

Meter Reading: 36,168.00

Problem?

left side light bar cover broken R73

Task performed:

1. Need to get cover frm shop; did not have on truck.
2. Travel to Stn73; R/R light on pass side above rear tires.
3. C/O air horn not working; adj horns. j

Parts

Quantity

6819634283068-1963428-30 LENS CLR

2



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V38605

In Date: 02/18/2011
Close Date: 03/07/2011

Meter Reading: 36,168.00

Problem?

the truck did not want to turn over at 415am this morning. after the 3rd time of trying to start it, the truck started. the truck has been running rough and been documented several times in IBEM.

Task performed:

Parts

Quantity

Check all btrys; load test & volts all good; chk all btry conditionz - all tight now; chk starter wires & tighten; chk codes; computer wld not work; leave in svc; ok at this time. Coming to shop today. j (2/25/11)

NO PARTS USED

Travel to Stn73; C/O motor - FNP at this time.
J(3/7/11)

Workorder: V39272

In Date: 03/17/2011
Close Date: 03/24/2011

Meter Reading: 37,686.00

Problem?

BLUE SMOKE FROM EXHAUST R 73

Task performed:

Parts

Quantity

Travel to Stn73; C/O turbo - its blown; put back tog; return to shop. j

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V39238

In Date: 03/16/2011

Meter Reading: 37,868.00

Close Date: 04/04/2011

Problem?

C inspection and repairs as needed R 73

Task performed:

- C-Service
- 2. R/R wiper blades; R/R eng air filter; R/R L/frnt clearance light; ck ok.
- 3. Fnd foot holders off; drilled/mntd - ck ok.
- 4. Fnd pat door grab handle bolts msgng; tapped/replc bolt - ck ok.
- 5. Fnd inside rear tires rubbing on pat box; rem axle stops; bent stops; cut/welded, reenforced for cement plates; painted - ck ok.
- 6. Svc air dryer; R/R cartridge; R/R purge valve - ck ok.
- 7. Ck for coolant leaks; cldng eng firttings; tightened clamps on cooler & block; press test; cck okf - filled.
- 8. Fnd cab boot came unglued - resealed boot; ck ok.
- 9. Svc P/S sys; R/R filter/fluid - ck ok.
- 10. Ck for oil leaks; cldng eng; retorque valve cvr; ran/chk for leaks; ck ok.
- 11. R/R (3) pat A/C filters; R/I filter cvrs - ck ok.
- 12. Ck A/C inop; fnd A/C codes; t-shoot & reset ___ - ck ok.
- 13. Ck shoreline A/C inop; fnd A/C kicking power cord brkrs; installed heavy duty ext. cord; ran/ck ok; 9 AMP on ckt.
- 14. Ck door lock #3415-7 codes; t-shoot sys; fnd lock pod bed bad; pod in right rear cab door; ordered part. j
- 15. Ck/eng msgng; ck/codes - none fnd; ran eng; test drove, rechk codes - ck ok; ran eng dia test - ck ok; rechk when cold; ck ok; starts good - ok. j

Parts

Quantity

065624AD-IP DRIER	1
1501450007750USE 0775145	3
15W40BSYN OIL BULK QTS	30
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
2507061C1PS RESV GASKET	1
46870AIR FILTER	1
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
K022105PURGE VALVE AD-IP-IS	1
VML/T1808D2503221C1 FILTER POWER STEERING	1

Workorder: V38773

In Date: 02/25/2011

Meter Reading: 36,168.00

Close Date: 04/05/2011

Problem?

repair o2 system r 73

Task performed:

Repairs completed. j

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V39394

In Date: 03/23/2011
Close Date: 04/05/2011

Meter Reading: 37,686.00

Problem?

Spoke to BC and he said it would be ok to put on FOG lights and the rumbler on the rescue.

Task performed:

1. Install fog lights; cut, made, drilled/mntd brkts for lights; wired lights; added light cord to lights; loomed all wires; ck opn - ck ok.
2. Install howler kit; drilled/mntd spkrs; boomed/wired AMP; drilled/mnt activation switch; reassem all parts; ran/ck opn; ck ok. j

Parts	Quantity
5291FOG LIGHTS	1
59024-102SWITCH	1
9061420057SEAL RING EXHAUST MANIFOLD	2
9061421101EXHAUST MANIFOLD CENTER	1
9061421201EXHAUST MANIFOLD R/L	2
A9261420080EXHAUST GASKET	3
DDE/00009903150TURBO NUTS	4
DDE/0019904605TURBO STUD	2
DDE/9049900412EXHAUST BOLTS	12

Workorder: V39833

In Date: 04/11/2011
Close Date: 04/11/2011

Meter Reading: 38,155.00

Problem?

Small quarter size tear in front passenger seat. Sta. 73.

Task performed:

deferred repair to pm.

Parts	Quantity
NO PARTS USED	

Workorder: V40013

In Date: 04/19/2011
Close Date: 04/22/2011

Meter Reading: 38,155.00

Problem?

belts screeching badly, at training tower.

Task performed:

1. Travel to training tower; C/O belts, A/C compressor, etc; adj A/C belts.
2. R/R hood side marker ight lens asy. j

Parts	Quantity
3530089C95T/S SIGNAL LAMP R/H	1
3565527C1BOLT FLANGE T/S LIGHT	2



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V40458

In Date: 05/06/2011
Close Date: 05/17/2011

Meter Reading: 39,204.00

Problem?

the engine is starting hard. the rescue stalled out twice tonight while moving it 20 feet forward. this seems to be an ongoing problem.R73

Task performed:

Travel to Stn73; C/O truck; chk fuel sys; chk codes, etc.; hi-press pump going out; call shop; will send spare truck tomorrow; return to shop. j

Parts

NO PARTS USED

Quantity

Workorder: V40718

In Date: 05/19/2011
Close Date: 05/24/2011

Meter Reading: 39,204.00

Problem?

Drivers side front rim has a 18 inch gash (possible curb check damage) doesn't effect the driveability just damage, Sta 73.

Task performed:

1. Load up jack driver side tire and tools to R/R tire; travel to Stn73; C/O tire; fnd rim to be useable & ____ ok.
2. Mnt eqmpt in truck & install holders; mnt glove boxes on back of truck; travel to stn73.
3. Replc stn 110V plugs from ceiling; replc ____ for rescues & rep DC plug. j

Parts

5-20PH1PGK4 CONNECTOR 120V 20A FEMALE
5269LPVM-5 SM MOUNT

4
2

Quantity

Workorder: V40708

In Date: 05/19/2011
Close Date: 05/26/2011

Meter Reading: 39,204.00

Problem?

Air dump is not refilling R 73 B

Task performed:

Travel to Stn73; C/O air dump working. j

Parts

NO PARTS USED

Quantity

Workorder: V40524

In Date: 05/10/2011
Close Date: 05/27/2011

Meter Reading: 39,204.00

Problem?

check fuel system, hard start no start.

Task performed:

Chk for fault codes - none; performed hardstart - no start diagnostics; fnd oil level to be very hig oveer full mark; changed oil using 30 qts; ran eng - all ok. j

Parts

15W40BSYN OIL BULK QTS

30

Quantity



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V41070

In Date: 06/02/2011
Close Date: 06/13/2011

Meter Reading: 40,330.00

Problem?
A/C inop.

Task performed:

Parts

Quantity

Travel to Stn73; C/O A/C on cab unit; freon ok; reset unit to set doors - ok; travel back to shop. j

NO PARTS USED

Workorder: V41458

In Date: 06/20/2011
Close Date: 06/20/2011

Meter Reading: 40,865.00

Problem?
flat tire, lefty rear outside.

Task performed:

Parts

Quantity

Call tire co. for emergency call out to stn73; w/for call back; ref #1466; Boulevard called 2:35 to let me know completed. j

NO PARTS USED

Talked w/Mike about the wait on phone (one hour on phone). j

Workorder: V41335

In Date: 06/14/2011
Close Date: 06/24/2011

Meter Reading: 40,865.00

Problem?
plug in rear of rescue bay has bent pin inside will not connect to rescue. r 73

Task performed:

Parts

Quantity

Travel to Stn73; C/O problem cord frm ceiling; follow plug; was run over; get ladder, unhook cord; R/R plug & rewire; hook plug back up; test ok. j

5-20PH1PGK4 CONNECTOR 120V 20A FEMALE

1

Workorder: V41472

In Date: 06/20/2011
Close Date: 07/14/2011

Meter Reading: 40,865.00

Problem?
REPAIR FLAT R 73

Task performed:

Parts

Quantity

Rep flat R73 - Boulevard j

NO PARTS USED

Vendor? BOULEVARD



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V41962

In Date: 07/12/2011 Meter Reading: 42,052.00
Close Date: 07/20/2011

Problem?

The air horn do no work on the right side of truck. R73

Task performed:

TRAVEL TO ST 73 R&R HORN KITS IN AIR HORNS
AND ADJUST AK

Parts

1094KIT-AIR HORN-GROVER

Quantity

2

Workorder: V42601

In Date: 08/05/2011 Meter Reading: 42,799.00
Close Date: 08/12/2011

Problem?

Rear air is not blowing cold when truck is plugged in/front a/c is not blowing cold in crew compartment. R 73

Task performed:

travel to st 73 check out rear 110v a/c systm found fans
inop check power and ground r&r bad fans reinstall unit

Parts

50-1500USE FAN KIT PANCAKE MOTOR DANHARD

Quantity

2

Workorder: V43015

In Date: 08/24/2011 Meter Reading: 43,403.00
Close Date: 08/29/2011

Problem?

the rear privicy windows are flickering on and off. R 73

Task performed:

TRAVEL TO ST 73 CHECK OUT REAR WINDOWS
CHECK OUT WINDOW AMPS AT EACH DOOR OK
INSTALL EXTRA PWOER SUPPLY FOR REAR
WINDOWS REWIRE UNIT FOR EACH TO HAVE OWN
POWER SUPPLY

Parts

10006527WINDOW INVERTOR

Quantity

1

Workorder: V43463

In Date: 09/06/2011 Meter Reading: 44,098.00
Close Date: 09/14/2011

Problem?

drivers side fog lamp missing protective cover. passanger side center ground lights 1 out of socket & 1 not working. Sta 73.

Task performed:

travel to st 73 r&r fog lamp vocer check ut light not
working found broken wire repair ok

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V43937

In Date: 09/27/2011
Close Date: 10/03/2011

Meter Reading: 44,821.00

Problem?

Truck won't start.

Task performed:

went to belle glade truck broke down on the side of the road crew already swaped into spare help load truck followed wrecker to shop aired up system to release brakes unload at shop return home

Parts

Quantity

NO PARTS USED

Workorder: V44020

In Date: 09/29/2011
Close Date: 10/06/2011

Meter Reading: 44,821.00

Problem?

truck won't start.

Task performed:

Eng cranks/no start; fnd faulty codes 2372, 1136 for low EFP; chkd EFP sensor/harness.

While cranking, EFP was OPSI; rem filters & fnd metal debris; rem filter head asy; fnd damaged; chkd valve & loose metal in rpimer button; diss filter head completely; cind all metal debris; replc damaged chk valve & replc fuel supply pump because debris went thru it.

Replc filters & reassem filter heap; primed sys & ran eng; all ok at this time; chkd fuel tanks for debris frm return line; fnd no debris. j

Parts

Quantity

1812348C1FUEL LINE SLEEVE INT	3
1872550C91FUEL FITTING CHECK VALVE INT	1
1876108C922511369C91 FUEL PUMP LOW PRESS	1

Workorder: V44116

In Date: 10/03/2011
Close Date: 10/06/2011

Meter Reading: 44,821.00

Problem?

REPLACE BODY MOUNTS R 731

Task performed:

repaired body mounts

replace body mounts

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V44354

In Date: 10/13/2011

Meter Reading:

Close Date: 10/20/2011

Problem?

toggle switch for spot light is broken off. Sta 73.

Task performed:

check out go light switch couldnt repair will get new one and return

Parts

Quantity

2020-DDASH MOUNT REMOTE CONTROL

1

9007H9007 BULB ASSY

1

travel to st 73 r&r switch for go light on roof

Workorder: V43746

In Date: 09/18/2011

Meter Reading: 44,589.00

Close Date: 10/24/2011

Problem?

the lever that locks the oxygen bottle in the compartment is broken. Sta 73.

Task performed:

found broken order new part

Parts

Quantity

NO PARTS USED

Workorder: V44497

In Date: 10/19/2011

Meter Reading: 4,543.10

Close Date: 10/24/2011

Problem?

Won't start.

Task performed:

travel to st 73, check out motor codes, found throttle pedal sensor bad, order new one, air up brakes, tow to back lot till parts come in

Parts

Quantity

10008930SLIDE W/LOCK O2 TANK

1

2606578C91THROTTLE PEDAL ASSY

1

3505300C1RELAY

2

FREIGHTSHIPPING CHARGES

10

travel to st 73 check out trk code 168 power replace relays for start ck and run ok



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V43608

In Date: 09/12/2011
Close Date: 10/26/2011

Meter Reading: 44,828.00

Problem?

B INSPECTION R 731

Task performed:

- B-Inspection
- 2. Oil diluted w/fuel; change oil.
- 3. Rep brkn grd light mnt & replc light; tightened all other grd light mnts; had to retap some of mntng holes.
- 4. replc leaking drain on air tank.
- 5. Tightene all inner compt door panels; replc brkn strap in L-2 compt.
- 6. Foot valve exh while foot on brake pedal; air also exhaustic from quick release valve on emer side; t-shoot, determine bad foot valve; R/R foot valve & test all ok.
- 7. Put truck on jack stands to have tire replcd. j

Parts	Quantity
103385NDRAIN COCK	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
2FC00ZCR4 IN ROUND LED	1
388863HOSE KIT	2
5774457744XD OIL FILTER	2
800629 VALVE THROTTLE FOOT	1
MFG01876GROUND LT BRACKET	1

Workorder: V44777

In Date: 10/30/2011
Close Date: 11/02/2011

Meter Reading:

Problem?

head light on passenger side is out and clear strobe/marker light on driver's side is broken. R73

Task performed:

- Travel to Stn73; R/R headlight & rep light lens on tir 6 on driver side rear; return to shop. j

Parts	Quantity
9007H9007 BULB ASSY	1

Workorder: V44962

In Date: 11/04/2011
Close Date: 11/15/2011

Meter Reading: 45,799.00

Problem?

Change wiper blades.

Task performed:

- Travel to Stn73; R/R wiper blades. j

Parts	Quantity
91-22WIPER BLADE	2



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V45977

In Date: 12/20/2011 Meter Reading: 48,226.00
Close Date: 12/22/2011

Problem?

The handle to get into the rear compartment is broken, Sta73

Task performed:

TRAVEL TO ST. 73 R&R OUTER DOOR HANDLES AND ADJUST.

Parts	Quantity
10007599WINDOW HORTON	1
10008145HANDLE LH HORTON	2

R&R SIAD E WINDOW REWIRE TEST OK.

Workorder: V46054

In Date: 12/24/2011 Meter Reading: 73,749.00
Close Date: 12/28/2011

Problem?

r731 clicker does not open bay door 5

Task performed:

FOUND REMOTE NOT WORKING FOR BAY DOORS - COULD NOT GET REMOTE TO WORK.

Parts	Quantity
NO PARTS USED	

Workorder: V47291

In Date: 02/14/2012 Meter Reading: 50,085.00
Close Date: 02/14/2012

Problem?

Coolant leak. sta 73

Task performed:

WENT TO 73 - FILLED TANK - PRESS - TESTED - FOUND RAD. CAP BAD - NEEDS CAP - RETURN HOME.

Parts	Quantity
NO PARTS USED	

Workorder: V47295

In Date: 02/14/2012 Meter Reading: 50,085.00
Close Date: 02/27/2012

Problem?

REPLACE RADIATOR CAP

Task performed:

TRAVEL TO ST 73 R&R RADIATOR CAP PRESSURE TEST OK TOP OFF COOLANT.

Parts	Quantity
F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STANT	1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V47208

In Date: 02/10/2012
Close Date: 02/28/2012

Meter Reading: 49,953.00

Problem?

Rear door on the rescue is missing 1 of the 2 black buttons on the door. The missing button turns on the light to the inside on the treatment compartment. All lights work. This is not a high priority fix. R73

Task performed:

TRAVEL TO ST 73 TO INSTALL NEW SWITCH NOT THERE AT SHOP WILL REPAIR IN A.M.

Parts

3910010SW COVER LED

Quantity

1

Workorder: V47408

In Date: 02/18/2012
Close Date: 02/28/2012

Meter Reading: 50,446.00

Problem?

r731 has slow coolant leak.Sta 73

Task performed:

CHECK OUT COOLANT LEAK PROBLEM DIDN'T FIND LEAK W PRESSURE TESTER TOP OFF FLUID OK.

Parts

NO PARTS USED

Quantity

Workorder: V47355

In Date: 02/15/2012
Close Date: 03/01/2012

Meter Reading: 50,085.00

Problem?

right front scene light out air pressure alarm on brake #1 will not stop beeping. Sta 73

Task performed:

TRAVEL TO ST 73 CHECK OUT SCENE LIGHT COULD NOT GET TO RAIL. CHECK OUT ALARM GOING OFF MUST HAVE HAD WATER IN SWITCH.

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V47498

In Date: 02/22/2012

Meter Reading: 50,446.00

Close Date: 03/07/2012

Problem?

C INSPECTION R 73

Task performed:

1. C SERVICE AND INSPECTION.
2. R&R 3 BATTERIES.
3. R&R REAR END GEAR LUBE.
4. TORQUE AXLE U-BOLTS.
5. SERVICE AIR DRYER - R&R FILTER AND PURGE VALVE.
6. CLEANED A/C CONDENSORS - R&R WIPER BLADES.
7. FOUND CRI TIRE WON'T READ PSI - REPLACED EXTENSION AND SHORTEND CORE DEPRESSOR - RRI TIRE 60 PSI - FOUND PSI SENSORS LEAKING - AIRED TIRE - INSTALLED LED MONITORS - REMOVED TIRE GAURD SYSTEM.
8. FOUND DEFROST INOP - REMOVED PANELS - TROUBLESHOOT AND REPLACE SERVO MOTOR - ADJUSTED AND CHECK OK. REASSEMBLED.
9. REPAIR BODY GROUNDS - REMOVED ALL STAR WASHERS - CLEANED CONNECTIONS - CHECK OK.
10. R&R RT. SCENE LT. BULB - R&R PAT. DOME LIGHT BULBS.
11. REPLACE ENGINE BELTS - R&R ENGINE AND A/C BELTS.
12. R&R PAT. A/C FILTERS - R&R ENGINE AIR FILTER.
13. STRAIGHTENED OUT STEP AS BEST AS POSSIBLE - WELD UP WIDE SPLIT IN STEP.
14. INSTALLED CAB FUEL TANK COVER AND STEP ASSEMBLY AFTER REPAIRS WERE MADE.
15. REMOVED ALL TRUCK NUMBER AND CAMPAIGN PLACKARD FRAMES AND INSTALL NEW STYLE FRAMES. ALSO MADE UP NEW NUMBER AND CAPAIN PLACKARD AND INSTALLED.
16. FOUND DRIVER'S SIDE STEP BROKEN, TWISTED AND CRACKED - REMOVED TANK COVER AND STEP - HEATED AND STRAIGHTENED STEP AFTER BEING REMOVED FROM COVER.

Parts

Quantity

065624AD-IP DRIER	1
109494CHK VLV KIT AD-IP	1
1501450007750USE 0775145	3
1847727C1BELT	1
1878042C91FUEL FILTER 2008 HORTON	1
2506271C1DRAIN VALVE RADIATOR NAV	1
2506656C124316 WIX CAB A/C FILTER	1
322502BULB PATIENT GH22	1
3542606C12611234C1 VENT ACTUATOR	1
440-44 1/8 IN VALVE EXT	2
46870AIR FILTER	1
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
ACX-84534LUG NUT COVER PK10	7
AMH-1AMH-1 VALVE EXTENSION	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	3
H50SN12BULB	1
HP-31DBATTERY 950CCA HP-31D	3
K022105PURGE VALVE AD-IP-IS	1
K060695BELT	1
L PLACARDLARGE SIDE PLACARD	4
L PLACARD INSERTLARGE PLACARD INSERT CARD	4
RWTG1234LED PRESSURE CAP	6
S PLACARDFRONT AND BACK PLACARD	1
S PLACARD INSERTFRONT AND BACK INSERT CARD	1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V44205

In Date: 10/06/2011
Close Date: 03/09/2012

Meter Reading: 44,821.00

Problem?

replace tires r 73

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V47499

In Date: 02/22/2012
Close Date: 03/27/2012

Meter Reading: 50,446.00

Problem?

LOSS OF COOLANT R 73

Task performed:

Parts

Quantity

PRESS TEST SYSTEM - TROUBLESHOOT EGR COOLERS LEAKING - DRAINED COOLENT - REMOVED FENDER, HOSES, BRACKETS, FITTINGS, PIPES AND COOLERS - R&R BOTH EGR COOLERS - R&R ALL HOSE COUPLINGS, CLAMPS AND EGR VALVE AND GASKETS - REASSEMBLED - CLEARED ENGINE CODES - FILLED COOLING SYSTEM - PRESS TESTED - TEST DROVE - RAN PARK REGEN. CHECK OK.

1844447C1ORING	2
1875808C1GASKET EGR COOLER	2
1876261C98EGR COOLER EXH SIDE USE 7090595C91	1
1876262C96EGR COOLER INT SIDE USE 4307362R91	1
1878918C2EGR VALVE	1
CORECORE CHARGE	1

Workorder: V48296

In Date: 03/30/2012
Close Date: 04/16/2012

Meter Reading: 51,477.00

Problem?

REPAIR AIR LEAK

Task performed:

Parts

Quantity

- CHECK FOR AIR LEAKS FOUND PARK BRAKE VALVE LEAKING TRAVEL TO ST 73.
- TRAVEL TO ST 73 R&R AIR BRAKE PARK VALVE RECHECK SYSTEM. OK.

2505876C91DASH VALVE	1
----------------------	---



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V48635

In Date: 04/13/2012
Close Date: 05/09/2012

Meter Reading: 51,824.00

Problem?

Mirror on the right side does not move left or right with power control. Only a up and down motion. r 73

Task performed:

1. TRAVEL TO ST 73 CHECK OUT MIRROR ON TRUCK. FOUND WIRE OFF FOR LEFT AND CONTROL REPAIR TEST OK.
2. LENS TRAVEL TOS T 73 R&R LENS ON SIDE LIGHT.

Parts

Quantity

Z8012062C-02LENS CLEAR 9 X 7 FLUTED

1

Workorder: V49588

In Date: 05/23/2012
Close Date: 06/01/2012

Meter Reading: 53,886.00

Problem?

REPAIR A/C R 73

Task performed:

- TRAVEL TO ST 73 CHECK OUT A/C ADD FREON TO TEST FOR LEAKS OK.

Parts

Quantity

NO PARTS USED

Workorder: V49731

In Date: 05/30/2012
Close Date: 06/12/2012

Meter Reading: 54,242.00

Problem?

Front cab will not cool. Blowing hot air. r73

Task performed:

1. TRAVEL TO ST 73 CHECK OUT A/C SYSTEM. RESET BLEND DOORS CHECK FREON CLOSE WATER VALVES CHECK FAN CLUTCH ADD FREON.
2. MOUNT STRAPS FOR TOOLS.

Parts

Quantity

SAHSVS2510STRAP

4

Workorder: V50100

In Date: 06/13/2012
Close Date: 06/28/2012

Meter Reading: 54,645.00

Problem?

headsets not working. not sure if headset issue or comm system issue. headsets removed and placed on workbench on south side of bays. R73

Task performed:

- LOOK FOR HEAD SET ASK CREW COULD NOT FIND

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V50445

In Date: 06/28/2012 Meter Reading: 54,645.00
Close Date: 07/16/2012

Problem?

light above drivers rear wheel is cracked R73

Task performed:

TRAVEL TO ST 73 R&R LIGHT OVER REAR WHEEL
AND REWIRE.

Parts

50R03ZCRLIGHT LED RED TIR 6

Quantity

1

Workorder: V50571

In Date: 07/03/2012 Meter Reading: 55,483.00
Close Date: 07/16/2012

Problem?

LEB cover fall off driver side R73

Task performed:

REPLACED ON WORK ORDER #50445.

Parts

NO PARTS USED

Quantity

Workorder: V50967

In Date: 07/18/2012 Meter Reading: 55,706.00
Close Date: 07/20/2012

Problem?

Front A/C is blowing warm air. R73

Task performed:

- TRAVEL TO ST 73 CHECK OUT A/C SYSTEM, CHECK PRESSURE ETC. FOUND LOSS TOO MUCH FREON IN SYSTEM OR OIL SEND TO SHOP FOR REPAIR.
- CHECK CAB A/C - INSTALLED GAUGES - FOUND COMPRESSOR BAD - RECOVER FREON - REMOVED BELT, A/C LINES, AIR CLEANER, COMPRESSOR AND DRIER - HAD TO CUT EXP. VALVE BOLTS - REPLACED EXP. VALVE AND A/C CONT: - REPLACED DRIER AND EXP. VALVE SCREWS - MODIFIED SCREWS - REPLACED COMPRESSOR - VAC AND CHARGE SYSTEM ASSEMBLED AND ALL PARTS RANT AND CHECK OPERATION - CHECK OK
- FOUND COOLANT LEAKING ON OFFICERS SIDE OF ENG. - PRESSURE TEST SYSTEM - CUT ALL TIE WRAPS ON HOSES - FOUND CLAMP LOOSE - TIGHTENED ALL CLAMPS - FILLED RES. - CHECK OK.

Parts

3611894C9103-0805 A/C COMPRESSOR 4347

3660853C22512331C1 EXP VALVE NAV

3666273C1A/C DRIER NAV

Quantity

1

1

1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V51968

In Date: 08/29/2012

Meter Reading:

Close Date: 09/12/2012

Problem?

r731 running rough. engine sputters and has very low power.

Task performed:

1. TRAVEL TO ST 73 CHK MOTOR HOOK UP LAP TOP TOLD DRIVER IN AM TRUCK HAD TO WARM UP OK.

Parts

15W40QSYN OIL QT

Quantity

3

Workorder: V51730

In Date: 08/20/2012

Meter Reading: 57,278.00

Close Date: 09/18/2012

Problem?

B INSPECTION R 73

Task performed:

1. B INSP
2. B INSP
3. R&R FANBELT AND INSTALL CORRECTLY.
4. CHK A/C FOR LEAKS FOUND SCHRADER VALVE LEAKING EVACUATE AND RECHARGE SYST.
5. INSTALL WIPER BLADES.
6. REMOVE REAR A/C COVER AND INSTALL NEW FILTER ND 1 A/C VENT.
7. REPLACE A/C FILL VALVES EVACUATE AND RECHARGE SYST.
8. INSTALL ALL 4 CAB AJAR SWITCHES.
9. TIGHTEN REAR FLIP BUMPER BOLTS AND REPLACE MISSING BOLT.
10. REPLACE L/R DOOR PANEL CUP.
11. REPLACE L/S BACK UP CORNER LIGHT.

Parts

16-31438915 VALVE CORE A/C 3544706C1

1878042C91FUEL FILTER 2008 HORTON

2505201C1CONTAINER

2506656C124316 WIX CAB A/C FILTER

3579984C1DOOR SWITCH

4DA2545W LAMP

5774457744XD OIL FILTER

72R31001720 DIFFUSER A/C 3.5 IN

78R539018-2699 A/C FILTER

8916HIFLOW VALVE CORE

91-22WIPER BLADE

Quantity

1

1

1

2

4

1

1

1

1

1

2

Workorder: V51830

In Date: 08/23/2012

Meter Reading: 57,278.00

Close Date: 09/19/2012

Problem?

running rough

Task performed:

1. DIAGNOSE MISFIRE AT STARTUP SCAN COMP RUN ALL SELF TEST NO CODES FOUND. INSPECT BUZZ TEST #3 INJECTOR FAILED.
2. REMOVE VALVE COVER AND RUN BUZZ TEST REPLACE #3 OIL RAIL O-RINGS AND ICP SENSOR.
3. SCAN AND CLEAR CODES TEST DRIVE.

Parts

1842626C951842626C96 OIL RAIL MANIFOLD SEALS

1875784C921875784C93 ICP SENSOR

5010561R925010561R93 INJECTOR

CORECORE CHARGE

Quantity

1

1

1

1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V52590

In Date: 09/24/2012
Close Date: 09/26/2012

Meter Reading:

Problem?

right fog light is out and filled with water R 73

Task performed:

REMOVE FOG LIGHT INSTALL BULB HOLDER TEST OK.

Parts

H3LIGHT BULB BP1255/H3 H

Quantity

1

Workorder: V52966

In Date: 10/09/2012
Close Date: 10/17/2012

Meter Reading:

Problem?

cap on shoreline plug is broken off R 73

Task performed:

TRVL TO ST 73 R&R SUPER AUTO EJECT PLUG COVER.

Parts

091-3YWCOVER KUSSMAUL AUTO EJECT

Quantity

1

Workorder: V53045

In Date: 10/12/2012
Close Date: 11/08/2012

Meter Reading:

Problem?

The rod on the locking componet is sightly bent, the lock it self is still working but needs to be looked at....Jose

Task performed:

TRAVEL TO ST 73 CHECK OUT STRETCHER LOCK WORKING GOOD OK NOW BEND IS NOT BAD.

Parts

NO PARTS USED

Quantity

Workorder: V53642

In Date: 11/08/2012
Close Date: 11/08/2012

Meter Reading:

Problem?

The stretcher is malfunctioning again. I have sent documentation to Ed Ehrke and called EMSAR.

Task performed:

EMSAR has been contacted.

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V53658

In Date: 11/09/2012
Close Date: 11/13/2012

Meter Reading: 60,724.00

Problem?

replaced stretcher lock

Task performed:

STRETCHER LOOKS INOP- REMOVE AND INSTALL
NEW LOCKED SECURELY ADJUSTED.

Parts

0567042LONG STRECHER BAR

Quantity

1

Workorder: V54053

In Date: 11/28/2012
Close Date: 12/19/2012

Meter Reading:

Problem?

undercarriage light under step rail on driver's side bolts came loose and was dangling. Put zip ties temporarily so it doesn't get ripped off while driving. r72

Task performed:

REMOUNT LIGHT DRILL AND TAP RAIL.

Parts

621714 IN LIGHT

Quantity

2

Workorder: V54890

In Date: 01/07/2013
Close Date: 01/11/2013

Meter Reading:

Problem?

REAR COMPARTMENT DOOR WONT STAY CLOSED. COMPARTMENT OVER STEP R73

Task performed:

TRAVEL TO ST 72 PULL DOOR APART FREE UP
STUCK LATCH.

Parts

NO PARTS USED

Quantity

Workorder: V55179

In Date: 01/20/2013
Close Date: 01/24/2013

Meter Reading: 65,445.00

Problem?

"warn engine" light came on while enroute to a call. Inverted orange triangle is also illuminated.

Task performed:

TRAVEL TO ST 72 TRUCK IS GOING TO SHOP THEY
WILL FIX IT.

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V55254

In Date: 01/11/2013

Close Date: 02/12/2013

Meter Reading: 65,445.00

Problem?

C inspection

Task performed:

Parts

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

1. C INSP	02500147O2 SOLENOID HORTON	1
2. C INSP	065624AD-IP DRIER	1
3. JACK UP VEH R&R L/R WHEELS REPAIR LEAK AT INNER WHEEL VALVE STEM.	1842626C951842626C96 OIL RAIL MANIFOLD SEALS	1
4. SET AND REPLACE 4 TPMS INDICATORS.	1875784C921875784C93 ICP SENSOR	1
5. R&R CABS AUX A/C FILTER.	1878042C91FUEL FILTER 2008 HORTON	1
6. R&R WIPER BLADES.	2506656C124316 WIX CAB A/C FILTER	1
7. TIGHTEN ALL COMPT DOOR HOLD OPEN HARDWARE IN L-2.	2507385C1CAB AIR LEVEL VALVE INT	1
8. REPLACE DEFECTIVE MOUNTINGHARDWARE ON BOTH RUMBLER SIRENS.	29526898 29548988 TRANS FILTER ALLISON	1
9. REPAIR AIR PAC HOLDER IN COMPT L-1. HOLES STRIPPED. DRILL AND TAP NEW HOLES.	3757REAR DRUMS 3757X 3647X	2
10. R&R REAR STEP BUMPER- HAD TO CUT BOLTS OFF DRILL. DRILL ON T INSERTS REPLACE THREADED INSERTS AND ALL HARDWARE.	46870AIR FILTER	2
11. OPEN BAR STEP COMPT. REMOVE INNEER COVER ON HANDLE AND LATCHES ASSY DISSEMBLE CLEAN AND FREEUP DOOR LATCHES AND HANDLE ASSY.	5010561R925010561R93 INJECTOR	1
12. R&R MAD LT HAD TO R&R CONSOLE AND CUSTOM MAKE MOUNTING BRKT. ORIGINAL WAS DIFFERENT.	5774457744XD OIL FILTER	1
13. REMOVE L/S COMPAIGN SIGN FRAME. REMOVE ALL OLD ADHESIVE FROMJ FRAME AND TRUCK BODY. APPLY NEW ADHESIVE AND INSTALL.	78R539018-2699 A/C FILTER	1
14. SERVICE ALLISON TRANS OIL AND FILTERS.	91-22WIPER BLADE	2
15. SERVICE AIR DRYER. REMOVE DRYER MAIN HOUSING FROM VEH TO WASH OUT CONTAMINANTS.	CORECORE CHARGE	1
16. DIAGNOSE AND ORDER O2 SOLENOIDS IN PATIENT AREA.	K022105PURGE VALVE AD-IP-IS	1
17. AIR LEAK DIAGNOSIS R&R 2 FITTINGS AT GOVERNOR. R&R AIR FITTING AT BRAKE VALVE R&R FITTING AT CAB LEVELING VALVE.	LF18TS-LEDMAP LIGHT LED 18 IN	1
18. CONTINUE AIR LEAK DIAGNOSIS.	RWTG1234LED PRESSURE CAP	4
19. ENG DIAGNOSE HOOK UP LAPTOP RAN ENGINE CODES RUN FUELING TEST SERIES PERFORM CYC CUT ON TEST ETC. ERASE CODES. RAD TEST VEH RE-READ CODES- NONE CAME BACK.	XK4034707QPMHD SHOE KIT 3/8 BEAM	2
20. WORK ON INSTALLING NEW SOLENOID IN REAR OF TRUCK DROP DOWN PANEL TO REMOVE SWITCH WIRE TOP FITTING REINSTALLED ALL REMOVEED PARTS.		
21. INSTALLED NEW LEVELING VALVE TO CAP LEAKING AIR INSTALLED NEW OK.		
22. INSTALLED NEW CPU MODULE IN REAR OF TRUCK.		
23. Q INSPECTION.		



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V55255

In Date: 01/23/2013
Close Date: 02/12/2013

Meter Reading: 65,445.00

Problem?

Map light on Officers side is broken. Rear air bags have a slow leak.

Task performed:

1. R&R AND REPAIR LICENSE PLATE.
2. REMOVE REAR BENCH SEAT FOR UPHOLSTERY REPAIR.
3. R&R CAB AUX A/C DRAIN HOSE.
4. R&R REAR DRUM BRAKES AND REPLACE DRUMS.

Parts

NO PARTS USED

Quantity

Workorder: V55901

In Date: 02/21/2013
Close Date: 02/22/2013

Meter Reading: 229,908.00

Problem?

remove lights on back for graphics and reinstall lights

Task performed:

1. REMOVE ALL LIGHTS FROM BACK OF TRUCK FOR GRAPHICS.
2. BE INSTALLED ALL LIGHTS, REPAIR HOLES IN BACK NO CLIPS TO SCREW IN REINSTALLED CLIPS COMPLETE LIGHTS.

Parts

NO PARTS USED

Quantity

Workorder: V56028

In Date: 02/26/2013
Close Date: 02/27/2013

Meter Reading: 65,698.00

Problem?

will not start

Task performed:

INSTALLED NEW BATTERIES.

Parts

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTER
HP-31D BATTERY 950CCA HP-31D

4

4



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V55658

In Date: 02/09/2013
Close Date: 03/13/2013

Meter Reading: 65,445.00

Problem?

engine running rough

Task performed:

1. WORK ON REMOVING BAD INJECTOR AFTER TROUBLE SHOOT PROBLEM IN ENGINE, REMOVE BAD INJECTOR HOLD ON PARTS ORDER.
2. WORK ON INSTALLING INJECTOR IN ENGINE.
3. COMPLETE WORK ON INJECTOR INSTALLED IN ENGINE TIE UP LINES CHECK FOR LEAKS, DRIVE TRUCK ABOUT 10 TO 15 MI.

Parts

Quantity

NO PARTS USED

Workorder: V56832

In Date: 04/04/2013
Close Date: 04/09/2013

Meter Reading: 68,366.00

Problem?

R-S mirror bracket R-72

Task performed:

REPAIR MIRROR ARM BKT RETURN TO SHOP.

Parts

Quantity

NO PARTS USED

Workorder: V57119

In Date: 04/18/2013
Close Date: 04/24/2013

Meter Reading: 69,292.00

Problem?

On the drivers side the ground light is hanging.

Task performed:

TRAVEL TO ST 72 REPAIR BRACKETS ON DRIVER SIDE UNDER BODY GROUND LIGHTS. REMOVE LIGHTS AND BRACKETS' STRAIGHTEN IN VISE AND REINSTALL BRACKETS AND LIGHTS.

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V57664

In Date: 05/11/2013
Close Date: 05/20/2013

Meter Reading:

Problem?

left front tire needs to be changed due to tread wear. Also the drawer labeled "IV bags" in the patient compartment needs a new latch. When vehicle slows down drawer slides open.

Task performed:

- CHECK TIRES R&R TWO FRONTER.
- R&R LATCH AND ADJUST DOORS LATCHES NOT FITTING ON UPPER DOORS.

Parts

Quantity

NO PARTS USED

Workorder: V57790

In Date: 05/16/2013
Close Date: 05/29/2013

Meter Reading:

Problem?

left headlight is out in the rescue.

Task performed:

TRAVEL TO 72 R&R HEAD LIGHT.

Parts

Quantity

2586872C1LOCK RING HEADLITE	1
2587313C1SPRING WASHER HEADLITE	1
9007H9007 BULB ASSY	1

Workorder: V57906

In Date: 05/22/2013
Close Date: 05/30/2013

Meter Reading: 69,969.00

Problem?

Replace front tires R72

Task performed:

REPLACE FRONT TIRES R72.

Parts

Quantity

216568BRIDGESTONE 255/70R22.5

2

Vendor? BOULEVARD TIRE

Workorder: V55767

In Date: 02/14/2013
Close Date: 06/05/2013

Meter Reading: 65,445.00

Problem?

restripe faulty stripes on rear

Task performed:

RESTRIPE FAULTY STRIPES ON REAR.

Parts

Quantity

NO PARTS USED

Vendor? SIGNS OF THE TIMES V



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V58204

In Date: 06/04/2013

Meter Reading:

Close Date: 06/07/2013

Problem?

Small emergency light above right side back tire is missing the lens. R72

Task performed:

TRAVEL TO STA 72. REPLACED LIGHT.

Parts

50R03ZCRLIGHT LED RED TIR 6

Quantity

1

Workorder: V58090

In Date: 05/31/2013

Meter Reading: 72,753.00

Close Date: 06/12/2013

Problem?

dome lite in cab will not turn off....we have it disconnected and in the cpt office

Task performed:

- CHECK VEHICLE DOOR SWITCHES OK. PLUGED IN DOME LIGHT FIXTURE. LIGHT CAME ON AND THEN STAYED OFF. DOME LIGHT FIXTURE BAD.
- TRAVEL TO ST 72, REPLACED FRONT DOME LIGHT.
- TRAVEL BACK TO SHOP.

Parts

3579984C1DOOR SWITCH

3609781C1DOME LIGHT

Quantity

1

1

Workorder: V58520

In Date: 06/18/2013

Meter Reading: 73,605.00

Close Date: 06/19/2013

Problem?

replace 4 rear tires

Task performed:

REPLACE FOUR REAR TIRES.

Parts

216568BRIDGESTONE 255/70R22.5

Quantity

4

Vendor? BOULEVARD TIRE CENTE

Workorder: V58273

In Date: 06/09/2013

Meter Reading: 73,238.00

Close Date: 06/25/2013

Problem?

O2 tank braket on strecher is coming loose and need new rivets, only one left on it now R 72

Task performed:

TRAVEL TO ST 72 REMOUNT O2 BRACKET ON STRETCHER BRACKET.

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V58634

In Date: 06/23/2013

Meter Reading: 73,785.00

Close Date: 06/28/2013

Problem?

cab a/c not blowing cold

Task performed:

Parts

Quantity

REPAIRED ON W.O. #58686

NO PARTS USED

Workorder: V58667

In Date: 06/25/2013

Meter Reading: 74,045.00

Close Date: 07/05/2013

Problem?

front a/c is blowing warm

Task performed:

Parts

Quantity

REPAIRED ON WORK ORDER 58684.

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V58684

In Date: 06/25/2013

Close Date: 07/05/2013

Meter Reading: 74,045.00

Problem?

B inspection R72

Task performed:

Parts

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

1. B INSPECTION.
2. REPLACE BATTERIES, CLEAN TERMINALS AND CABLES.
3. REATTACH FUEL LABEL TO FUEL TANK.
4. REMOVE ACCREDITED DECALS.
5. PATIENT SIDE DOOR PRIVACY WINDOW IN/OP. DIAGNOSE PROBLEM - FOUND BAD INVERTER. REPLACED INVERTER.
6. CHECK ALL TIRE PRESSURE SENSORS - FOUND LRI ONE BAD. REPLACED SENSOR.
7. FRONT A/C WARM - CHECK GAUGE PRESSURES (NO GOOD) RECOVER FREON AND RECHARGE WITH CORRECT AMOUNT AND RECHECK GAUGES (NO GOOD). RECOVER FREON AND REPLACED EXPANSION VALVE. CHARGE SYSTEM AND RECHECK GAUGES (NO GOOD) RECOVER FREON AND REPLACE COMPRESSOR. CHECK OIL LEVEL IN OLD AND NEW COMPRESSORS AND ADD CORRECT AMOUNT TO NEW. VACUUM SYSTEM AND CHARGE. INSTALL BELT TEST PRESSURES AND OUTLET TEMP (OK).
8. ADJUST FRONT BRAKES.
9. CAB AIR LEVEL NOT INFLATING - FOUND LINK FOR AIR LEVEL VALVE. DISCONNECTED. CONNECTED LINK AND TEST (OK).
10. LEAK TEST LEFT REAR TIRES. TIGHTEN VALVE STEM HOSES AND SENSORS (OK).
11. STRAP RADIATOR HOSE TO BRACKET.
12. REAR C LEARNANCE LIGHT CENTER LIGHT DIM. FOUND WHOLE STRIP LED AND WOULD HAVE TO REPLACE STRIP FOR CENTER SECTION. OK FOR NOW.
13. 110 VOLT A/C BLOWING CIRCUIT BREAKER. DRY WATER OUT OF AUTO EJECT. PLUG IN EXT CORD AND CONNECT GAUGES. CHECK PRESSURES. ADD 8 OZ. FREON. (OK)
14. OIL LEAK LEFT SIDE OF ENGINE DEGREASE AREA AND RUN VEHICLE. DIAGNOSE OIL LEAK - FOUND LEAKING OIL SENSOR AT WIRE CONNECTION. REMOVE WASHER BOTTLE AND FRAME BRACKET. REMOVED SENSOR. INSTALL NEW SENSOR. CLEAN WIRE CONNECTOR OF OIL. REINSTALL BRACKET AND WASHER BOTTLE.
15. GLUE DOOR PAD BACK ON DOOR PANEL L REAR DOOR.
16. TIGHTEN DOOR HOLD OPEN SHOCK BOLTS.
17. REAR AUX A/C DRAIN PLUGGED UP AND FILTER AND HOUSING RUSTED. REMOVE DRAIN HOSE AND BLOW OUT BLOCKAGE. CLEAN HOUSING OF STANDING WATER AND RUST. REPLACED FILTER.
18. Q & A VEHICLE.

10006527WINDOW INVERTOR	1
15-40B15W40 MOTOR OIL NON SYN	30
1839415C91OIL PRESSURE SENSOR	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
3611894C9103-0805 A/C COMPRESSOR 4347	1
3660853C22512331C1 EXP VALVE NAV	1
5774457744XD OIL FILTER	1
78R539018-2699 A/C FILTER	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	3
HP-31DBATTERY 950CCA HP-31D	3
RWTG1234LED PRESSURE CAP	1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V59044

In Date: 07/12/2013
Close Date: 07/15/2013

Meter Reading: 74,305.00

Problem?

air bags leaking

Task performed:

1. DIAGNOSE PROBLEM WITH NO AIR IN LEFT AIR BAG. FOUND BAD VALVE. REPLACED BOTH AIR BAGS AND VALVES. ADJUST HEIGHT. LEFT ADJUST ROD MISSING SJHOLDER BOLT OR BUSHING. INSTALL NEW SHOLDER BOLT.
2. HELP BYRUM R&R AIR BAGS AND VALVES.

Parts

Quantity

2505186C91ROD AIR BAG LEVEL	1
90054007VALVE AIR SUSP HEIGHT CONTROL	2
GUI1R11216GY1R11216 AIR BAG INT.	2

Workorder: V59032

In Date: 07/12/2013
Close Date: 07/18/2013

Meter Reading: 74,305.00

Problem?

When the truck hits the smallest bump it bottoms out in the patient compartment. Very rough ride. The light bars do not stay active when the truck is in neutral. Safety concern when on the roadway for vehicle accidents.

Task performed:

1. TRAVEL TO ST 72 CHECK OUT AIR BAGS LOWER RID HIGH AND BAGS ALL THE WAY UP AFTER ADJUSTMENT CRACKS IN BAG LEAKING SEND TO SHOP.
2. CHECK OUT LIGHT PATTERN ON MASTER SWITCH LITE BARS ARE GOING OFF IN SECONDARY MODE WILL NEED REPROGRAM GET PRIMARY TO SET ALL ON FOR NOW.

Parts

Quantity

NO PARTS USED

Workorder: V59132

In Date: 07/16/2013
Close Date: 07/18/2013

Meter Reading: 74,852.00

Problem?

Hard start responding to a call rough idel would not turn up rpm lipped back to station

Task performed:

TRAVEL TO 72 ROAD TESTED RESCUE RUNS FINE HOKED UP COMPUTER AND CHECKED CODES NONE FOUND ROAD TESTED AGAIN. OK.

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V60030

In Date: 08/26/2013
Close Date: 09/05/2013

Meter Reading: 77,932.00

Problem?

shore line ejecter not working....shore lines will not eject

Task performed:

CHECK OUT AUTO EJECT PULL UNIT WATER IN UNIT R&R AND REWIRE AUTO EJECT TEST OK. TRAVEL TO 72

Parts

Quantity

091-3YWCOVER KUSSMAUL AUTO EJECT
0915520120AUTO EJECT 20 AERO OTL3925

1
1

Workorder: V59858

In Date: 08/16/2013
Close Date: 09/11/2013

Meter Reading: 77,244.00

Problem?

shore line A/C kicks off before reaching set temp

Task performed:

- CHECK OUT A/C POST NEEDS NEW THERMOSTAT WILL RETURN.
- TRAVEL TO 72 DRIVER COMPLAINT 110 VOLTS A/C INOP REPLACED THERMOSTAT AND REWIRED.

Parts

Quantity

TH5220D1003WALL THERMOSTATE HORTON

1

Workorder: V59859

In Date: 08/16/2013
Close Date: 10/15/2013

Meter Reading: 77,244.00

Problem?

power vent fan in rear is not working

Task performed:

- NEED NEW FAN MOTOR HAS POWER ORDER NEW BLOWER.
- TRAVEL TO 72 DRIVER COMPLAINT EXHAUST FAN INOP REMOVED OLD FAN NEW FAN TWICE THE SIZE WILL NOT FIT TUBING ORDERED NEW PARTS.
- TRAVEL TO 72 REPLACED VENT FAN AND TESTED OK.

Parts

Quantity

02850008FAN VENT HORTON 3 IN
FREIGHTSHIPPING CHARGES

1
1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V60779

In Date: 09/25/2013

Meter Reading: 80,024.00

Close Date: 10/15/2013

Problem?

The light turns on but does not rotate. No street lights out here so it helps. Also we would like the inverter connected to the battery so we can keep the stretcher battery charger in the truck.

Task performed:

Parts

Quantity

1. TRAVEL TO 72 RESCUE RECEIVED BACK TO BACK CALLS WILL RETURN.
2. DRIVER COMPLAINT LIGHT DOES NOT ROTATE REPAIRED LOOSE CONNECTION AT SWITCH OK.

NO PARTS USED

Workorder: V61454

In Date: 10/22/2013

Meter Reading:

Close Date: 11/14/2013

Problem?

Need to please have brackets placed on the Lt side of the rescue for the trip tix. Thank you.

Task performed:

Parts

Quantity

DRILLED AND MOUNTED BRKTS- CH OK.

5269LPVM-5 SM MOUNT

2



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V61385

In Date: 10/19/2013

Close Date: 11/18/2013

Meter Reading: 82,095.00

Problem?

C inspection R72

Task performed:

Parts

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

1. C-INSP.	02841108BATTERY TRAY KWIKEE	1
2. C-INSP.	10003455STRAPS BATTERY HOLD DOWN	2
3. ENG BREATHER SYSTM, REMOVE ENG BREATHER SYSTEM CANISTER FROM SIDE OF ENG. ON BENCH REBUILD- REINSTALL WASH OFF ALL OIL RESIDUE FROM SIDE OF ENG OIL PAN, BELT HOUSING AND FRONT OF TRANS.	1003INTERIOR DOME BULB	1
4. FOUND RT SIDE BACK UP LGHT OUT- REMOVED LGH ASSMEBLY R&R BULB CHK OK, REASSEMBLED LT.	14-23353018 ORIFICE TUBE GREEN	2
5. FOUND L/REAR CAB DOOR SWITCH EGR- R&R SWITCH- CHK OK.	15-40B15W40 MOTOR OIL NON SYN	30
6. FOUND L/FRT CLEANRANCE LT OUT- R&R LT FOUND ALL BOX MARKER-LTS OUT-TROUBLESHOOT AND TRACED CIRCUIT-REPAIRED CONECTION AT MODULE- R&R TAP MARKER- SHK ALL LTS CHK OK.	1501450007750USE 0775145	3
7. REPLACE BATT BOX SLIDE TRAY- REMOVED BABLES, BATTERY AIR TANKS.	16-31438915 VALVE CORE A/C 3544706C1	2
8. REPLACE BATT SLIDE TRAY CONT. R&R BATT TRAY ASSEMBLY REINSTALLED AIR TANKS BATT AND CABLES-ADJUSTED COVER LATCHES- LUBED SLIDES AND CHK OK.	1841923C97INJ PUCK ADAPTER	6
9. FOUND DOOR CLOSE CUPS LOOSE- TIGHTENED ALL CUPS- REINSTALLED OFFICERS SEAT- CHK OK	1875326C92PIPE AIR INTAKE TURBO	1
10. CHK ENG- CODES- COULD NOT GET STARTED- PUT CHARGER ON BATT- STARTED AND CHK CABLES-NO CODES.	1875880C2SEAL	1
11. CHK FOR COOLANT LEAKS- PRESSURE SYSTEM- FOUND COOLANT HOSE LEAKING-TIGHTENED CLAMPS.	1876922C91SEAL KIT	1
12. CHK COOLANT LEAKS- TIRGHTENED COOLANT HOSE LEAKING- TIGHTENED CLAMPS.	1878042C91FUEL FILTER 2008 HORTON	1
13. CHK COOLANT LEAKS- TIGHTENED COOLANT TUBE HOSE CLAMPS CHK OK.	1878918C2EGR VALVE	1
14. CHK-SHORELINE A/C INOP. FOUND BREAKER IN SUPPLY POWER TRIPPING RECOVER FREON- FOUND COMPRESSOR -BAD - REMOVED LINES AND COMP-REPLACED COMPRESSOR- FLUSHED ENTIRE SYSTEM- REMOVED ACCENT OR TUBE.	23-5094DANHARD ACCUMULATOR	1
15. CHK SHORELINE A/C CONT; REASSEMBLED LINES-WIRED COMPRESSOR.	2506656C124316 WIX CAB A/C FILTER	1
16. SERVICE P/S SYSTEM- DRAINED R&R FILTER AND GASKET- REPLACED FLUID- RAN AND CHK OK	2507061C1PS RESV GASKET	1
17. REPAIR PAT A/C FILTER HOLDERS- REMOVED BROKEN SCREWS- DRILLED, TAPPED AND REPLACED SCREWS AND FILTERS.	3579984C1DOOR SWITCH	1
18. REPAIR PAT A/C CONT REPLACED OR FACE TUBE AND ACCUM/ DRIER INSTALLED A/C HOSES AND LEAK TEST SYSTEM.	4307362R91KIT EGR COOLER COLD SIDE OLD 1876262C	1
19. FOUND D.P.F 8990 FULL- REMOVED FILTER- CLEANED FANGES ON EXH PIPE DPF.	4DA2545W LAMP	1
20. REPAIR PAT A/C -VAC AND CHARGE A/C - RAN AND CHK OK.	50-215050-2105 DANHARD COMPRESSOR	1
	5774457744XD OIL FILTER	1
	6256LNC6256LNC COVER LUG NUT	1
	7090595C91COOLER EGR KIT 330MM EXH SIDE OLD 1876	1
	91-22WIPER BLADE	2
	CLR9185209186-1500-20 MARKER LT.AMBER LED	2
	DPFCLEANED UNIT	1
	VML/T1808D2503221C1 FILTER POWER STEERING	1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

- 21. REPLACE D.P.F- PULLED TRUCK ITO SHOP- CLEANED PRE-FILTER REPLACED D.P.F- RAN ENGINE.
- 22. CHK-ENG FOR MISS WHEN COLD AND REMOVED AIR CLEANER, AIR TUBES HARNESS AND VALVE CARES- RAN ENG FOUND INJECTOR PUCKS LEAKING - ORDERED PARTS- PUT VAVLE COVER ON AND PARKED TRACK CLEAN.
- 23. CHK ENG MISS-PULLED TRACK INTO SHOP- REMOVED VALVE COVER VALVE COVER GASKET AND INJ HARNESS AND OIL RAIL ASSEMBLY.
- 24. CHK ENG MISS- R&R INJECTOR PLUCKS- INSTALLED OIL RAIL, VALVE COVER HARNESS-VALVE COVER.
- 25. CHK EGR COOLERS FOR LEAK- REMOVED CROSSOVER TUBE ASSEMBLY-FOUND EXH EGR COOLER LEAKING- DRAINED ANTIFREEZE.
- 26. REPLACE EGR COOLERS- REMOVED RT FENDER, COOLANT CROSSOVER LINES.
- 27. REPLACE EGR COOLERS- REMOVED INTAKE COOLER ASSEMBLY.
- 28. REPLACE EGR COOLERS- REMOVED LINES HOSES BRKTS AND VEH COOLERS- CLEANED WATER, TUBED AND REMOVED HOSES.
- 29. REPLACE EGR COOLERS-REMOVED EXH COOLER AND MT-REMOVED LOWER COOLANT TUBES AND HOSE- REPLACED EXH COOLER.
- 30. REPLACE EGR COOLERS- REPLACED EGR VALVE AND INTAKE COOLER- REPLACED COOLANT HOSES AND CLAMPS.
- 31. REPLACE EGR COOLERS- REASSEMBLED ALL HOSES, CLAMPS, BRKTS.
- 32. REPLACE EGR COOLERS- FILLED COOLING SYSTEM- INSTALLED WINDSHEILD NUMBERS- CLEARED CODES-TEST DROVE- CHK CODES CHK OK- CK FOR LEAKS- CHK OK.
- 33. Q.A INSPECTION.

Workorder: V62226

In Date: 11/24/2013 **Meter Reading:** 82,674.00
Close Date: 12/03/2013

Problem?

windshield washer fluid pump does not work R72

Task performed:

REPLACE WINDSHIELD. WATER PUMP TEST FOR OPERATION IS GOOD NOW.

Parts

Quantity

A2254926000WASHER PUMP W/GROMMET

1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V62460

In Date: 12/04/2013
Close Date: 12/05/2013

Meter Reading: 83,185.00

Problem?

The ride in the back of R72 when transporting a patient is worse than it has ever been. Not sure if air was added or taken away during PM. R72

Task performed:

WENT TO 72 - CHECK AIR BAGS AND DUMP OPERATION - CHECK BODY MOUNTS CHECK OK. RETURN TO SHOP.

Parts

NO PARTS USED

Quantity

Workorder: V62558

In Date: 12/07/2013
Close Date: 12/16/2013

Meter Reading:

Problem?

Fog light fell off front bumper. R72

Task performed:

1. TRAVEL TO 72 DRIVER COMPLAINT LIGHT FELL OF REINSTALL SPOT LIGHT AND ALSO SECURED OTHER SPOT OK.
2. REPLACED DOME LIGHT BULBS.

Parts

322502BULB PATIENT GH22

Quantity

4

Workorder: V62575

In Date: 12/08/2013
Close Date: 12/16/2013

Meter Reading:

Problem?

CHANGE OIL ILLUMINATION CAME OVER THE DASH DISPLAY, WITH THE WRENCH LIGHT R72

Task performed:

DRIVER COMPLAINT OIL CHANGE LIGHT ON RESET OIL LIGHT.

Parts

NO PARTS USED

Quantity

Workorder: V62808

In Date: 12/18/2013
Close Date: 12/31/2013

Meter Reading:

Problem?

The rear suspension bottoms out every time you hit any bump. If we have a patient with a neck injury it is going to cause significant further damage. The ride is also very rough for the crews.

Task performed:

TRAVEL TO 72 DRIVER COMPLAINT SUSPENSION BOTTOM OUT ON BUMPS. ADJUSTED ALL BAGS AND TEST DROVE OK.

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V63459

In Date: 01/16/2014 Meter Reading: 86,299.00
Close Date: 01/24/2014

Problem?

passenger front airhorn bracket is broken.

Task performed:

TRAVEL TO 72 DRIVER COMPLAINT AIR HORN
BRACKET BROKEN REPLACED BROKEN BRACKET.

Parts

Quantity

GRV1720244770R1 HORN SUPPORT BRKT

1

Workorder: V63532

In Date: 01/20/2014 Meter Reading: 86,618.00
Close Date: 01/24/2014

Problem?

stryer stretcher will not raise in smooth motion asset #10177028 as marked will not take in system R72

Task performed:

OPERATED STRETCHER AND CALLED FOR REPAIR
TECH.

Parts

Quantity

NO PARTS USED

Workorder: V64104

In Date: 02/10/2014 Meter Reading:
Close Date: 02/13/2014

Problem?

Driver side rear outside tire has a large gash in it.

Task performed:

DRIVER SIDE REAR OUTSIDE TIRE HAS A LARGE
GASH IN IT.

Vendor? BOULEVARD TIRE

Parts

Quantity

NO PARTS USED

Workorder: V64374

In Date: 02/20/2014 Meter Reading:
Close Date: 02/21/2014

Problem?

The cab and sometimes the pt compartment of the rescue is infested with german cock roaches. This happened at 73 and the truck needed to be tented. R72

Task performed:

THE CAB AND SOMETIMES THE PT COMPARTMENT
OF THE RESCUE IS INFESTED WITH GERMAN COCK
ROACHES. THIS HAPPENED AT 73 AND THE TRUCK
NEEDED TO BE TENTED. R72.

Vendor? ERLA INC

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V64276

In Date: 02/17/2014

Meter Reading:

Close Date: 03/10/2014

Problem?

There is alot of water coming out from underneath the jumpseat the patient compartment while the AC is running.

Task performed:

Parts

Quantity

WATER COMING OUT UNDER JUMP EAT A/C DRAIN
CLOGGED. CLEAN DRAIN.

NO PARTS USED

Workorder: V65129

In Date: 03/22/2014

Meter Reading:

Close Date: 04/02/2014

Problem?

Outer left rear tire is flat. R72

Task performed:

Parts

Quantity

OUTER LEFT REA TIRE FLAT. R72

NO PARTS USED

Vendor? BOULEVARD TIRE

Workorder: V65666

In Date: 04/12/2014

Meter Reading:

Close Date: 04/15/2014

Problem?

Can you please change out the two latches in the patient compartment that do not latch. One is on the drivers side (the lowest one)
The other latch is on the passenger side very top (small compartment). R72

Task performed:

Parts

Quantity

TRAVEL TO 72 DRIVER COMPLAINT DRAWER
LATCHES INOP ADJUSTED LATCH STOPS.

5632-1010 IN DRAWER SLIDES PR

1

5632-1212 IN PAIR DRAWER SLIDES

1

Workorder: V62633

In Date: 12/10/2013

Meter Reading:

Close Date: 04/17/2014

Problem?

STRETCHER HYDRAULIC SLIPPED WHILE UNLOADING PATIENT. CP7 NOTIFIED CONTACTING STRYKER STRETCHER
#10177028

Task performed:

Parts

Quantity

REPAIRED ON INSPECTION.

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V65609

In Date: 04/10/2014
Close Date: 04/17/2014

Meter Reading: 91,403.00

Problem?

B inspection R72

Task performed:

1. B INSP.
2. B INSP.
3. R&R 2 R/S CAB DOOR SWITCHES.
4. R&R WIPER BLADES.
5. TIGHTEN ALL BOLTS ON BOTH FRONT MUD FLAPS.

Parts

Quantity

15-40B15W40 MOTOR OIL NON SYN	30
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
3579984C1DOOR SWITCH	2
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2

Workorder: V66071

In Date: 04/29/2014
Close Date: 05/07/2014

Meter Reading: 153,798.00

Problem?

QC back from Rechten

Task performed:

1. Q. C TRUCK.
2. CAB A/C NOT COLD, FOUND LOW ON FREON DUE TO LEAKING HIGH SIDE SCHRADER VALVE.
3. STRAIGHT PULL TO LEFT, CHECK AIR PRESSURE SWAP TIRES.

Parts

Quantity

NO PARTS USED

Workorder: V65801

In Date: 04/18/2014
Close Date: 06/12/2014

Meter Reading: 91,403.00

Problem?

fumigate rescue for german roaches

Task performed:

Fumigate for german roaches.

Parts

Quantity

NO PARTS USED

Vendor? HULETT



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V67054

In Date: 06/07/2014
Close Date: 06/17/2014

Meter Reading:

Problem?

Rear A/C in cab seems to have a clogged drain line and is leaking water into the cab, A/C for the pt compartment seems to have same issue and leaks as well. Reading light up front turns on and off while driving.

Task performed:

Parts

Quantity

1. TRAVEL TO 72 COMPLAINT A/C INOP A/C WORKS FINE NO PROBLEM FOUND.
2. CLEANED OUT ALL A/C DRAINS.
3. REPAIRED GROUND TO MAP LIGHT.

NO PARTS USED

Workorder: V67132

In Date: 06/11/2014
Close Date: 06/17/2014

Meter Reading:

Problem?

dome light stays on, condensation from A/C leaves puddle passenger rear side front cab

Task performed:

Parts

Quantity

1. TRAVEL TO 72 DRIVER COMPLAINT DOME LIGHT STAYS ON. FOUND NO COMPUTER ISSUE SENT TO SHOP.
2. DRIVER COMPLAINT A/C LEAKS IN CAB CLEANED OUT A/C DRAINS.

NO PARTS USED

Workorder: V67142

In Date: 06/11/2014
Close Date: 06/17/2014

Meter Reading: 92,824.00

Problem?

Dome light stays on

Task performed:

Parts

Quantity

CHECK WIRE GOING TO DOOR SWITCH FOUND DIODE MISSING INSTALLED DIODE AND DOME LIGHT WORKED.

091-84-022DIODE 6 AMP

1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V66617

In Date: 05/20/2014
Close Date: 06/18/2014

Meter Reading: 156,230.30

Problem?

running rough

Task performed:

- 1) diagnose rough running, order parts.
- 2) R&R injector and reseal pucks & test drive & ck, for codes burn off DPF ok.

Parts	Quantity
1842626C951842626C96 OIL RAIL MANIFOLD SEALS	1
1875784C921875784C93 ICP SENSOR	2
35200-YLIGHT MARKER LEDAMBER	4
5010561R925010561R93 INJECTOR	6

Workorder: V67657

In Date: 07/03/2014
Close Date: 07/18/2014

Meter Reading:

Problem?

3 out of 4 of the Plastic Medical Glove Box holders inside the cab are broken beyond repair.

Task performed:

Driver complaint plastic glove holders broke. Replaced glove holders.

Parts	Quantity
NO PARTS USED	

Workorder: V68031

In Date: 07/19/2014
Close Date: 07/28/2014

Meter Reading:

Problem?

Front a/c is in need of freon. R72

Task performed:

travel to sta,72 reiver complant a/c weak front condencer fill of bug and debris cleaned radiator add small amount of freon to system ck, ok.

Parts	Quantity
NO PARTS USED	

Workorder: V68781

In Date: 08/19/2014
Close Date: 08/19/2014

Meter Reading: 97,724.00

Problem?

truck stuck in neutral

Task performed:

Truck stuck in neutral. Drove out to 73. Check codes and check out speed sensor did a fast adapt test drove truck around to ensure works fine.

Parts	Quantity
NO PARTS USED	



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V68719

In Date: 08/16/2014
Close Date: 08/28/2014

Meter Reading: 97,724.00

Problem?

AC leaking in cab. Significant amount of water on floor. R72

Task performed:

Checked A/C. Cleaned out drains

1.Vacuumed system. Installed new compressor expansion valve thermistors and dryer. Vacuumed system charged. Found rear drain line kinked rerouted with new hose through floor board.

Parts

Quantity

3611894C9103-0805 A/C COMPRESSOR 4347	1
3622764C32606229C92 THERMISTER	1
3660853C22512331C1 EXP VALVE NAV	1
3666273C1A/C DRIER NAV	1

Workorder: V68720

In Date: 08/16/2014
Close Date: 08/28/2014

Meter Reading: 97,724.00

Problem?

Lower latch on patient compartment left rear door does not lock. R72

Task performed:

Checked latches. Found no problem.

1.Removed door grab handle and door skin. Installed new stricker latch. Installed new nut serts.

Parts

Quantity

B484RB484R REFLECT-RED	2
LTC594111656-16 LATCH R/H MEDIC MASTER	1

Workorder: V68950

In Date: 08/26/2014
Close Date: 09/03/2014

Meter Reading: 97,724.00

Problem?

B inspection R72

Task performed:

1."B" service ans inspection
2.Service air dryer. Remove and replace filter and purge valve.
3. Found ground lights loose. Repaired loose light mounts. Remove and replace cab marker light. Check ok.
4. Remove and replace wipers, engine air filter and radiator cap. Removed rear air dump flow light panel did not have one. Ok to run.

Parts

Quantity

03910007SW CAP BLANK	2
065624AD-IP DRIER	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
3529900C95MARKER LIGHT WPB	1
46870AIR FILTER	1
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STANT	1
K022105PURGE VALVE AD-IP-IS	1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V69384

In Date: 09/15/2014
Close Date: 09/17/2014

Meter Reading: 98,865.00

Problem?

The apparatus was difficult to start in the morning, the apparatus was plugged in and all battery switches turned off all night.

Task performed:

Braker for shoreline blowen reset braker and replaced batts.

Parts

Quantity

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF
HP-31DBATTERY 950CCA HP-31D

3
3

Workorder: V69597

In Date: 09/23/2014
Close Date: 10/30/2014

Meter Reading: 99,220.00

Problem?

broken lense on right rear lower light (white) light works lense broke when washin the unit with the vehicle brush

Task performed:

Replaced broken lens on RR corner LED

Parts

Quantity

6819634283068-1963428-30 LENS CLR

3

Workorder: V70019

In Date: 10/09/2014
Close Date: 11/05/2014

Meter Reading: 100,448.00

Problem?

Window/power lock switch not funtioning

Task performed:

Repaired loose connection to window switch

Parts

Quantity

NO PARTS USED

Workorder: V70069

In Date: 10/11/2014
Close Date: 11/05/2014

Meter Reading: 100,627.00

Problem?

Officer side front door, electronic locking switch is not working. All other doors work properly.

Task performed:

Repaired window

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V70076

In Date: 10/11/2014
Close Date: 11/05/2014

Meter Reading: 100,627.00

Problem?

Officer side window does not roll down from the controls of both the driver side and passenger side. The locking mechanism is no working on the officer side.

Task performed:

Repaired window

Parts

Quantity

NO PARTS USED

Workorder: V70340

In Date: 10/21/2014
Close Date: 11/05/2014

Meter Reading: 101,128.00

Problem?

Rescue has trouble starting.

Task performed:

Checked for codes no codes oil overfilled will send to shop for oil change

Parts

Quantity

NO PARTS USED

Workorder: V70517

In Date: 10/28/2014
Close Date: 11/10/2014

Meter Reading: 101,606.00

Problem?

change engine oil

Task performed:

1. Side door handle broken. Removed and replaced door handle.
2. Repaired rear door latch and tested door.
3. Repaired A/C that was blowing warm.
4. Move vehicle out of my bay. Bring in R-72. Change engine oil. and filter. Check under hood - vis inspection.

Parts

Quantity

15-40B15W40 MOTOR OIL NON SYN
5774457744XD OIL FILTER

30
1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V70827

In Date: 11/10/2014
Close Date: 11/12/2014

Meter Reading: 102,533.00

Problem?
no start

Task performed:

No start-R/R batts tried to start-still no start R/R starter truck started clamed up area.

Parts	Quantity
82000056808 38MT 12T STARTER	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	3
HP-31DBATTERY 950CCA HP-31D	3

Workorder: V69857

In Date: 10/02/2014
Close Date: 11/13/2014

Meter Reading: 59,155.00

Problem?

Two of the three charging stations for the box lights have broken tabs which prevent the lights from locking in making it easy for them to fall off. The charging stations are located in the middle compartment DR side

Task performed:

1. Brakes operating normally. All associated parts of equipment looks and working as manifactory specs. upon hand application. Clunking sound right side. No fault found. In service until further notice.

Parts	Quantity
NO PARTS USED	

2. Replaced broken light box holders

Workorder: V70972

In Date: 11/17/2014
Close Date: 11/19/2014

Meter Reading: 10,358.00

Problem?

Wont build air pressure

Task performed:

1. Went to 72. Found air gov. inoperable. R & R gov. Ran and checked OK. Return home.

Parts	Quantity
284358GOVERNOR D-2	1

Workorder: V71487

In Date: 12/08/2014
Close Date: 12/09/2014

Meter Reading: 104,436.00

Problem?

R72 is running rough, more than normal amount of smoke coming from exhaust. Idles rough.

Task performed:

Travel to 72-checked codes found cylinder pressure abnormal and knocking noise tow to shop for repair.

Parts	Quantity
NO PARTS USED	



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V71580

In Date: 12/11/2014 Meter Reading: 104,436.00
Close Date: 12/11/2014

Problem?

tow r-72 to shop from station 72 10175527

Task performed:

Towed R72 to shop from station 72

Parts

NO PARTS USED

Quantity

Vendor? MOSS TRANSPORTATION

Workorder: V71613

In Date: 12/13/2014 Meter Reading: 104,436.00
Close Date: 01/02/2015

Problem?

remove engine and replace with engine out of old R33 10175530

Task performed:

1. R/R engine transmission and all needed accessories to it
2. Assist with R/R engine
3. Check engine-removed air cleaner tubes and valve cover-removed in harness and high pressure oil rail and found #3 cam lobes damaged. Reinstalled valve spring bridge.
4. Assisted in continuing to install and hook up engine
5. Continued install of engine and all related parts
6. Install engine in R-72
- 7-10. Install engine
11. Assist kevin with above
12. Install engine
13. Install engine continue
14. Found no high idle-traced out wiring on both trucks added and wired to trans harness and check ok
15. Installed oil rail and valve cover

Parts

10008530KNEEL MODULE HORTON
 16-31438915 VALVE CORE A/C 3544706C1
 3544706C1SCHRADER VALVE INT.
 3610318C2RADIATOR HOSE
 3610324C1RAD HOSE

Quantity

1
1
1
1
1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V71732

In Date: 12/18/2014
Close Date: 01/02/2015

Meter Reading: 100,261.00

Problem?

C-inspection

Task performed:

- 1." C" service
2. Assist with above
- 3-4. "C" service
5. Service air dryer-R/R filter and purge valve
6. Torque u-bolts, torque all axle u-bolts
7. Replace engine belt and tensioner for engine belt. Replaced belts and engine tensioner ran and check ok.
8. Found officers seat protection cover off-found snaps damaged repaired snaps-drilled and mounted cover.
9. Check body codes-HVAC door codes-reset doors and check ok. Check fuel sender code-check ok.
10. Found left front tire worn-removed wheel-replaced wheel with used tire from building 3-check ok.
11. Check officers seat mount-tightened tracks-reinstalled bottom cushion-check ok.
12. Engine fan stays on all the time-found air lane leaking. Repaired line-ran and check ok.
13. Rear door air dump inop-repaired magnetic sensor-removed switch and reinstalled and check operation-check ok.
14. Found radio inop-swapped radio with suprlus truck. R/R wiperblades and R/R engine air filter.

Parts

Quantity

065624AD-IP DRIER	1
15-40B15W40 MOTOR OIL NON SYN	30
1847727C1BELT	1
1873217C2BELT TENSIONER	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
46870AIR FILTER	1
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
K022105PURGE VALVE AD-IP-IS	1
K060695BELT	1

Workorder: V72639

In Date: 01/27/2015
Close Date: 01/29/2015

Meter Reading: 105,845.00

Problem?

Replace r/f tire

Task performed:

WORK AS REQUESTED.

Parts

Quantity

NO PARTS USED

Vendor? BLVD TIRE CENTER



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V72154

In Date: 01/09/2015
Close Date: 02/02/2015

Meter Reading: 105,630.00

Problem?
engine miss

Task performed:

1. Went to ST 72. Check oil level - check ok. Ran engine. Engine has miss - ran engine off and engine run tests. #3 injector not firing - regen. fail. Went to ST 73. Return to ST 72. Return to Shop with driver that delivered spare Rescue.

Parts	Quantity
NO PARTS USED	

Workorder: V72258

In Date: 01/12/2015
Close Date: 02/09/2015

Meter Reading: 105,630.00

Problem?
Engine miss R72

Task performed:

1. Removed inner fenders air filter and hoses to access valve cover. Removed valve cover oil rail and injector harness - changed.
2. Injectors, oil rail seals and ICP sensor reinstalled.

Parts	Quantity
1842626C951842626C96 OIL RAIL MANIFOLD SEALS	1
1875784C921875784C93 ICP SENSOR	1
5010561R925010561R93 INJECTOR	6

Workorder: V72979

In Date: 02/09/2015
Close Date: 02/18/2015

Meter Reading:

Problem?
Oil level to high. R72

Task performed:

Travel to ST 72. Changed oil in Rescue 72.

Parts	Quantity
5774457744XD OIL FILTER	1

Workorder: V73142

In Date: 02/13/2015
Close Date: 02/24/2015

Meter Reading:

Problem?
Officer window is OOS. Window control and door lock are also OOS.

Task performed:

Repaired loose connection on door switch.

Parts	Quantity
NO PARTS USED	



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V73289

In Date: 02/20/2015
Close Date: 02/24/2015

Meter Reading:

Problem?

The fluor timer switch thats on the back door of the rescue popped out and will not go back in. Looks like it was glued in place. Th LT side winbdow does not roll down.

Task performed:

Travel to ST 72. Replaced broken switch panel.

Parts

Quantity

03210072SWITCH DUMP/FLOR LT

1

Workorder: V73727

In Date: 03/07/2015
Close Date: 03/24/2015

Meter Reading:

Problem?

Power steering fluid leak. R72

Task performed:

1. Travel to station 72, found P/S fluid low and leak at reservoir hose clamp. Tightened clamp. Topped off reservoir. Clean hose and check leak ok. Check tanker for codes- Found no active and old codes for coolant level. Earsed codes and add small amount of coolant to reservoir.

Parts

Quantity

NO PARTS USED

Workorder: V73835

In Date: 03/12/2015
Close Date: 04/29/2015

Meter Reading: 110,100.00

Problem?

B Inspection R72

Task performed:

B inspection

Parts

Quantity

1878042C91FUEL FILTER 2008 HORTON

1

5774457744XD OIL FILTER

1

Vendor? OCS



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V72657

In Date: 01/27/2015
Close Date: 05/04/2015

Meter Reading:

Problem?

Oxygen sensor alarms despite having full tank. Have to manually silence every time truck is started.

Task performed:

1. Removed sensor parts, gave me wrong sensor, plugged port for now.
2. Replaced O-2 sensor in patient compartment.

Parts	Quantity
10004858O2 SENSOR HORTON 0-3000	2
10012320TRANSDUCER LINE PRESSURE HORTON	1
3544936C6DOOR POD 2 DOOR OFFICER SIDE	1
FRT V27628FREIGHT CHARGES	1

Workorder: V73534

In Date: 03/01/2015
Close Date: 05/04/2015

Meter Reading:

Problem?

can you please have the mechanic install two hooks in the drivers compartment to hang a helmet and jacket. please contact ken druggan on c-shift R72

Task performed:

1. Installed hooks in L2 compartment.

Parts	Quantity
14-7014HGR-1 HELMET HOOK	2

Workorder: V74247

In Date: 03/27/2015
Close Date: 05/04/2015

Meter Reading:

Problem?

Right side fog light out. A/C takes quite some time to cool truck, its working just kinda weak. R72

Task performed:

1. Travel to 72, replaced bulbs in fog lights.

Parts	Quantity
H3-100WBP1210H3 BULB	2

Workorder: V74209

In Date: 03/26/2015
Close Date: 06/04/2015

Meter Reading:

Problem?

The right Fog light is not working , it does not turn on

Task performed:

Parts	Quantity
NO PARTS USED	



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175527

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V72039

In Date: 01/03/2015
Close Date: 06/30/2015

Meter Reading:

Problem?

Headlight bulb replaced out of 73 supply. Please send spare headlight bulb to 73. R72

Task performed:

Parts	Quantity
9007H9007 BULB ASSY	1

Workorder: V72042

In Date: 01/03/2015
Close Date: 06/30/2015

Meter Reading:

Problem?

Outer tread on right front tire is extremely worn. R72

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V73548

In Date: 03/02/2015
Close Date: 06/30/2015

Meter Reading:

Problem?

The right rear outside tire appears to be low. All of the other tires appear to have enough tread but are at different tread levels.

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V74208

In Date: 03/26/2015
Close Date: 07/08/2015

Meter Reading:

Problem?

Passenger side rear view side mirror fell off.

Task performed:

replace mirrior

Parts	Quantity
A22-58516-001MIRROR HEAD	1



Palm Beach County Fire Rescue

Fleet Maintenance Asset History

Asset: (10175527) 2009 - HORTON 4400 Advanced Life Support Vehicle

10175527

CSHOP-2015-1126

Comments: **R72 SPOT LIGHT WILL NOT ROTATE 360 DEGREES SHORELINE A/C UNIT DOES NOT WORK WHEN PLUGGED IN**
Date Opened 6-11-2015 Date Finished 6-16-2015 Meter 1 Reading: 111,683

TASKS PERFORMED

NO PARTS USED

WAIT TIME TO BE CHARGED TO WORK ORDER
TRAVEL TO BE CHARGED TO WORK ORDER
SPOT LIGHTS

CSHOP-2015-116

Date Opened 4-17-2015 Date Finished 4-21-2015 Meter 1 Reading: 111,683

TASKS PERFORMED

Q PARTS

ELECTRICAL

2 BULB; H9007 BULB ASSY

CSHOP-2015-1544

Comments: **R72 AIR SYSTEM HAS A LEAK, LOW AIR ALARM GOES AFTER SITTING FOR TWO HOURS**
Date Opened 7-6-2015 Date Finished 7-9-2015 Meter 1 Reading: 111,683

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

CSHOP-2015-1774

Comments: **R72 AIR LEAK AT AIR BAG OR LEVELING VALVE.**
Date Opened 7-15-2015 Date Finished 7-16-2015 Meter 1 Reading: 111,683

TASKS PERFORMED

Q PARTS

SUSPENSION

2 BRAKE; GY1R11216 AIR BAG INT.

CSHOP-2015-1913

Comments: **R72 TIRES LOW**
Date Opened 7-22-2015 Date Finished 7-22-2015 Meter 1 Reading: 111,683

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? EARL COLVARD BOULEVARD TIRE

Asset Work Order History 10175527

CSHOP-2015-2314

Comments: **REAR SEATBELT NOT FUNCTIONING SHORELINE AC INOP R72**

Date Opened 8-14-2015

Date Finished 10-7-2015

Meter 1 Reading: 122,905

TASKS PERFORMED

NO PARTS USED

SEAT BELTS
AIR CONDITIONING

CSHOP-2015-2810

Comments: **R72 C INSPECTION**

Date Opened 9-9-2015

Date Finished 9-11-2015

Meter 1 Reading: 121,921

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1	STRAP; STRAP
1	FILTER; FUEL FILTER 2008 HORTON
1	FILTER; 24316 WIX CAB A/C FILTER
1	FILTER; 57744XD OIL FILTER
1	STRAP; STRAP
1	STRAP; UTILITY STRAP
1	FILTER; AIR FILTER
1	STRAP; STRAP

Asset Work Order History 10175527

CSHOP-2015-2811

Comments: **PM FOLLOW UP REPAIRS R72 SHORELINE AC INOP**

Date Opened 9-9-2015

Date Finished 9-30-2015

Meter 1 Reading: 165,520

SHORE LINE A/C 10/7

TASKS PERFORMED

	<u>Q</u>	<u>PARTS</u>
STORAGE CABINET EMERGENCY VEH	6	STRUT; GSS1715UV 30LB STRUT GAS
WIPER BLADES	2	WIPER; WIPER BLADE
CAP	1	CAP; 9C3Z8101B RADIATOR CAP 10238 STANT
HOSE LOWER	2	BULB; F36BX-835 LIGHT BULB
HOSE UPPER	1	OXYGEN; OXM1757-01 OXYGEN WRENCH
COOLING SYSTEM	8	FLUID; COOLANT ANTIFREEZE GAL
OIL PAN-GASKET	1	SWITCH; SWITCH DUMP/FLOR LT
LENS	1	DRYER; AD-IP DRIER
LIGHTING SYSTEM	1	VALVE; PURGE VALVE AD-IP-IS
REPAIR FROM PM - AIR SYSTEM	1	DASH LOUVER
CONNECTOR	6	SHOCK; DOOR SHOCK HORTON
WIRING	-6	SHOCK; DOOR SHOCK HORTON
DIAGNOSE ELECTRICAL	2	PLUG; HEADLINER RETAINER PLUG
AIR DRIER	1	FILTER; 18-2699 A/C FILTER
AIR BAG SYSTEM	1	HANDLE; HANDLE LH HORTON
SAFTEY-EMERGENCY EQUIPMENT	6	MEDIC MASTER; HGR-1 HELMET HOOK
INTERIOR TRIM-MOLDINGS-UPHOLS	1	COMPRESSOR; 50-2105 DANHARD COMPRESSOR
HEAD LINER	1	A/C; DANHARD ACCUMULATOR
SEAT FRONT	1	FAN; FAN KIT DANHARD CONDENSER
CAB-INTERIOR ACCESSORIES	1	DRAIN; DRAIN COCK
CABIN AIR FILTER	1	BRAKE; BOLT KIT CARTRIDGE ADIP
EVAPORATOR-EVAPORATOR MOTOR		
DRIVERS AUX FAN		
EVACUATE AND RECHARGE		
A/C COMPRESSOR		
HOSES-LINES & FITTINGS		
AIR CONDITIONING		

CSHOP-2015-3151

Comments: **SHORELINE AC R72**

Date Opened 9-30-2015

Date Finished 10-16-2015

Meter 1 Reading: 123,699

TASKS PERFORMED

	<u>Q</u>	<u>PARTS</u>
TRAVEL TO BE CHARGED TO WORK ORDER	1	CHARGER; CONVERTOR 110V 80 AMP
AIR CONDITIONING		

Service Requests:

09/29/2015

A/C / 12: BROKEN / EXCHANGE - NEW

THE SHORE LINE AC UNIT IS WORKING BUT THE AIR IS NOT COLD IN THE BACK. THE PT AC WHEN THE TRUCK IS UNPLUGGED WORKS FINE.

Asset Work Order History 10175527

CSHOP-2015-3241

Comments: **R72 SEAT BELT IN REAR PASS SIDE INOP**

Date Opened 10-5-2015 Date Finished 10-16-2015 Meter 1 Reading: 123,699

TASKS PERFORMED

Q PARTS

SCBA BRACKETS
SEAT BELTS

1 BELT; SEAT BELT
1 BELT; BELT RECIEVER

Service Requests:

10/05/2015 SEATS / 12: BROKEN / EXCHANGE - NEW
THE SEAT BELT ON THE REAR PASS. SEAT DRIVERS SIDE DOES NOT RETRACT WHEN PUT ON OR TAKEN OFF. THE BELT IS ALL THE WAY OUT AND DOES NOT TIGHTEN UP WHEN A PASS. IS IN THE SEAT.

10/05/2015 BODY / 19: LOOSE / REPAIR
THE AIR PACK BRACKET IN THE DRIVERS COMPARTMENT IS MISSING ALL BUT ONE SCREW AND IS ABOUT TO FALL OFF THE THE DOOR WHERE IT IS MOUNTED.

CSHOP-2015-3246

Comments: **R72 LEANING BAD TO THE LEFT, POSSIBLE AIR BAG ISSUE**

Date Opened 10-5-2015 Date Finished 10-16-2015 Meter 1 Reading: 123,699

TASKS PERFORMED

Q PARTS

WAIT TIME TO BE CHARGED TO WORK ORDER
TRAVEL TO BE CHARGED TO WORK ORDER
REAR SPRING

1 VALVE; CAB AIR LEVEL VALVE INT
2 VALVE; VALVE AIR SUSP HEIGHT CONTROL

Service Requests:

10/05/2015 AIR RIDE / 12: BROKEN / EXCHANGE - NEW
R72 HAS A BAD LEAN TO THE LEFT PASS. SIDE OF THE TRUCK. THE REAR PASS AIRBAG MAY BE LOW.

CSHOP-2015-3493

Comments: **R72 SHORELINE A/C INOP**

Date Opened 10-19-2015 Date Finished 10-30-2015 Meter 1 Reading: 124,765

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
REPAIR FROM PM - O2 SYSTEM
AIR BAG SYSTEM
AIR CONDITIONING

Service Requests:

10/17/2015 A/C / 12: BROKEN / INSPECT
THE SHORE LINE AC UNIT DOES NOT RUN WHEN PLUGGED IN .

10/27/2015 A/C / 12: BROKEN / LUBRICATE
SHORELINE AC DOES NOT WORK WHEN PLUGGED IN

10/27/2015 SERVICE REQUEST / 18: LEAKING / REPAIR
MAIN 02 IS LEAKING

Asset Work Order History 10175527

CSHOP-2015-365

Comments: **OIL OVERFULL R72**

Date Opened 4-30-2015 Date Finished 5-1-2015 Meter 1 Reading: 111,683

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
OIL

CSHOP-2015-3832

Comments: **R72 BLINKER LIGHT BROKEN ANS SHORE LINE INOP**

Date Opened 11-9-2015 Date Finished 12-10-2015 Meter 1 Reading: 127,856

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
AIR CONDITIONING

1 LIGHT; LIGHT

Service Requests:

11/07/2015 LIGHTS / 12: BROKEN / EXCHANGE - NEW
THE LEFT SIDE BLINKER LIGHT NEXT TO THE DRIVERS DOOR IS FALLING OUT. PART OF THE PLASTIC THAT HOLDS IT
IN IS BROKE OFF.

11/07/2015 A/C / 12: BROKEN / INSPECT
THE SHORE LINE AC DOES NOT WORK

CSHOP-2015-4085

Comments: **R72 WATER LEAKING THROUGH DRIVERS SIDE DOOR SEAL**

Date Opened 11-23-2015 Date Finished 1-12-2016 Meter 1 Reading: 129,198

TASKS PERFORMED

Q PARTS

CHARGING SYSTEM
DOOR WEATHER MOLDING

2 HINGE; DOOR HINGES R F
-1 SEAL; DOOR SEAL F
1 SEAL; DOOR SEAL F

Service Requests:

11/20/2015 A/C / 38: SHORTED / RESET BREAKER
SHORELINE AC IS NOT WORKING WHEN PLUGGED IN

11/20/2015 BODY / 18: LEAKING / ADJUSTED DOOR
FRONT DRIVER SIDE DOOR SEAL DOES NOT SEAL AND ALLOWS MASS AMOUNTS OF WATER TO BLOW THROUGH
AND INTO CAB DRENCHING DRIVER WITH WATER

CSHOP-2015-4161

Comments: **CRANKS BUT NO START INTERMITTENT R72**

Date Opened 11-25-2015 Date Finished 12-1-2015 Meter 1 Reading: 127,239

TASKS PERFORMED

Q PARTS

FUEL SYSTEM

1 RELAY; 23-11276-041 RELAY VF28-35F14-Z05

Asset Work Order History 10175527

CSHOP-2015-4391

Comments: **R72**

Date Opened 12-9-2015

Date Finished 12-10-2015

Meter 1 Reading: 127,856

TASKS PERFORMED

NO PARTS USED

CHARGING SYSTEM
DOOR

Service Requests:

12/08/2015 SERVICE REQUEST / 19: LOOSE / REPAIR
STRYKER STRETCHER ON BOARD BATTERY CHARGER IS NOT CHARGING WHEN PLUGGED INTO PT COMPARTMENT
AT ANY TIME WHEN VEHICLE IS RUNNING OR PLUGGED INTO SHORELINE POWER

12/08/2015 BODY / 11: BINDS/STICKS / LUBRICATE
REAR STAIR CHAIR COMPARTMENT DOOR RIGHT LATCH IS STUCK OPEN, LEFT LATCH IS HOLDING DOOR CLOSED.

CSHOP-2015-4562

Comments: **ON-CALL R72 NO START**

Date Opened 12-21-2015

Date Finished 12-21-2015

Meter 1 Reading: 128,555

TASKS PERFORMED

Q PARTS

STARTER
AIR CONDITIONING

1 STARTER; 6808 38MT 12T STARTER
1 FITTING; 16-3408 A/C FITTING LOW SIDE
1 FITTING; 16-3409 A/C FITTING HIGH SIDE

Asset Work Order History 10175527

CSHOP-2015-4667

Comments: **REPAIRS FROM PM R72 A/C ISSUE**

Date Opened 12-28-2015

Date Finished

2-8-2016

Meter 1 Reading:

129,354

TASKS PERFORMED

WIPER BLADES
COOLING SYSTEM
OIL
ENGINE AND ACCESSORIES
LIGHTING SYSTEM
BATTERY
SWITCH-ELECTRICAL
HOSES-LINES & FITTINGS
POWER STEERING PUMP
REAR BRAKE PADS-SHOES
AIR SYSTEM
DOOR HINGE-PINS-BUSHINGS
SEAT FRONT
CAB-INTERIOR ACCESSORIES
A/C BELT REAR A/C
A/C COMPRESSOR
AIR CONDITIONING

Q

PARTS

2 WIPER; WIPER BLADE
1 SEAL; SEAL KIT OIL COOLER
1 COUPLER; COUPLER
1 SEAL; SEAL KIT
1 GASKET; 4988280 GASKET P/S PUMP TO AIR COMP
2 ORING; ORING
1 SENSOR; OIL PRESSURE SENSOR
1 SEAL; SEAL
-1 GASKET; OIL PAN GASKET DT466
1 HOSE; HOSE
1 GASKET; OIL PAN GASKET DT466
1 MOUNT; 4949PA/4962 320 AMP UPGRADE SADDLE MOUNT
1 LIGHT; HEADLITE KIT WITH SEALER
1 LAMP; LAMP
1 LIGHT; 854213 LIGHT GUIDE BUMPER
3 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
3 BATTERY; BATTERY 950CCA HP-31D
1 SWITCH; 19-1045 MASTER SWITCH 175 AMP
1 COOLER; COOLER LINE SUPPLY INT 3810611C4
1 COOLER; COOLER LINE RETURN INT 3810609C4
1 FLUID; P/S FLUID
1 FILTER; 2503221C1 FILTER POWER STEERING
1 GASKET; PS RESV GASKET
2 BRAKE; HD SHOE KIT 3/8 BEAM
2 BRAKE; REAR DRUMS 3757X 3647X
1 DRYER; AD-IP DRIER
1 VALVE; PURGE VALVE AD-IP-IS
1 GOVERNOR; GOVERNOR D-2
2 HINGE; DOOR HINGE REAR
2 HINGE; DOOR HINGE REAR
2 HINGE; DOOR HINGES R F
2 HINGE; DOOR HINGES R F
1 BRAKE; BRK PEDAL PAD
1 COMPRESSOR; 03-0805 A/C COMPRESSOR
1 VALVE; 2512331C1 EXP VALVE NAV
1 DRYER; A/C DRIER NAV
1 NEWPART; A/C HOSE COMPRESSOR TO CONDENSOR
3 FILTER; PANEL FILTER

Service Requests:

12/28/2015 A/C / 18: LEAKING / EXCHANGE - NEW
R72 A/C COMPRESSOR FAILING TO ENGAGE, BLOWING HOT AIR.

12/30/2015 A/C / 12: BROKEN / REPAIR
DRIVER & PASSENGER FRONT COMPARTMENT, AS IS BLOWING HOT, ADDITIONALLY SHORELINE AC DOES NOT WORK WHEN PLUGGED INTO SHORELINE POWER

Asset Work Order History 10175527

CSHOP-2015-4707

Comments: **R72 B SERVICE**

Date Opened 12-30-2015 Date Finished 2-4-2016 Meter 1 Reading: 129,354

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FILTER; FUEL FILTER 2008 HORTON
1 FILTER; 24316 WIX CAB A/C FILTER
1 FILTER; 57744XD OIL FILTER

CSHOP-2015-497

Comments: **R72 TROUBLE STARTING THIS MORNING FOG LIGHT OUT**

Date Opened 5-7-2015 Date Finished 5-13-2015 Meter 1 Reading: 111,683

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES

3 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
3 BATTERY; BATTERY 950CCA HP-31D

CSHOP-2015-641

Comments: **LEFT FOG LIGHT INOP R72**

Date Opened 5-14-2015 Date Finished 5-20-2015 Meter 1 Reading: 111,683

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
AUTO-EJECT

2 BULB; LIGHT BULB BP1255/H3 H
2 CHARGER; AUTO EJECT 20 AERO OTL3925

CSHOP-2016-1014

Comments: **R72 WINDOW FELL OUT OF TRACK, 2ND REQUEST FOR A/C**

Date Opened 3-3-2016 Date Finished 3-3-2016 Meter 1 Reading: 131,797

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR CONDITIONING

Service Requests:

03/02/2016 A/C / 18: LEAKING / SWAPPED OUT TRUCK BROKEN A/C LINE
A/C IS NOT BLOWING COLD. SYSTEM MAY NEED TO BE RECHARGED FOR BOTH CAB AND PATIENT COMPARTMENT

03/02/2016 WINDOW / 12: BROKEN / WILL REPAIR AT SHOP
FRONT PASSENGER WINDOW FELL OFF TRACK. WINDOW WILL NOT ROLL UP.

Asset Work Order History 10175527

CSHOP-2016-1167

Date Opened 3-11-2016 Date Finished 3-22-2016 Meter 1 Reading: 131,800

TASKS PERFORMED

Q PARTS

REAR DOOR SEAL	2	BULB; BULB
DOMELIGHTS	1	BULB; BULB
WINDOW REGULATOR	1	BULB; LAMP BULB
AIR CONDITIONING	1	WINDOW REGULATOR
	1	NEWPART; R/H WINDOW GLASS
	2	A/C; FREON LB
	2	FITTING; 08-6963BS FITTING A/C
	1	FITTING; 08-6933BS A/C FITTING STEEL
	1	LIGHT; LOUVER AC HORTON UV LIGHT
	1	COMPRESSOR; 50-2105 DANHARD COMPRESSOR
	1	TUBE; 3018 ORIFICE TUBE GREEN
	1	NEWPART; HOSE & FITTING
	1	A/C; DANHARD ACCUMULATOR
	1	NEWPART; HOSE & FITTING

CSHOP-2016-1601

Date Opened 4-4-2016 Date Finished 4-7-2016 Meter 1 Reading: 132,264

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
DOOR STRIKER PLATE

Service Requests:

04/04/2016 LIGHTS / 12: BROKEN / REPAIR
FRONT PASSENGER SIDE FOG LIGHT NEEDS REPLACING

04/04/2016 HAZARD / 12: BROKEN / EXCHANGE - NEW
SKID PLATE THAT COVERS BOLT THAT IS USED TO LOCK REAR PT COMPARTMENT DOORS IS MISSING. BOLT IS ON THE FLOOR ONCE YOU OPEN THE DOUBLE REAR DOORS OF THE RESCUE.

CSHOP-2016-1648

Comments: **R72**

Date Opened 4-7-2016 Date Finished 4-19-2016 Meter 1 Reading: 132,764

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	1	FILTER; 57744XD OIL FILTER
OIL		
STARTER		
CHARGING SYSTEM		

Service Requests:

04/07/2016 STARTER / 43: WEAK / INSPECT
TRUCK WILL NOT START

04/14/2016 OIL / 20: LUBE/OIL SOAKED / INSPECT
R72 OIL LEVEL IS ABOVE THE FULL LINE.

04/19/2016 SERVICE REQUEST / 23: NOT CONNECTED / EXCHANGE - NEW
SEEMS TO NOT CHARGE FROM SHORELINE

Asset Work Order History 10175527

CSHOP-2016-2001

Comments: **R72 NO START**

Date Opened 4-27-2016 Date Finished 4-29-2016 Meter 1 Reading: 133,278

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES

2 RELAY; 23-11276-041 RELAY VF28-35F14-Z05

CSHOP-2016-2164

Comments: **R72**

Date Opened 5-5-2016 Date Finished 5-18-2016 Meter 1 Reading: 134,350

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
STARTER RELAY-SOLENOID

1 CONNECTOR; 1PGK4 CONNECTOR 120V 20A FEMALE

Service Requests:

05/05/2016 ENGINE / 12: BROKEN / EXCHANGE - NEW
RESCUE 72 WILL NOT START.

CSHOP-2016-2196

Comments: **R72 WONT START AT HOSPITAL**

Date Opened 5-6-2016 Date Finished 5-6-2016 Meter 1 Reading: 133,652

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

CSHOP-2016-2914

Comments: **R72**

Date Opened 6-17-2016 Date Finished 8-17-2016 Meter 1 Reading: 139,525

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AUTO-EJECT

1 SWITCH; 82-2106 TOGGLE GUARD
1 COVER; OVAL AUTO EJECT COVER

Service Requests:

06/17/2016 BODY / 18: LEAKING / REPAIR
SHORELINE HINGED COVER BROKEN

Asset Work Order History 10175527

CSHOP-2016-3019

Comments: **R72**

Date Opened 6-23-2016

Date Finished

12-7-2016

Meter 1 Reading:

142,751

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SPOT LIGHTS
LIGHTING SYSTEM
FRONT TIRES

3 GASKET; 14023 GASKET 6 IN
12 NEWPART; MOTOR OIL

Service Requests:

11/23/2016 LIGHTS / 12: BROKEN / EXCHANGE - USED
THE JOY STICK TO MOVE THE SPOTLIGHT ON TOP OF THE TRUCK BROKE OFF. THE LIGHT CANNOT BE MOVED BUT DOES COME ON.

06/22/2016 LIGHTS / 49: CAN NOT DUPLICATE CONCERN / INSPECT
PASSENGER SIDE AUX FOG LAMP BULB BURNED OUT/NOT WORKING

CSHOP-2016-3295

Comments: **R72**

Date Opened 7-7-2016

Date Finished

9-13-2016

Meter 1 Reading:

140,653

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM
FLUID
GRILLE

1 BULB; LIGHT BULB BP1255/H3 H
6 FLUID; 50-50 EXTENDED LIFE COOLANT GAL
1 ASSEMBLY; GRILLE ASSY FIXED

Service Requests:

07/06/2016 SERVICE REQUEST / 12: BROKEN / REPAIR
SMALL TRANSMISSION FLUID LEAK

07/16/2016 BODY / 12: BROKEN / REPAIR
THE FRONT GRILL IS BROKE OFF IN THE TOP LEFT HAND CORNER .

07/16/2016 LIGHTS / 12: BROKEN / REPAIR
THE FRONT FOG LIGHT IS OUT

07/25/2016 BODY / 12: BROKEN / REPAIR
FRONT GRILL BROKEN IN SEVERAL LOCATIONS

08/22/2016 BODY / 19: LOOSE / REPAIR
REAR DOORS FOLDING STEP ON DRIVERS SIDE HINGE BOLTS ARE LOOSE

Asset Work Order History 10175527

CSHOP-2016-3577

Comments: **R72**

Date Opened 7-27-2016

Date Finished 7-29-2016

Meter 1 Reading: 138,555

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM
DIAGNOSE ELECTRICAL
AIR CONDITIONING

3 A/C; FREON LB

Service Requests:

07/25/2016

STARTER / 19: LOOSE / REPAIR
SHORELINE CHARGING SYSTEM BROKEN. GFI NOT RESETTING.

CSHOP-2016-3622

Comments: **R72 WONT START**

Date Opened 7-29-2016

Date Finished 7-30-2016

Meter 1 Reading: 138,674

WON`T START

TASKS PERFORMED

NO PARTS USED

DIAGNOSTIC TEST

1 FILTER; FUEL FILTER 2008 HORTON
-1 FILTER; FUEL FILTER 2008 HORTON

CSHOP-2016-3816

Comments: **R72 STRIKER COVER BROKEN**

Date Opened 8-5-2016

Date Finished 8-16-2016

Meter 1 Reading: 139,461

TASKS PERFORMED

NO PARTS USED

DOOR STRIKER PLATE

Service Requests:

08/05/2016

DOOR / 12: BROKEN / REPAIR
METAL TAB AT BOTTOM OF LEFT REAR DOOR THAT PROTECTS PIN OF LOCKING MECHANISM FROM GETTING
SNAGGED BROKE OFF

Asset Work Order History 10175527

CSHOP-2016-4211

Date Opened 8-26-2016

Date Finished

10-24-2016

Meter 1 Reading:

140,883

TASKS PERFORMED

ENGINE COOLANT TEMPERATURE SE
THERMOSTAT
FAN
BY-PASS HOSES
EGR COOLER
INTAKE MANIFOLD
FAULT CODE
REPAIR FROM PM - REAR A/C
AUTO-EJECT
SUSPENSION
AIR DRIER
AIR SYSTEM
GRILLE
STEPS
BODY EXTERIOR
SEAT TRACK ASSEMBLY
CAB-INTERIOR ACCESSORIES

Q PARTS

30	MOTOR; 15W40 MOTOR OIL NON SYN
2	FLUID; P/S FLUID
1	CAP; 9C3Z8101B RADIATOR CAP 10238 STANT
1	THERMOSTAT; 1842130C3 THERMOSTAT DT466
1	NEWPART; FAN CLUTCH
2	CLAMP; CLAMP
2	CLAMP; CLAMPS TURBO
1	BELT; BELT
2	VALVE; 8211237 HEATER VALVE
1	VALVE; EGR VALVE
1	MANIFOLD; SENSOR MANIFOLD AIR TEMP MAT
1	SENSOR; SENSOR MAP
1	COOLER; COOLER EGR KIT 330MM EXH SIDE OLD 1876261C98
1	HOSE; HOSE KIT
1	COOLER; KIT EGR COOLER COLD SIDE OLD 1876262C96
1	ASSEMBLY; HOUSING ASSY INTAKE THROTTLE
1	SEAL; SEAL
3	CLAMP; CLAMPS
1	PUMP; 1882259C94 HIGH PRESSURE OIL PUMP
1	FILTER; FUEL FILTER 2008 HORTON
1	FILTER; SEAL FUEL FILTER HSG
6	INJECTOR; 5010561R93 INJECTOR
1	FILTER; 57744XD OIL FILTER
2	FLUID; P/S FLUID
1	DRYER; AD-IP DRIER
6	SLEEVE; FUEL LINE SLEEVE INT
1	ADAPTER; INJ PUCK ADAPTER
1	SEAL; 1842626C96 OIL RAIL MANIFOLD SEALS
1	PUMP; 1893940C93 OIL LINE HIGH PRESS PUMP
1	FITTING; FUEL FITTING
1	VALVE; PURGE VALVE AD-IP-IS
1	SENSOR; 1875784C93 ICP SENSOR
1	NEWPART; HOSE & FITTINGS
2	COUPLER; COUPLER
1	MANIFOLD; 03-3673 COMP USE 5591 MANIFOLD
1	DRYER; 07-0602A DRIER A/C 7118
1	NEWPART; HOSE & FITTING
1	VALVE; 1608 2 1/2 TON VALVE EXPANSION
2	NEWPART; A/C FLASH FLUSH SUPER COOL
2	VALVE; VALVE AIR SUSP HEIGHT CONTROL
1	COMPRESSOR; AIR COMPRESSOR 3596420C91 3663597C9
1	VALVE; VALVE THROTTLE FOOT
1	GASKET; COMP MOUNT GASKET
1	SENSOR; OIL PRESSURE SENSOR
1	COMPRESSOR; LINE OIL FEED COMPRESSOR INT.
1	GOVERNOR; GOVERNOR D-2
2	FILTER; PANEL FILTER

Asset Work Order History 10175527

Service Requests:

- 08/26/2016 ENGINE / 12: BROKEN / EXCHANGE - NEW
YELLOW WARNING TRIANGLE CAME ON WITH MESSAGE " WARN ENGINE" WHILE EN ROUTE TO HOSPITAL TONIGHT. ALL GAUGES READ NORMAL BUT ENGINE SMELLED HOT UPON ARRIVAL AT HOSPITAL. SHUT ENGINE OFF UNTIL DONE WITH CALL AND WARNING WAS GONE
 - 08/29/2016 AIR RIDE / 18: LEAKING / EXCHANGE - NEW
TRUCKS REAR SEEMS TO BOTTOM OUT A LOT MORE ON BUMPS
 - 08/29/2016 TIRES / 17: INSUFFICIENT LUBRICANT / INSPECT
BAD TIRES, RIGHT FRONT TIRE HAS LOWER THREAD THEN ALL OTHERS
 - 09/01/2016 SERVICE REQUEST / 11: BINDS/STICKS / LUBRICATE
THE SHORE POWER HOOKUP ON THE VEHICLE WILL INTERMITTENTLY GET STUCK. WHEN IT GETS STUCK YOU CANNOT PLUG INTO THE VEHICLE WITHOUT MANUALLY PUSHING IN THE MIDDLE TAB ON THE VEHICLES CONNECTOR.
-

CSHOP-2016-4917

Date Opened 10-16-2016 Date Finished 10-17-2016 Meter 1 Reading: 140,883

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES

1 FILTER; FUEL FILTER 2008 HORTON

Service Requests:

- 10/16/2016 ENGINE / 48: LOW PRESSURE / INSPECT
-

CSHOP-2016-4941

Comments: **R72**

Date Opened 10-17-2016 Date Finished 11-2-2016 Meter 1 Reading: 140,883

TASKS PERFORMED

Q PARTS

A INSPECTION
STORAGE CABINET EMERGENCY VEH
REAR DOOR
DOME LIGHTS
DIAGNOSE ELECTRICAL
REAR SPRING

1 LATCH; M1-63-8 LATCH STAINLESS
2 SLIDE; L/H W LOCK SLIDE 500 LBS
3 NEWPART; LED LITE KIT
1 LIGHT; FOG LIGHTS
3 SOLENOID; SOLENOID AIR DUMP INT
1 VALVE; CHECK VALVE INT

Service Requests:

- 10/15/2016 LIGHTS / 12: BROKEN / REPAIR
VEHICLE LIGHTS NOT WORKING- THE FOG LIGHTS ARE BOTH OUT.
 - 10/15/2016 AIR RIDE / 12: BROKEN / REPAIR
AIR RIDE ISSUE- THERE IS A LEAK IN THE AIR SYSTEM. IF LEFT TO SIT FOR 1 HOUR OR MORE THE AIR SYSTEM IS EMPTY AND YOU HAVE TO RUN THE TRUCK AT HIGH IDEL. THE AIR SYSTEM IS EMPTY BELOW 10PSI.
-

Asset Work Order History 10175527

CSHOP-2016-5225

Comments: **REPLACE REAR DOOR HANDLE**

Date Opened 11-4-2016 Date Finished 11-4-2016 Meter 1 Reading: 141,122

TASKS PERFORMED

Q PARTS

BODY EXTERIOR
DOOR HANDLES INSIDE-OUTSIDE

1 HANDLE; TM22676-02 HANDLE DOOR ENTRY

CSHOP-2016-5293

Comments: **R72**

Date Opened 11-10-2016 Date Finished 11-18-2016 Meter 1 Reading: 141,460

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM

Service Requests:

11/10/2016 RADIATOR / 18: LEAKING / REPAIR
RADIATOR LEAKING, COOLANT IS FOUND ON THE FLOOR OF THE BAY EVERY SHIFT

11/10/2016 SERVICE REQUEST / 12: BROKEN / REPAIR
SHORELINE FEMALE PLUGS BROKEN.

CSHOP-2016-5377

Comments: **C INSPECTION R72**

Date Opened 11-17-2016 Date Finished 12-2-2016 Meter 1 Reading: 142,486

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

24 NEWPART; MOTOR OIL

Service Requests:

11/15/2016 ENGINE / 12: BROKEN / REPAIR
ENGINE , TOO MUCH OIL

CSHOP-2016-777

Comments: **INSTALL NEW STRETCHER R72**

Date Opened 2-18-2016 Date Finished 3-2-2016 Meter 1 Reading: 131,797

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
STRETCHER

1 STRAP; RATCHET STRAP
3 NEWPART; STRIKER BAR/RAIL ASSY

Service Requests:

02/18/2016 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
THE STRETCHER IS SLOW TO RETRACT WHEN GOING TO LOAD THE PT INTO THE TRUCK. WE HAVE EITHER HAD TO KICK THE LOWER GEAR OR SOMEONE HAS TO PULL IT UP BEFORE THE HYDRAULICS KICK IN.

Asset Work Order History 10175527

CSHOP-2016-936

Comments: **R72**

Date Opened 2-29-2016 Date Finished 3-2-2016 Meter 1 Reading: 131,797

TASKS PERFORMED

NO PARTS USED

WAIT TIME TO BE CHARGED TO WORK ORDER
TRAVEL TO BE CHARGED TO WORK ORDER
WINDOW REGULATOR

Service Requests:

02/28/2016 DOOR / 12: BROKEN / REPAIRED WINDOW
OFFICER POWER WINDOW DROPPED WHEN RAISING UP, NOT OPERATING

CSHOP-2016-937

Comments: **ON-CALL R72 BATTERY SWITCH**

Date Opened 2-29-2016 Date Finished 3-9-2016 Meter 1 Reading: 131,797

TASKS PERFORMED

Q PARTS

IGNITION SYSTEM

1 SWITCH; 19-1045 MASTER SWITCH 175 AMP

Service Requests:

02/27/2016 ENGINE / 12: BROKEN / EXCHANGE - NEW
THE BATTERY SWITCH WILL NOT GO TO THE OFF POSITION THE BATTERY SWITCH STAYS ON AT ALL TIMES.

CSHOP-2017-207

Date Opened 1-10-2017 Date Finished 1-13-2017 Meter 1 Reading: 144,725

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

1 VALVE; VALVE AIR CONTROL

CSHOP-2017-497

Date Opened 1-23-2017 Date Finished 1-30-2017 Meter 1 Reading: 144,725

TASKS PERFORMED

Q PARTS

FUEL SYSTEM
SAFTEY-EMERGENCY EQUIPMENT

1 MODULE; GENERIC CANBUS VIB
1 NAF; BLUE DEF 2.5 GAL
1 EMBLEM; FRONT AND BACK PLACARD
2 EMBLEM; LARGE SIDE PLACARD
1 NEWPART; STRIKER BAR/RAIL ASSY
3 KNOB; RED KNOB

Asset Work Order History 10175527

CSHOP-2017-7

Comments: **R-72 BATTERY SWITCH NOT SHUTTING BATTERIES OFF**

Date Opened 1-3-2017

Date Finished 1-4-2017

Meter 1 Reading: 144,246

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
SWITCH-ELECTRICAL
DIAGNOSE ELECTRICAL

Service Requests:

01/02/2017

SERVICE REQUEST / 38: SHORTED / REPLACE NEW

VEHICLE BATTERY WILL NOT SHUT OFF WHEN BATTERY POWER SWITCH IS TURNED OFF.
