



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V030

In Date: 01/01/1900
Close Date: 10/07/2005

Meter Reading:

Problem?

air leak re-37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V150

In Date: 10/12/2005
Close Date: 10/17/2005

Meter Reading: 22,184.00

Problem?

D/SIDE SPOT LIGHT INOP, RE-37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V839

In Date: 12/08/2005
Close Date: 12/21/2005

Meter Reading:

Problem?

BOTH SUN VISORS LOOSE, RE-37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1086

In Date: 01/03/2006
Close Date: 01/06/2006

Meter Reading:

Problem?

ENGINE BELTS MAKING NOISE, RE-37

Task performed:

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V1050

In Date: 12/29/2005
Close Date: 01/09/2006

Meter Reading:

Problem?

NEED HURST HYD, FLUID, NEED LARGE CO2 EXTINGUISHER, RE-37

Task performed:

Parts	Quantity
180R002HURST HYD. FLUID QT	6
MTR3040VM-200 GUAGE DIGITAL AMP	1

Workorder: V1137

In Date: 01/09/2006
Close Date: 01/20/2006

Meter Reading:

Problem?

RED LENS ON FRONT LIGHT BAR BROKEN RE-37

Task performed:

Parts	Quantity
AMH-1AMH-1 VALVE EXTENSION	1

Workorder: V1379

In Date: 01/31/2006
Close Date: 02/08/2006

Meter Reading:

Problem?

FOAM REFILL INOP, RE-37

Task performed:

Parts	Quantity
6807200216DOOR CHECK ASSY	2

Workorder: V1423

In Date: 02/06/2006
Close Date: 02/24/2006

Meter Reading:

Problem?

R/REAR HUB CAP FELL OFF ENROUTE TO CALL NEED NEW ONE, RE-37

Task performed:

Parts	Quantity
6256RJN6256RJN NUT-OUTER/RIGHT	2
AMH-1AMH-1 VALVE EXTENSION	1
H1422TSX STUD	2
N251N252 WHEEL COVERS FRONT + REAR FOR ENGINE	1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V1484

In Date: 02/13/2006
Close Date: 02/28/2006

Meter Reading:

Problem?

HURST POWER UNIT WILL NOT RUN, RE-37

Task performed:

Parts

Quantity

3530033USE 353R222 HOSE HURST SWIVEL/ORING

4

Workorder: V1950

In Date: 03/24/2006
Close Date: 04/05/2006

Meter Reading:

Problem?

MED COMPARTMENT LEAKING WATER, RE-37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2065

In Date: 04/03/2006
Close Date: 04/05/2006

Meter Reading:

Problem?

HANDLIGHT INOP, RE-37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2203

In Date: 04/11/2006
Close Date: 04/26/2006

Meter Reading:

Problem?

INSTALL STRAP FOR SUSCTION STRAINER, RE-37

Task performed:

Parts

Quantity

UMVS254411STRAP 46 IN

2



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V2427

In Date: 05/01/2006

Meter Reading:

Close Date: 05/12/2006

Problem?

2 DISCHARGE DRAIN HOSES FELL OFF, RE-37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2528

In Date: 05/08/2006

Meter Reading:

Close Date: 05/17/2006

Problem?

SPOT LIGHT ON R/SIDE PUMP PANEL INOP, E-37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2580

In Date: 05/12/2006

Meter Reading:

Close Date: 06/09/2006

Problem?

LIGHT BOX ON OFFICER SIDE INOP, RE-37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2818

In Date: 06/01/2006

Meter Reading:

Close Date: 06/09/2006

Problem?

PRECONNECT GAUGE CRACKED, FOAM TANK FULL OF WATER, RE-37

Task performed:

Parts

Quantity

3320-0027CHECK VALVE 1/2 FOAMPRO

1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V2903

In Date: 06/08/2006

Meter Reading:

Close Date: 06/13/2006

Problem?

LATCH ON EXTRICATION COMPT, DOOR LOOSE, RE-37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2992

In Date: 06/14/2006

Meter Reading:

Close Date: 06/23/2006

Problem?

LIGHT BOX OFFICERS SIDE MISSING BOLT FOR STRAP, CHECK ROTATING LENS E-37

Task performed:

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V3062

In Date: 06/20/2006

Close Date: 07/03/2006

Meter Reading: 26,297.00

Problem?

B INSPECTION, RE-37

Task performed:

Parts

Quantity



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

038-1010-01HALE RELIEF VALVE W/ VULCANIZED SEAT	1
038-1550-00VALVE CHECK HALE 1/4"	1
040-1160-03-00 RING SEAL	1
042002000SPRING RELIEF VALVE HALE	1
0460130000DIAPHRAM PM/PMD	1
048009000SPEEDCOUNTER PUMP PANEL	1
064615900006-46159-001 SWITCH WIPER	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1156BULB	2
18-29935-001RH DOOR LATCH NEW	1
18-45484-000LATCH L/H	1
200054014LENS GREEN	1
265777HOSE AND FITTING	1
265797HOSE AND FITTINGS	1
35200-RLIGHT MARKER LED RED	1
4300-505PUMP FLOJET 12V	1
52-24WIPER BLADES ANCO 24	2
5460990500GASKET SEAL KIT P25/30	2
6806970098SEAL DOOR	1
7460967AIR FILTER 17210-ZE2-515 HONDA	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
91513AMBER LENS	2
9440BELT	1
9480BELT	1
A0631087000CABLE BATT. POS.	1
A0631088000CABLE BATT. NEG.	1
A1834388003MOLD R/H	2
BCPR5ESSPARK PLUGS 6130	1
CA8193AIR FILTER 46744 WIX	1
E-600013-3052 NUT	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HA24044HA24044 DOOR HOLDOPEN	4
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
IMMF11361SEAT BELT P/S	1
K080716BELT	1
PR338324070 WIX FILTER WATER	1
PVG-KITORING KIT	1
R90PFILTER FUEL 33231	1
SPRFL80WIPER MOTOR	1
VML-S1414FILTER P/S	1
VML-T1264GASKET P/S COVER	1
VML-T1279WASHER P/S	1



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

WL2000WLA200-A00 WATER TANKVISION OLD FERR # 35

1

Vendor? CENT0002

Workorder: V3135

In Date: 06/26/2006
Close Date: 07/31/2006

Meter Reading:

Problem?

Hand light bulb inop RE 37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3327

In Date: 07/07/2006
Close Date: 07/31/2006

Meter Reading:

Problem?

NEED MOUNTING BRAKET FOR SLEDGE HAMMER RE37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3646

In Date: 07/26/2006
Close Date: 07/31/2006

Meter Reading:

Problem?

RE37 REAR SCENE LIGHT OUT.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3769

In Date: 08/03/2006
Close Date: 08/21/2006

Meter Reading:

Problem?

(1)DRIVER DOOR LATCH NOT WORKING (2) REMOUNT BRACKET FOR PORTABLE MONITOR INTO THE R-REAR COMPARTMENTre37

Task performed:

Parts

Quantity

6807600070HANDLE DOOR EXT L/H

1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V4007

In Date: 08/18/2006
Close Date: 08/23/2006

Meter Reading:

Problem?

DURING FRIDAY CHECK OUT ON RE37 THE ON BOARD FOAM DOES NOT SEEM TO BE PUTTING OUT ENOUGH FOAM.ATTEMPTED TO FLUSH LINES BUT DID NOT HELP.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V4137

In Date: 08/27/2006
Close Date: 09/01/2006

Meter Reading:

Problem?

LEFT REAR TOP LIGHT NEEDS NEW BULB RE 37

Task performed:

Parts

Quantity

H50SN12BULB

1

Workorder: V4258

In Date: 09/05/2006
Close Date: 09/12/2006

Meter Reading: 21,327.00

Problem?

LEFT REAR TURN SIGNAL 10-7 RE37

Task performed:

Parts

Quantity

20X2136STUD

4

921LIGHT BULB

1

E-600013-3052 NUT

3

R004961ANUT ROTOR/HUB

5

S2R7017173USE KIT15625PM BRAKE PAD

2

STOPSN12BULB STOP/TAIL LIGHT

1

Workorder: V4464

In Date: 09/15/2006
Close Date: 10/05/2006

Meter Reading: 2,957.50

Problem?

throttle cable on pump panel broken. not locking. needs repair. E-37

Task performed:

Parts

Quantity

1. TRAVELED TO STN 37. REPLACED PUMP THROTTLE AND REPAIRED TRAFFIC ADVISOR. NOW IN GOOD WORKING ORDER.

01068234000CTACTLD1 CONTROL PANEL TRAFFIC

1

55790-135000008 ELECTRONIC THROTTLE 100076 FELS

1



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V4634

In Date: 09/28/2006
Close Date: 10/06/2006

Meter Reading: 2,994.70

Problem?

SEVERE FUEL LEAK E-37

Task performed:

1. TRAVELED TO STN 37. FOUND LIFT PUMP LEAKING, REFERED PROBLEM TO CUMMINS FOR REPAIR.

Parts

NO PARTS USED

Quantity

Workorder: V4820

In Date: 10/06/2006
Close Date: 10/06/2006

Meter Reading: 27,965.00

Problem?

On-Call Compartment warning going off RE37

Task performed:

COMPT WARNING GOING OFF

Parts

52-624SWITCH DOOR

Quantity

1

Workorder: V4152

In Date: 08/28/2006
Close Date: 10/26/2006

Meter Reading:

Problem?

rear scene light driver side burned out. RE37

Task performed:

1. TRAVELED TO STN 37. REPAIRED BAD GROUND ON SCENE LIGHT.

Parts

NO PARTS USED

Quantity

Workorder: V4662

In Date: 09/29/2006
Close Date: 10/26/2006

Meter Reading: 2,994.70

Problem?

WHILE RE37 IS AT THE SHOP COULD SOMEONE CHECK OUT THE BRAKES. I was told this morning by B. Maury that they need to be looked at. Thanks

Task performed:

1. TRAVELED TO STN 37. REPLACED FOOT BRAKE VALVE. ROAD TEST VEHICLE. BRAKES IN GOOD WORKING ORDER.

Parts

286171XUSE NEW FOOT VALVE REBUILT

Quantity

1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V5069

In Date: 10/24/2006
Close Date: 11/03/2006

Meter Reading: 3,004.50

Problem?

two strobes out on front lightbar RE37

Task performed:

1. TRAVELED TO STN 37. REPLACED STROBES AND TESTED/OK.

Parts	Quantity
02036141700GTURBO TUBE	2
02036273300 TURBO94 CORNERLINEAR REFLECTOR	2
9UTUBELINEAR REF CORNER	2

Workorder: V4655

In Date: 09/29/2006
Close Date: 11/06/2006

Meter Reading: 27,637.00

Problem?

TOW UNIT FROM STA 37 TO CUMMINS RE37

Task performed:

1. HAD UNIT TOWED TO CUMMINS POWER RIVERIA BEACH.

Parts	Quantity
NO PARTS USED	

Vendor? SISTERS TOWING

Workorder: V5189

In Date: 10/31/2006
Close Date: 11/07/2006

Meter Reading: 3,019.00

Problem?

driver's side lower tailboard emergency flasher out. RE37

Task performed:

1. repair bad ground on lighting system

Parts	Quantity
NO PARTS USED	

Workorder: V4354

In Date: 09/10/2006
Close Date: 11/27/2006

Meter Reading: 27,230.00

Problem?

Left rear blinker out. Top left strobe on light front light bar out. RE37

Task performed:

1. WORK ON THIS WORK ORDER DONE ON WORK ORDER 5356

Parts	Quantity
60R00FRR600 SERIES RED LED W/O FLANGE	1



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V5348

In Date: 11/10/2006

Meter Reading: 3,043.00

Close Date: 11/27/2006

Problem?

driver seat on engine 37, difficulty in getting belt to release from reel. hard to get slack to secure belt before driving

Task performed:

Parts

Quantity

1. SEAT BELT NOT WORKING RIGHT , FOUND NO PROBLEM

NO PARTS USED

Workorder: V5356

In Date: 11/12/2006

Meter Reading: 3,043.00

Close Date: 11/27/2006

Problem?

LEFT REAR TURN SIGNAL STILL NOT WORKING. NEEDS TO BE REPAIRED OR REPLACE WIRING. E37

Task performed:

Parts

Quantity

1. REWIRE LEFT TURN SIGNAL
2. WORK ORDER 5354 DONE ON THIS WORK ORDEI

NO PARTS USED

Workorder: V5636

In Date: 12/01/2006

Meter Reading: 28,307.00

Close Date: 12/05/2006

Problem?

POSSIBLE AIR BRAKE LEAK AFTER RETURNING FROM CALL. PEDAL SOFT WHEN BRAKE APPLIED. E37

Task performed:

Parts

Quantity

A0048201010SWITCH DOOR

1

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOF

1

Workorder: V5638

In Date: 12/01/2006

Meter Reading: 3,071.00

Close Date: 12/06/2006

Problem?

driver side rear door, interior light swithc on door frame loose, interior lights coming on when door is closed E37

Task performed:

Parts

Quantity

1. TRAVELED TO STN 37. REPLACED DOOR SWITCH

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V6357

In Date: 01/19/2007
Close Date: 01/23/2007

Meter Reading: 29,117.00

Problem?

Drivers and passenger side visers keep falling down obstructing vision. needs repair e37

Task performed:

1. TRAVELED TO STN 37. REPLACED 2 VISOR
RETAINING CLIPS.

Parts

1836267000VISOR RETRN

Quantity

2

Workorder: V6701

In Date: 02/11/2007
Close Date: 02/14/2007

Meter Reading: 3,211.11

Problem?

left front wheel lug covers damaged from sig-4 E37

Task performed:

Covers will be replaced at B Inspection

Parts

NO PARTS USED

Quantity

Workorder: V6860

In Date: 02/20/2007
Close Date: 02/27/2007

Meter Reading: 2,934.20

Problem?

Air conditioner not blowing cold air. re37

Task performed:

1. TRAVELED TO STN 37. INSTALLED NEW BLOWER
SWITCH. TEST/ OK.

Parts

ABPN8332229011-3050 SWITCH BLOWER

Quantity

1

Workorder: V6907

In Date: 02/23/2007
Close Date: 02/27/2007

Meter Reading: 2,934.20

Problem?

rear step light needs new bulb e37

Task performed:

1. TRAVELED TO STN 37. REPAIRED BAD GROUND.
TEST/ OK.

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V7535

In Date: 04/04/2007
Close Date: 04/10/2007

Meter Reading: 3,016.80

Problem?

AIR HORN SOUNDS WEAK AND AT TIMES DOES NOT WORK E37

Task performed:

1. Adjusted air horns
2. Repaired pump throttle
3. Adjusted #3 discharge handle

Parts

NO PARTS USED

Quantity

Workorder: V7644

In Date: 04/11/2007
Close Date: 05/02/2007

Meter Reading: 3,016.80

Problem?

rear a/c intake filter cover missing. need new one

Task performed:

installed new filter

Parts

78R536078R5360M 2PK FILTER AIR COND

Quantity

2

Workorder: V7952

In Date: 04/27/2007
Close Date: 05/02/2007

Meter Reading: 732.00

Problem?

hurst hose leaking. e37

Task performed:

1. Installed new hose on Hurst unit
2. Adj rear cable door latches
3. Adj tank to pump linkage
4. Adj A/C belts

Parts

180R002HURST HYD. FLUID QT

3530016HOSE HURST 16 ORANGE

Quantity

2

2

Workorder: V8164

In Date: 05/09/2007
Close Date: 05/17/2007

Meter Reading: 732.00

Problem?

Siren steering wheel control button needs repaired. E-37

Task performed:

Rep broken wires in steering wheel bottom

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V8082

In Date: 05/03/2007 Meter Reading: 30,968.00
Close Date: 05/18/2007

Problem?

need standard size funnell E37

Task performed:

dropped off funnel

Parts

NO PARTS USED

Quantity

Workorder: V8203

In Date: 05/10/2007 Meter Reading: 732.00
Close Date: 06/05/2007

Problem?

Driver's seatbelt broken. Sometimes unable to pull out to latch. E-37

Task performed:

1. installed glove box holder in cab
2. checked seat belt and repaired

Parts

IMMF11358SEAT BELTS

1

Quantity

Workorder: V9145

In Date: 07/05/2007 Meter Reading: 31,991.00
Close Date: 07/09/2007

Problem?

ON CALL THROTTLE ON PUMP PANEL 10-7

Task performed:

PUMP THROTTLE INOP; REM THROTTLE; RELAY STICKING; REPLACED RELAY

Parts

NO PARTS USED

Quantity

Workorder: V9146

In Date: 07/05/2007 Meter Reading: 31,991.00
Close Date: 07/18/2007

Problem?

PUMP THROTTLE 10-7 E37

Task performed:

1. CHECKED OPERATION OF PUMP THROTTLE AND TESTED -OK.
2. FOAM SYSTEM INOP.- RECALIBRATED FOAM AND TESTED-OK.
3. WATER LEVEL GAUGE NOT READING FULL RECALABRATED WATER GAUGE.

Parts

55790-1350000008 ELECTRONIC THROTTLE 100076 FELS

1

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V9226

In Date: 07/09/2007
Close Date: 07/27/2007

Meter Reading: 3,504.00

Problem?

round red clearance lamp cover missing. needs replacing. lamp also out. E-37

Task performed:

1. Rear dome lights out; replc (3) dome light bulbs
2. Air leak - traced out air leaks
3. Installed new marker light

Parts

Quantity

372000082CHROME MARKER LIGHT MOUNT

1

372000084MARKER LIGHT

2

372000085HARNES FOR MARKER LIGHT

1

Workorder: V9528

In Date: 07/25/2007
Close Date: 07/30/2007

Meter Reading: 32,529.00

Problem?

CHECK ENG LT ON E37

Task performed:

1. Fnd no oil pressure; rem sender & installed new one

Parts

Quantity

3408428OIL SENSOR 4921511 PRESSURE CUMMINS

1

Workorder: 10000

In Date: 08/20/2007
Close Date: 08/24/2007

Meter Reading: 3,539.50

Problem?

rear amber rotating beacon bulb burned out. e37

Task performed:

1. Replc bulb in R-rear rotator
2. A/C making noise; adj A/C belts
3. Chkd problem with relief valve light; adj switch/tested
4. Foam leak; rep foam leak at filter

Parts

Quantity

NO PARTS USED

Workorder: V9830

In Date: 08/11/2007
Close Date: 08/28/2007

Meter Reading: 3,539.50

Problem?

rear globe light officer side is out. E37

Task performed:

1. Replc bulb in R-rear spotlgt
2. Water level gauge inop; recalibrated gauges/test
3. Spotlights at pump panle inop; traced out; fnd bad conn at lights

Parts

Quantity

4537BULB 100W SPOT

2



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V10062

In Date: 08/22/2007
Close Date: 09/17/2007

Meter Reading: 32,529.00

Problem?

A inspection and related repairs E37

Task performed:

A-Inspection

Parts

Quantity

NO PARTS USED

Workorder: V10432

In Date: 09/13/2007
Close Date: 09/27/2007

Meter Reading: 3,620.00

Problem?

several clearance lamps out and need replacing. E37

Task performed:

At shop for B-Inspection

Parts

Quantity

NO PARTS USED

Workorder: V10506

In Date: 09/18/2007
Close Date: 09/27/2007

Meter Reading: 3,633.60

Problem?

AIR HORN NEEDS TO BE REPLACED. REPAIRED NUMEROUS TIMES AND PROBLEM KEEPS HAPPENING E-37

Task performed:

Truck at shop for B-Inspection; fnd there was no problem w/air horns

Parts

Quantity

NO PARTS USED

Workorder: V10507

In Date: 09/18/2007
Close Date: 09/27/2007

Meter Reading: 3,633.60

Problem?

FRONT INTAKE NEEDS TO BE RETROFITTED WITH THREADS THAT DON'T NEED ADAPTER FOR SOFT SLEEVE HOSE E

Task performed:

Truck needs adapter not retrofitting truck

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V10673

In Date: 09/26/2007

Meter Reading: 33,515.00

Close Date: 09/28/2007

Problem?

repair 2 seats E37 (outside agency-central auto trim)

Task performed:

Rep (2) seats - Central auto

Parts

Quantity

NO PARTS USED

Vendor? CENTRAL AUTO



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V10500

In Date: 09/17/2007

Meter Reading: 33,515.00

Close Date: 10/04/2007

Problem?

b inspection and repairs as needed e37

Task performed:

Parts

Quantity



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

1. "B" INSPECTION	038-1550-00VALVE CHECK HALE 1/4"	1
2. SWAPPED OUT OF ON CALL TRUCK	107796DRYER KIT AD9 -NEW	1
3. SERVICE T-CASE	107800VALVE CHECK AD9	1
4. SERVICE DIFF.	1113-8REGULATOR AIR	1
5. SERVICE DRYER	1142BULB	1
6. DISASSEMBLED, CLEANED, PAINTED AND MOUNTED BENCH VISE	1156BULB	2
7. SERVICE P/S	17211ZG98000AIR FILTER HONDA	1
8. REPLACED ENGINE AIR FLITER	200054014LENS GREEN	1
9. SERVICE BATTERIES	35200-YLIGHT MARKER LEDAMBER	1
10. REPLACED BELTS	353R023HURST HOSE W/O SWIVEL	4
11. R/R DASH TO ADJUST DEFROST CABLE	4864JBRALTERNATOR 270 A	1
12. REMOVED REAR LIGHT BAR CONTROL KNOB	5460990500GASKET SEAL KIT P25/30	1
13. REMOVED 2 SEATS TO BE REUPHOLSTERED, REINSTALLED ABOVE SEATS AFTER REPAIR	60R00FRR600 SERIES RED LED W/O FLANGE	1
14. REPLACED BROKEN "T" FITTING IN WINDSHIELD WASHER FLUID LINE. ALSO CLEANED DEBRIS FROM SQUIRTERS	680-10LAMERICAN FLAG W UV CLEAR LEFT	1
15. PAINTED FUEL TANK CAP	680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
16. REPLACE LEFT SIDE STROBE	6806970098SEAL DOOR	1
17. REPLACED BULB FOR RIGHT SIDE PUMP PANEL LIGHT	78R536078R5360M 2PK FILTER AIR COND	1
18. REPLACED BULB IN RIGHT REAR LOWER STEP	800405PURGE VALVE KIT	1
19. REPLACED AND REWIRED SIDE LOWER MARKER LIGHT	91823SWITCH SWT5499 MED MASTER	1
20. REPLACED FLAG STICKERS ON REAR BODY (FOLDED)	9440BELT	1
21. SERVICE GENERATOR	9480BELT	1
22. SERVICED HURST TOOLS	94862PIGTAIL LED MARKER LIGHTS	2
23. R/R DOOR PANEL TO LUBRICATE AND ADJUST INNER DOOR LATCH MECHANISM ON PASSENGER FRONT DOOR	A1834388002MOLD L/H	2
24. REPLACED ALL 4 DOOR TRIMS	A1834388003MOLD R/H	2
25. REPLACED 2 DOOR WEATHERSTRIPS	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	2
26. REPLACED OK TO PUMP LIGHT LENS	BCPR5ESSPARK PLUGS 6130	4
27. REMOVE, CLEAN, RECONNECT AT POS AND NEG BATTERY CONNECTIONS. SHORT POSITIVE BATTERY CABLE FROM FRAME STUD TO AMP SHUNT. (DIRTY/CORRODED)	BPR5ESSPARK PLUG 7734	1
28. REPLACE ALT. (LOW CHARGE CONDITION)	CA8193AIR FILTER 46744 WIX	1
29. REBUILD INTAKE RELIEF VALVE AND REPLACE CHECK VALVE	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
30. R/R PRIMER VALVE ASSEMBLY, OVERHAUL PRIMER VALVE	HP-31DBATTERY 950CCA HP-31D	2
31. INSTALLED PRECONNECT NETS	HPH6349AOIL FILTER 51748	1
32. ADJUST AIR HORN	K080716BELT	1
33. MOUNTED TIC CHARGER IN CAB	PR338324070 WIX FILTER WATER	1
	R90PFILTER FUEL 33231	1
	S638AIR REGULATOR FITTING	1
	SPR-W58-1TEE PLASTIC	1
	VML-S1414FILTER P/S	1
	VML-T1264GASKET P/S COVER	1
	VML-T1279WASHER P/S	1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V4822

In Date: 10/09/2006
Close Date: 10/15/2007

Meter Reading: 27,965.00

Problem?

Burning Smell RE37

Task performed:

Parts

Quantity

1. Burning Smell, inspected brakes all ok, Trans retarder found off
2. Battery box/step latch lubed and cleaned
3. repair wiring for left rear turn signal

NO PARTS USED

Workorder: V11147

In Date: 10/20/2007
Close Date: 10/30/2007

Meter Reading: 3,654.70

Problem?

SPARE BATTERY STRAP FOR THERMAL IMAGING CAMERA BROKEN.E37

Task performed:

Parts

Quantity

1. repair spare battery strap for camera battery

NO PARTS USED

Workorder: V11139

In Date: 10/19/2007
Close Date: 10/31/2007

Meter Reading: 3,654.70

Problem?

need 3 tubes of clear caulking to reseal gaps around passenger side compartment. dive gear and other misc. EMS equipment we due to water leak after rain.

Task performed:

Parts

Quantity

- 1 reseal medical comp

NO PARTS USED

Workorder: V11140

In Date: 10/19/2007
Close Date: 10/31/2007

Meter Reading: 3,654.70

Problem?

unable to tighten passenger side telescoping floodlights at base.E37

Task performed:

Parts

Quantity

1. Remove locking knob and rethreadlight pole and reinstalled knob

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V11410

In Date: 11/03/2007

Meter Reading: 33,717.00

Close Date: 11/13/2007

Problem?

handlight on driver side rear not working E37

Task performed:

Parts

Quantity

1. found no problem with hand lights
2. horn siren button inop-replaced broken wire in horn button
3. checked for water leak found master drain valve leaking-repaired fitting

NO PARTS USED

Workorder: V11600

In Date: 11/14/2007

Meter Reading: 34,304.00

Close Date: 11/29/2007

Problem?

When applying the seat belt on the drivers side the release to pull the strap forward is intermittently locking up . e37

Task performed:

Parts

Quantity

1. Checked problem with seat belt and found no problem.

NO PARTS USED

Workorder: V11789

In Date: 11/28/2007

Meter Reading: 3,720.80

Close Date: 12/06/2007

Problem?

Tractor ABS light is on e37

Task performed:

Parts

Quantity

1. Checked codes found front sencer out of adjustment, adjusted sencer.

NO PARTS USED

Workorder: V11940

In Date: 12/05/2007

Meter Reading: 34,600.00

Close Date: 12/18/2007

Problem?

tractor abs light is coming on in cab E37

Task performed:

Parts

Quantity

1. R+R rear brakes to changes ABS sensor both rear wheels. check and tighten rear wheel bearing .
2. R+R dash controler, R+R A/C dryer to rear.
3. Check all code in engine and ABS and Trans. Clean code on ABS system.

401581GASKET AXLE FL80 R002435

2

47697380003A SEAL REAR HUB RP

2

8201L17-3428 ESTER OIL E7

1

S4410325140R955342 SENSOR REAR ABS 4410328140

2



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V11798

In Date: 11/28/2007

Meter Reading: 3,720.80

Close Date: 12/19/2007

Problem?

Intermittent problem with gauge on discharge #3. Gauge was showing 100 psi even when truck was shut off. Tapped it with screwdriver to fix it. E37

Task performed:

1. Checked problem with guage found no problem with guage.

Parts

NO PARTS USED

Quantity

Workorder: V11942

In Date: 12/06/2007

Meter Reading: 34,600.00

Close Date: 12/21/2007

Problem?

B INSPECTION AND REPAIRS AS NEEDED E37

Task performed:

1. "B" service
2. Service trans. Repair driver door light, wire cut.
3. Torque U-bolts. Repair wire under truck.
4. Tighten alt. and A/C belts. Extended engine blow by tube.
5. Remove and rebuild trans accumulator.
6. Check code in ABS system.

Parts

1229V1504WASHER
 15W40BSYN OIL BULK QTS
 20X2136STUD
 240001240001 CORNER CAP
 2952271729552377 VALVE ASSY.ACCUM
 29526898 29548988 TRANS FILTER ALLISON
 29535973ACCUM.KIT
 372000084MARKER LIGHT
 6256RJN6256RJN NUT-OUTER/RIGHT
 6806890001LOCK DASH
 6808310398SEAL AIR DUCT
 71R755011-2624 TRINARY SWITCH A/C 1560
 74R258607-2613A RED DOT DRIER 7127
 78R536078R5360M 2PK FILTER AIR COND
 ABPN83322930CONTROL HEAD AC/HEAT
 FS1022FILTER FUEL WIX 33422 PS8689 FRAM
 H1422TSX STUD
 HPH6349AOIL FILTER 51748
 R004961ANUT ROTOR/HUB
 R90PFILTER FUEL 33231
 UMVS254411STRAP 46 IN

Quantity

6
21
6
1
1
1
1
1
1
4
1
1
1
1
1
1
1
1
18
1
1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V12138

In Date: 12/19/2007
Close Date: 12/31/2007

Meter Reading: 34,600.00

Problem?

BRAKES SMOKING E-37

Task performed:

Parts

Quantity

1. Road tested and checked brakes found adjustments to tight readjusted.

NO PARTS USED

Workorder: V6915

In Date: 02/23/2007
Close Date: 01/14/2008

Meter Reading: 2,934.20

Problem?

E37 fan switch on A/C in op. Needs to be replaced or fixed

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V8450

In Date: 05/28/2007
Close Date: 01/14/2008

Meter Reading: 364.00

Problem?

rear top clearance lamp by hosebed missing red lens cap. E-37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V12278

In Date: 12/30/2007
Close Date: 01/16/2008

Meter Reading: 3,761.00

Problem?

air leak in system. loses 25 psi in 3 hours while sitting. E37

Task performed:

Parts

Quantity

1. Replaced parking brake valve.

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V12326

In Date: 01/02/2008

Meter Reading: 3,761.00

Close Date: 01/16/2008

Problem?

floodlight on top of lightbar not working. need new bulb. E37

Task performed:

Parts

Quantity

1. Traced out problem with spot light found bad connection.

NO PARTS USED

Workorder: V12328

In Date: 01/03/2008

Meter Reading: 3,761.00

Close Date: 01/16/2008

Problem?

Air leak on truck still leaking Psi drop to 0 in about 4 hours. Atech Tommy worked on yesturday he asked us to follow up with this work order if the problem continued. E37

Task performed:

Parts

Quantity

1. Rechecked and found no leaks.

800034VALVE PARKING BRK.

1

Workorder: V12337

In Date: 01/03/2008

Meter Reading: 3,768.00

Close Date: 01/16/2008

Problem?

transmission would not shift into 5th gear. probably due to extreme cold conditions. (35 degrees). Just wanted it documented. e37

Task performed:

Parts

Quantity

1. Road test truck and found no problem with unit.
2. Rechecked for air leak found none at this time.

NO PARTS USED

Workorder: V12587

In Date: 01/15/2008

Meter Reading: 35,017.00

Close Date: 01/16/2008

Problem?

on call re37 air leak

Task performed:

Parts

Quantity

1. Air leak and alarm going off found fittings leaking and found low coolant alarm going off.

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V12577

In Date: 01/14/2008
Close Date: 01/18/2008

Meter Reading: 3,460.10

Problem?

low air alarm still sounding while driving and stops when the brake pedal is pressed. still has air leak.

Task performed:

- | | <u>Parts</u> | <u>Quantity</u> |
|---|---------------|-----------------|
| 1. Air leak, traced out air leaks and repaired. | NO PARTS USED | |

Workorder: V12433

In Date: 01/08/2008
Close Date: 01/22/2008

Meter Reading: 3,460.10

Problem?

spot light on top of light bar is out E37

Task performed:

- | | <u>Parts</u> | <u>Quantity</u> |
|--|-------------------------|-----------------|
| 1. Installed new spot light. | 620122SPOT LIGHT REMOTE | 1 |
| 2. rear rotator Inop. Repaired broken wires in rear. | | |
| 3. Cab A/C warm, recharged and repaired leaks. | | |

Workorder: V12801

In Date: 01/24/2008
Close Date: 02/04/2008

Meter Reading: 3,460.10

Problem?

We need transmission fluid for e37. We're completely out.

Task performed:

- | | <u>Parts</u> | <u>Quantity</u> |
|----------------------------|---------------|-----------------|
| Dropped off trans fluid. j | NO PARTS USED | |

Workorder: V12802

In Date: 01/24/2008
Close Date: 02/04/2008

Meter Reading: 3,460.10

Problem?

Buzzer sounding intermittently, possibly low on transmission fluid. e37

Task performed:

- | | <u>Parts</u> | <u>Quantity</u> |
|---|---------------|-----------------|
| Trace problem w/alarm going off. disconnected wire for alarm. j | NO PARTS USED | |



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V5008

In Date: 10/22/2006
Close Date: 02/07/2008

Meter Reading: 3,004.50

Problem?

roof mounted spot light is out, and the left indicator is still not working. E-37

Task performed:

Parts ----- Quantity

NO PARTS USED

Workorder: V5434

In Date: 11/17/2006
Close Date: 02/07/2008

Meter Reading: 3,043.00

Problem?

NUMEROUS FIRE EXTINGUISHERS NEED RECHARGING AND TAGGING. DRY CHEM. AS WELL AS CO2.

Task performed:

Parts ----- Quantity

NO PARTS USED

Workorder: V5582

In Date: 11/28/2006
Close Date: 02/07/2008

Meter Reading: 3,071.00

Problem?

ON RE37 THE LARGE INTAKE VALVE INDICATOR LIGHTS ON THE PASSENGER SIDE ARE NOT WORKING. APPEARS TH IT MAY BE A BLOWN FUSE.

Task performed:

Parts ----- Quantity

A0048201010SWITCH DOOR 3

Workorder: V5693

In Date: 12/05/2006
Close Date: 02/07/2008

Meter Reading: 3,071.00

Problem?

need new circle-d light. old fixture has broken fitting, cannot repair. e37

Task performed:

Parts ----- Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V13061

In Date: 02/05/2008

Meter Reading: 3,388.00

Close Date: 02/13/2008

Problem?

Replace the pass side dash map light e37

Task performed:

1. Replaced map light on dash

Parts

01046301700S30HACP STROBE CLEAR

2

LF18TS-LEDMAP LIGHT LED 18 IN

1

Workorder: V13153

In Date: 02/10/2008

Meter Reading: 3,388.00

Close Date: 02/13/2008

Problem?

Air filter dash light is on E37

Task performed:

1. Found bad connection in plug for dash light

Parts

NO PARTS USED

Quantity

Workorder: V12996

In Date: 02/01/2008

Meter Reading: 35,343.00

Close Date: 02/21/2008

Problem?

replace tires at st 37 callaghan

Task performed:

Replace tire at Stn37 - Callaghan

Parts

NO PARTS USED

Quantity

Vendor? CALLAGHAN

Workorder: V13575

In Date: 02/28/2008

Meter Reading: 35,558.00

Close Date: 02/27/2008

Problem?

HURST POWER UNIT LEAKS FOAM PICKUP LEAKS E37

Task performed:

1. Repaired leak on Hurst unit

2. repaired foam pickup that was leaking

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V13542

In Date: 02/27/2008
Close Date: 02/29/2008

Meter Reading: 35,558.00

Problem?

repair saw e37 regans

Task performed:

Repair saw E37 - Regans Small Eng

j

Parts

NO PARTS USED

Quantity

Vendor? REGANS SMALL ENG`

Workorder: V13135

In Date: 02/08/2008
Close Date: 03/04/2008

Meter Reading: 3,388.00

Problem?

Air Filter light activated on E37

Task performed:

1. INSTALLED NEW FILTER.

Parts

22-51374-000SENSOR AIR RESTRICTION

Quantity

1

Workorder: V13758

In Date: 03/08/2008
Close Date: 03/13/2008

Meter Reading: 3,833.00

Problem?

master intake valve light out, braket in eng compartment holding axe broken E37

Task performed:

1. Repaired axe holder that was falling off

Parts

NO PARTS USED

Quantity

Workorder: V13799

In Date: 03/11/2008
Close Date: 03/13/2008

Meter Reading: 35,558.00

Problem?

POWER STEERING FLUID LOW E37

Task performed:

1. Checked for leaks and topped off level

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V13752

In Date: 03/07/2008

Meter Reading: 3,833.00

Close Date: 03/19/2008

Problem?

missing 1 electric fan hook to hang on door jamb hanger. E37 has only 1x road flare left and the station is out of them.

Task performed:

- | Task performed: | Parts | Quantity |
|--|---------------|----------|
| 1. DC will order new hooks for station | NO PARTS USED | |

Workorder: V13685

In Date: 03/04/2008

Meter Reading: 3,833.00

Close Date: 03/20/2008

Problem?

lower officer's side step light out E37

Task performed:

- | Task performed: | Parts | Quantity |
|---|---------------|----------|
| 1. Step light out, repaired bad connection in light | NO PARTS USED | |

Workorder: V12818

In Date: 01/24/2008

Meter Reading: 3,460.10

Close Date: 04/14/2008

Problem?

Driver's side rear rotating beacon emergency light out.

Task performed:

- | Task performed: | Parts | Quantity |
|--|---------------|----------|
| 1. driver side rear rotating beacon emer. light out.
-repaired beacon, bad ground | NO PARTS USED | |

Workorder: V15138

In Date: 05/16/2008

Meter Reading: 3,971.80

Close Date: 06/10/2008

Problem?

Deluge gun rotates on truck and ground monitor. MIV lights do not work. One step light is out on rear of engine. E-37

Task performed:

- | Task performed: | Parts | Quantity |
|---|-----------------------------------|----------|
| 1. Replc both speed sensors; test driv e. | 1156BULB | 2 |
| 2. Replc deluge gun lock. | 1893BULB | 3 |
| 3. Replc (2) rear step light bulbs. | 4921597OUTBOARD SPEED SENSOR | 2 |
| 4. Chk master itnake valve lights; valve needs rebuild. | S976GAUGE AIR USE S986 | 1 |
| j | X170DECK GUN ROTATION LOCK INSERT | 2 |



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V13610

In Date: 02/29/2008

Meter Reading: 3,833.00

Close Date: 06/17/2008

Problem?

fail pump test e37

Task performed:

Parts

Quantity

1. Pump tested truck; also used truck to draft for (2) quints during training. - J. George
2. Assist with above. R. Levy. j

NO PARTS USED

Workorder: V15689

In Date: 06/12/2008

Meter Reading: 37,255.00

Close Date: 07/02/2008

Problem?

screws missing from ahndle on hurst unit e 37

Task performed:

Parts

Quantity

Installed new screw in Hurst handle. j

2150076SCREW

7



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V16031

In Date: 06/27/2008

Meter Reading: 37,631.00

Close Date: 07/10/2008

Problem?

C INSPECTION AND REPAIRS AS NEEDED RE 37

Task performed:

1. C-Inspection
2. Svc T-case
3. Sec loose exh clamp
4. R/R R-rear wheel humb to replc brake spider mounting bolts. (stretched).
5. Svc air brake dryer.
6. Replc all (4) batteries
7. Replc turn sig side marker lenses; rep rear steplight; rep (2) cab roof marker lits & (2) pump panel lits. Replace turn sig side markers lits & (2) pump panel lits; replc (1) pump panel light lens.
8. R/R wiper blades.
9. R/R cab rear A/C filter.
10. Rem traffic advisor knob.
11. Svc P/S.
12. Replc headlight swtch.
13. Replc/rewired triple light on tailboard (right side0.
14. painted fuel cap.
15. Replcd all (4) door weatherstrips. (ripped/torn).
- 16 Replc fuel gauge on pump panel.
17. Trbleshoot master intake relief valve indicator lights inop; traced problem to a completely corroded out inline fuse holder; rewired in a new inline fuse holder frm Class-one power distribution; positive stud back to indicator lights & installed new fuse.
18. Rebuilt intake relief valve.
19. Make new RPM counter cable.
20. Replc rear, lower compt light bulb.
21. Replc belts.
22. Replcd tank recirculator valve (leaking).
23. Swapped out of on-call truck; washed/refueled take home truck.
24. Bobcat traiing.
25. Adj right/left aire horns.
26. Vac tested pump sys; after leak repairs, vac start 24"; vac end 19".
27. Clean shop. j

Parts

Quantity

Parts	Quantity
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1141BULB	1
15W40BSYN OIL BULK QTS	24
2032-0000-30LENS CLEAR	1
23-09114-010WASHER	16
23-09444-225SPIDER BOLTS	8
23-09901-110HEX NUT 5/8	8
301-502301-104 FUEL GAUGE	1
35200-RLIGHT MARKER LED RED	1
380003ASEAL	1
401581GASKET AXLE FL80 R002435	1
52-24WIPER BLADES ANCO 24	4
546126000TPM/QG HALE REPAIR KIT	4
6256RJN6256RJN NUT-OUTER/RIGHT	2
6805400445SWITCH HEADLIGHT	1
6806970098SEAL DOOR	2
800405PURGE VALVE KIT	1
91368904 VALVE KIT 1 1/2 IN	1
91513AMBER LENS	2
9440BELT	1
9480BELT	1
94862PIGTAIL LED MARKER LIGHTS	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	4
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
H1422TSX STUD	2
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
K080716BELT	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
VML-S1414FILTER P/S	1
VML-T1264GASKET P/S COVER	1
VML-T1279WASHER P/S	1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V15992

In Date: 06/25/2008
Close Date: 07/16/2008

Meter Reading: 4,038.80

Problem?

OFFICER'S SCBA SEAT BRACKET CLAMP SNAPPED OFF. E37

Task performed:

Replaced SCBA bracket (broken) j

Parts

KD-UN-5-SFUSE 6-SF BRACKET

Quantity

1

Workorder: V15143

In Date: 05/16/2008
Close Date: 07/17/2008

Meter Reading: 3,971.80

Problem?

rebuild master intake valve(per shop) E37

Task performed:

Above repair fixed during PM Inspection. W/O 16031
j

Parts

NO PARTS USED

Quantity

Workorder: V16921

In Date: 08/08/2008
Close Date: 09/02/2008

Meter Reading: 38,268.00

Problem?

Need a rplacement air chuck for e 37's air hose

Task performed:

Dropped off air chuck for air hose. j

Parts

S506USE 501 GAUGE AIR
S777COUPLING NIPPLE

Quantity

1
3

Workorder: V17231

In Date: 08/21/2008
Close Date: 09/02/2008

Meter Reading: 0.04

Problem?

ONE BULB OUT ON MAIN LIGHTBAR, OFFICER'S SIDE, FRONT FACING. E37

Task performed:

Light out in light bar; fnd no lights out. j

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V17566

In Date: 09/08/2008

Meter Reading: 38,684.00

Close Date: 09/08/2008

Problem?

ON CALL E37 DRAIN CAME OFF WHILE PUMPING

Task performed:

r/r pump discharge line. diagnose foam system failure due to a bad control head.

Parts

NO PARTS USED

Quantity

Workorder: V17685

In Date: 09/13/2008

Meter Reading: 38,684.00

Close Date: 09/29/2008

Problem?

foam came out of air pressure line on E37. Mechanic looked at system and found no problems. No further attention needed.

Task performed:

Foam system secure, no foam coming out of air line. Operate pump all functioning normal at this time.

Parts

NO PARTS USED

Quantity

Workorder: V17851

In Date: 09/22/2008

Meter Reading: 38,684.00

Close Date: 09/29/2008

Problem?

foam system 10-7 e37

Task performed:

test foam system
repair air line to air seat
repair broken wiring on foam fill pump

Parts

168-0380-51USE 168-0380-56-0 OLD CONTROL UNIT HALE

1

Workorder: V17406

In Date: 08/29/2008

Meter Reading: 0.04

Close Date: 09/30/2008

Problem?

On board foam system not working. Problem is intermittent , flushed system. acts as if it is clogged E37

Task performed:

Ran foam system and tested OK

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V17888

In Date: 09/23/2008
Close Date: 10/02/2008

Meter Reading: 38,684.00

Problem?

air saw e37 regan

Task performed:

Air saw E37 - Regan Small Eng j

Parts

NO PARTS USED

Quantity

Vendor? REGANS SMALL ENG

Workorder: V13751

In Date: 03/07/2008
Close Date: 10/17/2008

Meter Reading: 3,833.00

Problem?

driver side pump panel light out and damaged, rear lower OIC side step light out. E37

Task performed:

1. repaired all lights that were out

Parts

NO PARTS USED

Quantity

Workorder: V18139

In Date: 10/06/2008
Close Date: 10/28/2008

Meter Reading: 39,210.00

Problem?

ROOF SPOT LIGHT INOP, E-37

Task performed:

1. Foam sys inop; tested sys & tested ok.
2. Spotlight inop; cld contacts on spotlight relay board.
j

Parts

NO PARTS USED

Quantity

Workorder: V18258

In Date: 10/10/2008
Close Date: 11/07/2008

Meter Reading: 4,181.00

Problem?

Onboard foam system not working. (-) bars appear on foam gauge. e37

Task performed:

1. Gen not running; replc in-line fuel filter.
2. Foam sys inop; tested foam sys & tested Ok. J

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V18406

In Date: 10/18/2008
Close Date: 11/07/2008

Meter Reading: 4,201.00

Problem?

front driverside tire is almost down to wear bars e37

Task performed:

1. Replc (2) front tires.
2. Sun visors falling down; rep sun visor holders.
3. Siren inop from handsfree; rep handsfree button. j

Parts

Quantity

NO PARTS USED

Workorder: V18803

In Date: 11/03/2008
Close Date: 11/18/2008

Meter Reading: 4,219.00

Problem?

driverside compartment door latch is loose E37

Task performed:

- Door not latching; readj door latch. j

Parts

Quantity

NO PARTS USED

Workorder: V19105

In Date: 11/16/2008
Close Date: 12/02/2008

Meter Reading: 4,219.00

Problem?

Unable to start chainsaw. E37

Task performed:

- Swapped out saw w/new one. j

Parts

Quantity

NO PARTS USED

Workorder: V19132

In Date: 11/18/2008
Close Date: 12/02/2008

Meter Reading: 4,219.00

Problem?

Spot light on top of light bar is out E37

Task performed:

1. Spotlight inop; rep bad connection in spotlight.
2. Replaced chain saw.
3. Rear marker lights inop; traced out problem & fnd bad grd. j

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V18730

In Date: 10/30/2008
Close Date: 12/05/2008

Meter Reading: 39,593.00

Problem?
replace front tires e37

Task performed:	Parts	Quantity
replace front tires e37	NO PARTS USED	

Vendor? CALLAGHAN

Workorder: V19310

In Date: 11/24/2008
Close Date: 12/05/2008

Meter Reading: 39,904.00

Problem?
repair saw e 37

Task performed:	Parts	Quantity
repair saw e37	NO PARTS USED	

Vendor? REGANS MOBILE SMALL

Workorder: V19492

In Date: 12/03/2008
Close Date: 12/11/2008

Meter Reading: 4,268.50

Problem?
seat belt buckle on drivers seat not working e37

Task performed:	Parts	Quantity
Replace driver's side seat belt & check operation. j	IMMF11358SEAT BELTS	1

Workorder: V19367

In Date: 11/27/2008
Close Date: 01/05/2009

Meter Reading: 7,807.00

Problem?
Fuel gauge on pump panel only shows 1/4 tank when truck is full E-37

Task performed:	Parts	Quantity
Test fuel gauge; tested ok. j	7605-7235GAUGE FUEL	1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V19547

In Date: 12/05/2008 Meter Reading: 40,233.00
Close Date: 01/05/2009

Problem?

PICK UP AND DELIVER FUEL TO STATION 37 FOR MULE

Task performed:

Parts

Quantity

pickup fuel from Stn31; dropped off at Stn37; fueled up
mule & generator. j

NO PARTS USED

Workorder: V19732

In Date: 12/14/2008 Meter Reading: 4,292.60
Close Date: 01/05/2009

Problem?

Station doesn't have synthetic oil E37 is low.

Task performed:

Parts

Quantity

Dropped off oil at Stn. j

NO PARTS USED

Workorder: V19733

In Date: 12/14/2008 Meter Reading: 4,292.60
Close Date: 01/05/2009

Problem?

air chuck doesn't fit in air hose on E37.

Task performed:

Parts

Quantity

Chkd air chuck; fnd unit working. j

NO PARTS USED

Workorder: V19789

In Date: 12/16/2008 Meter Reading: 4,292.60
Close Date: 01/05/2009

Problem?

air chuck cuplink to pressurise water extinguisher does not fit truck e37

Task performed:

Parts

Quantity

Chkd air adapters & all work. j

7200000050VALVE SS 2IN 720-0000-00-50

1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V19970

In Date: 12/26/2008
Close Date: 01/05/2009

Meter Reading: 4,300.50

Problem?

driver side step light and 1 rear step light out. E-37

Task performed:

Fnd no step lights out. j

Parts

NO PARTS USED

Quantity

Workorder: V20180

In Date: 01/07/2009
Close Date: 01/27/2009

Meter Reading: 4,300.50

Problem?

strobe on top light bar out, chainsaw will not start. e37

Task performed:

1- spot light out, repaired bad connection.

Parts

4537BULB 100W SPOT

7ELTUBE7ELTUBE LINEAR STROBE REF

Quantity

1

1

Workorder: V20353

In Date: 01/14/2009
Close Date: 01/29/2009

Meter Reading: 4,332.00

Problem?

strobe light on light bar of e37 out

Task performed:

1- strobe light out, replaced strobe light.

Parts

7ELTUBE7ELTUBE LINEAR STROBE REF

Quantity

3

Workorder: V20463

In Date: 01/20/2009
Close Date: 02/12/2009

Meter Reading: 40,859.00

Problem?

LOW ON OIL, E-37

Task performed:

1- Low oil, brought oil to sta to top off E-37

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V20086

In Date: 01/02/2009
Close Date: 02/24/2009

Meter Reading: 4,300.50

Problem?

pump on e37 has a slow leak unable to determine where it is coming from, not sure if it is a problem that needs immediate attention or if it can wait till PM

Task performed:

1. Rebuild pressure relief valve.
2. Water leak; tank-to-pump valve leaking; will repair at B-inspection.
3. Relief valve; tested relief valve & tested ok. j

Parts	Quantity
538-1400-00QG VALVE	1
546126000TPM/QG HALE REPAIR KIT	1

Workorder: V20481

In Date: 01/20/2009
Close Date: 02/24/2009

Meter Reading: 4,332.00

Problem?

Front steamer connection cap stripped, won't screw on intake. Would also like request to retrofit this intake on next pm. E-37

Task performed:

- Will have done at B-inspection frnt steamer connection.
j

Parts	Quantity
NO PARTS USED	

Workorder: V20774

In Date: 02/01/2009
Close Date: 02/24/2009

Meter Reading: 4,332.00

Problem?

Need appropriate engine oil for Engine 37.

Task performed:

- Dropped off oil at station. j

Parts	Quantity
NO PARTS USED	

Workorder: V20809

In Date: 02/02/2009
Close Date: 02/24/2009

Meter Reading: 4,332.00

Problem?

charging system is running at 13.3 to 13.8 volts engine keeps kicking to high idle. E37

Task performed:

- Chkd charging sys & tested ok j

Parts	Quantity
NO PARTS USED	



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V21154

In Date: 02/17/2009

Meter Reading:

Close Date: 02/25/2009

Problem?

starter bendix is kicking out engine is not starting e37

Task performed:

Parts

Quantity

1. No start; replcd starter.
2. Adj air horns. j

10461277USE 10461089

1

Workorder: V16081

In Date: 07/01/2008

Meter Reading: 4,038.80

Close Date: 03/02/2009

Problem?

PLEASE RETROFIT THE FRONT INTAKE ON E37 SO ADAPTER NOT NEEDED FOR SOFT SLEEVE HOSE. E37 IS AT THE CENTRAL SHOP NOW FOR PM. MUCHOS GRACIAS.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V19175

In Date: 11/19/2008

Meter Reading: 7,807.00

Close Date: 03/02/2009

Problem?

Audible air leak under unit, midship, center area. R37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V20395

In Date: 01/15/2009

Meter Reading: 4,332.00

Close Date: 03/09/2009

Problem?

THERMAL IMAGING DEVICE SHOWING GHOST IMAGE. OCCURRED AT TRAINING, STILL SHOWING DEFECTIVE IMAGE AFTER TESTING AT STATION 37. NEEDS REPAIRED OR REPLACED. E37

Task performed:

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V21267

In Date: 02/22/2009

Meter Reading:

Close Date: 03/26/2009

Problem?

Main drain valve on driver's side near hose well has moderate leak. E-37

Task performed:

- 1. Mount tools; remount tools in L1.
- 2. Water leak; rep leak at pump area.
- 3. Steplights inop; fnd bad grnd. j

Parts

Quantity

104967DIAPHRAM FOR 6 PORT DUMP VALVE	2
78308930 AKRON 3 IN VALVE	1

Workorder: V21674

In Date: 03/10/2009

Meter Reading: 42,261.10

Close Date: 04/03/2009

Problem?

REPAIR DOME LIGHTS

Task performed:

- 1.Rep rear dome light that was out.
- 2. Rear bench seat not latching; rem latch & rep seat/latch. j

Parts

Quantity

NO PARTS USED

Workorder: V22065

In Date: 03/25/2009

Meter Reading: 42,261.10

Close Date: 04/06/2009

Problem?

pump leaking e 37

Task performed:

- Tank to pump valve leaking; need to be done at B-Inspection. j

Parts

Quantity

NO PARTS USED

Workorder: V22420

In Date: 04/08/2009

Meter Reading: 4,500.00

Close Date: 05/05/2009

Problem?

Need 5" soft sleeve front intake hose replaced. E37's is unsafe, has worn area where fibers are showing.

Task performed:

- DC will order new hose. j

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V23149

In Date: 05/08/2009
Close Date: 05/21/2009

Meter Reading: 4,500.00

Problem?

back left compartment tray will not lock into place. Eng/37

Task performed:

Rep rear tray that was not closing. j

Parts

Quantity

101281011GSS6297UM 60# DOOR STRUT QUINT

1

101281012GSS6298UH STRUTS 90#

1

Workorder: V23452

In Date: 05/21/2009
Close Date: 05/21/2009

Meter Reading: 42,714.00

Problem?

replace rear tires at shop callaghan

Task performed:

Parts

Quantity

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V22895

In Date: 04/29/2009
Close Date: 05/26/2009

Meter Reading: 4,500.00

Problem?

replace lettering on the front doors of engine 37 lettering is damaged

Task performed:

Air leak; rep air fitting on air tank that was leaking. j

Parts

Quantity

NO PARTS USED

Workorder: V23547

In Date: 05/26/2009
Close Date: 06/04/2009

Meter Reading: 42,714.00

Problem?

replace hose bed cover e37 central

Task performed:

Parts

Quantity

NO PARTS USED

Vendor? CENTRAL



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V23742

In Date: 06/02/2009

Meter Reading: 42,714.00

Close Date: 06/04/2009

Problem?

repair seat E37 (outside agency-central auto trim)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor? CENTRAL



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: **V22577**

In Date: 04/16/2009

Meter Reading: 42,714.00

Close Date: 06/11/2009

Problem?

C INSPECTION AND REPAIRS AS NEEDED E37

Task performed:

1. Perform C-Service.
2. Replcd oil pan gskt; (leaking)
3. Replcd trans oil cooler & lower coolant hoses at inlet/outlet of cooler.
4. Svc air brake dryer.
5. R/R driver's side rear seat to be repaired (ripped/torn)
6. Rebuilt intake relief valve(leaking); also replcd brass chk valve.
7. Svc T-case.
8. cd rear brake pads, pin kits & svc brake calipers.
10. Replcd o-ring seals on air brake compressor coolant line (leaking).
11. Painted fuel cap.
12. Replcd wiper blades.
13. Replcd rear cab A/ C filter.
14. Rebuilt #1 discharge valve (leaking).
15. Rebuilt #2 discharge valve (leaking).
16. Replcd driver's side rear door latch.
17. replcd weatherstripping on driver's side rear door; (ripped/torn).
18. Sec rear cab A/C vents (falling off).
19. Cind debris frm windshield washer squirters.
20. Sec driver's door panel to door (loose/falling off).
21. Replcd left/right lower steplight bulbs.
22. Replcd left side pump panel light asy & pump panel light bulb.
23. Replcd belts.
24. Replcd air filter (engine).
25. Replcd L-1 compt light bulb.
26. Adj door latches, tightened shelves & lubed all latched, hold opens & hinges.
27. Replcd door alarm switch on left, rear, upper compt.
28. Vac tested truck again & fnd deck gun valve leaking; replcd deck gun valve.
29. Replcd tank recirc valve (leaking0).
30. R/R intake relief valve to try & rep leak at mntng surface; resurfaced mnt flanges & reassembled.
31. Replcd left brake light bulb.
32. Filled truck w/water, ran pump to test all repairs; ran foam sys; perform vac test once again; road tested truck to chk for eng/trans fluid leaks.
33. Rebuilt primer valve.
34. Cl nd shop after PM Inspection. j

Parts

Quantity

0460050000GASKET	3
05-16423-000HOSE LOWER RADIATOR	2
073004100PISTON	1
104967DIAPHRAM FOR 6 PORT DUMP VALVE	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1156BULB	1
120257100C2030-7110-30 CLEAR DOME STEP	1
14022-1-5COOLER 14032	1
15016KIT15016 PIN KIT	2
15W40BSYN OIL BULK QTS	24
18-45484-000LATCH L/H	1
3911638PLUG OIL DRAIN C	1
3934044 3938160 OIL PAN C GASKET	1
52-24WIPER BLADES ANCO 24	2
52-624SWITCH DOOR	1
546126000TPM/QG HALE REPAIR KIT	1
6806970098SEAL DOOR	1
78308930 AKRON 3 IN VALVE	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
91388906 VALVE KIT 2.5 IN AKRON	2
91398907 VALVE KIT 3 IN AKRON	1
9440BELT	1
9480BELT	1
A-1779-WGREASE ROCKWELL A-1779-W-283	1
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
K080716BELT	1
PR338324070 WIX FILTER WATER	1
PVG-KITORING KIT	1
S1003-A3103015 SEAL	2
S2R7017173USE KIT15625PM BRAKE PAD	2
STOPSN12BULB STOP/TAIL LIGHT	1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V23267

In Date: 05/13/2009
Close Date: 06/15/2009

Meter Reading: 4,500.00

Problem?

water leak pump area e37

Task performed:

Chkd water leak; fnd tank to pump valve leaking; replcd tank to pump valve. j

Parts

Quantity

NO PARTS USED

Workorder: V23268

In Date: 05/13/2009
Close Date: 06/15/2009

Meter Reading: 4,500.00

Problem?

foam doesnt always work e37

Task performed:

Tested foam sys repeatedly; fnd no problems. j

Parts

Quantity

NO PARTS USED

Workorder: V23820

In Date: 06/04/2009
Close Date: 06/19/2009

Meter Reading: 4,591.20

Problem?

Audible air leaking from yellow parking brake lever pull handle. e37

Task performed:

Air leak; rem parking brake valve & installed new one. j

Parts

Quantity

NO PARTS USED

Workorder: V23845

In Date: 06/05/2009
Close Date: 06/19/2009

Meter Reading: 43,867.70

Problem?

AIR LEAK, E-37

Task performed:

Air leak; replcd parking brake valve. j

Parts

Quantity

800034VALVE PARKING BRK.

1



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V23748

In Date: 06/02/2009
Close Date: 06/24/2009

Meter Reading: 42,714.00

Problem?

pump test E37

Task performed:

1. Pump test.
2. Rep faulty connection for left rear rotator.
3. Replcd alt. j

Parts

4864JBRALTERNATOR 270 A

Quantity

1

Workorder: V23879

In Date: 06/07/2009
Close Date: 07/28/2009

Meter Reading: 4,591.20

Problem?

Would it be possible to mount the New York Hook on the passengers side running board like (e35) many of the other trucks in service. Thought it was going to get done last PM. Can that be done without taking truck OOS? E37

Task performed:

1. Mounted tool in L-1 compt.
2. Deck gun leaking; readj valve linkage. j

Parts

NO PARTS USED

Quantity

Workorder: V24711

In Date: 07/12/2009
Close Date: 07/28/2009

Meter Reading: 400.00

Problem?

1. Left rear outside tire has rubber separating from the sidewall... needs a inspection to see if it's normal. It seems as if it was a retread the way it's separating but doesn't have retread stamped on the sidewall??? E37

Task performed:

- Chkd tires & chkd out ok. j

Parts

NO PARTS USED

Quantity

Workorder: V24712

In Date: 07/12/2009
Close Date: 07/28/2009

Meter Reading: 400.00

Problem?

1. The pump panel fuel gauge is reading about 1/2 tank lower than the cab mounted fuel gauge. 2. One rear steplight is inoperativ E37

Task performed:

1. Fuel gauge inop; recalibrated gauge.
2. Spotlights in rear not working; fnd bad grnd. j

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V24754

In Date: 07/13/2009
Close Date: 07/28/2009

Meter Reading: 400.00

Problem?

drivers side rear window broken (not rolling up or down properly) E37

Task performed:

1. Rep rear window that was not roling up.
2. 110 A/C inop; reprogramed unit. j

Parts

A1818557002HANDLE-WINDOW

Quantity

1

Workorder: V24905

In Date: 07/20/2009
Close Date: 07/28/2009

Meter Reading: 419.00

Problem?

Air horn hasn't been sounding too healthy lately and is now no longer working or only working briefly... on the last run it worked for about one second, didn't sound good, then quit entirely. e37

Task performed:

- Air horns inop; readj air horns & tested. j

Parts

EL360081760611 SOLENOID AIR HORN

Quantity

1

Workorder: V25057

In Date: 07/24/2009
Close Date: 08/24/2009

Meter Reading: 44,815.00

Problem?

The hose divider at the front of E37 Hose bed separating the 3" supply & the 2.5" preconnect is not secured. The wieght of the supply presses against it making the 2.5" deployment difficult since divider is too short.

Task performed:

1. Mov hose bed divided over for 3" hose.
2. Remntd hose nozzle in rear & pro bar. j

Parts

NO PARTS USED

Quantity

Workorder: V25301

In Date: 08/04/2009
Close Date: 08/27/2009

Meter Reading: 44,815.00

Problem?

reinstall 30' probar E37

Task performed:

1. Reinstalled pry bar & move other tools.
2. Tank-to-pump valve hard to open; readj valve linkage

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V25550

In Date: 08/15/2009
Close Date: 09/30/2009

Meter Reading: 467.00

Problem?

Need divider shelf installed in backboard compartment to store new high rise coil pack & 2 1/2" hose. E37

Task performed:

Air leak; fnd fitting on air tankloose; rep/chkd.

j

Parts

NO PARTS USED

Quantity

Workorder: V25800

In Date: 08/26/2009
Close Date: 09/30/2009

Meter Reading: 44,815.00

Problem?

k-12 saw won't start e37

Task performed:

dropped saw off at shop for repair.

2. Remntd axe brkts. j

Parts

NO PARTS USED

Quantity

Workorder: V26078

In Date: 09/05/2009
Close Date: 10/07/2009

Meter Reading: 467.00

Problem?

bracket on rear bumper that holds gate valve is broken. e37

Task performed:

1. Chainsaw inop; rep/tested.

2. Sunvisor brkn; replc clip on visor. j

Parts

NO PARTS USED

Quantity

Workorder: V26023

In Date: 09/03/2009
Close Date: 10/15/2009

Meter Reading: 44,815.00

Problem?

repair chainsaw E37 (outside agency-regan's small engine service)

Task performed:

Repair chain saw E37 - Regans j

Parts

NO PARTS USED

Quantity

Vendor? REGANS SMALL ENG



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V26234

In Date: 09/14/2009
Close Date: 10/22/2009

Meter Reading: 467.00

Problem?

Chainsaw needs repair or replacement. Ongoing problem. e37

Task performed:

1. Rep fuel line on chain saw.
2. Adj rear door lock. j

Parts

1836267000VISOR RETRN

Quantity

3

Workorder: V26800

In Date: 10/10/2009
Close Date: 10/22/2009

Meter Reading: 46,435.80

Problem?

Driver's seat belt malfunctioning, screw in passenger side rear tire. E37

Task performed:

1. Went to Stn37; replc drivers side seat.
2. Fnd & rem bolt frm tire; did no penetrate.
3. Rep loose connection in dome light of drivers seat. j

Parts

NO PARTS USED

Quantity

Workorder: V26918

In Date: 10/15/2009
Close Date: 10/22/2009

Meter Reading: 46,435.80

Problem?

check brakes E37

Task performed:

1. Travel to Stn37 from C/S; travel to C/S from St73.
2. Inspect rear brakes; chk linings rotors slacks; adj/release; road test veh; NPF; brakes ok. j

Parts

NO PARTS USED

Quantity

Workorder: V25684

In Date: 08/21/2009
Close Date: 11/06/2009

Meter Reading: 467.00

Problem?

rear step light out E37

Task performed:

1. Rear steplights out; rep brnd wire.
2. Air leak; rep air leaks. j

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V26527

In Date: 09/29/2009 Meter Reading: 467.00
Close Date: 11/06/2009

Problem?

replace lettering on drivers door of e-37

Task performed:

Replc lettering on pass side door. j Parts _____ Quantity _____
NO PARTS USED

Workorder: V26529

In Date: 09/29/2009 Meter Reading: 44,815.00
Close Date: 11/06/2009

Problem?

we are out of motor oil can you please send us 12 qts e37

Task performed:

1. Rep gen pull cable that broke off. j Parts _____ Quantity _____
2. Rep left side door latch that was not opening. j NO PARTS USED

Workorder: V26683

In Date: 10/05/2009 Meter Reading: 4,821.00
Close Date: 11/06/2009

Problem?

light out left lower rear step and lower left step e37

Task performed:

1. Eng light on; cleared codes & road tested. j Parts _____ Quantity _____
2. Rep drivers seat belt that wld not latch. j NO PARTS USED

Workorder: V26853

In Date: 10/14/2009 Meter Reading: 46,435.80
Close Date: 11/16/2009

Problem?

repair chain saw e 37 regan

Task performed:

Repair chain saw E37 - Regan j Parts _____ Quantity _____
NO PARTS USED

Vendor? REGAN SMALL ENGINE



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V27721

In Date: 11/16/2009

Meter Reading: 4,828.70

Close Date: 11/30/2009

Problem?

SMALL AIR LEAK TO BRAKE SYSTEM. UNKNOWN LOCATION. see wo #27720

Task performed:

See W/O 27720 j

Parts

NO PARTS USED

Quantity

Workorder: V27031

In Date: 10/20/2009

Meter Reading: 46,435.80

Close Date: 12/09/2009

Problem?

need a 2 1/2 trilock on rear bumper E37

Task performed:

1. Rep rear step lights that were out.
2. installed new SI-40 hand night charger in rear.
3. Installed tri-lock on rear of truck. j

Parts

NO PARTS USED

Quantity

Workorder: V28445

In Date: 12/17/2009

Meter Reading: 47,157.00

Close Date: 12/17/2009

Problem?

PARTS ONLY 2.5 IN HOSE GASKETS E37

Task performed:

PARTS ONLY NO LABOR FOR BATT 7

Parts

0714021GASKET 2 1/2"

Quantity

6

Workorder: V27720

In Date: 11/16/2009

Meter Reading: 4,828.70

Close Date: 01/13/2010

Problem?

SMALL BRAKE SYSTEM AIR LEAK. UNKNOW TO LOCATE LEAK. E37

Task performed:

1. Stn needs oil; dropped off oil & chkd all fluids in eng.
2. Chk for air leaks; fnd none at this time. j

Parts

15W40QSYN OIL QT

Quantity

12



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V27962

In Date: 11/27/2009
Close Date: 01/13/2010

Meter Reading: 4,893.90

Problem?

Hands free siren is not working, only the horn is working regardless of what position the switch is in. E37

Task performed:

REP BAD CONNECTION ON SIREN.

J

Parts

NO PARTS USED

Quantity

Workorder: V29247

In Date: 01/19/2010
Close Date: 02/17/2010

Meter Reading: 47,671.50

Problem?

The reciprocating saw on Engine 37 is falling apart and needs to be replaced. Thank you very much.

Task performed:

DC will call & order new one. j

Parts

NO PARTS USED

Quantity

Workorder: V28533

In Date: 12/22/2009
Close Date: 02/22/2010

Meter Reading: 692.70

Problem?

Very difficult to start and won't continue to run unless throttle is activated. This is an ongoing problem.E37 Chain saw

Task performed:

Ran chain saw & fnd no problem with saw.

j

Parts

NO PARTS USED

Quantity

Workorder: V28716

In Date: 12/31/2009
Close Date: 02/22/2010

Meter Reading: 47,671.50

Problem?

Station 37 needs 3 gallons of radiator fluid e37

Task performed:

1. Coolant leak; rep leak & tested.
2. Door open light comes on;r eadj lights.

j

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V29132

In Date: 01/14/2010

Meter Reading: 47,671.50

Close Date: 02/25/2010

Problem?

REPAIR FLAT TIRE E37

Task performed:

Repair flat tire E37 - Callaghan j

Parts

NO PARTS USED

Quantity

Vendor? CALLAGHAN

Workorder: V29882

In Date: 02/11/2010

Meter Reading: 48,411.60

Close Date: 03/08/2010

Problem?

B INSPECTION AND REPAIRS AS NEEDED E37

Task performed:

- B-Service
- 2. Replcd rear A/C filter.
- 3. Replcd bulb in left frt signal light.
- 4. Replcd R/side pump panel light bulb.
- 5. Replcd left side pump panel light bulb & rep faulty grnd.
- 6. Adj R-1 compt shelf - straighten & secure.
- 7. Adj body door latches-loose.
- 8. Replcd L-1 compt light bulb/lens - brkn.
- 9. Chkd trk over for air leaks; fnd no leaks. j

Parts

1141BULB
 1142BULB
 1156BULB
 15W40BSYN OIL BULK QTS
 78R536078R5360M 2PK FILTER AIR COND
 80351DOME LIGHT
 FS1022FILTER FUEL WIX 33422 PS8689 FRAM
 HPH6349AOIL FILTER 51748
 R90PFILTER FUEL 33231

Quantity

1
1
2
28
1
1
1
1
1

Workorder: V29562

In Date: 01/31/2010

Meter Reading: 48,411.60

Close Date: 03/18/2010

Problem?

rear red rotating emergency light needs light bulb E37

Task performed:

Chkd rear rotators; fnd both working normally. j
Rep brkn warning light. j

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V29168

In Date: 01/15/2010
Close Date: 03/19/2010

Meter Reading: 692.70

Problem?

driver side rear emergency light is out. R37

Task performed:

Replc strobelight that was out. j

Parts

Quantity

NO PARTS USED

Workorder: V30366

In Date: 03/02/2010
Close Date: 03/26/2010

Meter Reading: 48,411.60

Problem?

Air dump inop R37

Task performed:

Adj air dump valve linkage. j

Parts

Quantity

NO PARTS USED

Workorder: V25973

In Date: 09/02/2009
Close Date: 04/13/2010

Meter Reading: 44,815.00

Problem?

SPARE SPARK PLUG PARTS ONLY E37

Task performed:

parts only no labor

Parts

Quantity

4626BPMR7A SPARK PLUG

1

Workorder: V30475

In Date: 03/05/2010
Close Date: 04/22/2010

Meter Reading: 48,411.60

Problem?

Flat tire at sat E37

Task performed:

Flat tire at sat E37 - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor? BOULEVARD TIRE



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V31024

In Date: 03/25/2010
Close Date: 05/01/2010

Meter Reading: 49,280.10

Problem?

Please send st 37 a case of motor oil we have used up all the extra oil we had on hand.

Task performed:

Dropped off 4-qts of oil. j

Parts

15W40QSYN OIL QT

Quantity

12

Workorder: V31252

In Date: 04/03/2010
Close Date: 05/01/2010

Meter Reading: 49,545.70

Problem?

Need 4 containers of pyrocool for E37. We're low on engine and need 3 for re-supply.

Task performed:

DC will call on foam. j

Parts

NO PARTS USED

Quantity

Workorder: V31270

In Date: 04/05/2010
Close Date: 05/05/2010

Meter Reading: 49,545.70

Problem?

Hood latch/strap broken E37

Task performed:

1. Stretcher latch inop; readj latch.
2. Replc lens on rear of truck. j

Parts

680-880-01-60LATCH

68118358150600 SER OPTIC RED

68318358730600 SER LENS NON OPTIC

Quantity

1

1

1

Workorder: V31627

In Date: 04/19/2010
Close Date: 05/11/2010

Meter Reading: 49,869.70

Problem?

Left rotating light is not working E37

Task performed:

Rep short in lite in rear. j

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V31698

In Date: 04/21/2010
Close Date: 05/11/2010

Meter Reading: 49,869.70

Problem?

HURST TOOL BRACKET BASE ONLY HAS ONE BOLT HOLDING IT TO THE POWER UNIT. e37

Task performed:

Installed all motor mnts on motor. j

Parts

HR149460107MOUNT VIBRATION (NEWER POWER UNITS

Quantity

4

Workorder: V31867

In Date: 04/28/2010
Close Date: 06/04/2010

Meter Reading: 50,089.00

Problem?

rear step light out p31192 E37

Task performed:

rep rear step lights. j

Parts

NO PARTS USED

Quantity

Workorder: V32008

In Date: 05/05/2010
Close Date: 06/04/2010

Meter Reading: 50,089.00

Problem?

Right rear spot light out & bottom right rear work light out. E37

Task performed:

1. Air leak-trace air leaks & rep.
 2. Light out in rear; fnd bad grd; rep grd/tested.
- j

Parts

NO PARTS USED

Quantity

Workorder: V31866

In Date: 04/28/2010
Close Date: 06/10/2010

Meter Reading: 50,089.00

Problem?

Rear work light needs replaced. E37

Task performed:

rep broken grd. j

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V32043

In Date: 05/06/2010

Meter Reading: 50,089.00

Close Date: 06/10/2010

Problem?

engine 37 rear white work/marker lights 3 of the 4 are blown. E37

Task performed:

Parts

Quantity

1. Fnd bad connection for rear lights.
2. Relief valve inop; tested & tested ok. j

NO PARTS USED

Workorder: V32297

In Date: 05/19/2010

Meter Reading: 50,089.00

Close Date: 06/10/2010

Problem?

3 REAR WHITE STEP LIGHTS OUT. CREW BELIEVES THEY HAVE BEEN REPAIRED AND ARE OUT AGAIN. e37

Task performed:

Parts

Quantity

1. Rep rear steplights.
2. Readj rear door latch. j

NO PARTS USED

Workorder: V32301

In Date: 05/19/2010

Meter Reading: 50,089.00

Close Date: 06/10/2010

Problem?

Rear Officer's side spot light out. Glove boxinside cab needs repaired also. E37

Task performed:

Parts

Quantity

- Installed new maplight grd wire. j

ART20EXTGENESIS HOSE

1

Workorder: V32357

In Date: 05/21/2010

Meter Reading: 50,089.00

Close Date: 06/28/2010

Problem?

left rear spotlight out. E37

Task performed:

Parts

Quantity

1. Spotlight inop; replcd head.
2. L/rear rotator inop; FNP w/lights.
3. Air leak; traced out air leaks & rep where needed.
4. A/C warm; recharge sys. j

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V32617

In Date: 06/02/2010
Close Date: 06/28/2010

Meter Reading: 50,745.80

Problem?

Driver's side rear rotating beacon still needs repair. Fixed temporarily, but out again. e37

Task performed:

Replc rear rotater. j

Parts

RB6DRPRB6PRP RED ROTATING BEACON

Quantity

1

Workorder: V32618

In Date: 06/02/2010
Close Date: 06/28/2010

Meter Reading: 50,745.80

Problem?

Glove box needs to be remounted. Tried to remount with double sided tape, but box under too much stress to be held by tape. e37

Task performed:

- 1. Spot lite inop.
- 2. Rotater inop. j

Parts

4537BULB 100W SPOT

6811813493LENS CLEAR 68-1181349-3

Quantity

1

1

Workorder: V33851

In Date: 07/28/2010
Close Date: 08/09/2010

Meter Reading: 51,691.50

Problem?

REPAIR ROTATOR LIGHT E 37

Task performed:

Right rotater bulb blown; rem bulb & install new bulb.
ja

Parts

H50SN12BULB

Quantity

1

Workorder: V33140

In Date: 06/25/2010
Close Date: 08/16/2010

Meter Reading: 51,104.50

Problem?

button for hose reel does not work E37

Task performed:

Installed new solenoid for hose reel. ja

Parts

50R03ZCRLIGHT LED RED TIR 6

599908STARTER SOLENOID EONE

Quantity

1

1



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V34396

In Date: 08/19/2010
Close Date: 08/20/2010

Meter Reading: 52,096.00

Problem?

E37 Mobile radio/microphone cord connection loose. Transmissions out are intermittent.

Task performed:

contact radio shop for repair 08/20

Parts

NO PARTS USED

Quantity

Workorder: V34578

In Date: 08/28/2010
Close Date: 09/03/2010

Meter Reading: 52,193.60

Problem?

Engineer's compartment won't open. Appears long metal rod locking mechanism snapped. E37

Task performed:

Duplie - see WO 34580 js

Parts

NO PARTS USED

Quantity

Workorder: V34580

In Date: 08/28/2010
Close Date: 09/03/2010

Meter Reading: 52,193.60

Problem?

D/E COMPARTMENT DOOR RIGHT SIDE IS NOT OPENING LATCH IS NOT OPERATING. ABLE TO OPEN LEFT DOOR BUT NOT RIGHT DOOR. NEED ACCESS TO COMPARTMENT ASAP.E37

Task performed:

Door open lock brkn; travel to shop for part; rep door open lock. js

Parts

NO PARTS USED

Quantity

Workorder: V33901

In Date: 07/29/2010
Close Date: 09/17/2010

Meter Reading: 51,691.50

Problem?

Air horn pedal on E37 not working.

Task performed:

1. Replc air horn solenoid.
2. Rear A/C filter replcd. j

Parts

78R536078R5360M 2PK FILTER AIR COND
HDY-H005700SOLENOID HORN AIR

Quantity

2
1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V34103

In Date: 08/07/2010
Close Date: 09/17/2010

Meter Reading: 51,691.50

Problem?

HOSE REEL REWIND BUTTON/MOTOR O.O.S. E37

Task performed:

Rep hose reel; replcd switch. j

Parts

NO PARTS USED

Quantity

Workorder: V34848

In Date: 09/09/2010
Close Date: 09/27/2010

Meter Reading: 52,409.00

Problem?

Interior handle loose on officer's side rear passenger door. e37

Task performed:

handle brkn; went to stn; replcd handle. j

Parts

6807200575HANDLE DOOR

Quantity

1

Workorder: V31823

In Date: 04/27/2010
Close Date: 10/19/2010

Meter Reading: 50,000.20

Problem?

HOSE APPLIANCE LOCKING MECHANISM NOT WORKING TO HOLD 3" HOSE TO TAILBOARD. E37

Task performed:

Completed j

Parts

NO PARTS USED

Quantity

Workorder: V35069

In Date: 09/20/2010
Close Date: 10/20/2010

Meter Reading: 52,657.00

Problem?

HAVING PROBLEMS WITH HOSE REEL. BUTTON/MANUAL METHODS DOES NOT WORK. E37

Task performed:

1. inspect hose reel, repair manual hand crank, teeth bent, adjusted lock to align.. jab

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V34579

In Date: 08/28/2010
Close Date: 10/21/2010

Meter Reading: 52,193.60

Problem?

Right front hub center cap missing, along with a lugbolt cover. E37

Task performed:

1. check for door open light, repaired ladder compartment door open switch. jab

Parts

NO PARTS USED

Quantity

Workorder: V35568

In Date: 10/12/2010
Close Date: 11/16/2010

Meter Reading: 52,657.00

Problem?

Requesting 1 case of 15/40 oil for E37. None in station. E37 leaking oil, oil low.

Task performed:

1. drop of oil to station.
2. check for oil leak, no oil leak found. jab

Parts

15W40QSYN OIL QT

Quantity

12

Workorder: V35854

In Date: 10/22/2010
Close Date: 11/16/2010

Meter Reading: 52,657.00

Problem?

Replace 4 rear tires. (boulevard tire) E37

Task performed:

Replc (4) rear tires E37- Boulevard j

Parts

NO PARTS USED

Quantity

Vendor? BOULEVARD TIRE



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V35955

In Date: 10/27/2010

Meter Reading: 53,475.00

Close Date: 12/03/2010

Problem?

C INSPECTION AND REPAIRS AS NEEDED E37

Task performed:

Parts

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

C-Inspection

2. Btrys failed load test; btrys were 2 yrs, 5 mo old; replc all btrys.
3. Btry/ign lites on dash inop; replc both lite asys.
4. Rem instrument panel frm cab dash; on bench diss instr back panel & replc all illumination bulbs; reassem/reinstall in dash.
5. Replc wiper blade refills.
6. All cab door steplights inop; pigtail wiring bad on all (4) doors; install new pigtails to all door lite skts.
7. Interior cab ovrhd red/clear lites inop; rem cvrs/chk; red bulbs ok; clear burnt out; chk w/parts-no bulbs this style avail; use (4) bulbs that cld work but mod was ness.
8. Step lites to pump panel inop; fnd burnt bulbs in both but had to rep grnd, also on r/side.
9. (2) pump panel lites inop; replc bulbs both lites; drill wtr drain holes in lenses.
10. (3) rear step lites inop; replc burnt out bulbs, (3) had bad grnds; repl all, cln lens; drill wtr drain holes in all new lenses.
11. (2) compt lites inop; R/R burnt out bulbs.
12. Handlight base very loose in floor; resecure to floor.
13. Pump compt lites inop; replc bulbs in both; still didn't work; chk power-NG; trace wiring & fnd brkn wire; rep break.
14. Sev clearance/mrkr lites inop; rep all mrkr/clearance lites; some took bulbs others took new fixtures or lite asys.
15. Replc all (4) cab door window moldings.
16. Replc 6" o-ring on R/side steamer cap.
17. (4) compt door hold opens loose; tighten all doors.
18. Rem dash panel & adj A/C cntrl blend door/defroster door; reassem panel.
19. Rem all ladders & (2) sets of old heat sensors; install new sensors.
20. Wash out road debris frm btry draw slides; cln/blow/relobe & work draw to slide freely; cln/lube locking latch.
21. Wash out road debris frm trash line draw slides; relube/work til frre.
22. Replc both frnt shocks; hanger bolts frzn; spray w/rust-buster & beat out bolts; cln.
23. Replc R/frnt seat belt asy; Both reas had to be ordered will install when recvd.
24. Svc rear diff.
25. Svc P/S.
26. Replc all eng belts.
27. Replc serpentine aut-belt tensioner.
28. Rem A/C belt adjuster; rebuild on bench; reinstall.
29. Buff out lenses on hood strobes, brake/tail turn, back-up & scene lites; body strobes.
30. Replc cab doors weather stripping.
31. Rem frnt/right seat; send out for repair; reinstall.

012-0160-00T-HANDLE	1
037-1341-50-0VPS SHIFT KIT 2 PIECE	1
040-1130-03RING-PISTON SEAL (QG RELIEF VALVE)	1
042-0550-00SPRING-VALVE QG RELIEF VALVE	1
0465060000GASKET	1
0465130010GASKET GEARBOX COVER	2
05-17223-000CAP RADIATOR 10 LB	1
073-0011-00PISTON-RELIEF VALVE (QG VALVE)	1
073004100PISTON	1
0772750010SNAP RING	1
0913912CHARGER 2000	1
0915520120AUTO EJECT 20 AERO OTL3925	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1141BULB	20
12105QUICK DRAIN	3
12854DOME LIGHT BULBS	4
15W40BSYN OIL BULK QTS	30
194BULB	10
2032-0000-30LENS CLEAR	6
203FFBEARING PULLEY	1
211-2BULB	1
250-0214-06250-0214-06 BEARING	1
2952271729552377 VALVE ASSY.ACCUM	1
29526898 29548988 TRANS FILTER ALLISON	1
29535973ACCUM.KIT	1
2962540000SEAL SAME AS 29867 C/R	2
3157TAIL LIGHT BULBS	4
33046FUEL FILTER	1
35200-RLIGHT MARKER LED RED	4
35200-YLIGHT MARKER LEDAMBER	1
372000030BATTERY ON DISPLAY	1
372000031IGNITION ON DISPLAY	1
372000084MARKER LIGHT	1
39768315259022 GROOVED TENSIONER OLD#3936213	1
411-0768170 PIGTAIL	4
4923090025DASH BULB VDO	8
538-0180-00SHIFT CONTROL VALVE PUMP ROAD	1
546126000TPM/QG HALE REPAIR KIT	1
6803230300 65482 SHOCK FRONT ENGINE	2
6806970098SEAL DOOR	1
6807200575HANDLE DOOR	1
78R536078R5360M 2PK FILTER AIR COND	1
800034VALVE PARKING BRK.	1
800373SC-3 CHECK VALVE 5003525	1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

- 32. Rem air dryer frm veh & rebuild on bench; reinstall.
- 33. Svc trans.
- 34. Diss complete lower half of T-case; reseal/rebearing; rebuild complete air shifter; reassem; fill w/oil & chk for leaks - oil/air; all ok.
- 35. Chase down chassis air leak(s); looses air in abt 1-1/2 hrs; fnd sev leaks - fittings, air lines under/in dash, park brake valve, T-case air shifter under dash, etc.; replc all air tank fittings.
- 36. Rem trans retarder/accum; rebuild/reinstall; fill trans; start/ran/chk for leaks; all good.
- 37. C/O prob w/booster reel-binds up badly; adj motor chain-still binds up; fnd hose rollup barrel not stright in frame, back side chain & sprocket bolts.
- 38. Install btry charger in veh for computer deck.
- 39. Press rel valve inop; rem frm pump & rebuild on bench; reinstall; rechk-now ok.
- 40. Failed vac test; replc intake rel valve; chk valve-readj sev valve rods to close compeltely; mod some rods.
- 41. Temp sensor top of pump broke loose; cln pump surface, grind off old apoxy; apply new apoxy.
- 42. Make up kick screen to protect A/C intake filter.

j

800405PURGE VALVE KIT	1
89BULB	1
9440BELT	1
9480BELT	1
99080C ROUND CLEAR LENS	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	4
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
IMMF11361SEAT BELT P/S	1
IMMF13251SEAT BELT OLD IMMF11848	1
K080716BELT	1
P56AN227MOTOR HOSE REEL	1
PR338324070 WIX FILTER WATER	1
PVG-KITORING KIT	1
R90PFILTER FUEL 33231	1
REDG6S14023 GASKET 6 IN	1
U-24RWIPER REFILL	1
VML-S1414FILTER P/S	1
VML-T1264GASKET P/S COVER	1
VML-T1279WASHER P/S	1
VML-T1311COVER PWR STEER RES	1

Workorder: V36398

In Date: 11/12/2010
Close Date: 12/03/2010

Meter Reading: 53,348.60

Problem?

OIL PRESSURE UPDATE E 37 CUUMINS

Task performed:

Oil press update E37 - Cummins j

Parts

NO PARTS USED

Quantity

Vendor? CUMMINS



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V34758

In Date: 09/05/2010
Close Date: 12/22/2010

Meter Reading: 52,193.60

Problem?

generator backfiring and when taken off choke wants to shut off and then powers back up. not running right. E37

Task performed:

Parts

Quantity

(1) GENERATOR BACKFIRING AND WANTS TO STALL WHEN TAKEN OFF CHOKE AND THEN POWERS BACK UP. NOT RUNNING RIGHT. OFF OF E34.

NO PARTS USED

CLEANED OUT THE CARB AND REPLACED THE FUEL. RAN UNIT AND TESTED GOOD. J.W.

Workorder: V35569

In Date: 10/12/2010
Close Date: 12/22/2010

Meter Reading: 52,657.00

Problem?

E37 has slow oil leak.

Task performed:

Parts

Quantity

(1) TRAVELED TO ST 37 TO CHECK OIL LEAK ON E37. FOUND IT TO BE COMING FROM THE BREATHER TUBE. OK.

NO PARTS USED

(2) DROPPED OF OIL AT ST37. J.W.

Workorder: V36910

In Date: 12/06/2010
Close Date: 01/11/2011

Meter Reading: 53,348.60

Problem?

OIC side emergency light bar is out. e37

Task performed:

Parts

Quantity

Rep lights on cab that were out. j

NO PARTS USED

Workorder: V36911

In Date: 12/06/2010
Close Date: 01/11/2011

Meter Reading: 53,348.60

Problem?

rear scene lights out e37

Task performed:

Parts

Quantity

1. Rep rear lights that was not working.
2. Rep air ride seat that was not working. j

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V37150

In Date: 12/14/2010
Close Date: 01/11/2011

Meter Reading: 53,348.60

Problem?

fix or replace air back mounting brachet. air pack falls out of it. e37

Task performed:

1. Rep rear air pack brkt.
2. Hose reel inop; rep grnd wire & tested. j

Parts

9910-1119GEAR CHAIN DRIVE HANNA
P56AN227MOTOR HOSE REEL

Quantity

1
1

Workorder: V37517

In Date: 12/30/2010
Close Date: 01/21/2011

Meter Reading: 53,348.60

Problem?

repair flat callaghan

Task performed:

- Rep flat - Boulevard j

Parts

NO PARTS USED

Quantity

Vendor? BOULEVARD TIRE

Workorder: V37423

In Date: 12/27/2010
Close Date: 02/07/2011

Meter Reading: 53,348.60

Problem?

There is a halogen bulb out on the roof emergency light bar on the OIC side. Thanks E37

Task performed:

1. Replc d bulb & tested.
2. Readj all cb door latches. j

Parts

NO PARTS USED

Quantity

Workorder: V38270

In Date: 02/03/2011
Close Date: 02/24/2011

Meter Reading: 54,972.40

Problem?

Bulb that Tommy replaced last shift (1/31) out again. I can't actually see if there is a bulb in place, lenses are extremely oxidized from the sun. Talked to Tommy about changing lens covers so lights are more visible. E37

Task performed:

1. Rep grnd wire on light bar.
2. Adj all tools in L-1 compt that wld not fit brkts. j

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V38088

In Date: 01/27/2011
Close Date: 03/08/2011

Meter Reading: 54,846.00

Problem?

Lanyard for E37 TIC broken

Task performed:

Rep lanyard for TIC. j

Parts

NO PARTS USED

Quantity

Workorder: V38092

In Date: 01/27/2011
Close Date: 03/08/2011

Meter Reading: 54,846.00

Problem?

Hurst a-b valve handle broken. Have to use screwdriver. E37

Task performed:

Rep valve on pump & ran pump; tested ok. j

Parts

TURB6HALSTROBE

Quantity

2

Workorder: V38118

In Date: 01/28/2011
Close Date: 03/08/2011

Meter Reading: 54,945.20

Problem?

Firefighter's handlight charger won't connect with light. R37

Task performed:

Fnd charger not charging; rep connections. j

Parts

NO PARTS USED

Quantity

Workorder: V38345

In Date: 02/08/2011
Close Date: 03/08/2011

Meter Reading: 55,114.00

Problem?

generator on e37 not running properly. written up before but still doing same problem. generator shuts off when taken off choke ar even when first started with choke on.

Task performed:

Cld carb & tested unit, all ran good. j

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V39258

In Date: 03/17/2011

Meter Reading: 55,945.20

Close Date: 03/24/2011

Problem?

CHECK OPERATION OF PUMP THROTTLE E 37

Task performed:

Parts

Quantity

Drive to Stn37; C/O pump throttle; driver did not have throttle shut down all the way; showed driver; ok. j

NO PARTS USED

refer to wo 39255

Workorder: V38651

In Date: 02/20/2011

Meter Reading: 55,260.70

Close Date: 03/28/2011

Problem?

TWO STEP LIGHTS IN THE REAR OF E37 NEED REPLACING E37

Task performed:

Parts

Quantity

1. Rep rear step light that had bad grd.
2. Adj rear cab door latch & tested. j

NO PARTS USED

Workorder: V38930

In Date: 03/03/2011

Meter Reading: 55,679.00

Close Date: 03/28/2011

Problem?

Driver's side rear rotating red beacon out, as well as 2 step lights at rear. E37

Task performed:

Parts

Quantity

1. Rear light inop; rem light & rep wires & reinstalled light.
2. Air leak; traced air leaks & fnd none at this time.
3. Rep (2) step lights that were out. j

NO PARTS USED

Workorder: V38985

In Date: 03/06/2011

Meter Reading: 55,679.00

Close Date: 03/28/2011

Problem?

Top light bar, passenger side bulb out. Rear top driver's side light out. Rear step lights - two passenger side lights out. Left intake-slow leak, possibly through valve. E37

Task performed:

Parts

Quantity

1. Light bad inop; rep grd wire & tested.
2. Hurst unit not starting; cld carb & change gas; started unit & ran.
3. Installed new brkts for axes. j

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V39115

In Date: 03/11/2011
Close Date: 04/05/2011

Meter Reading: 55,679.00

Problem?

smoke coming from alternator E37

Task performed:

Replcd alternator. j

Parts

NO PARTS USED

Quantity

Workorder: V39588

In Date: 03/31/2011
Close Date: 05/05/2011

Meter Reading: 56,364.50

Problem?

FYI THE RIGHT FRONT TIRE ON E37 IS BEGINNING TO SHOW WEAR MAY NEED TO BE CHANGED IN THE NEAR FUTUR

Task performed:

Chkd tires & all tested ok. j

Parts

NO PARTS USED

Quantity

Workorder: V39834

In Date: 04/11/2011
Close Date: 05/11/2011

Meter Reading: 56,364.50

Problem?

emergency light bar light is out over OIC side E37

Task performed:

1. Replcd strobe bulb.
2. Remntd tools in rear compt. j

Parts

15W40QSYN OIL QT

Quantity

12

Workorder: V40414

In Date: 05/04/2011
Close Date: 06/03/2011

Meter Reading: 567,727.20

Problem?

SHORELINE GOT CAUGHT ON E37 WHILE RESPONDING. NEED REPLACEMENT SHORE LINE AND RE-INSTALLATION TO AVOID PROBLEM RECURRING. E37

Task performed:

Rep shoreline plug that was damaged. j

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V40522

In Date: 05/10/2011
Close Date: 06/03/2011

Meter Reading: 57,048.70

Problem?

generator will not stay running, Sta 37.

Task performed:

Cln carb on gen & tested unit; ran good after cleaning carb. j

Parts

NO PARTS USED

Quantity

Workorder: V40608

In Date: 05/13/2011
Close Date: 06/03/2011

Meter Reading: 57,048.70

Problem?

audible air leak behind the pump panel. Air tanks that supply the brakes completely bleed down to 0 psi less than 30 min after running the engine. Sta 37.

Task performed:

1. Air leak; fnd frnt suction valve leaking; rep leak.
2. Readj all cab doors that were hard to close. j

Parts

NO PARTS USED

Quantity

Workorder: V40945

In Date: 05/28/2011
Close Date: 06/28/2011

Meter Reading: 57,048.70

Problem?

Front suction/intake drain handle is missing E37

Task performed:

Reinstalled handle on front suction ak

Parts

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR

Quantity

1

Workorder: V41162

In Date: 06/07/2011
Close Date: 06/28/2011

Meter Reading: 57,048.70

Problem?

Engineer's compartment door keeps opening intermittently when E37 makes a right turn. Has happened numerous times. Sta 37.

Task performed:

RRplaced latch at top and bottom of door ak

Parts

1012910235619A STRIKER PLATE

Quantity

3



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V41788

In Date: 07/05/2011
Close Date: 07/05/2011

Meter Reading: 57,048.70

Problem?

Belts making noise.

Task performed:

adjusted all engine belts that were making noise ak

Parts

NO PARTS USED

Quantity

Workorder: V41434

In Date: 06/18/2011
Close Date: 07/11/2011

Meter Reading: 57,048.70

Problem?

Auto Charger lights on engine aren't lighting up when the shore line is plugged in. Unable to tell if power is supplied. Shore line is plugged in all the way, and no breakers are activated at power panel. E37

Task performed:

Chkd charger; fnd problem with 110 frm stn. j

Parts

NO PARTS USED

Quantity

Workorder: V41830

In Date: 07/06/2011
Close Date: 07/20/2011

Meter Reading: 57,048.70

Problem?

FOAM GAUGE LIGHTS NOT WORKING. ALSO, ENGINE RUNNING ROUGH, AND BRAKES REPORTED AS EMITTING ODOF BY A SHIFT AT PASSDOWN. Sta 37.

Task performed:

FOAM GAUGE INOP RECALABRATED FROAM GAUGE AND TESTED GAUGE

Parts

NO PARTS USED

Quantity

ENGINE RUNNING ROUGH FOUND NO ROBLEM WITH ENGINE

BRAKES SMOKING ROAD TESTED TRUCK FOUND RETSTARTER NOT ON AK

Workorder: V39255

In Date: 03/16/2011
Close Date: 08/05/2011

Meter Reading: 55,945.20

Problem?

rear gate valve holder on dimond plate removed, needs replacing, no longer holds gate valve securely e 37

Task performed:

refer to wo 39258

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V41863

In Date: 07/07/2011

Meter Reading: 57,048.70

Close Date: 08/08/2011

Problem?

rear emergency light cover missing, light is still operational, no apparent damage to area, sta 37.

Task performed:

installed new lens for rear light

Parts

15W40QSYN OIL QT

Quantity

4

repaired 110 a/c that was not working

RB6DRPRB6PRP RED ROTATING BEACON

1

Workorder: V42653

In Date: 08/08/2011

Meter Reading: 58,132.80

Close Date: 08/08/2011

Problem?

Auto Charge inoperative again. Lights aren't on. Sta 37.

Task performed:

found no 110 from station

Parts

NO PARTS USED

Quantity

Workorder: V42156

In Date: 07/20/2011

Meter Reading: 58,132.80

Close Date: 08/10/2011

Problem?

B inspection.

Task performed:

B-Inspection

2. R/R cab A/C filter.

3. Replc rear cracked reflector.

4. Replc chipped door handles on all pass doors.

5. Replc burnt pump panel light.

6. Rem frnt tire to have replcd.

7. Replcd worn compt door struts.

8. Replcd worn/loose mansaver cvr.

9. Put new screws in Class 1 panel cvr.

10. Replc hood strap; rem frm surplus eng; replc strap.

11. Fnd L-1 door catch loose; rep/added lock nuts to catch; ck ok.

12. Qualtiy check. j

Parts

1141BULB

15W40BSYN OIL BULK QTS

17-12438-000HOOD LATCH

6807600070HANDLE DOOR EXT L/H

6807600170HANDLE DOOR EXT. R/H

78R536078R5360M 2PK FILTER AIR COND

98032R 41032-3 RED REFLECTOR OVAL REFLECTOR

FS1022FILTER FUEL WIX 33422 PS8689 FRAM

HLD39917DC23-5011 50 # HOLD-OPEN RESCUE

HPH6349AOIL FILTER 51748

MSA150-A18MANSAYER COVER

R90PFILTER FUEL 33231

Quantity

1

3

2

1

2

1

1

1

2

1

2

1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V42661

In Date: 08/08/2011
Close Date: 08/15/2011

Meter Reading: 58,132.80

Problem?
left rear flat e 37

Task performed:

Left rear flat E37 - Boulevard j

Parts	Quantity
NO PARTS USED	

Vendor? BOULEVARD

Workorder: V42432

In Date: 08/01/2011
Close Date: 08/16/2011

Meter Reading: 58,132.80

Problem?
replace front tire

Task performed:

REPLACE FRONT TIRE OUTSIDE AGENCY REPAIR

Parts	Quantity
NO PARTS USED	

Vendor? BOULEVARD

Workorder: V42059

In Date: 07/15/2011
Close Date: 08/25/2011

Meter Reading: 58,132.80

Problem?
FOAM LIGHT BAR INOPERATIVE AGAIN. JUST FIXED A COUPLE OF DAYS AGO.E37

Task performed:

recalibrated foam gauge and tested

Parts	Quantity
WL2600WLA260-A00 FOAM TANK VISION OLD FERR # 352	1

Workorder: V43544

In Date: 09/09/2011
Close Date: 09/09/2011

Meter Reading: 58,757.30

Problem?
e37- chain sent for chainsaw is wrong size. Please send a spare sparkplug, Sta 37.

Task performed:

Parts only.

Parts	Quantity
4626BPMR7A SPARK PLUG	1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V41916

In Date: 07/11/2011
Close Date: 09/20/2011

Meter Reading: 58,036.90

Problem?

REPAIR FLAT E 37

Task performed:

Repair flat E37 - Boulevard j

Parts

NO PARTS USED

Quantity

Vendor? BOULEVARD

Workorder: V42232

In Date: 07/22/2011
Close Date: 09/21/2011

Meter Reading: 58,132.80

Problem?

E37. Velcro strap for the hose clamp.

Task performed:

installed velcro strap

Parts

UMVS-0811-11STRAP ZICO
UMVS254411STRAP 46 IN

Quantity

1
1

Workorder: V43558

In Date: 09/09/2011
Close Date: 10/03/2011

Meter Reading: 58,757.30

Problem?

Hello Paris, please send a 20"chainsaw type chain to 37.The last one was a vent saw chain. E37

Task performed:

dropped off chain saw blade and installed

Parts

NO PARTS USED

Quantity

Workorder: V43904

In Date: 09/25/2011
Close Date: 10/14/2011

Meter Reading: 59,228.80

Problem?

left rear hurst compartment on E37 is opening when going around turns.

Task performed:

READJUSTED DOOR LATCH AND TESTED

Parts

1012910235619A STRIKER PLATE
10129102690ZNF/WO FLUSH LOCK BOLT

Quantity

2
2



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V44508

In Date: 10/19/2011
Close Date: 10/28/2011

Meter Reading: 59,769.10

Problem?

Pump making noise.

Task performed:

ran pump - fnd no nosie in pump. j

Parts

NO PARTS USED

Quantity

Workorder: V41940

In Date: 07/12/2011
Close Date: 11/02/2011

Meter Reading: 58,132.80

Problem?

Auto Charge inoperative again. Lights aren't on. Sta 37.

Task performed:

ref to wo 42059

Parts

NO PARTS USED

Quantity

Workorder: V44832

In Date: 11/01/2011
Close Date: 11/09/2011

Meter Reading: 59,886.20

Problem?

ON CALL COMPT DOOR WONT OPEN R 37

Task performed:

Compt door will not open; cut off latch & opened door;
reinstalled new door latch & handle. j

Parts

79L-SSD RING LATCH
HI-550NON-LOCKING SLAM

Quantity

1
1

Workorder: V44949

In Date: 11/04/2011
Close Date: 12/02/2011

Meter Reading:

Problem?

Throttle control needs adjusted. Also, trouble getting prime on pump after putting in gear. sta 37

Task performed:

repaired throttle that was loose

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V45225

In Date: 11/16/2011

Meter Reading:

Close Date: 12/02/2011

Problem?

tommy repaired passenger door catch, sta 37.

Task performed:

Parts

Quantity

left side door latch, replaced and repaired door

18-29935-001RH DOOR LATCH NEW

1

repaired generator that was hard to start

Workorder: V45529

In Date: 11/30/2011

Meter Reading:

Close Date: 12/12/2011

Problem?

NEED OIL LEAK CHECKED, GETTING WORSE. Sta 37

Task performed:

Parts

Quantity

checked and repaired oil leak

NO PARTS USED

adjusted all cab doors

Workorder: V45599

In Date: 12/03/2011

Meter Reading:

Close Date: 12/12/2011

Problem?

Rear outside tires showing wear, almost time to be replaced.

Task performed:

Parts

Quantity

will monitor tires

NO PARTS USED

Workorder: V45717

In Date: 12/08/2011

Meter Reading:

Close Date: 12/16/2011

Problem?

did not eject cord and puld cord out of ceiling, Sta 37

Task performed:

Parts

Quantity

REPAIRED PLUG AND TESTED AUTO EJECT.

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V46091

In Date: 12/27/2011
Close Date: 12/28/2011

Meter Reading: 61,062.00

Problem?

E37 oil leak

Task performed:

ENGINE OIL LOW. FF SHOWED RECORD. ADDED 3 QUARTS EARLIER IN THE MONTH. CHECKED FOR LEAKS, FOUND LOTS OF OIL ROUND FILTER AND WATER FILTER. I CHANGED OIL FILTER AND CLEANED RIGHT SIDE OF MOTOR.

Parts

NO PARTS USED

Quantity

Workorder: V46591

In Date: 01/15/2012
Close Date: 01/23/2012

Meter Reading: 61,470.60

Problem?

small air leak in front engine compartment E 37

Task performed:

REAR STROBE LIGHTS OUT - REPLACED AND TESTED.

Parts

02036317300STROBE LINEAR REFLECTOR 6ELTUBE

2

Quantity

Workorder: V46589

In Date: 01/15/2012
Close Date: 02/03/2012

Meter Reading: 61,759.10

Problem?

Air leak.

Task performed:

REPAIRED AIR LEAK - FOUND PURGE VALVE LEAKING.

Parts

NO PARTS USED

Quantity

Workorder: V46892

In Date: 01/27/2012
Close Date: 02/03/2012

Meter Reading: 61,915.60

Problem?

Officer side headlight is out. E37

Task performed:

1. REPLACED HEAD LIGHT.
2. REPLACED PLUG IN HURSTUNIT AND RAN UNIT - AND TESTED.

Parts

BPR5ESSPARK PLUG 7734

4

Quantity



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V47301

In Date: 02/14/2012
Close Date: 02/14/2012

Meter Reading: 62,209.20

Problem?

REPLACE REAR TIRES

Task performed:

REPLACE REAR TIRES.

Parts

NO PARTS USED

Quantity

Vendor? *

Workorder: V47209

In Date: 02/10/2012
Close Date: 02/27/2012

Meter Reading: 62,131.60

Problem?

DRIVER COMPARTMENT DOOR DOES NOT APPEAR TO BE CLOSING PROPERLY E37

Task performed:

READJUSTED ALL DOOR LOCKS.

Parts

NO PARTS USED

Quantity

Workorder: V47249

In Date: 02/12/2012
Close Date: 02/27/2012

Meter Reading: 62,209.20

Problem?

REAR TIRES ON E37 (PROBABLY REAR OUTSIDE)WILL NEED TO BE CHANGED IN THE NEAR FUTURE, Sta 37

Task performed:

1. AIR LEAK - REPAIRED AIR LEAK AT REAR AIR TANK.
2. PULLS TO RIGHT - ROAD TESTED AND ADJUSTED BRAKES.
3. WILL MONITOR REAR TIRES.

Parts

NO PARTS USED

Quantity

Workorder: V47569

In Date: 02/25/2012
Close Date: 03/13/2012

Meter Reading: 62,563.10

Problem?

TIC is not chargeing E 37

Task performed:

REPAIRED TIC CHARGER.

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V47685

In Date: 03/01/2012
Close Date: 03/16/2012

Meter Reading: 62,563.10

Problem?
tic inop.

Task performed:

REPAIRED TIC AND TESTED.

Parts

NO PARTS USED

Quantity

Workorder: V47717

In Date: 03/02/2012
Close Date: 03/16/2012

Meter Reading: 62,563.10

Problem?
Slow starting.

Task performed:

FOUND TRUCK NOT PLUG IN, LOAD TESTED
BATTERIES AND TESTED GOOD.

Parts

NO PARTS USED

Quantity

Workorder: V47820

In Date: 03/08/2012
Close Date: 03/16/2012

Meter Reading: 62,720.90

Problem?
TWO LEFT SIDED REAR STEP WHITE LIGHTS OUT. Sta 37

Task performed:

1. AIR LEAK, CHECKED FOR AIR LEAKS.
2. REPLACED WIPERS.

Parts

91-20WIPER BLADE 20 IN
91-22WIPER BLADE

Quantity

2
2

Workorder: V47954

In Date: 03/14/2012
Close Date: 04/02/2012

Meter Reading: 62,835.00

Problem?
NEW MOTOR OIL LEAK FROM E37 IN AREA OF MOTOR. UNABLE TO LOCATE EXACT AREA OF LEAK. E37

Task performed:

CHECKED FOR LAK - REPAIRED LEAK.

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V48051

In Date: 03/19/2012
Close Date: 04/02/2012

Meter Reading: 62,835.00

Problem?

WONT HANDLE LOAD WITH ELECTRIC FAN. SHUTS OFF. e 37

Task performed:

READJUSTED CARB AND TESTED.

Parts

NO PARTS USED

Quantity

Workorder: V48147

In Date: 03/23/2012
Close Date: 04/02/2012

Meter Reading: 63,062.90

Problem?

rear step lights are out

Task performed:

REPAIRED BAD GROUND ON STEP LIGHTS.

Parts

NO PARTS USED

Quantity

Workorder: V48400

In Date: 04/03/2012
Close Date: 04/10/2012

Meter Reading: 63,285.00

Problem?

E37 will not pump water unless primed first, even from on board tank

Task performed:

TRAVEL TO ST 37 CHECK OUT TK UNCAP ALL DISCHARGES AND INTAKE PUMP TK CHECK FOR LEAKS FOUND POSS LEAKS ON 2 1/2 INTAKES AND #4 DISCHARGE TK DIDN'T NEED PRIME TOW ORK. PUMP DON'T KNOW WHEN PROB. HAPPENS TK WORKED GOOD.

Parts

NO PARTS USED

Quantity

Workorder: V48449

In Date: 04/05/2012
Close Date: 04/20/2012

Meter Reading: 63,285.00

Problem?

Trouble getting prime while doing hose testing. Had to prime several times . Sta 37

Task performed:

FOUND NO PROBLEM GETTING PRIME.

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V48450

In Date: 04/05/2012
Close Date: 04/20/2012

Meter Reading: 63,285.00

Problem?

Preconnect 1 valve possibly leaking during hose testing. All connections checked, no water leaking, pressure wouldn't hold. Sta 3

Task performed:

VACUUM TESTED FOUND NO LEAKS.

Parts

NO PARTS USED

Quantity

Workorder: V48451

In Date: 04/05/2012
Close Date: 04/20/2012

Meter Reading: 63,285.00

Problem?

E37 still leaking oil. Sta 37

Task performed:

NO OIL LEAKS.

Parts

NO PARTS USED

Quantity

Workorder: V48538

In Date: 04/09/2012
Close Date: 04/20/2012

Meter Reading: 63,285.00

Problem?

left 2.5" intake leaks, center white strobes on front light bar do not function, and the generator will not operate while under load un after approximately 5 minutes of warm up. Sta 37

Task performed:

- 1. GENERATOR WILL NOT RUN.
- 2. STROBE LIGHT INOP.

Parts

NO PARTS USED

Quantity

Workorder: V48557

In Date: 04/10/2012
Close Date: 04/20/2012

Meter Reading: 63,285.00

Problem?

Engine 37 is leaking motor oil. Frequency has been increasing and is now a daily puddle under vehicle, sta 37

Task performed:

FOUND NO LEAKS.

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V48558

In Date: 04/10/2012 Meter Reading: 63,285.00
Close Date: 04/20/2012

Problem?

Front preconnect crosslay does not hold pressure. Handline was charged & bled off, nozzle and valve closed, and line quickly dro pressure. There are no leaks in the line or nozzle. sta 37

Task performed:

ADJUSTED VALVE LINKAGE AND TESTED.

Parts

NO PARTS USED

Quantity

Workorder: V48582

In Date: 04/11/2012 Meter Reading: 63,285.00
Close Date: 04/20/2012

Problem?

left intake valve leaking E37

Task performed:

RAN PUMP FOUND NO LEAK.

Parts

NO PARTS USED

Quantity

Workorder: V48583

In Date: 04/11/2012 Meter Reading: 63,285.00
Close Date: 04/20/2012

Problem?

e37 leaking oil

Task performed:

FOUND NO OIL LEAK, ONLY FROM DRIP TUBE.

Parts

15W40QSYN OIL QT

Quantity

12

Workorder: V48785

In Date: 04/20/2012 Meter Reading: 63,547.60
Close Date: 05/07/2012

Problem?

Engine is making a loud clunk the put in drive. e 37

Task performed:

CHECKED FOR CODES REPROGRAMMED SHIFT
ATTITUDE AND TEST DROVE.

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V49146

In Date: 05/07/2012

Meter Reading: 63,624.60

Close Date: 05/10/2012

Problem?

Fast adapt trans and test drive.

Task performed:

TEST DROVE - RAN TRANS-SHIFT PROGRAM - NO PROBLEMS FOUND RAN IN PUMP GEAR - CHECK OK.

Parts

NO PARTS USED

Quantity

Workorder: V48623

In Date: 04/12/2012

Meter Reading: 63,285.00

Close Date: 05/11/2012

Problem?

We would like to get some STA-BIL fuel stabilizer for our small engine gas can. We also need 4 more quarts of 15W-40 as we are down to one quart in reserve and our Engine continues to leak oil. Thank you sir. E37

Task performed:

NOTE: FOURTH TIME ON COMPLAINT ON OIL LEAK CHECKED FOUR TIMES AND THERE IS NO LEAK.

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V48867

In Date: 04/24/2012

Close Date: 05/17/2012

Meter Reading: 63,624.60

Problem?

C INSPECTION E37

Task performed:

Parts

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

1. C-Inspection.	0100030000SCREEN 6 IN	1
2. C-Inspection.	107796DRYER KIT AD9 -NEW	1
3. C-Inspection.	107800VALVE CHECK AD9	1
4. Install sacrificial anode into fire pump - pump had none - had to be at old cover off and grind surface for o-ring to seal on new anode cover assy.	1141BULB	8
5. Take oil samples of rear axle, pump trans and engine oil.	1142BULB	1
6. R&R 6 lenses R&R 6 bulbs in pump panel lts (4) and step lights (3).	15016KIT15016 PIN KIT	2
7. Fabricate new intake screen for front suction pipe - they don't make this size.	23-11345-714INSTRUMENT CLUSTER SCREWS 1 1/2 LON	1
8. R&R dash get numbers off Allison computer to order a new one. Also get serial number off trans I.D. tag.	2332920005SMASK LENS W/RST BUTTON VDO	1
9. Rear brake job.	3218K167ROTOR-BRAKE	2
10. Clean p/s reservoir, hoses and steering box to diagnose leak.	359-5990PLUG - HUB OIL CAP	2
11. Disassemble, clean, reassemble and adjust hose reel brake assy.	380003ASEAL	2
12. Clean lube, and adjust latches on battery tray door/step and trashline door/step.	401581GASKET AXLE FL80 R002435	2
13. Rear brake job.	529008000529-0080-10-0 1 1/4 ANODE KIT	1
14. L/R cab door light and screws holding light to door.	6256RJN6256RJN NUT-OUTER/RIGHT	2
15. R&R booster reel compartment light fixture.	681181583LIS68-1181583-LIS LENS AMBER	1
16. R&R 2 a/c registers in cab aux a/c unit - had to r&r l/r seat to disassemble a/c unit also tightened another register.	681181583RISLENS AMBER ARROW - RIGHT	1
17. R&R R/R cab door light lens and bulb. also R&R tag light bulb.	684-4 VALVE - FILL AIR TANK	2
18. R&R both front marker light lenses.	72R311018-2640 VENT A/C NEW # 1719	2
19. R&R both rear turn signal lenses.	78R536078R5360M 2PK FILTER AIR COND	1
20. Both front hubs leaking oil. Wash wheel covers and hub caps wash wheels and hubs install new fill caps and tighten window screws.	800405PURGE VALVE KIT	1
21. Rear brakes.	80344USE 62201	1
22. R&R L/R inner tire inflation hose - wrong one - won't fit holder bracket.	89BULB	2
23. Diagnose pump panel fuel gauge - Runs different than cab.	91513AMBER LENS	2
24. R&R clear dash board cover on instrument panel.	A13263M1157CALIPER ASSY ENGREAR L/H	1
25. Service AD-9 dryer.	A23263M1157CALIPER ASSY ENG REAR R/H	1
26. Diagnose pump panel arm counter. Remove inner cable broken - make a new inner cable with kit.	CA8193AIR FILTER 46744 WIX	1
27. Tighten exhaust system bracket mounted to comp. floor.	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
28. Reposition trans cooler. Move hose bracket to another hole in oil pan add hose protectors to stop hose rub on front axle.	H1422TSX STUD	2
29. Headset hooks in rear of cab have had over size screws so many times no screws in shop are big enough. Drill holes to accept nut serts. Install and attach head set hooks on r/ and left rear cab wall.	HLD39917DC23-5011 50 # HOLD-OPEN RESCUE	1
30. Tighten hold opens in R-1, R-3 and L-1. R&R hold open in L-3.	HPH6349AOIL FILTER 51748	1
	K022884NT3030ELS-80 LONG CHAMBER 30/30	2
	KIT15625PMAVEL SET	1
	PR338324070 WIX FILTER WATER	1
	R802462SLACK ADJ	2
	R802463SLACK ADJUSTER	1
	R90PFILTER FUEL 33231	1
	S4410325140R955342 SENSOR REAR ABS 4410328140	2



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

- 31. Remove hose bed cover - send out for repair.
- 32. R&R both sides crosslay nets.
- 33. R&R 3 sections of dash R&R cab computer mount. Repair and adjust heater control cables to repair no defroster condition.
- 34. Road test vehicle after brake job.
- 35. Rewrite labels on emer switch I.D. labels.
- 36. Test fit Scott air pac and make adjustments to 2 rear cab SCBA holders in seats.
- 37. Allison trans diagnosis.
- 38. R&R rear a/c condenser fan motor and fan.
- 39. Install hose bed cover and replace buckles at tail board end.
- 40. As per Ed Ehrke - do along road test. Check all electrical connections at trans sensors and trans main wiring connector also check connectors at trans computer - hard shifting not present during this time.

Workorder: V49906

In Date: 06/05/2012 **Meter Reading:** 64,197.00
Close Date: 06/15/2012

Problem?

I need: 2 spark plugs for K12 saw(NGK BPMR7A), a hydrant bag or heavy duty zip lock to isolate K12 blades from gasoline vapor 10 gallons of fire aide foam, and 6 of the 30" velcro straps for the coil pack. e 37

Task performed:	<u>Parts</u>	<u>Quantity</u>
repaired k-12 saw and tested unit.	NO PARTS USED	

Workorder: V49984

In Date: 06/08/2012 **Meter Reading:** 64,197.00
Close Date: 06/25/2012

Problem?

2 spark plugs and a new foam air filter for the Partner K950 k-12 saw E 37

Task performed:	<u>Parts</u>	<u>Quantity</u>
1. DROPPED OFF SUPPLIES AT STATION.	4626BPMR7A SPARK PLUG	2
2. READJUSTED TANK FILL LINKAGE THAT WAS LEAKING.		

Workorder: V50381

In Date: 06/25/2012 **Meter Reading:** 64,804.80
Close Date: 07/09/2012

Problem?

small screw on front officer tire removed. No air leak after screw was removed. E37

Task performed:	<u>Parts</u>	<u>Quantity</u>
CHECKED TIRE OK.	NO PARTS USED	



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V50015

In Date: 06/10/2012

Meter Reading: 64,197.00

Close Date: 07/13/2012

Problem?

MEDICAL COMPARTMENT ON E37 LEAKING HEAVILY. ECG MONITOR DAMAGED BADLY DUE TO THE AMOUNT OF WAT INFILTRATING THE COMPARTMENT. E 37

Task performed:

SEALED TOP OF DOOR THAT WAS LEAKING.

Parts

NO PARTS USED

Quantity

Workorder: V50224

In Date: 06/19/2012

Meter Reading: 64,601.00

Close Date: 07/13/2012

Problem?

Portable generator will not hold a load when switching it on, shuts down. Tried multiple times. e 37

Task performed:

FOUND NO PROBLEM WITH GENERATOR.

Parts

NO PARTS USED

Quantity

Workorder: V50380

In Date: 06/25/2012

Meter Reading: 64,804.80

Close Date: 07/13/2012

Problem?

Foam system is not working. When Foam is turned on it says "Lo A" on the screen. Unable to flow any foam. Foam tank was visually checked and full. E37

Task performed:

1. RAN FOAM SYSTEM AND TESTED OK.
2. REPAIRED CAB DOOR LATCHES THAT WERE HARD TO CLOSE.

Parts

NO PARTS USED

Quantity

Workorder: V50690

In Date: 07/09/2012

Meter Reading: 64,925.60

Close Date: 07/13/2012

Problem?

Flashlight on E37 not charging and only puts out extremely dim light. Tried swapping chargers to ensure charger was not problem and light is still dim.

Task performed:

1. REWIRED HAND LIGHT CHARGER TO BETTER GROUND.
2. AIR LEAK FOUND NO AIR LEAKS AT THIS TIME.

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V50839

In Date: 07/13/2012 Meter Reading: 65,228.70
Close Date: 07/25/2012

Problem?

E37 HAS A SQUEELING NOISE AT THE THROTTLE BODY

Task performed:

Parts

Quantity

1. RAN TRUCK AND ROAD TESTED, DID NOT HEAR ANY NOISE.
2. AIR LEAK FOUND NO AIR LEAKS AT THIS TIME.

NO PARTS USED

Workorder: V50796

In Date: 07/12/2012 Meter Reading: 65,228.70
Close Date: 08/03/2012

Problem?

White rear step light out and Wig-Wags are inoperative. e 37

Task performed:

Parts

Quantity

1. AIR LEAK - REPAIRED AIR LEAK AT PUMP SHIFTER.
2. REPAIRED WIG-WAGS FOUND BAD CONNECTION.

NO PARTS USED

Workorder: V50907

In Date: 07/17/2012 Meter Reading: 65,301.90
Close Date: 08/06/2012

Problem?

The honda generator EG3500 will not run longer than 2 minutes either under load or not. The asset # 10155570 is not listed in un the asset catalog. E37

Task performed:

Parts

Quantity

1. RAN GENERATOR AND CLEANED CARB AND RETESTED.

NO PARTS USED

Workorder: V50941

In Date: 07/18/2012 Meter Reading: 65,301.90
Close Date: 08/06/2012

Problem?

Medical compartment still not fixed. Heavy leak when it rains. \$30,000 egc monitor damaged for second time in less than 2 month E37

Task performed:

Parts

Quantity

1. REPAIRED LEAK IN MED COMPARTMENT.

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V51421

In Date: 08/07/2012
Close Date: 08/09/2012

Meter Reading: 65,781.80

Problem?

On board foam system will no supply foam to preconnects. numerous attemps made to flush it. Potable generator will not run for longer than 2 minutes before it cuts off. 2 back up lamps are out on rear of engine. E37

Task performed:

CHECKED FOAM SYSTEM - OK. REBUILT GENERATOR FUEL SWITCH - INSTALLED NEW STEP LIGHT BULBS.

Parts

1156BULB

Quantity

10

Workorder: V51423

In Date: 08/07/2012
Close Date: 08/09/2012

Meter Reading: 65,781.80

Problem?

Transmission is shifting very hard from neutral to drive. Entire truck lunges. E37

Task performed:

PERFORMED DIAGNOSTIC FOUND NO CODES - DID FAST ADAPT TESTED OK.

Parts

NO PARTS USED

Quantity

Workorder: V51551

In Date: 08/13/2012
Close Date: 09/13/2012

Meter Reading:

Problem?

winshield wipers and broken. glass on metal. E37

Task performed:

1. REPLACED WIPERS.

Parts

52-24WIPER BLADES ANCO 24

Quantity

2

Workorder: V51175

In Date: 07/27/2012
Close Date: 09/14/2012

Meter Reading:

Problem?

E37 SIREN CONTROL BUTTON ON STEERING WHEEL NOT WORKING.

Task performed:

1. CHKD TRUCK OK LOOSE CONNECTION.

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V51389

In Date: 08/06/2012

Meter Reading:

Close Date: 09/14/2012

Problem?

foam system failed on a fire. number 1 discharge foam not working

Task performed:

Parts

Quantity

RAN FOAM SYST AND TESTED OK FOUND FOAM SYST WORKING. REPAIRED PUMP LEAK AT FITTINGS ON PUMP.

NO PARTS USED

Workorder: V51979

In Date: 08/29/2012

Meter Reading:

Close Date: 09/20/2012

Problem?

1. hurst tool power unit only runs on choke 2. generator does not run on a full load/turns off E 37

Task performed:

Parts

Quantity

REPAIRED BY RAGAN.

NO PARTS USED

Workorder: V52100

In Date: 09/03/2012

Meter Reading:

Close Date: 09/20/2012

Problem?

weter tank on the engine is leaking E 37

Task performed:

Parts

Quantity

CHKD FOR LEAK-FOUND LEAK WILL HAVE REPAIRED.

NO PARTS USED

Workorder: V52319

In Date: 09/11/2012

Meter Reading:

Close Date: 10/01/2012

Problem?

tractor abs indicator light is on E 37

Task performed:

Parts

Quantity

FPUND NO LIGHT ON AT THIS TIME.

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V52376

In Date: 09/14/2012

Meter Reading:

Close Date: 10/01/2012

Problem?

TIC strap is broken and spare battery is not charging

Task performed:

REPLACED TIC CHARGER.

Parts

605-257AIR FILTER K950

Quantity

1

Workorder: V52744

In Date: 10/01/2012

Meter Reading:

Close Date: 10/16/2012

Problem?

Chainsaw needs a new blade e 37

Task performed:

INSTALLED NEW BLADE.

Parts

NO PARTS USED

Quantity

Workorder: V52786

In Date: 10/02/2012

Meter Reading:

Close Date: 10/16/2012

Problem?

front tires need to be replaced and we need oil for thr engine and rescue one case e 37

Task performed:

NEEDS NEW TIRES.

Parts

NO PARTS USED

Quantity

Workorder: V52875

In Date: 10/05/2012

Meter Reading:

Close Date: 10/16/2012

Problem?

hale foam system is reading LO V and is not working. front strobe light not working

Task performed:

FOUND NO PROBLEM WITH FOAM SYSTEM.
REPLACED FRT TROBE AND REWIRED.

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V52991

In Date: 10/10/2012
Close Date: 10/16/2012

Meter Reading: 67,214.00

Problem?

While doing morning truck check and using the primer. The volt meter would go to "LO" on pump guage and front dash. 1200rpm meter guage would go to "LO". E37

Task performed:

CHECKED OK.

Parts

NO PARTS USED

Quantity

Workorder: V53053

In Date: 10/12/2012
Close Date: 11/09/2012

Meter Reading:

Problem?

The small stick on reflector on the drivers side rear bumper broke off while removing traffic cones. Very minor. E 37

Task performed:

REPLACED REFLECTOR ON REAR.

Parts

NO PARTS USED

Quantity

Workorder: V53382

In Date: 10/30/2012
Close Date: 11/16/2012

Meter Reading:

Problem?

E 37 chain saw chain is dull. The spare chain is also dull. E 37

Task performed:

DC WILL GET NEW SAW FOR ST 37.

Parts

NO PARTS USED

Quantity

Workorder: V53803

In Date: 11/15/2012
Close Date: 11/19/2012

Meter Reading:

Problem?

While doing draft trainin,g Primer pump stopped working 15-20 seconds into priming the pump. Now when you go to pull the prime nothing happens.

Task performed:

PRIMER PUMP INOP MOTOR BURST REPLACED
PRIMER PUMP MOTOR ASSY.

Parts

501-3090-00PRIMER PUMP MOTOR

Quantity

1



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V53480

In Date: 11/01/2012

Meter Reading:

Close Date: 11/30/2012

Problem?

E37 AIR TANK IS EMPTY EVERY 6 TO 8 HRS

Task performed:

TRACED OUT AIR LEAKS.

Parts

NO PARTS USED

Quantity

Workorder: V54101

In Date: 11/30/2012

Meter Reading:

Close Date: 01/03/2013

Problem?

rear work light out on step and engineer's compartment door stop broken

Task performed:

STATUS INFO GAUGE INOP.

Parts

012-1510-05-0KNOB

101847ENGINE STATUS CTR

Quantity

1

1

Workorder: V54353

In Date: 12/10/2012

Meter Reading:

Close Date: 01/03/2013

Problem?

Map light is broken at base of wand. E 37

Task performed:

REPLACED MAP LIGHT.

Parts

LF18TS-LEDMAP LIGHT LED 18 IN

Quantity

1

Workorder: V54690

In Date: 12/28/2012

Meter Reading: 68,746.00

Close Date: 01/25/2013

Problem?

Engine battery will not charge. Power to cord. Truck checked for disconnected wires.

Task performed:

FOUND NOT POWER TO 110 CORD.

Parts

NO PARTS USED

Quantity



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V55062

In Date: 01/15/2013

Meter Reading: 69,067.50

Close Date: 02/12/2013

Problem?

air leak

Task performed:

INSTALLED PURGE VALVE AND TESTED.

Parts

K022105PURGE VALVE AD-IP-IS

Quantity

2



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V55852

In Date: 02/19/2013

Close Date: 03/07/2013

Meter Reading: 69,584.00

Problem?

B inspection

Task performed:

Parts

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

1. B-INSPECTION.
2. FAILED BATTERY TEST - REPLACE ALL BATTERIES.
3. BATT CHARGER INOP - FOUND WIRING BURNT UP AT CHARGE AND WIRING FOR REMOTE CHARGE INDICATOR BROKEN - REPAIR ALL WIRING AND RETEST - ALL OK.
4. REMOVE LEFT REAR CAB SEAT TO BE SENT OUT FOR REPAIR.
5. REPLACED 3 REAR STEP LIGHT BULBS. (BURNT)
6. REPLACE LEFT TAILBOARD REFLECTOR.
7. REPLACED WIPER BLADES, INSTALLED HOSE "T" FITTING FOR WINDSHIELD SKIRTTERS. CLEANED DIRT AND DEBRIS FROM SKIRTTERS.
8. CHECKED TRUCK FOR AIR LEAKS: FOUND TWO CONSIDERABLE LEAKS AT FOOT VALVE, REPLACED AND RESEALED FITTINGS, TRIMED AIR HOSE AND RECHECKED TRUCK. WILL CHECK AGAIN AFTER LUNCH.
9. RECHECK TRUCK AIR PRESSURE FOUND AIR PRESSURE HAD LEAK DOWN 20 PSI OVER LUNCH TIME. CHECKED TRUCK OVER AGAIN AND FOUND 1 MORE ADDITIONAL LEAK AT FOOT VALVE FITING. REPLACED AND RESEALED FITTING WILL RECHECK AGAIN FOR AIR LOSS.
10. REPLACED DRIVER'S CAB DOOR CHECK. (WORN/SIZED) ALSI, WHILE DOOR WAS OFF I CLEANED AND LUBED WINDOW REGULATOR. ALSO REPLACE DOOR TRIM. SECURED DOOR PANEL WITH EXTRA SCREWS. (LOOSE).
11. REPLACE 3 CAB DOOR WEATHERSTRIPS (TORN)
12. BEGAN CHECKING OUT ROCKER SWITCHES ON CENTER CONSOLE INOP.
13. CONTINUED CHECKING OUT MASTER SWITCH AND EMERGENCY LIGHT SWITCH ON CENTER CONSOLE. TRIED TO MAKE ALTERNATIVE SWITCHES WORK OUT COULD NOT. FINALLY FOUND CORRECT SWITCHES IN SERVICE TRUCK AND REPLACED.
14. CHECKED OUT HAND HELD SPOT LIGHT INOP. BENCH TESTED LIGHT, LIGHT WORKS. CHECKED FUSE, FOUND FUSE BURNT. REPLACED FUSE. LIGHT STILL INOP. REMOVED DASH FOUND WIRES TO OUTLET MELTED. REPLACED OUTLET IN DASH AND REPAIRED WIRES. LIGHT NOW WORKS NORMALLY.
15. CHECKED ROOF SPOT LIGHT INOP. TRACED PROBLEM TO FAULTY CONNECTION ON LIGHT ASSEMBLY. SECURED WIRES. COULD NOT GET LIGHT TO FAIL AGAIN.
16. RECEIVED SEAT BACK FROM UPHOLSTRY SHOP, REPAIRED MOUNTING BOLT HOLE THREADS (CROSSTHREADED). REINSTALLED SEAT WITH NEW BOLTS.

1141BULB	2
52-24WIPER BLADES ANCO 24	2
56415CIG. LIGHTER ACCES.	1
6806970098SEAL DOOR	1
6807200216DOOR CHECK ASSY	1
78R536078R5360M 2PK FILTER AIR COND	1
98032R 41032-3 RED REFLECTOR OVAL REFLECTOR	1
A1834388002MOLD L/H	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	4
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

- 17. REPLACED REAR A/C FILTER.
- 18. R&R LEFT REAR DOOR PANEL TO SECURE OUTSIDE DOOR LATCH (LOOSE). ALSO CLEANED AND LUBED WINDOW REGULATOR.
- 19. REPLACED FUEL GAUGE ON PUMP PANEL (INACCURATE). REWIRED HARNESS TO ACCEPT DIFFERENT TERMINALS ON NEW GAUGE.
- 20. DRILLED OUT BROKEN GREASE FITTING ON REAR OF DRAG LINK. REMOVED WITH SCREW EXTRACTOR. INSTALLED NEW GREASE FITTING AND GREASED JOINT.
- 21. GENTLY REMOVED FIRE RESCUE STICKERS FROM DRIVER'S SO'S NOT TO DAMAGE OR PEEL OLD PAINT.
- 22. CLEANED OFF DRIVER'S DOOR AND INSTALLED NEW FIRE RESCUE STICKERS.
- 23. CHECKED OVER TRUCK BEFORE RETURN TO STATION.

Workorder: V56437

In Date: 03/16/2013 Meter Reading: 70,202.80
Close Date: 03/22/2013

Problem?
Chain saw will not start. E37

Task performed:	<u>Parts</u>	<u>Quantity</u>
REPAIRED CHAIN SAW.	NO PARTS USED	

Workorder: V48548

In Date: 04/10/2012 Meter Reading:
Close Date: 04/08/2013

Problem?
E37 failed pump test. Disregard if this has already been submitted. Sta 37

Task performed:	<u>Parts</u>	<u>Quantity</u>
	NO PARTS USED	

Workorder: V48581

In Date: 04/11/2012 Meter Reading:
Close Date: 04/08/2013

Problem?
generator on the engine turn off under a load. E37

Task performed:	<u>Parts</u>	<u>Quantity</u>
	NO PARTS USED	



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V48684

In Date: 04/15/2012

Meter Reading:

Close Date: 04/08/2013

Problem?

Engine 37 shifts very hard from neutral to drive, and lunges somewhat. It does the same when going in and out of pump gear. We also need some new plastic funnels to fuel equipment as all are cracked that are on E37.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V50948

In Date: 07/18/2012

Meter Reading:

Close Date: 04/08/2013

Problem?

Medical equipment compartment is leaking heavily inside. Whenever the truck is driven in the rain the medical equipment inside gets soaked. Lifepack is having to be sent for service a second time due to getting wet. E37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V53147

In Date: 10/17/2012

Meter Reading:

Close Date: 04/08/2013

Problem?

foam float cylinder is broken and floating loose in the foam tank. needs to be replaced E37

Task performed:

Parts

Quantity

013-2020-02OBSOLETE 2011 CABLE 6 PIN HALE FOAM SY 1

013-2020-056 PIN CABLE HALE CONTROL 1

200-2700-00HALE CAFTEC TRANSORB ASSY. FOAM SYS 1

2510-0032FOAM PRO TANK FLOAT SENSOR 1

513-0320-04WIRING HARNES MST HALE 1

Workorder: V52833

In Date: 10/03/2012

Meter Reading: 66,934.10

Close Date: 04/09/2013

Problem?

REPLACE FRONT TIRES E37

Task performed:

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V56688

In Date: 03/28/2013
Close Date: 04/19/2013

Meter Reading: 108,428.00

Problem?

Hydraulic tool engine keeps throttling up and down after taken off of choke. After running a while, the throttling up and down appears to stop, but then starts again when the hydraulic tools are being operated. E 37

Task performed:	Parts	Quantity
REPAIRED THROTTLE SPRING AND RETESTED UNI	NO PARTS USED	

Workorder: V56689

In Date: 03/28/2013
Close Date: 04/19/2013

Meter Reading: 108,428.00

Problem?

2 of the white lights on the rear booster reel door are not working. E37

Task performed:	Parts	Quantity
REPAIRED GROUND ON ALL LIGHTS.	NO PARTS USED	

Workorder: V56959

In Date: 04/11/2013
Close Date: 04/26/2013

Meter Reading: 70,768.00

Problem?

Repair Hurst power unit E-37

Task performed:	Parts	Quantity
REPAIRED HURST CARB AND TEST OK.	NO PARTS USED	

Workorder: V57178

In Date: 04/21/2013
Close Date: 04/29/2013

Meter Reading: 70,971.80

Problem?

Hit station door E37

Task performed:	Parts	Quantity
REMOVED TRUCK FROM DOOR AND REPAIRED LIGHT BAR.	6811811495068-1181149-50 LENS	1
	9ECAPR9ECAPR END CAP RED	1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V57284

In Date: 04/26/2013

Meter Reading:

Close Date: 05/17/2013

Problem?

driver side rubber hood lock broke.

Task performed:

Parts

Quantity

1. REPLACED HOOD LATCH.
2. REAR CAB A/C INOP, RECHARGED.

680-880-01-60LATCH

1

Workorder: V57717

In Date: 05/14/2013

Meter Reading:

Close Date: 05/20/2013

Problem?

need a d flood light bulb.

Task performed:

Parts

Quantity

- TRAVEL TO ST 37 R&R D BULB ON LIGHT CHECK
TIRES ON RESCUE CALL FOR REPLACEMENT.

NO PARTS USED

Workorder: V57749

In Date: 05/15/2013

Meter Reading:

Close Date: 05/31/2013

Problem?

Hydraulic Cutters have two screws missing off the back side of the black housing near the thumb switch. The black housing is slightly loose. Please replace. In addition, E37 is requesting 2 quarts of Hydraulic fluid. E37

Task performed:

Parts

Quantity

1. REPAIRED CUTTER AND TESTED.
2. READJUSTED REAR DOORS THAT WERE HARD TO OPEN.

NO PARTS USED

Workorder: V57750

In Date: 05/15/2013

Meter Reading:

Close Date: 06/07/2013

Problem?

Both axe holders on both driver side compartment doors are broken/ cracked. Please replace. E37

Task performed:

Parts

Quantity

1. REPAIRED AXE HANDLES AND BRACKET.
2. HURST OIL-DROPPED OFF.

180R002HURST HYD. FLUID QT

2



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V58892

In Date: 07/06/2013
Close Date: 07/19/2013

Meter Reading: 72,173.00

Problem?

E37 belt is slipping. Audible 'sqeeling' when driving

Task performed:

Parts

Quantity

1. ROAD TESTED AND CHECKED BELTS.
2. REPAIRED TOP MOUNTED SPOTLIGHTS.

NO PARTS USED

Workorder: V59239

In Date: 07/22/2013
Close Date: 07/23/2013

Meter Reading: 17,732.80

Problem?

E37 air leak

Task performed:

Parts

Quantity

REPAIRED AIR LEAK AT TANK.

NO PARTS USED

Workorder: V59530

In Date: 08/03/2013
Close Date: 08/19/2013

Meter Reading: 73,024.60

Problem?

scew in the left front tire. E37

Task performed:

Parts

Quantity

1. AIR LEAK - REPAIRED LEAKS WERE NEEDED.
2. REPAIRED WATER LEAK AT FRONT OF WATER TANK.

NO PARTS USED

Workorder: V59605

In Date: 08/05/2013
Close Date: 08/19/2013

Meter Reading: 73,024.60

Problem?

Flushed and attempted to operate foam system... not functioning at all... last 2 car fires no foam... I know we are 'supposed' to be getting a new pumper, but would be nice to have this working if possible? Thanks :)

Task performed:

Parts

Quantity

RAN FOAM SYSTEM, SYSTEM WAS WORKING AT THIS TIME WILL NEED TO CHANGE SOME CABLES AT LATER TIME.

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V59728

In Date: 08/11/2013 Meter Reading: 73,024.60
Close Date: 08/30/2013

Problem?

Need spare sparkplugs for chainsaw. Thanks, E37

Task performed:

DROPPED OFF TOOLS AT STATION.

Parts

NO PARTS USED

Quantity

Workorder: V59741

In Date: 08/12/2013 Meter Reading: 73,024.60
Close Date: 08/30/2013

Problem?

need rear step light bulbs for e37

Task performed:

REPLACED BULBS WERE NEEDED.

Parts

NO PARTS USED

Quantity

Workorder: V60291

In Date: 09/05/2013 Meter Reading: 73,756.20
Close Date: 09/10/2013

Problem?

One set of hurst tool hoses does not allow fluid to flow

Task performed:

1. TRAVEL TO ST 37 TO REPLACE HURST HOSE CALLED IN BY JOHN M. THEY WANTED ANOTHER GREEN HOSE WILL RETURN WITH HOSE.
2. TRAVEL TOST 37 DROP OFF HURST HOSES.

Parts

353R091USE 353R403 HURST HOSE 16 GREEN

1

Quantity

Workorder: V60375

In Date: 09/08/2013 Meter Reading: 73,756.20
Close Date: 09/19/2013

Problem?

The deck gun discharge handle broke off and it is still operational but in the back up hole only. Also the panel lights would stay on for several minutes and then randomly shut off for a minute (kept repeating). E37

Task performed:

1. REPLACE DECK GUN HANDLE AND PIVOT.
2. DECK GUN VALVE HARD TO OPEN, REMOVE VALVE FOUND TRUNION WORN, TRY TO REPLACE WITH NEW VALVE, BUT WAS NOT WORKING, VALVE TURNED WRONG ??? LEAVE OFF SLOW CLOSE.

Parts

102AKRON LONG ARM RC-4

883088301201 3 IN SLO-CLOZ W/R1 HANDLE

1

1

Quantity



2/27/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V60062

In Date: 01/21/2014
Close Date: 01/23/2014

Meter Reading: 73,559.40

Problem?

HAD TO CAP RELIEF VALVE TO PASS DRY VACUUM TEST.

Task performed:

TRUCK WENT BACK TO SHOP.

Parts

NO PARTS USED

Quantity

Workorder: V63156

In Date: 01/06/2014
Close Date: 02/04/2014

Meter Reading: 2,026.00

Problem?

REPAIR FUEL SYSTEM

Task performed:

REPAIR FUEL SYSTEM.

Parts

NO PARTS USED

Quantity

Vendor? CUMMINS

Workorder: V59850

In Date: 08/16/2013
Close Date: 03/25/2014

Meter Reading:

Problem?

PUMP TEST AT HQ

Task performed:

REPAIRED AT SHOP.

Parts

NO PARTS USED

Quantity

Workorder: V63106

In Date: 03/24/2014
Close Date: 03/28/2014

Meter Reading:

Problem?

Primer inop

Task performed:

CHECK OUT FOUND PRIMERS SOLENOID BAD,
REPLACE WITH NEW ONE. OK.

Parts

2000071102000072100 SOLENOID HALE PRIMER

Quantity

1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V60358

In Date: 09/07/2013

Meter Reading:

Close Date: 04/16/2014

Problem?

engine not throttling up properly when in pump. E37

Task performed:

REPAIRED ON B INSPECTION.

Parts

Quantity

55790-135000008 ELECTRONIC THROTTLE 100076 FELS

1

Workorder: V65584

In Date: 04/09/2014

Meter Reading: 74,569.50

Close Date: 04/24/2014

Problem?

brakes scraping

Task performed:

1. START TO C/O TRUCK TO ADJUST BRAKES LEFT REAR CLEVES NOT MOVING NEED TO CHECK FOR BRAKES STICKING.

2. REMOVED REAR TIRES FOUND DISC BRAKE CALIPERS FROZEN NOT MOVING REBUILD SLIDE PINS INSTALLED NEW PADS AND ROTOR LEFT SIDE- SERVICED RIGHTS.

Parts

Quantity

15016KIT15016 PIN KIT

1

3218K167ROTOR-BRAKE

1

380003ASEAL

2

401581GASKET AXLE FL80 R002435

1

KIT15625PMAXEL SET

1

S4410325140R955342 SENSOR REAR ABS 4410328140

1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V61492

In Date: 10/24/2013

Meter Reading: 68,746.00

Close Date: 05/05/2014

Problem?

C inspection old E37

Task performed:

1. C INSP.
2. WIPER BLADES.
3. REPLACE REAR A/C FILTER.
4. REPLACE HOSE BED STRAPS AND SNAPS.
5. TIGHTEN ALL DOOR HOLD OPEN BRACKETS, REPLACE WORN BRACKETS, STRAIGHTEN BENT BRACKETS.
6. REPLACE ALL DISCHARGE CAP AND CLAMPS.
7. TIGHTEN ALL COMP TOOL HOLDERS, LOOSE.
8. STRAIGHTEN DECK GUN HANDLE.
9. R&R WATER PUMP, TENSIONER AND BULBS.
10. REPLACE BAD COOLANT AND HOSES.
11. SERVICE POWER STEERING.
12. SERVICE AIR DRYER.
13. REPLACE FRONT SUCTION AIR SWITCH.
14. SERVICE T-CASE.
15. STRAIGHTEN REAR DOOR TRFM.
16. CHECK FOR AIR LEAKS, REPLACE PARKING BRAKE VALVE, SWITCHES AND RELAY VALVE.
17. RESEAL TRANS RETARDER FITTINGS LEAKING.
18. REMOVE DRIVE SHAFT FLANGE AND SLIP JOINT, CLEAN OUT OLD GREASE, REINSTALL GREASE.
19. RUN AND LUBE PRIMER MOTOR.
20. TROUBLESHOOT TRUCK STILL HAS AIR LEAK, FOUND BAD CHECK VALVE ON AIR TANK.
21. TORQUE U-BOLTS.
22. REMOVE CLEAN AND REPLACE PUMP ANODE.
23. REPAIR DEFROSTER CABLE.
24. TROUBLEHOOT INTERMITTENT COMP DOOR OPEN WARNING.
25. TROUBLESHOOT DOOR OPEN ALARM FOUND TIP OF R-2 COMP SWITCH WORN AND NOT CONTACTING DOOR SWITCH REPLACE SWITCH.
26. REPLACE REAR TIRES WITH, WHEELS FROM BLDG 3.
27. REPLACE ALL COMPARTMENT DOOR HANDLES WITH LOCKING HANDLES.
28. REPLACE COMPARTMENT HANDLES.
29. FINISH REPLACE COMP DOOR HANDLES.

Parts

Quantity

101305002DH0007-5 BRACKET RIGHT	1
103081XR7 VALVE	1
103385NDRAIN COCK	3
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
108-12FBEADED CHAIN W/CONN 12	6
15W40BSYN OIL BULK QTS	23
279LSS1250D-RING HANDLE W/LOCK 101280008	5
3157TAIL LIGHT BULBS	1
35200-RLIGHT MARKER LED RED	1
39768315259022 GROOVED TENSIONER OLD#3936213	1
40896474309418 PUMP-WATER ISC REBUILT	1
473794C91KN32005/800064 QUICK RELEASE VALVE	1
52-24WIPER BLADES ANCO 24	2
52-624SWITCH DOOR	1
6805013082UPPER RAD.HOSE - SILICONE	1
78R536078R5360M 2PK FILTER AIR COND	1
800034VALVE PARKING BRK.	1
800405PURGE VALVE KIT	1
80351DOME LIGHT	2
9440BELT	1
9480BELT	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
FSC17492134NC SW PARK BK SPADE TYPE CONNECTOF	2
HPH6349AOIL FILTER 51748	1
K080716BELT	1
KN3117190555409 VALVE CHECK PRESSURE PROTECTE	1
MJTV5 VALVE AIR CONTROL	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
VML-S1414FILTER P/S	1
VML-T1264GASKET P/S COVER	1
VML-T1279WASHER P/S	1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V69383

In Date: 09/15/2014

Meter Reading: 75,301.00

Close Date: 09/17/2014

Problem?

Will not build air pressure. Air leak out of bottom of drier

Task performed:

No problem found and added coolant. No leaks found.

Parts

NO PARTS USED

Quantity





2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V70285

In Date: 10/20/2014

Close Date: 11/20/2014

Meter Reading: 75,301.00

Problem?

B inspection E95

Task performed:

Parts

Quantity



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

1. "B" inspection
2. Left rear cab door panel was falling off door-push pins on some were missing-others broken or stripped out redrill new holes and secure with ss-screws.
3. Replace rusted out light fixture-using revised light fixtures-necessary to install grounding circuit.
4. Left side step lights inop-Check out bulbs all ok. Trace back wiring and found broken wire-make necessary repairs.
5. Left front fender turn/clearance light assy was melted in light sockets-Replace entire assy.
- 6.Rear cluster, trio light fixture was inop. Remove entire cluster from rear bumper on bench. Disassemble fixture-found the ground circuit was corroded. Grind of corrosion and install all new connectors and wiring. Reassemble and reinstalled in bumper.
7. Left side center of vehicle turn marker light was very dim-Disconnect and remove. Found ground circuit was all corroded-grind out corrosion-retap body screw hole and install new eyelet on wire-Reinstall-now ok.
8. Wiper knock and clink when turned on-very loud on high speed. Remove and install left side if it is necessary to remove cowling from cab body for clearance. Reinstall cowling, pivots,pull arms and wiper arms.
9. Eng. compartment lights are inop-Check power to switch-SW bad. Replace-now found one light inop. Remove lens and replace bulb.
10. Both L1 and L2 compt. lights inop.-Check out light fixtures all ok. Check out door switches-both corroded badly replace both switches, now both ok.
11. Cent. take down lights in center of front light bar inop. Check out power to lights-all ok. Replace take down light assemble/reassemble light bar-retest, now ok.
12. Replace wiperblades.
13. Readjust washer nozzle on r/side as it spays on the hood-make proper adjustments.
14. Replace all batts and make repairs on 3 wire connector engs.
15. Batt slide drawer and trash line were hard to open-wash out and clean tracks and lube work drawers back and forth until they rolled freely-also locking latches were bound up. Clean and work them also to free up/
16. Replace all engine belts
17. Repair fuel tank fill cap
18. Defrosters when turned on do not operate properly dismantile dash to gain access to master control and cables-two of the cables attached to the control very loose and bent-straighten cables and secure to control-adjust doors and reassemble dash.
- 19-21. #1 and 3 discharge valves-L/side intake valve-trash line valve and tank to pump valve-All leaking water badly-remove each valve and rebuild on bench then reinstall- Note: tank to pump valve was too worn out-remove again and replace with new valve assy.

02038247700OBSOLETE OCSILLATER PIERCER ALERT	1
0772092772142 TRUNNION HAND	1
0773149TRUNION BALL BRASS	1
1141BULB	3
1156BULB	1
120257100C2030-7110-30 CLEAR DOME STEP	1
16-31438915 VALVE CORE A/C 3544706C1	2
160012-2012A EXPANSION VALVE 71R8301	1
52-24WIPER BLADES ANCO 24	2
52-624SWITCH DOOR	1
5582-10 82-2111 GROTE ON-OFF WEATHERPROOF	1
576403-3470 COMPRESSOR A/C 5720	1
6808200020LIGHT ASSY. TURN SIGNAL	1
71R755011-2624 TRINARY SWITCH A/C 1560	1
74R258607-2613A RED DOT DRIER 7127	1
78308930 AKRON 3 IN VALVE	1
91378905 VALVE KIT 2 IN AKRON	1
91388906 VALVE KIT 2.5 IN AKRON	3
9440BELT	1
9480BELT	1
AMH-1AMH-1 VALVE EXTENSION	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	4
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
GRO716SGRO716S MIRROR S/S	1
H6054USE CV TYPE SEALED BEAM	1
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
K080716BELT	1
KIT15625PMAXEL SET	1
LML-1102-0023CAB AIR BAG IS4007	2
LML-1350-0113AIR RIDE VALVE (CAB)	1
R802462SLACK ADJ	1
R90PFILTER FUEL 33231	1
SPR-908-028BELLOWS JOINT BELLOW	3
SPR-S4804WEATHER CAP FOR WIPERS	2
SPR-W58-1TEE PLASTIC	1
SPRC2157WASHER WIPER SHAFT	2
SPRGS39681SHAFT	1
SPRGS39902WIPER SHAFT	1



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

22-25. Rear A/C blows warm-install freon to make test. Note: system was so empty it wouldn't operate. Check for leaks-line at dryer leaking and big leak at expansion valve. Replace both vaccum and recharge system, pressures were too low on high side. Evacuate system and replace original compressor Note: one of the four mounting bolts was missing and the mounting eye on the other broken. When installing new compressor I found that spacers for the rear mounts were too short-make up shims to mount rear ears without breaking them. Vaccum and recharge system again. Now all cools good(39 degrees-40 degrees) reassemble rear wall unit after rechecking for leaks.

LINE 25-28 IS ON WO#71029

Workorder: V71029

In Date: 10/20/2014 Meter Reading: 75,301.00
Close Date: 11/20/2014

Problem?

B-inspection Continued from V70285

Task performed:

25. Check out problem with rear brake-shows that only r/side is operating-replace bad slack adjuster on l/side also cut chamber rod length to proper length. Reassemble and retest to proper adjustment-install new pads on r/side and also adjust-properly.

26-28. First spray check under and above vehicle with soapy/water solution found several fittings leaking. Repair all and retest vehicle still leaking badly, remove dash cluster and found l/fitting in dash leaking. Make repairs, retest still leaking air put on ear sensor and hand held monitor. Found leakage at cab lift system, change out both air bags and retest. Leaking now from cab lift sensor valve, replace valve assembly with ears. Check over entire vehicle from one end to the other, found one more leak coming from top fittings of front suction valve. One fitting was sandwiched between pump case housing and valve. Cut fitting in half to remove, refabbed to install new fitting. Retest now ok.

Parts

Quantity

NO PARTS USED

Workorder: V68138

In Date: 07/24/2014 Meter Reading:
Close Date: 12/22/2014

Problem?

1. Foam level gauge not working 2. Deckgun handle broken 3. Foam system works in simulated mode but will not turn on with on button. 4. Left middle t in light bar not workingurn signal not working 5. 1-White light

Task performed:

Parts

Quantity

NO PARTS USED



2/27/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142393

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V73057

In Date: 02/11/2015

Meter Reading:

Close Date: 03/13/2015

Problem?

transmission will not go into 4th gear lockup for pumping operations

Task performed:

Parts

Quantity

1. Run pump and checked operation and checked out ok.

NO PARTS USED

Workorder: V73170

In Date: 02/15/2015

Meter Reading:

Close Date: 03/16/2015

Problem?

handle for deck gun broke off

Task performed:

Parts

Quantity

1. R&R handle assembly found valve lever had bad angle-made new valve lever.

102AKRON LONG ARM RC-4

1

2. Assist Jerry S. With modification of valve lever.

X125QUAD SEAL FOR CROSSFIRE

1



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10142393) 2002 - FERRARA FL80 1250 Gpm Pumper

10142393

CSHOP-2015-1419

Comments: **E95 CLASS ONE PUMP INFO CENTER NEEDS TO BE REPLACED**

Date Opened 6-26-2015 Date Finished 7-17-2015 Meter 1 Reading: 75,970

TASKS PERFORMED

Q PARTS

FIRE PUMP

1 CLASS 1; ENGINE STATUS CTR

CSHOP-2015-2656

Comments: **WATER TEMP GAUGE ON PUMP PANEL INOP @TRAINING**

Date Opened 9-1-2015 Date Finished 9-23-2015 Meter 1 Reading: 75,970

TASKS PERFORMED

NO PARTS USED

TIRES & WHEELS

CSHOP-2015-3490

Comments: **PRIMER INOP ON E775 PRIMER MOTOR NEEDS REPLACED. NORRIS HAS ALREADY DIGNOSED THE PROBLEM @ TRAINING**

Date Opened 10-19-2015 Date Finished 11-5-2015 Meter 1 Reading: 75,970

TASKS PERFORMED

Q PARTS

PRIMING PUMP FIRE PUMP

1 PUMP; PRIMER PUMP MOTOR

CSHOP-2015-3797

Comments: **C-INSPECTION**

Date Opened 11-5-2015 Date Finished 11-6-2015 Meter 1 Reading: 78,894

TASKS PERFORMED

Q PARTS

PM SERVICE C

23 FLUID; SYN OIL BULK QTS
1 FILTER; FILTER FUEL 33231
1 FILTER; FILTER FUEL WIX 33422 PS8689 FRAM
1 FILTER; OIL FILTER 51748
1 FILTER; AIR FILTER 46744 WIX

Asset Work Order History 10142393

CSHOP-2015-3822

Comments: **REPAIRS FROM PM**

Date Opened 11-6-2015

Date Finished 11-23-2015

Meter 1 Reading: 78,894

TASKS PERFORMED

Q PARTS

WATER TANK LEVEL LIGHTS	1	NEWPART; HOSE & FITTINGS
FOAM SYSTEM	12	DECAL; LADDER OUT OF SERVICE STICKER
FIRE FIGHTING EQUIPMENT	1	GAUGE; GUAGE
PUMP PANEL	1	ORING; ORING KIT
RELIEF VALVE FIRE PUMP	1	PUMP; PISTON
PRIMING PUMP FIRE PUMP	1	STRAINER; STRAINER 6 IN
FIRE PUMP	2	STRAINER; STRAINER 2.5 IN
HOSE REEL	1	GASKET
EQUIPMENT MOUNTING BRACKETS	1	ANODE; ANODE ONLY
DISCHARGE GAUGE	1	HANDLE; MIV HANDLE
COOLING SYSTEM	1	CAMERA; SCREEN 6 IN
SPOT LIGHTS	1	ORING; O-RING
LIGHTING SYSTEM	3	CHAIN; BEADED CHAIN W/CONN 12
AUTO-EJECT	1	VALVE; GEAR BOX MIV VALVE
DIAGNOSE ELECTRICAL	1	SWITCH; SWITCH COVER
ELECTRICAL	1	GAUGE; GUAGE
FLUID	1	PLUG; PLUG RAD. DRAIN
OIL COOLER-HEAT EXCHANGER	36	FLUID; SYN OIL BULK QTS
FILTER	1	FILTER; 24070 WIX FILTER WATER
RESERVOIR	2	LENS; LENS CLEAR
AIR DRIER	1	LIGHT; LIGHT MARKER LED RED
AIR SYSTEM	1	BULB; BULB 12 VOLT
AIR HORN	1	REFLECTOR; 41032-3 RED REFLECTOR OVAL REFLECTOF
SAFTEY-EMERGENCY EQUIPMENT	1	LIGHT; AMBER CLEARANCE SIG.STAT 1030A
DOOR WEATHER MOLDING	2	REFLECTOR; REFLECT-AMBER
DOOR	1	LENS; LENS CLEAR
INSTRUMENTS-GAUGES-WARNING &	1	COVER; OVAL AUTO EJECT COVER
CABLES- HEATER-DEFROSTER	1	FUSE; FUSE 20AMP
HOSES-LINES & FITTINGS	1	FUSE; FUSE 25 AMP
AIR CONDITIONING	2	STEP; 2030-7110-30 CLEAR DOME STEP
	1	SWITCH; 76072-15-DC SWITCH SW76072
	1	COOLER; COOLER 14032
	6	FLUID; ALLISON TRANS FLUID GAL
	1	FILTER; 29548988 TRANS FILTER ALLISON
	1	FILTER; FILTER P/S
	1	DRYER; AIR DRYER
	1	VALVE; 401150 VALVE AIR SEAT
	1	COVER; MANSAYER COVER
	1	WINDOW; MOLD L/H
	1	SEAL; SEAL DOOR
	1	BRACKET; DH0007-5 BRACKET RIGHT
	1	SHOCK; 8 IN HOLD OPEN 30 LB

Asset Work Order History 10142393

CSHOP-2016-2338

Comments: **ENGINEER AT TRAINING**

Date Opened 5-16-2016 Date Finished 5-16-2016 Meter 1 Reading: 80,100

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
PRIMING PUMP FIRE PUMP

Service Requests:

05/16/2016 SERVICE REQUEST / 15: FOREIGN MATERIAL / REPAIR
THE PRIMER MOTOR SMELL LIKE IT IS BURNING. THERE WAS A SMELL OF ELECTRICAL BURNING WHILE DRAFTING
TRY IN BAY OPEN VALVES TO PUMP WORKING OK.

CSHOP-2016-3784

Comments: **TRAINING ENGINE**

Date Opened 8-4-2016 Date Finished 8-9-2016 Meter 1 Reading: 80,100

TASKS PERFORMED

Q PARTS

BRAKES

2 NEWPART; BRAKE CHAMBER 16" FRONT

Service Requests:

08/04/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
FRONT INTAKE PLUMBING BROKEN OFF RIGHT FRONT AIR BRAKE CHAMBER DAMAGED

CSHOP-2016-3886

Date Opened 8-9-2016 Date Finished 8-9-2016 Meter 1 Reading: 80,100

TASKS PERFORMED

NO PARTS USED

FIRE FIGHTING EQUIPMENT

VENDOR? REGANS SMALL ENGINE SERVICE

CSHOP-2016-4057

Comments: **C SERVICE BY H2**

Date Opened 8-16-2016 Date Finished 8-18-2016 Meter 1 Reading: 81,167

TASKS PERFORMED

Q PARTS

PM SERVICE C

1 FILTER; FILTER FUEL 33231
1 FILTER; FILTER FUEL WIX 33422 PS8689 FRAM
1 FILTER; 24070 WIX FILTER WATER
1 FILTER; OIL FILTER 51748
1 FILTER; AIR FILTER 46744 WIX

Asset Work Order History 10142393

CSHOP-2016-4120

Date Opened 8-22-2016 Date Finished 9-13-2016 Meter 1 Reading: 81,121

TASKS PERFORMED

	Q	PARTS
FIRE APPARATUS	1	BULB; BULB
LIGHTING SYSTEM	1	SWITCH; SWITCH PRESSURE ALLISON
TRANSFER CASE	1	SWITCH; SWITCH TRANS
AIR DRIER	1	VALVE; VALVE CHECK AD9
SAFTEY-EMERGENCY EQUIPMENT	1	DRYER; DRYER KIT AD9 -NEW
BODY EXTERIOR	1	VALVE; PURGE VALVE KIT
A/C FILTER SCREENS	1	COVER; MANSAYER COVER
	4	BUMPER; BOLT BUMPER
	1	FREIGHTLINER; FUEL SENDING UNIT
	1	NEWPART; HOSE & FITTINGS
	1	GASKET; FUEL SENDER GASKET M2
	1	NEWPART; HOSE & FITTING
	1	FILTER; 78R5360M 2PK FILTER AIR COND

CSHOP-2017-3637

Date Opened 6-20-2017 Date Finished 6-20-2017 Meter 1 Reading: 82,787

TASKS PERFORMED

	Q	PARTS
BATTERY	4	1AD; BATTERY 31 SERIES

Service Requests:

06/20/2017 STARTER / 43: WEAK / REPLACE
VEHICLE WILL NOT START BATTERIES WILL NOT HOLD CHARGE OVER NIGHT BATTERIES ALMOST THREE YEARS OLD

CSHOP-2017-3885

Date Opened 6-30-2017 Date Finished 7-20-2017 Meter 1 Reading: 83,157

TASKS PERFORMED

	Q	PARTS
FIRE PUMP PLUMBING	1	5TF; CUP SEAL
	1	5TF; CUP SEAL
	2	9IP; DECK GUN ROTATION LOCK INSERT

Service Requests:

06/30/2017 SERVICE REQUEST / 12: BROKEN / REPLACED
SERVICE REQUEST DECK GUN SWIVEL LOCK BROKEN AND O-RING IN DECK GUN NOT SEALING

CSHOP-2017-4237

Date Opened 7-20-2017 Date Finished 8-24-2017 Meter 1 Reading: 83,273

TASKS PERFORMED

	Q	PARTS
INTAKE MANIFOLD	1	5TN; STRAINER

Service Requests:

07/20/2017 SERVICE REQUEST / 12: BROKEN / INSPECT
SERVICE REQUEST 2.5" INTAKE SCREEN MISSING FROM RIGHT INTAKE VALVE ON PUMP PANEL

Asset Work Order History 10142393

CSHOP-2017-4480

Date Opened 8-2-2017 Date Finished 8-10-2017 Meter 1 Reading: 83,273

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
INSTRUMENTS-GAUGES-WARNING &

Service Requests:

08/02/2017 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
SERVICE REQUEST STATUS CENTER ON PUMP PANEL NOT WORKING

CSHOP-2017-4622

Date Opened 8-9-2017 Date Finished 8-24-2017 Meter 1 Reading: 83,273

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 1WL; BULB

Service Requests:

08/09/2017 SERVICE REQUEST / 12: BROKEN / REPAIR
SERVICE REQUEST EMERGENCY LIGHT OUT ON UPPER LEFT REAR WARNING LIGHT

CSHOP-2017-4999

Date Opened 8-25-2017 Date Finished 8-30-2017 Meter 1 Reading: 83,273

TASKS PERFORMED

Q PARTS

COMMERCIAL WORK - OUTSIDE AGENCY
FAULT CODE

2 2CU; SENSOR

VENDOR? REGANS SMALL ENGINE SERVICE

Service Requests:

08/25/2017 SERVICE REQUEST / 38: SHORTED / EXCHANGE - NEW
SERVICE REQUEST CHECK ENGINE LIGHT COMES ON

CSHOP-2017-5682

Comments: **TRAINING ENGINE**

Date Opened 9-29-2017 Date Finished 10-25-2017 Meter 1 Reading: 83,772

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
COMMERCIAL WORK - OUTSIDE AGENCY
FIRE PUMP PLUMBING

1 9IP; AKRON LONG ARM RC-4

Service Requests:

09/29/2017 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
SERVICE REQUEST DECK GUN HANDLE BROKEN

Asset Work Order History 10142393

CSHOP-2017-681

Comments: **TRAINING**

Date Opened 2-1-2017

Date Finished

2-6-2017

Meter 1 Reading:

81,167

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

01/31/2017

ENGINE / 43: WEAK / INSPECT
ENGINE CHECK ENGINE LIGHT ON

CSHOP-2017-950

Date Opened 2-15-2017

Date Finished

3-13-2017

Meter 1 Reading:

81,167

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP PLUMBING
PRIMING PUMP FIRE PUMP

1 NONSTOCK; FREIGHT CHARGE
6 9AP; ROLLER MACHINED
6 9AP; RIGHT PAWL PLASTIC PIN
6 9AP; LEFT PAWL PLASTIC PIN
1 9IP; 2000072100 SOLENOID HALE PRIMER

CSHOP-2018-188

Comments: **PREP FOR SURPLUS**

Date Opened 1-9-2018

Date Finished

1-12-2018

Meter 1 Reading:

84,603

TASKS PERFORMED

Q PARTS

SURPLUS PREP
FIRE APPARATUS

1 9AP; HAND SOAP PUM (TOTAL TRK)