

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10183699    2011 FORD ESCAPE Suv, Mid-Size, 4X4, Hybrid**

**Workorder:** 1104934    **Meter:** 307    **In Date:** 05/10/2011    **Closed:** 05/13/2011

**Problem:** reseal rear tail lights, where strobes mount

|   |                                |              |
|---|--------------------------------|--------------|
| - Reseal tank light so strobe bulbs wont leak | <b>Parts List</b>              | <b>Qty</b>   |
| - Shop Supplies                               | Shop Supplies                  | 1.00         |
|   | 82194 Gray Silicone (permatex) | 1.00         |
| Hours 1.00                                    | Labor: 60.00                   | Parts: 8.56  |
| :   |                                | Total: 68.56 |

**Workorder:** 1104944    **Meter:** 0    **In Date:** 05/10/2011    **Closed:** 05/10/2011

**Problem:** Pre Delivery Inspection

|                           |               |             |               |
|---------------------------|---------------|-------------|---------------|
| - Pre Delivery Inspection |               |             |               |
| - Wash Vehicle            |               |             |               |
| Hours 3.00                | Labor: 180.00 | Parts: 0.00 | Total: 180.00 |
| :                         |               |             |               |

**Workorder:** 1105094    **Meter:** 319    **In Date:** 05/12/2011    **Closed:** 05/12/2011

**Problem:** 1 - Wash ticket(s) issued

|                             |             |             |             |
|-----------------------------|-------------|-------------|-------------|
| - 1 - Wash ticket(s) issued |             |             |             |
| Hours 0.00                  | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| :                           |             |             |             |

**Workorder:** 1111953    **Meter:** 5053    **In Date:** 11/07/2011    **Closed:** 11/17/2011

**Problem:** P.M. service.

|                                   |                                      |               |
|-----------------------------------|--------------------------------------|---------------|
| - P.m. Service.                   | <b>Parts List</b>                    | <b>Qty</b>    |
| - Rotate and balance all tires.   | Shop Supplies                        | 1.00          |
| - Service and adjust rear brakes. | 1348 Oil Filter Frm Ph3614 Wix 51348 | 1.00          |
| - Shop Supplies                   | 1066 White Lithium (crc 05037)       | 1.00          |
|                                   | 5w20 Engine Oil                      | 5.00          |
| Hours 4.75                        | Labor: 285.00                        | Parts: 20.04  |
| :                                 |                                      | Total: 305.04 |

**Workorder:** 1200941    **Meter:** 6654    **In Date:** 01/30/2012    **Closed:** 01/30/2012

**Problem:** Right rear tire went flat.

|                                       |                   |              |
|---------------------------------------|-------------------|--------------|
| - Repair and balance right rear tire. | <b>Parts List</b> | <b>Qty</b>   |
| - Shop Supplies                       | Shop Supplies     | 1.00         |
| Hours 1.00                            | Labor: 60.00      | Parts: 2.00  |
| :                                     |                   | Total: 62.00 |

**Workorder:** 1200963    **Meter:** 6654    **In Date:** 01/30/2012    **Closed:** 01/30/2012

**Problem:** passenger Rear flat tire

|   |             |             |             |
|---|-------------|-------------|-------------|
| - Tire Service 8100 Forest Hill Blvd - passenger Rear flat tire |             |             |             |
| Hours 0.00  | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| :   |             |             |             |

**Palm Beach County Fleet Management  
Asset Maintenance History**

|   |                     |                                      |                           |
|---|---------------------|--------------------------------------|---------------------------|
| <b>Workorder:</b> 1206135   | <b>Meter:</b> 9820  | <b>In Date:</b> 06/29/2012           | <b>Closed:</b> 07/17/2012 |
| <b>Problem:</b> P.M. Service.   |                     |                                      |                           |
| - P.m. Service.   |                     | <b>Parts List</b>                    | <b>Qty</b>                |
| - Service and adjust rear brakes.   |                     | Shop Supplies                        | 1.00                      |
| - Rotate and balance all tires.   |                     | 1348 Oil Filter Frm Ph3614 Wix 51348 | 1.00                      |
| - Transport vehicle to dealer for leaking a/c condensor.                      |                     | 5w20 Engine Oil                      | 5.00                      |
| - Shop Supplies   |                     | Ww-2046 Wiper Blade (motorcraft)     | 2.00                      |
| Hours 6.75  | Labor: 405.00       | Parts: 57.80                         | Total: 462.80             |
| :   |                     |                                      |                           |
| <b>Workorder:</b> 1210845   | <b>Meter:</b> 12545 | <b>In Date:</b> 11/06/2012           | <b>Closed:</b> 11/08/2012 |
| <b>Problem:</b> low tire pressure   |                     |                                      |                           |
| - repair right rear tire  |                     | <b>Parts List</b>                    | <b>Qty</b>                |
| - Shop Supplies   |                     | Shop Supplies                        | 1.00                      |
| Hours 1.00  | Labor: 60.00        | Parts: 2.00                          | Total: 62.00              |
| :   |                     |                                      |                           |
| <b>Workorder:</b> 1301946   | <b>Meter:</b> 14759 | <b>In Date:</b> 02/26/2013           | <b>Closed:</b> 03/18/2013 |
| <b>Problem:</b> P.M. service and check A/C.                                   |                     |                                      |                           |
| - P.m. Service.   |                     | <b>Parts List</b>                    | <b>Qty</b>                |
| - Service and adjust rear brakes.   |                     | Filter                               | 1.00                      |
| - Rotate and balance all tires.   |                     | 5w20 Engine Oil                      | 5.00                      |
| - Transport vehicle to dealer for a/c concern.(unable to<br>dulicate problem) |                     | Ca10170 Air Filter Lb                | 1.00                      |
|   |                     | 05046 Battery Protect                | 1.00                      |
| - Shop Supplies   |                     | Shop Supplies                        | 1.00                      |
| Hours 6.75  | Labor: 405.00       | Parts: 51.04                         | Total: 456.04             |
| :   |                     |                                      |                           |
| <b>Workorder:</b> 1302544   | <b>Meter:</b> 14497 | <b>In Date:</b> 03/13/2013           | <b>Closed:</b> 03/13/2013 |
| <b>Problem:</b> 1 - Detail Vehicle Wash Ticket(s) Issued                      |                     |                                      |                           |
| - 1 - Detail Vehicle Wash Ticket(s) Issued                                    |                     |                                      |                           |
| Hours 0.00  | Labor: 0.00         | Parts: 0.00                          | Total: 0.00               |
| :   |                     |                                      |                           |
| <b>Workorder:</b> 1310407   | <b>Meter:</b> 19508 | <b>In Date:</b> 10/16/2013           | <b>Closed:</b> 11/18/2013 |
| <b>Problem:</b> P.M. service and check sync system.                           |                     |                                      |                           |
| - P.m. Service.   |                     | <b>Parts List</b>                    | <b>Qty</b>                |
| - Service and adjust rear brakes.   |                     | Napagold Oil Filter                  | 1.00                      |
| - Rotate and balance all tires.   |                     | 5w20 Engine Oil                      | 5.00                      |
| - Transport vehicle to dealer for inop Sync system.(bad<br>radio)             |                     | Wiper Blade                          | 2.00                      |
|   |                     | Ww-1202 Wiper Blade M                | 1.00                      |
| - Shop Supplies   |                     | Shop Supplies                        | 1.00                      |
| Hours 6.75  | Labor: 405.00       | Parts: 62.71                         | Total: 467.71             |
| :   |                     |                                      |                           |
| <b>Workorder:</b> 1311426   | <b>Meter:</b> 19249 | <b>In Date:</b> 11/12/2013           | <b>Closed:</b> 11/12/2013 |
| <b>Problem:</b> 1 - Detail Vehicle Wash Ticket(s) Issued                      |                     |                                      |                           |
| - 1 - Detail Vehicle Wash Ticket(s) Issued                                    |                     |                                      |                           |
| Hours 0.00  | Labor: 0.00         | Parts: 0.00                          | Total: 0.00               |
| :   |                     |                                      |                           |

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1405117      **Meter:** 22216      **In Date:** 05/27/2014      **Closed:** 06/10/2014

**Problem:** P.M. service and check engine light on.

|   |                               |               |
|---|-------------------------------|---------------|
| - P.m. Service.   | <b>Parts List</b>             | <b>Qty</b>    |
| - Diagnose check engine light.p0455.perform evap system bay test and pin-point test.replace dfective vent valve.clear codes and re-run test.pass. | 5w20 Engine Oil               | 5.00          |
| - Service and adjust rear brakes.   | Napagold Oil Filter           | 1.00          |
| - Rotate and balance all tires.   | Washer FI                     | 1.00          |
| - Shop Supplies   | canister vent valve tube fuel | 1.00          |
|   | Shop Supplies                 | 1.00          |
| Hours 6.75  | Labor: 405.00                 | Parts: 171.07 |
| :   |                               | Total: 576.07 |

**Workorder:** 1405515      **Meter:** 21939      **In Date:** 06/04/2014      **Closed:** 06/04/2014

**Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

|  |            |             |             |             |
|--|------------|-------------|-------------|-------------|
| - 1 - Detail Vehicle Wash Ticket(s) Issued | Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
|  | :          |             |             |             |

**Workorder:** 1411933      **Meter:** 27545      **In Date:** 11/26/2014      **Closed:** 12/10/2014

**Problem:** Pm service.Request to detail vehicle.

|   |                       |               |                 |
|---|-----------------------|---------------|-----------------|
| - Pm service.   | <b>Parts List</b>     | <b>Qty</b>    |                 |
| - Check battery and charging system.battery failed loadtest after recharge.replace defective battery. | Wiper Blade           | 2.00          |                 |
| - Replace and balance all four tires.   | Ww-1202 Wiper Blade M | 1.00          |                 |
| - Complete four wheel alignment.test drive.   | Washer Fluid Concentr | 1.00          |                 |
| - Inspect and service rear drum brakes.   | Battery               | 1.00          |                 |
| - Shop Supplies   | Bat Term Protector    | 1.00          |                 |
|   | 183407418 P235-70r16  | 4.00          |                 |
|   | 5w20 Engine Oil       | 5.00          |                 |
|   | Napagold Oil Filter   | 1.00          |                 |
|   | Shop Supplies         | 1.00          |                 |
|   | Tire Disposal Fee     | 4.00          |                 |
| Hours 9.25  | Labor: 555.00         | Parts: 976.27 | Total: 1,531.27 |
| :   |                       |               |                 |

**Workorder:** 1412351      **Meter:** 27545      **In Date:** 12/10/2014      **Closed:** 12/10/2014

**Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

|  |            |             |             |             |
|--|------------|-------------|-------------|-------------|
| - 1 - Detail Vehicle Wash Ticket(s) Issued | Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
|  | :          |             |             |             |

**Workorder:** 1505871      **Meter:** 32508      **In Date:** 06/12/2015      **Closed:** 06/18/2015

**Problem:** P.M. service.

|                                      |                       |              |               |
|--------------------------------------|-----------------------|--------------|---------------|
| - Pm service.                        | <b>Parts List</b>     | <b>Qty</b>   |               |
| - Service rear brakes.               | 5w20 Engine Oil       | 5.00         |               |
| - Rotate and balance all four tires. | Napagold Oil Filter   | 1.00         |               |
| - Shop Supplies                      | Wiper Blade           | 2.00         |               |
|                                      | Ww-1202 Wiper Blade M | 1.00         |               |
|                                      | Shop Supplies         | 1.00         |               |
| Hours 4.75                           | Labor: 285.00         | Parts: 68.54 | Total: 353.54 |
| :                                    |                       |              |               |

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1600335      **Meter:** 37226      **In Date:** 01/11/2016      **Closed:** 01/27/2016  
**Problem:** Pm service.

|                                      |                       |               |
|--------------------------------------|-----------------------|---------------|
| - Pm service.                        | <b>Parts List</b>     | <b>Qty</b>    |
| - Inspect and service rear brakes.   | 5w20 Engine Oil       | 5.00          |
| - Rotate and balance all four tires. | Napagold Oil Filter   | 1.00          |
| - Shop Supplies                      | Napagold Air Filter   | 1.00          |
|                                      | Wiper Blade           | 2.00          |
|                                      | Ww-1202 Wiper Blade M | 1.00          |
|                                      | Shop Supplies         | 1.00          |
| Hours 4.75                           | Labor: 285.00         | Parts: 76.15  |
| :                                    |                       | Total: 361.15 |

**Workorder:** 1604684      **Meter:** 41662      **In Date:** 05/04/2016      **Closed:** 05/13/2016  
**Problem:** P.M. Service.A/C not cold.Detail

|  |                       |                 |
|--|-----------------------|-----------------|
| - P.m. Service.  | <b>Parts List</b>     | <b>Qty</b>      |
| - Pressure test and inspect engine and hybrid cooling systems.flush and refill both systems.   | 5w20 Engine Oil       | 5.00            |
| - A/c performance test.,system low on freon.replace leaking condensor,accumulator and expansion valve.vacuum and recharge system to specs. | Napagold Oil Filter   | 1.00            |
| - Rotate and balance all tires.  | Wiper Blade           | 2.00            |
| - Service and adjust rear brakes.  | Washer Fluid Concentr | 1.00            |
| - Shop Supplies  | Ww-1202 Wiper Blade M | 1.00            |
|  | Ford Red Antifreeze   | 2.00            |
|  | Condenser Ac          | 1.00            |
|  | R134a Lv Shop 2       | 2.00            |
|  | Oil                   | 1.00            |
|  | Cap And Valve Kit     | 1.00            |
|  | Accumulator           | 1.00            |
|  | Expansion Valve       | 1.00            |
|  | Rapid Seal Kit        | 1.00            |
|  | dehydrator            | 1.00            |
|  | Shop Supplies         | 1.00            |
|  | Freight Charge        | 1.00            |
| Hours 11.75  | Labor: 705.00         | Parts: 863.84   |
| :  |                       | Total: 1,568.84 |

**Workorder:** 1604943      **Meter:** 41500      **In Date:** 05/12/2016      **Closed:** 05/12/2016  
**Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

|  |            |             |             |             |
|--|------------|-------------|-------------|-------------|
| - 1 - Detail Vehicle Wash Ticket(s) Issued | Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| :  |            |             |             |             |

**Workorder:** 1605373      **Meter:** 42533      **In Date:** 05/24/2016      **Closed:** 05/24/2016  
**Problem:** 2 - Wash ticket(s) issued

|                             |            |             |             |             |
|-----------------------------|------------|-------------|-------------|-------------|
| - 2 - Wash ticket(s) issued | Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| :                           |            |             |             |             |

**Palm Beach County Fleet Management  
Asset Maintenance History**

|  |                       |                            |                           |
|--|-----------------------|----------------------------|---------------------------|
| <b>Workorder:</b> 1609306  | <b>Meter:</b> 51520   | <b>In Date:</b> 09/07/2016 | <b>Closed:</b> 09/27/2016 |
| <b>Problem:</b> P.M. service and left rear tire going flat and washers inop and detail.  |                       |                            |                           |
| - P.m. Service.  | <b>Parts List</b>     | <b>Qty</b>                 |                           |
| - Inspect and service rear differential.   | 5w20 Engine Oil       | 5.00                       |                           |
| - Repair left rear tire,rotate and balance all four.   | Napagold Oil Filter   | 1.00                       |                           |
| - Shop Supplies  | Wiper Blade           | 2.00                       |                           |
|  | Ww-1202 Wiper Blade M | 1.00                       |                           |
|  | 75w140 Ford Axle Lube | 1.00                       |                           |
|  | Shop Supplies         | 1.00                       |                           |
| Hours 5.75   | Labor: 345.00         | Parts: 92.09               | Total: 437.09             |
| :  |                       |                            |                           |
| <b>Workorder:</b> 1609536  | <b>Meter:</b> 50891   | <b>In Date:</b> 09/13/2016 | <b>Closed:</b> 09/13/2016 |
| <b>Problem:</b> 1 - Detail Vehicle Wash Ticket(s) Issued   |                       |                            |                           |
| - 1 - Detail Vehicle Wash Ticket(s) Issued   |                       |                            |                           |
| Hours 0.00   | Labor: 0.00           | Parts: 0.00                | Total: 0.00               |
| :  |                       |                            |                           |
| <b>Workorder:</b> 1610827  | <b>Meter:</b> 52816   | <b>In Date:</b> 10/20/2016 | <b>Closed:</b> 10/31/2016 |
| <b>Problem:</b> ABS light comes on at times.   |                       |                            |                           |
| - Diagnose Abs light.c1029.replace Hcu.flush and bleed system.clear code.  | <b>Parts List</b>     | <b>Qty</b>                 |                           |
| - Shop Supplies  | A . B . S . Module    | 1.00                       |                           |
|  | B Fluid Dot 3-32oz    | 4.00                       |                           |
|  | Non-chlor Brake Clnr  | 2.00                       |                           |
|  | Shop Supplies         | 1.00                       |                           |
| Hours 5.00   | Labor: 300.00         | Parts: 1,643.53            | Total: 1,943.53           |
| :  |                       |                            |                           |
| <b>Workorder:</b> 1612902  | <b>Meter:</b> 55127   | <b>In Date:</b> 12/16/2016 | <b>Closed:</b> 01/02/2017 |
| <b>Problem:</b> P.M. service and tire pressure light on.   |                       |                            |                           |
| - P.m. Service.  | <b>Parts List</b>     | <b>Qty</b>                 |                           |
| - Flush and refill transmission.   | 5w20 Engine Oil       | 6.00                       |                           |
| - Rotate and balance tires.  | Napagold Oil Filter   | 1.00                       |                           |
| - Service and adjust rear brakes.  | Wiper Blade           | 2.00                       |                           |
| - Shop Supplies  | Accufit Rear          | 1.00                       |                           |
|  | Syn-atf Trans Fluid S | 6.00                       |                           |
|  | Shop Supplies         | 1.00                       |                           |
| Hours 6.25   | Labor: 375.00         | Parts: 82.78               | Total: 457.78             |
| :  |                       |                            |                           |
| <b>Workorder:</b> 1701940  | <b>Meter:</b> 57805   | <b>In Date:</b> 02/24/2017 | <b>Closed:</b> 03/13/2017 |
| <b>Problem:</b> A/C not cold ,left rear tire going flat and detail.  |                       |                            |                           |
| - A\c performance test,low freon.recharge system and test for leaks.replace condensor seals.vacuum and recharge system to specs. | <b>Parts List</b>     | <b>Qty</b>                 |                           |
| - Replace and balance left rear tire.  | Seal Kits             | 2.00                       |                           |
| - Shop Supplies  | Oil                   | 1.00                       |                           |
|  | Freon Lv Shop 2       | 2.00                       |                           |
|  | Shop Supplies         | 1.00                       |                           |
| Hours 4.00   | Labor: 240.00         | Parts: 112.09              | Total: 352.09             |
| :  |                       |                            |                           |

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1702133      **Meter:** 57540      **In Date:** 03/01/2017      **Closed:** 03/01/2017  
**Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

**Workorder:** 1705014      **Meter:** 60378      **In Date:** 05/19/2017      **Closed:** 05/25/2017  
**Problem:** P.M. service.

- P.m. service.

**Parts List**

**Qty**

|   |                       |      |
|---|-----------------------|------|
| - Remove instrument clusterpanel and replace faulty dimmer resistor due to binding. | 5w20 Engine Oil       | 5.00 |
| - Remove front and rear asset number decals faded.replace with new.                 | Napagold Oil Filter   | 1.00 |
| - Inspect and service rear brakes.  | Wiper Blade           | 2.00 |
| - Rotate and balance four tires.  | Accufit Rear          | 1.00 |
| - Shop Supplies   | Washer Fluid Concentr | 1.00 |
|   | Dimmer Switch         | 1.00 |
|   | Shop Supplies         | 1.00 |

Hours 5.85      Labor: 351.00      Parts: 71.42      Total: 422.42  
:

**Workorder:** 1705600      **Meter:** 60485      **In Date:** 06/06/2017      **Closed:** 06/21/2017  
**Problem:** leaking at top by drivers door

- Water test for leak-remove headliner and found rust hole in roof under roof rack-send to bodyshop for repair. Reinstall headliner and trim and water test  
- Shop Supplies

**Parts List**

**Qty**

|               |      |
|---------------|------|
| Shop Supplies | 1.00 |
|---------------|------|

Hours 4.00      Labor: 240.00      Parts: 2.00      Total: 242.00  
:

**Workorder:** 1706267      **Meter:** 60485      **In Date:** 06/07/2017      **Closed:** 06/26/2017  
**Problem:** repair rust under roof rack

- repair rust under roof rack

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

**Workorder:** 1708753      **Meter:** 62607      **In Date:** 09/05/2017      **Closed:** 09/07/2017  
**Problem:** Left tail light out.

- Replace left rear brake light bulb.

**Parts List**

**Qty**

|      |      |
|------|------|
| Bulb | 1.00 |
|------|------|

Hours 0.30      Labor: 18.00      Parts: 0.78      Total: 18.78  
:

**Workorder:** 1708913      **Meter:** 62847      **In Date:** 09/15/2017      **Closed:** 09/15/2017  
**Problem:** 2 - Wash ticket(s) issued

- 2 - Wash ticket(s) issued

Hours 0.00      Labor: 0.00      Parts: 0.00      Total: 0.00  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1709112      **Meter:** 63175      **In Date:** 09/21/2017      **Closed:** 09/28/2017  
**Problem:** Check engine light, stalling & detail.

|  |                   |               |
|--|-------------------|---------------|
| - Computer diagnose check engine light ,code P0130.perform pinpoint test .r&r defective ho2 bank 1 sensor1 .clear codes Retest.reprogrm Pcm with updated calibration . | <b>Parts List</b> | <b>Qty</b>    |
|  | O2 Sensor         | 1.00          |
|  | Shop Supplies     | 1.00          |
| - Shop Supplies  |                   |               |
| Hours 2.50   | Labor: 150.00     | Parts: 156.32 |
| :  |                   | Total: 306.32 |

**Workorder:** 1709441      **Meter:** 63016      **In Date:** 09/27/2017      **Closed:** 09/27/2017  
**Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued

|            |             |             |             |
|------------|-------------|-------------|-------------|
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| :          |             |             |             |

**Workorder:** 1711303      **Meter:** 65326      **In Date:** 11/16/2017      **Closed:** 12/07/2017  
**Problem:** P.M. servicew and water leaking for windshield.

|  |                     |               |               |
|--|---------------------|---------------|---------------|
| - P.m. service.  | <b>Parts List</b>   | <b>Qty</b>    |               |
| - Check battery and charging system.battery failed load test after fully charge .replace defective battery.    | 5w20 Engine Oil     | 5.00          |               |
|  | Napagold Oil Filter | 1.00          |               |
| - Inspect and service rear brakes.   | 20in Exactfit-beam  | 2.00          |               |
| - Balance and rotate all four tires.   | 12in Exactfit-rear  | 1.00          |               |
| - Check for water leak with hose several times.found no leak .dry out under carpet from previous leak .retest. | Battery             | 1.00          |               |
|  | Mac Battery Protect | 1.00          |               |
| - Shop Supplies  | Shop Supplies       | 1.00          |               |
| Hours 6.75   | Labor: 405.00       | Parts: 228.89 | Total: 633.89 |
| :  |                     |               |               |

**Workorder:** 1800941      **Meter:** 67201      **In Date:** 01/25/2018      **Closed:** 01/30/2018  
**Problem:** Towed in will not stay running.

|  |                   |             |               |
|--|-------------------|-------------|---------------|
| - Scan computer system,no codes present.found air intake hose loose at M.a.f sensor.secure and torque clamp.test drive.  | <b>Parts List</b> | <b>Qty</b>  |               |
|  | Shop Supplies     | 1.00        |               |
| - Inspect vehicle for excessive fuel consumption.raise vehicle on lift and inspect fuel tank and lines.no leaks found, all component tight and secure.this vehicle is averaging 28.2 Mpg per instument cluster reading.no problem found. |                   |             |               |
| - Shop Supplies  |                   |             |               |
| Hours 2.00   | Labor: 120.00     | Parts: 2.00 | Total: 122.00 |
| :  |                   |             |               |

**Workorder:** 1800957      **Meter:** 67140      **In Date:** 01/25/2018      **Closed:** 01/25/2018  
**Problem:** No Start

- Tow From: 15801 Orange Blvd (library) To: Lv Shop

|            |             |             |             |
|------------|-------------|-------------|-------------|
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| :          |             |             |             |

**Workorder:** 1801591      **Meter:** 67344      **In Date:** 02/09/2018      **Closed:** 02/09/2018  
**Problem:** 2 - Wash ticket(s) issued

- 2 - Wash ticket(s) issued

|            |             |             |             |
|------------|-------------|-------------|-------------|
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| :          |             |             |             |

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1806395      **Meter:** 71731      **In Date:** 06/21/2018      **Closed:** 07/03/2018  
**Problem:** PM Service

|   |  |                 |
|---|--|-----------------|
| - P.m. service.   | <b>Parts List</b>                        | <b>Qty</b>      |
| - Replace four tires .balance and nitogen fill tires. Reset Tpm.  | Brake Pad                                | 1.00            |
| - Replace front brake pads .resurface front rotors .service calipers and flush and bleed brake system .inspect and service rear brakes. | 5w20 Engine Oil                          | 5.00            |
| - Perform complete four wheel alignment.  | Napagold Oil Filter                      | 1.00            |
| - Shop Supplies   | 12in Exactfit-rear                       | 1.00            |
|   | 20in Exactfit-beam                       | 2.00            |
|   | Mac Wite Lithium Gres                    | 1.00            |
|   | 183407418 P235-70r16                     | 4.00            |
|   | Tire Pressure Monitoring System Sensor ( | 4.00            |
|   | Non-chlor Brake Clnr                     | 2.00            |
|   | Shop Supplies                            | 1.00            |
|   | Tire Disposal Fee                        | 4.00            |
| Hours 11.75   | Labor: 705.00                            | Parts: 898.69   |
| :   |  | Total: 1,603.69 |

**Workorder:** 1809617      **Meter:** 73965      **In Date:** 09/18/2018      **Closed:** 09/19/2018  
**Problem:** Spare on right front.

|  |                      |               |
|--|----------------------|---------------|
| - Replace right front tire and balance . Nitrogen fill tires. Remount spare. | <b>Parts List</b>    | <b>Qty</b>    |
| - Shop Supplies  | 183407418 P235-70r16 | 1.00          |
|  | Shop Supplies        | 1.00          |
|  | Tire Disposal Fee    | 1.00          |
| Hours 0.50   | Labor: 30.00         | Parts: 187.77 |
| :  |                      | Total: 217.77 |

**Workorder:** 1809676      **Meter:** 73852      **In Date:** 09/17/2018      **Closed:** 09/19/2018  
**Problem:** PF tire flat, put spare on

|                              |             |             |             |
|------------------------------|-------------|-------------|-------------|
| - Tow From: Croc, Admin side |             |             |             |
| Hours 0.00                   | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| :                            |             |             |             |

**Workorder:** 1811863      **Meter:** 75105      **In Date:** 11/19/2018      **Closed:** 11/19/2018  
**Problem:** Transition Prep Charge

|                          |               |             |               |
|--------------------------|---------------|-------------|---------------|
| - Transition Prep Charge |               |             |               |
| Hours 2.00               | Labor: 134.00 | Parts: 0.00 | Total: 134.00 |
| :                        |               |             |               |