10189873 2013 FORD ESCAPE Suv, Mid Size

		101	89873	2013 FORD	ESCAPI	= Suv, Iviia	Size			
Workorder: Problem:	1306921 1061 - Pre De	Meter: elivery Insp	326 ection			In Date:	07/11/2013	Closed:	07/11/2	013
- Pre Delivery	/ Inspection									
	Hour :	s 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	1402928 Pm service.	Meter:	4987			In Date:	03/26/2014	Closed:	04/08/2	014
- Pm service.					Parts Li	ist				Qty
- Rotate and I	balance tires.				Napa Q	uart 5w20			6.00	
- Test drive.					Napago	ld Oil Filter			1.00	
- Shop Suppli	ies				Shop St	upplies				1.00
	Hour :	s 3.50		Labor:	210.00	Parts:	28.25	Total:	238.25	
Workorder: Problem:	1407371 Flat tire.	Meter:	7352			In Date:	07/28/2014	Closed:	08/12/2	014
- Repair flat ti	ire.				Parts Li	ist				Qty
- Shop Suppli					Shop Su	upplies				1.00
	Hour	s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1500145 Pm service	Meter:	12198			In Date:	01/06/2015	Closed:	01/08/2	015
- Pm service.					Parts Li	ist				Qty
- Rotate and balance tires.					5w20 O	il Bulk				6.00
- Test drive.					Napago	ld Oil Filter				1.00
- Shop Suppli	ies				Washer	Fluid Conce			1.00	
					Napago	ld Fuel Filte	r			1.00
					Shop St	upplies				1.00
	Hour :	s 3.50		Labor:	210.00	Parts:	27.68	Total:	237.68	
Workorder: Problem:	1509576 Pm service.	Meter:	18987			In Date:	09/22/2015	Closed:	09/23/2	015
- Pm service.					Parts Li	ist				Qty
- Rotate and I	balance tires.				5w20 O	il Bulk				6.00
- Test drive.					Napago	ld Oil Filter				1.00
- Shop Suppli	ies				Washer	Fluid Conce	entr			1.00
					Shop St	upplies				1.00
	Hour :	s 3.50		Labor:	210.00	Parts:	22.78	Total:	232.78	
Workorder: Problem:	1509868 Factory recall	Meter:	18987			In Date:	09/29/2015	Closed:	09/29/2	015
- Tow From: F	Pa shop To: Al	Packer								
		s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	

Workorder: Problem:	1509959 Transport	Meter:	18987			In Date:	10/01/2015	Closed:	10/01/2015	
- Tow From: A	Al Packer To:	Pa shop								
	Hou :	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1602574 needs spare	Meter: key	23289			In Date:	03/10/2016	Closed:	03/15/2016	
- Secure amd	program one	spare key			Parts L	_ist			Qty	
- Shop Suppli	es				Key				1.00	
					Shop S	Supplies			1.00	
	Hou :	ırs 1.00		Labor:	60.00	Parts:	84.29	Total:	144.29	
Workorder: Problem:	1605333 Pm service.	Meter:	25578			In Date:	05/24/2016	Closed:	06/01/2016	
- Pm service.					Parts List (
- Rotate and I	balance tires.				5w20 C	6.00				
- Test drive.					Napago	old Oil Filter			1.00	
- Shop Suppli	es				Accufit	Beam			2.00	
					Blade				1.00	
					Washe	r Fluid Conce	entr		1.00	
					Shop S	Supplies			1.00	
	Hou :	ırs 3.50		Labor:	210.00	Parts:	75.07	Total:	285.07	
Workorder: Problem:	1612579 Pm service.	Meter:	31133			In Date:	12/08/2016	Closed:	12/15/2016	
- Pm Service					Parts List Qt					
- Rotate & Balance						5w20 Oil Bulk 6.0				
- Diagnose ar	nd Replace roo	of mounted	stop light ass	embly	Napagold Oil Filter 1					
- Test Drive						Accufit Beam				
- Shop Suppli	es				Washer Fluid Concentr				1.00	
					Napa A	Air Filter			1.00	
					Lamp /	Asy Real Tai	il Gate		1.00	
					Shop S	Supplies			1.00	

Labor: 270.00

Parts: 153.95

Total: 423.95

Hours 4.50

Workorder: 1706610 Meter: 374 Problem: Pm service.	130	In Date:	07/06/2017	Closed:	07/07/2017	
- Pm service.		Parts List			Qty	
- Replace worn tires. Nitro fill and balance.		5w20 Oil Bulk			6.00	
- Test drive.		Napagold Oil Filter			1.00	
- Shop Supplies		Washer Fluid Cond	entr		1.00	
		Napa Cabin Air Filt	er		1.00	
		P235 55r17 Fuel M	lax		4.00	
		Shop Supplies			1.00	
		Tire Disposal Fee			4.00	
Hours 4.50 :	Labor:	270.00 Parts	717.61	Total:	987.61	
Workorder: 1800350 Meter: 433 Problem: Pm service.	380	In Date:	01/10/2018	Closed:	01/19/2018	
- Pm service.		Parts List			Qty	
- Battery failed load test. Replace battery.		5w20 Oil Bulk			6.00	
- Rotate and balance tires.		Napagold Oil Filter				
- Test drive.		Washer Fluid Cond	entr		1.00	
- Shop Supplies		Wiper Blade				
		Wiper Blade			1.00	
		Battery			1.00	
		Shop Supplies			1.00	
Hours 4.50 :	Labor:	270.00 Parts	220.84	Total:	490.84	
Workorder: 1806936 Meter: 48 Problem: Pm service.	708	In Date:	07/09/2018	Closed:	07/10/2018	
- Pm service.		Parts List			Qty	
- Replace a/c filter.		Napagold Oil Filter			1.00	
- Clean throttle body.		5w20 Oil Bulk			6.00	
- Rotate and balance tires.		Washer Fluid Cond	entr		1.00	
- Test drive.		Wiper Blade			1.00	
- Shop Supplies		Wiper Blade				
		Napa Air Filter			1.00	
					1.00	
		Napa Cabin Air Filt	.er		1.00	
		Napa Cabin Air Fili Clean-r-carb 20oz	ei		1.00	
		-	eı			

Workorder: Problem:	1812821 Pm service.	Meter:	54190		ln	Date:	12/18/2018	Closed:	12/26/20	018
- Pm service.					Parts List					Qty
- Replace cab	Wiper Blade	е				1.00				
- Rotate and b	palance tires.				Napagold Oil Filter					1.00
- Test drive.					5w20 Oil Bu	ulk				6.00
- Shop Supplies					Blade					1.00
					Washer Flu	id Conce			1.00	
					Wiper Blade					1.00
					Napa Cabin Air Filter					1.00
					Shop Supp	lies				1.00
	Hour	s 4.00		Labor:	268.00	Parts:	89.87	Total:	357.87	
Workorder: Problem:	1907580 P.M. service ,	Meter: left rear wi	−59592 ill not close ,Re	ecall 16S		Date:	07/22/2019	Closed:	08/28/20	019
- P.m. service					Parts List					Qty
- Inspect all lig	ghts . Test and	-	-			Dil Filter				Qty 1.00
- Inspect all lig	ghts . Test and Replace two tire	es due to d	cupping . Rotat		Parts List					-
 Inspect all lig Road test . Feed bath 	ghts . Test and Replace two tire lance all four ti	es due to d res . Nitrof	cupping . Rotat fill all.	te and	Parts List Napagold C	ne Oil				1.00
Inspect all ligRoad test . Fhigh speed baDiagnose ra	ghts . Test and Replace two tir lance all four ti dio volumn cor	es due to de res . Nitrofentrol inop .	cupping . Rotat fill all.	te and	Parts List Napagold C 5w20 Engir	ne Oil e				1.00 6.00
 Inspect all lig Road test . Fe high speed ba Diagnose rage replace radio of 	ghts . Test and Replace two tire lance all four ti dio volumn cor control head . F	es due to de res . Nitrofentrol inop . Retest .	cupping . Rotat fill all. R&r dash trim	te and to	Parts List Napagold C 5w20 Engir Wiper Blade	ne Oil e				1.00 6.00 1.00
 Inspect all lig Road test . If high speed ba Diagnose rate replace radio of Perform communication 	ghts . Test and Replace two tird lance all four ti dio volumn cor control head . F aplete front end	es due to dres . Nitrol ntrol inop . Retest . d alignmen	cupping . Rotatifill all. R&r dash trim	te and to	Parts List Napagold C 5w20 Engir Wiper Blade Wiper Blade	ne Oil e e	entr			1.00 6.00 1.00 1.00
- Inspect all lig - Road test . F high speed ba - Diagnose ra replace radio of - Perform com - Transport to	ghts . Test and Replace two tire lance all four ti dio volumn cor control head . F aplete front end and from deal	es due to dres . Nitrol ntrol inop . Retest . d alignmen	cupping . Rotatifill all. R&r dash trim	te and to	Parts List Napagold C 5w20 Engir Wiper Blade Wiper Blade Blade Washer Flu Mac Wite L	ne Oil e e iid Conce ithium G				1.00 6.00 1.00 1.00
 Inspect all lig Road test . If high speed ba Diagnose rate replace radio of Perform communication 	ghts . Test and Replace two tire lance all four ti dio volumn cor control head . F aplete front end and from deal	es due to dres . Nitrol ntrol inop . Retest . d alignmen	cupping . Rotatifill all. R&r dash trim	te and to	Parts List Napagold C 5w20 Engir Wiper Blade Wiper Blade Blade Washer Flu	ne Oil e e iid Conce ithium G				1.00 6.00 1.00 1.00 1.00
- Inspect all lig - Road test . F high speed ba - Diagnose ra replace radio of - Perform com - Transport to	ghts . Test and Replace two tire lance all four ti dio volumn cor control head . F aplete front end and from deal	es due to dres . Nitrol ntrol inop . Retest . d alignmen	cupping . Rotatifill all. R&r dash trim	te and to	Parts List Napagold C 5w20 Engir Wiper Blade Wiper Blade Blade Washer Flu Mac Wite L	ne Oil e e iid Conce ithium G atures				1.00 6.00 1.00 1.00 1.00 1.00
- Inspect all lig - Road test . F high speed ba - Diagnose ra replace radio of - Perform com - Transport to	ghts . Test and Replace two tire lance all four ti dio volumn cor control head . F aplete front end and from deal	es due to dres . Nitrol ntrol inop . Retest . d alignmen	cupping . Rotatifill all. R&r dash trim	te and to	Parts List Napagold C 5w20 Engir Wiper Blade Wiper Blade Blade Washer Flu Mac Wite L Boxed Minis	ne Oil e e iid Conce ithium G atures '17 Mic				1.00 6.00 1.00 1.00 1.00 1.00 1.00
- Inspect all lig - Road test . F high speed ba - Diagnose ra replace radio of - Perform com - Transport to	ghts . Test and Replace two tire lance all four ti dio volumn cor control head . F aplete front end and from deal	es due to dres . Nitrol ntrol inop . Retest . d alignmen	cupping . Rotatifill all. R&r dash trim	te and to	Parts List Napagold C 5w20 Engir Wiper Blade Wiper Blade Blade Washer Flu Mac Wite L Boxed Minit Tire235/55/	ne Oil e e iid Conce ithium G atures '17 Mic				1.00 6.00 1.00 1.00 1.00 1.00 1.00 2.00
- Inspect all lig - Road test . F high speed ba - Diagnose ra replace radio of - Perform com - Transport to	ghts . Test and Replace two tire lance all four ti dio volumn cor control head . F aplete front end and from deal	es due to dres . Nitrol ntrol inop . Retest . d alignmen	cupping . Rotatifill all. R&r dash trim	te and to	Parts List Napagold C 5w20 Engir Wiper Blade Wiper Blade Blade Washer Flu Mac Wite L Boxed Minis Tire235/55/ Control Rac	ne Oil e e iid Conce ithium G atures (17 Mic dio lies				1.00 6.00 1.00 1.00 1.00 1.00 1.00 2.00

Workorder: 2004310 Meter: 63402 Problem: Pm service.	In Date: 04/30/2020 Closed: 05/05/2020
- Pm service.	Parts List Qty
- Replace worn rear tires.	Napagold Oil Filter 1.00
- Replace broken front ds window regulator.	5w20 Oil Bulk 6.00
- Replaced cracked wheel covers.	Washer Fluid Concentr 1.00
- Replace worn steering wheel.	Wiper Blade 1.00
- Replaced leaking rear shocks.	Wiper Blade 1.00
- Test drive.	Blade 1.00
- Shop Supplies	Tire235/55/17 Mic 2.00
	Window Motor/regulator 1.00
	Wheel Cover 4.00
	Steering Wheel Asy 1.00
	Real Shock Motorcraft 2.00
	Shop Supplies 1.00
	Tire Disposal Fee 2.00
Hours 8.00 Lal	oor: 584.00 Parts: 1,296.10 Total: 1,880.10
Workorder: 2009397 Meter: 64454 Problem: Transition Prep Charge	In Date: 09/18/2020 Closed: 09/18/2020
- Transition Prep Charge	
Hours 2.00 Lal	oor: 146.00 Parts: 0.00 Total: 146.00