

**Palm Beach County Fleet Management
Asset Maintenance History**

10198897 2015 FORD ESCAPE Suv, Mid Size

Workorder: 1507870	Meter: 309	In Date: 08/06/2015	Closed: 08/06/2015
Problem: 1061 - Pre Delivery Inspection			
- Pre Delivery Inspection			
Hours 2.00	Labor: 120.00	Parts: 0.00	Total: 120.00
:			
Workorder: 1600337	Meter: 7687	In Date: 01/11/2016	Closed: 01/20/2016
Problem: Pm service.			
- Pm service.			
Parts List			
- Rotate and balance all four tires.	5w20 Engine Oil		6.00
- Shop Supplies	Napagold Oil Filter		1.00
	Washer Fluid Concentr		1.00
	Shop Supplies		1.00
Hours 3.00	Labor: 180.00	Parts: 19.84	Total: 199.84
:			
Workorder: 1601122	Meter: 8249	In Date: 02/01/2016	Closed: 02/04/2016
Problem: Left front tire going flat.			
- Repair and balance left front tire.			
Parts List			
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1606042	Meter: 15162	In Date: 06/13/2016	Closed: 06/21/2016
Problem: P.M. service.			
- P.m. Service.			
Parts List			
- Rotate and balance all tires.	5w20 Engine Oil		6.00
- Shop Supplies	Oil Filter		1.00
	Washer Fluid Concentr		1.00
	Brk Fluid Dot 4-12oz		1.00
	Shop Supplies		1.00
Hours 3.00	Labor: 180.00	Parts: 26.56	Total: 206.56
:			
Workorder: 1608690	Meter: 20741	In Date: 08/22/2016	Closed: 09/07/2016
Problem: P.M. service			
- P.m. Service.			
Parts List			
- Rotate and balance all tires.	5w20 Engine Oil		6.00
- Shop Supplies	Napagold Oil Filter		1.00
	Accufit Beam		3.00
	Wpr/blde		1.00
	Used Fire X Refurbished		1.00
	Shop Supplies		1.00
Hours 3.00	Labor: 180.00	Parts: 93.56	Total: 273.56
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1611152	Meter: 24407	In Date: 10/27/2016	Closed: 10/31/2016
Problem: P.M. service and left front tire flat spare on truck.			
- P.m. Service.	Parts List	Qty	
- Replace and balance four new tires.	5w20 Engine Oil	6.00	
- Replace leaking rear shocks.	Napagold Oil Filter	1.00	
- Complete wheel alignment.test drive.	235/55r17 Assurance	4.00	
- Shop Supplies	Rear Shock Absorber	2.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	4.00	
Hours 7.50	Labor: 450.00	Parts: 762.31	Total: 1,212.31
:			
Workorder: 1611275	Meter: 24507	In Date: 10/27/2016	Closed: 11/01/2016
Problem: Flat tire on L/F			
- Tire Service Jpp Parks Security - Flat tire on L/f			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1612596	Meter: 27378	In Date: 12/08/2016	Closed: 12/14/2016
Problem: Left rear tire going flat.			
- Repair and balance left rear tire.	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1700934	Meter: 31067	In Date: 01/30/2017	Closed: 02/13/2017
Problem: P.M. service and recall 15C06			
- P.m. Service.	Parts List	Qty	
- Rotate and balance tires.	5w20 Engine Oil	6.00	
- Transport vehicle to dealer for recall #15c06.	Napagold Oil Filter	1.00	
- Shop Supplies	Wiper Blade	1.00	
	Wiper Blade	1.00	
	Blade	1.00	
	Used Fire X Refurbished	1.00	
	Shop Supplies	1.00	
Hours 5.00	Labor: 300.00	Parts: 89.87	Total: 389.87
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1704065	Meter: 35872	In Date: 04/24/2017	Closed: 04/28/2017
Problem: P.M. service.			
- P.m. service.	Parts List	Qty	
- Mount and balance four new tires. Nitrogen fill tires	5w20 Engine Oil	6.00	
- Load test battery.recharge battery but failed retest .replace battery with new.	Napagold Oil Filter	1.00	
- Shop Supplies	Washer Fluid Concentr	1.00	
	Napa Cabin Air Filter	1.00	
	P235 55r17 Fuel Max	4.00	
	Battery	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	4.00	
Hours 5.00	Labor: 300.00	Parts: 865.51	Total: 1,165.51
:			
Workorder: 1707002	Meter: 41660	In Date: 07/18/2017	Closed: 07/31/2017
Problem: P.M. service.			
- P.m. service.	Parts List	Qty	
- Balance and rotate all four tires.	5w20 Engine Oil	6.00	
- Shop Supplies	Napagold Oil Filter	1.00	
	Accufit Beam	2.00	
	Wpr/blde	1.00	
	Washer Fluid Concentr	1.00	
	Shop Supplies	1.00	
Hours 3.00	Labor: 180.00	Parts: 63.40	Total: 243.40
:			
Workorder: 1710206	Meter: 45892	In Date: 10/18/2017	Closed: 10/19/2017
Problem: Left rear tire going flat.			
- Remove nail,repair and balance left rear tire.	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1710461	Meter: 46304	In Date: 10/24/2017	Closed: 10/25/2017
Problem: P.M. service.			
- P.m. service.	Parts List	Qty	
- Rotate and high speed balance all four wheels.nitro fill all.	5w20 Engine Oil	6.00	
- Shop Supplies	Napagold Oil Filter	1.00	
	Washer Fluid Concentr	1.00	
	Wiper Blade	1.00	
	Wiper Blade	1.00	
	Blade	1.00	
	Shop Supplies	1.00	
Hours 3.00	Labor: 180.00	Parts: 76.13	Total: 256.13
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1712357	Meter: 49791	In Date: 12/15/2017	Closed: 12/19/2017
Problem: Right rear tire going flat.			
- Repair right rear tire and balance .nitrogen fill tires.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1800027	Meter: 50741	In Date: 01/02/2018	Closed: 01/08/2018
Problem: P.M. service and brake light out and vibration in front end.			
- P.m. service.	Parts List		Qty
- Removed left rear tail light assembly.replace brake light bulb and retest.	Brake Pad		1.00
	Napagold Oil Filter		1.00
- Replace front brake pads and resurface front rotors .service calipers and flush and bleed brake system.	5w20 Engine Oil		6.00
- Mount and balance four new tires.nitrofill.	Wiper Blade		1.00
- Perform complete four wheel alignment.test drive.	Wiper Blade		1.00
- Check complaint.test drive. R&r left hub bearing .test drive noise gone .operating as design.	Blade		1.00
- Shop Supplies	Bulb		1.00
	B Fluid Dot 3-32oz		1.00
	235/55r17 Assurance		4.00
	Bering		1.00
	Shop Supplies		1.00
	Tire Disposal Fee		4.00
Hours 13.60	Labor: 816.00	Parts: 907.75	Total: 1,723.75
:			
Workorder: 1800981	Meter: 52218	In Date: 01/26/2018	Closed: 01/30/2018
Problem: License plate lights out			
- Replace license plate bulbs .scan for codes and clear .retest lighting system.	Parts List		Qty
	Bulb		2.00
Hours 0.60	Labor: 36.00	Parts: 1.20	Total: 37.20
:			
Workorder: 1802698	Meter: 54591	In Date: 03/12/2018	Closed: 03/19/2018
Problem: Clicking noise while turning.			
- Check and confirm concern .remove and replace left front axle shaft.test drive.	Parts List		Qty
- Shop Supplies	Axel Nut		1.00
	Left Front Axle		1.00
	Shop Supplies		1.00
Hours 2.00	Labor: 120.00	Parts: 176.77	Total: 296.77
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1803704	Meter: 55686	In Date: 04/09/2018	Closed: 04/11/2018
Problem: P.M. service.			
- P.m. service.	Parts List	Qty	
- Perform automatic transmission drain and refill service.road test.	5w20 Engine Oil	6.00	
	Napagold Oil Filter	1.00	
- Make and replace front asset number.	Washer Fluid Concentr	1.00	
- Repair left front tire .rotate and balance all four tires.	Used Fire X Refurbished	1.00	
- Shop Supplies	oil auto	5.00	
	Shop Supplies	1.00	
Hours 6.00	Labor: 360.00	Parts: 74.41	Total: 434.41
:			
Workorder: 1806050	Meter: 58698	In Date: 06/13/2018	Closed: 06/19/2018
Problem: Front driver side headlight is out.			
- Replace left front low beam head light.	Parts List	Qty	
	Blister Pack Capsules	1.00	
Hours 0.50	Labor: 30.00	Parts: 11.88	Total: 41.88
:			
Workorder: 1807445	Meter: 60783	In Date: 07/23/2018	Closed: 07/25/2018
Problem: P.M. service.			
- P.m. service.	Parts List	Qty	
- Rotate and balance all four tires. Nitrogen fill tires.	Napagold Oil Filter	1.00	
- Shop Supplies	5w20 Engine Oil	6.00	
	Blade	1.00	
	Wiper Blade	1.00	
	Wiper Blade	1.00	
	Shop Supplies	1.00	
Hours 3.00	Labor: 180.00	Parts: 76.01	Total: 256.01
:			
Workorder: 1808025	Meter: 61644	In Date: 08/06/2018	Closed: 08/09/2018
Problem: Right headlight inop.			
- Test and replace right low beam headlight bulb.	Parts List	Qty	
	Blister Pack Capsules	1.00	
Hours 0.50	Labor: 30.00	Parts: 11.88	Total: 41.88
:			
Workorder: 1808428	Meter: 62463	In Date: 08/16/2018	Closed: 08/20/2018
Problem: Right front tire going flat.			
- Repair left front tire and balance . Nitrofill tires.	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1809513	Meter: 63872	In Date: 09/14/2018	Closed: 09/18/2018
Problem: Screw in passenger side front tire.			
- Repair right frontr tire and balance . Nitrofill all.	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1810855 **Meter:** 66054 **In Date:** 10/22/2018 **Closed:** 10/24/2018
Problem: P.M. service.

<ul style="list-style-type: none"> - P.m. service. - Replace two tires . Rotate and balance all four tires. Nitrogen fill tires. - Shop Supplies 	<table border="0" style="width: 100%;"> <tr> <th style="text-align: left;">Parts List</th> <th style="text-align: right;">Qty</th> </tr> <tr><td>Napagold Oil Filter</td><td style="text-align: right;">1.00</td></tr> <tr><td>5w20 Engine Oil</td><td style="text-align: right;">6.00</td></tr> <tr><td>Blade</td><td style="text-align: right;">1.00</td></tr> <tr><td>Wiper Blade</td><td style="text-align: right;">1.00</td></tr> <tr><td>Wiper Blade</td><td style="text-align: right;">1.00</td></tr> <tr><td>Washer Fluid Concentr</td><td style="text-align: right;">1.00</td></tr> <tr><td>Ford Triton Pvc Swc</td><td style="text-align: right;">1.00</td></tr> <tr><td>Tire235/55/17 Mic</td><td style="text-align: right;">2.00</td></tr> <tr><td>Shop Supplies</td><td style="text-align: right;">1.00</td></tr> <tr><td>Tire Disposal Fee</td><td style="text-align: right;">2.00</td></tr> </table>	Parts List	Qty	Napagold Oil Filter	1.00	5w20 Engine Oil	6.00	Blade	1.00	Wiper Blade	1.00	Wiper Blade	1.00	Washer Fluid Concentr	1.00	Ford Triton Pvc Swc	1.00	Tire235/55/17 Mic	2.00	Shop Supplies	1.00	Tire Disposal Fee	2.00
Parts List	Qty																						
Napagold Oil Filter	1.00																						
5w20 Engine Oil	6.00																						
Blade	1.00																						
Wiper Blade	1.00																						
Wiper Blade	1.00																						
Washer Fluid Concentr	1.00																						
Ford Triton Pvc Swc	1.00																						
Tire235/55/17 Mic	2.00																						
Shop Supplies	1.00																						
Tire Disposal Fee	2.00																						
Hours 4.00	Labor: 268.00 Parts: 478.29 Total: 746.29																						
:																							

Workorder: 1813017 **Meter:** 69991 **In Date:** 12/26/2018 **Closed:** 12/27/2018
Problem: Right low beam headlight inop.

<ul style="list-style-type: none"> - Test and replace right low beam headlight bulb. 	<table border="0" style="width: 100%;"> <tr> <th style="text-align: left;">Parts List</th> <th style="text-align: right;">Qty</th> </tr> <tr><td>Blister Pack Capsules</td><td style="text-align: right;">1.00</td></tr> </table>	Parts List	Qty	Blister Pack Capsules	1.00
Parts List	Qty				
Blister Pack Capsules	1.00				
Hours 0.50	Labor: 33.50 Parts: 12.59 Total: 46.09				
:					

Workorder: 1900250 **Meter:** 70580 **In Date:** 01/07/2019 **Closed:** 01/17/2019
Problem: P.M. service and left front tire going flat.

<ul style="list-style-type: none"> - P.m. service. - Check all tires . Repair one tire and replace two tires . Rotate and high speed balance all four tires. Nitrofill all. - Remove left front seat for repair and reinstall after . - Perform complete four wheel alignment and road test. - Shop Supplies 	<table border="0" style="width: 100%;"> <tr> <th style="text-align: left;">Parts List</th> <th style="text-align: right;">Qty</th> </tr> <tr><td>Napagold Oil Filter</td><td style="text-align: right;">1.00</td></tr> <tr><td>Napa Quart 5w20</td><td style="text-align: right;">6.00</td></tr> <tr><td>Wiper Blade</td><td style="text-align: right;">1.00</td></tr> <tr><td>Wiper Blade</td><td style="text-align: right;">1.00</td></tr> <tr><td>Blade</td><td style="text-align: right;">1.00</td></tr> <tr><td>Washer Fluid Concentr</td><td style="text-align: right;">1.00</td></tr> <tr><td>Lug Nut</td><td style="text-align: right;">2.00</td></tr> <tr><td>Tire235/55/17 Mic</td><td style="text-align: right;">2.00</td></tr> <tr><td>Seat R And R</td><td style="text-align: right;">1.00</td></tr> <tr><td>Shop Supplies</td><td style="text-align: right;">1.00</td></tr> <tr><td>Tire Disposal Fee</td><td style="text-align: right;">2.00</td></tr> </table>	Parts List	Qty	Napagold Oil Filter	1.00	Napa Quart 5w20	6.00	Wiper Blade	1.00	Wiper Blade	1.00	Blade	1.00	Washer Fluid Concentr	1.00	Lug Nut	2.00	Tire235/55/17 Mic	2.00	Seat R And R	1.00	Shop Supplies	1.00	Tire Disposal Fee	2.00
Parts List	Qty																								
Napagold Oil Filter	1.00																								
Napa Quart 5w20	6.00																								
Wiper Blade	1.00																								
Wiper Blade	1.00																								
Blade	1.00																								
Washer Fluid Concentr	1.00																								
Lug Nut	2.00																								
Tire235/55/17 Mic	2.00																								
Seat R And R	1.00																								
Shop Supplies	1.00																								
Tire Disposal Fee	2.00																								
Hours 7.50	Labor: 502.50 Parts: 855.94 Total: 1,358.44																								
:																									

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1904614	Meter: 75448	In Date: 04/29/2019	Closed: 04/30/2019
Problem: P.M. service.			
- P.m. service.	Parts List	Qty	
- Repair left rear tires . Rotate and balance all four tires . Nitrofill all.	Napagold Oil Filter	1.00	
- Shop Supplies	5w20 Engine Oil	6.00	
	Blade	1.00	
	Wiper Blade	1.00	
	Wiper Blade	1.00	
	Napa Cabin Air Filter	1.00	
	Shop Supplies	1.00	
Hours 4.00	Labor: 268.00	Parts: 87.62	Total: 355.62
:			
Workorder: 1907485	Meter: 79828	In Date: 07/19/2019	Closed: 07/23/2019
Problem: Right brake light inop.			
- Test and replace right brake light bulb .	Parts List	Qty	
	Boxed Miniatures	1.00	
Hours 0.50	Labor: 33.50	Parts: 0.77	Total: 34.27
:			
Workorder: 1907807	Meter: 80439	In Date: 07/29/2019	Closed: 08/08/2019
Problem: PM Service			
- P.m. Service.	Parts List	Qty	
- Replace rear brake rotors and brake pads.service and lube calipers.flush and bleed system.	5w20 Engine Oil	6.00	
- Replace both rear shocks.	Napagold Oil Filter	1.00	
- Tune-up.replace spark plugs.	Used Fire X Refurbished	1.00	
- Clean throttle body.service and clean induction system.flush injectors.	Washer Fluid Concentr	1.00	
- Rotate and balance tires.	Non-chlor Brake Clnr	1.00	
- Shop Supplies	Brk Fluid Dot 4-12oz	2.00	
	Rotor	2.00	
	Rear Brake Pad	1.00	
	Rear Shock Absorber	2.00	
	Spark Plug	4.00	
	Intake Cleaner Kit	1.00	
	Injector Cleaner	1.00	
	Shop Supplies	1.00	
Hours 11.00	Labor: 737.00	Parts: 592.64	Total: 1,329.64
:			
Workorder: 1908968	Meter: 81580	In Date: 08/27/2019	Closed: 08/29/2019
Problem: Towed in for check engine light and running rough .			
- Computer diagnose check engine light , code P2111 . Perform pinpoint test . R&r defective throttle body . Clear code and reset Kam . Retest .	Parts List	Qty	
- Shop Supplies	Throttle	1.00	
	Shop Supplies	1.00	
Hours 2.00	Labor: 134.00	Parts: 62.33	Total: 196.33
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1908998	Meter: 81440	In Date: 08/27/2019	Closed: 08/28/2019
Problem: CK Engine Light and Sputtering			
- Tow From: Logger Run Park (11185 Palmetto Park Rd, Boca) To: Lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1911717	Meter: 85032	In Date: 11/12/2019	Closed: 11/14/2019
Problem: P.M. service and check battery .			
- P.m. service.	Parts List	Qty	
- Charge battery fully . Test battery and charging system .	Napagold Oil Filter	1.00	
Battery failed load test . R&r defective battery . Hook up Ids to reset Bms .	5w20 Engine Oil	6.00	
- Rotate and balance all four tires . Nitrofill all .	Washer Fluid Concentr	1.00	
- Shop Supplies	Blade	1.00	
	Wiper Blade	1.00	
	Wiper Blade	1.00	
	Battery	1.00	
	Shop Supplies	1.00	
Hours 4.50	Labor: 328.50	Parts: 262.47	Total: 590.97
:			
Workorder: 1912859	Meter: 87373	In Date: 12/17/2019	Closed: 12/18/2019
Problem: Left rrear tire going flat .			
- Repair left rear tire and balance . Nitrofill all.	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 73.00	Parts: 4.00	Total: 77.00
:			
Workorder: 2000849	Meter: 89846	In Date: 01/27/2020	Closed: 01/30/2020
Problem: P.M. service.			
- P.m. service.	Parts List	Qty	
- Diagnose vibration in gear . R&r defective right front motor mount . Retest .	Napagold Oil Filter	1.00	
- Rotate and balance all four tires . Nitrofill all.	5w20 Engine Oil	6.00	
- Shop Supplies	Blade	1.00	
	Wiper Blade	1.00	
	Wiper Blade	1.00	
	Engine Mount	1.00	
	Shop Supplies	1.00	
Hours 4.30	Labor: 313.90	Parts: 191.65	Total: 505.55
:			
Workorder: 2001200	Meter: 90508	In Date: 02/04/2020	Closed: 02/18/2020
Problem: Left brake light inop .			
- Test and replace left brake light bulb .	Parts List	Qty	
	Boxed Miniatures	1.00	
Hours 0.50	Labor: 36.50	Parts: 0.77	Total: 37.27
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 2003995	Meter: 93974	In Date: 04/22/2020	Closed: 04/23/2020
Problem: driver side healight out.			
- Test and replace left low beam headlight bulb .	Parts List		Qty
- Shop Supplies	Blister Pack Capsules		1.00
	Shop Supplies		1.00
Hours 0.50	Labor: 36.50	Parts: 17.86	Total: 54.36
:			
Workorder: 2004691	Meter: 94697	In Date: 05/11/2020	Closed: 05/14/2020
Problem: P.M. service.			
- P.m. service.	Parts List		Qty
- Pressure test and inspect cooling system . Replace leaking coolant recovery tank . Refill system and retest .	5w20 Engine Oil		6.00
- Diagnose clinking noise from front end on turns . R&r defective right front axle shaft . Retest .	Napagold Oil Filter		1.00
- R&r both leaking rear shocks .	Napa Cabin Air Filter		1.00
- Inspect and replace both loose front outter tie rod end .	Used Fire X Refurbished		1.00
- Perform four wheel alignment and road test .	Anti Freeze Motorcraft		1.00
- Rotate and balance all four tires . Nitrofill all.	Tank Assy		1.00
- Shop Supplies	Shaft Assy Motorcraft		1.00
	Rear Shock		2.00
	Tie Rod		1.00
	Tie Rod		1.00
	Shop Supplies		1.00
Hours 11.50	Labor: 839.50	Parts: 684.69	Total: 1,524.19
:			
Workorder: 2006389	Meter: 97400	In Date: 06/29/2020	Closed: 06/30/2020
Problem: Towed in for right front tire flat .			
- Repair right front tire and balance . Nitrofill all.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 73.00	Parts: 4.00	Total: 77.00
:			
Workorder: 2006513	Meter: 97439	In Date: 06/29/2020	Closed: 06/30/2020
Problem: Flat tire on passenger side front			
- Tow From: John Prince Park To: Lv			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 2007033	Meter: 99183	In Date: 07/20/2020	Closed: 07/27/2020
Problem: Left low beam headlight inop .			
- Test and replace left low beam headlight bulb .	Parts List		Qty
- Shop Supplies	Blister Pack Capsules		1.00
	Shop Supplies		1.00
Hours 0.50	Labor: 36.50	Parts: 17.86	Total: 54.36
:			

Workorder: 2008451	Meter: 99405	In Date: 08/25/2020	Closed: 08/25/2020
Problem: remove extra decals for surplus			
- remove extra decals	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 73.00	Parts: 4.00	Total: 77.00
:			
Workorder: 2008457	Meter: 99405	In Date: 08/25/2020	Closed: 08/25/2020
Problem: Transition Prep Charge			
- Transition Prep Charge			
Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00
:			