

**Palm Beach County Fleet Management
Asset Maintenance History**

10192537 2013 FORD ESCAPE Suv, Mid Size, 4X4

Workorder: 1303772 **Meter:** 325 **In Date:** 04/17/2013 **Closed:** 04/17/2013
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 1309927 **Meter:** 1529 **In Date:** 10/01/2013 **Closed:** 10/15/2013
Problem: P.M. service.

- Perform pm service complete.

- Rotate and balance all four tires.

- Shop Supplies

Parts List

5w20 Engine Oil Qty 5.00

Napagold Oil Filter Qty 1.00

Shop Supplies Qty 1.00

Hours 3.75 Labor: 225.00 Parts: 18.88 Total: 243.88
:

Workorder: 1310366 **Meter:** 1529 **In Date:** 10/15/2013 **Closed:** 10/15/2013
Problem: 1 - Wash ticket(s) issued

- 1 - Wash ticket(s) issued

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1403223 **Meter:** 5869 **In Date:** 04/02/2014 **Closed:** 04/17/2014
Problem: P.M. service and install customer supplied PA system.

- P.m. Service.

- Fabricate and install costomer supplied P.a. system.

- Rotate and balance all tires.

- Shop Supplies

Parts List

Napagold Oil Filter Qty 1.00

5w20 Engine Oil Qty 5.00

Accufit Beam Qty 2.00

Fuse Holder Qty 1.00

Vinyl Electrical Tape Qty 1.00

Shop Supplies Qty 1.00

Hours 9.75 Labor: 585.00 Parts: 54.26 Total: 639.26
:

Workorder: 1410094 **Meter:** 10201 **In Date:** 10/07/2014 **Closed:** 10/27/2014
Problem: Pm service.Wiper blades.Safety recalls 13S12,14S03 and 14S04

- Pm service.

- Rotate and balance all four tires.

- Transport vehicle to and from dealer for safety recalls#13s12,14s03 and 14s04.replace thermostat,oil dipstick and heat shield.reprogram restraints control module.inspect and adjust left front and rear door outer handles

- Shop Supplies

Parts List

Napagold Oil Filter Qty 1.00

5w20 Engine Oil Qty 5.00

Accufit Beam Qty 2.00

Mac Wite Lithium Gres Qty 1.00

Shop Supplies Qty 1.00

Hours 5.75 Labor: 345.00 Parts: 54.82 Total: 399.82
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1504104	Meter: 14552	In Date: 04/21/2015	Closed: 04/30/2015
Problem: Pm service.			
- Pm service.	Parts List	Qty	
- Rotate and balance all four tires.	5w20 Engine Oil	5.00	
- Shop Supplies	Napagold Oil Filter	1.00	
	Shop Supplies	1.00	
Hours 3.75	Labor: 225.00	Parts: 18.20	Total: 243.20
:			
Workorder: 1504753	Meter: 14878	In Date: 05/11/2015	Closed: 05/29/2015
Problem: Multiple warning lights on dash.ABS and stability control message.			
- Transport vehicle to and from dealer for left rear Abs sensor replacement.	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
Workorder: 1510640	Meter: 18490	In Date: 10/21/2015	Closed: 11/16/2015
Problem: Pm service.Wiper blades.Recall.			
- Pm service.	Parts List	Qty	
- Rotate and balance all four tires.	Napagold Oil Filter	1.00	
- Transport vehicle to and from dealer for safety recall # 14s21 and Abs light on.	5w20 Engine Oil	5.00	
- Shop Supplies	Accufit Beam	2.00	
	Accufit Rear	1.00	
	Washer Fluid Concentr	1.00	
	Mac Battery Protect	1.00	
	Blade	1.00	
	Shop Supplies	1.00	
Hours 5.75	Labor: 345.00	Parts: 88.87	Total: 433.87
:			
Workorder: 1513041	Meter: 19360	In Date: 12/30/2015	Closed: 01/05/2016
Problem: Left rear tire damage beyond repairs.			
- Replace and balance two tires.	Parts List	Qty	
- Shop Supplies	P235 55r17 Fuel Max	2.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	2.00	
Hours 1.00	Labor: 60.00	Parts: 329.28	Total: 389.28
:			
Workorder: 1604924	Meter: 21398	In Date: 05/11/2016	Closed: 05/31/2016
Problem: P.M. service and wiper blades.			
- P.m. Service.	Parts List	Qty	
- Rotate and balance tires.	5w20 Engine Oil	5.00	
- Shop Supplies	Napagold Oil Filter	1.00	
	Accufit Beam	2.00	
	Washer Fluid Concentr	1.00	
	Shop Supplies	1.00	
Hours 3.75	Labor: 225.00	Parts: 52.04	Total: 277.04
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1612081	Meter: 25236	In Date: 11/23/2016	Closed: 12/13/2016
Problem: P.M. service and wiper blades.			
- P.m. Service.	Parts List	Qty	
- Replace noisy right front axle assemble.	5w20 Engine Oil	5.00	
- Test battery and charging system.recharge and retest battery,fail load test.replace defective battery.	Napagold Oil Filter	1.00	
- Rotate and balance tires.	Accufit Beam	2.00	
- Com[lete wheel alignment.test drive.	Wpr/blde	1.00	
- Shop Supplies	Washer Fluid Concentr	1.00	
	Battery	1.00	
	Battery Terminal Protectors	1.00	
	Front Axles Asy	1.00	
	Shop Supplies	1.00	
Hours 9.25	Labor: 555.00	Parts: 425.06	Total: 980.06
:			
Workorder: 1707011	Meter: 29390	In Date: 07/18/2017	Closed: 07/31/2017
Problem: P.M. service.			
- P.m. service.	Parts List	Qty	
- Rotate and high speed balance all four tires.	5w20 Engine Oil	5.00	
- Shop Supplies	Napagold Oil Filter	1.00	
	Accufit Beam	2.00	
	Wpr/blde	1.00	
	Washer Fluid Concentr	1.00	
	Shop Supplies	1.00	
Hours 3.75	Labor: 225.00	Parts: 61.22	Total: 286.22
:			
Workorder: 1712607	Meter: 33138	In Date: 12/21/2017	Closed: 01/04/2018
Problem: ABS/Brake lights on.			
- Diagnose with scan tool the Abs light code C0037 and C003a . perform pinpoint test on circuits and replace both failed rear speed sensors with new .clear codes and road test.	Parts List	Qty	
- Load test battery due to slow crank.attempt to recharge and retest.replace failed battery with new.draw test and recheck charging system okay at this time.	Sensor Asy	2.00	
- Shop Supplies	Battery	1.00	
	Shop Supplies	1.00	
Hours 4.00	Labor: 240.00	Parts: 192.76	Total: 432.76
:			
Workorder: 1801115	Meter: 33820	In Date: 01/30/2018	Closed: 02/06/2018
Problem: P.M. service and detail.			
- P.m. service.	Parts List	Qty	
- Perform tire balance and rotation on all four wheels.nitrofill.	Napagold Oil Filter	1.00	
- Shop Supplies	5w20 Engine Oil	5.00	
	Mac Wite Lithium Gres	1.00	
	Shop Supplies	1.00	
Hours 3.75	Labor: 225.00	Parts: 21.10	Total: 246.10
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1801406	Meter: 33704	In Date: 02/06/2018	Closed: 02/06/2018
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued			
- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1808050	Meter: 36532	In Date: 08/06/2018	Closed: 08/15/2018
Problem: P.M. Service.			
- P.m. service. - Rotate and balance all four tires . Nitrofill. - Shop Supplies	Parts List		
	Napagold Oil Filter		
	5w20 Engine Oil		
	Washer Fluid Concentr		
	Blade		
	Wiper Blade		
	Wiper Blade		
	Napa Cabin Air Filter		
	Shop Supplies		
Hours 3.75	Labor: 225.00	Parts: 86.39	Total: 311.39
:			
Workorder: 1901144	Meter: 38542	In Date: 01/30/2019	Closed: 02/13/2019
Problem: P.M. service and detail.			
- P.m. service. - Replace two worn tires . Rotate and balance all four tires . Nitrofill all. - Shop Supplies	Parts List		
	Napagold Oil Filter		
	5w20 Engine Oil		
	Washer Fluid Concentr		
	Tire235/55/17 Mic		
	Shop Supplies		
	Tire Disposal Fee		
Hours 4.75	Labor: 318.25	Parts: 400.78	Total: 719.03
:			
Workorder: 1901534	Meter: 38457	In Date: 02/08/2019	Closed: 02/08/2019
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued			
- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1905423	Meter: 40987	In Date: 05/20/2019	Closed: 05/20/2019
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued			
- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1907882	Meter: 42497	In Date: 07/30/2019	Closed: 08/07/2019
Problem: PM Service, Check front tires, making loud noise.			
- P.m. Service.	Parts List	Qty	
- Replace leaking rear shocks	Napagold Oil Filter	1.00	
- Replace two tires,rotate and balance all four.	5w20 Engine Oil	5.00	
- Shop Supplies	Washer Fluid Concentr	1.00	
	Blade	1.00	
	Wiper Blade	1.00	
	Wiper Blade	1.00	
	Rear Shock Absorber	2.00	
	Tire235/55/17 Mic	2.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	2.00	
Hours 5.95	Labor: 398.65	Parts: 678.99	Total: 1,077.64
:			
Workorder: 1909887	Meter: 44014	In Date: 09/25/2019	Closed: 09/25/2019
Problem: 3 - Wash ticket(s) issued			
- 3 - Wash ticket(s) issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1911030	Meter: 44851	In Date: 10/25/2019	Closed: 10/30/2019
Problem: Missing right front fog light cap and noise front left front on turns and backing up .			
- Diagnose noise from left front . R&r defective left front axle assembly . Road test .	Parts List	Qty	
	Left Front Axle	1.00	
- Replace missing right side bumper grill .	Axle Nut	1.00	
- Shop Supplies	Cover	1.00	
	Grille	1.00	
	Shop Supplies	1.00	
Hours 2.50	Labor: 182.50	Parts: 300.87	Total: 483.37
:			
Workorder: 1913015	Meter: 46358	In Date: 12/19/2019	Closed: 12/30/2019
Problem: Left rear tire going flat .			
- Repair left rear tire and balance . Replace five defective lug nuts . Nitrofill all tires .	Parts List	Qty	
	Lug Nut	5.00	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 73.00	Parts: 37.30	Total: 110.30
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 2001598 **Meter:** 47694 **In Date:** 02/14/2020 **Closed:** 02/24/2020

Problem: PM Service, AC mold/fungus smell, Clicking noise in reverse, Noise left back door & fender, Headligh

- P.m. service.road test for noise in reverse could not duplicate at this time .	Parts List	Qty
- Diagnose smell from A/c . Replace cabin air filter and clean fresh air intake . Flush and deodorize A/c evap . Retest .	Napagold Oil Filter	1.00
- Recondition both headlight assemblies .	5w20 Engine Oil	5.00
- Rotate and balance all four tires . Nitrofill all.	Washer Fluid Concentr	1.00
- Shop Supplies	A C Odor Out	1.00
	Evap Odor Elinitator	1.00
	Napa Cabin Air Filter	1.00
	3m Tm Headlight Lens	1.00
	Shop Supplies	1.00
Hours 6.75	Labor: 492.75	Parts: 86.50
:		Total: 579.25

Workorder: 2006773 **Meter:** 51836 **In Date:** 07/10/2020 **Closed:** 07/27/2020

Problem: P.M. service, ABS and traction control lights on , clicking noise when backing and recall 16S30 .

- P.m. service.	Parts List	Qty
- Computer diagnose Abs light , code C003a . Perfrom pinpoint test . R&r defective right rear Abs wheel speed sensor . Clear code and retest .	Blade	1.00
- R&r broken right front overhead assiste handle .	Wiper Blade	1.00
- Replace both rear brake rotors and pads . Sertvice calipers . Flush and bleed brake system . Road test .	Wiper Blade	1.00
- Rotate and balance all four tires . Nitrofill all.	Washer Fluid Concentr	1.00
- Transport to and from dealer for recall 16s30 .	Napagold Oil Filter	1.00
- Shop Supplies	5w20 Engine Oil	5.00
	Rotor	2.00
	lube	1.00
	Brk Fluid Dot 4-32oz	1.00
	Rear Brake Pad	1.00
	Handle	1.00
	Sensor Asy	1.00
	Shop Supplies	1.00
Hours 12.05	Labor: 879.65	Parts: 452.89
:		Total: 1,332.54

Workorder: 2010071 **Meter:** 53489 **In Date:** 10/06/2020 **Closed:** 10/15/2020

Problem: Right side splash shield hanging down .

- Replace damaged engine splash shield and mounting nut inserts .	Parts List	Qty
- Shop Supplies	Nut	8.00
	Screw	8.00
	screw and	2.00
	Engine Cover Shield	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 73.00	Parts: 278.88
:		Total: 351.88

Workorder: 2011892 **Meter:** 53954 **In Date:** 12/01/2020 **Closed:** 12/01/2020

Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00 Labor: 146.00 Parts: 0.00 Total: 146.00
: