10187816

## Palm Beach County Fleet Management Asset Maintenance History 2012 CHEVROLET COLORADO CS1540 Pickup, Compact

Total Hours: 139.40		Parts: 6,505.92 Comm: 4,451.97		Charged: 19997.58				
Work Order: 12080 Problem: 1061	-	Meter: pection	166		In Date:	08/23/2012	Closed:	08/23/2012
Work Completed	l							
- Pre Delivery Ins	pection							
- Wash Vehicle								
	Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 0.0	0	Total:	180.00
Work Order: 12084 Problem: 1 - Wa		<b>Meter:</b> ed	167		In Date:	09/06/2012	Closed:	09/06/2012
Work Completed								
- 1 - Wash ticket(	s) issued							
	Hours: 0.00		Comm: 9.73	Labor: 0.00	Parts: 0.0	0	Total:	9.73
Work Order: 12096 Problem: order		Meter:	337		In Date:	10/09/2012	Closed:	10/18/2012
Work Completed	1			Parts Issued			Qı	uantity
- Open ticket and	order keys, notify	y custon	ner ready for pick up.	Ignition Key				2.00
- Shop Supplies				Shop Supplies				1.00
	Hours: 0.50		Comm: 0.00	Labor: 30.00	Parts: 25.	19	Total:	55.19
Work Order: 13011 Problem: Pm se		Meter:	2278		In Date:	01/31/2013	Closed:	02/11/2013
Work Completed	1			Parts Issued			Qı	uantity
- P.m. Service.				Dexos 5w30				5.00
- Rotate and bala	nce all tires.			Napagold Oil Filter				1.00
- Shop Supplies				Wd40 Spray Lube S	tock			1.00
				Shop Supplies				1.00
	Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 43.	61	Total:	223.61

10187816

#### Palm Beach County Fleet Management Asset Maintenance History 2012 CHEVROLET COLORADO CS1540 Pickup, Compact

Work Order: 1308319 Meter: 5853 08/19/2013 **Closed:** 09/06/2013 In Date: **Problem:** Pm service and recall #12319.Inspect for secondary hood latch. **Work Completed Parts Issued** Quantity Dexos 5w30 5.00 - Perform pm service. Napagold Oil Filter 1.00 - Perform rear drum brake service and adjust brake shoes. Wiper Blade 1.00 - Rotate, nitrogen fill and balance all four tires. Wiper Blade 1.00 - Transport vehicle to and from dealer for performing secondary hood latch 1.00 **Brake Cleaner** 

**Shop Supplies** 

Labor: 360.00

recall#12319

- Shop Supplies Hours: 6.00

Meter: 7660

Comm: 0.00

In Date:

Parts: 48.07

03/04/2014 Closed:

03/11/2014

1.00

Total: 408.07

Problem: P.M. service.

Work Order: 1402109

Work Completed		Parts Issued	Quantity	
- Perform pm service.		Napa Quart 5w30	5.00	
- Rotate and balance all four tires.		Napagold Oil Filte	er	1.00
- Shop Supplies		Washer Fl		1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 26.95	Total: 206.95

Work Order: 1408923 Meter: 10781 In Date: 09/04/2014 **Closed**: 09/26/2014

**Problem:** Pm service and ac blower intermittent.

Work Completed		Parts Issued	Quantity	
- Pm service.	Dexos 5w30 Oil		5.00	
- Inspect and service rear drum brakes.	Napagold Oil Filte	er	1.00	
- Rotate and balance all four tires.	Wiper Blade		1.00	
- Transport vehicle to and from dealer for replacing blower motor.		Wiper Blade		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 6.00	Comm: 0.00	Labor: 360.00	Parts: 44.62	Total: 404.62

10187816

#### Palm Beach County Fleet Management Asset Maintenance History 2012 CHEVROLET COLORADO CS1540 Pickup, Compact

Work Order: 1503031 Meter: 14203 In Date: 03/24/2015 Closed: 04/07/2015

**Problem:** Pm service.Right tail lamp inop.

Work Completed	Part	s Issued		Quantity
- Pm service.	Dexe	os 5w30 Oil		5.00
- Inspect front suspension and replace defective/leaking left fro	nt strut. Nap	agold Oil Filter	1.00	
- Test and replace defective right brake lamp bulb.	Wip	er Blade	1.00	
- Inspect and service rear drum brakes.	Wip	er Blade		1.00
- Rotate and balance all four tires.	Was	her Fluid Concer	ntr	1.00
- Shop Supplies	Bulb			1.00
	Fron	t Strut Rh		1.00
	Shop	Supplies		1.00
Hours: 6.00 Comn	n: 0.00 Labo	or: 360.00	Parts: 114.23	Total: 474.23

Work Order: 1511749 Meter: 18918 In Date: 11/17/2015 Closed: 12/09/2015

**Problem:** Pm service. Check driver side window and mirror.

Work Completed		Parts Issued		Quantity
- Pm service.	Dexos 5w30		5.00	
- Test starting and charging system.battery failed loadtest	t after	Napagold Oil Filte	r	1.00
recharge.replace defective battery.	Wiper Blade		2.00	
- Replace broken left view mirror assembly.		Washer Fluid Cond	centr	1.00
- Replace and balance all four tires.		Wiper Blade		1.00
- Complete front end alignment.test drive.	- Complete front end alignment.test drive.			1.00
- Shop Supplies		215 70r16 All Season		4.00
	Left Mirrior Assy			1.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 8.50	Comm: 0.00	Labor: 510.00	Parts: 871.11	Total: 1,381.11

10187816

#### Palm Beach County Fleet Management Asset Maintenance History 2012 CHEVROLET COLORADO CS1540 Pickup, Compact

Work Order: 1512876 Meter: 18918 In Date: 12/01/2015 Closed: 12/21/2015

Problem: damage to lft frt fender

#### **Work Completed**

- damage to lft frt fender

Hours: 0.00 Comm: 1,119.36 Labor: 0.00 Parts: 0.00 Total: 1,119.36

Work Order: 1605223 Meter: 21876 In Date: 05/19/2016 Closed: 05/31/2016

**Problem:** P.M. Service.

Work Completed		Parts Issued		Quantity
- P.m,. Service.		Napagold Oil Filte	1.00	
- Replace right brake lamp socket and bulb.		Dexos 5w30		5.00
- Service and adjust rear brakes.		Washer Fluid Con	centr	1.00
- Rotate and balance tires.		22" Wiper Blade		2.00
- Shop Supplies		Breake Light Socket Lamp Assy		1.00
		Shop Supplies		1.00
Hours: 4.50	Comm: 0.00	Labor: 270.00	Parts: 132.77	Total: 402.77

Work Order: 1612907 Meter: 26096 In Date: 12/16/2016 Closed: 01/23/2017

**Problem:** P.M. service and check lights.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Napa Syn 5w30 C	Qt .	5.00
- Replace left brake lamp bulb.	Napagold Oil Filte	r	1.00	
- Replace leaking rear wheel cylinders.flush and ble	ed system.	Washer Fluid Cond	centr	1.00
- Replace and balance four new tires.	22" Wiper Blade Bulb		2.00	
- Complete wheel alignment.test drive.			1.00	
- Transport vehicle to dealer for front engine cover	Drum Brake Whl C	2.00		
- Shop Supplies		B Fluid Dot 3-32oz 215/70r16 Wrangler Sra Tire		1.00
,				4.00
		20" Wiper Blade Shop Supplies		1.00
				1.00
		Tire Disposal Fee		4.00
Hours: 11.00	Comm: 0.00	Labor: 660.00	Parts: 602.65	Total: 1,262.65

10187816

#### Palm Beach County Fleet Management Asset Maintenance History 2012 CHEVROLET COLORADO CS1540 Pickup, Compact

Work Order: 1703095 Meter: 27411 In Date: 03/28/2017 Closed: 04/04/2017

**Problem:** Had to jump start in A/M.

Work Completed	Parts Issued	Quantity		
- Diagnose intermittent no crank/no start.b2960	Housing	1.00		
test.replace ignition/passlock housing.relearn pa	Bolt	1.00		
- Shop Supplies		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 102.04	Total: 282.04

Work Order: 1709385 Meter: 31697 In Date: 09/27/2017 Closed: 10/16/2017

**Problem:** P.M. service and low tire pressure light on.

Work Completed	Parts Issued	Quantity
- P.m. service.	Napa Quart 5w30	5.00
- Pressure test and inspect cooling system.flush with new.	Napagold Oil Filter	1.00
- Headlights inop.check system and diagnoise headlight switch f	led .r&r 22" Wiper Blade	1.00
with new.	Wiper Blade Anco	1.00
- Inspect and service rear brakes.	Washer Fluid Concentr	1.00
- Rotate and high speed balance all four tires.left rear tire pressu	e sensor Napagold Air Filter	1.00
failed .r&r with new.	Peak Global Antifrz	2.00
- Shop Supplies	Switch	1.00
	Sensor	1.00
	Napagold Oil Filter	1.00
	Napagold Air Filter	1.00
	Shop Supplies	1.00
Hours: 8.00 Comm	0.00 Labor: 480.00 Parts: 388.66	Total: 868.66

Work Order: 1710804 Meter: 32158 In Date: 11/01/2017 Closed: 11/02/2017

**Problem:** Right headlight out.

Work Completed	Parts Issued	Quantity		
- Replace right headlamp bulb.		Halogen Capsule		1.00
Hours: 0.50	Comm: 0.00	Labor: 30.00	Parts: 5.55	Total: 35.55

10187816

## Palm Beach County Fleet Management Asset Maintenance History 2012 CHEVROLET COLORADO CS1540 Pickup, Compact

Work Order:	1803523	Meter:	35822		In Date:	04/04/2018	Closed:	04/19/2018
Problem:	P.M. service and check engine	light on.						
Work Com	pleted			Parts Issued			Qı	uantity
- P.m. serv	ice.			Sensor				1.00
- Compute	er diagnoise check engine light .p	erform pinpo	int test .r&r	Door Handele				1.00
defective b	ank one sensor one oxygen sens	or .clear code	s and retest.	Brake Cylinder A/c [	Delco			2.00
- R&r brok	en left outside door handle asse	embly.		Sensor				3.00
•	eaking rear wheel cylinders .blee	d and flush bi	akes .service and	Big G Degreaser 1 G	al			1.00
	brake shoes.			5w20 Engine Oil				5.00
•	er diagnoise Tpms light .replace t	hree Tpms sei	nsors.rotate and	Napagold Oil Filter			1.00	
	four tires.nitrogen fill tires.			Wiper Blade Anco			1.00	1.00
- Shop Suբ	oplies			20" Wiper Blade				1.00
				Washer Fluid Conce	entr			1.00
				brake fluid				2.00
				Non-chlor Brake Clr	nr			2.00
				Door Handel				1.00
				Napa Quart 5w30				5.00
				Shop Supplies				1.00
	Hours: 10.50		Comm: 0.00	Labor: 630.00	Parts: 628	3.75	Total:	1,258.75
Work Order:		Meter:	37028		In Date:	05/30/2018	Closed:	05/31/2018
Problem:	Headlight out.							
Work Com	pleted			Parts Issued			Qı	uantity
- Test and	replace left low beam headlight	bulb.		Halogen Capsule				1.00
	Hours: 0.50		Comm: 0.00	Labor: 30.00	Parts: 8.7	2	Total:	38.72
Work Order:	1808751 Brake light out.	Meter:	39387		In Date:	08/24/2018	Closed:	08/28/2018
i iobiciii.	Drake light out.							
Work Com	pleted			Parts Issued			Qı	uantity
- Test and	replace right stop light bulb.			Boxed Miniatures				1.00
	Hours: 0.50		Comm: 0.00	Labor: 30.00	Parts: 0.7	7	Total:	30.77

10187816

### Palm Beach County Fleet Management Asset Maintenance History 2012 CHEVROLET COLORADO CS1540 Pickup, Compact

Work Order: 1809870 Meter: 40151 In Date: 09/25/2018 Closed: 10/04/2018

Problem: P.M. service and check lights.

Work Completed		Parts Issued		Quantity	
- P.m. service.		Napagold Oil Filte	Napagold Oil Filter		
- Check starting and charging system . Battery failed loa	Napa Quart 5w30	5.00			
defective battery.	20" Wiper Blade	1.00			
- Replace all four tires . Nitrogen fill and balance all four	r tires.	Wiper Blade Anco	1.00		
- Check lights and replace right brake bulb and retest.	Non-chlor Brake C	1.00			
- Perform front end alignment. Road test.	Battery	1.00			
- Shop Supplies	215/70r16 Wrangl	4.00			
		Shop Supplies		1.00	
		Tire Disposal Fee		4.00	
Hours: 8.00	Comm: 0.00	Labor: 536.00	Parts: 786.11	Total: 1,322.11	

Work Order: 1905702 Meter: 45741 In Date: 05/30/2019 Closed: 06/05/2019

Problem: P.M. service.

Work Completed		Parts Issued	Quantity	
- P.m. service.	Napagold Oil Filte	1.00		
- Inspect and service rear brakes .		Napa Quart 5w30	5.00	
- Rotate and high speed balance all four tires . Nitrofill	Washer Fluid Con	1.00		
- Shop Supplies		Wiper Blade Anco	1.00	
		20" Wiper Blade	1.00	
		Shop Supplies		1.00
Hours: 4.00	Comm: 0.00	Labor: 268.00	Parts: 35.54	Total: 303.54

10187816

# Palm Beach County Fleet Management Asset Maintenance History 2012 CHEVROLET COLORADO CS1540 Pickup, Compact

Work Order: 1906632 Meter: 46233 In Date: 06/25/2019 **Closed:** 07/03/2019

Problem: Check engine light on

Work Completed	Parts Issued		Quantity		
- Test fuel system . Perform complete air intake decarb and cleaning . Flush injectors .		Injector Cleaner		1.00	
		Intake Cleaner Kit		1.00	
- Remove intake to replace leaking valve cover gaskets . Clean excess oil from vehicle .		Spark Plugs A/c			4.00
		Non-chlor Brake Clnr		1.00	
	- Computer diagnose check engine light code P0303 and P0316 . Perform power balance test . Perform tune up , replace all four spark plugs . Clear codes and retest .				1.00
					1.00
- Shop Supplies					
Hours: 10.00	Comm: 0.00	Labor: 670.00	Parts: 183.54	Total:	853.54
ork Order: 1908487	Meter: 47208		In Date: 08/14/2019	Closed:	08/26/20

**Problem:** Radio doesn't work, A/C #3 doesn't work, Runs rough, Engine light on.

Work Completed	Parts Issued		Quantity
- Diagnose radio inop . Test and replace defective radio . Retest	Radio		1.00
- Diagnose A/c blower . Replace defective burnt blower resistor and ha	ness Harness		1.00
and blower motor . Retest operation.	A/c Blower Resisto	or	1.00
- Computer diagnose check engine light , codes P0106and P0107 . Perf	, ,		1.00
pinpoint test . R&r defective Map sensor and wire in new connector . Cle codes and retest .	ear Connector		1.00
	Sensor		1.00
- Shop Supplies	Shop Supplies		1.00
Hours: 6.00 Comm: 0.00	Labor: 402.00	Parts: 691.02	Total: 1,093.02

10187816

# Palm Beach County Fleet Management Asset Maintenance History 2012 CHEVROLET COLORADO CS1540 Pickup, Compact

Work Order: 1911804 Meter: 49294 In Date: 11/14/2019 Closed: 11/25/2019

Problem: P.m. service.

Work Completed		Parts Issued		Quantity
- P.m. service.	Napa Quart 5w30		5.00	
- Test and replace defective left tag light bulb .	Napagold Oil Filte	r	1.00	
- Rotate and balance all four tires . Nitrofill all.		20" Wiper Blade	1.00	
- Inspect and service rear brakes.		Wiper Blade Anco	1.00	
- Shop Supplies		Boxed Miniatures	1.00	
		Wheel Nut		1.00
		Shop Supplies		1.00
Hours: 4.50	Comm: 0.00	Labor: 328.50	Parts: 38.20	Total: 366.70

**Problem:** Both rear tires going flat .

Work Completed	Parts Issued		Quantity	
- Repair both rear tires and balance . Nitrofill all and reset Tpms .		Shop Supplies		1.00
- Shop Supplies				
Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 4.00	Total: 150.00

fender

10187816

Hours: 0.00

## Palm Beach County Fleet Management Asset Maintenance History 2012 CHEVROLET COLORADO CS1540 Pickup, Compact

Work Order: 2004779 Problem: P.M. service.	<b>Meter:</b> 52523		In Date:	05/12/2020	Closed:	05/26/2020
Work Completed		Parts Issued			Qı	uantity
- P.m. service.		Napagold Oil Filte	er			1.00
<ul> <li>Computer diagnose check engine light,code P0455 . Perform evap test .</li> <li>R&amp;r defectivepurge valve and vent valve . Retest and clear code .</li> <li>Pressure test and inspect cooling system . R&amp;r leaking radiator and cap .</li> <li>Flush cooling system and refill . Test drive .</li> <li>Rotate and balance all four tires . Nitrofill all</li> </ul>		Napa Quart 5w30				5.00
		Washer Fluid Con-	centr			1.00
		20" Wiper Blade				2.00
		Chevy Gold Bow S	Swc			1.00
		Evap Valve				1.00
·	- Inspect and service rear brakes.		Hose Evap			1.00
- Shop Supplies		Dex Coolant Engir	ne			1.00
		Radiador Assy				1.00
		Rad Cap				1.00
		Shop Supplies				1.00
Hours: 11.50	Comm: 0.00	Labor: 839.50	Parts: 40	5.51	Total:	1,245.01
Work Order: 2010733 Problem: minor accident	<b>Meter:</b> 56938		In Date:	10/22/2020	Closed:	10/26/2020
Work Completed						
- Tow From: Okeeheelee Maint Compo	ound To: Accident line					
Hours: 0.00	Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00
Work Order: 2012787 Problem: Damage to front bumper, le	<b>Meter:</b> 56938 eft front fender, hood, left door & righ	t rear fender	In Date:	10/29/2020	Closed:	12/22/2020
Work Completed						
- Damage to front bumper, left front fe	ender hood left door & right rear					

Comm: 3,136.48 Labor: 0.00

Total: 3,136.48

Parts: 0.00

- Shop Supplies

Hours: 1.50

10187816

## Palm Beach County Fleet Management Asset Maintenance History 2012 CHEVROLET COLORADO CS1540 Pickup, Compact

Work Order: 2100086 Problem: It is also due for PM Service. Ca	<b>Meter:</b> 57330 n you please complete the PM		In Date:	01/05/2021	Closed:	01/13/2021
Work Completed	Parts Issued	Parts Issued				
- Preventive Maint. Service		Napagold Oil Filter				1.00
- All tires worn to or below 4/32nds. Replace all 4 worn out tires with new. mount balance and nitrogen fill tires. Reinstall.		Napa Syn 5w30 Qt				5.00
		20" Wiper Blade				2.00
- Service rear brakes and adjust parking brake. Lube assemblies. Reassemble. Remove brake fluid from reservoir with extractor and refill to clean.		215/70r16 Cont				4.00
		Non-chlor Brake Cln	r			2.00
	t machina Usa alignment	Shop Supplies				1.00
<ul> <li>Preform 4 wheel alignment using alignment machine. Use alignment machine to adjust Toe into spec. Re-center steering wheel. Test drive to verify alignment.</li> </ul>		Tire Disposal Fee				4.00
- Shop Supplies						
Hours: 7.50	Comm: 0.00	Labor: 547.50	Parts: 89	4.53	Total:	1,442.03
Work Order: 2101851 Problem: Had to jump start and reaim head	<b>Meter:</b> 58256 dlights .		In Date:	02/18/2021	Closed:	02/23/2021
Work Completed		Parts Issued			Q	uantity
<ul><li>Charge battery fully . Diagnose bad battery, Replace battery and service cables.</li><li>Aim headlamps</li></ul>		Battery				1.00
		Shop Supplies				1.00

Comm: 0.00

Labor: 109.50

Parts: 223.78

Total: 333.28

10187816

## Palm Beach County Fleet Management Asset Maintenance History 2012 CHEVROLET COLORADO CS1540 Pickup, Compact

Work Order:		Meter:			In Date:	06/29/2021	Closed:	07/07/2021
Problem:	PM Service. Left front window in	nop and left b	rake light out					
Work Com	Work Completed			Parts Issued			Qı	uantity
- Preventiv	ve Maint. Service			Napa Syn 5w30 Qt				5.00
- Rotated a	- Rotated and balanced all 4 tires. Nitrogen filled all tires.			Napagold Oil Filter				1.00
- Diagnose	- Diagnose left brake light out. Found to have bad bulb. Replaced bad bulb.		20" Wiper Blade	20" Wiper Blade				
- Diagnose	e Left window inop. Found to hav	e broken wind	dow regulator. R	Windshield Washer				1.00
and R wind	low regulator.			Steering Wheel Cove	r Large			1.00
•	- Inspect and service rear brakes . Replaced both leaking rear wheel		Boxed Miniatures				1.00	
-	lushed braked fluid. Test drove.			Non-chlor Brake Clnr				2.00
- Shop Sup	oplies			Brk Fluid Dot 4-32oz				1.00
				Brake Cylinder				2.00
				Window Regulator				1.00
				Shop Supplies				1.00
	Hours: 7.90		Comm: 0.00	Labor: 576.70	Parts: 200	0.06	Total:	776.76
Work Order:		Meter:	61400		In Date:	08/13/2021	Closed:	
Problem:	NO START							
Work Com	pleted							
-								
	Hours: 0.00		Comm: 0.00	Labor: 0.00	Parts: 0.0	0	Total:	0.00
Work Order:	2108857 NO START	Meter:	61400		In Date:	08/13/2021	Closed:	08/16/2021
Problem:	NO START							
Work Com	pleted							
- Tow Fron	n: Okeeheelee Park To:							
	Hours: 0.00		Comm: 90.40	Labor: 0.00	Parts: 0.0	0	Total:	90.40
Work Order:		Meter:	61400		In Date:	08/20/2021	Closed:	08/20/2021
Problem:	Transition Prep Charge							

#### **Work Completed**

- Transition Prep Charge

10187816

Palm Beach County Fleet Management Asset Maintenance History 2012 CHEVROLET COLORADO CS1540 Pickup, Compact

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 139.40

Total Labor: 9,039.70

Total Comm: 4,451.97

Total Parts: 6,505.92