

10/17/2025
10:26:33 AM

Palm Beach County Fleet Management Asset Maintenance History
10210363 2019 FORD F150 Pickup, 1/2 Ton, Ext Cab

Total Hours: 98.50 Labor: 7,190.50 Parts: 3,791.46 Comm: 4,392.80 Charged: 15374.76

Work Order: 1910561 **Meter:** 300 **In Date:** 10/11/2019 **Closed:** 10/15/2019
Problem: pre delivery inspection

Work Completed

Parts Issued

Quantity

- pre delivery inspection
- Shop Supplies

Shop Supplies 1.00

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 4.00 Total: 150.00

Work Order: 2001422 **Meter:** 5515 **In Date:** 02/10/2020 **Closed:** 02/18/2020
Problem: PM Service.

Work Completed

Parts Issued

Quantity

- Pm Service.
- Rotate and balance tires.
- Shop Supplies

Napa Quart 5w20 6.00

Napagold Oil Filter 1.00

Washer Fluid Concentr 1.00

Shop Supplies 1.00

Hours: 2.75 Comm: 0.00 Labor: 200.75 Parts: 34.20 Total: 234.95

Work Order: 2006084 **Meter:** 10990 **In Date:** 06/18/2020 **Closed:** 06/23/2020
Problem: PM service.Floor mats.Steering wheel cover.Trailer brake message on dash.

Work Completed

Parts Issued

Quantity

- Pm Service.
- Replace floor mats and steering covers.
- Replace corroded trailer socket
- Rotate and balance tires.
- Shop Supplies

Napagold Oil Filter 1.00

Napa Quart 5w20 6.00

22" Wiper Blade 2.00

Washer Fluid Concentr 1.00

Napagold Air Filter 1.00

Used Fire X Refurbished 1.00

2pc Hd Mat Set Blk 1.00

Ford Triton Pvc Swc 1.00

trailer plug 1.00

Shop Supplies 1.00

Hours: 5.75 Comm: 0.00 Labor: 419.75 Parts: 136.32 Total: 556.07

10/17/2025
10:26:33 AM

Palm Beach County Fleet Management Asset Maintenance History
10210363 2019 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 2010561 **Meter:** 16544 **In Date:** 10/21/2020 **Closed:** 11/13/2020
Problem: PM Service.Trailer brake message.Tail light and sluggish on turns.

Work Completed

- Preventive Maint. Service
- cabin air filter.
- replace right rear tail light.
- rotate & balance tires.
- Replace damage trailer plug wire harness and replace socket.
- Shop Supplies

Parts Issued

Quantity

Napa Quart 5w20	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Cabin Air Filter	1.00
Boxed Miniatures	1.00
Wire Term 16-14 Blt	10.00
trailer plug	1.00
Term 8 12-10 Connectr	10.00
Shop Supplies	1.00

Hours: 6.75

Comm: 0.00

Labor: 492.75 Parts: 95.38 Total: 588.13

Work Order: 2102513 **Meter:** 22020 **In Date:** 03/04/2021 **Closed:** 03/10/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- replaced ac cabin filter
- replaced damaged 6 way socket and repaired wiring harness
- rotate balanced 4 tires
- replaced how's my driving sticker and worn decal
- clean engine compartment
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Oil Filter	1.00
Napa Quart 5w20	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Cabin Filter	1.00
trailer plug	1.00
Shop Supplies	1.00

Hours: 6.75

Comm: 0.00

Labor: 492.75 Parts: 91.06 Total: 583.81

10/17/2025
10:26:33 AM

Palm Beach County Fleet Management Asset Maintenance History
10210363 2019 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 2104175 **Meter:** 23746 **In Date:** 04/13/2021 **Closed:** 04/15/2021
Problem: Right front tire damage not repairable.

Work Completed

- Replace right front tire and mount spare back under vehicle.
- Shop Supplies

Parts Issued

Quantity

245/70/17 Tire Mich	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 285.84 Total: 358.84

Work Order: 2105290 **Meter:** 25496 **In Date:** 05/11/2021 **Closed:** 05/24/2021
Problem: Right rear turn signal inop.

Work Completed

- Test and replace bad right rear turnsignal light bulb

Parts Issued

Quantity

Boxed Miniatures	1.00
------------------	------

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 0.77 Total: 37.27

Work Order: 2106897 **Meter:** 28538 **In Date:** 06/24/2021 **Closed:** 06/30/2021
Problem: PM Service.

Work Completed

- Performed P.m. Service & Inspection.
- Performed Tire Rotation Balance On All 4 Wheels, Reset Tpms.
- Strobes Lights Inop Check Power And Ground, Found No Ground Trace Wire, Found Short In Wire & Switch Repair Then Replaced And Checked.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Universal Switch	1.00
Shop Supplies	1.00

Hours: 3.80 Comm: 0.00 Labor: 277.40 Parts: 61.74 Total: 339.14

10/17/2025
10:26:33 AM

Palm Beach County Fleet Management Asset Maintenance History
10210363 2019 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 2110783 **Meter:** 35258 **In Date:** 10/05/2021 **Closed:** 10/14/2021
Problem: PM Service. flat tire on right front

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Mount Two New Tires, Rotate And Balance Four. Nitro Fill All .
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
245/70/17 Tire Mich	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 438.91 Total: 730.91

Work Order: 2200212 **Meter:** 40486 **In Date:** 01/07/2022 **Closed:** 01/13/2022
Problem: PM Service. passenger front tire has a slow leak

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Checked Rf tire for leak. Unable to repair leak replaced 2 tires. Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Battery tested bad. Charged battery fully and retested bad. Replaced bad battery. Use scan tool to reset Bms.
- Replaced cabin filter. Clean debris from fresh air intake.
- Shop Supplies

5w20 Engine Oil	6.00
Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
245/70/17 Tire Mich	2.00
Battery	1.00
Cabin Filter	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 6.00 Comm: 0.00 Labor: 438.00 Parts: 663.11 Total: 1,101.11

Work Order: 2201557 **Meter:** 42613 **In Date:** 02/11/2022 **Closed:** 02/11/2022
Problem: screw in driver"s rear tire

Work Completed

Parts Issued

Quantity

- Tire Repair
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

10/17/2025
10:26:33 AM

Palm Beach County Fleet Management Asset Maintenance History
10210363 2019 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 2308874 **Meter:** 71018 **In Date:** 08/31/2023 **Closed:** 09/08/2023
Problem: PM Service and steering wheel cover

Work Completed

- Perform Pm Service
- Repair right rear tire, Rotate, balance all4 and nitro service all.
- Shop Supplies

Parts Issued

Quantity

Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Steering Wheel Cover Large	1.00
Used Fire X Refurbished	1.00
Napagold Air Filter	1.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 292.00 Parts: 75.59 Total: 367.59

Work Order: 2400551 **Meter:** 75529 **In Date:** 01/18/2024 **Closed:** 01/30/2024
Problem: P.M. service and left rear tire going flat

Work Completed

- Preventive Maint. Service
- patch right Front 1 mount 1 tire rotate and balance all 4 tires nitro fill all
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
245/70/17 Tire Mich	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 4.00

Comm: 0.00

Labor: 292.00 Parts: 236.38 Total: 528.38

10/17/2025
10:26:33 AM

Palm Beach County Fleet Management Asset Maintenance History
10210363 2019 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 2405459 **Meter:** 80659 **In Date:** 06/04/2024 **Closed:** 06/13/2024
Problem: PM Service

Work Completed

- Preventive Maint. Service complete
- check,pin point test and replaced defective r/r turn signal bulb
- check,verify needs front pads,sop ,resurfaced both front brake rotors,replaced pads,czlipers,flush and bleed fluid then road test to verify normal oeration
- Diagnose engine misfire .performed major tune up by replaced all six sprk plugs and upper intake manifold gaskets
- performed top engine decab , injector flush and clean throttl body
- check battry,charging system after fully charge it fail load test,r&r defective battery and reset bms
- Shop Supplies

Parts Issued

Quantity

Cover	1.00
Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	2.00
Boxed Miniatures	1.00
Bracketed Caliper	1.00
Bracketed Caliper	1.00
Brake Pad	1.00
Brake Fl-dot 3-4 32oz	1.00
Spark Plug	6.00
Plenum Gskt Set	1.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Battery	1.00
Brake Rotor	2.00
Shop Supplies	1.00

Hours: 13.70

Comm: 0.00

Labor: 1,000.10

Parts: 877.04

Total: 1,877.14

Work Order: 2407854 **Meter:** 83440 **In Date:** 08/14/2024 **Closed:** 08/15/2024
Problem: left rear flat tire

Work Completed

- Repair left rear tire and balance . Nitro fill all and reset Tpms . Remount spare
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

10/17/2025
10:26:33 AM

Palm Beach County Fleet Management Asset Maintenance History
10210363 2019 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 2409823 **Meter:** 85269 **In Date:** 10/11/2024 **Closed:** 10/21/2024
Problem: PM Service PM Service. Cracked windshield.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Rotated and balanced all 4 tires. Nitrogen filled all tire.
- Diagnose check engine light codesp0171 and P0420. Codes were not current. Performed crankshaft relearn. Cleaned codes and test drove.
- Replaced cabin filter and cleaned debris from fresh air intake.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	2.00
White Lithium Grease	1.00
Cabin Air Filter	1.00
Shop Supplies	1.00

Hours: 4.50

Comm: 0.00

Labor: 328.50

Parts: 46.09

Total: 374.59

Work Order: 2410115 **Meter:** 85269 **In Date:** 10/22/2024 **Closed:** 10/29/2024
Problem: replace cracked windshield

Work Completed

Parts Issued

Quantity

- Glass,cab, set up repairs & asset
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 704.12

Labor: 73.00

Parts: 2.65

Total: 779.77

Work Order: 2502819 **Meter:** 90433 **In Date:** 03/25/2025 **Closed:** 04/07/2025
Problem: PM Service.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 219.00

Parts: 48.94

Total: 267.94

10/17/2025
10:26:33 AM

Palm Beach County Fleet Management Asset Maintenance History
10210363 2019 FORD F150 Pickup, 1/2 Ton, Ext Cab

Work Order: 2507502 **Meter:** 95312 **In Date:** 08/11/2025 **Closed:** 08/14/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 98.50

Total Labor: 7,190.50

Total Comm: 4,392.80

Total Parts: 3,791.46