

1/2/2018
10:57:23AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 744654

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	Quantity
In Date: 09/26/2007	Hours	Description	
- Pre-Delivery Inspection	8.00		
Parts Charge: 0.00	Labor Charge: 440.00		

Workorder: 745296

Problem: 9950

Meter Reading: 11	Labor	Parts	Quantity
In Date: 10/05/2007	Hours	Description	
- On Site Lube And Fueling	26.00	SHOP SUPPLIES	1.00
- Fabricate Mud Flap To Mount On Loader			
- Fill Tires W/Water			
- Fueled And Lubed			
- Field Service Run			
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 360.00		

Workorder: 746178

Problem: 9950

Meter Reading: 50	Labor	Parts	Quantity
In Date: 10/25/2007	Hours	Description	
- On Site Lube And Fueling	10.00	SHOP SUPPLIES	1.00
- Shop Supplies		15/40 OIL	2.00
Parts Charge: 5.99	Labor Charge: 600.00		

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 833431

Problem: 9950

Meter Reading: 267		Labor		Parts	Quantity
In Date: 01/30/2008	Close Date: 03/13/2008	Hours	Description		
- Lube & Fueled		17.00	SHOP SUPPLIES		1.00
- Repair Broken Grease Fitting.Drill Out And Tap. Repair Fittings.					
- To Boca Pit 3 Times					
- Lube & Fuel 2 Times					
- Stand By					
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 180.00			

Workorder: 836007

Problem: 9103

Meter Reading: 400		Labor		Parts	Quantity
In Date: 03/25/2008	Close Date: 04/03/2008	Hours	Description		
- Pm Service		9.00	1R-0762		1.00
- Travel			7X-6041		2.00
- Shop Supplies			245-3819		1.00
			1R-1808		1.00
			245-3818		1.00
			SHOP SUPPLIES		1.00
			1R-0770		1.00
Parts Charge: 376.08		Labor Charge: 120.00			

Workorder: 837177

Problem: 9950

Meter Reading: 483		Labor		Parts	Quantity
In Date: 04/18/2008	Close Date: 04/25/2008	Hours	Description		
- Lube/Fuel		3.00	SHOP SUPPLIES		1.00
- Lube Fuel					
- Fuel/Lube					
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 60.00			

1/2/2018
10:57:23AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 837558

Problem: 9950

Meter Reading: 503		Labor		Parts	
In Date: 04/25/2008	Close Date: 05/29/2008	Hours	Description		Quantity
- On Site Lube		12.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 720.00			

Workorder: 839232

Problem: 9950

Meter Reading: 605		Labor		Parts	
In Date: 05/30/2008	Close Date: 06/27/2008	Hours	Description		Quantity
- Onsite Lube		12.00	SHOP SUPPLIES		1.00
- Hyd Leak,Clean Sys. Locate And Repair Leak.Test Run Ok			MUD FLAP		1.00
- Frt Mudflap Order.Remove Rusted Bolts And Replace Frt Mud Flap					
- Shop Supplies					
Parts Charge: 65.56		Labor Charge: 60.00			

Workorder: 840654

Problem: 9103

Meter Reading: 692		Labor		Parts	
In Date: 06/27/2008	Close Date: 07/25/2008	Hours	Description		Quantity
- Perform Onsite Lube		14.50	AIR FILTER		1.00
- Pm Service			AIR FILTER		1.00
- Ir0769 Part Order.Replace Fuel Filter Drain/Glass Section			OIL FILTER		1.00
- Shop Supplies			FUEL FILTER		1.00
			FUEL FILTER		1.00
			CAB FILTER		2.00
			SEAL O-RING		1.00
			FUEL BOWEL		1.00
			SHOP SUPPLIES		1.00
Parts Charge: 398.03		Labor Charge: 30.00			

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 841853		Problem: 9950			
Meter Reading: 757					
In Date: 07/23/2008		Close Date: 09/05/2008			
		Labor Hours	Description	Parts	Quantity
- On Site Lube		12.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	720.00	
Workorder: 844335		Problem: 9950			
Meter Reading: 904					
In Date: 09/17/2008		Close Date: 09/30/2008			
		Labor Hours	Description	Parts	Quantity
- Onsite Lube		13.00	SHOP SUPPLIES		1.00
- Repair Ac Part On Order.Remv Evaporator Cover Ck			HOUSING		1.00
Burning Smlin Ac,Repl Fan Housing.			1355 NEW CAT YELLOW PLASTI-KOTE		2.00
- Sent To Kelly Tractor To Pickup Part					
- Shop Supplies					
Parts Charge:		49.49	Labor Charge:	60.00	
Workorder: 844991		Problem: 9950			
Meter Reading: 917					
In Date: 10/01/2008		Close Date: 11/04/2008			
		Labor Hours	Description	Parts	Quantity
- On Site Lube		14.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	840.00	
Workorder: 846728		Problem: 9950			
Meter Reading: 1022					
In Date: 11/04/2008		Close Date: 12/06/2008			
		Labor Hours	Description	Parts	Quantity
- Onsite Lube		12.00	NUTS		12.00
- Replace All Cutting Edge On Bucket.			CUTTING EDGE		2.00
- Drop Off Blades.			SHOP SUPPLIES		1.00
- Shop Supplies			CUTTING EDGE		2.00
			BOLTS		12.00
Parts Charge:		1,930.49	Labor Charge:	120.00	

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 847712

Problem: 9950

Meter Reading: 1029		Labor		Parts	
In Date: 12/03/2008	Close Date: 01/30/2009	Hours	Description		Quantity
- Onsite Lube		18.50	USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Replace Fire Ext			AIR FILTER		1.00
- Pm Svc			OIL FILTER		1.00
- Shop Supplies			FUEL FILTER		1.00
			FUEL FILTER		1.00
			CAB FILTER		2.00
			WIPER BLADES		1.00
			ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407)		2.00
			SHOP SUPPLIES		1.00
			AIR FILTER		1.00
Parts Charge: 493.92		Labor Charge: 420.00			

Workorder: 933432

Problem: HARDFACE THE BUCKET

Meter Reading: 1135		Labor		Parts	
In Date: 02/03/2009	Close Date: 03/05/2009	Hours	Description		Quantity
- Hard Fale Bucket By Vanlinda		11.00	SHOP SUPPLIES		1.00
- Onsite Lube					
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 660.00		Commercial Charge: 1,099.20	

Workorder: 935657

Problem: 9950

Meter Reading: 1209		Labor		Parts	
In Date: 03/25/2009	Close Date: 04/29/2009	Hours	Description		Quantity
- On Site Lube		29.50	STEPS BELT		2.00
- Step Bracket.Replace Step Assy L/Rear			15/40 OIL		4.00
- Paint Spray Rust Spot On Loader.			1355 NEW CAT YELLOW PLASTI-KOTE		3.00
- Wash Equipment. 03/27/09			SHOP SUPPLIES		1.00
- Wash Equipment 04/27/09			BRACKET ASSY		2.00
- Shop Supplies					
- Safety Check At Boca Pit 04/24/09*					
Parts Charge: 243.52		Labor Charge: 1,470.00			

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 937213

Problem: 9950

Meter Reading: 1383		Labor		Parts	
In Date: 04/30/2009	Close Date: 06/24/2009	Hours	Description		Quantity
- Onsite Lube		36.00	OIL FILTER		1.00
- Pm Service			FUEL FILTER		1.00
- Shop Supplies			AIR FILTER		1.00
			FUEL FILTER		1.00
			15/40 OIL		36.00
			CAB FILTER		2.00
			85/140 GEAR OIL GEAR LUBE		26.00
			AIR FILTER		1.00
			H/DUTY A/FREEZE EXT/LIFE (CAT 238-8648)		1.00
			SHOP SUPPLIES		1.00
Parts Charge: 535.14		Labor Charge: 2,160.00			

Workorder: 940032

Problem: 9950

Meter Reading: 1560		Labor		Parts	
In Date: 07/02/2009	Close Date: 07/29/2009	Hours	Description		Quantity
- On Site Lube		17.00	AW68 HYDRO FLUID HYDRAULIC OIL 68		100.00
- Commercial Workorder Entry Replace Five Hyd. Lines			SHOP SUPPLIES		1.00
- Boca Pit To Masthead For Hyd. Lines					
- Shop Supplies					
Parts Charge: 239.57		Labor Charge: 1,020.00		Commercial Charge: 125.64	

Workorder: 942534

Problem: 9950

Meter Reading: 1720		Labor		Parts	
In Date: 08/26/2009	Close Date: 09/01/2009	Hours	Description		Quantity
- Onsite Lube		13.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 600.00			

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 942841

Problem: 9950

Meter Reading: 1741		Labor		Parts	
In Date: 09/01/2009	Close Date: 09/28/2009	Hours	Description		Quantity
- On Site Lube		20.50	SHOP SUPPLIES		1.00
- Flip The Cutting Edge					
- To The Boca Pit And Back					
- Replace The Cutting Edge					
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 1,080.00			

Workorder: 944139

Problem: 9950

Meter Reading: 1833		Labor		Parts	
In Date: 10/02/2009	Close Date: 11/02/2009	Hours	Description		Quantity
- Onsite Lube		21.00	AIR FILTER 245-3818		1.00
- P.M.			AIR FILTER 245-3819		1.00
- R&R Hyd. Filters			Oil Filter		1.00
- Service Transmission			FUEL FILTER 326-1644		1.00
- Shop Supplies			CAB FILTER 7X-6041		2.00
			WIPER BLADE 6V-7419		2.00
			HYDRAULIC FILTER 225-4118		1.00
			15/40 OIL		36.00
			HYDRAULIC FILTER 144-0832		1.00
			HYDRAULIC FLUID 50WT (5GAL PAIL) 8T9576		4.00
			SHOP SUPPLIES		1.00
			TRANS FILTER 328-3655		1.00
			FUEL FILTER 1R-0762		1.00
Parts Charge: 1,408.52		Labor Charge: 1,260.00			

Workorder: 945690

Problem: 9950

Meter Reading: 1929		Labor		Parts	
In Date: 11/04/2009	Close Date: 11/30/2009	Hours	Description		Quantity
- Onsite Lube		8.00	15/40 OIL		2.00
- Check A/C			SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 6.15		Labor Charge: 960.00			

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 946465

Problem: 9950

Meter Reading: 1983		Labor		Parts	
In Date: 11/30/2009	Close Date: 01/04/2010	Hours	Description		Quantity
- On Site Lube		13.00	BLEND DOOR / 320-1457		1.00
- Repair A/C			SHOP SUPPLIES		1.00
- Shop Supplies			BLEND DOOR / 177-6716		1.00
			FOAM PAD / 199-7499		1.00
			DOOR ACCUATOR / 177-6727		1.00
			LEVER / 179-4682		2.00
			ROD / 179-4683		1.00
Parts Charge: 245.26		Labor Charge: 1,560.00			

Workorder: 1000117

Problem: 9950

Meter Reading: 2065		Labor		Parts	
In Date: 01/04/2010	Close Date: 02/23/2010	Hours	Description		Quantity
- On Site Lube		24.00	SUPPORT ASSY		1.00
- Pm Service			AW68 HYDRO FLUID HYDRAULIC OIL 68		12.00
- Repair L. S. Step			SHOP SUPPLIES		1.00
- Shop Supplies			15/40 OIL		36.00
			15/40 OIL		2.00
			OIL FILTER		1.00
			FUEL FILTER		1.00
			CAB FILTER		2.00
			FUEL FILTER		1.00
			TRANSMISSION FILTER		1.00
			HYDRAULIC FILTER		1.00
			STEP ASSY		1.00
			STRAPS		2.00
			AIR FILTER		1.00
			HYDRAULIC FILTER		1.00
			WIPER BLADE		2.00
			AIR FILTER		1.00
			LATCH		1.00
Parts Charge: 1,956.13		Labor Charge: 1,440.00			

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1001966		Problem: 9950			
Meter Reading: 2222					
In Date: 02/24/2010		Close Date: 03/22/2010			
		Labor Hours	Description	Parts	Quantity
- Onsite Lube		8.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	480.00	
Workorder: 1002920		Problem: 9950			
Meter Reading: 2310					
In Date: 03/22/2010		Close Date: 05/03/2010			
		Labor Hours	Description	Parts	Quantity
- On Site Lube		14.00	SHOP SUPPLIES		1.00
- Replace Fuel Sending Unit			FUEL SENDING UNIT		1.00
- Shop Supplies					
Parts Charge:		60.13	Labor Charge:	840.00	
Workorder: 1004587		Problem: 9950			
Meter Reading: 2441					
In Date: 05/03/2010		Close Date: 05/25/2010			
		Labor Hours	Description	Parts	Quantity
- On Site Lube		7.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	420.00	

1/2/2018
10:57:23AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1005488

Problem: 9103

Meter Reading: 2522		Labor		Parts	
In Date: 05/26/2010	Close Date: 06/23/2010	Hours	Description		Quantity
- Pm Service		25.00	TRANSMISSION FILTER		1.00
- On Site Lube			7X-6041 CAB FILTER FRM NONE WIX 42448		2.00
- Replace Cutting Edge			FUEL FILTER		1.00
- Service Trans Replace Filter			15/40 OIL		36.00
- Replace Two Hyd. Filters And Service			CUTTING EDGE		2.00
- Test Run			END BIT		1.00
- Fm To Benoist Pit			END BIT		1.00
- Fm To Kelly			BOLT		12.00
- Shop Supplies			NUT		12.00
			HYDRAULIC FILTER		1.00
			FUEL FILTER		1.00
			SHOP SUPPLIES		1.00
			AIR FILTER		1.00
			AIR FILTER		1.00
			OIL FILTER		1.00
			WIPER BLADE		2.00
			HYDRAULIC FILTER		1.00
Parts Charge: 3,026.90		Labor Charge: 1,500.00			

Workorder: 1006823

Problem: 9950

Meter Reading: 2629		Labor		Parts	
In Date: 06/29/2010	Close Date: 07/26/2010	Hours	Description		Quantity
- R&R Strobe Light		17.50	250ADH12A STROBE STROBE LIGHT 12/24VT		1.00
- R&R Door Latch			DOOR LATCH		2.00
- Change Out Lube In Front Axel			8T-9576 TRANS FLUID 50 WEIGHT (BY PAILS)		2.00
- R&R Cutting Edge			CAM LATCH		1.00
- Replace Fuel Cap			SHOP SUPPLIES		1.00
- On Site Lube			FUEL CAP		1.00
- Shop Supplies			15/40 OIL		64.00
Parts Charge: 721.25		Labor Charge: 1,050.00			

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1008602

Problem: PM Service

Meter Reading: 2832		Labor		Parts	
In Date: 08/10/2010	Close Date: 09/01/2010	Hours	Description	Quantity	
- Pm Service		18.00	1R-0762 FUEL FILTER FRM NONE WIX 33640	1.00	
- On Site Lube			1R-0716 OIL FILTER FRM HPH3335 WIX 51792XE	1.00	
- Repair Loader Control Valve Kelly			6V-7419 WIPER BLADE	2.00	
- Shop Supplies			15/40 OIL	4.00	
			326-1644 FUEL FILTER FRM PS10264 WIX 33606	1.00	
			7X-6041 CAB FILTER FRM NONE WIX 42448	2.00	
			245-3818 AIR FILTER FRM NONE WIX 49811	1.00	
			15/40 OIL	36.00	
			245-3819 AIR FILTER FRM NONE WIX 49810	1.00	
			SHOP SUPPLIES	1.00	
			15/40 OIL	8.00	
Parts Charge: 492.88		Labor Charge: 1,020.00		Commercial Charge: 4,295.63	

Workorder: 1010622

Problem: 9950

Meter Reading: 2917		Labor		Parts	
In Date: 09/28/2010	Close Date: 09/28/2010	Hours	Description	Quantity	
- On Site Lube		10.00	SHOP SUPPLIES	1.00	
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 60.00			

Workorder: 1011926

Problem: 9950

Meter Reading: 3014		Labor		Parts	
In Date: 10/25/2010	Close Date: 10/26/2010	Hours	Description	Quantity	
- On Site Lube		7.00	SHOP SUPPLIES	1.00	
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 420.00			

1/2/2018
10:57:23AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1013048

Problem: 9950

Meter Reading: 3094

In Date: 11/24/2010

Close Date: 11/30/2010

Labor

Hours

Description

Parts

Quantity

- On Site Lube	12.00	SHOP SUPPLIES	1.00
- Shop Supplies			

Parts Charge: 2.00

Labor Charge: 180.00

Workorder: 1013210

Problem: PM Service

Meter Reading: 3101

In Date: 11/30/2010

Close Date: 12/29/2010

Labor

Hours

Description

Parts

Quantity

- Pm Service	19.00	USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- On Site Lube		15/40 OIL	36.00
- Shop Supplies		PB-16 PBBLASTER	1.00
		326-1644 FUEL FILTER FRM PS10264 WIX 33606	1.00
		1R-0762 FUEL FILTER FRM NONE WIX 33640	1.00
		245-3818 AIR FILTER FRM NONE WIX 49811	1.00
		6V-7419 WIPER BLADE	1.00
		05023 BATTERY CLEANER	1.00
		SHOP SUPPLIES	1.00
		1R-0716 OIL FILTER FRM HPH3335 WIX 51792XE	1.00
		7X-6041 CAB FILTER FRM NONE WIX 42448	1.00
		245-3819 AIR FILTER FRM NONE WIX 49810	1.00

Parts Charge: 422.32

Labor Charge: 1,140.00

Workorder: 1100940

Problem: Hardface blade by Van Linda

Meter Reading: 3246

In Date: 01/25/2011

Close Date: 02/23/2011

Labor

Hours

Description

Parts

Quantity

- Hard Face By Vanlinda	17.50	SHOP SUPPLIES	1.00
- Replace Cutting Edges		NUT	12.00
- On Site Lube		BOLT	12.00
- Hook And Unhook Batteries For Welder		CUTTING EDGE	1.00
- Shop Supplies		CUTTING EDGE	2.00
		CUTTING EDGE	1.00

Parts Charge: 2,197.04

Labor Charge: 1,050.00

Commercial Charge: 2,386.80

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1102563

Problem: 9950

Meter Reading: 3377		Labor		Parts	
In Date: 03/07/2011	Close Date: 03/18/2011	Hours	Description		Quantity
- On Site Lube		16.50	326-1644 FUEL FILTER FRM PS10264 WIX 33606		1.00
- Pm Service			15/40 OIL		36.00
- Unhook Battery [Welding]			7X-6041 CAB FILTER FRM NONE WIX 42448		1.00
- Shop Supplies			6V-7419 WIPER BLADE		1.00
			245-3818 AIR FILTER FRM NONE WIX 49811		1.00
			SHOP SUPPLIES		1.00
			245-3819 AIR FILTER FRM NONE WIX 49810		1.00
			1R-0716 OIL FILTER FRM HPH3335 WIX 51792XE		1.00
			1R-0762 FUEL FILTER FRM NONE WIX 33640		1.00
Parts Charge: 400.46		Labor Charge: 990.00			

Workorder: 1104460

Problem: 9950

Meter Reading: 3666		Labor		Parts	
In Date: 04/26/2011	Close Date: 07/15/2011	Hours	Description		Quantity
- On Site Lube		56.00	E8 A/C OIL R134A A/C OIL (TSI)		1.00
- Replace Compressor,Dryer, Belt,Evac And Recharge			CUTTING EDGE		1.00
- Service Call Kelly Test Ride Control			FRONT MUD FLAP		2.00
- Fm To Boca Pit			NUT		5.00
- Replace Cutting Edge			BOLT		12.00
- Pm Service			326-1644 FUEL FILTER FRM PS10264 WIX 33606		1.00
- Replace Front Mud Flaps			1R-0716 OIL FILTER FRM HPH3335 WIX 51792XE		1.00
- Shop Supplies			245-3818 AIR FILTER FRM NONE WIX 49811		1.00
			A/C DRIER		1.00
			245-3819 AIR FILTER FRM NONE WIX 49810		1.00
			A/C COMPRESSOR		1.00
			SHOP SUPPLIES		1.00
			END BIT		2.00
			15/40 OIL		36.00
			BPLT		5.00
			NUT		12.00
			CUTTING EDGE		1.00
			FAN BELT		1.00
			1R-0762 FUEL FILTER FRM NONE WIX 33640		1.00
Parts Charge: 3,909.19		Labor Charge: 3,360.00		Commercial Charge: 1,892.41	

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1107632

Problem: 9950

Meter Reading: 3861		Labor		Parts	
In Date: 07/20/2011	Close Date: 08/16/2011	Hours	Description		Quantity
- On Site Lube		21.00	328-3655 TRANS FILTER FRM NONE WIX NONE		1.00
- Pm Service			15/40 OIL		36.00
- Repair Parking Brake Cable {Pull Dash}			1R-0716 OIL FILTER FRM HPH3335 WIX 51792XE		1.00
- Add Oil			326-1644 FUEL FILTER FRM PS10264 WIX 33606		1.00
- Shop Supplies			7X-6041 CAB FILTER FRM NONE WIX 42448		2.00
			245-3818 AIR FILTER FRM NONE WIX 49811		1.00
			AW68 HYDRO FLUID HYDRAULIC OIL 68		20.00
			1R-0762 FUEL FILTER FRM NONE WIX 33640		1.00
			144-0832 HYDR FILTER FRAM P7252 WIX 51746		1.00
			225-4118 HYDR FILTER (USE WIX 57418)		1.00
			SHOP SUPPLIES		1.00
			245-3819 AIR FILTER FRM NONE WIX 49810		1.00
Parts Charge: 603.19		Labor Charge: 1,260.00			

Workorder: 1108656

Problem: hyd. leak

Meter Reading: 3889		Labor		Parts	
In Date: 08/16/2011	Close Date: 08/24/2011	Hours	Description		Quantity
- On Site Lube		10.50	SHOP SUPPLIES		1.00
- Replace Hyd. Hose From Pump To Loader Control Valve					
- Fm To Boca Pit					
- To Mako					
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 630.00		Commercial Charge: 141.54	

Workorder: 1110364

Problem: 9950

Meter Reading: 4021		Labor		Parts	
In Date: 09/28/2011	Close Date: 10/04/2011	Hours	Description		Quantity
- On Site Lube		10.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 600.00			

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1111924

Problem: pm service

Meter Reading: 4138		Labor		Parts	
In Date: 11/07/2011	Close Date: 11/22/2011	Hours	Description		Quantity
- Pm Service		25.50	SHOP SUPPLIES		1.00
- Replace Cutting Edges			15/40 OIL		36.00
- On Site Lube			1R-0716 OIL FILTER FRM HPH3335 WIX 51792XE		1.00
- Fm To Boca Pit			326-1644 FUEL FILTER FRM PS10264 WIX 33606		1.00
- Shop Supplies			245-3819 AIR FILTER FRM NONE WIX 49810		1.00
			7X-6041 CAB FILTER FRM NONE WIX 42448		2.00
			225-4118 HYDR FILTER (USE WIX 57418)		1.00
			144-0832 HYDR FILTER FRAM P7252 WIX 51746		1.00
			328-3655 TRANS FILTER FRM NONE WIX NONE		1.00
			245-3818 AIR FILTER FRM NONE WIX 49811		1.00
			NUT		12.00
			BOLT		12.00
			CUTTING EDGE		2.00
			1R-0762 FUEL FILTER FRM NONE WIX 33640		1.00
			CUTTING EDGE		2.00
Parts Charge: 2,776.62		Labor Charge: 1,530.00			

Workorder: 1113532

Problem: 9950

Meter Reading: 4236		Labor		Parts	
In Date: 12/29/2011	Close Date: 01/26/2012	Hours	Description		Quantity
- On Site Lube 13Xs		13.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 780.00			

Workorder: 1201483

Problem: 9950

Meter Reading: 4334		Labor		Parts	
In Date: 02/14/2012	Close Date: 02/16/2012	Hours	Description		Quantity
- On Site Lube		8.00	SHOP SUPPLIES		1.00
- Fm To Boca Pit					
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 480.00			

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1201969

Problem: pm service

Meter Reading: 4357		Labor		Parts	
In Date: 02/28/2012	Close Date: 03/01/2012	Hours	Description		Quantity
- Pm Service		9.00	7X-6041 CAB FILTER FRM NONE WIX 42448		1.00
- Fm To Boca Pit			245-3819 AIR FILTER FRM NONE WIX 49810		1.00
- Shop Supplies			57418 HYDRAULIC FILTER (WIX)		1.00
			7X-6041 CAB FILTER FRM NONE WIX 42448		1.00
			15/40 OIL		36.00
			326-1644 FUEL FILTER FRM PS10264 WIX 33606		1.00
			144-0832 HYDR FILTER FRAM P7252 WIX 51746		1.00
			8T-9576 TRANS FLUID 50 WEIGHT (BY PAILS)		1.00
			328-3655 TRANS FILTER FRM NONE WIX NONE		1.00
			245-3818 AIR FILTER FRM NONE WIX 49811		1.00
			SHOP SUPPLIES		1.00
			1R-0716 OIL FILTER FRM HPH3335 WIX 51792XE		1.00
			1R-0762 FUEL FILTER FRM NONE WIX 33640		1.00
Parts Charge:		665.99	Labor Charge:	540.00	

Workorder: 1203796

Problem: low power

Meter Reading: 4484		Labor		Parts	
In Date: 04/23/2012	Close Date: 04/23/2012	Hours	Description		Quantity
- Replace Fuel Filter		2.00	SHOP SUPPLIES		1.00
- Shop Supplies			326-1644 FUEL FILTER FRM PS10264 WIX 33606		1.00
			1R-0762 FUEL FILTER FRM NONE WIX 33640		1.00
Parts Charge:		43.44	Labor Charge:	120.00	

Workorder: 1204191

Problem: 9950

Meter Reading: 4509		Labor		Parts	
In Date: 05/02/2012	Close Date: 05/03/2012	Hours	Description		Quantity
- On Site Lube		7.50	SHOP SUPPLIES		1.00
- Replace Back Up Alarm			9-2951 BACKUP ALARM ECCO 575 GROTE 73120		1.00
- Shop Supplies					
Parts Charge:		61.61	Labor Charge:	450.00	

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1205134

Problem: 9950

Meter Reading: 4578

In Date: 06/01/2012

Close Date: 06/01/2012

Labor

Hours

Description

Parts

Quantity

- On Site Lube	7.00	SHOP SUPPLIES	1.00
- Shop Supplies			

Parts Charge: 2.00

Labor Charge: 420.00

Workorder: 1205476

Problem: 9103

Meter Reading: 4632

In Date: 06/11/2012

Close Date: 06/19/2012

Labor

Hours

Description

Parts

Quantity

- P.M.	11.00	SHOP SUPPLIES	1.00
- On Site Lube		15/40 OIL	36.00
- Shop Supplies		1R-0716 OIL FILTER FRM HPH3335 WIX 51792XE	1.00
		1R-0762 FUEL FILTER FRM NONE WIX 33640	1.00
		6V-7419 WIPER BLADE	2.00
		245-3819 AIR FILTER FRM NONE WIX 49810	1.00
		7X-6041 CAB FILTER FRM NONE WIX 42448	2.00
		144-0832 HYDR FILTER FRAM P7252 WIX 51746	1.00
		57418 HYDRAULIC FILTER (WIX)	1.00
		328-3655 TRANS FILTER FRM NONE WIX NONE	1.00
		326-1644 FUEL FILTER FRM PS10264 WIX 33606	1.00
		245-3818 AIR FILTER FRM NONE WIX 49811	1.00

Parts Charge: 618.49

Labor Charge: 660.00

Workorder: 1206289

Problem: Hard face the bucket by Van Linda

Meter Reading: 4773

In Date: 07/05/2012

Close Date: 08/06/2012

Labor

Hours

Description

Parts

Quantity

- Hardface Bucket	15.00	SHOP SUPPLIES	1.00
- Reconect Batteries		LATCH ASSY	1.00

- To Boca Pit
- Replace Lock On Door
- On Site Lube
- Shop Supplies

Parts Charge: 36.37

Labor Charge: 900.00

Commercial Charge: 1,642.80

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1207574

Problem: Install Blade

Meter Reading: 4804

In Date: 08/13/2012

Close Date: 09/13/2012

Labor

Hours

Description

Parts

Quantity

-	Replace Blade Bolts/ Install Cutting Edge	17.00	CUTTING EDGE	2.00
-	To Pit 2Xs		CUTTING EDGE BOLTS	12.00
-	To Kelly Tractor		CUTTING EDGE NUTS	12.00
-	On Site Lube		CUTTING EDGE	2.00
-	Shop Supplies		CUTTING EDGE BOLTS	12.00
			CUTTING EDGE NUTS	12.00
			SHOP SUPPLIES	1.00
Parts Charge: 2,434.76		Labor Charge: 1,020.00		

Workorder: 1208843

Problem: P.M.

Meter Reading: 4895

In Date: 09/17/2012

Close Date: 09/25/2012

Labor

Hours

Description

Parts

Quantity

-	P.M.	13.00	15/40 OIL	36.00
-	On Site Lube		245-3818 AIR FILTER FRM NONE WIX 49811	1.00
-	Shop Supplies		1R-0716 OIL FILTER FRM HPH3335 WIX 51792XE	1.00
			57418 HYDRAULIC FILTER (WIX)	1.00
			1R-0762 FUEL FILTER FRM NONE WIX 33640	1.00
			7X-6041 CAB FILTER FRM NONE WIX 42448	2.00
			328-3655 TRANS FILTER FRM NONE WIX NONE	1.00
			6V-7419 WIPER BLADE	2.00
			245-3819 AIR FILTER FRM NONE WIX 49810	1.00
			326-1644 FUEL FILTER FRM PS10264 WIX 33606	1.00
			SHOP SUPPLIES	1.00
			144-0832 HYDR FILTER FRAM P7252 WIX 51746	1.00
			AW68 HYDRO FLUID HYDRAULIC OIL 68	15.00
Parts Charge: 625.10		Labor Charge: 780.00		

Workorder: 1209747

Problem: 9950

Meter Reading: 4934

In Date: 10/11/2012

Close Date: 10/12/2012

Labor

Hours

Description

Parts

Quantity

-	On Site Lube	2.00	SHOP SUPPLIES	1.00
-	Shop Supplies			
Parts Charge: 2.00		Labor Charge: 120.00		

1/2/2018
10:57:23AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1210133

Problem: Service differentials

Meter Reading: 4970		Labor		Parts	
In Date: 10/22/2012	Close Date: 10/30/2012	Hours	Description		Quantity
- Service Diff.		9.00	Differential Oil		3.00
- Service Diff.			Differential additive		2.00
- On Site Lube			8T-9576 TRANS FLUID 5		4.00
- Shop Supplies			SHOP SUPPLIES		1.00
Parts Charge: 1,155.95		Labor Charge: 540.00			

Workorder: 1210876

Problem: 9950

Meter Reading: 4986		Labor		Parts	
In Date: 11/06/2012	Close Date: 11/13/2012	Hours	Description		Quantity
- On Site Lube		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 60.00			

Workorder: 1211366

Problem: 9950

Meter Reading: 5000		Labor		Parts	
In Date: 11/26/2012	Close Date: 11/26/2012	Hours	Description		Quantity
- On Site Lube		5.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 300.00			

Workorder: 1212149

Problem: 9950

Meter Reading: 5044		Labor		Parts	
In Date: 12/18/2012	Close Date: 12/18/2012	Hours	Description		Quantity
- On Site Lube		3.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 180.00			

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1300112

Problem: fuel filters

Meter Reading: 5063

In Date: 01/03/2013

Close Date: 01/08/2013

Labor

Hours

Description

Parts

Quantity

- Replace Fuel Filters	3.00	OIL FILTER 3261644	1.00
- Fm To Boca Pit		SHOP SUPPLIES	1.00
- Shop Supplies		FUEL FILTER	1.00

Parts Charge: 38.12

Labor Charge: 180.00

Workorder: 1300496

Problem: 9950

Meter Reading: 5078

In Date: 01/14/2013

Close Date: 01/15/2013

Labor

Hours

Description

Parts

Quantity

- On Site Lube	5.00	SHOP SUPPLIES	1.00
- Shop Supplies			

Parts Charge: 2.00

Labor Charge: 300.00

Workorder: 1300867

Problem: 9950

Meter Reading: 5195

In Date: 01/24/2013

Close Date: 02/27/2013

Labor

Hours

Description

Parts

Quantity

- On Site Lube	16.00	15w40 serv truck	36.00
- Replace Latch On Battery Cut Off Door		OIL FILTER 3261644	1.00
- P.M.		NAPAGOLD FUEL FILTER	1.00
- Shop Supplies		OIL FILTER 1R0716	1.00
		245-3818 AIR FILTER F	1.00
		air filter 245-3819	1.00
		hydraulic filter	1.00
		NAPAGOLD OIL FILTER	1.00
		CABIN AIR FILTER 7X6041	2.00
		LATCH ASSY	1.00
		LATCH CAM	1.00
		6V-7419 WIPER BLADE	2.00
		SHOP SUPPLIES	1.00
		SERVICE AW68	12.00

Parts Charge: 618.94

Labor Charge: 960.00

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1302037		Problem: 9950			
Meter Reading: 5202					
In Date: 02/27/2013		Close Date: 02/27/2013			
		Labor Hours	Description	Parts	Quantity
- On Site Lube		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	60.00	
Workorder: 1302296		Problem: steering cylinder leak			
Meter Reading: 5230					
In Date: 03/07/2013		Close Date: 03/13/2013			
		Labor Hours	Description	Parts	Quantity
- Reseal Steering Cylinders		9.00	SHOP SUPPLIES		1.00
- Fm To Boca Pit			STEERING SEAL KIT		2.00
- Shop Supplies			SERVICE AW68		25.00
Parts Charge:		496.45	Labor Charge:	540.00	
Workorder: 1303083		Problem: 9950			
Meter Reading: 5270					
In Date: 03/29/2013		Close Date: 04/01/2013			
		Labor Hours	Description	Parts	Quantity
- On Site Lube		7.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	420.00	
Workorder: 1303150		Problem: 9950			
Meter Reading: 5311					
In Date: 04/01/2013		Close Date: 04/12/2013			
		Labor Hours	Description	Parts	Quantity
- Replace Mud Flap And Step Belts		6.50	STEP BELT		2.00
- Replace Cuttng Edge			MUD FLAP		2.00
- Fm To Boca Pit			CUTTING EDGE END		2.00
- Shop Supplies			BOLT		12.00
			SHOP SUPPLIES		1.00
			CUTTING EDGE		2.00
			NUT		12.00
Parts Charge:		2,836.76	Labor Charge:	390.00	

1/2/2018
10:57:23AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1303692

Problem: seat belt

Meter Reading: 5329		Labor		Parts	
In Date: 04/15/2013	Close Date: 05/02/2013	Hours	Description		Quantity
-	Replace Seat Belt	13.50	WEAR PLATE		2.00
-	Replace Bolts For Skid Plate		WEAR PLATE BOLT		8.00
-	On Site Lube		WEAR PLATE NUT		8.00
-	Shop Supplies		WEAR PLATE WASHER		8.00
			SEAT BELT GP		1.00
			SHOP SUPPLIES		1.00
Parts Charge: 1,187.21		Labor Charge: 810.00			

Workorder: 1305096

Problem: wheel chocks

Meter Reading: 5434		Labor		Parts	
In Date: 05/23/2013	Close Date: 06/10/2013	Hours	Description		Quantity
-	Onsite Lube	18.00	NAPAGOLD OIL FILTER		1.00
-	P.M.		328-3655 TRANS FILTER		1.00
-	Wheel Chalks/ R&R Hood Actuator		NAPAGOLD AIR FILTER		2.00
-	Shop Supplies		Differential Oil		1.00
			HOOD ACTUATOR		1.00
			15w40 serv truck		36.00
			SHOP SUPPLIES		1.00
			OIL FILTER 1R0716		1.00
			NAPAGOLD FUEL FILTER		1.00
			air filter 245-3819		1.00
			245-3818 AIR FILTER F		1.00
			hydraulic filter		1.00
			660-01017 WHEEL CHOCK		2.00
			NAPAGOLD FUEL FILTER		1.00
Parts Charge: 3,203.48		Labor Charge: 1,080.00			

Workorder: 1306419

Problem: 9950

Meter Reading: 5493		Labor		Parts	
In Date: 06/26/2013	Close Date: 06/26/2013	Hours	Description		Quantity
-	Onsite Lube 6Xs	6.00	SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge: 2.00		Labor Charge: 360.00			

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1307379

Problem: repair bucket control valve

Meter Reading: 5570

Labor

Parts

In Date: 07/24/2013

Close Date: 09/23/2013

Hours

Description

Quantity

- Repair Bucket Control Valve

Parts Charge: 0.00

Labor Charge: 0.00

Commercial Charge: 483.16

Workorder: 1307448

Problem: hardface

Meter Reading: 5570

Labor

Parts

In Date: 07/25/2013

Close Date: 08/09/2013

Hours

Description

Quantity

- Hard Face Bucket Area

Parts Charge: 0.00

Labor Charge: 0.00

Commercial Charge: 1,142.70

Workorder: 1308344

Problem: Blower Motor

Meter Reading: 5668

Labor

Parts

In Date: 08/19/2013

Close Date: 09/03/2013

Hours

Description

Quantity

- Replace Ac Blower Motor, Switch And Cab Filter Cover
- Replace Insulation Hardware
- On Sit Lube
- Shop Supplies

24.50

SWITCH

1.00

THUMB SCREW

2.00

PLATE

1.00

CLIP

12.00

WASHER

12.00

WASHER

2.00

A/C FILTER CAT

2.00

BLOWER FAN

1.00

SHOP SUPPLIES

1.00

COVER ASSEMBLY

1.00

Parts Charge: 1,293.24

Labor Charge: 1,470.00

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1309278

Problem: stalled out

Meter Reading: 5719

In Date: 09/12/2013

Close Date: 10/09/2013

Labor

Hours

Description

Parts

Quantity

- R&R Filters And Prime System	22.50	NAPA HYDRAULIC FILTER	1.00
- To Boca Pit		air filter 245-3819	1.00
- P.M.		NAPAGOLD FUEL FILTER	1.00
- Replace Bad Hyd. Hoses On Machine		6V-7419 WIPER BLADE	1.00
- To Boca Pit		OIL FIL	1.00
- Shop Supplies		HOSE	1.00
		FLANGE	2.00
		SHOP SUPPLIES	1.00
		15w40 serv truck	36.00
		NAPAGOLD FUEL FILTER	1.00
		NAPAGOLD OIL FILTER	1.00
		SERVICE AW68	140.00
		NAPAGOLD AIR FILTER	1.00
		BRAKE CLEANER	4.00
		HOSE	1.00
		328-3655 TRANS FILTER	1.00

Parts Charge: 1,329.11

Labor Charge: 1,350.00

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1310115

Problem: Pins & Bushings

Meter Reading: 5819		Labor		Parts	
In Date: 10/07/2013	Close Date: 01/17/2014	Hours	Description	Quantity	
- Pins And Bushings		41.00	PIN CLA		2.00
- Replace Fire Exsingusher			BRG SLV		2.00
- Repair A/C Open In Wiring			BRG		2.00
- Onsite Lube 16Xs			SEAL		4.00
- Replace Batteries			WASHER		4.00
- Test Charging System And Battery For Draw			SEAL		4.00
- Remove Restriction In Heater Core			WASHER		4.00
- Pm Service			DISTILLED WATER 1GAL		1.00
- Replace Bucket Pins And Bushings			SHOP SUPPLIES		1.00
- Shop Supplies			PIN CLA		2.00
			SHOP SUPPLIES		1.00
			OIL FIL		1.00
			NAPAGOLD FUEL FILTER		1.00
			15-40 OIL		36.00
			NAPAGOLD AIR FILTER		1.00
			SPACER		4.00
			NAPAGOLD AIR FILTER		1.00
			GREASE NLGI 2		1.00
			USED FIRE X REFURBISHED		1.00
			NAPAGOLD FUEL FILTER		1.00
			BATTERY		2.00
			hydraulic filter		1.00
			NAPAGOLD AIR FILTER		1.00
			NAPAGOLD OIL FILTER		1.00
			NAPA HYDRAULIC FILTER		1.00
Parts Charge: 2,114.09		Labor Charge: 2,460.00			

Workorder: 1310386

Problem: will not travel in forward

Meter Reading: 5779		Labor		Parts	
In Date: 10/15/2013	Close Date: 11/19/2013	Hours	Description	Quantity	
- Replace Control Valve And Coil Kelly					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 860.24	

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1311961		Problem: Won't go forward				
Meter Reading: 5891				Labor	Parts	
In Date: 12/02/2013	Close Date: 12/09/2013	Hours	Description			Quantity
- Replace Wirring Harness By Kelly						
	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	1,992.35
Workorder: 1312274		Problem: Replace transmission segments				
Meter Reading: 5905				Labor	Parts	
In Date: 12/09/2013	Close Date: 02/19/2014	Hours	Description			Quantity
- Repairs At Cat						
	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	10,048.82
Workorder: 1400499		Problem: Center Pin				
Meter Reading: 5955				Labor	Parts	
In Date: 01/15/2014	Close Date:	Hours	Description			Quantity
-						
	Parts Charge:	0.00	Labor Charge:	0.00		
Workorder: 1400642		Problem: Transport for repair to Kelly Tractor on 1/15/14 am				
Meter Reading: 5955				Labor	Parts	
In Date: 01/14/2014	Close Date: 01/21/2014	Hours	Description			Quantity
- Tow From: Fleet He Shop To: Kelly Tractor (Okeechobee W Of Haverhill)						
	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	220.54
Workorder: 1401508		Problem: Transport after repair from Kelly Tractor to Boca Pit am of 2/7/2014				
Meter Reading: 5966				Labor	Parts	
In Date: 02/06/2014	Close Date: 02/14/2014	Hours	Description			Quantity
- Tow From: Kelly Tractor To: Boca Pit						
	Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	220.54

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1401777

Problem: 9950

Meter Reading: 5989

In Date: 02/24/2014

Close Date: 02/25/2014

Labor

Hours

Description

Parts

Quantity

- Onsite Lube	6.00	SHOP SUPPLIES	1.00
- Shop Supplies			

Parts Charge: 2.00

Labor Charge: 360.00

Workorder: 1402470

Problem: cutting edges

Meter Reading: 6006

In Date: 03/13/2014

Close Date: 03/19/2014

Labor

Hours

Description

Parts

Quantity

- Replace Cutting Edges	5.50	BOLT	12.00
- To Boca Pit		NUT	12.00
- Shop Supplies		CUTTING EDGE	2.00
		CUTTING EDGE END	2.00
		SHOP SUPPLIES	1.00

Parts Charge: 2,600.21

Labor Charge: 330.00

Workorder: 1403074

Problem: A/C

Meter Reading: 6081

In Date: 03/28/2014

Close Date: 04/23/2014

Labor

Hours

Description

Parts

Quantity

- Check A/C. Check Harness, Replace Fuse	20.00	15w40 serv truck	36.00
- To Boca Pit		OIL FIL	1.00
- Pm		NAPA HYDRAULIC FILTER	1.00
- On Site Lube		NAPAGOLD OIL FILTER	1.00
- Replace Grease Fittings On Front Drive Shaft		NAPAGOLD AIR FILTER	1.00
- Shop Supplies		NAPA HYDRAULIC FILTER	1.00
		NAPAGOLD FUEL FILTER	1.00
		SERVICE AW68	12.00
		NAPAGOLD FUEL FILTER	1.00
		SHOP SUPPLIES	1.00
		NAPAGOLD AIR FILTER	1.00

Parts Charge: 353.81

Labor Charge: 1,200.00

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1404726		Problem: Repair electrical system / Transmission			
Meter Reading: 6138		Labor	Parts		
In Date: 05/14/2014	Close Date: 05/15/2014	Hours	Description	Quantity	
- Repairs By Kelly Tractor					
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 2,249.04
Workorder: 1404741		Problem: 9950			
Meter Reading: 6145		Labor	Parts		
In Date: 05/14/2014	Close Date: 05/15/2014	Hours	Description	Quantity	
- Onsite Lube					
		7.00	SHOP SUPPLIES	1.00	
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	420.00	
Workorder: 1405473		Problem: Onsite Lube			
Meter Reading: 6170		Labor	Parts		
In Date: 06/04/2014	Close Date: 06/04/2014	Hours	Description	Quantity	
- Onsite Lube					
		4.00	SHOP SUPPLIES	1.00	
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	240.00	
Workorder: 1405683		Problem: diff service			
Meter Reading: 6215		Labor	Parts		
In Date: 06/09/2014	Close Date: 06/18/2014	Hours	Description	Quantity	
- Service Diff					
		17.00	Differential Oil	4.00	
- Service Diff					
			Differential additive	2.00	
- Wash Radiator And Coolers					
			Differential Oil	3.00	
- Onsite Lube					
			SHOP SUPPLIES	1.00	
- Blow Out Air Filter And Cab Filter					
- Shop Supplies					
Parts Charge:		1,243.04	Labor Charge:	1,020.00	

1/2/2018
10:57:23AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1406050

Problem: Hyd. Leak

Meter Reading: 6226	Labor	Parts	
In Date: 06/19/2014	Hours	Description	Quantity
- Replace Hyd Hose From Accumulator To Steering Valve	12.50	HYD HOSE	136.00
- To Boca Pit 2 Times		SHOP SUPPLIES	1.00
- To Mako		AW68 HYDRO FLUID HYDR	128.00
- Shop Supplies		HOSE FITTING	4.00
		BRAKE CLEANER	4.00
Parts Charge:	461.84	Labor Charge:	750.00

Workorder: 1406416

Problem: AC

Meter Reading: 6239	Labor	Parts	
In Date: 06/30/2014	Hours	Description	Quantity
- Check Ac Sent To Shop	13.00	A/C PRESSURE SWITCH	1.00
- To Pit		A/C LOW SIDE PORT	1.00
- Belt		A/C COMPRESSOR	1.00
- Replaced Ac Compresor And Dryer Recharged System		HIGH SIDE PORT	1.00
- Shop Supplies		DRIVE BELT	1.00
		SHOP SUPPLIES	1.00
		E8 A/C OIL UNIV W DYE	1.00
		A/C DRYER	1.00
		R134A FREON	6.00
Parts Charge:	1,528.61	Labor Charge:	780.00

Workorder: 1407489

Problem: 9950

Meter Reading: 6471	Labor	Parts	
In Date: 07/30/2014	Hours	Description	Quantity
- Onsite Lube 2Xs	4.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	240.00

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1407773

Problem: P.M.

Meter Reading: 6329		Labor		Parts	
In Date: 08/06/2014	Close Date: 08/19/2014	Hours	Description		Quantity
- Pm		11.00	SHOP SUPPLIES		1.00
- Onsite Lube			NAPAGOLD AIR FILTER		1.00
- Shop Supplies			NAPAGOLD OIL FILTER		1.00
			15w40 serv truck		36.00
			NAPAGOLD AIR FILTER		1.00
			NAPAGOLD FUEL FILTER		1.00
			NAPAGOLD FUEL FILTER		1.00
			NAPA TRANS FILTER		1.00
			OIL FIL		1.00
			NAPA HYDRAULIC FILTER		1.00
Parts Charge: 326.02		Labor Charge: 660.00			

Workorder: 1408469

Problem: tilt cylinder

Meter Reading: 6373		Labor		Parts	
In Date: 08/25/2014	Close Date: 09/05/2014	Hours	Description		Quantity
- Repack Tilt Cylinder		18.00	SEAL KIT		1.00
- To Boca Pit 2Xs			GREASE NLGI 2		2.00
- On Site Lube			BRAKE CLEANER		4.00
- Shop Supplies			SHOP SUPPLIES		1.00
Parts Charge: 344.84		Labor Charge: 1,080.00			

Workorder: 1409486

Problem: hyd leak

Meter Reading: 6408		Labor		Parts	
In Date: 09/22/2014	Close Date: 09/25/2014	Hours	Description		Quantity
- Replace Hoses To Lift Cylinders On Both Sides		24.00	SERVICE AW68		120.00
- To Mako			HYDRAULIC HOSE MAKE UP		1.00
- To Boca Pit 2Xs			SHOP SUPPLIES		1.00
- Onsite Lube					
- Shop Supplies					
Parts Charge: 1,611.54		Labor Charge: 1,440.00			

1/2/2018
10:57:23AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1410403

Problem: cutting edges

Meter Reading: 6464		Labor		Parts	
In Date: 10/17/2014	Close Date: 10/23/2014	Hours	Description		Quantity
- Cutting Edges		13.00	BOLT		16.00
- To Kelly			CUTTING EDGE		2.00
- To Boca Pit 2 Xs			SHOP SUPPLIES		1.00
- Onsite Lube			NUT		16.00
- Shop Supplies			CUTTING EDGE END		2.00
Parts Charge: 2,580.74		Labor Charge: 780.00			

Workorder: 1411051

Problem: Bucket controls

Meter Reading: 6515		Labor		Parts	
In Date: 11/04/2014	Close Date: 12/09/2014	Hours	Description		Quantity
- Replace Control Solinode At Control Valve And Reseal Lines		21.50	SHOP SUPPLIES		1.00
			GP VALVE SOLENOID		1.00
- To Boca Pit 2Xs					
- Onsite Lube					
- Shop Supplies					
Parts Charge: 179.94		Labor Charge: 1,290.00			

1/2/2018
10:57:23AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1500247

Problem: PM

Meter Reading: 6582

In Date: 01/08/2015

Close Date: 02/02/2015

Labor

Hours

Description

Parts

Quantity

- Pm	21.00	15w40 serv truck	36.00
- Onsite Lube 8Xs		OIL FIL	1.00
- Replace Hyd Hose To Bucket Cylinder		NAPAGOLD FUEL FILTER	1.00
- To Mako		NAPAGOLD AIR FILTER	1.00
- Shop Supplies		NAPAGOLD AIR FILTER	1.00
		NAPA HYDRAULIC FILTER	1.00
		NAPAGOLD OIL FILTER	1.00
		NAPAGOLD FUEL FILTER	1.00
		SERVICE AW68	12.00
		BRAKE CLEANER	3.00
		NAPAGOLD AIR FILTER	2.00
		NAPA TRANS FILTER	1.00
		HOSE MAKE UP	1.00
		SHOP SUPPLIES	1.00

Parts Charge: 1,500.92

Labor Charge: 1,260.00

Workorder: 1500298

Problem: Rear Tires Low

Meter Reading: 6582

In Date: 01/08/2015

Close Date: 01/12/2015

Labor

Hours

Description

Parts

Quantity

- Tire Repair			
Parts Charge:	0.00	Labor Charge:	0.00
Commercial Charge:	151.04		

Workorder: 1500625

Problem: Replace LF tire

Meter Reading: 6587

In Date: 01/16/2015

Close Date: 01/26/2015

Labor

Hours

Description

Parts

Quantity

- Replace Two Tires			
Parts Charge:	0.00	Labor Charge:	0.00
Commercial Charge:	9,881.74		

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1502015

Problem: Battery switch

Meter Reading: 6709		Labor		Parts	
In Date: 02/25/2015	Close Date: 03/30/2015	Hours	Description		Quantity
-	Replace Batt Switch	13.50	SERVICE AW68		20.00
-	Onsite Lube		BATTERY DISCONNECT		1.00
-	Reseal Lines To Lift Cylinder		SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge:		165.79	Labor Charge:	810.00	

Workorder: 1503780

Problem: 9950

Meter Reading: 6758		Labor		Parts	
In Date: 04/13/2015	Close Date: 04/17/2015	Hours	Description		Quantity
-	Onsite Lube	11.00	SHOP SUPPLIES		1.00
-	Washed Out Radator And Coolers, Blew Out Filters				
-	Shop Supplies				
Parts Charge:		2.00	Labor Charge:	660.00	

Workorder: 1505500

Problem: PM

Meter Reading: 6895		Labor		Parts	
In Date: 06/02/2015	Close Date: 06/12/2015	Hours	Description		Quantity
-	Pm	14.50	NAPAGOLD FUEL FILTER		1.00
-	Coolent Leak R&R Radiator Cap		15w40 serv truck		36.00
-	To Boca Pit 2Xs		OIL FIL		1.00
-	Onsite Lube		NAPA HYDRAULIC FILTER		1.00
-	Shop Supplies		SEVERE DUTY		1.00
			TRANSMISSION FILTER		1.00
			SHOP SUPPLIES		1.00
			NAPAGOLD FUEL FILTER		1.00
			A/C FILTER CAT		2.00
			RADIATOR CAP		1.00
			H DUTY ANTI-FREEZE		3.00
			NAPAGOLD OIL FILTER		1.00
			NAPAGOLD AIR FILTER		1.00
			NAPAGOLD AIR FILTER		1.00
Parts Charge:		659.11	Labor Charge:	870.00	

1/2/2018
10:57:23AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1506186		Problem: 9950			
Meter Reading: 6883					
In Date: 06/19/2015		Close Date: 06/22/2015			
		Labor Hours	Description	Parts	Quantity
- Onsite Lube		2.00	SHOP SUPPLIES		1.00
- Install Hyd Cover					
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	120.00	
Workorder: 1508823		Problem: boom will not raise			
Meter Reading: 7064					
In Date: 09/02/2015		Close Date: 10/07/2015			
		Labor Hours	Description	Parts	Quantity
- Repair Boom					
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 1,422.59
Workorder: 1510024		Problem: 9950			
Meter Reading: 7084					
In Date: 10/02/2015		Close Date: 10/02/2015			
		Labor Hours	Description	Parts	Quantity
- Onsite Lube 10Xs		10.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	600.00	
Workorder: 1510515		Problem: fuel filters			
Meter Reading: 7125					
In Date: 10/19/2015		Close Date: 10/20/2015			
		Labor Hours	Description	Parts	Quantity
- R&R 2 Fuel Filters		3.00	DIESEL WATER REMOVER		1.00
- To Boca Pit			SHOP SUPPLIES		1.00
- Shop Supplies			NAPAGOLD FUEL FILTER		1.00
			NAPAGOLD FUEL FILTER		1.00
Parts Charge:		35.66	Labor Charge:	180.00	

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1510678

Problem: pm/edges

Meter Reading: 7132		Labor		Parts	
In Date: 10/21/2015	Close Date: 10/29/2015	Hours	Description		Quantity
- Pm		15.00	NAPA TRANS FILTER		1.00
- To Boca Pit 2 Times			SHOP SUPPLIES		1.00
- Cutting Edges			CUTTING EDGE END		4.00
- Shop Supplies			CUTTING EDGE		4.00
			BOLT		32.00
			NUT		32.00
			NAPAGOLD AIR FILTER		2.00
			OIL FIL		1.00
			NAPAGOLD FUEL FILTER		1.00
			NAPAGOLD FUEL FILTER		1.00
			15-40 OIL		36.00
			NAPAGOLD AIR FILTER		1.00
			NAPAGOLD AIR FILTER		1.00
			NAPA HYDRAULIC FILTER		1.00
			NAPA HYDRAULIC FILTER		1.00
			15w40 serv truck		36.00
Parts Charge: 5,640.97		Labor Charge: 900.00			

Workorder: 1511586

Problem: Filter light

Meter Reading: 7203		Labor		Parts	
In Date: 11/12/2015	Close Date: 12/16/2015	Hours	Description		Quantity
- Replace Trans Filter		5.50	NAPA HYDRAULIC FILTER		1.00
- Replace Lift Cylinder			TRANSMISSION FILTER		1.00
- To Boca Pit			SHOP SUPPLIES		1.00
- Road Test			NAPA HYDRAULIC FILTER		1.00
- Shop Supplies			SEAL KIT		2.00
Parts Charge: 864.98		Labor Charge: 330.00			

Workorder: 1511766

Problem: Transmission Light

Meter Reading: 7194		Labor		Parts	
In Date: 11/17/2015	Close Date: 01/11/2016	Hours	Description		Quantity
- Replace Filter Housing And Switch. Diagnostic Time.					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 1,704.32	

1/2/2018
10:57:23AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1513054

Problem: Repack Cyl

Meter Reading: 7232	Labor	Parts		
In Date: 12/30/2015	Hours	Description	Quantity	
- R&R Cylinders And Rebuild	36.50	AW68 HYDRO FLUID HYDR	80.00	
- To Kelly 2Xs		SHOP SUPPLIES	1.00	
- Clean Loader				
- Road Test				
- Shop Supplies				
Parts Charge:	184.40	Labor Charge:	2,190.00	

Workorder: 1600413

Problem: Cylinder Repair

Meter Reading: 7235	Labor	Parts		
In Date: 01/12/2016	Hours	Description	Quantity	
- Rebuild Cyl.				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 1,214.86

Workorder: 1600585

Problem: Onsite lube

Meter Reading: 7265	Labor	Parts		
In Date: 01/19/2016	Hours	Description	Quantity	
- Onsite Lube	1.00	SHOP SUPPLIES	1.00	
- Shop Supplies				
Parts Charge:	2.00	Labor Charge:	60.00	

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1602205

Problem: PM

Meter Reading: 7384

In Date: 03/02/2016

Close Date: 03/21/2016

Labor

Hours

Description

Parts

Quantity

- Pm	9.00	SHOP SUPPLIES	1.00
- To Boca Pit		A/C FILTER CAT	2.00
- Shop Supplies		15w40 serv truck	34.00
		OIL FIL	1.00
		NAPAGOLD FUEL FILTER	1.00
		NAPAGOLD FUEL FILTER	1.00
		NAPAGOLD AIR FILTER	1.00
		NAPA TRANS FILTER	1.00
		NAPAGOLD AIR FILTER	1.00
		NAPA HYDRAULIC FILTER	1.00
		NAPA HYDRAULIC FILTER	1.00
		SEVERE DUTY	1.00
		SERVICE AW68	12.00

Parts Charge: 546.77

Labor Charge: 540.00

Workorder: 1602561

Problem: repair pinion seal leak by Kelly Tractor

Meter Reading: 7385

In Date: 03/10/2016

Close Date: 04/28/2016

Labor

Hours

Description

Parts

Quantity

- Repair Diff Leak			
- Credit For Wrong Billing On Work Order 1600413			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	522.24

Workorder: 1603189

Problem: onsite lube

Meter Reading: 7430

In Date: 03/28/2016

Close Date: 04/07/2016

Labor

Hours

Description

Parts

Quantity

- Onsite Lube 4Xs	4.00	SHOP SUPPLIES	1.00
- Shop Supplies			

Parts Charge: 2.00

Labor Charge: 240.00

1/2/2018
10:57:23AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1604434

Problem: 9950

Meter Reading: 7478

In Date: 04/27/2016

Close Date: 04/28/2016

Labor

Hours

Description

Parts

Quantity

- Onsite Lube 6Xs	6.00	SHOP SUPPLIES	1.00
- Shop Supplies			

Parts Charge: 2.00

Labor Charge: 360.00

Workorder: 1605172

Problem: 9950

Meter Reading: 7496

In Date: 05/18/2016

Close Date: 06/21/2016

Labor

Hours

Description

Parts

Quantity

- Fuel And Lube 6Xs	28.00	Differential Oil	5.00
- Drive To Boca Pit 6Xs		SHOP SUPPLIES	1.00
- Service Front Diff		Differential additive	2.00
- Service Rear Diff			
- Move Blades To Boca Pit			
- Shop Supplies			

Parts Charge: 868.09

Labor Charge: 1,680.00

Workorder: 1606533

Problem: PM

Meter Reading: 7760

In Date: 06/27/2016

Close Date: 08/01/2016

Labor

Hours

Description

Parts

Quantity

- Pm	19.00	SHOP SUPPLIES	1.00
- To Boca Pit		15w40 serv truck	34.00
- Road Test		OIL FIL	1.00
- Lube		NAPAGOLD FUEL FILTER	1.00
- Shop Supplies		NAPAGOLD FUEL FILTER	1.00
		328-3655 TRANS FILTER	1.00
		NAPA HYDRAULIC FILTER	1.00
		head lamp	1.00
		NAPAGOLD AIR FILTER	1.00
		lamp	1.00
		NAPA HYDRAULIC FILTER	1.00
		NAPAGOLD AIR FILTER	1.00

Parts Charge: 931.84

Labor Charge: 1,140.00

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1607945		Problem: 9950			
Meter Reading: 7764				Parts	
In Date: 08/02/2016	Close Date: 08/02/2016	Labor Hours	Description		Quantity
- Onsite Lube 4Xs		12.00	SHOP SUPPLIES		1.00
- To Boca Pit 4Xs					
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 720.00			
Workorder: 1608432		Problem: 9950			
Meter Reading: 7793				Parts	
In Date: 08/16/2016	Close Date: 08/18/2016	Labor Hours	Description		Quantity
- Onsite Lube		2.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 120.00			
Workorder: 1609332		Problem: 9950			
Meter Reading: 7862				Parts	
In Date: 09/07/2016	Close Date: 09/13/2016	Labor Hours	Description		Quantity
- Onsite Lube 4Xs		4.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 240.00			
Workorder: 1611080		Problem: 9950			
Meter Reading: 7969				Parts	
In Date: 10/26/2016	Close Date: 11/09/2016	Labor Hours	Description		Quantity
- Onsite Lube 4Xs		8.50	SHOP SUPPLIES		1.00
- Replace Cutting Edges			CUTTING EDGE END		2.00
- To Boca Pit			NUT		16.00
- Shop Supplies			BOLT		16.00
			CUTTING EDGE		2.00
			cor guard lh		1.00
			bolt		4.00
			guard cor rh		1.00
Parts Charge: 3,428.18		Labor Charge: 510.00			

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1611837		Problem: 9950			
Meter Reading: 8153					
In Date: 11/16/2016		Close Date: 11/16/2016			
		Labor Hours	Description	Parts	Quantity
- Onsite Lube 4Xs		4.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	240.00	

Workorder: 1612139		Problem: pm			
Meter Reading: 8113					
In Date: 11/28/2016		Close Date: 01/20/2017			
		Labor Hours	Description	Parts	Quantity
- Pm		25.50	SHOP SUPPLIES		1.00
- Onsite Lube 7Xs			NAPAGOLD AIR FILTER		1.00
- Repair Bottom Articulating Pin And Greased			SERVICE AW68		10.00
- To Boca Pit 3Xs			SWITCH KEY		1.00
- Lower Bucket Pins Won'T Take Greese			NAPAGOLD AIR FILTER		1.00
- To Boca Pit			NAPAGOLD FUEL FILTER		1.00
- Shop Supplies			USED FIRE X REFURBISHED		1.00
			NAPAGOLD FUEL FILTER		1.00
			NAPAGOLD AIR FILTER		2.00
			OIL FIL		1.00
			15w40 serv truck		34.00
			oil dip stick		1.00
Parts Charge:		435.99	Labor Charge:	1,530.00	

Workorder: 1701341		Problem: 9950			
Meter Reading: 8188					
In Date: 02/08/2017		Close Date: 02/10/2017			
		Labor Hours	Description	Parts	Quantity
- Onsite Lube 4Xs		4.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	240.00	

1/2/2018
10:57:23AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1701905		Problem: 9950			
Meter Reading: 8188					
In Date: 02/23/2017		Close Date: 02/24/2017			
		Labor Hours	Description	Parts	Quantity
- Fuel And Lube		4.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	240.00	
Workorder: 1702398		Problem: Onsite Lube			
Meter Reading: 8211					
In Date: 03/08/2017		Close Date: 03/09/2017			
		Labor Hours	Description	Parts	Quantity
- Onsite Lube 4Xs		4.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	240.00	
Workorder: 1702949		Problem: DEF			
Meter Reading: 8260					
In Date: 03/23/2017		Close Date: 03/24/2017			
		Labor Hours	Description	Parts	Quantity
- Def			BLUE DF		2.00
Parts Charge:		27.15	Labor Charge:	0.00	
Workorder: 1703071		Problem: pins			
Meter Reading: 8351					
In Date: 03/27/2017		Close Date: 04/25/2017			
		Labor Hours	Description	Parts	Quantity
- Loosen Frozen Bucket Pins		11.00	SHOP SUPPLIES		1.00
- To Boca Pit					
- Fuel And Lube					
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	660.00	

1/2/2018
10:57:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1704535

Problem: PM

Meter Reading: 8406

In Date: 05/05/2017

Close Date: 05/19/2017

**Labor
Hours**

Parts

Quantity

- Pm	23.00	NAPAGOLD AIR FILTER	1.00
- Fuel And Lube		SHOP SUPPLIES	1.00
- To Boca Pit		NAPAGOLD AIR FILTER	2.00
- To Mako		NAPAGOLD FUEL FILTER	1.00
- Hyd Leak. R&R Hyd Hose And Refill System.		NAPAGOLD AIR FILTER	1.00
- Shop Supplies		OIL FIL	1.00
		hose made mako	1.00
		15w40 serv truck	34.00
		NAPAGOLD FUEL FILTER	1.00
		MULTI-TRAC HYD FLUID	16.00

Parts Charge: 374.53

Labor Charge: 1,380.00

Workorder: 1706005

Problem: 9950

Meter Reading: 8428

In Date: 06/16/2017

Close Date: 06/19/2017

**Labor
Hours**

Parts

Quantity

- Fuel And Lube	6.00	SHOP SUPPLIES	1.00
- Shop Supplies			

Parts Charge: 2.00

Labor Charge: 360.00

Workorder: 1707075

Problem: bucket curl

Meter Reading: 8499

In Date: 07/19/2017

Close Date: 07/31/2017

**Labor
Hours**

Parts

Quantity

- Replace Bucket Controller	8.00	hand controller	1.00
- To Boca Pit		SHOP SUPPLIES	1.00
- Shop Supplies			

Parts Charge: 632.45

Labor Charge: 480.00

1/2/2018
10:57:23AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1707989

Problem: trans service

Meter Reading: 8520		Labor		Parts	
In Date: 08/15/2017	Close Date: 09/20/2017	Hours	Description		Quantity
- Trans Svc		43.50	WASHER		4.00
- Diff Svc			CAT BATTERY		2.00
- Final Drive Svc			HYD ADDITIVE		2.00
- Parking Brake Fail Replace Brake Actuator Cyl Shoes			NAPA TRANS FILTER		1.00
And Hardware			spring		1.00
- To Boca Pit			actuator		1.00
- Rplace Driveshaft Bearing Order Pins Bushings For			parking shoe		1.00
Bucket			bolt		1.00
- Replace Batteries			nut		2.00
- To Kelly Tractor			socket		1.00
- Test Drive			spring		2.00
- Shop Supplies			parking shoe		1.00
			WEAR PLATE WASHER		4.00
			Freight Charge		1.00
			spacer		4.00
			retainer		1.00
			lining kit b		1.00
			pin		2.00
			ring		2.00
			screw adjust		1.00
			nut		1.00
			SHOP SUPPLIES		1.00
			brace		1.00
			center bearing		1.00
			center bearing		1.00
			Freight Charge		1.00
			pin lower bucket		2.00
			bearing		2.00
			Differential Oil		2.00
			Differential Oil		2.00
			bolt		4.00
			SEAL		4.00
			Differential Oil		4.00
Parts Charge:		7,203.90	Labor Charge:	2,610.00	

1/2/2018
10:57:23AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10170978 2007 CATERPILLAR 966H Loader,A/C Cab,5 Yd Buckt

Workorder: 1710445

Problem: fuel and lube

Meter Reading: 8576		Labor		Parts	
In Date: 10/24/2017	Close Date: 11/22/2017	Hours	Description		Quantity
- Fuel And Lube		7.00	NUT		16.00
- Replace Edges			BOLT		12.00
- To Boca Pit			SHOP SUPPLIES		1.00
- To Kelly Tractor					
- Shop Supplies					
Parts Charge:		400.34	Labor Charge:	420.00	

Workorder: 1711621

Problem: lube

Meter Reading: 8576		Labor		Parts	
In Date: 11/28/2017	Close Date: 12/01/2017	Hours	Description		Quantity
- Lube		6.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	360.00	

Workorder: 1711976

Problem: Transition Prep Charge

Meter Reading: 8576		Labor		Parts	
In Date: 12/06/2017	Close Date: 12/06/2017	Hours	Description		Quantity
- Transition Prep Charge		2.00			
Parts Charge:		0.00	Labor Charge:	0.00	

Total Parts Charges:	76,548.60	Total Labor Charges:	84,080.00	Total Comm. Charges:	43,698.20
----------------------	-----------	----------------------	-----------	----------------------	-----------