

1/2/2018
11:07:05AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 345922

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts		
In Date: 08/13/2003	Hours	Description	Quantity	
- Pre-Delivery Inspection	4.00			
Parts Charge:	0.00	Labor Charge:	200.00	

Workorder: 345946

Problem: REPLACED 12V BATTERY

Meter Reading: 0	Labor	Parts		
In Date: 08/13/2003	Hours	Description	Quantity	
- Replaced 12V Battery	1.00	PS1250F1 BATTERY (POWER SONIC PS-1250-F1)	1.00	
- Shop Supplies		SHOP SUPPLIES	1.00	
Parts Charge:	26.55	Labor Charge:	50.00	

Workorder: 351399

Problem: TAIL LIGHT ON RIGHT SIDE OF TRAILER NEEDS TO BE REPLACED,DAMAGED

Meter Reading: 0	Labor	Parts		
In Date: 11/10/2003	Hours	Description	Quantity	
- Replace Right Rear Light	3.30	2641 RH TAIL LIGHT GROTE# 52302	1.00	
- Repair Wire Harness		PS1250F1 BATTERY (POWER SONIC PS-1250-F1)	1.00	
- Rewire Brake Away Charger-Replace Dead Battery		SHOP SUPPLIES	1.00	
- Shop Supplies				
Parts Charge:	30.84	Labor Charge:	165.00	

Workorder: 446809

Problem: P.M./SEE REQUEST

Meter Reading: 0	Labor	Parts		
In Date: 06/04/2004	Hours	Description	Quantity	
- Pm Service	6.50	58856 SEAL	4.00	
- Replace Two Tires		762171406 205/75R15 MARATHON C	2.00	
- Repair Trailer Wiring		SHOP SUPPLIES	1.00	
- Shop Supplies				
Parts Charge:	107.38	Labor Charge:	325.00	

1/2/2018
11:07:05AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 454908

Problem: TAIL LIGHT R/SIDE NOT WORKING

Meter Reading: 0		Labor		Parts	
In Date: 08/23/2004	Close Date: 08/31/2004	Hours	Description		Quantity
-	Test Lights: Replace Right Tail Lamp/Repair Wiring	2.00	2640 LH TAIL LIGHT GROTE# 52312		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
Parts Charge:		7.69	Labor Charge:	100.00	

Workorder: 535525

Problem: FIX BRAKE LIGHTS CHECK ALL LIGHTS TAG LOST REPLACE

Meter Reading: 0		Labor		Parts	
In Date: 02/07/2005	Close Date: 02/18/2005	Hours	Description		Quantity
-	Lights	3.00	SHOP SUPPLIES		1.00
-	Shop Supplies		26330 TAG LIGHT (TKR LITE)		1.00
			2641 RH TAIL LIGHT GROTE# 52302		1.00
Parts Charge:		8.96	Labor Charge:	150.00	

Workorder: 543988

Problem: PM/NEW TIRES/CK.LIGHTS

Meter Reading: 0		Labor		Parts	
In Date: 05/05/2005	Close Date: 05/31/2005	Hours	Description		Quantity
-	Pm Service	9.50	SET 4 BEARING SET TIMKEN L44649/L44610		2.00
-	Replace 4 Tires		762171137 MTHN TRLR 205/75R 15		4.00
-	Repalce 2 Wheel Brgs On Left Wheels		PS1250F1 BATTERY (POWER SONIC PS-1250-F1)		1.00
-	Repair Wiring For Electric Brakes		58856 SEAL		4.00
-	Repalce Brake Away Battery		SHOP SUPPLIES		1.00
-	Shop Supplies		81733 GREASE CAP		2.00
Parts Charge:		295.72	Labor Charge:	475.00	

Workorder: 633160

Problem: LIGHTS NOT WORKING

Meter Reading: 0		Labor		Parts	
In Date: 01/23/2006	Close Date: 01/26/2006	Hours	Description		Quantity
-	Replace Male Plug And Repair Wire Harness	2.50	755-5046 MALE CONNECTOR		1.00
-	Cut & Shorten Safety Chains		2850 1/4" LINK		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
Parts Charge:		6.88	Labor Charge:	50.00	

1/2/2018
11:07:05AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 636080

Problem: P.M./ RIGHT TAIL LIGHT OUT/GATE NEEDS WELDING

Meter Reading: 0		Labor	Parts	
In Date: 03/21/2006	Close Date: 03/30/2006	Hours	Description	Quantity
- Pm Axle Trailer		9.40	762171406 205/75R15 MARATHON C	2.00
- Replace 2 Frt Tires			2841 3/4" SAFETY HOOK	1.00
- Repaired Assorted Lights			SHOP SUPPLIES	1.00
- Repair 2 Broken Wire Circuits For Brakes (Electric)			TR416 VALVE STEM	2.00
- Repair Winch Cable			58856 SEAL	4.00
- Shop Supplies			TIRE DISPOSAL FEE	2.00
Parts Charge: 128.89		Labor Charge: 50.00		

Workorder: 637255

Problem: REPAIR RAMPS

Meter Reading: 0		Labor	Parts	
In Date: 04/12/2006	Close Date: 04/21/2006	Hours	Description	Quantity
- Repair Tailgate		11.50	1/4X2X20 STEEL FLAT BAR	5.00
- Shop Supplies			3/4#9 RAISED EXP METAL	33.00
			T-29 YELLOW PAINT SCHOOL BUS	4.00
			T-29 YELLOW PAINT SCHOOL BUS	2.00
			T-235 GRAY PRIMER	3.00
			SHOP SUPPLIES	1.00
Parts Charge: 101.51		Labor Charge: 575.00		

Workorder: 639797

Problem: ENGINE WON'T RUN EXCEPT ON CHOKE

Meter Reading: 0		Labor	Parts	
In Date: 05/23/2006	Close Date: 05/25/2006	Hours	Description	Quantity
- Void Run				
Parts Charge: 0.00		Labor Charge: 0.00		

1/2/2018
11:07:05AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 650015

Problem: LIST SEE REQUEST-GONZALAS - PM NOT DUE TILL 3/07

Meter Reading: 0		Labor	Parts	
In Date: 12/15/2006	Close Date: 01/19/2007	Hours	Description	Quantity
- 4 New Tires		6.00	2640 LH TAIL LIGHT GROTE# 52312	1.00
- Nitro 4 Tires			4086 SWITCH CABLE	1.00
- Repair Tail Light (Replace) Tag Holder And Light			762171406 205/75R15 MARATHON C	4.00
- Repair Rear Brakes And Brakes And Break-A-Way Cable.			30881 JACK	1.00
- Tongue Jack (Weld On) Install New Coupler			SHOP SUPPLIES	1.00
- Shop Supplies			018820 COULPER	1.00
Parts Charge: 494.84		Labor Charge: 27.50		

Workorder: 732461

Problem: MINOR WELD REPAIR OR MACHINING.

Meter Reading: 0		Labor	Parts	
In Date: 01/08/2007	Close Date: 01/08/2007	Hours	Description	Quantity
- Minor Weld Repair Or Machining.		4.00		
Parts Charge: 0.00		Labor Charge: 82.50		

Workorder: 737000

Problem: PM SERVICE,REPAIR LIGHTS

Meter Reading: 0		Labor	Parts	
In Date: 04/10/2007	Close Date: 04/25/2007	Hours	Description	Quantity
- Pm		10.00	09997 BRAKE CLEAN	2.00
- Repair Lights			2641 RH TAIL LIGHT GROTE# 52302	1.00
- Repair Deck			2616 RED MARKER LIGHT SQUARE	2.00
- Repair Winch			58856 SEAL	4.00
- Shop Supplies			CARRIAGE/BOLT 1/4-20 25C250BCGOZ 2 1/2	2.00
			FLOOR/SCREWS 69279	1.00
			SHOP SUPPLIES	1.00
			NUTS 25CNFHOZ 1/4-20	2.00
			DS-167 TOGGLE SWITCH (STANDARD)	2.00
Parts Charge: 100.92		Labor Charge: 110.00		

1/2/2018
11:07:05AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 739828

Problem: PM/TIRES/LIGHTS/CK.BRAKES

Meter Reading: 0		Labor	Parts	
In Date: 06/08/2007	Close Date: 06/13/2007	Hours	Description	Quantity
- Pm Service		7.50	58856 SEAL	4.00
- Installed Battery Box And Battery Reconnected Break Out Switch To Harness			4053 BATTERY BOX	1.00
			PS1250F1 BATTERY (POWER SONIC PS-1250-F1)	1.00
- Replaced Tag Light And License Bracket And Wired Back Into Light Circuit Reconnected Right Rear Marker Lamp			TAG LIGHT W/BRKT 002594	1.00
			SHOP SUPPLIES	1.00
	Parts Charge: 35.74	Labor Charge: 110.00		

Workorder: 746657

Problem: SEE REQUEST

Meter Reading: 0		Labor	Parts	
In Date: 11/02/2007	Close Date: 11/09/2007	Hours	Description	Quantity
- R/R 2 Tires		6.50	8616-100 TRAILER WIRE 6 WIRE 14 GAUGE	35.00
- Nitro 2 Tires			2640 LH TAIL LIGHT GROTE# 52312	1.00
- Trl Plug Rewire Trl Both Tail Lights			SHOP SUPPLIES	1.00
- Rewire Brakes (Not Working)			2641 RH TAIL LIGHT GROTE# 52302	1.00
- Install 1 New Stud			762171406 205/75R15 MARATHON C	2.00
- Shop Supplies			755-5046 MALE CONNECTOR	1.00
	Parts Charge: 206.08	Labor Charge: 30.00		

Workorder: 832890

Problem: PM/SEE LIST

Meter Reading: 0		Labor	Parts	
In Date: 01/17/2008	Close Date: 01/25/2008	Hours	Description	Quantity
- Pm Service		6.00	2640 LH TAIL LIGHT GROTE# 52312	1.00
- R/R L/R Tail Lamp. Repair Wiring For Right Tail Lamp			SHOP SUPPLIES	1.00
- Repair Brake Wiring				
- Shop Supplies				
	Parts Charge: 7.33	Labor Charge: 30.00		

1/2/2018
11:07:05AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 837566

Problem: BRAKES

Meter Reading: 0		Labor	Parts	
In Date: 04/25/2008	Close Date: 04/29/2008	Hours	Description	Quantity
-	Replace Shorted Trl Plug And Broken License Plate Light & Bracket, Ck All Lights	5.00	755-5046 MALE CONNECTOR	1.00
			26330 TAG LIGHT (TKR LITE)	1.00
-	R/R Frt Tires (Dry Rott)		762176400 205/75R14 MARATHON C	2.00
-	Nitro 2 Tires		762176400 205/75R14 MARATHON C	-2.00
-	Repair And Replace Broken Wiring (Pull Out) To 3 Pit Pf 4		SHOP SUPPLIES	1.00
-	Brakes And Secure To A Higher Location		762171406 205/75R15 MARATHON C	2.00
-	Shop Supplies			
Parts Charge: 142.60		Labor Charge: 30.00		

Workorder: 838930

Problem: PM, BRAKES LOCK-UP?, LIGHTS

Meter Reading: 0		Labor	Parts	
In Date: 05/23/2008	Close Date: 05/30/2008	Hours	Description	Quantity
-	Pm	4.50	SHOP SUPPLIES	1.00
-	Repair Brake Wiring On Rear Axle -Crushed Wires Between Frmeand Axle)			
-	Shop Supplies			
Parts Charge: 2.00		Labor Charge: 30.00		

1/2/2018
11:07:05AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 841188

Problem: PM SERVICE,REPLACE TAILLAMPS

Meter Reading: 0		Labor		Parts	
In Date: 07/10/2008	Close Date: 07/21/2008	Hours	Description		Quantity
- Pm		12.20	58856 SEAL		4.00
- R/R L/R Tail Light And Male Connector			05048 GALVANIZE SPRAY		1.00
- R/R Rear Tire			GREASE CAP		4.00
- R/R Backing Plate And Rwire-Adj Brakes 1.5			09997 BRAKE CLEAN		1.00
- Nitro 2 Tires			2640 LH TAIL LIGHT GROTE# 52312		1.00
- Shop Supplies			755-5046 MALE CONNECTOR		1.00
			755-5046 MALE CONNECTOR		1.00
			TIRE DISPOSAL FEE		2.00
			762171406 205/75R15 MARATHON C		2.00
			LH ELECTRIC BRAKE		1.00
			RH ELECTRIC BRAKE		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		292.53	Labor Charge:	30.00	

Workorder: 843683

Problem: BRAKE LIGHTS INOP

Meter Reading: 0		Labor		Parts	
In Date: 09/03/2008	Close Date: 09/04/2008	Hours	Description		Quantity
- Replaced Stop Light And Tag Light Bulbs Test All Lights		3.00	81733 GREASE CAP		1.00
- Replaced Missing Dust Cap, L/Rear Clean And Repair			SHOP SUPPLIES		1.00
- Bearing Wheel					
- Shop Supplies					
Parts Charge:		2.84	Labor Charge:	90.00	

Workorder: 845780

Problem: REPIAR LIGHTS , CHECK TIRES

Meter Reading: 0		Labor		Parts	
In Date: 10/16/2008	Close Date: 10/23/2008	Hours	Description		Quantity
- Check Lights-Replace Trailer Plug And 1 Tail Lamp Bulb		5.00	755-5046 MALE CONNECTOR		1.00
- Rf Brakes Inop 1.5 Repaired Blue Wire In Harness Near Lr			SHOP SUPPLIES		1.00
- Brake, Repaired Broken Blue And White Wires On Axle					
- Near Rf Brake Rplcd Brkn					
- Shop Supplies					
Parts Charge:		7.48	Labor Charge:	180.00	

1/2/2018
11:07:05AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 932937

Problem: TAIL LIGHT OUT, SLOW LEAK IN LEFT TIRES,CK ALL

Meter Reading: 0		Labor		Parts	
In Date: 01/20/2009	Close Date: 01/22/2009	Hours	Description		Quantity
-	Replace Two Tire	3.00	TIRE DISPOSAL FEE		2.00
-	Replace Tail Light Asm Replace Bulbs		TR416 VALVE STEM		2.00
-	Nitro Fill All Fourt Tires		SHOP SUPPLIES		1.00
-	Shop Supplies		2640 LH TAIL LIGHT GROTE# 52312		1.00
			762171406 205/75R15 MARATHON C		2.00
Parts Charge:		152.99	Labor Charge:	180.00	

Workorder: 940211

Problem: PM SERVICE/CHECK WIRING

Meter Reading: 0		Labor		Parts	
In Date: 07/02/2009	Close Date: 07/10/2009	Hours	Description		Quantity
-	Pm Service	9.00	58856 SEAL		4.00
-	Wiring For Rear Brakes-Broken On Axle Replace 1 Wire		4086 SWITCH CABLE		1.00
-	And Repaired Connections On Other Wire And Resecure To Axle Tube		2808 TAIL LIGHT LED LEFT HAND (EXPEDITER)		1.00
-	Replace Breakaway Switch And Battery		2809 TAIL LIGHT LED RIGHT HAND (EXPEDITER)		1.00
-	Replaced L&R Tail Lamps		PS1250F1 BATTERY (POWER SONIC PS-1250-F1)		1.00
-	Replace R/Rear Tire And Renitro		SHOP SUPPLIES		1.00
-	Shop Supplies		TIRE DISPOSAL FEE		1.00
			762171406 205/75R15 MARATHON C		1.00
Parts Charge:		176.89	Labor Charge:	540.00	

1/2/2018
11:07:05AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 946579

Problem: Repair: Lights , Tires Trailer plug, tool rack. License Tag

Meter Reading: 0		Labor	Parts	
In Date: 12/02/2009	Close Date: 12/14/2009	Hours	Description	Quantity
-	Repair Tool Racks Fabricate Lower Support For Racks	10.00	2852 3/8" CHAIN LINK 3/8"THREADED LINK	2.00
	And Reattach		2845 3/8" CHAIN HOOK	2.00
-	Repalce Bolt On Hitch Assy		TIRE DISPOSAL FEE	1.00
-	Replace Safety Chain Hooks To Proper Size		BUSHEN	12.00
-	Rebuild Complete Suspension Replace All Bushings And		BOLTS	12.00
	Bolt Not Combinations.		SHACKLES	2.00
-	Replace Rt Rear Tire		BOLTS	2.00
-	Shop Supplies		EQUALIZERS	2.00
			NUTS	14.00
			SHOP SUPPLIES	1.00
			BALL COUPLER	1.00
			762171406 205/75R15 MARATHON C	1.00
	Parts Charge:	278.25	Labor Charge:	1,200.00

Workorder: 1007403

Problem: tires

Meter Reading: 0		Labor	Parts	
In Date: 07/12/2010	Close Date: 07/14/2010	Hours	Description	Quantity
- Jpp				
Parts Charge: 0.00		Labor Charge: 0.00	Commercial Charge:	82.80

Workorder: 1007404

Problem: service

Meter Reading: 0		Labor		Parts	
In Date: 07/12/2010	Close Date: 07/14/2010	Hours	Description	Quantity	
- Jpp					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 48.00	

1/2/2018
11:07:05AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 1008104

Problem: PM -- SPOT #295

Meter Reading: 0	Labor	Parts		
In Date: 07/30/2010	Hours	Description	Quantity	
- Pm Service	11.00	58856 SEAL	4.00	
- Repalce Trailer Plug		014901 LUBRICANT PENT 45NC (405540006)DON'T REORDE	1.00	
- Repalce 1 Outer Bearing And Cup		SET 4 BEARING SET TIMKEN L44649/L44610	1.00	
- Replace Breakaway Cable, Repair Wire From Brake Away		4086 SWITCH CABLE	1.00	
- Repair Broken Wiring To R/Side Brake		755-5046 MALE CONNECTOR	1.00	
- Weld Ramp		T-1 BLACK PAINT GLOSS	1.00	
- Shop Supplies		SHOP SUPPLIES	1.00	
		1/2 4X8 SHEET STEEL	12.00	
Parts Charge:	240.67	Labor Charge:	660.00	

Workorder: 1106352

Problem: right rear flat tire

Meter Reading: 0	Labor	Parts		
In Date: 06/08/2011	Hours	Description	Quantity	
- Jpp Maint Compound				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 96.11

Workorder: 1106353

Problem: service

Meter Reading: 0	Labor	Parts		
In Date: 06/11/2011	Hours	Description	Quantity	
- Jpp				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 24.00

Workorder: 1108191

Problem: service

Meter Reading: 0	Labor	Parts		
In Date: 05/23/2011	Hours	Description	Quantity	
- Jpp				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 24.00

1/2/2018
11:07:05AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 1202125

Problem: pm/ check lights

Meter Reading: 0	Labor	Parts		
In Date: 03/01/2012	Hours	Description	Quantity	
- Pm Service	16.00	58856 SEAL	4.00	
- Replaced Trailer Plug		755-5046 MALE CONNECTOR	1.00	
- Replaced R/Rear Tail Lamp And Repair Wiring To Side Marker Light		2809 TAIL LIGHT LED RIGHT HAND (EXPEDITER)	1.00	
- Replace 2 Tires And Nitro		TIRE DISPOSAL FEE	2.00	
- Resecure Loose Deck Boards		5/16-18X3 DECK SCREWS T/C TORX M/S BLK	10.00	
- Replaced L&R Brake Assembly		004098 BREAKAWAY SWITCH	1.00	
- Repaired Gound Connection For All 4 Brakes		LH BRAKE ASSY	1.00	
- Replace All Asset #'S And County Decals		RH BRAKE ASSY	1.00	
- Repair Winch Hook And Service Winch		762171406 205/75R15 MARATHON C	2.00	
- Travel Time To Expeditor To Pick Up Parts		81733 GREASE CAP	1.00	
- Shop Supplies		SHOP SUPPLIES	1.00	
Parts Charge: 485.16		Labor Charge: 960.00		

Workorder: 1206075

Problem: trailer lights

Meter Reading: 0	Labor	Parts		
In Date: 06/28/2012	Hours	Description	Quantity	
- Test Trailer Sys Replace Right Rear Trailer Light And Rewire	1.00	SHOP SUPPLIES	1.00	
- Shop Supplies		2809 TAIL LIGHT LED RIGHT HAND (EXPEDITER)	1.00	
Parts Charge: 36.03		Labor Charge: 60.00		

1/2/2018
11:07:05AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 1304065

Problem: PM / Right side tires ? Brake light out

Meter Reading: 0	Labor	Parts		
In Date: 04/24/2013	Hours	Description	Quantity	
- Pm	8.50	TIRE DISPOSAL FEE	3.00	
- Replace Trailer Plug		58856 SEAL	4.00	
- Repalce Breakaway Battery		12V5AMP/HOUR BATTERY	1.00	
- Replace 3 Tires		TRAILER CONN PLUG	1.00	
- Repalce R/Frt Marker Light		2616 RED MARKER LIGHT	1.00	
- Shop Supplies		SHOP SUPPLIES	1.00	
		762171406 205-75R15	3.00	
Parts Charge:	473.37	Labor Charge:	510.00	

Workorder: 1304075

Problem: Service

Meter Reading: 0	Labor	Parts		
In Date: 12/26/2012	Hours	Description	Quantity	
- Tire Service Jpp Maint Compound - Service				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 33.60

Workorder: 1304076

Problem: Tires

Meter Reading: 0	Labor	Parts		
In Date: 12/26/2012	Hours	Description	Quantity	
- Tire Service Jpp Maint Compound - Tires				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 99.38

Workorder: 1309489

Problem: service call

Meter Reading: 0	Labor	Parts		
In Date: 09/19/2013	Hours	Description	Quantity	
- Tire Service Jpp Maint Compound - Service Call				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 69.94

1/2/2018
11:07:05AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 1309827

Problem: Flat tire (replace tire)..set up for 9/20/13 am

Meter Reading: 0	Labor	Parts		
In Date: 09/19/2013	Hours	Description	Quantity	
- Tire Service Jpp Maint Compound - Flat Tire (Replace Tire)..Set Up For 9/20/13 Am				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 46.40

Workorder: 1309838

Problem: SERVICE (MOUNT/DISMOUNT)

Meter Reading: 0	Labor	Parts		
In Date: 09/19/2013	Hours	Description	Quantity	
- Tire Service Jpp - Service (Mount/Dismount)				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 15.60

Workorder: 1309932

Problem: needs tire

Meter Reading: 0	Labor	Parts		
In Date: 10/01/2013	Hours	Description	Quantity	
- Tire (Parts Only)				
- Shop Supplies				
ST205/75R15 TIRE				
SHOP SUPPLIES				
TIRE DISPOSAL FEE				
Parts Charge:	96.78	Labor Charge:	0.00	

1/2/2018
11:07:05AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 1402174

Problem: pm/ check tires and deck boards

Meter Reading: 0		Labor	Parts	
In Date: 03/05/2014	Close Date: 03/24/2014	Hours	Description	Quantity
- Pm Service		32.00	RH ELEC BRAKE ASSY 10 X 2 1/4	2.00
- Replace Trailer Plug			LH ELEC BRAKE ASSY 10 X 2 1/4	2.00
- Replace Brake Away Battery , Replace Brakeway Cable			2X8-16FT PT DECK WOOD	10.00
- Repalce One Tire And Rotate W/Nitro Fill			TAPPERED BEARING SET	3.00
- Replace All Deck Boards			5/16-18X3 DECK SCREWS	150.00
- Replace Inner Outer Bearings And Repack			TAPPERED BEARING SET	3.00
- Repair Broken Wiring To Left Side Brake. Repair Ground			SHOP SUPPLIES	1.00
Wiring To Front Brake			BACKING PLATE ASSM	2.00
- Replace Front Brake Assy			BACKING PLATE ASSM	2.00
- Replace Rear Brake Assy			2X8-12FT PT WOOD	5.00
- Service Winch And Lube			TIRE DISPOSAL FEE	1.00
- Shop Supplies			762171406 205-75R15	1.00
			TRAILER CONN PLUG	1.00
			12V5AMP/HOUR BATTERY	1.00
			SEAL 1.719 2.561 .500	4.00
Parts Charge:		943.60	Labor Charge:	1,920.00

Workorder: 1406140

Problem: right trailer light

Meter Reading: 0		Labor	Parts	
In Date: 06/23/2014	Close Date: 06/26/2014	Hours	Description	Quantity
- Replace Right Side Light Assy		1.00	LED RH S T T LAMP	1.00
- Shop Supplies			SHOP SUPPLIES	1.00
Parts Charge:		30.36	Labor Charge:	60.00

1/2/2018
11:07:05AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 1407703

Problem: lift gate/ check tires/ see notes

Meter Reading: 0	Labor	Parts		
In Date: 08/05/2014	Hours	Description	Quantity	
- Replace Ramp Asst Spirngs	6.00	762171406 205-75R15	2.00	
- Replace Dust Cap		MAC WITE LITHIUM GRES	1.00	
- Replace 2 Tires Nitro Fill And Valve Stem		GREASE CAP	2.00	
- Left Side Brake Inop. It Has Broken Wire Harness. Repair		SHOP SUPPLIES	1.00	
Wires To Left Side Rr And Rear Brake Drums		RAMP ASSIST SPRING	1.00	
- Shop Supplies		TIRE DISPOSAL FEE	2.00	
Parts Charge:	332.33	Labor Charge:	360.00	

Workorder: 1409728

Problem: tire

Meter Reading: 0	Labor	Parts		
In Date: 09/29/2014	Hours	Description	Quantity	
- Replace Tire				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 62.00

Workorder: 1409748

Problem: tire

Meter Reading: 0	Labor	Parts		
In Date: 09/29/2014	Hours	Description	Quantity	
- Order Tire		ST205/75R15 TIRE	1.00	
- Shop Supplies		TIRE DISPOSAL FEE	1.00	
		SHOP SUPPLIES	1.00	
Parts Charge:	102.67	Labor Charge:	0.00	

Workorder: 1411834

Problem: P/R Flat tire at S.C. Reg. Park inside Fence service set for 11/20/14a

Meter Reading: 0	Labor	Parts		
In Date: 11/17/2014	Hours	Description	Quantity	
- Tire Service South County Regional Park - P/R Flat Tire At S.C. Reg. Park Inside Fence Service Set For 11/20/14A				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 66.34

1/2/2018
11:07:05AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 1412153

Problem: replace right front tire

Meter Reading: 0		Labor	Parts	
In Date: 12/04/2014	Close Date: 12/09/2014	Hours	Description	Quantity
- Replace R/F Tire		1.00	SHOP SUPPLIES	1.00
- Shop Supplies			TIRE DISPOSAL FEE	1.00
			762171406 205-75R15	1.00
			TR416 VALVE STEM	1.00
Parts Charge: 140.51		Labor Charge: 60.00		

Workorder: 1412480

Problem: nail in left rear tire

Meter Reading: 0		Labor	Parts	
In Date: 12/15/2014	Close Date: 12/16/2014	Hours	Description	Quantity
- Repair Left Rear Tire		1.00	SHOP SUPPLIES	1.00
- Shop Supplies				
Parts Charge: 2.00		Labor Charge: 60.00		

Workorder: 1412646

Problem: tag/ springs/ tail light/ pigtail/ see notes

Meter Reading: 0		Labor	Parts	
In Date: 12/18/2014	Close Date: 12/23/2014	Hours	Description	Quantity
- Replaced L/Tailamp, Tag Light, Install Tag		11.50	LED LH S T T W LIC	1.00
- Replace Trailer Plug			TRAILER CONN PLUG	1.00
- Replaced Breakaway Switch, Repaired Wiring For Both			BREAKAWAY SWITCH	1.00
Rear Brakes And Battery			RAMP ASSIST SPRING	1.00
- R&R Ramps To Replace Assist Springs			SHOP SUPPLIES	1.00
- Shop Supplies			LICENSE LAMP	1.00
Parts Charge: 104.33		Labor Charge: 690.00		

Workorder: 1412782

Problem: needs helper springs for tailgate

Meter Reading: 0		Labor	Parts	
In Date: 12/23/2014	Close Date: 01/21/2015	Hours	Description	Quantity
- Install Spring Helpers		2.00	SHOP SUPPLIES	1.00
- Shop Supplies			GORILLA LIFT SPRING ASSISTS	1.00
Parts Charge: 381.50		Labor Charge: 120.00		

1/2/2018
11:07:05AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 1504744

Problem: pm/ nail right rear tire

Meter Reading: 0	Labor	Parts	
In Date: 05/11/2015	Hours	Description	Quantity
- Pm	15.00	BULK TRAILER WIRE	30.00
- Replace R/R Tire, Nitro Tire		SHOP SUPPLIES	1.00
- Replace Trailer Battery Mount New Battery Box Rewire		762171406 205-75R15	1.00
Ground		VINYL ELECTRICAL TAPE	1.00
- Rewire Trailer Battery Mount New Battery Box Rewire		TR416 VALVE STEM	1.00
Ground		SEAL 1.719 2.561 .500	4.00
- Male Trailer Plug Replacement		GREASE CAP	4.00
- Replace Winch Cable And Gear Box Lube		BRAKE CLEANER	2.00
- Clean And Readjust All Brake Drums And Shoes Replace		12V5AMP/HOUR BATTERY	1.00
Trailer Brake Away Unit Rewire Brakes And Tst		BREAKAWAY BATTERY CASE	1.00
- Shop Supplies		SUB LIGHT KIT	1.00
		BULK TRAILER WIRE	8.00
		CLR MKR LAMP	2.00
		TRAILER CONN PLUG	1.00
		WINCH CABLE W HOOK 1/4 X 35	1.00
		BREAKAWAY SWITCH	1.00
		TIRE DISPOSAL FEE	1.00
Parts Charge:	398.45	Labor Charge:	900.00

Workorder: 1509035

Problem: left rear wheel bearing

Meter Reading: 0	Labor	Parts	
In Date: 09/09/2015	Hours	Description	Quantity
- Replace Axle Assembly And Wheel Bearings	6.00	3.5k BEAM AXLE	1.00
- Replace Rear Brakes Drum And Adjust		U-BOLT	4.00
- Rewire Trailer Brakes		SHOP SUPPLIES	1.00
- Shop Supplies		BEARING ASSEMBLY	2.00
		NYLON LOCKNUT	8.00
		BRAKE CLEANER	1.00
Parts Charge:	283.88	Labor Charge:	360.00

1/2/2018
11:07:05AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 1603057

Problem: check trailer plug

Meter Reading: 0	Labor	Parts		
In Date: 03/23/2016	Hours	Description	Quantity	
- Repair Trailer Plug Wiring	1.00	SHOP SUPPLIES	1.00	
- Shop Supplies				
Parts Charge:	2.00	Labor Charge:	60.00	

Workorder: 1604368

Problem: pm/ replace hitch/ check tires/ battery/ lights

Meter Reading: 0	Labor	Parts		
In Date: 04/26/2016	Hours	Description	Quantity	
- Pm	12.00	SEAL 1.719 2.561 .500	4.00	
- Replace 4 Tires, Clean Rust Paint Wheels		BRAKE CLEANER	2.00	
- Replace Breakaway Battery And Switch		TR416 VALVE STEM	4.00	
- Replace Front Marker Lights, And Repair Wiring For Tail Lights		MARK LMP	2.00	
- Replace Trailer Towing Coupler		TRAILER TONGUE	1.00	
- Ck Brakes Inop. Repair Broken Wires, Clean And Adjust Front And Rear Brakes		TRAILER BALL	1.00	
- Cut And Remove Damaged Winch Cable And Install New Cable		BREAK AWAY SYSTEM	1.00	
- Shop Supplies		762171406 205-75R15	4.00	
		SHOP SUPPLIES	1.00	
		TIRE DISPOSAL FEE	4.00	
		CABLE WINCH 7/32X25'	1.00	
Parts Charge:	813.38	Labor Charge:	720.00	

Workorder: 1608589

Problem: tire with slow leak

Meter Reading: 0	Labor	Parts		
In Date: 08/18/2016	Hours	Description	Quantity	
- Replace Tire	1.00	762171406 205-75R15	2.00	
- Shop Supplies		TR416 VALVE STEM	1.00	
		TIRE DISPOSAL FEE	1.00	
		SHOP SUPPLIES	1.00	
Parts Charge:	140.16	Labor Charge:	60.00	

1/2/2018
11:07:05AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 1612918

Problem: wheel bearing

Meter Reading: 0		Labor		Parts	
In Date: 12/19/2016	Close Date: 01/12/2017	Hours	Description		Quantity
- R/R Axle Assembly And Bearings		15.50	TIRE DISPOSAL FEE		1.00
- R/R Brake Backing Plates Amd Rewore Crushed Wiring			MALE TRAILER CONNECTOR		2.00
For Both Axles			SEAL 1.719 2.561 .500		4.00
- Pm			TRAILER WIRE		10.00
- R/R Trailer Plug			3.5k BEAM AXLE		1.00
- R/R Bent Wheel			WHEEL 15X5 5-4.75 WHITE		1.00
- R/R 1 Tire			U-BOLT KIT		2.00
- Shop Supplies			BEARING ASSEMBLY		2.00
			HUB DRUM ASSY 10 X 2.5		2.00
			WHEEL		1.00
			TR416 VALVE STEM		2.00
			RH ELEC BRAKE ASSY 10 X 2 1/4		2.00
			762171406 205-75R15		2.00
			GREASE CAP		2.00
			TR416 VALVE STEM		2.00
			LH ELEC BRAKE ASSY 10 X 2 1/4		2.00
			SHOP SUPPLIES		1.00
Parts Charge:		753.94	Labor Charge:	930.00	

Workorder: 1613013

Problem: Bearing Issue

Meter Reading: 0		Labor		Parts	
In Date: 12/19/2016	Close Date: 12/21/2016	Hours	Description		Quantity
- Tire Service Lantana And 441 - Bearing Issue					
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 96.00

Workorder: 1708202

Problem: needs 1 new tire

Meter Reading: 0		Labor		Parts	
In Date: 08/18/2017	Close Date: 08/25/2017	Hours	Description		Quantity
- Parts Only			SHOP SUPPLIES		1.00
- Shop Supplies			TIRE DISPOSAL FEE		1.00
			TIRE		1.00
Parts Charge:		103.50	Labor Charge:	0.00	

1/2/2018
11:07:05AM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10139981 2003 CROSLEY CR81X22 Trailer, 3 Ton, Dual Axle

Workorder: 1708231

Problem: Right flat tire

Meter Reading: 0	Labor	Parts		
In Date: 08/18/2017	Hours	Description	Quantity	
- Tire Service Jpp Maintenance - Right Flat Tire				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 63.56

Workorder: 1709133

Problem: 1 new tire

Meter Reading: 0	Labor	Parts		
In Date: 09/21/2017	Hours	Description	Quantity	
- Parts Only				
- Shop Supplies				
TIRE				
TIRE DISPOSAL FEE				
SHOP SUPPLIES				
Parts Charge:	103.50	Labor Charge:	0.00	

Workorder: 1709168

Problem: bubble on front right tire

Meter Reading: 0	Labor	Parts		
In Date: 09/05/2017	Hours	Description	Quantity	
- Tire Service Jpp/ Nursery - Bubble On Front Right Tire				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 67.16

Workorder: 1710009

Problem: Transition Prep Charge

Meter Reading: 0	Labor	Parts		
In Date: 10/12/2017	Hours	Description	Quantity	
- Transition Prep Charge				
Parts Charge:	0.00	Labor Charge:	2.00	120.00

Total Parts Charges: 8,583.03 Total Labor Charges: 13,420.00 Total Comm. Charges: 894.89