

**Palm Beach County Fleet Management
Asset Maintenance History**

10174388 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 838561 **Meter:** 0 **In Date:** 05/14/2008 **Closed:** 05/14/2008
Problem: 001 WASH TICKET ISSUED OUT 05/14/08

- 001 Wash Ticket Issued Out 05/14/08

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 838601 **Meter:** 0 **In Date:** 05/15/2008 **Closed:** 05/15/2008
Problem: WASH VEHICLE

- Wash Vehicle

- Pre-delivery Inspection

Hours 3.00 Labor: 180.00 Parts: 0.00 Total: 180.00
:

Workorder: 840919 **Meter:** 1294 **In Date:** 07/07/2008 **Closed:** 07/11/2008
Problem: INSTALL FUEL TANK

- Install & Wire Aux Fuel Tank; Install Tool Box; Test Pump & Test Drive	Parts List	Qty
	Shop Supplies	1.00
- Shop Supplies		

Hours 11.00 Labor: 660.00 Parts: 2.00 Total: 662.00
:

Workorder: 843706 **Meter:** 2659 **In Date:** 09/03/2008 **Closed:** 09/16/2008
Problem: INSTALL LADDER RACK.

- R&r Aux.fuel Tank & Tool Box.fabricate & Install Ladder Rack Re-install Wiring For Aux. Fuel Pump.	Parts List	Qty
	Shop Supplies	1.00
- Shop Supplies	Ladder Rack	1.00

Hours 7.00 Labor: 420.00 Parts: 334.40 Total: 754.40
:

Workorder: 848189 **Meter:** 5694 **In Date:** 12/15/2008 **Closed:** 12/19/2008
Problem: P.M.SERVICE

- Pm Service	Parts List	Qty
- Service Fuel Tank & Pump; R&r Fuel Filter; Ck & Secure Boltsservice & Adjust Ladder Rack	Shop Supplies	1.00
	1259 Hydr Filter Lbf Frm P1653a Wix 51259	1.00
- Nail In L/f Tire; Remove Nail & Patch; Mount, Balance & Add Nitrogen; Rotate All Tires	1372 Oil Filter Frm Ph2 Wix 51372	1.00
	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
- Shop Supplies	5w20 Engine Oil	8.00
	1066 White Lithium (crc 05037)	1.00
	Nb-19 Wiper Blades 19" Anco 31-19	2.00

Hours 6.25 Labor: 375.00 Parts: 78.63 Total: 453.63
:

Workorder: 938717 **Meter:** 10993 **In Date:** 06/08/2009 **Closed:** 06/12/2009
Problem: NAIL IN L FRONT TIRE

- Repair Nail In L/f Tire	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 938971 **Meter:** 11190 **In Date:** 06/15/2009 **Closed:** 06/22/2009
Problem: P.M.SERVICE/SEE NOTE

- Pm Service	Parts List	Qty
- Install New Decal	Shop Supplies	1.00
- Transport & Pick Up At Dealer For Warranty Repair; Defective L/f Tire Pressure Sensor	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	5w20 Engine Oil	8.00
	Used Firex Refurbed Fire Extingshers	1.00
Hours 5.00	Labor: 300.00	Parts: 56.34
:		Total: 356.34

Workorder: 1002318 **Meter:** 14912 **In Date:** 03/04/2010 **Closed:** 03/16/2010
Problem: P.M.SERVICE

- P. M.	Parts List	Qty
- Service fuel tank. Service ladder rack. R/r fuel filter.	Shop Supplies	1.00
- Shop Supplies	1259 Hydr Filter Lbf Frm P1653a Wix 51259	1.00
	Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
	1372 Oil Filter Frm Ph2 Wix 51372	1.00
	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
	5w20 Engine Oil	8.00
	Nb-19 Wiper Blades 19" Anco 31-19	2.00
Hours 5.25	Labor: 315.00	Parts: 94.75
:		Total: 409.75

Workorder: 1004359 **Meter:** 15002 **In Date:** 04/28/2010 **Closed:** 04/30/2010
Problem: DEAD BATTERY

- C/c: Dead battery. Jump start. Verify, battery dead. Vehicle sitting for a couple of months. Recharge battery, test. Battery good.

Hours 0.75 Labor: 45.00 Parts: 0.00 Total: 45.00
:

Workorder: 1004996 **Meter:** 15002 **In Date:** 05/13/2010 **Closed:** 05/21/2010
Problem: Check battery

- Recharge battery. Test charging system & battery. Found battery defective.	Parts List	Qty
- Transport & pick up vehicle at dealer. (defective battery).	Shop Supplies	1.00
- Shop Supplies		
Hours 2.50	Labor: 150.00	Parts: 2.00
:		Total: 152.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1012904 **Meter:** 18877 **In Date:** 11/18/2010 **Closed:** 11/23/2010
Problem: P.M.SERVICE

- P. M. Service.	Parts List	Qty
- Service ladder rack. Service Aux fuel tank.	Shop Supplies	1.00
- Replace 4 tires & left front tire strap.	1259 Hydr Filter Lbf Frm P1653a Wix 51259	1.00
- Shop Supplies	1372 Oil Filter Frm Ph2 Wix 51372	1.00
	5w20 Engine Oil	8.00
	Nb-19 Wiper Blades 19" Anco 31-19	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	Wheel Strap Attachm.	1.00
	179636492 Lt245/75r17 Wrangler Sr-a E	4.00
	Tire Disposal Fee	4.00
Hours 6.75	Labor: 405.00	Parts: 858.39
:		Total: 1,263.39

Workorder: 1100208 **Meter:** 19427 **In Date:** 01/05/2011 **Closed:** 01/10/2011
Problem: LEFT REAR SIGNAL LIGHT IS NOT WORKING

- Replace left rear turn signal bulb.	Parts List	Qty
	3157 Tail Light Bulbs	1.00
Hours 0.50	Labor: 30.00	Parts: 1.11
:		Total: 31.11

Workorder: 1100545 **Meter:** 19687 **In Date:** 01/13/2011 **Closed:** 01/19/2011
Problem: flash canceiver

- Reflash Canceiver and reprogram	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1106134 **Meter:** 22177 **In Date:** 06/09/2011 **Closed:** 06/17/2011
Problem: P. M. SERVICE

- P. M. Service	Parts List	Qty
- Service & check ladder rack & tool boxes.	Shop Supplies	1.00
- Shop Supplies	1259 Hydr Filter Lbf Frm P1653a Wix 51259	1.00
	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
	1372 Oil Filter Frm Ph2 Wix 51372	1.00
	5w20 Engine Oil	8.00
Hours 3.75	Labor: 225.00	Parts: 53.35
:		Total: 278.35

Workorder: 1108997 **Meter:** 23805 **In Date:** 08/25/2011 **Closed:** 08/26/2011
Problem: Diesel fuel pump inoperable

- C/s: Diesel fuel pump not working. Verify concern, perform pinpoint test & found bad fuel pump.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1300394	Meter: 36570	In Date: 01/10/2013	Closed: 01/18/2013
Problem: p.m.service,fuse for cigarette lighter			
- pm	Parts List		Qty
- ck cig lighter inop replace blown 20 amp fuse	Ford Fuel Filter		1.00
- tighten ladder rack	1372 Oil Filter		1.00
- Shop Supplies	Napa Quart 5w20		8.00
	Shop Supplies		1.00
Hours 4.25	Labor: 255.00	Parts: 49.22	Total: 304.22
:			
Workorder: 1302685	Meter: 38322	In Date: 03/19/2013	Closed: 03/22/2013
Problem: left rear tail light inop			
- replace left rear brake light bulb	Parts List		Qty
	Bulb		1.00
Hours 0.50	Labor: 30.00	Parts: 0.99	Total: 30.99
:			
Workorder: 1306555	Meter: 41134	In Date: 07/01/2013	Closed: 10/23/2013
Problem: ck engine lights on, pm			
- pm	Parts List		Qty
- service auoc fuel tank	Napagold Fuel Filter		1.00
- replace all 4 tires	Napagold Oil Filter		1.00
- ck engine light in on scan and found code u0073, u0155, u2023, po500. p1502.u2023, test drive and odometer goes blank speedometer notd working gas light comes on and tpm light come on perform pinpoint	Napa Quart 5w20		8.00
	Used Fire X Refurbished		1.00
	Napagold Air Filter		1.00
- perform pin point test trace wire harness and found bad pcm replace pcm and reprogram clear all codes	31-19 Wiper Blades 19		2.00
	Napa Trans Filter		1.00
- wiper not working properly ck and trace wire harness found bad wiper motor assembly replace wiper motor assembly	179636492 Lt245-75r17		4.00
	Speed Sensor		1.00
- ck abs sys for code u0073 perform pin point test trace wire harness and found shroted wire harness and bad abs module repair wire harness replace abs module and reprogram	Pcm Module		1.00
	Wiper Motor Assembly		1.00
- fill all tire with nitrogen	Abs Control Module		1.00
- clear all codes and test drive after repair	Shop Supplies		1.00
- service ladder rack	Tire Disposal Fee		4.00
- Shop Supplies			
Hours 25.25	Labor: 1,515.00	Parts: 2,685.25	Total: 4,200.25
:	0		
Workorder: 1310667	Meter: 41236	In Date: 10/24/2013	Closed: 10/30/2013
Problem: tire prressure sensor fault			
- ck tpms fault correct all tire pressure inspect for damage clear reset tpms			
Hours 0.50	Labor: 30.00	Parts: 0.00	Total: 30.00
:			
Workorder: 1401234	Meter: 43618	In Date: 02/06/2014	Closed: 02/10/2014
Problem: L/REAR TAIL LIGHT /UTILITY BED LIGHT INOP.			
- replace left rear tail light bulb and replace rr utility bed light	Parts List		Qty
	Bulb		1.00
Hours 0.75	Labor: 45.00	Parts: 0.99	Total: 45.99
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1405979 **Meter:** 47202 **In Date:** 06/18/2014 **Closed:** 06/26/2014
Problem: REPLACE LEFT REAR TAIL LIGHT

- repair left rear brake light

		Parts List	Qty
		Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 0.99	Total: 30.99
:			

Workorder: 1407130 **Meter:** 47671 **In Date:** 07/18/2014 **Closed:** 07/28/2014
Problem: P.M.SERVICE,A/C BLOWER,POWER OUTLET,TRAILER PLUG.

- pm

- svc aux fuel tank and repair handle

- ck ac only glow on 1 speed verify concern perform pinpoint test and found bad blower resistor replace resistor

- trailer warning light is on dash ck and found corroded wire harness and plus repair wire harness and replace plug (female connector)

- ck aux power outlt not working ck found no problem with sockets at this time

- Shop Supplies

		Parts List	Qty
		Napagold Fuel Filter	1.00
		Napagold Oil Filter	1.00
		Napa Quart 5w20	8.00
		Used Fire X Refurbished	1.00
		Napagold Air Filter	1.00
		Wiper Blade	2.00
		Washer FI	1.00
		Napa Trans Filter	1.00
		Blower Resistor	1.00
		5404 Female Connector	1.00
		Shop Supplies	1.00
Hours 10.00	Labor: 600.00	Parts: 129.41	Total: 729.41
:			

Workorder: 1409043 **Meter:** 48694 **In Date:** 09/09/2014 **Closed:**
Problem: AC

Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1500671 **Meter:** 51945 **In Date:** 01/20/2015 **Closed:** 01/22/2015
Problem: REPLACE RIGHT REAR TAIL LIGHT

- repair right rear tail light

		Parts List	Qty
		Bulb	1.00
Hours 0.75	Labor: 45.00	Parts: 0.75	Total: 45.75
:			

Workorder: 1502243 **Meter:** 53050 **In Date:** 03/03/2015 **Closed:** 03/09/2015
Problem: left rear tail light not working

- repair left rear tail light

		Parts List	Qty
		Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 0.75	Total: 30.75
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1504474 **Meter:** 54521 **In Date:** 04/30/2015 **Closed:** 05/07/2015
Problem: pm, replace head lamps 2

- pm	Parts List	Qty
- repair both head light	Napagold Fuel Filter	1.00
- svc axu fuel tank	Napagold Oil Filter	1.00
- repair 3rd brake light	Napa Quart 5w20	8.00
- Shop Supplies	Wiper Blade	2.00
	Washer Fl	1.00
	Halogen Lamp	2.00
	Napa Trans Filter	1.00
	Napagold Fuel Filter	1.00
	Shop Supplies	1.00
Hours 5.75	Labor: 345.00	Parts: 90.65
:		Total: 435.65

Workorder: 1504614 **Meter:** 54521 **In Date:** 05/06/2015 **Closed:** 05/07/2015
Problem: replace break away switch

- replace break away switch	Parts List	Qty
- Shop Supplies	Breakaway Switch	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 10.45
:		Total: 70.45

Workorder: 1505049 **Meter:** 54824 **In Date:** 05/19/2015 **Closed:** 05/26/2015
Problem: PINTLE PIN

- replace pintle pin	Parts List	Qty
	Pintle Pin W/chain	1.00
Hours 0.25	Labor: 15.00	Parts: 2.61
:		Total: 17.61

Workorder: 1509444 **Meter:** 57541 **In Date:** 09/18/2015 **Closed:** 09/24/2015
Problem: replace right tail light

- Repair Right Rear Trail Light	Parts List	Qty
	Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 0.75
:		Total: 30.75

Workorder: 1510596 **Meter:** 58078 **In Date:** 10/20/2015 **Closed:** 10/27/2015
Problem: pm, flat tire

- pm	Parts List	Qty
- svc aux fuel tank	Napagold Oil Filter	1.00
- repair right front tire	Napa Quart 5w20	8.00
- Shop Supplies	Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
	Napagold Air Filter	1.00
	Napa Trans Filter	1.00
	Shop Supplies	1.00
Hours 4.75	Labor: 285.00	Parts: 80.90
:		Total: 365.90

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1511578 **Meter:** 58775 **In Date:** 11/12/2015 **Closed:** 11/30/2015
Problem: r/rear signal light inop.

- repair right rear brake light	Parts List	Qty
	Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 0.75
:		Total: 30.75

Workorder: 1512251 **Meter:** 59120 **In Date:** 12/03/2015 **Closed:** 12/17/2015
Problem: replace brake booster ck brakes, ck trailer wiring fault

- remove coolant degas reservoir air filter housing and replace leaking brake booster	Parts List	Qty
	Female Conn Socket	1.00
- replace wire harness and female trailer connector	Term 24-22 Conn	1.00
- Shop Supplies	Butt Connector	50.00
	Booster	1.00
	Wire Term 16-14 Blt	10.00
	Shop Supplies	1.00
Hours 6.25	Labor: 375.00	Parts: 313.81
:		Total: 688.81

Workorder: 1604701 **Meter:** 59700 **In Date:** 05/04/2016 **Closed:** 05/17/2016
Problem: Pm service right tail light inop.

- Pm service.	Parts List	Qty
- Service auxiliary fuel tank.	Napagold Oil Filter	1.00
- Replace right tail lamp assembly.left and right tail lamp sockets and bulbs.	Napa Trans Filter	1.00
	Stp Trn TI Lgt Socket	2.00
- Replace 6 cab mounts.	Rear Tail Lamp Assembly	1.00
- Rotate and balance all tires	Napa Quart 5w20	8.00
- Shop Supplies	Wiper Blade Anco	1.00
	Washer Fluid Concentr	1.00
	Bulb	2.00
	Body Mount Kit	2.00
	Body Mount Kit	4.00
	Wiper Blade	1.00
	Shop Supplies	1.00
Hours 12.25	Labor: 735.00	Parts: 599.24
:		Total: 1,334.24

Workorder: 1612341 **Meter:** 60169 **In Date:** 12/01/2016 **Closed:** 12/12/2016
Problem: DEAD BATTERY

- C/c battery.test battery bad.replace battery check charging system.	Parts List	Qty
	Battery	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 0.75	Labor: 45.00	Parts: 126.43
:		Total: 171.43

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1700059 **Meter:** 60330 **In Date:** 01/03/2017 **Closed:** 01/17/2017
Problem: PM service

- Pm service	Parts List	Qty
- Service auxiliary fuel tank.	5w20 Engine Oil	8.00
- Install pintle pin.	Wiper Blade Anco	2.00
- Replace four tires.	Napagold Oil Filter	1.00
- Fill tires with nitrogen and reset Tpm System.	Washer Fluid Concentr	1.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Napagold Air Filter	1.00
	Napagold Fuel Filter	1.00
	Napa Trans Filter	1.00
	Pintle Pin W/clip	1.00
	179636492 Lt245-75r17	4.00
	Napa Quart 5w20	8.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 6.75	Labor: 405.00	Parts: 1,108.53
:		Total: 1,513.53

Workorder: 1706907 **Meter:** 60672 **In Date:** 07/14/2017 **Closed:** 07/24/2017
Problem: PM Service

- Pm Service.	Parts List	Qty
- Rotate and balance tires.	Napagold Oil Filter	1.00
- Shop Supplies	Napa Quart 5w20	8.00
	Wiper Blade Anco	2.00
	Washer Fluid Concentr	1.00
	Shop Supplies	1.00
Hours 3.50	Labor: 210.00	Parts: 43.87
:		Total: 253.87

Workorder: 1800057 **Meter:** 60741 **In Date:** 01/03/2018 **Closed:** 01/03/2018
Problem: Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 120.00	Parts: 0.00
:		Total: 120.00