

**Palm Beach County Fleet Management
Asset Maintenance History**

10189452 2012 TORO GRNDSMSTR 7200 Mower, Zero Turn Radius (Ztr), 72 In.

Workorder: 1208523 **Meter:** 1 **In Date:** 09/07/2012 **Closed:** 09/07/2012
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
 :

Workorder: 1400197 **Meter:** 403 **In Date:** 01/07/2014 **Closed:** 02/11/2014
Problem: pm service

- Pm Service

- Hyd Service

- R/r 1 Caster wheel Asm (belt)

- R/r rubber deflector

- Shop Supplies

Parts List

	Qty
Tire & Wheel Assy	1.00
Bearing	2.00
Seal	2.00
Spacer	1.00
Screw	1.00
Deflector	1.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
15-40 Oil	4.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	5.00
Shop Supplies	1.00

Hours 6.00 Labor: 360.00 Parts: 359.62 Total: 719.62
 :

Workorder: 1411623 **Meter:** 403 **In Date:** 11/18/2014 **Closed:** 11/20/2014
Problem: flat tire

- Replace tire

- Shop Supplies

Parts List

	Qty
15-600-6 Nhs Str Rib 04	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours 1.00 Labor: 60.00 Parts: 60.93 Total: 120.93
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1502360	Meter: 719	In Date: 03/05/2015	Closed: 03/18/2015
Problem: pm service/ needs blades			
- Pm	Parts List	Qty	
- Replace two rear tires	Tire 24x12x12 6 Ply	2.00	
- Replace two plastic deck wheels and hardware. one front	Roller Scalp	2.00	
caster Tireand replace bearings on wheels	Tube-spanner	2.00	
- Clean and readjust parking brake and disc brakes	Screw	2.00	
- hydro service	15-6.00x6 Ribbed Tire	1.00	
- Replace deck Blades and hardware and clean out grass	Brake Cleaner	1.00	
under deck	Rotary Blade	3.00	
- Wash eqpt	Blade Bolt	3.00	
- Replace Mower Chute	Rubber Deflector Assy	1.00	
- Shop Supplies	Napagold Oil Filter	1.00	
	Napagold Fuel Filter	1.00	
	Napagold Air Filter	1.00	
	15-40 Oil	4.00	
	Napa Hydraulic Filtr	1.00	
	Aw68 Hydro Fluid Hydr	5.00	
	Shop Supplies	1.00	
	Freight Charge	1.00	
Hours 11.50	Labor: 690.00	Parts: 1,205.47	Total: 1,895.47
:			
Workorder: 1605221	Meter: 1049	In Date: 05/19/2016	Closed: 06/15/2016
Problem: pm/ filter housing/ new blades			
- Pm	Parts List	Qty	
- Hyd Service	Napagold Oil Filter	1.00	
- Replace 3 deck blades	Napagold Air Filter	1.00	
- Replace all deck roller and hardware	Napa Qt 15w40	4.00	
- Replace right front caster tire and wheel assembly	Napagold Fuel Filter	1.00	
- Replace air cleaner housing cover	Napa Hydraulic Filtr	1.00	
- Wash Eqpt	Aw68 Hydro Fluid Hydr	5.00	
- Check charging sys battery failed load test replace battery	Rotary Blade	3.00	
and clean terminals	Deck Roller	2.00	
- Shop Supplies	Roller,deck	1.00	
	Flange Nut Ni	2.00	
	Screw	2.00	
	Tube-spanner	2.00	
	Roller Scalp	2.00	
	Tube Spacer	2.00	
	Air Cleaner Cover Assy	1.00	
	Battery	1.00	
	Roller	1.00	
	15-6.00x6 Ribbed Tire	1.00	
	Shop Supplies	1.00	
Hours 11.50	Labor: 690.00	Parts: 890.99	Total: 1,580.99
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1611172 **Meter:** 1261 **In Date:** 10/28/2016 **Closed:** 11/07/2016
Problem: rear deck tires bad, check all tires, replace blades

- Replace all deck wheels replace 1) frt caster wheel replace bearing	Parts List	Qty
	15-6.00x6 Ribbed Tire	1.00
- Replace all 3 blades	Roller,deck	1.00
- Shop Supplies	Spacer-roller	1.00
	Bolt	1.00
	Roller	1.00
	Shaft,roller	1.00
	Roller Scalp	2.00
	Tube-spanner	2.00
	Deck Roller	2.00
	Shaft	2.00
	Rotary Blade	3.00
	Blade Bolt	3.00
	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 751.64
:		Total: 991.64

Workorder: 1612589 **Meter:** 1262 **In Date:** 12/08/2016 **Closed:** 12/20/2016
Problem: hydraulic leak/ see notes

- R&r right rear wheel motor, disassemble and reseal and test Run	Parts List	Qty
	Non-chlor Brake Clnr	1.00
- Shop Supplies	Seal Kit	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours 6.00	Labor: 360.00	Parts: 128.23
:		Total: 488.23

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1701136 **Meter:** 1355 **In Date:** 02/02/2017 **Closed:** 02/22/2017

Problem: need caster wheels, 1 roller on bottom of deck fell off

	Parts List	Qty
- Pm		
- R/r right rear wheel motor and service sys	Napagold Air Filter	1.00
- R/r 3 blades	Napagold Fuel Filter	1.00
- R/r scalping wheels, hardware and reinstall roller	Napagold Oil Filter	1.00
- R/r radiator hoses and service cooling sys	15-40 Oil	4.00
- Install new air filter cover assembly	Blaster Penetrant	1.00
- R/r rear tires	Napa Hydraulic Filtr	1.00
- Shop Supplies	Aw68 Hydro Fluid Hydr	6.00
	Rotary Blade	3.00
	Screw	2.00
	Tube-spanner	2.00
	Tube Spacer	2.00
	Roller Scalp	2.00
	Napakool	1.00
	Air Cleaner Cover Assy	1.00
	Valve-actuator	1.00
	24x12x12 6 Ply Kenda	2.00
	Rh Hyd Motor Assy	1.00
	O-ring	1.00
	Oring	1.00
	O R Ing	1.00
	Gasket	1.00
	1gal Rtu Antifreeze	2.00
	Rad Cap	1.00
	O Ring	1.00
	Upper Radiator Hose	1.00
	Lower Radiator Hose	1.00
	Rad Ca[	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
	Freight Charge	1.00
Hours 14.00	Labor: 840.00	Parts: 2,628.00
:		Total: 3,468.00

Workorder: 1709287 **Meter:** 1483 **In Date:** 09/25/2017 **Closed:** 09/27/2017

Problem: deck belt/ blades

	Parts List	Qty
- Replace both deck belt and free up and lube tensioners		
- Replace 3 blades	V-belt	1.00
- Shop Supplies	V-belt	1.00
	Rotary Blade	3.00
	Shop Supplies	1.00
Hours 3.50	Labor: 210.00	Parts: 253.33
:		Total: 463.33

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder:	1800058	Meter:	1483	In Date:	01/03/2018	Closed:	01/03/2018
Problem:	Transition Prep Charge						
- Transition Prep Charge							
	Hours 2.00		Labor: 120.00		Parts: 0.00		Total: 120.00
	:						