

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11737 2006 CHEVROLET TRAILBLAZER Suv, Mid Size

Total Hours: 266.60	Labor: 17,057.40	Parts: 11,605.05	Comm: 137.95	Charged: 28800.39
----------------------------	-------------------------	-------------------------	---------------------	--------------------------

Work Order: 635742	Meter: 0	In Date: 03/14/2006	Closed: 03/14/2006
Problem: TAG CHG	03/14/06		

Work Completed

- Tag Chg 03/14/06

Hours: 0.00

Comm: 0.00

Parts Issued

Vehicle Tag Charge

1.00

Labor: 0.00

Parts: 34.35

Total: 34.35

Work Order: 636330	Meter: 0	In Date: 03/27/2006	Closed: 03/27/2006
Problem: PRE-DELIVERY INSPECTION			

Work Completed

- Pre-delivery Inspection

Hours: 2.00

Comm: 0.00

Labor: 100.00

Parts: 0.00

Total: 100.00

Work Order: 636613	Meter: 58	In Date: 03/31/2006	Closed: 03/31/2006
Problem: INSTALL F/EXTINGUISHER			

Work Completed

- Fabricate & Install Fire Extinguisher W/bracket

Hours: 0.50

Comm: 0.00

Labor: 25.00

Parts: 0.00

Total: 25.00

Work Order: 641884	Meter: 4571	In Date: 07/06/2006	Closed: 07/07/2006
Problem: P.M.SERVICE			

Work Completed

- Pm Service

- Shop Supplies

Hours: 2.75

Comm: 0.00

Parts Issued

Shop Supplies

1.00

Ca9345 Air Filter Lbf Af2014 Wix 42729

1.00

1522 Oil Filter Frm Ph3675/9837 Wix 51522

1.00

10w30 Motor Oil

5.00

Labor: 137.50

Parts: 24.08

Total: 161.58

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11737 2006 CHEVROLET TRAILBLAZER Suv, Mid Size

Work Order: 647412 **Meter:** 9249 **In Date:** 10/19/2006 **Closed:** 10/23/2006
Problem: P.M. SERVICE.

Work Completed

- Pm Service
- Nitrogen Fill All Tires.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Ca9345 Air Filter Lbf Af2014 Wix 42729	1.00
1522 Oil Filter Frm Ph3675/9837 Wix 51522	1.00
10w30 Motor Oil	5.00

Hours: 3.75

Comm: 0.00

Labor: 206.25	Parts: 24.94	Total: 231.19
---------------	--------------	---------------

Work Order: 734017 **Meter:** 14835 **In Date:** 02/08/2007 **Closed:** 02/09/2007
Problem: P.M SERVICE

Work Completed

- Perform Pm Service Complete.
- High Speed Balance All Tires To Correct Vibration Over 55mph
- Perform Wheel Alignment Complete To Correct Right Pulling Condition On Level Road Way.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Ca9345 Air Filter Lbf Af2014 Wix 42729	1.00
1522 Oil Filter Frm Ph3675/9837 Wix 51522	1.00
10w30 Motor Oil	6.00
31-22 Wiper Blades 22" Wiper Blade	2.00

Hours: 6.25

Comm: 0.00

Labor: 343.75	Parts: 38.23	Total: 381.98
---------------	--------------	---------------

Work Order: 739341 **Meter:** 20001 **In Date:** 05/31/2007 **Closed:** 06/04/2007
Problem: P.M. SERVICE.

Work Completed

- Pm Service
- Transmission Flush
- Rebalance All 4 Tires.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
1522 Oil Filter Frm Ph3675/9837 Wix 51522	1.00
10020 Injector Cleaner Don't Reorder	1.00
Syn/atf Trans Fluid Synthetic	10.00
10w30 Motor Oil	6.00
31-22 Wiper Blades 22" Wiper Blade	2.00

Hours: 5.25

Comm: 0.00

Labor: 288.75	Parts: 77.76	Total: 366.51
---------------	--------------	---------------

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11737 2006 CHEVROLET TRAILBLAZER Suv, Mid Size

Work Order: 746277 **Meter:** 0 **In Date:** 10/23/2007 **Closed:** 10/25/2007
Problem: 004 WASH TICKETS ISSUED OUT 10/23/07

Work Completed

- 004 Wash Tickets Issued Out 10/23/07

Hours: 0.00 Comm: 33.36 Labor: 0.00 Parts: 0.00 Total: 33.36

Work Order: 746430 **Meter:** 25814 **In Date:** 10/30/2007 **Closed:** 10/31/2007
Problem: P.M. SERVICE.

Work Completed

- Pm Service
- Mount Four New Tires And High Speed Balance Nitro Fill
- Shop Supplies

Parts Issued **Quantity**

Shop Supplies 1.00

Ca9345 Air Filter Lbf Af2014 Wix 42729 1.00

1522 Oil Filter Frm Ph3675/9837 Wix 51522 1.00

10020 Injector Cleaner Don't Reorder 1.00

10w30 Motor Oil 6.00

31-22 Wiper Blades 22" Wiper Blade 2.00

Tire Disposal Fee 4.00

773430430 235/75r16 Wrangler St Sl 4.00

Hours: 4.75 Comm: 0.00 Labor: 285.00 Parts: 478.18 Total: 763.18

Work Order: 835116 **Meter:** 31254 **In Date:** 03/06/2008 **Closed:** 03/11/2008
Problem: P.M SERVICE

Work Completed

- Pm Service
- Rotate And Balance All 4 Tires
- Shop Supplies

Parts Issued **Quantity**

Shop Supplies 1.00

Ca9345 Air Filter Lbf Af2014 Wix 42729 1.00

Ph9837 Oil Filter Wix 51522 1.00

10w30 Motor Oil 7.00

31-16 Wiper Blades 16" Wiper Blade 1.00

31-22 Wiper Blades 22" Wiper Blade 2.00

Used Firex Refurbed Fire Extingshers 1.00

Hours: 3.75 Comm: 0.00 Labor: 225.00 Parts: 54.17 Total: 279.17

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11737 2006 CHEVROLET TRAILBLAZER Suv, Mid Size

Work Order: 835895 **Meter:** 31911 **In Date:** 03/21/2008 **Closed:** 03/25/2008
Problem: L/R TIRE FLAT

Work Completed

- Repair L/r Tire.
- Shop Supplies

Parts Issued

Shop Supplies

Quantity

1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 2.00

Total: 62.00

Work Order: 839448 **Meter:** 35780 **In Date:** 06/04/2008 **Closed:** 06/10/2008
Problem: P.M SERVICE,CHECK ENGINE LIGHT ON

Work Completed

- Pm Service
- Induction Cleaning Service.test Drive.
- Ck Eng Lamp On.diag Scan Test.p0449 Evap Vent Solenoid Ctl
Circuit.actuator Test.solenoid Not Working.diag Circuit.power & Ground
Ok.repl
- Rotate And High Speed Balance 4 Tires.refill W/nitrogen.
- Shop Supplies

Parts Issued

L17301a Engine Fog Kit Hard Carbon (smart
Blend)

1.00

Shop Supplies

1.00

Ph9837 Oil Filter Wix 51522

1.00

10w30 Motor Oil

6.00

31-16 Wiper Blades 16" Wiper Blade

1.00

31-22 Wiper Blades 22" Wiper Blade

2.00

Evap Vent Solenoid

1.00

Hours: 7.75

Comm: 0.00

Labor: 465.00

Parts: 131.59

Total: 596.59

Work Order: 845671 **Meter:** 40975 **In Date:** 10/15/2008 **Closed:** 10/21/2008
Problem: PM SERVICE,CHECK HEAD LIGHTS SEE NOTES

Work Completed

- Pm Service
- Ck Hed Light Operation.test W/scan Tool-b2575,diag,monitor Head Lgts
W Scan Tool,repl Defective Low Beam Relay.clear Code.
- Rotate & Hi Speed Balance 4 Tires.nitro Fill Tires.
- Shop Supplies

Parts Issued

Shop Supplies

1.00

Ca9345 Air Filter Lbf Af2014 Wix 42729

1.00

Ph9837 Oil Filter Wix 51522

1.00

10w30 Motor Oil

6.00

31-16 Wiper Blades 16" Wiper Blade

1.00

31-22 Wiper Blades 22" Wiper Blade

2.00

Hdm Relay

1.00

Hours: 4.75

Comm: 0.00

Labor: 285.00

Parts: 81.49

Total: 366.49

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K117317 2006 CHEVROLET TRAILBLAZER Suv, Mid Size

Work Order: 934662 **Meter:** 45985 **In Date:** 03/03/2009 **Closed:** 03/10/2009
Problem: P.M SERVICE

Work Completed

- Pm Service
- Ck Battery And Charging Sys R&r Defective Battery
- Service Transfer Cas Drain And Refill
- Diagnose And Test Noise In Belt Area,r&r Defective Idler Pulley & Wornbelt.pressure Est And Inspect Cooling Sys. Flush And Refill
- Repair 1 Tire Mount L/f Hi Speed Balance All 4 Tires. Nitro Fill.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Fan Belt	1.00
Ph9837 Oil Filter Wix 51522	1.00
12378508 Fluid Transfer Case	2.00
10w30 Motor Oil	6.00
Group 75 Battery (acd 75ps)	1.00
Group 75 Battery (acd 75ps)	-1.00
Group 78 Battery (acd 78ps)	1.00
Antifreeze Ext/life All Makes (peak 407)	2.00
Idler Pulley	1.00

Hours: 10.25

Comm: 0.00

Labor: 615.00 Parts: 237.88 Total: 852.88

Work Order: 939100 **Meter:** 50844 **In Date:** 06/17/2009 **Closed:** 06/22/2009
Problem: P.M. SERVICE.

Work Completed

- Pm Service
- Transmission Service.flush And Filter.
- Balance 4 Tires. Nitro Fill.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Ft1217 Trans Filter Atp B-165 Wix Don't Use	1.00
Ph9837 Oil Filter Wix 51522	1.00
10w30 Motor Oil	6.00
Syn/atf Trans Fluid Synthetic	12.00
31-22 Wiper Blades 22" Wiper Blade	2.00
Used Firex Refurbed Fire Extingshers	1.00

Hours: 6.25

Comm: 0.00

Labor: 375.00 Parts: 114.24 Total: 489.24

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11737 2006 CHEVROLET TRAILBLAZER Suv, Mid Size

Work Order: 946903 **Meter:** 56630 **In Date:** 12/10/2009 **Closed:** 12/29/2009

Problem: P.M service.

Work Completed

- P.m service.
- Service front differential.
- Service rear differential.
- Mount, balance & nitro fill four new tires.
- Alignment.
- Shop Supplies

Parts Issued

Quantity

82194 Gray Silicone (permatex)	1.00
Axle Additive	1.00
Shop Supplies	1.00
Ph9837 Oil Filter Wix 51522	1.00
Ca9345 Air Filter Lbf Af2014 Wix 42729	1.00
09997 Brake Clean	1.00
12345841 Gear Oil Synthetic 75w-90	1.00
12345841 Gear Oil Synthetic 75w-90	1.00
10w30 Motor Oil	7.00
31-22 Wiper Blades 22" Wiper Blade	2.00
31-16 Wiper Blades 16" Wiper Blade	1.00
183680418 P235/75r16 Wrangler Sr-a 109s	4.00
Tire Disposal Fee	4.00

Hours: 9.25

Comm: 0.00

Labor: 555.00 Parts: 675.25 Total: 1,230.25

Work Order: 1004788 **Meter:** 61388 **In Date:** 05/10/2010 **Closed:** 05/13/2010

Problem: P.M service, see notes.

Work Completed

- P.m service.
- Diagnose fuel gauge inop. R&r fuel tank & replace fuel pump & sender assembly, clean fuel tank & test drive.
- Perform computer diagnostics, test & replace failed upstream O2 sensor, clear codes & retest.
- Test starting & charging system, test & replace battery.
- Test & replace R/r brake light bulb.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Ph9837 Oil Filter Wix 51522	1.00
10w30 Motor Oil	7.00
31-22 Wiper Blades 22" Wiper Blade	2.00
Used Firex Refurbed Fire Extinguishers	1.00
Group 78 Battery (acd 78ps)	1.00
3157 Tail Light Bulbs	1.00
Fuel Pump	1.00
Sending Unit	1.00
Oxygen Sensor	1.00

Hours: 10.95

Comm: 0.00

Labor: 657.00 Parts: 729.18 Total: 1,386.18

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11731 2006 CHEVROLET TRAILBLAZER Suv, Mid Size, 4X4

Work Order: 1010344 **Meter:** 66225 **In Date:** 09/21/2010 **Closed:** 09/29/2010
Problem: P.M. Service.

Work Completed

- Perform pm service.
- Inspect and replace both failed front and rear shocks with new.
- Rotate and balance four tires.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Ph9837 Oil Filter Wix 51522	1.00
Ca9345 Air Filter Lbf Af2014 Wix 42729	1.00
Wd40 Spray Lube Stock# 405540002	1.00
10w30 Motor Oil	7.00
Front Shocks	2.00
Rear Shocks	2.00

Hours: 6.25

Comm: 0.00

Labor: 375.00 Parts: 329.16 Total: 704.16

Work Order: 1103416 **Meter:** 67179 **In Date:** 03/30/2011 **Closed:** 04/07/2011
Problem: P.M. service.

Work Completed

- Perform pm service.
- Perform induction service and clean throttle body.power flush all fuel injectors and clear codes with scan tool.
- Inspect and replace damage trailer wiring harness and plug receptacle with new six pin style.fabricate and repair damage bracket.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

L17301a Engine Fog Kit Hard Carbon (smart Blend)	1.00
L17040 Inject Cleaner One Part (smart Blend)	1.00
Shop Supplies	1.00
Ph9837 Oil Filter Wix 51522	1.00
10w30 Motor Oil	7.00
Used Firex Refurbed Fire Extingshers	1.00
31-22 Wiper Blades 22" Wiper Blade	2.00
31-16 Wiper Blades 16" Wiper Blade	1.00
8616-100 Trailer Wire 6 Wire 14 Gauge	3.00
5404 Female Connector	1.00
5402 Socket Bracket	1.00

Hours: 8.25

Comm: 0.00

Labor: 495.00 Parts: 147.71 Total: 642.71

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11731 2006 CHEVROLET TRAILBLAZER Suv, Mid Size, 4X4

Work Order: 1110129 **Meter:** 67752 **In Date:** 09/22/2011 **Closed:** 09/28/2011
Problem: Pm service

Work Completed

- P.m. Service.
- Rotate and balance all tires.
- Repair driver seat trim.
- Shop Supplies

Hours: 4.25

Comm: 0.00

Parts Issued

Quantity

Shop Supplies	1.00
Ph9837 Oil Filter Wix 51522	1.00
10w30 Motor Oil	7.00
31-22 Wiper Blades 22" Wiper Blade	2.00

Labor: 255.00

Parts: 31.16

Total: 286.16

Work Order: 1300595 **Meter:** 69348 **In Date:** 01/16/2013 **Closed:** 01/29/2013
Problem: Pm service.

Work Completed

- Perform pm service.
- Test starting and charging system.battery failed loadtest after recharge.replace failed battery with new.
- Diagnose for winding noise and replace failed belt idler pulley with new.
- Diagnose blower motor speeds inop.replace failed blower resistor with new.also fabricate and replace failed connector and pigtail harness with new.
- Inspect and replace failed driver seat trim/ knob with new.
- Rotate and balance all four tires.
- Shop Supplies

Hours: 8.25

Comm: 0.00

Parts Issued

Quantity

Cover	1.00
Knob	1.00
10w30 Motor Oil	7.00
Napagold Oil Filter	1.00
Ca9345 Air Filter Lbf	1.00
31-22 Wiper Blades 22	2.00
31-16 Wiper Blades 16	1.00
Used Firex Refurberd F	1.00
Group 78 Acd	1.00
Idle	1.00
Resistor	1.00
Pt2195 Pigtail Blower	1.00
Shop Supplies	1.00

Labor: 495.00

Parts: 373.24

Total: 868.24

Work Order: 1302517 **Meter:** 69507 **In Date:** 03/13/2013 **Closed:** 03/20/2013
Problem: Right front headlight inop.

Work Completed

- Replace right headlamp bulb.

Hours: 0.50

Comm: 0.00

Parts Issued

Quantity

Halogen Capsule	1.00
-----------------	------

Labor: 30.00

Parts: 6.42

Total: 36.42

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11731 2006 CHEVROLET TRAILBLAZER Suv, Mid Size, 4X4

Work Order: 1307887 **Meter:** 69755 **In Date:** 08/07/2013 **Closed:** 08/21/2013

Problem: Pm service.

Work Completed

- P.m. Service.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

10w30 Motor Oil	7.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 225.00

Parts: 31.51

Total: 256.51

Work Order: 1311211 **Meter:** 70102 **In Date:** 11/05/2013 **Closed:** 11/15/2013

Problem: Wiper blades will not clear windsheild.

Work Completed

- Replace wiper blades.

Parts Issued

Quantity

Wiper Blade	2.00
-------------	------

Hours: 0.25

Comm: 0.00

Labor: 15.00

Parts: 8.49

Total: 23.49

Work Order: 1402708 **Meter:** 70731 **In Date:** 03/20/2014 **Closed:** 04/07/2014

Problem: Pm service.

Work Completed

- Perform pm service.
- Install two new tires to the front wheels.nitrogen fill and balance all four.
- Diagnose and replace failed canister purge valve with new.
- Computer diagnose for check engine light on.test and replace failed thermostat with new.reverse flush and renew engine coolant.
- Replace failed seat panel and adjusting knob for seat lumber adjustment with new.
- Perform wheel alignment complete.
- Shop Supplies

Parts Issued

Quantity

10w30 Motor Oil	7.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Washer Fl	1.00
183680418 P235-75r16	2.00
Thermostat	1.00
Cover	1.00
Knob	1.00
Peak Global	1.00
Evap Valve	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 13.00

Comm: 0.00

Labor: 780.00

Parts: 542.00

Total: 1,322.00

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11731 2006 CHEVROLET TRAILBLAZER Suv, Mid Size, 4X4

Work Order: 1501428 **Meter:** 75046 **In Date:** 02/06/2015 **Closed:** 02/27/2015
Problem: Pm service.Safety recall#12180

Work Completed

- Pm service.
- Replace two tires.rotate and balance all four.
- Replace front brake pads.resurface both front brake rotors.replace both front brake calipers.flush and bleed brake system.
- Perform tune up.replace all six worn spark plugs.
- Check battery and charging system.battery failed loadtest after recharge.replace defective battery.
- Diagnose for noise and replace defective right front wheel bearing assembly.
- Transport vehicle to and from dealer for safety recall #12180
- Shop Supplies

Parts Issued

Quantity

10w30 Motor Oil	7.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
183680418 P235-75r16	2.00
Group 78 Battery	1.00
1401 Brake Fluid Bra	2.00
Spark Plus	6.00
Reman/ca	1.00
Reman/ca	1.00
Disc Brake Pads	1.00
Reman Brake Caliper	1.00
Reman/ca	1.00
Hub Bearing Assembly	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 13.85

Comm: 0.00

Labor: 831.00 Parts: 1,253.30 Total: 2,084.30

Work Order: 1509105 **Meter:** 76167 **In Date:** 09/10/2015 **Closed:** 09/28/2015
Problem: P.M/. Service.

Work Completed

- Pm service.
- Inspect and replace broken driver side seat trim and lumbar knob.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

Cover	1.00
10w30 Motor Oil	7.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Wiper Blade	1.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours: 4.25

Comm: 0.00

Labor: 255.00 Parts: 72.67 Total: 327.67

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11731 2006 CHEVROLET TRAILBLAZER Suv, Mid Size, 4X4

Work Order: 1603665 **Meter:** 76351 **In Date:** 04/07/2016 **Closed:** 04/22/2016
Problem: P.M. service and check water leak leftfront and A/C does not shut off and wiper blades.

Work Completed

- P.m. Service.
- Check for water leak on left side.seal hole in firewall at rubber grommet.
- Resurface rear brake rotors.replace calipers and pads.flush and bleed system
- Diagnose and repair wire connector at A/c control head.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

10w30 Motor Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Wiper	1.00
Washer Fluid Concentr	1.00
Clr Rtv Silcn Sealant	3.00
Used Fire X Refurbished	1.00
Real Caliper	1.00
Real Caliper	1.00
B Fluid Dot 3-32oz	1.00
Brake Cleaner	1.00
Brake Real Pad	1.00
Shop Supplies	1.00

Hours: 9.25

Comm: 0.00

Labor: 555.00

Parts: 252.25

Total: 807.25

Work Order: 1610221 **Meter:** 76523 **In Date:** 09/29/2016 **Closed:** 11/01/2016
Problem: P.M. service.

Work Completed

- P.m. Service.
- Replace rear axle bump stoppers.
- Repair trailer connector wiring.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

Rear Stops Bump	2.00
10w30 Motor Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Wiper	1.00
Washer Fluid Concentr	1.00
Rear Stops Bump	2.00
Shop Supplies	1.00

Hours: 4.75

Comm: 0.00

Labor: 285.00

Parts: 174.52

Total: 459.52

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11731 2006 CHEVROLET TRAILBLAZER Suv, Mid Size, 4X4

Work Order: 1703863 **Meter:** 76856 **In Date:** 04/17/2017 **Closed:** 04/28/2017
Problem: P.M. service.

Work Completed

- P.m. service.
- Battery failed load test after recharge.check eletrical system .replace bad battery.
- Diagnose strobe lamps not working properly.replace two switches and fuse.
- Rotate and balance four tires.nitrofill.
- Shop Supplies

Parts Issued

Quantity

10w30 Motor Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Battery	1.00
Rocker Switch	2.00
Fmx-30 Fuse	1.00
Shop Supplies	1.00

Hours: 5.75

Comm: 0.00

Labor: 345.00 Parts: 171.23 Total: 516.23

Work Order: 1710632 **Meter:** 77212 **In Date:** 10/27/2017 **Closed:** 11/09/2017
Problem: PM Service

Work Completed

- P.m. service.
- Rotate and balance four tires.
- Shop Supplies

Parts Issued

Quantity

10w30 Motor Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Wiper	1.00
Washer Fluid Concentr	1.00
Mac Wite Lithium Gres	1.00
Big G Degreaser 1 Gal	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 225.00 Parts: 41.63 Total: 266.63

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11731 2006 CHEVROLET TRAILBLAZER Suv, Mid Size, 4X4

Work Order: 1804429 **Meter:** 77872 **In Date:** 04/27/2018 **Closed:** 05/03/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Rotate and high speed balance all four tires.
- Shop Supplies

Parts Issued

Quantity

10w30 Motor Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Wiper	1.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 225.00 Parts: 53.17 Total: 278.17

Work Order: 1810489 **Meter:** 78158 **In Date:** 10/11/2018 **Closed:** 10/17/2018
Problem: P.M. service .

Work Completed

- P.m. service.
- Perform battery load test . Charge battery . battery failed load test . R&R defective battery .
- Perform computer diagnose check engine light . Code P0455. Perform evap test ,smoke test . Replace evap vent solenoid and fuel cap . retest.
- Check circuit and replace strobe light switch . Retest.
- Check and install missing lumbar Knob.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
10w30 Motor Oil	7.00
22" Wiper Blade	2.00
Wiper	1.00
Washer Fluid Concentr	1.00
Fuel Cap	1.00
Evap solenoid	1.00
Rocker Red 20a	1.00
Battery	1.00
Knob	1.00
Shop Supplies	1.00

Hours: 6.45

Comm: 0.00

Labor: 432.15 Parts: 261.65 Total: 693.80

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11731 2006 CHEVROLET TRAILBLAZER Suv, Mid Size, 4X4

Work Order: 1904241 **Meter:** 78424 **In Date:** 04/18/2019 **Closed:** 04/29/2019
Problem: P.M. service.

Work Completed

- P.m. service.
- Replace missing lumber adjusting knob . Adjust rear window washer jet .
- Rotate and balance all four tires. Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
10w30 Motor Oil	7.00
Wiper	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Knob	1.00
Shop Supplies	1.00

Hours: 4.05

Comm: 0.00

Labor: 271.35

Parts: 63.29

Total: 334.64

Work Order: 1905849 **Meter:** 78538 **In Date:** 06/03/2019 **Closed:** 06/10/2019
Problem: Towed in will not come out of gear .

Work Completed

- Diagnose and replace broken shifter cable and adjust cable . Retest .
- Shop Supplies

Parts Issued

Quantity

Tranmission Shhift Cable	1.00
Shop Supplies	1.00

Hours: 2.50

Comm: 0.00

Labor: 167.50

Parts: 94.08

Total: 261.58

Work Order: 1905864 **Meter:** 78456 **In Date:** 06/03/2019 **Closed:** 06/03/2019
Problem: Wont move out of gear

Work Completed

- Tow From: Mobil stn (cell phone prkng) @ FI Mango and Bel To: Lv shop

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11737 2006 CHEVROLET TRAILBLAZER Suv, Mid Size

Work Order: 1910718 **Meter:** 79144 **In Date:** 10/18/2019 **Closed:** 10/31/2019
Problem: P.M. service.

Work Completed

- P.m. service.
- Replace two tires . Rotate and high speed balance all four wheels . Nitrofill all.
- Check and diagnose both rear speakers inop . Remove both rear door panels to replace defective speakers .
- Road test . Replace left front hub bearing assembly and retest .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
10w30 Motor Oil	7.00
Wiper	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
183680418 P235-75r16	2.00
Real Speaker	2.00
Hub Bearing	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 7.75

Comm: 0.00

Labor: 565.75 Parts: 1,087.21 Total: 1,652.96

Work Order: 2004284 **Meter:** 79533 **In Date:** 04/29/2020 **Closed:** 05/13/2020
Problem: P.M. service and recall N140291 .

Work Completed

- P.m .service.
- Replace two tires . Balance and rotate all four tires . Nitrofill all .
- R&r broken left seat lumbar adjuster knob and seat track cover .
- Transport to and from dealer for recall N140291 .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
10w30 Motor Oil	7.00
Wiper	1.00
22" Wiper Blade	2.00
183680418 P235-75r16	2.00
Cover	1.00
Knob	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 7.55

Comm: 0.00

Labor: 551.15 Parts: 473.77 Total: 1,024.92

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11737 2006 CHEVROLET TRAILBLAZER Suv, Mid Size

Work Order: 2101784 **Meter:** 80383 **In Date:** 02/17/2021 **Closed:** 02/27/2021
Problem: PM

Work Completed

- Preventive Maint. Service
- A/c performance test . Drivers side a/c vent heat comes out, Diagnose code #b0408 . Remove dash to replace defective left side temp actuator failed . Clear code and calibrate actuators
- Check and repair rear strobe switch inop
- Rotate and speed balance all, nitro fill
- Shop Supplies

Parts Issued

Quantity

10w30 Motor Oil	7.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Wiper	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Actuator	1.00
Rocker Red 20a	1.00
Shop Supplies	1.00

Hours: 10.75

Comm: 0.00

Labor: 784.75 Parts: 127.95 Total: 912.70

Work Order: 2109721 **Meter:** 80590 **In Date:** 09/07/2021 **Closed:** 09/20/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- R&r Worn Front Driver Side Upper Control Arm.
- Load Test Battery And Recharge Fully. R&r Failed Battery Due To Normal Wear And Check Charging System Ok Athis Time.
- Rotate And Balance Four Tires. Nitro Fill All
- Complete Front End Alignment And Road Test.
- Shop Supplies

Parts Issued

Quantity

Wiper	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napagold Oil Filter	1.00
10w30 Motor Oil	7.00
Battery	1.00
Napa 10w30 Qt	7.00
Control Arm Assy	1.00
Control Arm	1.00
Shop Supplies	1.00

Hours: 8.75

Comm: 0.00

Labor: 638.75 Parts: 368.25 Total: 1,007.00

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11737 2006 CHEVROLET TRAILBLAZER Suv, Mid Size

Work Order: 2201985 **Meter:** 80791 **In Date:** 02/22/2022 **Closed:** 02/28/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa 10w30 Qt	7.00
Wiper	1.00
22" Wiper Blade	2.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 273.75 Parts: 41.12 Total: 314.87

Work Order: 2208522 **Meter:** 81145 **In Date:** 08/16/2022 **Closed:** 08/23/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- R&r Failed Rear Hatch Struts And Window Struts Not Holding Up.
- Rotate And Balance Four Tires. Nitro fill all.
- Shop Supplies

Parts Issued

Quantity

Washer Fluid Concentr	1.00
Wiper	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Napagold Oil Filter	1.00
Napa 10w30 Qt	7.00
Strut	1.00
Strut	1.00
Strut	1.00
Strut	1.00
Shop Supplies	1.00

Hours: 4.55

Comm: 0.00

Labor: 332.15 Parts: 196.09 Total: 528.24

Work Order: 2300221 **Meter:** 81285 **In Date:** 01/09/2023 **Closed:** 01/11/2023
Problem: INSPECT BATTERY, WAS DEAD.

Work Completed

- Charge battery fully . Test battery and charging system . Battery failed load test . R&r defective battery .
- Shop Supplies

Parts Issued

Quantity

Battery	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00 Parts: 123.39 Total: 196.39

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11737 2006 CHEVROLET TRAILBLAZER Suv, Mid Size

Work Order: 2301317 **Meter:** 81462 **In Date:** 02/09/2023 **Closed:** 02/21/2023

Problem: PM Service. Radio has no sound, windshield wipers spray fluid just by turning wipers on.

Work Completed

- Preventive Maint. Service
- Inspect Radio electrical connection Ground & power, ok Test radio Not available called Charles Inspect wiper operation, check circuit short to ground R & I multifunction switch, after installation notice burning odor from motor, R & I burnt cover .
- Drivers seat lumbar knob missing, install new
- Rotate and speed balance, nitro fill
- Shop Supplies

Parts Issued

Quantity

Napa 10w30 Qt	7.00
Napagold Oil Filter	1.00
Wiper	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Wiper Switch	1.00
Knob	1.00
Kit Wip Motor	1.00
Shop Supplies	1.00

Hours: 5.55

Comm: 0.00

Labor: 405.15 Parts: 451.91 Total: 857.06

Work Order: 2309018 **Meter:** 81809 **In Date:** 09/05/2023 **Closed:** 09/13/2023

Problem: PM Service

Work Completed

- Preventive Maint. Service
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa 10w30 Qt	7.00
Wiper	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 273.75 Parts: 62.47 Total: 336.22

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11737 2006 CHEVROLET TRAILBLAZER Suv, Mid Size

Work Order: 2402683 **Meter:** 82176 **In Date:** 03/15/2024 **Closed:** 04/04/2024

Problem: PM Service. Strokes are INOP and employee stated power steering isn't working.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Strobe Lights Not Working Found Aux Fuse Popped Test For Short Replace Fuse And Retest
- Power Steering Fluid Low Filled Resivior And Found Cooler Leaking Replace Power Steering Cooler And Bleed Air Out Of System And Retest
- Test Drove Vehicle Found Losseness In Steering Wheel Shock Down Tires And Found Lower And Upper Control Arms Bushings Bad Replace Upper And Lower Control Arms And Ball Joints On Both Sides
- Test Drive And Perform Front End Alingment Retest
- Rear Wiper Fluid Not Working Tested Power And Gorund At The Pump Replace Pump And Retest
- Shop Supplies

Napagold Oil Filter	1.00
Napa Syn 5w30 Qt	8.00
Wiper Blade	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Fls-30 Fuse	1.00
P/s Cooler	1.00
Psf Qt	2.00
Ball Joint	2.00
Control Arm Assy	1.00
Control Arm Assy	1.00
Control Arm Assy	1.00
Control Arm Assy	1.00
Hose Clamp	2.00
Washer Pump	1.00
Shop Supplies	1.00

Hours: 15.55

Comm: 0.00

Labor: 1,135.15

Parts: 923.66

Total: 2,058.81

Work Order: 2410775 **Meter:** 82697 **In Date:** 11/01/2024 **Closed:** 11/08/2024

Problem: 1 - Wash ticket(s) Issued to: Charles Sisson

Work Completed

- 1 - Wash ticket(s) Issued to: Charles Sisson

Hours: 0.00

Comm: 8.59

Labor: 0.00

Parts: 0.00

Total: 8.59

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11737 2006 CHEVROLET TRAILBLAZER Suv, Mid Size

Work Order: 2501059 **Meter:** 82965 **In Date:** 02/03/2025 **Closed:** 02/21/2025

Problem: PM Service. Also operator stated vehicles AC blows warm air.

Work Completed

- Preventive Maint. Service
- Mount and balanced 4 new tires due to age and dry rot. Nitrogen filled all tires.
- Battery tested bad. Charged battery fully and retested bad. Replaced bad battery.
- Diagnose front washers inop. Found to have bad washer pump. R&r faulty washer pump. Top off fluid and check proper function.
- During inspection found coolant leaking around radiator cap area. Pressure tested system and no leak found. Replaced radiator cap and top off fluid
- Diagnose A/c not cooling. Found to be low on freon. Checked for leaks and unable to pinpoint leak at this time. Replaced both service ports and add stop leak to system. Recharge freon to factory spec
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Syn 5w30 Qt	8.00
16in Exactfitblade	1.00
22in Exactfitblade	2.00
Used Fire X Refurbished	1.00
Battery	1.00
Washer Fluid Concentr	1.00
Freon Lv Shop 1	2.00
Red Angel Ac Stop Lk	1.00
washer pump	1.00
Cap	1.00
A/c Valve Core	1.00
P235/75r16xl Hankook Dynapro	4.00
A/c Valve Core	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 9.35

Comm: 0.00

Labor: 682.55

Parts: 1,068.01

Total: 1,750.56

Work Order: 2507271 **Meter:** 83051 **In Date:** 08/05/2025 **Closed:** 08/18/2025

Problem: PM Service. Check battery had to jump start. left front tire going low, turn signal out

Work Completed

- Preventive Maint. Service
- check & repair left front tire, Rotate and speed balance, nitro fill
- Check battery , perform battery analyzing load and charging system test battery tested good, Alternator output 135 amps, 14.3 volts, charge to 100% Check for drain, 0.2 Amps after Gps disco returned to service Battery just replaced 2/25
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Syn 5w30 Qt	8.00
Washer Fluid Concentr	1.00
16in Exactfitblade	1.00
Wiper Blade	2.00
Shop Supplies	1.00

Hours: 5.25

Comm: 0.00

Labor: 383.25

Parts: 67.84

Total: 451.09

6/30/2026
2:45:36 PM

Palm Beach County Fleet Management Asset Maintenance History
K11737 2006 CHEVROLET TRAILBLAZER Suv, Mid Size

Work Order: 2511467 **Meter:** 83311 **In Date:** 12/10/2025 **Closed:** 12/11/2025

Problem: Rear Passenger tire has nail employee will be their tomorrow morning for repair.

Work Completed

Parts Issued

Quantity

- Repair right rear tire and balance . Nitro fill all .
- Shop Supplies

Shop Supplies

1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

Total Hours: 266.60

Total Labor: 17,057.40

Total Comm: 137.95

Total Parts: 11,605.05