Workorder:	020600	10174392	0	FORD F250			-	Closed	05/19/2	000
	838699 PRE-DELIVE	Meter: ERY INSPE	-			In Date:	05/19/2008	Closed:	05/19/20	008
- Pre-delivery	Inspection									
	Hou :	urs 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	847815 P.M.SERVIC	Meter:	1372			In Date:	12/08/2008	Closed:	12/12/20	800
- Pm Service					Parts Li	ist				Qty
- Road Test					Shop Su	upplies				1.00
- Shop Suppli	es				1372 O	il Filter Frm	n Ph2 Wix 51	372		1.00
					5w20 Er	ngine Oil				7.00
					Used Fi	rex Refurbe	d Fire Extings	shers		1.00
	Hou :	urs 3.25		Labor:	195.00	Parts:	50.64	Total:	245.64	
Workorder: Problem:	940420 p.m.service	Meter:	2105			In Date:	07/07/2009	Closed:	07/10/2	009
- p.m.service					Parts Li	ist				Qty
- installed no	smoking deca	als			Shop Su	upplies				1.00
- Shop Suppli	es				1372 O	il Filter Frm	n Ph2 Wix 51	372		1.00
					5w20 Ei	ngine Oil				7.00
					31-20 W	/iper Blades	s 20" Blade			2.00
	Hou	urs 3.00		Labor:	180.00	Parts:	50.02	Total:	230.02	
Workorder: Problem:	1001245 P. M.	Meter:	2922			In Date:	02/03/2010	Closed:	02/09/2	010
- P. M.					Parts Li	ist				Qty
- Unseized hit	tch & lubed.				Shop Su	upplies				1.00
- Shop Suppli	es				1372 O	il Filter Frm	n Ph2 Wix 51	372		1.00
					5w20 Er	ngine Oil				8.00
					Used Fi	rex Refurbe	d Fire Extings	shers		1.00
	Hou :	urs 3.25		Labor:	195.00	Parts:	57.46	Total:	252.46	
Workorder: Problem:	1002543 SCREW IN 1	Meter: TIRE, TIRE	3066 LOSING A		(	In Date:	03/11/2010	Closed:	03/16/2	010
- C/c nail in R	/rear tire. disn	nount. patcl	h, mount, h	alance.	Parts Li	ist				Qty
- Shop Suppli		, <b>F</b>	, <u> </u>		Shop St					1.00
<b></b>		urs 1.00		Labor:		Parts:	2.00	Total:	62.00	
	:	10 1.00		Labol.	50.00	1 413.	2.00	rotal.	52.00	

Workorder:         1011894         Meter:         4137           Problem:         P. M. SERVICE	In Date: 10/25/2010 Closed: 10/28/20	010
- P. M. service.	Parts List	Qty
- Check all bolts on tool box.	Shop Supplies	1.00
- Strobe light assy on back window came loose. Remove	1372 Oil Filter Frm Ph2 Wix 51372	1.00
assy, repair brackets & reinstall.	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
- Shop Supplies	5w20 Engine Oil	8.00
Hours 5.75 Labor:	345.00         Parts: 50.07         Total: 395.07	
Workorder: 1107599 Meter: 5005 Problem: P. M. SERVICE	In Date: 07/20/2011 Closed: 07/22/20	011
- Performed P.m.	Parts List	Qty
- Straightened exhaust (damaged).	Shop Supplies	1.00
- R&r bulb for center stop. Repaired & cleaned connection	1372 Oil Filter Frm Ph2 Wix 51372	1.00
for back up lamp.	5w20 Engine Oil	8.00
- Retightened tool box legs.	Used Firex Refurbed Fire Extingshers	1.00
- Install driving decal.	31-20 Wiper Blades 20" Blade	2.00
- R&r and balanced 2 tires.	179636492 Lt245/75r17 Wrangler Sr-a E	2.00
- Shop Supplies	Tire Disposal Fee	2.00
Hours 6.75 Labor:	405.00 Parts: 439.72 Total: 844.72	
Workorder: 1204276 Meter: 5907 Problem: pm, ck battery had to jump it a couple of times	In Date: 05/04/2012 Closed: 05/25/20 , display show low tire pressure	012
<ul> <li>pm battery passed all test</li> </ul>	Parts List	Qty
<ul> <li>rr bulb for back up light repaired socket for tail light</li> </ul>	Shop Supplies	1.00
<ul> <li>repaired housing for strobe assy and wiring through pillar post</li> </ul>	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- unseized lubed hitch	5w20 Engine Oil	8.00
- rr balance two tires	31-20 Wiper Blades 20" Blade	2.00
- tire repair l rear	Used Firex Refurbed Fire Extingshers 3156 Wagner Bulb	1.00 1.00
- Shop Supplies	Tire Disposal Fee	2.00
	179636492 Lt245/75r17 Wrangler Sr-a E	2.00
Hours 7.75 Labor:	465.00         Parts:         464.39         Total:         929.39	2.00
Workorder:         1211513         Meter:         6378           Problem:         pm	In Date: 11/29/2012 Closed: 12/07/20	012
- pm	Parts List	Qtv
- pm - Shop Supplies	Parts List Ph2 Oil Filter Lbf Ph	<b>Qty</b> 1.00
- pm - Shop Supplies		-
	Ph2 Oil Filter Lbf Ph Ford Fuel Filter	1.00
	Ph2 Oil Filter Lbf Ph	1.00 1.00

Workorder: Problem:	1403270 battery	Meter:	9035			In Date:	04/03/2014	Closed:	04/08/20	)14
- ck dead bat	tery ck chargir	ng sys test l	pattery bac	replace	Parts L	ist				Qty
battery	, ,	0,	,	•	Battery					1.00
- Shop Suppli	ies				Shop St	upplies				1.00
	Hou	ırs 0.75		Labor:			121.61	Total:	166.61	
Workorder:	1406847	Meter:	10230			In Date:	07/11/2014	Closed:	08/07/20	)14
Problem:	P.M.SERVIC	E,NEEDS	SPOT MIR	RORS						
- pm					Parts L	ist				Qty
- clean mirror	and in stall sp	oot mirror			Napago	ld Oil Filter				1.00
- replace pint	le pin				Napa Q	uart 5w20				8.00
- repair both r	ont visor strot	be light and	back wind	seild strobe	Napago	ld Fuel Filte	r			1.00
light					Wiper B	lade				2.00
- repair 3rd bi	rake light and	utility bed li	ght		Used Fi	re X Refurb	ished			1.00
- repair left fro	ont tire				Washer	FI				1.00
- Shop Suppli	ies				Mirror					2.00
					Pintle P	in W/chain				1.00
					Divider					2.00
					Diode B	oard Ambei	ſ			2.00
					Amber L	_ed Module				1.00
					Circuit E	Board				1.00
					Shop Su	upplies				1.00
					Freight	Charge				1.00
	Hou :	ırs 9.50		Labor:	570.00	Parts:	593.86	Total:	1,163.86	6
Workorder: Problem:	1502367 screw in form	Meter: t dirvers tire	12409 e			In Date:	03/05/2015	Closed:	03/09/20	)15
- ck screw in	tire verify scre	w in rr tire s	side wall u	hable to	Parts L	ist				Qty
repair replace						492 Lt245-7	′5r17			1.00
- Shop Suppli	ies				Shop St		-			1.00
						posal Fee				1.00
	Hou	ırs 1.00		Labor:			263.52	Total:	323.52	
Workorder: Problem:	1502639 P.M.SERVIC	Meter:	12732			In Date:	03/13/2015	Closed:	03/20/20	)15
- pm					Parts L	ist				Qty
-	n rear tires and	d rotate to th	ne front			ld Oil Filter				1.00
- fill all tires w						uart 5w20				8.00
- Shop Suppli	-				Wiper B					2.00
Chop Ouppi					Washer					1.00
						Id Air Filter				1.00
						492 Lt245-7				2.00
					Shop Si		0117			1.00
						posal Fee				2.00
	Hai	ırs 4.75		l shar	285.00		578.24	Total	863.24	2.00
	:			Labor.	200.00	1 0113.	010.27	i otal.	000.24	

Problem:	1508891 pm	Meter:	13091		I	n Date:	09/03/2015	Closed:	09/14/20	015
- pm					Parts List					Qty
- Shop Suppli	ies				Napagold	Oil Filter				1.00
					Napa Qua	rt 5w20				8.00
					Shop Sup	plies				1.00
	Ho	ours 2.75		Labor:	165.00	Parts:	35.09	Total:	200.09	
Workorder: Problem:	1603378 rr turn lamp	Meter:	13477		l	n Date:	03/31/2016	Closed:	04/05/20	016
- Check right	tail light.repla	ace right reai	tail light bulb	).	Parts List					Qty
					Bulb					1.00
	Ho	ours 0.50		Labor:	30.00	Parts:	0.78	Total:	30.78	
Workorder: Problem:	1603478 P.M.SERVI	Meter: CE,FLOOR I	13485 MAT,HESITA	TES WHE		n Date: NG,R/REA	04/01/2016 R TAIL LIGH	<b>Closed:</b> T BROKEN	04/20/20	016
- Pm service.					Parts List					Qty
- Replace dar	mage right re	ar lens.			Napagold	Oil Filter				1.00
- Replace wor	rn out body n	nounts.			Napa Qua	rt 5w20				8.00
- Install steeri	na wheel cov	ver floor mate	s and how is i	mv		Blada				0.00
driving atickar				iiiy	20" Wiper					
•				-	Washer Fl	uid Conce				1.00
driving sticker. - Replace and	d rekey new i	ignition lock/	cylinder to vin	n number.	Washer Fl Napagold	uid Conce Fuel Filte	r			1.00 1.00
- Replace and - Computer di	d rekey new i iagnose for ti	ignition lock/o	cylinder to vin concern.no co	n number. odes	Washer Fl Napagold Used Fire	uid Conce Fuel Filte	r			1.00 1.00 1.00
- Replace and - Computer di found.check fo	d rekey new i iagnose for ti	ignition lock/o	cylinder to vin concern.no co	n number. odes	Washer Fl Napagold Used Fire Bulb	uid Conce Fuel Filte X Refurbi	r			1.00 1.00 1.00 2.00
- Replace and - Computer di found.check fo	d rekey new i iagnose for tr or updates ar	ignition lock/o	cylinder to vin concern.no co	n number. odes	Washer Fl Napagold Used Fire Bulb Lamp Asy	uid Conce Fuel Filte X Refurbi	r			1.00 1.00 1.00 2.00
- Replace and - Computer di found.check fo roadtest.	d rekey new i iagnose for tr or updates ar	ignition lock/o	cylinder to vin concern.no co	n number. odes	Washer Fl Napagold Used Fire Bulb Lamp Asy Body Mou	uid Conce Fuel Filte X Refurbi nt Kit	r			2.00 1.00 1.00 2.00 1.00 2.00
- Replace and - Computer di found.check fo roadtest.	d rekey new i iagnose for tr or updates ar	ignition lock/o	cylinder to vin concern.no co	n number. odes	Washer Fl Napagold Used Fire Bulb Lamp Asy Body Mou Body Mou	uid Conce Fuel Filte X Refurbi nt Kit	r			1.00 1.00 2.00 1.00 2.00 4.00
- Replace and - Computer di found.check fo roadtest.	d rekey new i iagnose for tr or updates ar	ignition lock/o	cylinder to vin concern.no co	n number. odes	Washer Fl Napagold Used Fire Bulb Lamp Asy Body Mou Body Mou Floor Mat	uid Conce Fuel Filte X Refurbi nt Kit nt Kit	r ished			1.00 1.00 2.00 1.00 2.00 4.00
- Replace and - Computer di found.check fo roadtest.	d rekey new i iagnose for tr or updates ar	ignition lock/o	cylinder to vin concern.no co	n number. odes	Washer Fl Napagold Used Fire Bulb Lamp Asy Body Mou Body Mou Floor Mat Stg Wheel	uid Conce Fuel Filte X Refurbi nt Kit nt Kit I Cov - Fo	r ished			1.00 1.00 2.00 1.00 2.00 4.00 1.00
- Replace and - Computer di found.check fo roadtest.	d rekey new i iagnose for tr or updates ar	ignition lock/o	cylinder to vin concern.no co	n number. odes	Washer Fl Napagold Used Fire Bulb Lamp Asy Body Mou Body Mou Floor Mat Stg Wheel Ingition Lo	uid Conce Fuel Filte X Refurbi nt Kit nt Kit I Cov - Fo ock	r ished rd			1.00 1.00 2.00 1.00 2.00 4.00 1.00 1.00
- Replace and - Computer di found.check fo roadtest.	d rekey new i iagnose for tr or updates ar	ignition lock/o	cylinder to vin concern.no co	n number. odes	Washer Fl Napagold Used Fire Bulb Lamp Asy Body Mou Body Mou Floor Mat Stg Wheel Ingition Lo Floor Mat	uid Conce Fuel Filte X Refurbi nt Kit nt Kit I Cov - Fo ck 2pc Rub I	r ished rd			1.00 1.00 2.00 1.00 2.00 4.00 1.00 1.00
- Replace and - Computer di found.check fo roadtest.	d rekey new i iagnose for tr or updates ar	ignition lock/o	cylinder to vin concern.no co	n number. odes	Washer Fl Napagold Used Fire Bulb Lamp Asy Body Mou Body Mou Floor Mat Stg Wheel Ingition Lo Floor Mat- Blades De	uid Conce Fuel Filte X Refurbi nt Kit nt Kit I Cov - Fo ock 2pc Rub I ewalt	r ished rd			1.00 1.00 2.00 1.00 2.00 4.00 1.00 1.00 1.00 1.00
- Replace and - Computer di found.check fo roadtest.	d rekey new i iagnose for tr or updates ar	ignition lock/o	cylinder to vin concern.no co	n number. odes	Washer Fl Napagold Used Fire Bulb Lamp Asy Body Mou Body Mou Floor Mat Stg Wheel Ingition Lo Floor Mat- Blades De Friction Mat	uid Conce Fuel Filte X Refurbi nt Kit nt Kit I Cov - Fo ock 2pc Rub I ewalt odifier	r ished rd			1.00 1.00 2.00 1.00 2.00 4.00 1.00 1.00 1.00 1.00
- Replace and - Computer di found.check fo roadtest.	d rekey new i iagnose for tr or updates ar	ignition lock/o	cylinder to vin concern.no co	n number. odes and	Washer Fl Napagold Used Fire Bulb Lamp Asy Body Mou Body Mou Floor Mat Stg Wheel Ingition Lo Floor Mat- Blades De	uid Conce Fuel Filte X Refurbi nt Kit nt Kit Cov - Fo ock 2pc Rub I ovalt odifier plies	r ished rd		1,699.93	1.00 1.00 2.00 1.00 2.00 1.00 1.00 1.00

	1701424 PM Service.D	Meter: ead batter	14002 y.			In Date:	02/10/2017	Closed:	02/21/20	017
- Pm Service.					Parts Li	st				Qty
- C/c Dead bat	tery.test batte	ry bad.che	ck charging		Halogen	Lamp				2.00
system.replace	•				Napagol	d Oil Filter				1.00
- Repair right r N2.relearn Tpm		balance a	II.add N2.corr	ect	Napa Qu	art 5w20				8.00
- Verify both he		condens	ation r&r 2 hea	dliaht	20" Wipe	er Blade				2.00
assm.	sadiigino nave	Condense		langin	Used Fir	e X Refurb	ished			1.00
- Verify washe blades.	r fluid not spra	iying.repai	r sprayers.r&r	wiper	Battery Shop Su	pplies				1.00 1.00
- Shop Supplie	)S									
	Hour :	s 7.50		Labor:	450.00	Parts:	207.13	Total:	657.13	
	1707743 PM Service	Meter:	14609			In Date:	08/08/2017	Closed:	08/21/20	)17
- Pm Service.					Parts Li	st				Qty
- Replace left r	rear tire.balan	ce all four	tires.rotate the	e best	Napagol	d Oil Filter				1.00
ones to the fror	•				Napa Qu	art 5w20				8.00
- Replace corre		cketand p	ntle pin.		20" Wipe	er Blade				2.00
- Repair right r	-				Napagol	d Fuel Filte	r			1.00
- Shop Supplie	÷S				Napagol	d Air Filter				1.00
						Fluid Conc	entr			1.00
					Pintle Pi	•				1.00
					trailer plu	g				1.00
					Bulb		. 1			2.00
						Silcn Sealar				1.00
					Shop Su	92 Lt245-7	500			1.00 1.00
					-					1.00
	Hour	s 7.75		Labor.	465.00	osal Fee Parts:	339.21	Total	804.21	1.00
	:	3 1.15		Labor.	403.00	1 arts.	555.21		004.21	
	1801845 PM Service	Meter:	15301			In Date:	02/16/2018	Closed:	02/26/20	018
- Pm Service					Parts Li	st				Qty
- Replace right		lamp bulb	and repaired a	and	Used Fir	e X Refurb	ished			1.00
clean socket.re		~~				d Oil Filter				1.00
- Rotate and ba		38.			Drain Plu	•				1.00
- Shop Supplie	:5				•	art 5w20				8.00
					20" Wipe					2.00
						Fluid Conc	entr			1.00
										4 0 0
					Bulb					
		s 4.25			Bulb Shop Su 255.00		64.90		319.90	1.00 1.00

Workorder: Problem:	1803606 Damage to rig	Meter: ht rear fer	15301 nder & right f	ront fende	r	In Date:	03/20/2018	Closed:	04/05/2018
- Damage to r	right rear fende	r & right fr	ont fender						
	Hour :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1811614 PM Service.	Meter:	15447			In Date:	11/13/2018	Closed:	11/30/2018
- Pm Service					Parts L	.ist			Qt
- Repair right	rear turnsignal				Napa C	Quart 5w20			8.0
- Check and r	eplace bad bat	tery.			Napago	old Oil Filter			1.0
- Shop Suppli	es				Washe	r Fluid Conce	entr		1.0
					22" Wip	oer Blade			2.0
					Boxed	Miniatures			1.0
					Battery				1.0
					Shop S	upplies			1.0
	Hour :	s 4.00		Labor:	268.00	Parts:	181.13	Total:	449.13
Workorder: Problem:	1905195 PM Service.	Meter:	16031			In Date:	05/14/2019	Closed:	05/29/2019
- Pm Service.					Parts L	.ist			Qt
- Repaired fro	ont head light				Napago	old Oil Filter			1.0
- Shop Suppli	es				Napa C	Quart 5w20			8.0
					22" Wip	oer Blade			2.0
					Washe	r Fluid Conce	entr		1.0
					Napago	old Fuel Filte	r		1.0
					Napago	old Air Filter			1.0
					Used F	ire X Refurbi	ished		1.0
					Haloge	n Sealed Be	ams		1.0
					Shop S	upplies			1.0
	Hour :	s 3.75		Labor:	251.25	Parts:	90.92	Total:	342.17
Workorder: Problem:	1906239 remove cance	Meter:	16139			In Date:	06/13/2019	Closed:	06/17/2019
- Remove car	nceiver				Parts L	.ist			Qt
- Shop Suppli	es				Shop S	upplies			1.0
	Hour :	s 1.00		Labor:	67.00	Parts:	3.00	Total:	70.00

	1911811	Meter:	16960			In Date:	11/14/2019	Closed:	11/25/2019
	P.M.SERVICE	, HESITAT	EIUSIARI	SOME	IMES				
- Pm Service.					Parts Lis				C
- Repair left r	everse light and	replace b	ulb.		Napa Qu	art 5w20			8.
- Replace bot	h rear shocks.				Napagolo	d Oil Filter			1.
	to start some ti		tarting and wa	as	Washer F	Fluid Conce	entr		1.
	fy concern at thi	s time.			22" Wipe	r Blade			2.
- Shop Suppl	les				Boxed M	iniatures			1.
					Gas Grar	nde Shock			2.
					Shop Sup	oplies			1.
	Hours :	\$ 5.25		Labor:	383.25	Parts:	169.75	Total:	553.00
Workorder: Problem:	2001609 Brakes locking	<b>Meter:</b> Jup. See n	17319 otes.			In Date:	02/14/2020	Closed:	02/28/2020
- Resurface f	ront and rear rot	tors.replac	e calipers and	t	Parts Lis	st			G
pads.flush bra	ike system.				Non-chlo	r Brake Clr	nr		2.
- Test drive b	efore and after i	repairs.			B Fluid D	ot 3-32oz			1.
- Shop Suppl	ies				Brake Pa	d			1.
					Caliper w	/ Hardware	e - Left Rear (	(eclipse	1.
					Caliper w	/ Hardware	e - Right Rea	r (eclips	1.
					Brake Pa	d			1.
					Caliper w	/ Hardware	e - Right Fron	t (eclip	1.
					Caliper w	/ Hardware	e - Left Front	(eclips	1.
					Shop Su	oplies			1.
	Hours	s 11.00		Lobor	803.00	Dorto:	464.47	Total <sup>.</sup>	1,267.47
				Labor.	003.00	Faits.	404.47	i otal.	1,207.47
	2005244 P.M.SERVICE	Meter:	17504			In Date:	05/26/2020	Closed:	06/09/2020
	: 2005244 P.M.SERVICE	Meter:	17504			In Date:	_		06/09/2020
Problem: - Pm Service.	: 2005244 P.M.SERVICE	Meter:				In Date:	_		
Problem: - Pm Service. - Replace driv	2005244 P.M.SERVICE	Meter:			<b>Parts Lis</b> Napa Qu	In Date: at art 5w20	_		06/09/2020 G
Problem: - Pm Service. - Replace driv cylinder	2005244 P.M.SERVICE	Meter:	embly and loc		<b>Parts Lis</b> Napa Qu Napagolo	In Date:	05/26/2020		06/09/2020 C 8.
- Pm Service. - Replace driv cylinder	2005244 P.M.SERVICE ver outer door h	Meter:	embly and loc		<b>Parts Lis</b> Napa Qu Napagolo	In Date: at art 5w20 d Oil Filter Fluid Conce	05/26/2020		06/09/2020 C 8. 1.
Problem: - Pm Service. - Replace driv cylinder - Replace 6 w	2005244 P.M.SERVICE ver outer door h vay socket and v	Meter:	embly and loc		<b>Parts Lis</b> Napa Qu Napagolo Washer F 22" Wipe	In Date: at art 5w20 d Oil Filter Fluid Conce	05/26/2020 entr		06/09/2020 C 8. 1. 1.
Problem: - Pm Service. - Replace driv cylinder - Replace 6 w - Replace left - Service batt	2005244 P.M.SERVICE ver outer door h vay socket and v	Meter: andle asse	embly and loc less.		Parts Lis Napa Qu Napagolo Washer F 22" Wipe Napagolo	In Date: at art 5w20 d Oil Filter Fluid Conce r Blade	05/26/2020 entr		06/09/2020 8. 1. 1. 2.
Problem: - Pm Service. - Replace driv cylinder - Replace 6 w - Replace left - Service both	2005244 P.M.SERVICE ver outer door h vay socket and v sun visor kit. ery cables	Meter: andle asse	embly and loc less.		Parts Lis Napa Qu Napagolo Washer F 22" Wipe Napagolo	In Date: art 5w20 d Oil Filter Fluid Conce r Blade d Fuel Filte e X Refurbi	05/26/2020 entr		06/09/2020 8. 1. 1. 2. 1.
Problem: - Pm Service. - Replace driv cylinder - Replace 6 w - Replace left - Service both	2005244 P.M.SERVICE ver outer door h vay socket and v sun visor kit. ery cables n tool boxes to c balance 4 tires.	Meter: andle asse	embly and loc less.		Parts Lis Napa Qu Napagolo Washer F 22" Wipe Napagolo Used Fire	In Date: art 5w20 d Oil Filter Fluid Conce r Blade d Fuel Filte e X Refurbi	05/26/2020 entr		06/09/2020 8. 1. 1. 2. 1. 1.
Problem: - Pm Service. - Replace driv cylinder - Replace 6 w - Replace left - Service batt - Service bott - Rotate and - Repaired rig	2005244 P.M.SERVICE ver outer door h vay socket and v sun visor kit. ery cables n tool boxes to c balance 4 tires.	Meter: andle asse wiring harn close prope	embly and loc less. erly.		Parts Lis Napa Qu Napagolo Washer F 22" Wipe Napagolo Used Fire Handle A	In Date: art 5w20 d Oil Filter Fluid Conce r Blade d Fuel Filte e X Refurbi	05/26/2020 entr		06/09/2020 8. 1. 1. 2. 1. 1. 1.
Problem: - Pm Service. - Replace driv cylinder - Replace 6 w - Replace left - Service batt - Service batt - Rotate and - Repaired rig - Scanned an - Cleaned en	2005244 P.M.SERVICE ver outer door h vay socket and v sun visor kit. ery cables n tool boxes to c balance 4 tires. ght front tire. d clear gas cap gine compartme	Meter: andle asse wiring harn close prope	embly and loc less. erly.		Parts Lis Napa Qu Napagolo Washer F 22" Wipe Napagolo Used Fire Handle A trailer plu	In Date: art 5w20 d Oil Filter Fluid Conce r Blade d Fuel Filte e X Refurbi sy	05/26/2020 entr		06/09/2020 <b>C</b> 8. 1. 1. 2. 1. 1. 1. 1. 1. 1.
Problem: - Pm Service. - Replace driv cylinder - Replace 6 w - Replace left - Service batt - Service bott - Rotate and l - Repaired rig - Scanned an	2005244 P.M.SERVICE ver outer door h vay socket and v sun visor kit. ery cables n tool boxes to c balance 4 tires. ght front tire. id clear gas cap gine compartme	Meter: andle asse wiring harn close prope	embly and loc less. erly.	k	Parts Lis Napa Qu Napagolo Washer F 22" Wipe Napagolo Used Fire Handle A trailer plu Retainer	In Date: art 5w20 d Oil Filter Fluid Conce r Blade d Fuel Filte e X Refurbit sy g	05/26/2020 entr	Closed:	06/09/2020 C 8. 1. 1. 2. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
Problem: - Pm Service. - Replace driv cylinder - Replace 6 w - Replace left - Service batt - Service batt - Rotate and - Repaired rig - Scanned and - Cleaned eng - Shop Suppli	2005244 P.M.SERVICE ver outer door h vay socket and v sun visor kit. ery cables n tool boxes to c balance 4 tires. ght front tire. d clear gas cap gine compartme ies Hours : 2011899	Meter: andle asse wiring harn close prope loose code ent. s 12.75 Meter:	embly and loc less. erly.	k	Parts Lis Napa Qu Napagolo Washer F 22" Wipe Napagolo Used Fire Handle A trailer plu Retainer Shop Sup 930.75	In Date: art 5w20 d Oil Filter Fluid Conce r Blade d Fuel Filte e X Refurbit sy g	05/26/2020 entr r ished	Closed:	06/09/2020 8. 1. 1. 2. 1. 1. 1. 1. 1. 1. 1. 1. 1.
Problem: - Pm Service. - Replace driv cylinder - Replace 6 w - Replace left - Service batt - Service bott - Rotate and - Repaired rig - Scanned an - Cleaned eng - Shop Suppli Workorder: Problem:	2005244 P.M.SERVICE ver outer door h vay socket and v sun visor kit. ery cables n tool boxes to c balance 4 tires. ght front tire. d clear gas cap gine compartme ies Hours 2011899 Transition Prep	Meter: andle asse wiring harn close prope loose code ent. s 12.75 Meter:	embly and loc less. erly. e.	k	Parts Lis Napa Qu Napagolo Washer F 22" Wipe Napagolo Used Fire Handle A trailer plu Retainer Shop Sup 930.75	In Date: art 5w20 d Oil Filter Fluid Conce r Blade d Fuel Filte e X Refurbi sy 9 oplies Parts:	05/26/2020 entr r ished 168.79	Closed:	06/09/2020 8. 1. 1. 2. 1. 1. 1. 1. 1. 1. 1. 1. 099.54
Problem: - Pm Service. - Replace driv cylinder - Replace 6 w - Replace left - Service batt - Service batt - Rotate and - Repaired rig - Scanned and - Cleaned eng - Shop Suppli	: 2005244 P.M.SERVICE ver outer door h vay socket and w sun visor kit. ery cables n tool boxes to c balance 4 tires. ght front tire. d clear gas cap gine compartme ies Hours : 2011899 Transition Prep Prep Charge	Meter: andle asse wiring harn close prope loose code ent. s 12.75 Meter:	embly and loc less. erly. e.	k Labor:	Parts Lis Napa Qu Napagolo Washer F 22" Wipe Napagolo Used Fire Handle A trailer plu Retainer Shop Sup 930.75	In Date: art 5w20 d Oil Filter Fluid Conce r Blade d Fuel Filte e X Refurbi sy 9 oplies Parts:	05/26/2020 entr r ished 168.79 12/01/2020	Closed: Total: Closed:	06/09/2020 8. 1. 1. 2. 1. 1. 1. 1. 1. 1. 1. 1. 099.54