Workorder:	1405229	Meter:	334			In Date:	05/29/2014	Closed:	05/29/2014
	1061 - Pre De					in Date.	03/23/2014	010360.	03/23/2014
- Pre Delivery	Inspection								
	Hou	rs 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00
Workorder: Problem:	1405767 Install strobe	Meter: lights.	360		l	In Date:	06/11/2014	Closed:	06/17/2014
	d install four c				Parts Lis	t			Qt
	for power and		stall lighte	d switch and	Vtx609c L	ed Strobe	Cl		2.0
fuse holder to protect circuit. - Shop Supplies				Vtx609a L	ed Strobe	e Am		2.00	
	00				Switch				1.00
					Fuse Hold	der			1.00
					Brake Ca	liper Boot	An		1.00
					Clr Rtv Si	lcn Sealar	nt		1.00
					Floor Mat	-2pc Rub	Bk		1.0
					Fab Loom	n-split Poly	/		25.0
					Shop Sup	plies			1.0
	Hour	rs 8.00		Labor:	480.00	Parts:	551.17	Total:	1,031.17
Workorder: Problem:	1410371	Meter:	4534			In Date:	10/16/2014	Closed:	10/17/2014
	Nall through t	igni iear in	e.						
	-	•			Parts Lis	t			Qt
- Repair flat a	nd balance rig	•							<b>Qt</b> 1.00
	nd balance rig es	•		Labor:	Shop Sup		2.00	Total:	-
- Repair flat a - Shop Suppli Workorder:	nd balance rig es	ht rear tire.		Labor:	Shop Sup 60.00	plies	2.00 11/14/2014	Total: Closed:	1.00
- Repair flat a - Shop Suppli Workorder:	nd balance rig es Hour : 1411404	ht rear tire.		Labor:	Shop Sup 60.00	plies Parts: In Date:			62.00
<ul> <li>Repair flat a</li> <li>Shop Suppli</li> <li>Workorder: Problem:</li> <li>Pm service.</li> </ul>	nd balance rig es Hour : 1411404	ht rear tire. rs 1.00 Meter:		Labor:	Shop Sup 60.00	plies Parts: In Date:			1.00 62.00 11/25/2014
<ul> <li>Repair flat a</li> <li>Shop Suppli</li> <li>Workorder: Problem:</li> <li>Pm service.</li> <li>Rotate and b</li> </ul>	nd balance rig es Hou : 1411404 Pm service	ht rear tire. rs 1.00 <b>Meter:</b> r tires.		Labor:	Shop Sup 60.00 Parts Lis	pplies Parts: In Date: t jine Oil			1.00 62.00 11/25/2014 Qty 6.00
<ul> <li>Repair flat a</li> <li>Shop Suppli</li> <li>Workorder: Problem:</li> <li>Pm service.</li> <li>Rotate and b</li> </ul>	nd balance rig es Hou 1411404 Pm service palance all fou service winch.	ht rear tire. rs 1.00 <b>Meter:</b> r tires.		Labor:	Shop Sup 60.00 Parts Lis 5w20 Eng	pplies Parts: In Date: t jine Oil Oil Filter	11/14/2014		1.00 62.00 11/25/2014 Qty 6.00 1.00
<ul> <li>Repair flat a</li> <li>Shop Suppli</li> <li>Workorder: Problem:</li> <li>Pm service.</li> <li>Rotate and b</li> <li>Inspect and</li> </ul>	nd balance rig es Hou 1411404 Pm service palance all fou service winch.	ht rear tire. rs 1.00 <b>Meter:</b> r tires.		Labor:	Shop Sup 60.00 Parts Lis 5w20 Eng Napagold	plies Parts: In Date: t jine Oil Oil Filter X Refurb	11/14/2014 ished		1.00 62.00 11/25/2014 <b>Qt</b> 6.00 1.00 1.00
<ul> <li>Repair flat a</li> <li>Shop Suppli</li> <li>Workorder: Problem:</li> <li>Pm service.</li> <li>Rotate and b</li> <li>Inspect and</li> </ul>	nd balance rig es Hou 1411404 Pm service palance all fou service winch.	ht rear tire. rs 1.00 <b>Meter:</b> r tires.		Labor:	Shop Sup 60.00 Parts Lis 5w20 Eng Napagold Used Fire	plies Parts: In Date: In Date:	11/14/2014 ished		1.00 62.00 11/25/2014 Qt
<ul> <li>Repair flat a</li> <li>Shop Suppli</li> <li>Workorder: Problem:</li> <li>Pm service.</li> <li>Rotate and b</li> <li>Inspect and</li> </ul>	nd balance rig es Hou 1411404 Pm service palance all fou service winch.	ht rear tire. rs 1.00 <b>Meter:</b> r tires.		Labor:	Shop Sup 60.00 Parts Lis 5w20 Eng Napagold Used Fire Stg Whee	plies Parts: In Date: t jine Oil Oil Filter X Refurb I Cov - Fo Protector	11/14/2014 ished		1.00 62.00 11/25/2014 <b>Qty</b> 6.00 1.00 1.00

Workorder: Problem:	1504266 Pm service	Meter: and right rea	9932 ar turnsigna	al light inop.S		<b>n Date:</b> II #14C10	04/24/2015	Closed:	05/07/20	015
- Pm service.					Parts List	t				Qty
- Rotate and I	balance all fo	our tires.			5w20 Eng					6.00
- Inspect and		Napagold	Oil Filter				1.00			
- Transport ve 14c10	ehicle to and	from dealer	for safety r	ecall #	Shop Sup	plies				1.00
- Shop Suppli	es									
	Hc	ours 6.00		Labor:	360.00	Parts:	21.19	Total:	381.19	
Workorder: Problem:	1506470 1 - Wash tio	Meter: cket(s) issued	12213 d		I	n Date:	06/29/2015	Closed:	06/29/20	015
- 1 - Wash tic	ket(s) issued									
	Ho :	ours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1507001 Replace rig	Meter: ht rear tire.	13050		I	n Date:	07/14/2015	Closed:	07/21/20	015
- Replace and	d balance rig	ht rear tire.			Parts List	t				Qty
- Shop Supplies					Hankook P235 75r17 Dp At					1.00
					Shop Sup					1.00
					Tire Dispo	sal Fee				1.00
	Hc :	ours 0.50		Labor:	30.00	Parts:	220.09	Total:	250.09	
	: 1507167 Flat tire on	<b>Meter:</b> r/r dismount				Parts: n Date:	220.09 07/14/2015	Total: Closed:	250.09 07/17/20	015
Problem: - Tire Service	: 1507167 Flat tire on Tamarind A	<b>Meter:</b> r/r dismount	Spare							015
Problem:	: 1507167 Flat tire on Tamarind A t Spare	<b>Meter:</b> r/r dismount	Spare		1		07/14/2015		07/17/20	015
Problem: - Tire Service on r/r dismour Workorder:	: 1507167 Flat tire on Tamarind A t Spare	Meter: r/r dismount ve block Nor ours 0.00 Meter:	Spare	es - Flat tire	0.00	n Date:	07/14/2015	Closed:	07/17/20	
Problem: - Tire Service on r/r dismour Workorder:	: 1507167 Flat tire on Tamarind A Tamarind A t Spare Ho : 1509826 Right front t	Meter: r/r dismount ve block Nor ours 0.00 Meter: tire flat.	Spare th of Pblak	es - Flat tire	0.00	n Date: Parts: n Date:	07/14/2015	Closed: Total:	07/17/20	015
Problem: - Tire Service on r/r dismour Workorder: Problem:	: 1507167 Flat tire on Tamarind A Tamarind A Tamarind A Tamarind A Ho to Tamarind A Ho Tamarind A Ho Tamarind A Ho to Tamarind A Ho to Tamarind A Ho Tamarinda Ho Tamarinda Ho Tamarinda Ho Tamarinda Ho Tamarinda Ho Tamarinda Ho to Tamarinda Ho to Tamarinda Ho to Tamarinda Ho to Tamarinda Ho to Tamarinda Ho to Tamarinda Ho to Tamarinda Ho to Tamarinda Ho to Tamarinda Ho to Tamarinda Ho to Tamarinda Ho to Tamarinda Ho to Tamarinda Ho to Tamarinda Ho to Tamarinda Ho to Tamarinda Ho to Tamarinda Ho	Meter: r/r dismount ve block Nor ours 0.00 Meter: tire flat.	Spare th of Pblak	es - Flat tire	0.00	n Date: Parts: n Date:	07/14/2015	Closed: Total:	07/17/20	
Problem: - Tire Service on r/r dismour Workorder: Problem: - Repair and I	: 1507167 Flat tire on Tamarind Ar t Spare Ho : 1509826 Right front t balance right	Meter: r/r dismount ve block Nor ours 0.00 Meter: tire flat.	Spare th of Pblak	es - Flat tire	0.00 Parts List Shop Sup	n Date: Parts: n Date:	07/14/2015 0.00 09/29/2015	Closed: Total: Closed:	07/17/20	015 Qty
Problem: - Tire Service on r/r dismour Workorder: Problem: - Repair and I - Shop Suppli Workorder:	: 1507167 Flat tire on Tamarind Ar t Spare Ho : 1509826 Right front t balance right	Meter: r/r dismount ve block Nor ours 0.00 Meter: tire flat. front tire. ours 1.00 Meter:	Spare th of Pblak	es - Flat tire Labor:	0.00 I Parts List Shop Sup 60.00	n Date: Parts: n Date: t plies	07/14/2015 0.00 09/29/2015	Closed: Total: Closed:	07/17/20	015 <b>Qty</b> 1.00
Problem: - Tire Service on r/r dismour Workorder: Problem: - Repair and I - Shop Suppli Workorder: Problem:	: 1507167 Flat tire on Tamarind Ar Tamarind Ar t Spare Ho 1509826 Right front t balance right tes Ho 1510001	Meter: r/r dismount ve block Nor ours 0.00 Meter: tire flat. front tire. ours 1.00 Meter:	Spare th of Pblak 16310	es - Flat tire Labor:	0.00 I Parts List Shop Sup 60.00	n Date: Parts: n Date: t plies Parts: n Date:	07/14/2015 0.00 09/29/2015 2.00	Closed: Total: Closed: Total:	07/17/20 0.00 09/30/20 62.00	015 <b>Qty</b> 1.00
Problem: - Tire Service on r/r dismour Workorder: Problem: - Repair and R - Shop Suppli Workorder: Problem: - Pm service.	: 1507167 Flat tire on Tamarind An t Spare Ho 1509826 Right front t balance right es Ho 1510001 Pm service.	Meter: r/r dismount ve block Nor ours 0.00 Meter: tire flat. front tire. ours 1.00 Meter:	Spare th of Pblak 16310	es - Flat tire Labor:	0.00 I Parts List Shop Sup 60.00 I Parts List	n Date: Parts: n Date: t plies Parts: n Date:	07/14/2015 0.00 09/29/2015 2.00	Closed: Total: Closed: Total:	07/17/20 0.00 09/30/20 62.00	015 Qty 1.00 015 Qty
Problem: - Tire Service on r/r dismour Workorder: Problem: - Repair and I - Shop Suppli Workorder: Problem:	: 1507167 Flat tire on Tamarind An t Spare Ho 1509826 Right front t balance right ies Ho 1510001 Pm service.	Meter: r/r dismount ve block Nor ours 0.00 Meter: tire flat. front tire. ours 1.00 Meter: h.	Spare th of Pblak 16310	es - Flat tire Labor:	0.00 I Parts List Shop Sup 60.00 I Parts List 5w20 Eng	n Date: Parts: n Date: t plies Parts: n Date: t time Oil	07/14/2015 0.00 09/29/2015 2.00	Closed: Total: Closed: Total:	07/17/20 0.00 09/30/20 62.00	015 Qty 1.00 015 Qty 6.00
Problem: - Tire Service on r/r dismour Workorder: Problem: - Repair and I - Shop Suppli Workorder: Problem: - Pm service. - Inspect and	: 1507167 Flat tire on Tamarind Ar Tamarind Ar t Spare Ho 1509826 Right front t balance right es Ho 1510001 Pm service. service winc	Meter: r/r dismount ve block Nor ours 0.00 Meter: tire flat. front tire. ours 1.00 Meter: h.	Spare th of Pblak 16310	es - Flat tire Labor:	0.00 I Parts List Shop Sup 60.00 I Parts List	n Date: Parts: n Date: t plies Parts: n Date: t ine Oil Oil Filter	07/14/2015 0.00 09/29/2015 2.00	Closed: Total: Closed: Total:	07/17/20 0.00 09/30/20 62.00	015 Qty 1.00 015 Qty 6.00 1.00
Problem: - Tire Service on r/r dismour Workorder: Problem: - Repair and R - Shop Suppli Workorder: Problem: - Pm service. - Inspect and R	: 1507167 Flat tire on Tamarind Ar Tamarind Ar t Spare Ho 1509826 Right front t balance right es Ho 1510001 Pm service. service winc	Meter: r/r dismount ve block Nor ours 0.00 Meter: tire flat. front tire. ours 1.00 Meter: h.	Spare th of Pblak 16310	es - Flat tire Labor:	0.00 I Parts List Shop Sup 60.00 I Parts List 5w20 Eng Napagold	n Date: Parts: n Date: n Date: plies Parts: n Date: t ine Oil Oil Filter de	07/14/2015 0.00 09/29/2015 2.00 10/01/2015	Closed: Total: Closed: Total:	07/17/20 0.00 09/30/20 62.00	015 Qty 1.00 015 Qty 6.00 1.00 2.00
Problem: - Tire Service on r/r dismour Workorder: Problem: - Repair and R - Shop Suppli Workorder: Problem: - Pm service. - Inspect and R	: 1507167 Flat tire on Tamarind Ar Tamarind Ar t Spare Ho 1509826 Right front t balance right es Ho 1510001 Pm service. service winc	Meter: r/r dismount ve block Nor ours 0.00 Meter: tire flat. front tire. ours 1.00 Meter: h.	Spare th of Pblak 16310	es - Flat tire Labor:	0.00 I Parts List Shop Sup 60.00 I Parts List 5w20 Eng Napagold Wiper Bla	n Date: Parts: n Date: n Date: Parts: n Date: n Date: t ine Oil Oil Filter de luid Conce	07/14/2015 0.00 09/29/2015 2.00 10/01/2015	Closed: Total: Closed: Total:	07/17/20 0.00 09/30/20 62.00	015 <b>Qty</b> 1.00
Problem: - Tire Service on r/r dismour Workorder: Problem: - Repair and R - Shop Suppli Workorder: Problem: - Pm service. - Inspect and R	: 1507167 Flat tire on Tamarind Ar Tamarind Ar t Spare Ho 1509826 Right front t balance right es Ho 1510001 Pm service. service winc	Meter: r/r dismount ve block Nor ours 0.00 Meter: tire flat. front tire. ours 1.00 Meter: h.	Spare th of Pblak 16310	es - Flat tire Labor:	0.00 I Parts List Shop Sup 60.00 I Parts List 5w20 Eng Napagold Wiper Bla Washer F	n Date: Parts: n Date: n Date: plies Parts: n Date: t ine Oil Oil Filter de luid Conce Air Filter	07/14/2015 0.00 09/29/2015 2.00 10/01/2015	Closed: Total: Closed: Total:	07/17/20 0.00 09/30/20 62.00	015 Qty 1.00 015 015 015 0.00 1.00 2.00 1.00

Palm Beach County Fleet Management
Asset Maintenance History

Workorder: Problem:	1602284 P.M. Service.	Meter:	21498			In Date:	03/03/2016	Closed:	03/14/20	16
- Pm service.					Parts Lis	st				Qty
- Inspect and	service power	winch.			5w20 En	gine Oil				6.00
- Replace two	tires.rotate ar	nd balance	all four.		Napagolo	d Oil Filter				1.00
- Perform con	nplete wheel a	lignment.			22" Wipe	r Blade				2.00
- Shop Suppli	es				Used Fire	e X Refurbi	shed			1.00
					Mac Batt	ery Protect				1.00
					Macs Ch	ain Cable L	_ube			1.00
					Hankook	P235 75r1	7 Dp At			2.00
					Shop Su	pplies				1.00
					Tire Disp	osal Fee				2.00
	Hou :	rs 7.50		Labor:	450.00	Parts:	488.37	Total:	938.37	
Workorder: Problem:	1606831 1 - Wash tick	Meter: et(s) issued	26787 1			In Date:	07/07/2016	Closed:	07/07/20	16
- 1 - Wash tic	ket(s) issued									
	Hou :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1607026 P.M. Service.	Meter:	27473			In Date:	07/12/2016	Closed:	07/25/20	16
- P.m. Service	Э.				Parts Lis	st				Qty
- Rotate and I	palance all tire	s.			5w20 En	gine Oil				6.00
- Inspect and	service winch.				Napagolo	d Oil Filter				1.00
- Shop Suppli	es				22" Wipe	r Blade				2.00
					Shop Su	pplies				1.00
	Hou :	rs 4.00		Labor:	240.00	Parts:	24.77	Total:	264.77	
Workorder: Problem:	1613048 P.M. Service.	Meter: Right rear	32889 tire flat.			In Date:	12/27/2016	Closed:	01/03/20	17
	2				Parts Lis	st				Qty
- P.m. Service			a all four		5w20 En					6.00
	ee tires,rotate	and balanc			5w20 En	gine Oli				
<ul> <li>Replace three</li> <li>Complete with</li> </ul>	ee tires,rotate heel alignmen				Napagolo	d Oil Filter				1.00
- Replace thre	ee tires,rotate heel alignmen					d Oil Filter				1.00 2.00
- Replace thre	ee tires,rotate heel alignmen				Napagolo 22" Wipe Washer I	d Oil Filter r Blade Fluid Conce	entr			2.00 1.00
- Replace thre	ee tires,rotate heel alignmen				Napagolo 22" Wipe	d Oil Filter r Blade Fluid Conce	entr			2.00
<ul> <li>Replace three</li> <li>Complete with</li> </ul>	ee tires,rotate heel alignmen				Napagolo 22" Wipe Washer I Wd40 Sp	d Oil Filter r Blade Fluid Conce				2.00 1.00 1.00 3.00
<ul> <li>Replace three</li> <li>Complete with</li> </ul>	ee tires,rotate heel alignmen				Napagolo 22" Wipe Washer I Wd40 Sp Hankook	d Oil Filter In Blade Fluid Conce or P235 75r1		Sensor (		2.00 1.00 1.00
<ul> <li>Replace three</li> <li>Complete with</li> </ul>	ee tires,rotate heel alignmen				Napagolo 22" Wipe Washer I Wd40 Sp Hankook	d Oil Filter Ir Blade Fluid Conce or P235 75r1 Issure Monit	7 Dp At	Sensor (		2.00 1.00 1.00 3.00
<ul> <li>Replace three</li> <li>Complete with</li> </ul>	ee tires,rotate heel alignmen				Napagolo 22" Wipe Washer I Wd40 Sp Hankook Tire Pres	d Oil Filter Fluid Conce P235 75r1 sure Monit	7 Dp At	Sensor (		2.00 1.00 1.00 3.00

Workorder: Problem:	1701958 Check engin	Meter: e light on.	35796			In Date:	02/24/2017	Closed:	03/13/2	017
- Diagnose ch test.r&r left do harness.clear	or panel and			oint	Parts Lis Wire Asy Shop Su	/				<b>Qty</b> 1.00 1.00
- Shop Suppli	es				Shop Su	philes				1.00
	Hou :	urs 2.00		Labor:	120.00	Parts:	29.72	Total:	149.72	
Workorder: Problem:	1704398 P.M. Service	Meter:	38621			In Date:	05/01/2017	Closed:	05/11/2	017
- P.m. service					Parts Lis	st				Qty
- Check batte	ry and chargi	ng system .t	ully charge		5w20 En	gine Oil				6.00
pattery.recheck. Failed load test .replace defective battery.					Napagolo	d Oil Filter				1.00
- Inspect and	service winch	1.			Used Fire	e X Refurbi	ished			1.00
- Balance and		ur tires.			Wd40 Sp	or				1.00
- Shop Suppli	es				White Lit	hium Grea	se			1.00
					22" Wipe	er Blade				2.00
					Battery 6	5				1.00
					Shop Su	pplies				1.00
	Hou	urs 5.00		Labor:	300.00	Parts:	201.43	Total:	501.43	
Workorder: Problem:	1708605 P.M. service	Meter:	44272			In Date:	08/30/2017	Closed:	09/07/2	017
- P.m. service	·.				Parts Lis	st				Qty
- Rotate and I	nigh speed ba	alance all fo	ur wheels.nit	rofill all .	5w20 En	gine Oil				6.00
- Inspect and	service winch	ı.			Napagolo	d Oil Filter				1.00
- Shop Suppli	es				22" Wipe	er Blade				2.00
					Washer I	Fluid Conce	entr			1.00
					Napagolo	d Air Filter				1.00
					Drain Plu	g				1.00
					Shop Su	pplies				1.00
	Hou	urs 4.00		Labor:	240.00	Parts:	39.91	Total:	279.91	
Workorder: Problem:	1711890 Left front tire	Meter: flat at traffi	47930 c lot.			In Date:	12/05/2017	Closed:	12/07/2	017
- Check and r	epair left fron	t tire and ba	lance .nitro	fill all.	Parts Lis	st				Qty
- Shop Suppli	•		-		Shop Su					1.00
1										

Workorder:	1800576 P.M. service	Meter:	49223			In Date:	01/17/2018	Closed:	01/30/2018
		÷.							
- P.m. service		CIII Cara and	d and a family of the		Parts Li				Qt
<ul> <li>Replace two speed balance</li> </ul>		n fill tires an	d rotate and	nign	5w20 En	d Oil Filter			6.0 1.0
- Replace bot		rotors and p	oads.service	calipers	22" Wipe				2.0
and flush and		•			•	e X Refurb	ished		1.0
<ul> <li>Pressure ter and thermosta</li> </ul>					Hankook	< P235 75r1	7 Dp At		2.0
cooling syster					Front Ro	otor			2.0
- Perform from	nt end alignm	ent.			Brake Pa	ad Set			1.0
- Inspect and		h.			B Fluid D	Dot 3-32oz			1.0
- Shop Suppl	ies					or Brake Cli			1.0
						stat Housin	g		1.0
					Water P	•	<i>c.</i>		1.0
						eze Motorci	aft		2.0
					A/cv Bel Serpenti				1.0 1.0
					Gasket	ne deil			1.0
					Shop Su	Innlies			1.0
						posal Fee		2.0	
	Но	urs 15.50		Labor:	930.00		1,088.15	Total:	2,018.15
	: 1801354	Meter:	49577			In Date:	02/05/2018	Closed:	02/05/2018
	1 - Wash tic ket(s) issued			Labor:	0.00	In Date: Parts:		Closed: Total:	
Problem:	1 - Wash tic ket(s) issued Ho :	ket(s) issue	d	Labor:	0.00	Parts:	0.00	Total:	0.00
Problem: - 1 - Wash tic Workorder:	1 - Wash tic ket(s) issued	ket(s) issue urs 0.00 Meter:	d 50078		0.00				
Problem: - 1 - Wash tic Workorder: Problem:	1 - Wash tic ket(s) issued Ho : 1802427 Damage to	ket(s) issue urs 0.00 <b>Meter:</b> rear bumper	d 50078 <sup>r</sup> & right rear f		0.00	Parts:	0.00	Total:	0.00
Problem: - 1 - Wash tic Workorder:	1 - Wash tic ket(s) issued Ho : 1802427 Damage to rear bumper o	ket(s) issue urs 0.00 <b>Meter:</b> rear bumper	d 50078 <sup>r</sup> & right rear f			Parts:	0.00 02/09/2018	Total:	0.00 03/05/2018
<ul> <li>1 - Wash tic</li> <li>Workorder: Problem:</li> <li>Damage to</li> <li>Workorder:</li> </ul>	1 - Wash tic ket(s) issued Ho : 1802427 Damage to rear bumper o	ket(s) issue urs 0.00 <b>Meter:</b> rear bumper & right rear f urs 0.00 <b>Meter:</b>	d 50078 <sup>r</sup> & right rear f fender 51895	ender		Parts: In Date:	0.00 02/09/2018	Total: Closed:	0.00 03/05/2018
Problem: - 1 - Wash tic Workorder: Problem: - Damage to Workorder: Problem: - Replace rigl	1 - Wash tic ket(s) issued Ho : 1802427 Damage to rear bumper of Ho : 1804049 Towed in rig ht front tire ar	ket(s) issue urs 0.00 <b>Meter:</b> rear bumper & right rear f urs 0.00 <b>Meter:</b> ght front tire	d 50078 r & right rear f fender 51895 flat.	ender Labor:		Parts: In Date: Parts: In Date:	0.00 02/09/2018 0.00	Total: <b>Closed:</b> Total:	0.00 03/05/2018 0.00
Problem: - 1 - Wash tic Workorder: Problem: - Damage to Workorder: Problem: - Replace rigl damage .nitro	1 - Wash tic ket(s) issued Ho : 1802427 Damage to rear bumper of Ho : 1804049 Towed in rig ht front tire ar gen fill tires.	ket(s) issue urs 0.00 <b>Meter:</b> rear bumper & right rear f urs 0.00 <b>Meter:</b> ght front tire	d 50078 r & right rear f fender 51895 flat.	ender Labor:	0.00 Parts Li	Parts: In Date: Parts: In Date:	0.00 02/09/2018 0.00 04/19/2018	Total: <b>Closed:</b> Total:	0.00 03/05/2018 0.00 04/27/2018
Problem: - 1 - Wash tic Workorder: Problem: - Damage to Workorder: Problem: - Replace rigl	1 - Wash tic ket(s) issued Ho : 1802427 Damage to rear bumper of Ho : 1804049 Towed in rig ht front tire ar gen fill tires.	ket(s) issue urs 0.00 <b>Meter:</b> rear bumper & right rear f urs 0.00 <b>Meter:</b> ght front tire	d 50078 r & right rear f fender 51895 flat.	ender Labor:	0.00 Parts Li Hankook Shop Su	Parts: In Date: Parts: In Date: st P235 75r1 upplies	0.00 02/09/2018 0.00 04/19/2018	Total: <b>Closed:</b> Total:	0.00 03/05/2018 0.00 04/27/2018 04/27/2018 04/27/2018
Problem: - 1 - Wash tic Workorder: Problem: - Damage to Workorder: Problem: - Replace rigl damage .nitro	1 - Wash tic ket(s) issued Ho : 1802427 Damage to rear bumper of Ho : 1804049 Towed in rig ht front tire ar gen fill tires.	ket(s) issue urs 0.00 <b>Meter:</b> rear bumper & right rear f urs 0.00 <b>Meter:</b> ght front tire	d 50078 r & right rear f fender 51895 flat.	ender Labor:	0.00 Parts Li Hankook Shop Su Tire Disp	Parts: In Date: Parts: In Date: st P235 75r1	0.00 02/09/2018 0.00 04/19/2018	Total: <b>Closed:</b> Total:	0.00 03/05/2018 0.00 04/27/2018 Qt 1.0
Problem: - 1 - Wash tic Workorder: Problem: - Damage to Workorder: Problem: - Replace rigl damage .nitro	1 - Wash tic ket(s) issued Ho 1802427 Damage to rear bumper of 1804049 Towed in rig ht front tire ar gen fill tires. ies	ket(s) issue urs 0.00 <b>Meter:</b> rear bumper & right rear f urs 0.00 <b>Meter:</b> ght front tire	d 50078 r & right rear f fender 51895 flat.	ender Labor:	0.00 Parts Li Hankook Shop Su Tire Disp	Parts: In Date: Parts: In Date: st P235 75r1 upplies posal Fee	0.00 02/09/2018 0.00 04/19/2018	Total: Closed: Total: Closed:	0.00 03/05/2018 0.00 04/27/2018 04/27/2018 04/27/2018
Problem: - 1 - Wash tic Workorder: Problem: - Damage to Workorder: Problem: - Replace rigl damage .nitro	1 - Wash tic ket(s) issued Ho : 1802427 Damage to rear bumper of Ho : 1804049 Towed in rig ht front tire ar gen fill tires. ies Ho : 1804382	ket(s) issued urs 0.00 <b>Meter:</b> rear bumper & right rear f urs 0.00 <b>Meter:</b> ght front tire ad balance .0	d 50078 r & right rear f fender 51895 flat.	ender Labor:	0.00 Parts Li Hankook Shop Su Tire Disp	Parts: In Date: Parts: In Date: st P235 75r1 upplies posal Fee	0.00 02/09/2018 0.00 04/19/2018 7 Dp At	Total: Closed: Total: Closed:	0.00 03/05/2018 0.00 04/27/2018 04/27/2018 04/27/2018
Problem: - 1 - Wash tic Workorder: Problem: - Damage to Workorder: Problem: - Replace rigl damage .nitro - Shop Suppl Workorder:	1 - Wash tic ket(s) issued Ho 1802427 Damage to rear bumper of Ho 1804049 Towed in rig ht front tire ar gen fill tires. ies Ho 1804382 FLat tire	ket(s) issued urs 0.00 Meter: rear bumper & right rear f urs 0.00 Meter: ad balance .0 urs 0.50 Meter:	d 50078 r & right rear f fender 51895 flat. due to sidewa	ender Labor:	0.00 Parts Li Hankook Shop Su Tire Disp	Parts: In Date: Parts: In Date: st P235 75r1 upplies posal Fee Parts:	0.00 02/09/2018 0.00 04/19/2018 7 Dp At 187.53	Total: Closed: Total: Closed: Total:	0.00 03/05/2018 0.00 04/27/2018 04/27/2018 1.0 1.0 1.0 217.53

Workorder: Problem:	1807348 P.M. service :	Meter: and bumpe	54870 er damage.			In Date:	07/19/2018	Closed:	07/25/2018
- P.m. service	).				Parts Li	ist			Qty
- Rotate and b	balance all fou	r tires .nitro	ogen fill tires.		Napago	ld Oil Filter			1.00
- Inspect and	service winch.				5w20 Er	ngine Oil			6.00
- Shop Suppli	es				Napago	ld Air Filter			1.00
					Washer	Fluid Conce	entr		1.00
					22" Wip	er Blade			2.00
					Shop Su	upplies			1.00
	Hou	rs 4.00		Labor:	240.00	Parts:	36.46	Total:	276.46
Workorder: Problem:	1808614 damage to re	Meter: ar bumper	54870			In Date:	07/24/2018	Closed:	08/21/2018
- damage to r	ear bumper								
	Hou :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1812322 P.M. Service.	Meter: Right front	58594 tire flat.			In Date:	12/04/2018	Closed:	12/10/2018
- P.m. service	<del>)</del> .				Parts Li	ist			Qty
- Replace two Nitrofill all.	worn tires . B	alance and	l rotate all four	r tires.		ld Oil Filter			1.00
	service winch				•	uart 5w20			6.00
- Shop Suppli					•	er Blade			2.00
enep euppn						re X Refurbi			1.00
						k P235 75r1	7 Dp At		2.00 1.00
					Shop Su	••			
	Ноц	rs 5.00		Labor:	335.00	posal Fee Parts:	500.08	Total	2.00 835.08
	:	15 5.00		Labui.	555.00	rans.	500.00	Total.	000.00
						In Date:	04/12/2019	Closed:	04/12/2019
	1903996 1 - Wash tick	Meter: et(s) issued	62776 d			in Date.	04/12/2013	Cioseu.	04/12/2019
Workorder: Problem: - 1 - Wash ticl	1 - Wash tick					in Date.	04/12/2013	Closed.	04/12/2019

Workorder:1905495Meter:64484Problem:P.M. service and strobe switch light inop.	In Date: 05/22/2019 Closed	: 05/31/2019
- P.m. service.	Parts List	Qty
- Test and replace both rear strobe bulbs and light switch .	Napagold Oil Filter	1.00
Test and replace tag light bulb on right side .	5w20 Engine Oil	6.00
- Inspect and service transmission . Replace filter and flush transmission and refill .	Engine Oil Stop Leak	1.00
- Inspect and service rear differential .drain and refill .	22" Wiper Blade	2.00
- Rotate and high speed balance all four tires . Nitrofill all.	Napagold Air Filter	1.00
- Inspect and service winch .	Non-chlor Brake Clnr	1.00
- Shop Supplies	Ford Triton Pvc Swc	1.00
end exprise	Boxed Miniatures	1.00
	Switch	1.00
	Vtx609a Led Strobe Am	2.00
	oil auto	16.00
	Screen Asy	1.00
	Friction Modifier	1.00
	75w140 Ford Axle Lube	3.00
	Shop Supplies	1.00
Hours 10.00 Labor:	670.00 Parts: 555.33 Tot	al: 1,225.33
Workorder:1907581Meter:66495Problem:A/C stopped blowing.	In Date: 07/22/2019 Closed	: 07/25/2019
- Diagnose blower motor inop . R&r defective blower motor	Parts List	Qty
and resistor . Retest .	Blower Resistor	1.00
- Shop Supplies	Blower motor	1.00
	Shop Supplies	1.00
Hours 1.50 Labor:	100.50 Parts: 250.37 Tot	al: 350.87
Workorder: 1910446 Meter: 69622 Problem: P.M. service.	In Date: 10/09/2019 Closed	: 10/24/2019
- P.m. service.	Parts List	Qty
- Check battery and charging system after fully charging	Drain Plug	1.00
battery . Battery failed load test . R&r defective battery . Hook		1.00
up Ids to reset Battery monitoring system .	Napagold Oil Filter	1.00
- Resurface both rear brake rotors and service calipers .replace brake pads . Flush and bleed brake system . Road	5w20 Engine Oil	6.00
test.	22" Wiper Blade	2.00
- Inspect and service winch .	Used Fire X Refurbished	1.00
- Balance and rotate all four tires . Nitrofill all.	Battery	1.00
- Shop Supplies	Brake Pad	1.00
	Shop Supplies	1.00
Hours 9.00 Labor:		al: 945.46

:

Workorder: Problem:	2000706 Left rear tire	Meter: going flat .	72597			In Date:	01/22/2020	Closed:	01/24/20	020
- Service call Nitrofill all .	to traffic lot .	Repair left r	ear tire and ba	alance .	Parts Li Shop Su					<b>Qty</b> 1.00
- Shop Suppli	es				onop ot	ppiloo				1.00
	Ho :	urs 2.00		Labor:	146.00	Parts:	4.00	Total:	150.00	
Workorder: Problem:	2004095 P.M. Service	Meter: e.	75456			In Date:	04/23/2020	Closed:	04/30/20	020
- P.m. service					Parts Li	st				Qty
- Diagnose sti	robes inop . I	R&r defective	e lighted swite	h and	Napago	ld Oil Filter				1.00
reterst.					5w20 Er	ngine Oil				6.00
- Rotate and b		ur tires . Niti	ofill all.		22" Wip	er Blade				2.00
- Shop Suppli	es				Switch					1.00
					Shop Su	upplies				1.00
	Ho	urs 4.00		Labor:	292.00	Parts:	38.37	Total:	330.37	
Workorder: Problem:	2005068 Right front t	Meter: ire going flat	75942			In Date:	05/20/2020	Closed:	05/26/20	020
- Repair right	front tire and	balance . N	itrofill all.		Parts Li	st				Qty
- Shop Suppli					Shop Su	upplies				1.00
		urs 1.00		Labor:		Parts:	4.00	Total:	77.00	
Workorder: Problem:	2007489 A/C blower	Meter: inop .	78026			In Date:	07/30/2020	Closed:	08/04/20	020
- Diagnose A/	c blower inor	o.R&r efect	ive blower mo	otor and	Parts Li	st				Qty
resistor.					resistor					1.00
- Shop Suppli	es				Blower I	Notor				1.00
					Shop Su	upplies				1.00
	Ho :	urs 1.50		Labor:	109.50	Parts:	245.95	Total:	355.45	
Workorder: Problem:	2010616 PM	Meter:	80491			In Date:	10/22/2020	Closed:		
- Pm										
	Ho	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
	•		81218			In Date:	12/01/2020	Closed:	12/01/20	120
	2011915 Transition P	Meter: rep Charge	01210					ciccou		
Workorder: Problem: - Transition P	Transition P		01210					0.0000		