

**Palm Beach County Fleet Management
Asset Maintenance History**

10193279 2008 INTERNATIONAL 7400 Sewer Cleaner/Vac Combo, Truck Mntd, 56,000 Gvwr +

Workorder: 944873 **Meter:** 6553 **In Date:** 10/21/2009 **Closed:** 12/01/2009
Problem: P.M. / List

	Parts List	Qty
- pm service	Freight	1.00
- replace hose on rear reel	Freight	1.00
- service cooling system and replace upper hose	Shop Supplies	1.00
- hyd hose per sample replace small reel and hose replace large reel hose	Upper Rad Hose / 3605681c2	1.00
- shop to masthead and to vanlinda	1842639c91 Oil Filter Frm Ph9971 Wix 57744	1.00
- replace split shift gasket{ air leak }	2506656c1 A/c Filter	1.00
- replace missing door hold open pin	Hyd Filter / /51746	1.00
- Repair saddle for boom vanlinda	Hyd Filter / 57415	1.00
- replace broken hyd. guage and hose counter	3994 Fuel Filter Int 1878042c92	1.00
- replace two rear mud flaps	15/40 Oil	30.00
- replace work light and repair wiring relamp back up lights	31-22 Wiper Blades 22" Wiper Blade	2.00
- rear springs will not take grease,work to make them take grease	Hyd Gauge / 202I254r	1.00
- replace fittings ,clean hoses on central lube system	Used Firex Refurbed Fire Extingshers	1.00
- replace hyd. filters	798 Flare Kits Triangle Reflector Kits	1.00
- install fire ext. and triangles	Custom5lb Bracket Firex Stock #340060300	1.00
- check tv system do not repair as per jimmy hartman	H-7610 Bulb Headlight	1.00
- Shop Supplies	81731 Weatherstrip Yellow Adhesive	1.00
	H/duty A/freeze Ext/life (cat 238-8648)	8.00
	Mud Flap 24x30 Splash Guard(spl66490730)	2.00
	High Psi Coupler 500-16-16	1.00
	Hose Reel / Cm32112m	1.00
	0-5000 Pse Gauge	1.00
	Hose Counter 220980	1.00
	Counter Tube	1.00
Hours 58.50	Labor: 3,510.0	Parts: 1,226.17
:	0	Total: 4,736.17

Workorder: 947222 **Meter:** 7275 **In Date:** 12/21/2009 **Closed:** 02/05/2010
Problem: Engine blowing white smoke from exhust

	Parts List	Qty
- Diagnose Engine Exhust Blowing White Smoke, Coolant Leak Inside Engine	Shop Supplies	1.00
- Prepare Truck To Be Transported		
- Inspect/repair Cooling System, Replace Leaking Egr Cooler. Reflash Ecm		
- Test Run		
-		
- Shop Supplies		
Hours 4.80	Labor: 288.00	Parts: 2.00
:		Total: 290.00

Workorder: 947282 **Meter:** 7133 **In Date:** 12/28/2009 **Closed:** 12/28/2009
Problem: engine blowing white smoke

- From: Pahokee/fleet To: Rechten International Trucks

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1000385	Meter: 7133	In Date: 01/11/2010	Closed: 01/11/2010
Problem: pick up at int.			
- pick up from int.		Parts List	Qty
- regeneration light is -regenerate		Shop Supplies	1.00
- Shop Supplies			
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
Workorder: 1000456	Meter: 7133	In Date: 12/21/2009	Closed: 01/12/2010
Problem: engine blowing white smoke			
- From: Pa Shop To: Reichtine International			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1001152	Meter: 7861	In Date: 02/01/2010	Closed: 02/16/2010
Problem: RECOVERY, STUCK IN MUD			
- From: Sr 715 Mobil Home Park			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1004258	Meter: 9634	In Date: 04/26/2010	Closed: 12/19/2010
Problem: REPLACE REAR TIRES			
- Replace Rear Tires		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
		11r22.5 Micheline Xze2 Partner	6.00
Hours 1.00	Labor: 60.00	Parts: 2,841.50	Total: 2,901.50
:			
Workorder: 1005085	Meter: 10044	In Date: 04/26/2010	Closed: 05/14/2010
Problem: L.R.O. TIRE FLAT			
- gua water plant			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1005087	Meter: 10044	In Date: 04/29/2010	Closed: 05/14/2010
Problem: SERVICE CALL - ONSITE			
- @ Pa Shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1009375	Meter: 12452	In Date: 08/30/2010	Closed: 08/30/2010
Problem: add oil			
- add oil		Parts List	Qty
		15/40 Oil	6.00
Hours 0.30	Labor: 18.00	Parts: 14.37	Total: 32.37
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1010123	Meter: 12598	In Date: 09/15/2010	Closed: 09/23/2010
Problem: REPAIR TAIL LIGHTS, CHECK HYDRAULIC LEAK			
- repair lights	Parts List	Qty	
- hyd leak / internal leak at hose reel.	Shop Supplies	1.00	
- Shop Supplies	Tail Lamp / Gro52892	2.00	
Hours 2.00	Labor: 120.00	Parts: 28.04	Total: 148.04
:			
Workorder: 1010952	Meter: 13145	In Date: 10/05/2010	Closed: 10/06/2010
Problem: add oil			
- add oil .	Parts List	Qty	
	15/40 Oil	4.00	
Hours 0.30	Labor: 18.00	Parts: 8.96	Total: 26.96
:			
Workorder: 1012067	Meter: 13641	In Date: 10/27/2010	Closed: 11/16/2010
Problem: replace broken lights.			
- replace strobe lite / tail lights / head lite .	Parts List	Qty	
- add hyd oil	Shop Supplies	1.00	
- add oil	15/40 Oil	1.00	
- Shop Supplies	Aw68 Hydro Fluid Hydraulic Oil 68	4.00	
	Work Lights / 64931	2.00	
	250adh12a Strobe Strobe Light 12/24vt	1.00	
	53650 Tail Light Led Two Connector (grote)	2.00	
	Head Light / 6014	1.00	
Hours 4.30	Labor: 258.00	Parts: 421.23	Total: 679.23
:			
Workorder: 1012882	Meter: 14193	In Date: 11/18/2010	Closed: 01/27/2011
Problem: pm service and list			
- pm service	Parts List	Qty	
- repair aps by pats pumps	Shop Supplies	1.00	
- replace mud flap and repair fender	Ca9346 Air Filter Lbf Laf9099 Wix 46870	1.00	
- replace fire ext.	1842639c91 Oil Filter Frm Ph9971 Wix 57744	1.00	
- add nitrogen to all tires	3994 Fuel Filter Int 1878042c92	1.00	
- Shop Supplies	15/40 Oil	30.00	
	Used Firex Refurbed Fire Extingshers	1.00	
	Mud Flap 24x30 Splash Guard(spl66490730)	1.00	
Hours 13.00	Labor: 780.00	Parts: 208.85	Total: 988.85
:			
Workorder: 1103316	Meter: 16945	In Date: 03/28/2011	Closed: 04/05/2011
Problem: repair camera			
- commercial repair			
Hours 0.30	Labor: 18.00	Parts: 0.00	Total: 18.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1103789	Meter: 17302	In Date: 04/07/2011	Closed: 05/02/2011
Problem: REPLACE BROKEN CONTROL HANDLE FOR 1/2" HOSE REEL			
- replace broken handle	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 0.50	Labor: 30.00	Parts: 2.00	Total: 32.00
:			
Workorder: 1106583	Meter: 19339	In Date: 06/22/2011	Closed: 07/05/2011
Problem: PM Service,light out in rear,water valve handles broken,lights stay on,			
- Pm Service	Parts List		Qty
- replaced tail light	Shop Supplies		1.00
- arrange commercial repair, replace rear tires	1842639c91 Oil Filter Frm Ph9971 Wix 57744		1.00
- performance test	3994 Fuel Filter Int 1878042c92		1.00
- Arrange commercial repair. aqua tech service,	Ca9346 Air Filter Lbf Laf9099 Wix 46870		1.00
- Shop Supplies	15/40 Oil		30.00
	31-22 Wiper Blades 22" Wiper Blade		2.00
	Tail Light / 50-60202r-3		1.00
Hours 10.00	Labor: 600.00	Parts: 238.44	Total: 838.44
:			
Workorder: 1107246	Meter: 19723	In Date: 07/11/2011	Closed: 07/19/2011
Problem: a/c / wipers / vacc switch / elec pto switch not working .			
-			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1107399	Meter: 19723	In Date: 07/14/2011	Closed: 07/18/2011
Problem: electrical short			
- Repair A/c actuator door	Parts List		Qty
- R&r 3 batteries	Shop Supplies		1.00
- Traced out, found, and repaired Intermitend Short	Group 31 Stud Battery (acd 31-900ct)		3.00
- Extended test drive	3542606c1 Acuator Door Vent		1.00
- Shop Supplies			
Hours 14.00	Labor: 840.00	Parts: 459.31	Total: 1,299.31
:			
Workorder: 1108322	Meter: 19979	In Date: 08/08/2011	Closed: 08/10/2011
Problem: Tires Flat			
- Diagnosed, arrange service, verified repair			
Hours 0.30	Labor: 18.00	Parts: 0.00	Total: 18.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1200585	Meter: 24022	In Date: 01/18/2012	Closed: 03/12/2012
Problem: pm service and list			
- pm service	Parts List	Qty	
- repairs by pats pump	Shop Supplies	1.00	
- replace two rear brake chambers	Air Filter	1.00	
- repair headlights, stop, marker arrow board and repair wiring	1842639c91 Oil Filter Frm Ph9971 Wix 57744	1.00	
- check all fluid levels and fill fuel tank { going to pat's }	3994 Fuel Filter Int 1878042c92	1.00	
- repair flat , and tire replacement boulevard	Ca9346 Air Filter Lbf Laf9099 Wix 46870	1.00	
- r&r seat for repair	2506656c1 A/c Filter	1.00	
- fill new tires with nitrogen	R810021 Clevis Brake Chamber	1.00	
- service cooling system repair leak near turbo	3030sb Brake Chamber (bendix 800831)	1.00	
- repair rear suspension by total truck	R810021 Clevis Brake Chamber	1.00	
- fm to total truck and central	Rear Brake Chamber	1.00	
- Shop Supplies	15/40 Oil	30.00	
	31-22 Wiper Blades 22" Wiper Blade	2.00	
	Used Firex Refurbed Fire Extingshers	1.00	
	H6024 Guide Lamps	1.00	
	53650 Tail Light Led Two Connector (grote)	1.00	
	94706 Adapter 3 Prong	1.00	
	60260r Tail Light Oval Red Led	1.00	
	3157 Tail Light Bulbs	1.00	
	H/duty A/freeze Ext/life (cat 238-8648)	6.00	
	11r225rc Tire Recapped	1.00	
	11r225rc Tire Recapped	2.00	
Hours 19.60	Labor: 1,176.0	Parts: 1,205.14	Total: 2,381.14
:	0		
Workorder: 1206103	Meter: 25163	In Date: 06/27/2012	Closed: 06/28/2012
Problem: WON'T GO INTO FOWARD OR REVERSE			
- Tow From: Hooker Hwy To: Vista / Heavy Equipment			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1206195	Meter: 25163	In Date: 07/02/2012	Closed: 07/09/2012
Problem: Will not move			
- service call pats pump and blower			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1206907	Meter: 25659	In Date: 07/25/2012	Closed: 07/27/2012
Problem: pto			
- free shift solenoids and install air line oiler	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
	Air Line Oiler	1.00	
Hours 3.50	Labor: 210.00	Parts: 67.79	Total: 277.79
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1300544	Meter: 28000	In Date: 01/15/2013	Closed: 02/26/2013
Problem: Repair Blower			
- Repair damaged wiring for rear marker lights.	Parts List	Qty	
- rebuild Dresser Roots 624 Rcs blower housing, install swivel and flange, service body, service chassis, Dot inspection	5 Multi-purpose Lamp	1.00	
- Pm service by Pats Pump and Blower.	Valve Handle Sw14	4.00	
- Replace leaking brake line.	Air Brake Hose	1.00	
- Replace rusted exhaust from Dpf to end.	Exhaust Support Assembly	1.00	
- Replace broken worklight on boom	Clamp	2.00	
- Replace all broken control valve handles	Shop Supplies	1.00	
- Drain water tanks. Remove and repair water tank crossover tee.			
- Test run.			
- Shop Supplies			
Hours 19.00	Labor: 1,140.00	Parts: 896.74	Total: 2,036.74
:	0		
Workorder: 1303037	Meter: 28491	In Date: 03/28/2013	Closed: 04/25/2013
Problem: Joystick not working. Remote not working			
- Pendant and joystick not working. Diagnose both circuits.	Parts List	Qty	
Replace shorted switches in joy stick control to correct .	Microswitch	2.00	
- Install new boom suction hose. Repair boom cradle.	Contact Cartridge	2.00	
- Test run to check boom functions.	Boom Hose Assembly	1.00	
- Shop Supplies	Shop Supplies	1.00	
	Freight Charge	1.00	
Hours 12.50	Labor: 750.00	Parts: 4,329.08	Total: 5,079.08
:			
Workorder: 1306289	Meter: 28515	In Date: 06/21/2013	Closed: 07/17/2013
Problem: TRANSPORT WONT RUN			
- Tow From: Sr80 And Hwy 715 To: Fleet Pahokee			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1306354	Meter: 28741	In Date: 06/25/2013	Closed: 06/27/2013
Problem: Shut off, won't start			
- Diagnose no start. Removed and cleaned fuel pump screen.	Parts List	Qty	
- Fm to Gua yard.	Brake Cleaner	1.00	
- Shop Supplies	Shop Supplies	1.00	
Hours 3.00	Labor: 180.00	Parts: 5.45	Total: 185.45
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1308459	Meter: 29197	In Date: 08/21/2013	Closed: 09/26/2013
Problem: Pm service. and list.			
- Pm service.	Parts List	Qty	
- Diag. a/c not blowing. Check sys. pressures. Replace clogged a/c filter.	Napa Cabin Air Filter	1.00	
- Replace fan belt.	15w40 Bulk Tank Pahoee	30.00	
- Replace damaged washer pump.	Napagold Oil Filter	1.00	
- Replace tires by Boulevard Tire.	Napagold Fuel Filter	1.00	
- Order replacement suction tubes.	Wiper Blade	2.00	
- Repair rear joystick control.	Washer FI	1.00	
- Test drive.	Hdvrbelt	1.00	
- Shop Supplies	Washer Pump	1.00	
	Washer Fluid Concentr	2.00	
	Extension Tube	1.00	
	Intake Tube	1.00	
	Microswitch	2.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	2.00	
	11r225rc Tire Recapped	2.00	
	Freight Charge	1.00	
Hours 13.50	Labor: 810.00	Parts: 2,137.42	Total: 2,947.42
:			
Workorder: 1309841	Meter: 29412	In Date: 09/30/2013	Closed: 10/08/2013
Problem: Flat tire.			
- Tire repair by Boulevard tire.	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
	Tire Disposal Fee	1.00	
	11r225rc Tire Recapped	1.00	
Hours 0.00	Labor: 0.00	Parts: 183.46	Total: 183.46
:			
Workorder: 1310228	Meter: 29606	In Date: 10/09/2013	Closed: 10/10/2013
Problem: Change tire			
- change tire			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1311305	Meter: 29878	In Date: 11/06/2013	Closed: 11/21/2013
Problem: Tire repair by Boulevard Tire.			
- Tire repair by Boulevard Tire.	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
	Tire Disposal Fee	1.00	
	11r225rc Tire Recapped	1.00	
Hours 0.00	Labor: 0.00	Parts: 183.46	Total: 183.46
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1402170 **Meter:** 31007 **In Date:** 03/05/2014 **Closed:** 03/06/2014
Problem: Replace headlight.

- Replace ds headlight.	Parts List	Qty
	Halogen Lamp	1.00
Hours 0.50	Labor: 30.00	Parts: 11.18
:		Total: 41.18

Workorder: 1403744 **Meter:** 31520 **In Date:** 04/16/2014 **Closed:** 07/02/2014
Problem: Pm service and list.

- Pm service.	Parts List	Qty
- Aps water pump damaged. Rebuild pump.	Brake Cleaner	1.00
- Replace boom work light. Replace shorted rf head light.	Hyd Fluid Tank Pahokee	7.00
- Replace leaking rear dump valve. Replace missing tube holder gaskets.	Grease Nlgi 2	1.00
- Replace tires by Boulevard tire.	15w40 Bulk Tank Pahokee	30.00
- Install asset #'s.	Napagold Oil Filter	1.00
- Service a/c filters. Clean and inspect housings.	Napagold Fuel Filter	1.00
- Test run truck to check all functions.	Wiper Blade	2.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
	Napa Cabin Air Filter	1.00
	Work Lmp	1.00
	Tube Clamp Rub Insert	8.00
	Piston O 55 Ms	3.00
	Sleeve Ms55	3.00
	Spacer	3.00
	Gasket Seal Ring 55ms	6.00
	Gasket Holder	3.00
	Soft Parts Kit Complete	1.00
	Screw	16.00
	Halogen Lamp	1.00
	Lever Valve 6 In Brass	1.00
	Shop Supplies	1.00
	11r225rc Tire Recapped	2.00
	Tire Disposal Fee	2.00
	Freight Charge	1.00
	Freight Charge	1.00
	Freight Charge	1.00
Hours 27.50	Labor: 1,650.0	Parts: 11,431.44
:	0	Total: 13,081.44

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1407923	Meter: 31579	In Date: 08/11/2014	Closed: 09/08/2014
Problem: List			
- Repair air leak. Replace cracked air line to air cyl. on tank.	Parts List	Qty	
- Remove lh water tanks. Reseal crossover pipe and gaskets. Reinstall water tanks.	Ptex Ultra Grey 3oz	1.00	
- Repair wiring in rear control box. Replace damaged switches.	Tube-nylon-black	10.00	
- Diagnose remote throttle switches not working. Replace Rescm and reprogram.	Switch	2.00	
- Shop Supplies	Toggle Switch 2 Pos	2.00	
	Shop Supplies	1.00	
Hours 20.00	Labor: 1,200.00	Parts: 56.00	Total: 1,256.00
:	0		
Workorder: 1409018	Meter: 31769	In Date: 09/08/2014	Closed: 09/11/2014
Problem: Pto shutting off.			
- Fm to Belle Glade water plant.	Parts List	Qty	
- Check complaint of pto not working. Checked for pto related dtc's. None found. Had operator operate all functions no problem found.	Shop Supplies	1.00	
- Shop Supplies			
Hours 2.50	Labor: 150.00	Parts: 2.00	Total: 152.00
:			
Workorder: 1500900	Meter: 33544	In Date: 01/26/2015	Closed: 02/24/2015
Problem: List.			
- Replace leaking airlines and air oiler	Parts List	Qty	
- Replace damaged water pump pistons and seals as needed.	Tube-nylon-black	6.00	
- Repair hose guide. Replace water valve.	Tube-nylon-black	8.00	
- Pm service.	Valve	1.00	
- Service a/c filters. Clean evap. Housing.	Oiler	1.00	
- Batteries failed load test. Replace batteries.	Ptex Ultra Grey 3oz	1.00	
- Replace Lr outside tire.	Piston	2.00	
- Test run to check water pump operation.	Seal Kit	1.00	
- Drain water from fuel tank.	Gasket Holder	2.00	
- Shop Supplies	15w40 Bulk Tank Pahokee	31.00	
	Fuel Fil	1.00	
	Napagold Oil Filter	1.00	
	Wiper Blade	2.00	
	Washer Fluid Concentr	1.00	
	Napa Cabin Air Filter	1.00	
	Group 31 Stud Delco	3.00	
	Syn Atf Bulk Pahokee	3.00	
	11r22.5 G661 Tire	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	1.00	
	Freight Charge	1.00	
Hours 31.50	Labor: 1,890.00	Parts: 5,637.22	Total: 7,527.22
:	0		

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1501969	Meter: 33666	In Date: 02/24/2015	Closed: 03/03/2015
Problem: Water leak			
- Replace leaking hose to water pump.	Parts List	Qty	
- Fm to Hyd. Supply.	Hydraulic Hose	1.00	
- Shop Supplies	Shop Supplies	1.00	
Hours 5.00	Labor: 300.00	Parts: 316.46	Total: 616.46
:			
Workorder: 1504749	Meter: 34465	In Date: 05/11/2015	Closed: 05/27/2015
Problem: Air leak			
- Fm to Gua yard 2x's.	Parts List	Qty	
- Replace leaking air regulator and filter housings.	Mini Filter Air	1.00	
- Shop Supplies	Regulator	1.00	
	Shop Supplies	1.00	
Hours 3.50	Labor: 210.00	Parts: 99.25	Total: 309.25
:			
Workorder: 1506141	Meter: 34639	In Date: 06/18/2015	Closed: 07/01/2015
Problem: Air leak.			
- Replace leaking Rr brake chamber.	Parts List	Qty	
- Replace broken rear led marker lights.	Led Chmsl Lamp	2.00	
- Repair damaged light wire harness.	Grommet	2.00	
- Shop Supplies	Led Adapter Plug	2.00	
	Chamber	1.00	
	Shop Supplies	1.00	
Hours 5.50	Labor: 330.00	Parts: 317.45	Total: 647.45
:			
Workorder: 1507494	Meter: 35177	In Date: 07/28/2015	Closed: 08/04/2015
Problem: Flat tire. Rear speed switch not working.			
- Replace rear tires as needed.	Parts List	Qty	
- Check rear speed control operation. Replace speed stich and cover.	11r22.5 G661 Tire	3.00	
- Repair bent tube clamp bracket.	switch cover	1.00	
- Shop Supplies	Momentary Switch	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	3.00	
Hours 5.00	Labor: 300.00	Parts: 1,480.91	Total: 1,780.91
:			
Workorder: 1507798	Meter: 35249	In Date: 08/04/2015	Closed: 08/11/2015
Problem: Aux. speed control not working			
- Use scan tool to check for Vsm related codes. No codes present.	Parts List	Qty	
- Check remote spped control circuit. Repair open in speed control wire harness.	Shop Supplies	1.00	
- Shop Supplies			
Hours 3.50	Labor: 210.00	Parts: 2.00	Total: 212.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1508983	Meter: 35669	In Date: 09/08/2015	Closed: 09/10/2015
Problem: Pm service,list			
- Pm service.	Parts List	Qty	
- Replace a/c filter. Replace broken blend door actuator.	3542606c1 Acuator Doo	1.00	
- Replace front tires.	15w40 Bulk Tank Pahokee	30.00	
- Reweld hose tie down chain.	Napagold Oil Filter	1.00	
- Test drive.	Fuel Fil	1.00	
- Shop Supplies	Washer Fluid Concentr	1.00	
	Wiper Blade	2.00	
	Napa Cabin Air Filter	1.00	
	11r22.5 G661 Tire	2.00	
	Peak Global	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	2.00	
Hours 13.00	Labor: 780.00	Parts: 1,456.16	Total: 2,236.16
:			
Workorder: 1509908	Meter: 35993	In Date: 09/30/2015	Closed: 10/06/2015
Problem: Arrowboard not working,strobe.			
- Replace shorted stobe light. Replace broken arrowboard lights and repair poor broken ground wire.	Parts List	Qty	
- Shop Supplies	Lamp	2.00	
	Strobe Lp Led	1.00	
	Shop Supplies	1.00	
Hours 3.00	Labor: 180.00	Parts: 141.71	Total: 321.71
:			
Workorder: 1510686	Meter: 36366	In Date: 10/22/2015	Closed: 11/09/2015
Problem: Replace tires by Boulevard Tire.			
- Replace tires by Boulevard tire.	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
	11r225rc Tire Recapped	3.00	
	Tire Disposal Fee	3.00	
Hours 0.00	Labor: 0.00	Parts: 542.52	Total: 542.52
:			
Workorder: 1512883	Meter: 37538	In Date: 12/21/2015	Closed: 12/31/2015
Problem: Repair drain hose.			
- Repair damaged tank drain hose.	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1602624	Meter: 38478	In Date: 03/11/2016	Closed: 03/11/2016
Problem: 1 - Key(s) issued			
- 1 - Key(s) issued	Parts List	Qty	
	Duplicate Vehicle Keys	1.00	
Hours 0.30	Labor: 18.00	Parts: 3.00	Total: 21.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1603608	Meter: 38720	In Date: 04/06/2016	Closed: 05/11/2016
Problem: Pm service,water leak.			
<ul style="list-style-type: none"> - Pm service. - Replace Rr reverse light and shorted reverse alarm. - Replace a/c filters and clean evap. - Replace leaking waterlines to main pump. Replace faded sight tubes on water tanks. Replace front pipe holders. - A/c shutting off. Replace bad a/c breaker. - Fm to Hyd. Supply. - Replace missing wire loom on tank wire harness. - Test drive repairs. 	Parts List		Qty
	15w40 Bulk Tank Pahokee		30.00
	Napagold Oil Filter		1.00
	Fuel Fil		1.00
	22" Wiper Blade		2.00
	Washer Fluid Concentr		1.00
	Peak Global		1.00
	Used Fire X Refurbished		1.00
	Alarm		1.00
	Napa Cabin Air Filter		1.00
	158h breaker		1.00
	30a Breaker		1.00
	1/4-20x51/2" Gr5 Nc Hex		4.00
	L0152-063 Gear Shield		1.00
	Tube Bracket		2.00
	Weldment		1.00
	Hose Made, Po#10193279		1.00
	Shop Supplies		1.00
	Freight Charge		1.00
Hours 26.00	Labor: 1,560.0	Parts: 2,421.08	Total: 3,981.08
:	0		
Workorder: 1607666	Meter: 40329	In Date: 07/27/2016	Closed: 08/29/2016
Problem: A/c Does not work			
<ul style="list-style-type: none"> - Check system pressures. Static pressure ok. A/c compressor worn. Replace compressor, dryer,expansion valve. Flush a/c lines. Evacuate and recharge a/c system. - Fm to Hyd. Supply 2x's. - Replace leaking high pressure water hose. - Replace strobe light and Rr taillight. Repair wiring harness. - Upper boom over rotated. Replace leaking hyd hoses. ? unwind boom and repair damaged hoses and wiring harnesses. - Lube boom extension. - Test drive. - Shop Supplies 	Parts List		Qty
	E8 A/c Oil Univ W Dye		1.00
	Pahokee Shop Freon		5.00
	Ac Compressor		1.00
	Expansion Alve		1.00
	A/c Dryer		1.00
	Dis2 Fluid		1.00
	Turn Lamp Led		1.00
	Napa Cabin Air Filter		1.00
	A C Vacuum Pump Oil		1.00
	Hose Made		1.00
	Strobe Lp Led		1.00
	Aw68 Hyd Fluid Tank Pahokee		34.00
	Slip Plate Spray 12oz		1.00
	hose made		1.00
	Shop Supplies		1.00
Hours 25.00	Labor: 1,500.0	Parts: 1,685.36	Total: 3,185.36
:	0		

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1609174	Meter: 40720	In Date: 09/01/2016	Closed: 09/12/2016
Problem: Does not go into gear			
- Replace broken pressure switch on transfer case. Replace shorted tcase shift solenoid.	Parts List		Qty
- Shop Supplies	air solenoid		1.00
	Switch		1.00
	Shop Supplies		1.00
Hours 4.00	Labor: 240.00	Parts: 136.16	Total: 376.16
:			
Workorder: 1610434	Meter: 40904	In Date: 10/05/2016	Closed: 10/26/2016
Problem: Pm service. Hyd. leak			
- Pm service.	Parts List		Qty
- Replace leaking hyd. hoses on boom.	15w40 Bulk Tank Pahokee		30.00
- A/c blowing warm. Replace stripped temp. door actuator.	Napagold Oil Filter		1.00
Replace leaking schrader valve,evacuate and recharge a/c system.	Fuel Fil		1.00
- Fm to Hyd. Supply.	22" Wiper Blade		2.00
- Repair Rri flat tire.	Washer Fluid Concentr		1.00
- Test drive.	Napa Cabin Air Filter		1.00
- Shop Supplies	3542606c1 Acuator Doo		1.00
	Aw68 Hyd Fluid Tank Pahokee		7.00
	A/c Valve Core		1.00
	Freon Pahokee Shop		4.00
	Tire Repair 11r22.5		1.00
	Hose Assy		1.00
	Shop Supplies		1.00
	Tire Disposal Fee		1.00
Hours 17.50	Labor: 1,050.00	Parts: 684.34	Total: 1,734.34
:	0		
Workorder: 1705627	Meter: 41976	In Date: 06/06/2017	Closed: 12/01/2017
Problem: repair blower			
- repair blower	Parts List		Qty
- Shop Supplies	parts and service		1.00
	Shop Supplies		1.00
Hours 0.00	Labor: 0.00	Parts: 21,621.75	Total: 21,621.75
:			
Workorder: 1710674	Meter: 44468	In Date: 10/30/2017	Closed: 10/31/2017
Problem: Add hyd. oil			
- Top off hyd. tank.	Parts List		Qty
- Shop Supplies	Aw68 Hyd Fluid Tank Pahokee		18.00
	Shop Supplies		1.00
Hours 0.50	Labor: 30.00	Parts: 42.77	Total: 72.77
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1711448	Meter: 45055	In Date: 11/20/2017	Closed: 12/13/2017
Problem: Hyd. Leak			
- Replace leaking transmission lines.	Parts List	Qty	
- Replace worn rear tires.	15w40 Bulk Tank Pahokee	30.00	
- Speed and tach gauges not working. Replace instrument cluster and trans temp gauge.	Napagold Oil Filter	1.00	
- Pm service.	Filter	1.00	
- Fm to Hyd. Supply.	22" Wiper Blade	2.00	
- Tighten loose exhaust clamps.	Napa Cabin Air Filter	1.00	
- Repair leak at air oiler housing.	Used Fire X Refurbished	1.00	
- Test drive.	Hyd Hose Made	1.00	
- Shop Supplies	Hyd Hose Made	1.00	
	Cluster	1.00	
	Syn Atf Bulk Pahokee	8.00	
	Non-chlor Brake Clnr	1.00	
	11r22.5	4.00	
	Tempguage	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	4.00	
Hours 14.50	Labor: 870.00	Parts: 4,160.33	Total: 5,030.33
:			
Workorder: 1801872	Meter: 45974	In Date: 02/16/2018	Closed: 05/02/2018
Problem: Coolent leak			
- top off cooling system. pressure test and found coolers leaking. tow to rechtien	Parts List	Qty	
- to rechtien 2xs. to mako	Hose Made Mako	1.00	
- R&r driver side cab mount	Rotell Elc Antifeerze	3.00	
- replace coolant tank	Cabin Mount Bushing	1.00	
- replace leaking rear hose	Coolant Tank	1.00	
- remove old light bar istall new and run wires to front of truck and install new controller	Cap	1.00	
- check strobes and light bar inop. trace wires and repair bad grounds. order new light bar	Light	1.00	
- Shop Supplies	Cable Tie	2.00	
	Tube Light	1.00	
	Shop Supplies	1.00	
	Freight Charge	1.00	
Hours 28.00	Labor: 1,680.00	Parts: 1,935.47	Total: 3,615.47
:	0		
Workorder: 1801946	Meter: 45964	In Date: 02/20/2018	Closed: 02/20/2018
Problem: Transport for repair			
- Tow From: He Shop To: Rechtien International			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1802070	Meter: 45964	In Date: 02/23/2018	Closed: 03/19/2018
Problem: engine repair			
- repair by rechtien			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1802121	Meter: 45964	In Date: 02/14/2018	Closed: 02/26/2018
Problem: Running Rough			
- Tow From: 3970 Hooker Hwy Belle Glade To: He shop			
	Hours 0.00	Labor: 0.00	Parts: 0.00
	:		Total: 0.00
Workorder: 1805199	Meter: 46377	In Date: 05/18/2018	Closed: 06/20/2018
Problem: List			
- repair water pump inop		Parts List	Qty
- replace strobe		valve check	1.00
- repair reel guide		tee	1.00
- replace multiplex switches at dash and solenoid boards		valve	1.00
- Shop Supplies		air solenoid	3.00
		bracket	1.00
		Strobe Lp Led	1.00
		Housing	1.00
		Shop Supplies	1.00
	Hours 14.50	Labor: 870.00	Parts: 1,010.48
	:		Total: 1,880.48
Workorder: 1806653	Meter: 46397	In Date: 06/28/2018	Closed: 08/14/2018
Problem: PM/ Jet pump			
- Pm		Parts List	Qty
- Service Ac		15-40 Oil	30.00
- Service air dryer, replace air manifold on air tank, and replaced 15' of air lines and fittings		Napa Hydraulic Filtr	1.00
- R&r vacume and Psi guages		Napagold Air Filter	1.00
- Replaced windshield washer fluid bottle and lines		Filter	1.00
- Clean and modify vacume clean out hinges		Napagold Oil Filter	1.00
- Repair electrical problems with guages		Used Fire X Refurbished	1.00
- Test run		Washer Fluid Concentr	1.00
- Shop Supplies		Wiper Blade	2.00
		Evap Odor Elinitator	1.00
		Napa Cabin Air Filter	1.00
		Reman/ad	1.00
		W P Kit	1.00
		Psi Gauge	1.00
		Vac Gauge	1.00
		Air Manifold	1.00
		Non-chlor Brake Clnr	2.00
		Tank	1.00
		Latch Clamp	2.00
		Tubing	35.00
		Fab Loom-split Poly	6.00
		Cable Tie	1.00
		Shop Supplies	1.00
		Freight Charge	1.00
	Hours 32.50	Labor: 1,950.0	Parts: 979.64
	:	0	Total: 2,929.64

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1807731	Meter: 46377	In Date: 07/31/2018	Closed: 08/23/2018
Problem: weld boom mounting base			
- Apex Welding (weld boom mount)			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1901468	Meter: 48597	In Date: 02/07/2019	Closed: 03/06/2019
Problem: Pm service.			
- Pm service.		Parts List	Qty
- Instrument cluster gauges not sweeping/ reading correctly.		Napagold Oil Filter	1.00
Replaced instrument cluster and air gauges.		15w40 Bulk Tank Pahokee	30.00
- Replace worn Rro tires.		Filter	1.00
- Replace cracked Rh headlight bulb and trim ring.		Washer Fluid Concentr	1.00
- Test drive.		22" Wiper Blade	2.00
- Shop Supplies		Rotell Elc Antifeerze	1.00
		HI Ring	1.00
		Halogen Sealed Beams	1.00
		Ring Headlight	1.00
		11r22.5 G661 Tire	2.00
		Bezel	1.00
		Cluster	1.00
		Guage Air Pressure	1.00
		Guage Air Pressure	1.00
		Shop Supplies	1.00
		Tire Disposal Fee	2.00
Hours 10.00	Labor: 670.00	Parts: 3,660.90	Total: 4,330.90
:			
Workorder: 1910145	Meter: 49153	In Date: 10/01/2019	Closed: 10/07/2019
Problem: Pm service.			
- Pm service.		Parts List	Qty
- Replace worn front tires.		Napagold Oil Filter	1.00
- Replace a/c filters.		15w40 Bulk Tank Pahokee	30.00
- Test drive.		Filter	1.00
- Shop Supplies		Washer Fluid Concentr	1.00
		22" Wiper Blade	2.00
		Rotell Elc Antifeerze	1.00
		Used Fire X Refurbished	1.00
		Napa Cabin Air Filter	1.00
		11r22.5 G661 Tire	2.00
		Shop Supplies	1.00
		Tire Disposal Fee	2.00
Hours 9.50	Labor: 693.50	Parts: 1,219.28	Total: 1,912.78
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 2001716	Meter: 49361	In Date: 02/19/2020	Closed: 02/20/2020
Problem: Won't start.			
- Jumpstart truck. Batteries passed load test once charged.	Parts List		Qty
- Fm to Bg water plant.	Shop Supplies		1.00
- Shop Supplies			
Hours 2.00	Labor: 146.00	Parts: 4.00	Total: 150.00
:			
Workorder: 2002199	Meter: 49369	In Date: 03/02/2020	Closed: 03/03/2020
Problem: Won't start.			
- Batteries failed load test. Replace batteries.	Parts List		Qty
- Fm to Bg water plant.	Group 31 Stud Delco		2.00
- Shop Supplies	Group 31 Post		1.00
	Shop Supplies		1.00
Hours 2.00	Labor: 146.00	Parts: 459.40	Total: 605.40
:			
Workorder: 2002791	Meter: 49423	In Date: 03/18/2020	Closed: 03/26/2020
Problem: Pm service, hyd leaks.			
- Pm service.	Parts List		Qty
- R&r rear door lock cyls. for rebuild.	Hoses Made 10193279		1.00
- Replaced leaking hyd hoses at upper control valve.	15w40 Bulk Tank Pahokee		30.00
- Fm to Hyd. Supply.	Napagold Oil Filter		1.00
- Test drive.	22" Wiper Blade		2.00
- Shop Supplies	Washer Fluid Concentr		1.00
	Napa Cabin Air Filter		1.00
	Filter		1.00
	Rebuilt Cyl		4.00
	Shop Supplies		1.00
Hours 12.50	Labor: 912.50	Parts: 2,060.14	Total: 2,972.64
:			
Workorder: 2003510	Meter: 49423	In Date: 04/07/2020	Closed: 04/14/2020
Problem: Boom won't move to the left.			
- Boom solenoid sticking. R&r boom control valve. Clean and reseal valve.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 7.50	Labor: 547.50	Parts: 4.00	Total: 551.50
:			
Workorder: 2004936	Meter: 49471	In Date: 05/15/2020	Closed: 05/15/2020
Problem: Transition Prep Charge			
- Transition Prep Charge			
Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00
:			