

55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 51284663 **Invoice Number:** 55345-51284663

**Client Department:** 

MRC: 5420 55345M **Equipment:** 

WO Desc: Ford E350 Champion Crusaders 1FDEE3FL3FDA06821 VIN:

PM A **Requested By: DARTHURS** Status: 40 **Created By: DARTHURS Priority:** 1

Class: WO **Driver: Arrangement:** Phone: Unassigned **Potential Warranty:** ETA: No

	Chronology	
Reported	May 18, 2018	11:22 AM
Started		
Completed	May 21, 2018	11:11 PM
Down Tir	<b>5</b> 0	

Meter	Reading	UOM		
WO		DH		
Life	188,022	DH		
System	187,836	DH		

# **WorkOrder Notes**

Line	Comment
10	COMPLAINT:
	CAUSE:
	CORRECTION:

Activity: 10 999 TOTAL VEHICLE **Activity Note:** Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

**Part Failure:** 

#### **Activity Comments**

**Parts Issued** 

Date Part Number Qty. Each Extended Description

**Labor Posted** 

Date Technician Rate Extended Hours

Activity 10 Sub Total

Parts: 0.00 Labor: 0.00

Labor Hours: 0.00 Sublet Parts: Sublet Labor:

0.00 0.00

**Activity Sub Total** 

0.00

Activity: 20

999 TOTAL VEHICLE

**Activity Note:** PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

**Part Failure:** 

#### **Activity Comments**

**Parts Issued** 

Date Part Number Description Qty. Each Extended

**Labor Posted** 

Technician Extended Date Hours Rate



55345 Palm Tran Connection v 2.2 Page 2 of 9



WorkOrder: 51284663
Invoice Number: 55345-51284663

**Client Department:** 

MRC: WO Desc:

PM A

55345M

**Equipment:** 

5420

Ford E350 Champion Crusaders

1FDEE3FL3FDA06821

Requested By: Created By:

DARTHURS DARTHURS WO VIN: Status: Priority: Driver:

40 1

Class: Arrangement: Potential Warranty:

Unassigned No Phone: ETA:

**Activity 20 Sub Total** 

Parts: Labor: 0.00 0.00

Labor Hours: 0.00 Sublet Parts: Sublet Labor:

0.00

**Activity Sub Total** 

0.00

0.00

0.00

Activity: 30

999 TOTAL VEHICLE

**Activity Note:** PRAMETER

**Reason for Repair:** 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure:

**Activity Comments** 

#### **Parts Issued**

Date Part Number Description Qty. Each	Extended
--	----------

#### **Labor Posted**

Date	Technician	Hours	Rate	Extended
	Activity	, 30 Sub	Total	

ACTIVITY 30 Sub lotal	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

#### WorkOrder 51284663 Grand Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.00
Sublet Parts: 0.00

Sublet Labor:

WorkOrder Grand Total

**Recent Repair History** 

. то оот тер	,			
WorkOrder	Date Completed	Life Meter	Class	Description
51378261	30-May-18	189,082	WO	Rear ac is not blowing
51284663	21-May-18	188,022	WO	PM A
51153912	24-Apr-18	183,650	WO	PM A

#### **Scheduled Preventative Maintenance**

Nest PM WorkOrder Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2	
----------------------------	-------------------	----------------------	---------------------	------------------------	--

#### **Other Open Repairs**



55345 Palm Tran Connection v 2.2 Page 3 of 9



**WorkOrder: 51284663 Invoice Number:** 55345-51284663

**Client Department:** 

**MRC:** 55345M **Equipment:** 5420

WO Desc: Ford E350 Champion Crusaders PM A VIN: 1FDEE3FL3FDA06821

Requested By: DARTHURS Status: 40

Created By: DARTHURS Status: 40
Created By: DARTHURS Priority: 1
Class: WO Driver:

Arrangement: Unassigned Phone: Potential Warranty: No ETA:

WorkOrder8	Date Reported	Life Meter	Class	Description
51369255	23-May-18	188,353	WO	ABS LIGHT ON
51363430	21-May-18	188,022	WO	FOLLOWUP¿¿front/rear brake pads
51153861	30-Mar-18	179,469	WO	Repalce shifter cable, serpentine belt

PH: Work Order: 51284663 Desc: PM A

Equip: 5420 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL3FDA06821

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 21-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	May 21, 2018 4:12:59 PM	No	
10,100	Safety Inspection	Done		CKARLENS	May 21, 2018 4:12:59 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	May 21, 2018 4:12:59 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		CKARLENS	May 21, 2018 4:12:59 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	May 21, 2018 4:13:00 PM	No	
10,140	Check Service Brakes	Done		CKARLENS	May 21, 2018 4:12:59 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	May 21, 2018 4:12:59 PM	No	
10,160	FRA Check Instruments and Horns	Done		CKARLENS	May 21, 2018 4:13:00 PM	No	
10,170	Check Fast Idle	Done		CKARLENS	May 21, 2018 4:13:00 PM	No	
10,180	Check Starter Protection Circuit	Done		CKARLENS	May 21, 2018 4:13:00 PM	No	
10,190	Check Reverse Warning System	Done		CKARLENS	May 21, 2018 4:13:00 PM	No	
11,100	Check Parking Brake	Done		CKARLENS	May 21, 2018 4:13:00 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		CKARLENS	May 21, 2018 4:13:00 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	May 21, 2018 4:13:00 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		CKARLENS	May 21, 2018 4:13:01 PM	No	
11,140	Road Test: Check for Proper Operation	Done		CKARLENS	May 21, 2018 4:13:01 PM	No	
11,150	Perform Brake Test	Done		CKARLENS	May 21, 2018 4:13:01 PM	No	
11,152	Decelerometer Results Test 1	FEET	na	CKARLENS	May 21, 2018 4:13:01 PM	No	
11,154	Decelerometer Results Test 2	FEET	na	CKARLENS	May 21, 2018 4:13:01 PM	No	
11,156	Decelerometer Results Test 3	FEET	na	CKARLENS	May 21, 2018 4:13:01 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	CKARLENS	May 21, 2018 4:13:01 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	na	CKARLENS	May 21, 2018 4:13:01 PM	No	
11,170	FRA Check Door Operation	Done		CKARLENS	May 21, 2018 4:13:01 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		CKARLENS	May 21, 2018 4:13:02 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		CKARLENS	May 21, 2018 4:13:01 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		CKARLENS	May 21, 2018 4:13:02 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		CKARLENS	May 21, 2018 4:13:02 PM	No	
20,230	FRA Check Wiring Under Dash	Done		CKARLENS	May 21, 2018 4:13:02 PM	No	
20,240	FRA Check Interior Lights	Done		CKARLENS	May 21, 2018 4:13:02 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		CKARLENS	May 21, 2018 4:13:02 PM	No	
20,260	Check Stop Request System	-	na	CKARLENS	May 21, 2018 4:13:03 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	na	CKARLENS	May 21, 2018 4:13:03 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	May 21, 2018 4:13:03 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	May 21, 2018 4:13:03 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		CKARLENS	May 21, 2018 4:13:03 PM	No	
22,110	Check Emergency Hatches	Done		CKARLENS	May 21, 2018 4:13:03 PM	No	
22,120	Check All Safety Equipment	Done		CKARLENS	May 21, 2018 4:13:03 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		CKARLENS	May 21, 2018 4:13:03 PM	No	
30,310	Check Passenger Doors	Done		CKARLENS	May 21, 2018 4:13:03 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		CKARLENS	May 21, 2018 4:13:03 PM	No	
30,330	Check Wheelchair Lift Operation	Done		CKARLENS	May 21, 2018 4:13:04 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	na	CKARLENS	May 21, 2018 4:13:04 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		CKARLENS	May 21, 2018 4:13:04 PM	No	
30,360	Check for Physical Damage and Decals	Done		CKARLENS	May 21, 2018 4:13:04 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		CKARLENS	May 21, 2018 4:13:04 PM	No	
30,380	Check Exterior Compartment Doors	Done		CKARLENS	May 21, 2018 4:13:04 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		CKARLENS	May 21, 2018 4:13:04 PM	No	
33,100	Check Lights and Reflectors	Done		CKARLENS	May 21, 2018 4:13:05 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	May 21, 2018 4:13:05 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		CKARLENS	May 21, 2018 4:13:05 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	May 21, 2018 4:13:05 PM	No	
40,420	Check Hood	Done		CKARLENS	May 21, 2018 4:13:05 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		CKARLENS	May 21, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					4:13:05 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	na	CKARLENS	May 21, 2018 4:13:05 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	May 21, 2018 4:13:05 PM	No	
40,442	Freeze Point	Degree Fahrenheit	na	CKARLENS	May 21, 2018 4:13:06 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	May 21, 2018 4:13:06 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	na	CKARLENS	May 21, 2018 4:13:06 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	na	CKARLENS	May 21, 2018 4:13:06 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	May 21, 2018 4:13:06 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		CKARLENS	May 21, 2018 4:13:06 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		CKARLENS	May 21, 2018 4:13:06 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	May 21, 2018 4:13:06 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		CKARLENS	May 21, 2018 4:13:07 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	May 21, 2018 4:13:07 PM	No	
44,130	FRA Check Exhaust System	Done		CKARLENS	May 21, 2018 4:13:06 PM	No	
44,140	FRA Check Intake System	Done		CKARLENS	May 21, 2018 4:13:07 PM	No	
44,150	FRA Inspect Turbocharger	-	na	CKARLENS	May 21, 2018 4:13:07 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	May 21, 2018 4:13:07 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		CKARLENS	May 21, 2018 4:13:07 PM	No	
44,180	FRA Check for Leaks	Done		CKARLENS	May 21, 2018 4:13:07 PM	No	
44,190	FRA Perform Battery Inspection	Done		CKARLENS	May 21, 2018 4:13:08 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	May 21, 2018 4:13:08 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		CKARLENS	May 21, 2018 4:13:08 PM	No	
50,510	Check Entire Steering System	Done		CKARLENS	May 21, 2018 4:13:08 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	May 21, 2018 4:13:08 PM	No	
60,610	FRA Check and Record Air Pressure	Done		CKARLENS	May 21, 2018 4:13:08 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		CKARLENS	May 21, 2018 4:13:08 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		CKARLENS	May 21, 2018 4:13:09 PM	No	
60,613	Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	May 21, 2018 4:13:09 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	May 21, 2018 4:13:09 PM	No	
60,615	Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	May 21, 2018 4:13:09 PM	No	
60,616	Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	May 21, 2018 4:13:09 PM	No	
60,620	Check Valve Stems and Caps	Done		CKARLENS	May 21, 2018 4:13:09 PM	No	
60,630	Check and Record Tread Depth	Done		CKARLENS	May 21, 2018 4:13:09 PM	No	
60,631	Tread Depth RF	8 32nds of an inch		CKARLENS	May 21, 2018 4:13:10 PM	No	
60,632	Tread Depth LF	8 32nds of an inch		CKARLENS	May 21, 2018 4:13:10 PM	No	
60,633	Tread Depth RRO	6 32nds of an inch		CKARLENS	May 21, 2018 4:13:10 PM	No	
60,634	Tread Depth RRI	6 32nds of an inch		CKARLENS	May 21, 2018 4:13:10 PM	No	
60,635	Tread Depth LRI	8 32nds of an inch		CKARLENS	May 21, 2018 4:13:10 PM	No	
60,636	Tread Depth LRO	8 32nds of an inch		CKARLENS	May 21, 2018 4:13:10 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		CKARLENS	May 21, 2018 4:13:10 PM	No	
60,650	Check Sidewall Wear	Done		CKARLENS	May 21, 2018 4:13:10 PM	No	
60,660	Inspect for Cuts and Tears	Done		CKARLENS	May 21, 2018 4:13:10 PM	No	
60,670	Check Dual Mating With Square	Done		CKARLENS	May 21, 2018 4:13:11 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	May 21, 2018 4:13:11 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		CKARLENS	May 21, 2018 4:13:11 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		CKARLENS	May 21, 2018 4:13:11 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		CKARLENS	May 21, 2018 4:13:11 PM	No	
70,710	Check Vibration Damper	Done		CKARLENS	May 21, 2018 4:13:11 PM	No	
70,720	Check Engine and Transmission Mounts	Done		CKARLENS	May 21, 2018 4:13:11 PM	No	
70,730	FRA Check Starter	Done		CKARLENS	May 21, 2018 4:13:12 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	May 21, 2018 4:13:12 PM	No	
70,750	FRA Check Transmission for Leaks	Done		CKARLENS	May 21, 2018 4:13:12 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		CKARLENS	May 21, 2018 4:13:12 PM	No	
70,770	FRA Check Exhaust System	Done		CKARLENS	May 21, 2018 4:13:12 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	May 21, 2018 4:13:12 PM	No	
70,790	Check All Body Mounts and Chassis	Done		CKARLENS	May 21, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Frame				4:13:13 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	May 21, 2018 4:13:13 PM	No	
77,110	FRA Check Fuel Tank	Done		CKARLENS	May 21, 2018 4:13:13 PM	No	
77,120	Check Suspension Components	Done		CKARLENS	May 21, 2018 4:13:13 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	May 21, 2018 4:13:13 PM	No	
77,131	Brake Pad Thickness LF	3 Inch	REPLACE FRONT BRAKED PADS	CKARLENS	May 21, 2018 4:25:27 PM	Yes	51363430
77,132	Brake Pad Thickness RF	5 Inch		CKARLENS	May 21, 2018 4:13:13 PM	No	
77,133	Brake Pad Thickness LR	5 Inch	REPLACE REAR BRAKE PADS	CKARLENS	May 21, 2018 4:25:28 PM	Yes	51363430
77,134	Brake Pad Thickness RR	5 Inch		CKARLENS	May 21, 2018 4:13:13 PM	No	
77,135	Brake Rotor LF	39.8 Inch		CKARLENS	May 21, 2018 4:13:13 PM	No	
77,136	Brake Rotor RF	39.8 Inch		CKARLENS	May 21, 2018 4:13:14 PM	No	
77,137	Brake Rotor LR	35.8 Inch		CKARLENS	May 21, 2018 4:13:14 PM	No	
77,138	Brake Rotor RR	35.8 Inch		CKARLENS	May 21, 2018 4:13:14 PM	No	
77,140	FRA Check Brake Hoses	Done		CKARLENS	May 21, 2018 4:13:14 PM	No	
77,150	Check King Pins	-	na	CKARLENS	May 21, 2018 4:13:14 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	May 21, 2018 4:13:15 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		CKARLENS	May 21, 2018 4:13:15 PM	No	
80,810	Completion of PMI Report	Done		CKARLENS	May 21, 2018 4:13:15 PM	No	
90,000	SECTION 9 Completion of PMI	Done		CKARLENS	May 21, 2018 4:13:15 PM	No	
90,910	Vehicle Returned to predetermined location	Done		CKARLENS	May 21, 2018 4:13:15 PM	No	

LH: 20 Desc: PM A

Task: PM A SERVICE Performed by: CKARLENS Performed on: 21-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		CKARLENS	May 21, 2018 4:15:48 PM	No	
101,000	FRA Change Oil Filters	Yes		CKARLENS	May 21, 2018 4:15:49 PM	No	
102,000	FRA Drain Engine Oil	Yes		CKARLENS	May 21, 2018 4:15:49 PM	No	
103,000	FRA Check Transmission Fluid	Done		CKARLENS	May 21, 2018 4:15:49 PM	No	
104,000	Lubricate Chassis	Done		CKARLENS	May 21, 2018 4:15:48 PM	No	
105,000	Replace or Clean A/C Filters	Done		CKARLENS	May 21, 2018 4:15:49 PM	No	
107,000	FRA Change Primary Fuel Filter	No	na	CKARLENS	May 21, 2018 4:15:50 PM	No	
108,000	Lube all pivoting Mechanisms	Done		CKARLENS	May 21, 2018 4:15:49 PM	No	

**LH: 30 Desc: PRAMETER** 

# Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 21-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	May 21, 2018 4:17:41 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 51443902 **Invoice Number:** 55345-51443902

**Client Department:** 

MRC: WO Desc: 55345M

**Equipment:** 

Ford E350 Champion Crusaders

Meter

PM A

**DARTHURS** 

VIN: Status:

1FDEE3FL3FDA06821 40

Requested By: Created By: Class:

**DARTHURS** WO

**Priority: Driver:** 

1

**Arrangement: Potential Warranty:**  Unassigned

Phone: ETA:

Reported Started Completed Chronology Jul 13, 2018 Jul 13, 2018 Jul 16, 2018

4:04 PM 8:35 AM

WO DH Life 196,078 DH System 196,279 DH

Reading

MOU

**Down Time** 

**WorkOrder Notes** 

Line		Comment
10	COMPLAINT:pmA	

CAUSE:Service

CORRECTION: Perform pmA Service Oil filter B329 qty1 Engine oil 5w20 gty 7 gts Fixed right rear inside tire Torque wheels 140 lbs second torque wheels 140 lbs

Activity: 10 **Activity Note:** Reason for Repair:

999 TOTAL VEHICLE Light Medium Duty PMI 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 

#### **Parts Issued**

Date Part Number Description

Qty. Each Extended

**Labor Posted** 

Date	Technician	Hours	Rate	Extended
13-Jul-18	Gaspard,Ronald	1.53	0.00	0.00

**Activity 10 Sub Total** 

0.00 Parts: Labor: 0.00 Labor Hours: 1.53 0.00

Sublet Parts: Sublet Labor: **Activity Sub Total** 

0.00 0.00

Activity: 20

999 TOTAL VEHICLE

**Activity Note:** 

PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 51512517 **Invoice Number:** 55345-51512517

Client Department:

MRC:

WO Desc: PM A

Reported

Completed

Started

Requested By: Created By: Class: Arrangement:

**Potential Warranty:** 

55345M

**CVERGARA** 

**CVERGARA** 

**Equipment:** 

VIN: Status: Priority:

Driver:

WO Unassigned No

Phone: ETA:

5420

Ford E350 Champion Crusaders 1FDEE3FL3FDA06821

40 1

Chronology

Aug 9, 2018 Aug 9, 2018 Aug 9, 2018 11:33 AM 11:58 PM

UOM Reading Meter DH WO 200,454 DH Life

**Down Time** 

**WorkOrder Notes** 

Line	Comment
10	COMPLAINT:pmA
	CAUSE: Service
	CORRECTION:Perform pmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts Air filter PA4075 qry1

Activity: 10 **Activity Note:** 

999 TOTAL VEHICLE

Light Medium Duty PMI 08 - Preventive Maintenance

Reason for Repair: Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 

**Parts Issued** 

Part Number Date

Description

Qty. Each Extended

abor Post	ed	Hours	Rate	Extended
Date	Technician	1.57	0.00	0.00
09-Aug-18	Gaspard,Ronald			

Activity 10 Sub Total

Parts: Labor:

Labor Hours: 1.57 Sublet Parts: Sublet Labor:

0.00 0.00 0.00

0.00

**Activity Sub Total** 

0.00

Activity: 20

999 TOTAL VEHICLE

PM A

**Activity Note:** 08 - Preventive Maintenance Reason for Repair:

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 51692577 **Invoice Number:** 55345-51692577

MOU

**Client Department:** 

MRC: WO Desc:

Reported

Completed

Started

55345M

Equipment:

5420

Ford E350 Champion Crusaders

PM A

VIN:

1FDEE3FL3FDA06821

Meter

Requested By: Created By:

**RGASPARD RGASPARD** WO

Status: Priority: Driver:

40 1

Class: Arrangement: **Potential Warranty:** 

Unassigned No

Phone: ETA:

Chronology

Oct 9, 2018

Oct 5, 2018

7:53 AM 8:29 AM

wo DH Life 209,526 DH 209,157 DH System

Reading

**Down Time** 

Comment

WorkOrder Notes

Line 10 COMPLAINT: pmA

CAUSE: Preventive Maintenance

CORRECTION: Perform Service lube all Pivoting Points Completed

Part Number

Activity: 10 **Activity Note:** 

999 TOTAL VEHICLE Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 

**Parts Issued** Date

**Labor Posted** 

Date

Technician

Hours

Rate

Qty. Each

Extended

**Activity 10 Sub Total** 

0.00

Parts: Labor:

Description

0.00

Labor Hours: 0.00

Sublet Parts:

Sublet Labor:

0.00

0.00

**Activity Sub Total** 

0.00

Activity: 20 **Activity Note:** 

999 TOTAL VEHICLE

Reason for Repair:

PM A 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 

**Parts Issued** 

Date	Part Number	Description	Qty, Each Exte	nded
09-Oct-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00 1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 51793850 Invoice Number: 55345-51793850

UOM

**Client Department:** 

MRC: WO Desc:

PM A

55345M

**Equipment:** 

5420

Ford E350 Champion Crusaders

Meter

1FDEE3FL3FDA06821

Requested By: Created By:

**CVERGARA CVERGARA** WO

Status: **Priority:** 

32 1

Class: Arrangement: **Potential Warranty:** 

Unassigned No

**Driver:** Phone: ETA:

VIN:

Chronology Reported

Started Completed

Nov 23, 2018 Nov 23, 2018 Nov 26, 2018

11:33 AM 9:22 AM

Reading WO DH Life 213,872 DH

**Down Time** 

**WorkOrder Notes** 

Line	Comment
10	COMPLAINT: PMA
	CAUSE: Service due
	CORRECTION: Performed and completed PMA Changed engine oil and replaced oil filter Changed rear AC filter

Activity: 10 **Activity Note:** 

999 TOTAL VEHICLE

Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 

**Parts Issued** 

Date Part Number Description

Each Extended

**Labor Posted** 

Date	Technician	Hours	Rate	Extended
23-Nov-18	Delva,Terry	0.62	0.00	0.00

Activity 10 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 0.62 Sublet Parts: Sublet Labor:

0.00 0.00

**Activity Sub Total** 

0.00

Activity: 20

999 TOTAL VEHICLE

**Activity Note:** Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 

Date	Part Number	Description	Qty.	Each	Extended
23-Nov-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52021828 **Invoice Number:** 55345-52021828

UOM

**Client Department:** 

MRC: WO Desc:

Started

Completed

PM A

55345M

**Equipment:** 

5420

Ford F350 Champion Crusaders

VIN:

1FDEE3FL3FDA06821

Meter

Requested By: Created By:

Status: **Priority:**  40 1

Class: Arrangement:

**Potential Warranty:** 

VAMRITTEEMAL WO

Driver:

Unassigned No

VAMRITTEEMAL

Phone: ETA:

Chronology Reported

Jan 22, 2019 Jan 22, 2019

Jan 23, 2019

8:44 AM

7:55 AM

Reading wo DH Life 222,895 DH

**Down Time** 

# **WorkOrder Notes**

Line	Comment
10	COMPLAINT:Perform PM-A
	CAUSE: Preventive Maintenance
	CORRECTION: Tech Performed PmA

Activity: 10

999 TOTAL VEHICLE

**Activity Note:** Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

#### **Activity Comments**

#### **Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended	

#### **Labor Posted**

Date	Technician	Hours	Rate	Extended
22-Jan-19	KARLENS,Cyrius	2.00	0.00	0.00

Activity 10 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 2.00 Sublet Parts:

0.00

Sublet Labor:

0.00

**Activity Sub Total** 

0.00

Activity: 20

999 TOTAL VEHICLE

**Activity Note:** 

PM A

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

**Part Failure:** 

#### **Activity Comments**

Date	Part Number	Description	Qty.	Each	Extended
22-Jan-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52103461 **Invoice Number:** 55345-52103461

**Client Department:** 

MRC:

55345M

**Equipment:** 

5420

WO Desc:

PM A

VIN:

Ford E350 Champion Crusaders 1FDEE3FL3FDA06821

Requested By: Created By:

**CVERGARA CVERGARA** WO

Status: **Priority:**  40 1

Class: **Arrangement:** 

Started

Completed

**Potential Warranty:** 

Unassigned

**Driver:** 

Phone: ETA:

Reported

Chronology Feb 19, 2019 Feb 20, 2019 Feb 20, 2019

No

10:06 AM 12:18 AM

Meter Reading MOU wo DH Life 227.024 DH System 227,184 ÐΗ

**Down Time** 

**WorkOrder Notes** 

Line COMPLAINT: Perform PMA Service 10

CAUSE: Service Due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points, check Brakes, clean batteries. Replace Air Filter.

Comment

Parts# B329 Qty (1) Parts #PA4075 Qty (1) Oil 5W200TY (6.5) Ot

Activity: 10 **Activity Note:** 

Reason for Repair:

999 TOTAL VEHICLE

Light Medium Duty PMI 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 

Parts Issued

Date Part Number Description

Labor Posted

Date Technician Hours Rate Extended 20-Feb-19 Arthurs, Durvin 1.50 0.00 0.00

Activity 10 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 1.50 Sublet Parts: Sublet Labor:

0.00 0.00

**Activity Sub Total** 

0.00

Activity: 20

999 TOTAL VEHICLE

**Activity Note:** Reason for Repair:

PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 



55345 Palm Tran Connection v 2.2

Page 1 of 9

VIN:



WorkOrder: 52255721 Invoice Number: 55345-52255721

**Client Department:** 

MRC: WO Desc:

PM A

55345M

Equipment:

5420

Ford E350 Champion Crusaders

1FDEE3FL3FDA06821

Requested By: Created By:

Completed

**CVERGARA CVERGARA**  Status: **Priority:**  40 1

Class: Arrangement: **Potential Warranty:** 

WO Unassigned No

Chronology

**Driver:** 

Phone: ETA:

Reported Started

Apr 9, 2019 Apr 9, 2019 Apr 9, 2019

11:01 PM

3:30 PM

Meter Reading UOM WO DH Life 235,560 DH

**Down Time** 

WorkOrder Notes

Line Comment 10 COMPLAINT: pmA Service

CAUSE: preventive maintenance

CORRECTION: Perform and completed pmA Service

Activity: 10

999 TOTAL VEHICLE

**Activity Note:** Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 

Parts Issued

Date Part Number Description	Qty. Each Extended

# **Labor Posted**

Date	Technician	Hours	Rate	Extended
09-Apr-19	AMRIT TEEMAL,VISHNU	1.00	0.00	0.00

Activity 10 Sub Total

Parts: 0.00 Labor: 0.00 Labor Hours: 1.00

Sublet Parts: 0.00 Sublet Labor: 0.00 0.00

**Activity Sub Total** 

Activity: 20

999 TOTAL VEHICLE

**Activity Note:** PM A Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

#### **Activity Comments**

Date	Part Num	ber Description	Qty. Each Ex	dended
10-Арг-19	B329(F)	FILTER, OIL SAME AS LF3681	-1.00 1.96	-1.96
09-Apr-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00 1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



**Invoice Number: 55345-52329310** 

**Client Department:** 

MRC:

WO Desc:

PM A Requested By:

Created By: Class:

**Arrangement: Potential Warranty:**  55345M

WO

No

VAMRITTEEMAL

VAMRITTEEMAL

Unassigned

**Equipment:** 

5420

40

1

11:03 AM

11:55 PM

Ford E350 Champion Crusaders

1FDEE3FL3FDA06821

VIN: Status:

**Priority:** 

Driver: Phone: ETA:

	Chronology		
Reported	May 3, 2019		

Started May 3, 2019 Completed May 3, 2019

**Down Time** 

Meter	Reading	UOM
wo		DH
Life	239,877	DH
System	240,072	DH

**WorkOrder Notes** 

Line	Comment
10	COMPLAINT:PMA
	CAUSE: Service
	CORRECTION:Perform PMA Service Oil filter B329 qty1

Engine oil 5W20 qty 7 Qts

Activity: 10 **Activity Note:** 

999 TOTAL VEHICLE

Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 

**Parts Issued** 

Date Part Number Description Qty. Each Extended

**Labor Posted** 

Date	Technician	Hours	Rate	Extended
03-May-19	Gaspard,Ronald	1.62	65.00	105.08

**Activity 10 Sub Total** 

Parts:

Labor:

Labor Hours: 1.62

Sublet Parts:

Sublet Labor:

105.08

0.00 0.00

0.00

105.08

**Activity Sub Total** 

Activity: 20

999 TOTAL VEHICLE

**Activity Note:** 

PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 

Date	Part Number	Description	Qty.	Each	Extended
03-May-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52463333 Invoice Number: 55345-52463333

**Client Department:** 

MRC: WO Desc: 55345M

Equipment:

5420

Ford E350 Champion Crusaders

PM A

VIN:

1FDEE3FL3FDA06821

Requested By: Created By:

**CKARLENS CKARLENS**  Status: **Priority:** 

40 1

Class: Arrangement: WO Unassigned Driver: Phone:

**Potential Warranty:** 

No

ETA:

	Chronology	
Reported	Jun 18, 2019	12:20 PM
Started	Jun 18, 2019	
Completed	Jun 18, 2019	10:44 PM

UOM Meter Reading WO DH Life 248,083 DH

WorkOrder Notes

Line 10

Comment

**Down Time** 

COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10

999 TOTAL VEHICLE

**Activity Note:** Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

**Part Failure:** 

**Activity Comments** 

**Parts Issued** 

Date Part Number Description

Each Extended

**Labor Posted** 

18-Jun-19	AMRIT TEEMAL, VISHNU	1.00	65.00	65.00	
Date	Technician	Hours	Rate	Extended	1

**Activity 10 Sub Total** 

Parts: Labor:

0.00 65.00

Labor Hours: 1.00 Sublet Parts:

0.00

Sublet Labor:

0.00

**Activity Sub Total** 

65.00

Activity: 20

999 TOTAL VEHICLE

**Activity Note:** PM A Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 

18-Ju	Part Number B329(F)	Description FILTER, OIL SAME AS LF3681	Qty. Each 1.00 1.96	
}	 5525(1)	TICTER, OIL SAME AS EFSOOT	1.00 1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52529112 **Invoice Number:** 55345-52529112

UOM

**Client Department:** 

MRC: WO Desc: 55345M

**Equipment:** 

5420

Ford E350 Champion Crusaders

1FDEE3FL3FDA06821

Meter

PM A Requested By: Created By:

**VAMRITTEEMAL** VAMRITTEEMAL Status: Priority: 40 1

Class: **Arrangement: Potential Warranty:**  WO Unassigned No

Driver: Phone:

ETA:

VIN:

Jul 16, 2019 Jul 16, 2019 Started Completed Jul 16, 2019

10:28 PM

12:00 AM

Reading WO DH Life 252,684 DH

**Down Time** 

**WorkOrder Notes** 

Line Comme	nt
------------	----

COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10 **Activity Note:** 

999 TOTAL VEHICLE Light Medium Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 

#### **Parts Issued**

Date Part Number	Description Oty, Each Extended

#### **Labor Posted**

. 2	Date 16-Jul-19	Technician  AMRIT TEEMAL-VISHNU	1	lours		Extended
1.1	10-541-13	: MUNCL LEEDING ASSESSO		1.00	65.00	65.00

#### **Activity 10 Sub Total**

Parts: Labor:

0.00 65.00

Labor Hours: 1.00

Subjet Parts: 0.00 Sublet Labor: 0.00

**Activity Sub Total** 

65.00

Activity: 20

999 TOTAL VEHICLE

**Activity Note:** PM A Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 

Date	Pai	t Number				Description	Qty.	Each	Extended	
16-Jul-19	B329(F)		FILTE	R, OIL SAM	E AS LF3681		1.00	1.96	1.96	
 the control of the second of the second of		~;~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	nang manusi ang m	es moneyanistical	-55 12 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	management and an early seem	 er er Grenninger ser	transa ng Paga	ng na aran mangagah	į



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52698376 Invoice Number: 55345-52698376

**Client Department:** 

MRC: WO Desc: 55345M

**Equipment:** 

5420

Ford E350 Champion Crusaders

1FDEE3FL3FDA06821

PM A Requested By:

**RGASPARD** 

VIN: Status:

32

Created By:

**RGASPARD** WO

**Priority:** Driver:

1

Class: **Arrangement: Potential Warranty:** 

Unassigned No

Phone:

ETA:

Reported	Chronology Sep 13, 2019
izoborcon	3ch 13, 2013

Started Sep 14, 2019 Completed Sep 14, 2019

12:07 PM 12:22 AM

Meter UOM Reading wo DH Life 261,140 DH

**Down Time** 

WorkOrder Notes

Line Comment COMPLAINT: PmA

CAUSE: Service

10

CORRECTION: perform PmA Service Oil filter B329 Qty1

Engine oil 5w20 qty 7 qts

Activity: 10 **Activity Note:** 

999 TOTAL VEHICLE Light Medium Duty PMI

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 

Parts Issued

Date Part Number Description

Qty. Each Extended

**Labor Posted** 

Date	Technician	Hours	Rate E	Extended	
14-Sep-19 Gaspard,Ronald		1.62	65.00	105.08	Access of the last

**Activity 10 Sub Total** 

Parts: Labor:

0.00 105.08

Labor Hours: 1.62

Sublet Parts: Sublet Labor:

0.00 0.00

**Activity Sub Total** 

105.08

Activity: 20 999 TOTAL VEHICLE

**Activity Note:** Reason for Repair:

PM A 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 

	14-Sep-19 B329(F)	FILTER, OIL SAME AS LF3681	1.00 1.96 1.96
1.1	2. 30p 23	TALTERY OLE SAME AS A SOCI	1,00 1,00 1,70



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52790974 **Invoice Number:** 55345-52790974

**Client Department:** 

MRC:

55345M

**Equipment:** 

5420

WO Desc:

PM A

VIN:

Ford E350 Champion Crusaders 1FDEE3FL3FDA06821

Requested By: Created By:

**RGASPARD RGASPARD**  Status: **Priority:**  40 1

Class:

Started

Completed

WO

**Driver:** Phone:

Arrangement: **Potential Warranty:** 

Unassigned Νo

ETA:

Chronology Reported

Oct 8, 2019 Oct 8, 2019 Oct 9, 2019 12:00 AM 12:16 AM

WO DH Life 265,746 DH

Reading

MOU

Meter

**Down Time** 

WorkOrder Notes

10	COMPLAINT: pmA
Line	Comment

CAUSE: Service

CORRECTION: perform pmA service Oil filter B329 qty1

Engine oil 5w20 qty 7 Ots

Activity: 10 **Activity Note:** 

Reason for Repair:

999 TOTAL VEHICLE

Light Medium Duty PMI 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

#### **Activity Comments**

#### Parts Issued

Date Part Numl	er i	Description	Qty. Each Extended

#### **Labor Posted**

Date	Technician	Hours	Rate	Extended
08-Oct-19	Gaspard,Ronald	1.58	65.00	102.92

#### Activity 10 Sub Total

Parts: Labor:

0.00 102.92

Labor Hours: 1.58 Sublet Parts: Sublet Labor:

0.00 0.00

**Activity Sub Total** 

102.92

Activity: 20 **Activity Note:** 

999 TOTAL VEHICLE

PM A

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

#### **Activity Comments**

Date Part Nu	mber Description	Qty.	Each	Extended
08-Oct-19 B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52955192 Invoice Number: 55345-52955192

UOM

**Client Department:** 

MRC:

Reported

Completed

Started

55345M

**Equipment:** 

5420

WO Desc:

PM A

VIN:

Ford E350 Champion Crusaders

Meter

1FDEE3FL3FDA06821

Requested By: Created By:

**RGASPARD RGASPARD**  Status: **Priority:**  40 1

Class:

WO Unassigned

Driver: Phone:

**Arrangement: Potential Warranty:** 

No

ETA:

Chronology Nov 22, 2019

Nov 22, 2019 Nov 22, 2019

8:11 PM

4:31 PM

WO DH Life 274,615 DH

Reading

**Down Time** 

**WorkOrder Notes** 

Line	Comment		
10	COMPLAINT: PMA SERVICE		

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10

999 TOTAL VEHICLE

**Activity Note:** Light Medium Duty PMI 08 - Preventive Maintenance Reason for Repair:

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 

#### **Parts Issued**

Date	Part Number	Description	Qty. Each Extended

# **Labor Posted**

Date	Technician	Hours	Rate	Extended
22-Nov-19	AMRIT TEEMAL, VISHNU	1.50	65.00	97.50

**Activity 10 Sub Total** 

Parts: Labor:

0.00 97.50

Labor Hours: 1.50 Sublet Parts:

0.00

Sublet Labor:

0.00

**Activity Sub Total** 

97.50

Activity: 20

999 TOTAL VEHICLE

**Activity Note:** PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:


**Activity Comments** 

Date	Part Number	Description	Qty.	Each	Extended
22-Nov-19 B32	9(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 53030832 **Invoice Number:** 55345-53030832

**Client Department:** 

MRC:

55345M

No

Equipment:

5420

WO Desc: PM A

VAMRITTEEMAL

VIN:

Ford E350 Champion Crusaders

1FDEE3FL3FDA06821

Requested By: Created By:

VAMRITTEEMAL

Status: **Priority:**  40 1

6:27 PM

Class:

Started

10

Completed

**Arrangement: Potential Warranty:**  WO Unassigned Driver:

Phone: ETA:

Chronology Reported

Dec 23, 2019 Dec 23, 2019 Dec 23, 2019 12:24 PM

Meter Reading UOM WO DH Life 279,034 DH

**Down Time** 

**WorkOrder Notes** 

Line Comment COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10

999/999/999 TOTAL VEHICLE

**Activity Note:** 

Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -Part Failure:

**Activity Comments** 

**Parts Issued** 

11210 Dart Number Decembries	
Date Part Number Description	Oty. Each Extended

# **Labor Posted**

Activity 10 Sub Total

Parts: 0.00 Labor: 72.80 Labor Hours: 1.12

Subjet Parts: Sublet Labor:

0.00 0.00

**Activity Sub Total** 

72.80

Activity: 20

999 TOTAL VEHICLE

**Activity Note:** PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure:

**Activity Comments** 

Date	Part Number		Description	Qty. Each Extende	d
23-Dec-19	B329(F)	FILTER, OIL	SAME AS LF3681	1.00 1.96 1.9	6



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 53208556 **Invoice Number:** 55345-53208556

**Client Department:** 

MRC:

55345M

Equipment:

5420

Ford E350 Champion Crusaders

Meter

WO

Life

Reading

287,604

UOM

DH

DΗ

WO Desc: PM A

**NPIERRE-LOUIS** 

**Down Time** 

VIN:

1FDEE3FL3FDA06821

Requested By: Created By:

**NPIERRE-LOUIS** WO

Status: **Priority:**  40 1

Class: **Arrangement:** 

Unassigned

Driver: Phone:

**Potential Warranty:** 

No

ETA:

i		Chronology	
1	Reported	Feb 17, 2020	2:40 PM
į	Started	Feb 17, 2020	
:	Completed	Feb 17, 2020	6:58 PM

WorkOrder Notes

Line Comment COMPLAINT: pmA 10

CAUSE: Service due

CORRECTION: Performed and completed pmA Replaced air intake filter

Activity: 10

999/999/999 TOTAL VEHICLE

**Activity Note:** Light Duty PMI Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: **Part Failure:** 

**Activity Comments** 

**Parts Issued** 

Date Part Number Description Each Extended

**Labor Posted** 

Date	Technician	Hours	Rate	Extended
17-Feb-20	Delva,Terry	2.33	0.00	0.00

**Activity 10 Sub Total** 

Parts: 0.00 Labor: 0.00 Labor Hours: 2.33 0.00

Sublet Parts: Sublet Labor: 0.00 **Activity Sub Total** 0.00

Activity: 20

999 TOTAL VEHICLE

**Activity Note:** Reason for Repair: PM A

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

**Part Failure:** 

**Activity Comments** 

1	17-Feb-20	B329(F)	FILTER, OIL, SPIN-ON	1.00 1.96 1.96
1.	Date	Part Number	Description	Qty. Each Extended



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 53293288 Invoice Number: 55345-53293288

**Client Department:** 

MRC:

WO Desc: PM A

Requested By: Created By: Class:

**Arrangement: Potential Warranty:**  55345M

**Equipment:** 

5420

Ford E350 Champion Crusaders

Reading

291,536

UOM

DH

DH

1FDEE3FL3FDA06821

**TDELVA TDELVA** WO

Unassigned

**Priority: Driver:** Phone: ETA:

Status:

VIN:

40 1

Chronology Reported Apr 8, 2020 12:56 PM Started Apr 8, 2020 Completed Apr 9, 2020

No

**Down Time** 

WO 8:20 AM Life

Meter

WorkOrder Notes

Line Comment 10 COMPLAINT: PMA

CAUSE: service

CORRECTION: Perform PMA service Oil filter B329 gty1 Engine oil 10w20 qty 7 qts

Activity: 10

999/999/999 TOTAL VEHICLE

Light Duty PMI

**Activity Note:** 

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -Part Failure:

**Activity Comments** 

**Parts Issued** 

Date Part Number Description Each Extended

**Labor Posted** 

Date Technician Hours Rate Extended 08-Apr-20 Gaspard, Ronald 1,45 0.00 0.00

Activity 10 Sub Total

Parts: 0.00 Labor: 0.00 Labor Hours: 1.45 Sublet Parts: 0.00 Sublet Labor: 0.00

**Activity Sub Total** 

0.00

Activity: 20 999 TOTAL VEHICLE **Activity Note:** PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A


Part Failure:

**Activity Comments** 

 08-Apr-20	B329(F)	FILTER, OIL, SPIN-ON SEE BALDWIN B329	1.00 1.96 1.96
Date	Part Number	Description	Qty. Each Extended



55345 Palm Tran Connection v 2.2 Page 1 of 10



WorkOrder: 53558548 Invoice Number: 55345-53558548

**Client Department:** 

MRC:

WO Desc:

Reported

Completed

Started

10

55345-LIGHT DUTY PMA

Requested By: Created By: Class:

Arrangement: **Potential Warranty:**  55345M

**NSTOLFO** 

**NSTOLFO** 

Unassigned

Jun 22, 2020

Jun 23, 2020

Jun 23, 2020

WO

No

Chronology

**Equipment:** 

5420

3

Ford E350 Champion Crusaders

Reading

299.977

299,977

UOM

DH

DΗ

DH

VIN:

1FDEE3FL3FDA06821 40

Status: **Priority:** 

Driver:

Phone: ETA:

12:00 AM	Meter WO
7:16 PM	Life

System

WorkOrder Notes

Line Comment

COMPLAINT: pmA

CAUSE:Service

CORRECTION: Perform pmA Service Oil filter B329 qty1 Engine oil 10w30 atv 7 Ots Replaced driver side head Light 9008 qty1

Activity: 5

999/999/999 TOTAL VEHICLE

**Down Time** 

**Activity Note:** PERSONAL RISK ASSESSMENT

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect Part Failure: 00 - No Failure

**Activity Comments** 

**Parts Issued** 

Date Part Number Description

Qty. Each Extended

Rate

**Labor Posted** 

Date

Technician

Extended

Activity 5 Sub Total

Hours

Parts: Labor:

0.00 0.00

Labor Hours: 0.00

Sublet Parts: Sublet Labor:

0.00 0.00

**Activity Sub Total** 

0.00

Activity: 10

999/999/999 TOTAL VEHICLE

**Activity Note:** Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -Part Failure:

**Activity Comments** 

**Parts Issued** 

Date Part Number Description Each Extended



55345 Palm Tran Connection v 2.2 Page 1 of 10



WorkOrder: **53644730 Invoice Number:** 55345-53644730

UOM

**Client Department:** 

MRC: WO Desc: 55345M

Equipment:

5420

Ford E350 Champion Crusaders

55345-LIGHT DUTY PMA

VIN: RGASPARD State 1FDEE3FL3FDA06821 40

Requested By: Created By: Class:

RGASPARD WO Status: Priority: Driver:

: 3

Arrangement:
Potential Warranty:

Unassigned No Phone: ETA:

Chronology

 Reported
 Jul 27, 2020

 Started
 Jul 28, 2020

 Completed
 Jul 28, 2020

12:23 PM

12:00 AM

WO DH
Life 304,501 DH
System 304,501 DH

Reading

Meter

**Down Time** 

#### **WorkOrder Notes**

Line	Comment			
10	COMPLAINT: PmA			
	CAUSE: Service due			

Activity: 5

999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT Reason for Repair: SW - Shop Work Order

CORRECTION: Performed and completed pmA

Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

**Activity Comments** 

**Parts Issued** 

Date Part Number Description Qty. Each Extended

**Labor Posted** 

Date Technician Hours Rate Extended

Activity 5 Sub Total
Parts:
Labor:

**Activity Sub Total** 

0.00 0.00

Labor Hours: 0.00 Sublet Parts: Sublet Labor:

0.00 0.00

Activity: 10

999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

**Reason for Repair:** 08 - Preventive Maintenance

Work Accomplished: Part Failure: -

**Activity Comments** 

**Parts Issued** 

Date Part Number Description Qty. Each Extended



55345 Palm Tran Connection v 2.2 Page 1 of 10



WorkOrder: 53822774 Invoice Number: 55345-53822774

**Client Department:** 

MRC: WO Desc:

Completed

55345-LIGHT DUTY PMA

**Requested By: Created By:** Class:

**Arrangement: Potential Warranty:** 

**Equipment:** 5420 55345M Ford E350 Champion Crusaders

VIN:

Status: **Priority: Driver:** 

Phone: ETA:

3

12:00 AM

12:30 AM

1FDEE3FL3FDA06821 40

> UOM Meter Reading WO DH Life 312,589 DH

Chronology

WO

No

**DARTHURS** 

**DARTHURS** 

Unassigned

Reported Oct 5, 2020 Oct 5, 2020 Started

Oct 6, 2020

**Down Time** 

#### **WorkOrder Notes**

l	Line	Comment			
	10	COMPLAINT:PMA			
		CAUSE: Service			
		CORRECTION:Perform pmA Service Oil filter B329 qty1 Engine oil 10w30 qty 7 qts			

Activity: 5

999/999/999 TOTAL VEHICLE

**Activity Note:** PERSONAL RISK ASSESSMENT

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect Part Failure: 00 - No Failure

**Activity Comments** 

Parts Issued

Date Part Number Qty. Each Extended Description

**Labor Posted** 

Date Technician Extended Hours Rate

**Activity 5 Sub Total** 

Parts: Labor:

Labor Hours: 0.00 Sublet Parts: Sublet Labor:

0.00 0.00

**Activity Sub Total** 

0.00

0.00

0.00

Activity: 10 **Activity Note:** 

999/999/999 TOTAL VEHICLE

Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -**Part Failure:** 

**Activity Comments** 

**Parts Issued** 

Qty. Each Extended Date Part Number Description



55345 Palm Tran Connection v 2.2 Page 1 of 10



WorkOrder: 53934293 **Invoice Number:** 55345-53934293

**Client Department:** 

MRC: WO Desc:

Started

**Equipment:** 55345M

5420

Ford E350 Champion Crusaders

VIN:

1FDEE3FL3FDA06821

55345-LIGHT DUTY PMA **Requested By: Created By:** 

**RGASPARD RGASPARD** WO

Status: **Priority: Driver:** 

40 3

Class: **Arrangement: Potential Warranty:** 

Unassigned

No

Phone:

ETA:

Chronology

Nov 11, 2020 Reported Nov 11, 2020 Completed Nov 11, 2020 12:00 AM 10:16 PM

Reading UOM Meter WO DH Life 317,053 DH

**Down Time** 

#### **WorkOrder Notes**

Line	Comment			
10	COMPLAINT: PMA Service			
	CAUSE: Service Due by Mileage.			
	CORRECTION: Change Oil & Filter. Lube all Pivoting Points . Check brakes. Clean batteries. Replace A/C Filter Parts # B329 Qty (1) Oil 10W30 Qty (6.5) Qt			

Activity: 5

999/999/999 TOTAL VEHICLE

**Activity Note:** PERSONAL RISK ASSESSMENT

Reason for Repair: SW - Shop Work Order Work Accomplished: 06 - Inspect

Part Failure: 00 - No Failure

**Activity Comments** 

Parts Issued

Date Part Number Qty. Each Extended Description

**Labor Posted** 

Date Technician Extended Hours Rate

**Activity 5 Sub Total** 

Parts: Labor:

Sublet Labor:

Labor Hours: 0.00 Sublet Parts:

0.00 0.00

**Activity Sub Total** 

0.00

0.00

0.00

Activity: 10

999/999/999 TOTAL VEHICLE

**Activity Note:** Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -**Part Failure:** 

**Activity Comments** 

**Parts Issued** 

Qty. Each Extended Date Part Number Description



55345 Palm Tran Connection v 2.2 Page 1 of 9

**Invoice Number:** 55345-51935078

**Client Department:** 

MRC:

WO Desc: PM B

Reported

Completed

Started

55345M

WO

**Equipment:** 

5420

Ford E350 Champion Crusaders

Meter

Reading

218,623

UOM

DH

DH

1FDEE3FL3FDA06821

Requested By:

Created By: Class: **Arrangement: Potential Warranty:**  **CVERGARA CVERGARA** 

Status: **Priority:** Driver:

40 1

Unassigned No

Phone: ETA:

VIN:

Chronology Dec 24, 2018 12:00 AM

Dec 24, 2018 Dec 24, 2018

WO 9:41 PM Life

**Down Time** 

#### **WorkOrder Notes**

Line	Comment
10	COMPLAINT: PMB Service
	CAUSE: Preventive Maintenance
	CORRECTION: Perform and completed PMB Service

Activity: 10 **Activity Note:** 

999 TOTAL VEHICLE

Light Mediun Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure:

#### **Activity Comments**

#### **Parts Issued**

Date Part Number Description Each Extended

# **Labor Posted**

Date	Technician	Hours	Rate	Extended
24-Dec-18	AMRIT TEEMAL, VISHNU	1.50	0.00	0.00

Activity 10 Sub Total

Parts: Labor: 0.00 0.00

Labor Hours: 1.50 Sublet Parts:

0.00

Sublet Labor:

0.00

**Activity Sub Total** 

0.00

Activity: 20

999 TOTAL VEHICLE

**Activity Note:** Reason for Repair: PM B

08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure:

#### **Activity Comments**

Date	Part Number	Description	Qty.	Each	Extended
24-Dec-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52400924 Invoice Number: 55345-52400924

UOM

**Client Department:** 

MRC: WO Desc:

Started

Completed

55345M

**Equipment:** 

5420

Ford E350 Champion Crusaders

Meter

1FDEE3FL3FDA06821

PM B Requested By: Created By:

RGASPARD **RGASPARD**  Status: Priority: 40 1

Class: **Arrangement:**  WO Unassigned Driver: Phone:

**Potential Warranty:** 

No

ETA:

VIN:

Chronology Reported

May 24, 2019

10:22 AM

May 26, 2019

12:39 PM

Reading WO DH Life 243,922 DH

**Down Time** 

WorkOrder Notes

Line Comment 10 COMPLAINT: Performe PM-B

CAUSE: preventive maintenance

CORRECTION: Tech Performed Pm-B

Activity: 10 **Activity Note:** 

999 TOTAL VEHICLE Light Mediun Duty PMI

Reason for Repair: 08 - Preventive Maintenance Work Accomplished: 06 - Inspect

Part Failure:

**Activity Comments** 

**Parts Issued** 

Date Part Number

Description

Each Extended

**Labor Posted** 

Date

Hours

Extended

**Activity 10 Sub Total** 

Parts:

Labor:

Labor Hours: 0.00 Sublet Parts:

0.00

0.00

0.00

Sublet Labor:

0.00

**Activity Sub Total** 

0.00

Activity: 20

999 TOTAL VEHICLE

**Activity Note:** 

PM B

08 - Preventive Maintenance

Reason for Repair: Work Accomplished: B - PM Level B

Part Failure:

**Activity Comments** 

**Parts Issued** 

Date	Part Nu	ımber			Description	Qty. Each Ex	ended
26-May-19	B329(F)		FILTER,	OIL SAME AS LF368	1	1.00 1.96	1.96



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52877380 **Invoice Number:** 55345-52877380

MOU

**Client Department:** 

MRC:

55345M

Equipment:

5420

40

1

WO Desc: PM B

Class:

Started

Completed

**RGASPARD** 

VIN: Status: 1FDEE3FL3FDA06821

Ford E350 Champion Crusaders

Requested By: Created By:

**RGASPARD** 

Priority:

WO

Driver:

Arrangement: **Potential Warranty:**  Unassigned No

Phone: ETA:

Chronology Reported Oct 31, 2019

Oct 31, 2019 Nov 1, 2019

12:00 AM

12:22 AM

Meter

Reading WO DH Life 270,257 DH

**Down Time** 

WorkOrder Notes

Line Comment

COMPLAINT: PMB

CAUSE: Service

CORRECTION: perform PMB Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 qts

Fixed right rear tire patched

Torque wheels 140 lbs second torque 140 lbs

Activity: 1.0

999 TOTAL VEHICLE

**Activity Note:** Light Mediun Duty PMI Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure:

**Activity Comments** 

Parts Issued

Date Part Number Description

Each Extended

**Labor Posted** 

31-Oct-19 Gaspard,Ronald 1.75 65.00 113.75	Date	Technician	Hours	Rate E	xtended	
	31-Oct-19	Gaspard,Ronald	1.75	65.00	113.75	and a

Activity 10 Sub Total

Parts: Labor:

0.00 113.75

Labor Hours: 1.75 Sublet Parts:

0.00

Sublet Labor:

0.00

**Activity Sub Total** 

113.75

Activity: 20

999 TOTAL VEHICLE

**Activity Note:** 

PM B

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure:

**Activity Comments** 



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 53462620 Invoice Number: 55345-53462620

MOU

DH

DH

Reading

295,605

**Client Department:** 

MRC: WO Desc: 55345M

**Equipment:** 

5420

Ford E350 Champion Crusaders

1FDEE3FL3FDA06821

PM B
Requested By:
Created By:
Class:

DKNOTT DKNOTT WO Status: Priority: Driver: 40 1

Arrangement: Potential Warranty:

Unassigned No

Chronology

Phone: ETA:

VIN:

11:53 AM	Meter
	lwo

Reported Started Completed

10

May 15, 2020 May 15, 2020 May 15, 2020

11:34 PM

# WorkOrder Notes

Line Comment

COMPLAINT:PMB

CAUSE: Service

CORRECTION: perform PMB service Oil filter B329 qty1

Engine oil 10w30 qty 7 Qts

Activity: 10

999/999/999 TOTAL VEHICLE

**Down Time** 

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: - Part Failure: -

**Activity Comments** 

Parts Issued

Date Part Number

Description

. Each Extended

#### **Labor Posted**

Date	Technician	Hours R	MCX 22 CO 2010 DE CO 1995 CO 1995	tended
15-May-20	Gaspard,Ronald	1.35	0.00	0.00
 	The grant of the contract of t			en communicação, e d

**Activity 10 Sub Total** 

Parts: Labor: 0.00

Labor Hours: 1.35 Sublet Parts: Sublet Labor:

0.00

**Activity Sub Total** 

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: PM

PM B

Reason for Repair: 08 - Preventive Maintenance Work Accomplished: B - PM Level B

Part Failure:

**Activity Comments** 

Date	Part Number		Description	Qty, Each	Extended
15-May-20	B329(F)	FILTER, OIL, SPIN-ON	SEE BALDWIN B329	1.00 1.96	1.96



55345 Palm Tran Connection v 2.2 Page 1 of 9



**WorkOrder: 51363979 Invoice Number:** 55345-51363979

**Client Department:** 

**MRC:** 55345M **Equipment:** 5420

WO Desc: Ford E350 Champion Crusaders

PM B VIN: 1FDEE3FL3FDA06821

Requested By:CKARLENSStatus:40Created By:CKARLENSPriority:1

Class: WO Driver:
Arrangement: Unassigned Phone:
Potential Warranty: No ETA:

	Chronology	
Reported	Jun 19, 2018	11:01 AM
Started	Jun 19, 2018	
Completed	Jun 19, 2018	11:46 PM
Do		

Meter	Reading	UOM
WO		DH
Life	192,196	DH
System	192,391	DH

#### **WorkOrder Notes**

Line	Comment
10	COMPLAINT:PMB Service
	CAUSE: Service due by Mileage
	CORRECTION: Change Oil& Filter. lube all Pivoting Points. check Brakes .Clean batteries. replace A/C Filter Parts# B329 Qty (1) Oil5W20 Qty (6.5) Qt

Activity: 10

999 TOTAL VEHICLE

**Activity Note:** Light Mediun Duty PMI **Reason for Repair:** 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure: -

#### **Activity Comments**

#### **Parts Issued**

# **Labor Posted**

Date	Technician		Rate	Extended
19-Jun-18	Arthurs, Durvin	2.00	0.00	0.00

 Activity 10 Sub Total

 Parts:
 0.00

 Labor:
 0.00

 Labor Hours: 2.00
 0.00

 Sublet Parts:
 0.00

 Sublet Labor:
 0.00

 Activity Sub Total
 0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: PM B

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure:

# **Activity Comments**

Date	Part Number	Description	Qty.	Each	Extended
19-Jun-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



55345 Palm Tran Connection v 2.2 Page 2 of 9



WorkOrder: 51363979 **Invoice Number:** 55345-51363979

**Client Department:** 

MRC: WO Desc:

PM B

55345M

**Equipment:** 

5420

Ford E350 Champion Crusaders 1FDEE3FL3FDA06821

**Requested By: Created By:** 

CKARLENS **CKARLENS** WO

Status: **Priority: Driver:** 

40 1

Class: **Arrangement: Potential Warranty:** 

Unassigned No

Phone: ETA:

VIN:

#### **Labor Posted**

Date	Technician		Rate	Extended
19-Jun-18	Arthurs, Durvin	0.42	0.00	0.00

Parts: 1.96 Labor: 0.00 Labor Hours: 0.42 Sublet Parts: 0.00 Sublet Labor: 0.00

**Activity 20 Sub Total** 

**Activity Sub Total** 

1.96

Activity: 30

999 TOTAL VEHICLE

**Activity Note: PRAMETER** 

**Reason for Repair:** 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure:

#### **Activity Comments**

#### **Parts Issued**

Date Part Number Description Qty. Each Exte	nded
---	------

#### **Labor Posted**

Date	Technician		Rate	Extended
19-Jun-18	Arthurs, Durvin	0.08	0.00	0.00

**Activity 30 Sub Total** Parts: 0.00 0.00 Labor: Labor Hours: 0.08 0.00 Sublet Parts: Sublet Labor: 0.00 **Activity Sub Total** 0.00

WorkOrder 51363979 G	Grand Total
Parts:	1.96
Labor:	0.00
Labor Hours: 2.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	1.96

Recent Repair History

	<b></b> ,			,
WorkOrder	Date Completed	Life Meter	Class	Description
51363979	19-Jun-18	192,196	WO	PM B
51378261	30-May-18	189,082	WO	Rear ac is not blowing



55345 Palm Tran Connection v 2.2 Page 3 of 9



**WorkOrder: 51363979 Invoice Number:** 55345-51363979

**Client Department:** 

**MRC:** 55345M **Equipment:** 5420

WO Desc: Ford E350 Champion Crusaders PM B VIN: 1FDEE3FL3FDA06821

Requested By: CKARLENS Status: 40
Created By: CKARLENS Priority: 1

Class: WO Driver: Arrangement: Unassigned Phone: Potential Warranty: No ETA:

WorkOrder	Date Completed	Life Meter	Class			Desc	ription		
51284663	21-May-18	188,022	WO	PM A					
Scheduled I	Preventativ	e Maintenaı	nce						
Nest		PM	WorkOrd	er	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
Other Open	Repairs								
WorkOrder8	Date Reported	Life Meter	Class			Desc	ription		

WorkOrder8	Date Reported	Life Meter	Class	Description
51443888	19-Jun-18	192,196	WO	Trannsmission Pan
51369255	23-May-18	188,353	WO	ABS LIGHT ON
51363430	21-May-18	188,022	WO	FOLLOWUP¿¿front/rear brake pads
51153861	30-Mar-18	179,469	WO	Repalce shifter cable, serpentine belt

PH: Work Order: 51363979 Desc: PM B

Equip: 5420 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL3FDA06821

LH: 10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 19-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jun 19, 2018 11:20:17 PM	No	
10,100	Safety Inspection	Done		DARTHURS	Jun 19, 2018 11:20:17 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jun 19, 2018 11:20:17 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jun 19, 2018 11:20:17 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jun 19, 2018 11:20:18 PM	No	
10,140	Check Service Brakes	Done		DARTHURS	Jun 19, 2018 11:20:18 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jun 19, 2018 11:20:18 PM	No	
10,160	FRA Check Instruments and Horns	Done		DARTHURS	Jun 19, 2018 11:20:18 PM	No	
10,170	Check Fast Idle	Done		DARTHURS	Jun 19, 2018 11:20:18 PM	No	
10,180	Check Starter Protection Circuit	Done		DARTHURS	Jun 19, 2018 11:20:19 PM	No	
10,190	Check Reverse Warning System	Done		DARTHURS	Jun 19, 2018 11:20:19 PM	No	
11,100	Check Parking Brake	Done		DARTHURS	Jun 19, 2018 11:20:19 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		DARTHURS	Jun 19, 2018 11:20:19 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jun 19, 2018 11:20:19 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		DARTHURS	Jun 19, 2018 11:20:19 PM	No	
11,140	Road Test: Check for Proper Operation	Done		DARTHURS	Jun 19, 2018 11:20:20 PM	No	
11,150	Perform Brake Test	Done		DARTHURS	Jun 19, 2018 11:20:20 PM	No	
11,152	Decelerometer Results Test 1	FEET	NA	DARTHURS	Jun 19, 2018 11:20:20 PM	No	
11,154	Decelerometer Results Test 2	FEET	NA	DARTHURS	Jun 19, 2018 11:20:20 PM	No	
11,156	Decelerometer Results Test 3	FEET	NA	DARTHURS	Jun 19, 2018 11:20:21 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jun 19, 2018 11:20:20 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jun 19, 2018 11:20:20 PM	No	
11,170	FRA Check Door Operation	Done		DARTHURS	Jun 19, 2018 11:20:21 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		DARTHURS	Jun 19, 2018 11:20:21 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jun 19, 2018 11:20:21 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		DARTHURS	Jun 19, 2018 11:20:21 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		DARTHURS	Jun 19, 2018 11:20:21 PM	No	
20,230	FRA Check Wiring Under Dash	Done		DARTHURS	Jun 19, 2018 11:20:21 PM	No	
20,240	FRA Check Interior Lights	Done		DARTHURS	Jun 19, 2018 11:20:21 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		DARTHURS	Jun 19, 2018 11:20:22 PM	No	
20,260	Check Stop Request System	-	NA	DARTHURS	Jun 19, 2018 11:20:22 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jun 19, 2018 11:20:22 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jun 19, 2018 11:20:22 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jun 19, 2018 11:20:22 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		DARTHURS	Jun 19, 2018 11:20:22 PM	No	
22,110	Check Emergency Hatches	Done		DARTHURS	Jun 19, 2018 11:20:23 PM	No	
22,120	Check All Safety Equipment	Done		DARTHURS	Jun 19, 2018 11:20:22 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jun 19, 2018 11:20:23 PM	No	
30,310	Check Passenger Doors	Done		DARTHURS	Jun 19, 2018 11:20:23 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		DARTHURS	Jun 19, 2018 11:20:23 PM	No	
30,330	Check Wheelchair Lift Operation	Done		DARTHURS	Jun 19, 2018 11:20:23 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jun 19, 2018 11:20:23 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		DARTHURS	Jun 19, 2018 11:20:24 PM	No	
30,360	Check for Physical Damage and Decals	Done		DARTHURS	Jun 19, 2018 11:20:24 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		DARTHURS	Jun 19, 2018 11:20:24 PM	No	
30,380	Check Exterior Compartment Doors	Done		DARTHURS	Jun 19, 2018 11:20:24 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		DARTHURS	Jun 19, 2018 11:20:24 PM	No	
33,100	Check Lights and Reflectors	Done		DARTHURS	Jun 19, 2018 11:20:24 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jun 19, 2018 11:20:24 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jun 19, 2018 11:20:25 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jun 19, 2018 11:20:25 PM	No	
40,420	Check Hood	Done		DARTHURS	Jun 19, 2018 11:20:25 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		DARTHURS	Jun 19, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:20:25 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jun 19, 2018 11:20:25 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jun 19, 2018 11:20:25 PM	No	
40,442	Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jun 19, 2018 11:20:26 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jun 19, 2018 11:20:26 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jun 19, 2018 11:20:26 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jun 19, 2018 11:20:26 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jun 19, 2018 11:20:26 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		DARTHURS	Jun 19, 2018 11:20:26 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		DARTHURS	Jun 19, 2018 11:20:26 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jun 19, 2018 11:20:27 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jun 19, 2018 11:20:27 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jun 19, 2018 11:20:27 PM	No	
44,130	FRA Check Exhaust System	Done		DARTHURS	Jun 19, 2018 11:20:27 PM	No	
44,140	FRA Check Intake System	Done		DARTHURS	Jun 19, 2018 11:20:27 PM	No	
44,150	FRA Inspect Turbocharger	-	NA	DARTHURS	Jun 19, 2018 11:20:27 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jun 19, 2018 11:20:27 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jun 19, 2018 11:20:28 PM	No	
44,180	FRA Check for Leaks	Done		DARTHURS	Jun 19, 2018 11:20:28 PM	No	
44,190	FRA Perform Battery Inspection	Done		DARTHURS	Jun 19, 2018 11:20:28 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jun 19, 2018 11:20:28 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		DARTHURS	Jun 19, 2018 11:20:28 PM	No	
50,510	Check Entire Steering System	Done		DARTHURS	Jun 19, 2018 11:20:28 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jun 19, 2018 11:20:28 PM	No	
60,610	FRA Check and Record Air Pressure	Done		DARTHURS	Jun 19, 2018 11:20:28 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Jun 19, 2018 11:20:29 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Jun 19, 2018 11:20:29 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Jun 19, 2018 11:20:29 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Jun 19, 2018 11:20:29 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Jun 19, 2018 11:20:29 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Jun 19, 2018 11:20:30 PM	No	
60,620	Check Valve Stems and Caps	Done		DARTHURS	Jun 19, 2018 11:20:29 PM	No	
60,630	Check and Record Tread Depth	Done		DARTHURS	Jun 19, 2018 11:20:29 PM	No	
60,631	Tread Depth RF	7 32nds of an inch		DARTHURS	Jun 19, 2018 11:20:30 PM	No	
60,632	Tread Depth LF	8 32nds of an inch		DARTHURS	Jun 19, 2018 11:20:30 PM	No	
60,633	Tread Depth RRO	6 32nds of an inch		DARTHURS	Jun 19, 2018 11:20:30 PM	No	
60,634	Tread Depth RRI	5 32nds of an inch		DARTHURS	Jun 19, 2018 11:20:30 PM	No	
60,635	Tread Depth LRI	5 32nds of an inch		DARTHURS	Jun 19, 2018 11:20:30 PM	No	
60,636	Tread Depth LRO	5 32nds of an inch		DARTHURS	Jun 19, 2018 11:20:30 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jun 19, 2018 11:20:30 PM	No	
60,650	Check Sidewall Wear	Done		DARTHURS	Jun 19, 2018 11:20:31 PM	No	
60,660	Inspect for Cuts and Tears	Done		DARTHURS	Jun 19, 2018 11:20:31 PM	No	
60,670	Check Dual Mating With Square	-	NA	DARTHURS	Jun 19, 2018 11:20:31 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jun 19, 2018 11:20:31 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jun 19, 2018 11:20:31 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jun 19, 2018 11:20:31 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jun 19, 2018 11:20:31 PM	No	
70,710	Check Vibration Damper	Done		DARTHURS	Jun 19, 2018 11:20:32 PM	No	
70,720	Check Engine and Transmission Mounts	Done		DARTHURS	Jun 19, 2018 11:20:32 PM	No	
70,730	FRA Check Starter	Done		DARTHURS	Jun 19, 2018 11:20:32 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jun 19, 2018 11:20:32 PM	No	
70,750	FRA Check Transmission for Leaks	Done		DARTHURS	Jun 19, 2018 11:20:32 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		DARTHURS	Jun 19, 2018 11:20:32 PM	No	
70,770	FRA Check Exhaust System	Done		DARTHURS	Jun 19, 2018 11:20:32 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jun 19, 2018 11:20:32 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jun 19, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					11:20:33 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jun 19, 2018 11:20:33 PM	No	
77,110	FRA Check Fuel Tank	Done		DARTHURS	Jun 19, 2018 11:20:33 PM	No	
77,120	Check Suspension Components	Done		DARTHURS	Jun 19, 2018 11:20:33 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jun 19, 2018 11:20:33 PM	No	
77,131	Brake Pad Thickness LF	10 Inch		DARTHURS	Jun 19, 2018 11:22:33 PM	No	
77,132	Brake Pad Thickness RF	10 Inch		DARTHURS	Jun 19, 2018 11:22:33 PM	No	
77,133	Brake Pad Thickness LR	6 Inch		DARTHURS	Jun 19, 2018 11:21:08 PM	No	
77,134	Brake Pad Thickness RR	6 Inch		DARTHURS	Jun 19, 2018 11:20:34 PM	No	
77,135	Brake Rotor LF	1.556 Inch		DARTHURS	Jun 19, 2018 11:22:33 PM	No	
77,136	Brake Rotor RF	1.555 Inch		DARTHURS	Jun 19, 2018 11:22:33 PM	No	
77,137	Brake Rotor LR	1.415 Inch		DARTHURS	Jun 19, 2018 11:22:34 PM	No	
77,138	Brake Rotor RR	1.414 Inch		DARTHURS	Jun 19, 2018 11:22:34 PM	No	
77,140	FRA Check Brake Hoses	Done		DARTHURS	Jun 19, 2018 11:22:34 PM	No	
77,150	Check King Pins	-	NA	DARTHURS	Jun 19, 2018 11:22:34 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jun 19, 2018 11:22:35 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		DARTHURS	Jun 19, 2018 11:22:34 PM	No	
80,810	Completion of PMI Report	Done		DARTHURS	Jun 19, 2018 11:22:35 PM	No	
90,000	SECTION 9 Completion of PMI	Done		DARTHURS	Jun 19, 2018 11:22:34 PM	No	
90,910	Vehicle Returned to predetermined location	Done		DARTHURS	Jun 19, 2018 11:22:35 PM	No	

# LH: 20 Desc: PM B

Task: PM B SERVICE Performed by: DARTHURS Performed on: 19-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		DARTHURS	Jun 19, 2018 11:24:03 PM	No	
101,000	FRA Change Oil Filters	Yes		DARTHURS	Jun 19, 2018 11:24:04 PM	No	
102,000	FRA Drain Engine Oil	Yes		DARTHURS	Jun 19, 2018 11:24:04 PM	No	
103,000	FRA Check Transmission Fluid	Done		DARTHURS	Jun 19, 2018 11:24:04 PM	No	
104,000	Lubricate Chassis	Done		DARTHURS	Jun 19, 2018 11:24:04 PM	No	
105,000	Replace or Clean A/C Filters	Done	Replace A/C	DARTHURS	Jun 19, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
			Filter		11:24:04 PM		
107,000	FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jun 19, 2018 11:24:04 PM	No	
108,000	Lube all pivoting Mechanisms	Done		DARTHURS	Jun 19, 2018 11:24:04 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Jun 19, 2018 11:24:04 PM	No	
201,000	Service Crankcase Breather	-	NA	DARTHURS	Jun 19, 2018 11:24:04 PM	No	
203,000	FRA Change Automatic Transmission Fluid	Yes		DARTHURS	Jun 19, 2018 11:24:05 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	No		DARTHURS	Jun 19, 2018 11:24:05 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Jun 19, 2018 11:24:05 PM	No	

# LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 19-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 19, 2018 11:24:29 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



55345 Palm Tran Connection

Page 1 of 9

Invoice Number: 55345-51611670 WorkOrder: 51611670

# Client Department: MRC:

WO Desc: PM C

Arrangement: Created By: Class:

**Equipment:** 55345M

Status: VIN:

Ford E350 Champion Crusaders 1FDEE3FL3FDA06821 5420 40

12:10 AM 12:02 PM Priority: Driver: Phone: ETA: Sep 5, 2018 Sep 5, 2018 Sep 6, 2018 Chronology RGASPARD Unassigned RGASPARD 9 Potential Warranty: Requested By: Completed Reported

Meter	Reading	MON
WO		품
Life	204,686	H
System	204,878	품

WorkOrder Notes

**Down Time** 

Started

Rotate tires and washed rims Torque wheels 140 lbs second torque 140 lbs Comment Perform PMC service Oil filter B329 qty 1 Engine oil 5w20 qty 7 Qts Gear Oil 80w90 qty 4 Qts Service Line 10

Activity: 10

Part Failure:

Parts Issued

Date

**Activity Comments** 

0.00 Extended 0.00 Rate 2.07 Hours Technician Gaspard, Ronald **Labor Posted** 05-Sep-18

Qty. Each Extended

Description

Part Number

Activity 10 Sub Total

Labor Hours: 2.07 Labor: Parts:

0.00

0.00 0.00 0.00

**Activity Sub Total** Sublet Labor: Sublet Parts:

Activity: 20

TOTAL VEHICLE Activity Note:

**Reason for Repair:** 08 - Preventive Maintenance **Work Accomplished:** C - PM Level C

Part Failure:

**Activity Comments** 



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 52185199 Invoice Number: 55345-52185199

**Client Department:** 

MRC: WO Desc:

Reported

Completed

Started

Line

PM C

55345M

Equipment:

5420

Ford E350 Champion Crusaders

VIN:

1FDEE3FL3FDA06821

Requested By: Created By:

DARTHURS DARTHURS

Status: Priority: 40 1

Class: Arrangement: WO Unassigned Driver:

Unassigned No Phone: ETA:

Potential Warranty:

Chronology
Mar 14, 2019
Mar 14, 2019
Mar 15, 2019

6:52 AM 8:32 AM

Down Time

Meter	Reading	UOM
wo		DH
Life	231,156	DH

#### WorkOrder Notes

Comment

10 Complaint. Pm c

Cause. Inspection

Correction. Perform pm c Service, changed engine oil and filter, Lube Pivoting Points, Check Brakes, Clean Batteries, Replaced a/c filter, Perform transmission service, differential service.

Activity: 10

999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure:

#### **Activity Comments**

#### **Parts Issued**

Date Part Number Description Qty. Each Extended

#### Labor Posted

	Date	Technician	Hours	Rate	Extended
į	14-Mar-19	KARLENS,Cyrius	2.00	0.00	0.00
			فحريت فتتتبع تصييره بالروفيية فيستو		activation and a production of the

# **Activity 10 Sub Total**

Parts: 0.00
Labor: 0.00
Labor Hours: 2.00

Sublet Parts: Sublet Labor: 0.00 0.00

**Activity Sub Total** 

0.00

Activity: 20

999 TOTAL VEHICLE

Activity Note: PM

PM C

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: C - PM Level C

Part Failure:

#### **Activity Comments**

14-Mar-19	20021	FILTER, TRANSMISSION, E350, '09 W/RUBBER N	
Date	Part Number	Description	Oty. Each Extended



55345 Palm Tran Connection v 2.2

Page 1 of 9



WorkOrder: 52607097 **Invoice Number:** 55345-52607097

**Client Department:** 

MRC: WO Desc:

Line

55345M

**Equipment:** 

5420

Ford E350 Champion Crusaders

1FDEE3FL3FDA06821

PM C Requested By:

VAMRITTEEMAL VAMRITTEEMAL VIN: Status:

40

Created By: Class:

WO

**Priority:** Driver:

1

**Arrangement:** 

Unassigned

Phone:

**Potential Warranty:** 

No

ETA:

	Down Time	<b>:</b>	
:	Completed	Aug 17, 2019	12:19 AM
	Started	Aug 16, 2019	
•	Reported	Aug 16, 2019	12:53 PM
į.		Chronology	

Meter	Reading	MOU
WO		DH
Life	256,817	DH

WorkOrder Notes

10 PMC Service Perform PMC service Oil filter B329 Qty1 Engine oil 5w20 qty 7 qts Air filter PA4075 Qty1 Replaced AC filter Gear Oil 80w90 qty 4 qts

Comment

Activity: 10 **Activity Note:** 

999 TOTAL VEHICLE Light Medium Duty PMI 05 - Inspection, Routine

Reason for Repair: Work Accomplished: 06 - Inspect

Part Failure:

**Activity Comments** 

**Parts Issued** 

Date Part Number

Description

Qty.

Each Extended

**Labor Posted** 

1	16-Aug-19	Gaspard,Ronald	1.63	65.00	106.17	1000000
	Date	Technician	Hours	Rate E	xtended	

**Activity 10 Sub Total** 

Parts: Labor:

0.00 106.17

Labor Hours: 1.63 Sublet Parts:

Sublet Labor:

0.00 0.00

**Activity Sub Total** 

106.17

Activity: 20

999 TOTAL VEHICLE

**Activity Note:** 

PM C

08 - Preventive Maintenance

Reason for Repair: Work Accomplished: C - PM Level C

Part Failure:

**Activity Comments** 



55345 Palm Tran Connection v 2.2 Page 1 of 9



WorkOrder: 53124738 **Invoice Number:** 55345-53124738

UOM

Reading

**Client Department:** 

MRC: 55345M **Equipment:** 

5420 WO Desc: Ford E350 Champion Crusaders

VIN: 1FDEE3FL3FDA06821 PM C

**Requested By:** VAMRITTEEMAL Status: 40 **Created By:** VAMRITTEEMAL **Priority:** 1

Class: WO **Driver: Arrangement:** Phone: Unassigned **Potential Warranty:** ETA: No

	Chronology	
Reported	Jan 22, 2020	10:33 AM
Started	l lan 23 2020 l	

Jan 23, 2020 Completed **Down Time** 

**WorkOrder Notes** 

		WO		DH
	11:59 AM	Life	283,304	DH
_		-		

Meter

Line	Comment
10	Complaint: PMC Service
	Cause: preventive maintenance
	Correction: perform PMC Service and lube all Pivoting Points

Activity: 10 999/999/999 TOTAL VEHICLE

**Activity Note:** Light Duty PMI

08 - Preventive Maintenance Reason for Repair:

Work Accomplished: -**Part Failure:** 

**Activity Comments** 

**Parts Issued** 

Date Each Extended Part Number Description

**Labor Posted** 

Date	Technician	Hours	Rate	Extended	
23-Jan-20	NELSON PIERRE-LOUIS	2.62	0.00	0.00	

**Activity 10 Sub Total** 0.00 Parts: Labor: 0.00 Labor Hours: 2.62 Sublet Parts: 0.00 Sublet Labor: 0.00

**Activity Sub Total** 

0.00

Activity: 20 999 TOTAL VEHICLE **Activity Note:** PM C

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: C - PM Level C

**Part Failure:** 

**Activity Comments** 

Date	Part Number	Description	Qty.	Each	Extended
23-Jan-20	20021	FILTER, TRANSMISSION, E350, '09 W/RUBBER NECK SEAL SAME AS FT180	1.00	17.27	17.27



55345 Palm Tran Connection v 2.2 Page 1 of 12



WorkOrder: 53735731 **Invoice Number:** 55345-53735731

**Client Department:** 

MRC:

WO Desc:

55345-LIGHT DUTY PMC **Requested By:** 

**Created By:** Class: **Arrangement:** Unassigned **Potential Warranty:** No

**Equipment:** 5420 55345M

VIN:

Ford E350 Champion Crusaders

1FDEE3FL3FDA06821

40 Status: 3 **Priority: Driver:** 

Phone: ETA:

Chronology

Reported Aug 27, 2020 2:26 PM Started Aug 27, 2020

> Aug 27, 2020 7:43 PM **Down Time**

TDFI VA

**TDELVA** 

WO

UOM Meter Reading WO DH Life 308,123 DH

**WorkOrder Notes** 

Line Comment

Perform PMC Service. Change Oil & Filter . Lube all Pivoting Points. Check brakes. Clean batteries. Replace A/C Filter.Perform Transmission Service Drain & Fill / Replace Filter. Drain & Fill differential.

Parts# B329 Qty (1) Parts # 20021 Qty (1) Oil 10W30 Qty (6.5) Qt Gear Oil 80W90 Qty (3) Qt

Activity: 5

Completed

999/999/999 TOTAL VEHICLE

**Activity Note:** PERSONAL RISK ASSESSMENT Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect **Part Failure:** 00 - No Failure

**Activity Comments** 

**Parts Issued** 

Part Number Each Extended Date Description

**Labor Posted** 

Technician Extended Date Hours Rate

**Activity 5 Sub Total** 

Parts: 0.00 Labor: 0.00

Labor Hours: 0.00 Sublet Parts: Sublet Labor:

**Activity Sub Total** 0.00

0.00

0.00

Activity: 10

999/999/999 TOTAL VEHICLE

**Activity Note:** Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -**Part Failure:** 

**Activity Comments** 

**Parts Issued** 

Date Part Number Description Each Extended