



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51296587
Invoice Number: 55345-51296587

Client Department:

MRC: 55345M

Equipment: 5446

WO Desc:

Ford E350 Champion Crusaders

PM A

VIN: 1FDEE3FL8FDA02747

Requested By: DARTHURS

Status: 40

Created By: DARTHURS

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology

Reported	May 23, 2018	8:41 AM
Started	May 23, 2018	
Completed	May 23, 2018	4:54 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	189,931	DH
System	190,063	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PM A CAUSE: Service Due CORRECTION: Performed and completed PM A.... Changed engine oil and replaced engine oil filter **Follow_Ups====> Front Shocks Needed&&Rear Brakes Needed&&Rear A/C line Leaks spotted** ===== > Supervisor inspected (Carlos)*****

Activity: 10



999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
23-May-18	Delva,Terry	1.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 2 of 9



WorkOrder: 51296587
Invoice Number: 55345-51296587

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5446
Ford E350 Champion Crusaders
1FDEE3FL8FDA02747
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Date	Part Number	Description	Qty.	Each	Extended
23-May-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

Date	Technician	Hours	Rate	Extended
23-May-18	Delva,Terry	1.00	0.00	0.00

Activity 20 Sub Total

Parts: 1.96
Labor: 0.00
Labor Hours: 1.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 1.96

Activity: **30** **999 TOTAL VEHICLE**

Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
23-May-18	Delva,Terry	0.77	0.00	0.00

Activity 30 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.77
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

WorkOrder 51296587 Grand Total

Parts: 1.96
Labor: 0.00
Labor Hours: 2.77
Sublet Parts: 0.00
Sublet Labor: 0.00
WorkOrder Grand Total 1.96

Recent Repair History



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 3 of 9



WorkOrder: 51296587
Invoice Number: 55345-51296587

Client Department:

MRC: 55345M

Equipment: 5446

WO Desc:

Ford E350 Champion Crusaders

PM A

VIN: 1FDEE3FL8FDA02747

Requested By: DARTHURS

Status: 40

Created By: DARTHURS

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

WorkOrder	Date Completed	Life Meter	Class	Description
51296587	23-May-18	189,931	WO	PM A
51286061	1-May-18	185,312	WO	MDT not working.
51167890	27-Apr-18	185,745	WO	PM A
51296499	27-Apr-18	185,745	WO	Front Rotor/ Front Pads & Wheel bearing/ Seals

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
------	----	-----------	----------	----------------	-------------------	------------------	---------------------

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51369461	23-May-18	189,931	WO	Needs front shocs 2 front tires and rear brakes job

PH: Work Order: 51296587 Desc: PM A**Equip: 5446 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL8FDA02747****LH: 10 Desc: Light Medium Duty PMI****Task: First Transit Light-Medium Duty PMI Performed by: TDELVA Performed on: 23-MAY-18**

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		TDELVA	May 23, 2018 3:55:00 PM	No	
10,100	Safety Inspection	Done		TDELVA	May 23, 2018 3:55:00 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	May 23, 2018 3:55:00 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		TDELVA	May 23, 2018 3:55:00 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		TDELVA	May 23, 2018 3:55:00 PM	No	
10,140	Check Service Brakes	Done		TDELVA	May 23, 2018 3:55:01 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		TDELVA	May 23, 2018 3:55:01 PM	No	
10,160	FRA Check Instruments and Horns	Done		TDELVA	May 23, 2018 3:55:01 PM	No	
10,170	Check Fast Idle	Done		TDELVA	May 23, 2018 3:55:01 PM	No	
10,180	Check Starter Protection Circuit	Done		TDELVA	May 23, 2018 3:55:01 PM	No	
10,190	Check Reverse Warning System	Done		TDELVA	May 23, 2018 3:55:01 PM	No	
11,100	Check Parking Brake	Done		TDELVA	May 23, 2018 3:55:02 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		TDELVA	May 23, 2018 3:55:02 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		TDELVA	May 23, 2018 3:55:02 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		TDELVA	May 23, 2018 3:55:02 PM	No	
11,140	Road Test: Check for Proper Operation	Done		TDELVA	May 23, 2018 3:55:03 PM	No	
11,150	Perform Brake Test	Done		TDELVA	May 23, 2018 3:55:02 PM	No	
11,152	Decelerometer Results Test 1	FEET	n/a	TDELVA	May 23, 2018 3:55:03 PM	No	
11,154	Decelerometer Results Test 2	FEET	n/a	TDELVA	May 23, 2018 3:55:02 PM	No	
11,156	Decelerometer Results Test 3	FEET	n/a	TDELVA	May 23, 2018 3:55:03 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	TDELVA	May 23, 2018 3:55:03 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	TDELVA	May 23, 2018 3:55:03 PM	No	
11,170	FRA Check Door Operation	Done		TDELVA	May 23, 2018 3:55:03 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		TDELVA	May 23, 2018 3:55:04 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		TDELVA	May 23, 2018 3:55:04 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		TDELVA	May 23, 2018 3:55:04 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		TDELVA	May 23, 2018 3:55:04 PM	No	
20,230	FRA Check Wiring Under Dash	Done		TDELVA	May 23, 2018 3:55:05 PM	No	
20,240	FRA Check Interior Lights	Done		TDELVA	May 23, 2018 3:55:05 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		TDELVA	May 23, 2018 3:55:05 PM	No	
20,260	Check Stop Request System	-	n/a	TDELVA	May 23, 2018 3:55:05 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	n/a	TDELVA	May 23, 2018 3:55:06 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		TDELVA	May 23, 2018 3:55:06 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		TDELVA	May 23, 2018 3:55:06 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		TDELVA	May 23, 2018 3:55:06 PM	No	
22,110	Check Emergency Hatches	Done		TDELVA	May 23, 2018 3:55:07 PM	No	
22,120	Check All Safety Equipment	Done		TDELVA	May 23, 2018 3:55:06 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		TDELVA	May 23, 2018 3:55:06 PM	No	
30,310	Check Passenger Doors	Done		TDELVA	May 23, 2018 3:55:06 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		TDELVA	May 23, 2018 3:55:07 PM	No	
30,330	Check Wheelchair Lift Operation	Done		TDELVA	May 23, 2018 3:55:07 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	n/a	TDELVA	May 23, 2018 3:55:07 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		TDELVA	May 23, 2018 3:55:08 PM	No	
30,360	Check for Physical Damage and Decals	Done		TDELVA	May 23, 2018 3:55:08 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		TDELVA	May 23, 2018 3:55:08 PM	No	
30,380	Check Exterior Compartment Doors	Done		TDELVA	May 23, 2018 3:55:08 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		TDELVA	May 23, 2018 3:55:08 PM	No	
33,100	Check Lights and Reflectors	Done		TDELVA	May 23, 2018 3:55:08 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		TDELVA	May 23, 2018 3:55:09 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		TDELVA	May 23, 2018 3:55:09 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		TDELVA	May 23, 2018 3:55:09 PM	No	
40,420	Check Hood	Done		TDELVA	May 23, 2018 3:55:09 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		TDELVA	May 23, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					3:55:10 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	n/a	TDELVA	May 23, 2018 3:55:10 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	TDELVA	May 23, 2018 3:55:10 PM	No	
40,442	Freeze Point	Degree Fahrenheit	n/a	TDELVA	May 23, 2018 3:55:10 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		TDELVA	May 23, 2018 3:55:11 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	n/a	TDELVA	May 23, 2018 3:55:11 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	n/a	TDELVA	May 23, 2018 3:55:11 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done	n/a	TDELVA	May 23, 2018 3:55:11 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		TDELVA	May 23, 2018 3:55:11 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		TDELVA	May 23, 2018 3:55:11 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		TDELVA	May 23, 2018 3:55:11 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		TDELVA	May 23, 2018 3:55:12 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		TDELVA	May 23, 2018 3:55:12 PM	No	
44,130	FRA Check Exhaust System	Done		TDELVA	May 23, 2018 3:55:12 PM	No	
44,140	FRA Check Intake System	Done		TDELVA	May 23, 2018 3:55:12 PM	No	
44,150	FRA Inspect Turbocharger	-	n/a	TDELVA	May 23, 2018 3:55:12 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		TDELVA	May 23, 2018 3:55:12 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		TDELVA	May 23, 2018 3:55:12 PM	No	
44,180	FRA Check for Leaks	Done		TDELVA	May 23, 2018 3:55:12 PM	No	
44,190	FRA Perform Battery Inspection	Done		TDELVA	May 23, 2018 3:55:12 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		TDELVA	May 23, 2018 3:55:13 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		TDELVA	May 23, 2018 3:55:13 PM	No	
50,510	Check Entire Steering System	Done		TDELVA	May 23, 2018 3:55:13 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		TDELVA	May 23, 2018 3:55:13 PM	No	
60,610	FRA Check and Record Air Pressure	Done		TDELVA	May 23, 2018 3:55:14 PM	No	
60,611	Air Pressure RF	65 Pounds per Square Inch		TDELVA	May 23, 2018 3:55:14 PM	No	
60,612	Air Pressure LF	65 Pounds per Square Inch		TDELVA	May 23, 2018 3:55:14 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		TDELVA	May 23, 2018 3:55:14 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		TDELVA	May 23, 2018 3:55:15 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		TDELVA	May 23, 2018 3:55:14 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		TDELVA	May 23, 2018 3:55:15 PM	No	
60,620	Check Valve Stems and Caps	Done		TDELVA	May 23, 2018 3:55:15 PM	No	
60,630	Check and Record Tread Depth	Done		TDELVA	May 23, 2018 3:55:15 PM	No	
60,631	Tread Depth RF	7 32nds of an inch		TDELVA	May 23, 2018 3:55:15 PM	No	
60,632	Tread Depth LF	8 32nds of an inch		TDELVA	May 23, 2018 3:55:16 PM	No	
60,633	Tread Depth RRO	6 32nds of an inch		TDELVA	May 23, 2018 3:55:16 PM	No	
60,634	Tread Depth RRI	4 32nds of an inch		TDELVA	May 23, 2018 3:55:16 PM	No	
60,635	Tread Depth LRI	7 32nds of an inch		TDELVA	May 23, 2018 3:55:16 PM	No	
60,636	Tread Depth LRO	6 32nds of an inch		TDELVA	May 23, 2018 3:55:16 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		TDELVA	May 23, 2018 3:55:16 PM	No	
60,650	Check Sidewall Wear	Done		TDELVA	May 23, 2018 3:55:17 PM	No	
60,660	Inspect for Cuts and Tears	Done		TDELVA	May 23, 2018 3:55:17 PM	No	
60,670	Check Dual Mating With Square	-	n/a	TDELVA	May 23, 2018 3:55:17 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		TDELVA	May 23, 2018 3:55:17 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		TDELVA	May 23, 2018 3:55:17 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		TDELVA	May 23, 2018 3:55:18 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		TDELVA	May 23, 2018 3:55:18 PM	No	
70,710	Check Vibration Damper	Done		TDELVA	May 23, 2018 3:55:17 PM	No	
70,720	Check Engine and Transmission Mounts	Done		TDELVA	May 23, 2018 3:55:18 PM	No	
70,730	FRA Check Starter	Done		TDELVA	May 23, 2018 3:55:18 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		TDELVA	May 23, 2018 3:55:18 PM	No	
70,750	FRA Check Transmission for Leaks	Done		TDELVA	May 23, 2018 3:55:18 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		TDELVA	May 23, 2018 3:55:19 PM	No	
70,770	FRA Check Exhaust System	Done		TDELVA	May 23, 2018 3:55:19 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		TDELVA	May 23, 2018 3:55:19 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		TDELVA	May 23, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					3:55:19 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		TDELVA	May 23, 2018 3:55:20 PM	No	
77,110	FRA Check Fuel Tank	Done		TDELVA	May 23, 2018 3:55:20 PM	No	
77,120	Check Suspension Components	Done		TDELVA	May 23, 2018 3:55:20 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		TDELVA	May 23, 2018 3:55:20 PM	No	
77,131	Brake Pad Thickness LF	10 Inch		TDELVA	May 23, 2018 3:55:20 PM	No	
77,132	Brake Pad Thickness RF	10 Inch		TDELVA	May 23, 2018 3:55:21 PM	No	
77,133	Brake Pad Thickness LR	6 Inch		TDELVA	May 23, 2018 3:55:21 PM	No	
77,134	Brake Pad Thickness RR	6 Inch		TDELVA	May 23, 2018 3:55:21 PM	No	
77,135	Brake Rotor LF	38.89 Inch		TDELVA	May 23, 2018 3:55:21 PM	No	
77,136	Brake Rotor RF	38.89 Inch		TDELVA	May 23, 2018 3:55:21 PM	No	
77,137	Brake Rotor LR	1.67 Inch		TDELVA	May 23, 2018 3:55:21 PM	No	
77,138	Brake Rotor RR	1.67 Inch		TDELVA	May 23, 2018 3:55:21 PM	No	
77,140	FRA Check Brake Hoses	Done		TDELVA	May 23, 2018 3:55:21 PM	No	
77,150	Check King Pins	-	n/a	TDELVA	May 23, 2018 3:55:22 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		TDELVA	May 23, 2018 3:55:22 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		TDELVA	May 23, 2018 3:55:22 PM	No	
80,810	Completion of PMI Report	Done		TDELVA	May 23, 2018 3:55:22 PM	No	
90,000	SECTION 9 Completion of PMI	Done		TDELVA	May 23, 2018 3:55:23 PM	No	
90,910	Vehicle Returned to predetermined location	Done		TDELVA	May 23, 2018 3:55:23 PM	No	

LH: 20 Desc: PM A

Task: PM A SERVICE Performed by: TDELVA Performed on: 23-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		TDELVA	May 23, 2018 3:56:02 PM	No	
101,000	FRA Change Oil Filters	Yes		TDELVA	May 23, 2018 3:56:03 PM	No	
102,000	FRA Drain Engine Oil	Yes		TDELVA	May 23, 2018 3:56:04 PM	No	
103,000	FRA Check Transmission Fluid	Done		TDELVA	May 23, 2018 3:56:04 PM	No	
104,000	Lubricate Chassis	Done		TDELVA	May 23, 2018 3:56:03 PM	No	
105,000	Replace or Clean A/C Filters	Done		TDELVA	May 23, 2018 3:56:05 PM	No	
107,000	FRA Change Primary Fuel Filter	No	n/a	TDELVA	May 23, 2018 3:56:04 PM	No	
108,000	Lube all pivoting Mechanisms	Done		TDELVA	May 23, 2018 3:56:05 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: TDELVA Performed on: 23-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	May 23, 2018 3:57:03 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51448911
Invoice Number: 55345-51448911

Client Department:

MRC: 55345M

Equipment: 5446

WO Desc:

Ford E350 Champion Crusaders

PM A

1FDEE3FL8FDA02747

Requested By:

RAUODRIGUEZ

VIN:

32

Created By:

RAUODRIGUEZ

Status:

1

Class:

WO

Priority:

Driver:

Arrangement:

Unassigned

Phone:

Potential Warranty:

No

ETA:

Chronology

Reported	Jul 18, 2018	9:53 AM
Started	Jul 18, 2018	
Completed	Jul 19, 2018	12:21 AM

Down Time

Meter	Reading	UOM
WO		DH
Life	198,188	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts

Activity: 10



999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
18-Jul-18	Gaspard,Ronald	1.53	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.53	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51710800
Invoice Number: 55345-51710800

Client Department:

MRC: 55345M
WO Desc:
PM A
Requested By: AOWENS
Created By: AOWENS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5446
Ford E350 Champion Crusaders
1FDEE3FL8FDA02747
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Oct 12, 2018	2:22 PM
Started	Oct 12, 2018	
Completed	Oct 12, 2018	11:34 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	211,058	DH
System	211,224	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
12-Oct-18	Gaspard,Ronald	1.58	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.58
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
12-Oct-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51809933
Invoice Number: 55345-51809933

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5446
Ford E350 Champion Crusaders
VIN: 1FDEE3FL8FDA02747
Status: 32
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Nov 6, 2018	1:49 PM
Started	Nov 6, 2018	
Completed	Nov 6, 2018	11:19 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	215,215	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Preventive Maintenance CORRECTION: Performed and completed PMA Service Replaced air filter

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
06-Nov-18	AMRIT TEEMAL,VISHNU	1.50	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.50
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
06-Nov-18	PA4075	FILTER, AIR, PAPER SAME AS AF25590	1.00	5.27	5.27



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51964743
Invoice Number: 55345-51964743

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5446
Ford E350 Champion Crusaders
VIN: 1FDEE3FL8FDA02747
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Dec 31, 2018	11:42 AM
Started	Dec 31, 2018	
Completed	Dec 31, 2018	10:02 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	223,646	DH
System	223,800	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PmA CAUSE:Service CORRECTION:perform PmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
31-Dec-18	Gaspard,Ronald	1.63	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.63
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -


Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
31-Dec-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52035542
Invoice Number: 55345-52035542

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5446
Ford E350 Champion Crusaders
VIN: 1FDEE3FL8FDA02747
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Jan 31, 2019	1:34 PM
Started	Jan 31, 2019	
Completed	Jan 31, 2019	11:50 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	227,773	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 Qty1 Engine oil 5w20 qty7 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
31-Jan-19	Gaspard,Ronald	1.58	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.58
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -


Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
31-Jan-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52213918
Invoice Number: 55345-52213918

Client Department:

MRC: 55345M
WO Desc:
PM A
Requested By: DKNOTT
Created By: DKNOTT
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5446
Ford E350 Champion Crusaders
VIN: 1FDEE3FL8FDA02747
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Mar 27, 2019	11:01 AM
Started	Mar 27, 2019	
Completed	Mar 28, 2019	12:06 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	236,072	DH
System	236,241	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points . Che k brakes . Clean batteries. Replace A/C Filter. Swap both L/ R Tire & R /R inner was flat. Parts # B 329 Qty (1) Oil 5W20QTY (6.5) Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
27-Mar-19	Arthurs,Durvin	1.50	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.50
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -


Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
27-Mar-19	B329	FILTER, OIL (FGA0000399/FSC0000399)	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52291802
Invoice Number: 55345-52291802

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5446
Ford E350 Champion Crusaders
1FDEE3FL8FDA02747
VIN: 40
Status: 1
Priority:
Driver:
Phone:
ETA:

Chronology		
Reported	Apr 23, 2019	1:34 PM
Started	Apr 23, 2019	
Completed	Apr 24, 2019	12:02 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	240,108	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service. CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check .brakes. Clean batteries replace one front Clearance light. Parts # B329 Qty (1) Oil 5W20 Qty (6.5) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
23-Apr-19	Arthurs,Durvin	1.50	65.00	97.50

Activity 10 Sub Total

Parts: 0.00
Labor: 97.50
Labor Hours: 1.50
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 97.50

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued


Date	Part Number	Description	Qty.	Each	Extended
23-Apr-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder

55345 Palm Tran Connection
v 2.2

Page 1 of 9



WorkOrder: 52451700

Invoice Number: 55345-52451700

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: CVERGARA
Created By: CVERGARA
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5446
Ford E350 Champion Crusaders
VIN: 1FDEE3FL8FDA02747
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology

Reported	Jun 18, 2019	12:21 PM
Started	Jun 18, 2019	
Completed	Jun 19, 2019	7:48 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	248,828	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE: Service CORRECTION:Perform pmA Service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts

Activity: 10



999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
18-Jun-19	Gaspard,Ronald	1.60	65.00	104.00

Activity 10 Sub Total

Parts:	0.00
Labor:	104.00
Labor Hours: 1.60	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	104.00

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
18-Jun-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52529813
Invoice Number: 55345-52529813

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RRENE
Created By: RRENE
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5446
Ford E350 Champion Crusaders
VIN: 1FDEE3FL8FDA02747
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Jul 19, 2019	3:11 PM
Started	Jul 19, 2019	
Completed	Jul 22, 2019	7:33 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	253,148	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE: Service CORRECTION:Perform pmA Service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
19-Jul-19	Gaspard,Ronald	1.67	65.00	108.33

Activity 10 Sub Total

Parts: 0.00
Labor: 108.33
Labor Hours: 1.67
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 108.33

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
19-Jul-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52709034
Invoice Number: 55345-52709034

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5446
Ford E350 Champion Crusaders
1FDEE3FL8FDA02747
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Sep 19, 2019	11:05 AM
Started	Sep 19, 2019	
Completed	Sep 20, 2019	8:16 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	262,065	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: perform pmA service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
19-Sep-19	Gaspard,Ronald	1.57	65.00	101.83

Activity 10 Sub Total

Parts: 0.00
Labor: 101.83
Labor Hours: 1.57
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 101.83

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
19-Sep-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52814047
Invoice Number: 55345-52814047

Client Department:

MRC: 55345M

Equipment: 5446

WO Desc:

Ford E350 Champion Crusaders

PM A

VIN: 1FDEE3FL8FDA02747

Requested By:

RRENE

Status: 40

Created By:

RRENE

Priority: 1

Class:

WO

Driver:

Arrangement:

Unassigned

Phone:

Potential Warranty:

No

ETA:

Chronology		
Reported	Oct 16, 2019	10:35 AM
Started	Oct 17, 2019	
Completed	Oct 17, 2019	12:24 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	266,121	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PmA CAUSE: Service CORRECTION: perform PmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 qts

Activity: 10



999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
17-Oct-19	Gaspard,Ronald	1.60	65.00	104.00

Activity 10 Sub Total

Parts:	0.00
Labor:	104.00
Labor Hours: 1.60	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	104.00

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
17-Oct-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

**WorkOrder**55345 Palm Tran Connection
v 2.2

Page 1 of 9

**WorkOrder: 53008160****Invoice Number: 55345-53008160****Client Department:****MRC:** 55345M**Equipment:** 5446**WO Desc:**

PM A

Requested By:

RRENE

VIN:

Ford E350 Champion Crusaders

Created By:

RRENE

Status:

40

Class:

WO

Priority:

1

Arrangement:

Unassigned

Driver:**Potential Warranty:**

No

Phone:**ETA:**

Chronology		
Reported	Dec 17, 2019	12:00 AM
Started	Dec 18, 2019	
Completed	Dec 19, 2019	12:31 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	275,485	DH
System	275,485	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: perform pmA service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts Replaced left side marker light

Activity: 10**999/999/999 TOTAL VEHICLE****Activity Note:**

Light Duty PMI

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: -**Part Failure:** -**Activity Comments****Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
18-Dec-19	Gaspard, Ronald	1.37	65.00	89.05
19-Dec-19	Gaspard, Ronald	0.32	65.00	20.80

Activity 10 Sub Total

Parts:	0.00
Labor:	109.85
Labor Hours: 1.69	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	109.85

Activity: 20**999 TOTAL VEHICLE****Activity Note:**

PM A

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: A - PM Level A**Part Failure:** -**Activity Comments****Parts Issued**

**WorkOrder**55345 Palm Tran Connection
v 2.2

Page 1 of 9

**WorkOrder: 53111266****Invoice Number: 55345-53111266****Client Department:****MRC:** 55345M**Equipment:** 5446**WO Desc:**

PM A

VIN: Ford E350 Champion Crusaders**Requested By:** RGASPARD**Status:** 40**Created By:** RGASPARD**Priority:** 1**Class:** WO**Driver:****Arrangement:** Unassigned**Phone:****Potential Warranty:** No**ETA:****Chronology**

Reported	Jan 30, 2020	11:02 AM
Started	Jan 30, 2020	
Completed	Jan 30, 2020	8:55 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	279,618	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: perform pmA service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts

Activity: 10**999/999/999 TOTAL VEHICLE****Activity Note:** Light Duty PMI**Reason for Repair:** 08 - Preventive Maintenance**Work Accomplished:** -**Part Failure:** -**Activity Comments****Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
30-Jan-20	Gaspard, Ronald	1.57	0.00	0.00

Activity 10 Sub Total


Parts:	0.00
Labor:	0.00
Labor Hours: 1.57	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20**999 TOTAL VEHICLE****Activity Note:** PM A**Reason for Repair:** 08 - Preventive Maintenance**Work Accomplished:** A - PM Level A**Part Failure:** -**Activity Comments****Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
30-Jan-20	B329(F)	FILTER, OIL	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 11



WorkOrder: 53558575
Invoice Number: 55345-53558575

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMA
Requested By: NSTOLFO
Created By: NSTOLFO
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5446
Ford E350 Champion Crusaders
VIN: 1FDEE3FL8FDA02747
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology

Reported	Aug 31, 2020	12:00 AM
Started	Aug 31, 2020	
Completed	Sep 1, 2020	12:09 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	287,793	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMA CAUSE: Service CORRECTION: perform PMA service Oil filter B329 qty1 Engine oil 10w30 qty 7 Qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 53832883
Invoice Number: 55345-53832883

Client Department:

MRC:	55345M	Equipment:	5446
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		VIN:	1FDEE3FL8FDA02747
Requested By:	RGASPARD	Status:	40
Created By:	RGASPARD	Priority:	3
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology

Reported	Oct 14, 2020	12:00 AM
Started	Oct 14, 2020	
Completed	Oct 15, 2020	12:42 AM

Down Time

Meter	Reading	UOM
WO		DH
Life	292,048	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION:Perform pmA Service Oil filter B329 qty1 Engine oil 10w30 qty7 qts Air filter PA4075 qty1

Activity: 5



999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10



999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51368893
Invoice Number: 55345-51368893

Client Department:

MRC: 55345M

Equipment: 5446

WO Desc:

Ford E350 Champion Crusaders

PM B

VIN: 1FDEE3FL8FDA02747

Requested By: TDELVA

Status: 40

Created By: TDELVA

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology

Reported	Jun 20, 2018	11:31 AM
Started	Jun 21, 2018	
Completed	Jun 21, 2018	12:33 PM

Down Time

Meter	Reading	UOM
WO		DH
Life	194,305	DH
System	194,305	DH

WorkOrder Notes

Line	Comment
10	PM. B Perform pm B service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time. Parts. Engine oil filter part # B329 qty 1 engine oil. 5W20 Qty 6 qts

Activity: 10



999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
21-Jun-18	Rodriguez,Raul	1.82	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.82	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM B

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
21-Jun-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 2 of 9



WorkOrder: 51368893
Invoice Number: 55345-51368893

Client Department:

MRC: 55345M
WO Desc: PM B
Requested By: TDELVA
Created By: TDELVA
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5446
Ford E350 Champion Crusaders
1FDEE3FL8FDA02747
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Labor Posted

Date	Technician	Hours	Rate	Extended
21-Jun-18	Rodriguez,Raul	0.75	0.00	0.00

Activity 20 Sub Total

Parts: 1.96
Labor: 0.00
Labor Hours: 0.75
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 1.96

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 30 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

WorkOrder 51368893 Grand Total

Parts: 1.96
Labor: 0.00
Labor Hours: 2.57
Sublet Parts: 0.00
Sublet Labor: 0.00
WorkOrder Grand Total 1.96

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51368893	21-Jun-18	194,305	WO	PM B
51296587	23-May-18	189,931	WO	PM A

Scheduled Preventative Maintenance



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 3 of 9



WorkOrder: 51368893
Invoice Number: 55345-51368893

Client Department:

MRC: 55345M

WO Desc:

PM B

Requested By: TDELVA

Created By: TDELVA

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 5446

Ford E350 Champion Crusaders

VIN: 1FDEE3FL8FDA02747

Status: 40

Priority: 1

Driver:

Phone:

ETA:

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
------	----	-----------	----------	-------------------	----------------------	---------------------	------------------------

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51369461	23-May-18	189,931	WO	Needs front shocs 2 front tires and rear brakes job

PH: Work Order: 51368893 Desc: PM B**Equip: 5446 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL8FDA02747****LH: 10 Desc: Light Medium Duty PMI****Task: First Transit Light-Medium Duty PMI Performed by: RAUODRIGUEZ Performed on: 21-JUN-18**

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:38 PM	No	
10,100	Safety Inspection	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:38 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:38 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:38 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:39 PM	No	
10,140	Check Service Brakes	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:40 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:39 PM	No	
10,160	FRA Check Instruments and Horns	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:39 PM	No	
10,170	Check Fast Idle	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:40 PM	No	
10,180	Check Starter Protection Circuit	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:40 PM	No	
10,190	Check Reverse Warning System	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:40 PM	No	
11,100	Check Parking Brake	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:40 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:41 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:41 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:41 PM	No	
11,140	Road Test: Check for Proper Operation	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:41 PM	No	
11,150	Perform Brake Test	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:41 PM	No	
11,152	Decelerometer Results Test 1	FEET	na	RAUODRIGUEZ	Jun 21, 2018 12:22:41 PM	No	
11,154	Decelerometer Results Test 2	FEET	na	RAUODRIGUEZ	Jun 21, 2018 12:22:41 PM	No	
11,156	Decelerometer Results Test 3	FEET	na	RAUODRIGUEZ	Jun 21, 2018 12:22:42 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RAUODRIGUEZ	Jun 21, 2018 12:22:42 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	na	RAUODRIGUEZ	Jun 21, 2018 12:22:42 PM	No	
11,170	FRA Check Door Operation	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:42 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:43 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:43 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:43 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:43 PM	No	
20,230	FRA Check Wiring Under Dash	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:44 PM	No	
20,240	FRA Check Interior Lights	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:44 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:44 PM	No	
20,260	Check Stop Request System	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:44 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:44 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:44 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:44 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:44 PM	No	
22,110	Check Emergency Hatches	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:45 PM	No	
22,120	Check All Safety Equipment	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:45 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:46 PM	No	
30,310	Check Passenger Doors	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:45 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:46 PM	No	
30,330	Check Wheelchair Lift Operation	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:46 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	na	RAUODRIGUEZ	Jun 21, 2018 12:22:46 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:46 PM	No	
30,360	Check for Physical Damage and Decals	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:46 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:47 PM	No	
30,380	Check Exterior Compartment Doors	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:47 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:47 PM	No	
33,100	Check Lights and Reflectors	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:47 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:48 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:48 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:48 PM	No	
40,420	Check Hood	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:48 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		RAUODRIGUEZ	Jun 21, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					12:22:48 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	na	RAUODRIGUEZ	Jun 21, 2018 12:22:48 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RAUODRIGUEZ	Jun 21, 2018 12:22:49 PM	No	
40,442	Freeze Point	Degree Fahrenheit	na	RAUODRIGUEZ	Jun 21, 2018 12:22:49 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:48 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	na	RAUODRIGUEZ	Jun 21, 2018 12:22:49 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	na	RAUODRIGUEZ	Jun 21, 2018 12:22:49 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:49 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:50 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:50 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:50 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:50 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:50 PM	No	
44,130	FRA Check Exhaust System	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:51 PM	No	
44,140	FRA Check Intake System	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:51 PM	No	
44,150	FRA Inspect Turbocharger	-	na	RAUODRIGUEZ	Jun 21, 2018 12:22:51 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:51 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:51 PM	No	
44,180	FRA Check for Leaks	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:51 PM	No	
44,190	FRA Perform Battery Inspection	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:51 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:51 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:52 PM	No	
50,510	Check Entire Steering System	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:52 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:52 PM	No	
60,610	FRA Check and Record Air Pressure	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:52 PM	No	
60,611	Air Pressure RF	65 Pounds per Square Inch		RAUODRIGUEZ	Jun 21, 2018 12:33:04 PM	No	
60,612	Air Pressure LF	65 Pounds per Square Inch		RAUODRIGUEZ	Jun 21, 2018 12:22:53 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		RAUODRIGUEZ	Jun 21, 2018 12:22:52 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		RAUODRIGUEZ	Jun 21, 2018 12:22:52 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		RAUODRIGUEZ	Jun 21, 2018 12:22:53 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		RAUODRIGUEZ	Jun 21, 2018 12:22:54 PM	No	
60,620	Check Valve Stems and Caps	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:53 PM	No	
60,630	Check and Record Tread Depth	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:54 PM	No	
60,631	Tread Depth RF	13 32nds of an inch		RAUODRIGUEZ	Jun 21, 2018 12:22:54 PM	No	
60,632	Tread Depth LF	13 32nds of an inch		RAUODRIGUEZ	Jun 21, 2018 12:22:54 PM	No	
60,633	Tread Depth RRO	4 32nds of an inch		RAUODRIGUEZ	Jun 21, 2018 12:22:54 PM	No	
60,634	Tread Depth RRI	5 32nds of an inch		RAUODRIGUEZ	Jun 21, 2018 12:22:54 PM	No	
60,635	Tread Depth LRI	6 32nds of an inch		RAUODRIGUEZ	Jun 21, 2018 12:22:55 PM	No	
60,636	Tread Depth LRO	4 32nds of an inch		RAUODRIGUEZ	Jun 21, 2018 12:22:55 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:55 PM	No	
60,650	Check Sidewall Wear	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:55 PM	No	
60,660	Inspect for Cuts and Tears	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:55 PM	No	
60,670	Check Dual Mating With Square	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:56 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:55 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:55 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:55 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:56 PM	No	
70,710	Check Vibration Damper	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:56 PM	No	
70,720	Check Engine and Transmission Mounts	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:56 PM	No	
70,730	FRA Check Starter	Done		RAUODRIGUEZ	Jun 21, 2018 12:22:56 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		RAUODRIGUEZ	Jun 21, 2018 12:27:08 PM	No	
70,750	FRA Check Transmission for Leaks	Done		RAUODRIGUEZ	Jun 21, 2018 12:27:08 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		RAUODRIGUEZ	Jun 21, 2018 12:27:08 PM	No	
70,770	FRA Check Exhaust System	Done		RAUODRIGUEZ	Jun 21, 2018 12:27:08 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		RAUODRIGUEZ	Jun 21, 2018 12:27:09 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		RAUODRIGUEZ	Jun 21, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					12:27:09 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		RAUODRIGUEZ	Jun 21, 2018 12:27:09 PM	No	
77,110	FRA Check Fuel Tank	Done		RAUODRIGUEZ	Jun 21, 2018 12:27:09 PM	No	
77,120	Check Suspension Components	Done		RAUODRIGUEZ	Jun 21, 2018 12:27:09 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		RAUODRIGUEZ	Jun 21, 2018 12:27:09 PM	No	
77,131	Brake Pad Thickness LF	Inch	9mm	RAUODRIGUEZ	Jun 21, 2018 12:27:09 PM	No	
77,132	Brake Pad Thickness RF	Inch	9mm	RAUODRIGUEZ	Jun 21, 2018 12:27:09 PM	No	
77,133	Brake Pad Thickness LR	Inch	7mm	RAUODRIGUEZ	Jun 21, 2018 12:27:10 PM	No	
77,134	Brake Pad Thickness RR	Inch	7mm	RAUODRIGUEZ	Jun 21, 2018 12:27:10 PM	No	
77,135	Brake Rotor LF	Inch	39.6mm	RAUODRIGUEZ	Jun 21, 2018 12:27:10 PM	No	
77,136	Brake Rotor RF	Inch	39.6mm	RAUODRIGUEZ	Jun 21, 2018 12:27:10 PM	No	
77,137	Brake Rotor LR	Inch	35.8mm	RAUODRIGUEZ	Jun 21, 2018 12:27:10 PM	No	
77,138	Brake Rotor RR	Inch	35.8mm	RAUODRIGUEZ	Jun 21, 2018 12:27:10 PM	No	
77,140	FRA Check Brake Hoses	Done		RAUODRIGUEZ	Jun 21, 2018 12:27:10 PM	No	
77,150	Check King Pins	-	na	RAUODRIGUEZ	Jun 21, 2018 12:27:11 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		RAUODRIGUEZ	Jun 21, 2018 12:27:11 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		RAUODRIGUEZ	Jun 21, 2018 12:27:11 PM	No	
80,810	Completion of PMI Report	Done		RAUODRIGUEZ	Jun 21, 2018 12:27:11 PM	No	
90,000	SECTION 9 Completion of PMI	Done		RAUODRIGUEZ	Jun 21, 2018 12:27:13 PM	No	
90,910	Vehicle Returned to predetermined location	Done		RAUODRIGUEZ	Jun 21, 2018 12:27:14 PM	No	

LH: 20 Desc: PM B

Task: PM B SERVICE Performed by: RAUODRIGUEZ Performed on: 21-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	-				No	
101,000	FRA Change Oil Filters	Yes		RAUODRIGUEZ	Jun 21, 2018 12:29:43 PM	No	
102,000	FRA Drain Engine Oil	Yes		RAUODRIGUEZ	Jun 21, 2018 12:29:43 PM	No	
103,000	FRA Check Transmission Fluid	Done		RAUODRIGUEZ	Jun 21, 2018 12:29:44 PM	No	
104,000	Lubricate Chassis	Done		RAUODRIGUEZ	Jun 21, 2018 12:29:44 PM	No	
105,000	Replace or Clean A/C Filters	Done		RAUODRIGUEZ	Jun 21, 2018 12:29:44 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
107,000	FRA Change Primary Fuel Filter	No	na	RAUODRIGUEZ	Jun 21, 2018 12:29:44 PM	No	
108,000	Lube all pivoting Mechanisms	Done		RAUODRIGUEZ	Jun 21, 2018 12:29:44 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		RAUODRIGUEZ	Jun 21, 2018 12:29:44 PM	No	
201,000	Service Crankcase Breather	Done		RAUODRIGUEZ	Jun 21, 2018 12:29:44 PM	No	
203,000	FRA Change Automatic Transmission Fluid	No	na	RAUODRIGUEZ	Jun 21, 2018 12:29:45 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	No	na	RAUODRIGUEZ	Jun 21, 2018 12:29:45 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		RAUODRIGUEZ	Jun 21, 2018 12:29:45 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: RAUODRIGUEZ Performed on: 21-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		RAUODRIGUEZ	Jun 21, 2018 12:30:32 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51884224
Invoice Number: 55345-51884224

Client Department:

MRC: 55345M

WO Desc:

PM B

Requested By: VAMRITTEEMAL

Created By: VAMRITTEEMAL

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 5446

Ford E350 Champion Crusaders

VIN: 1FDEE3FL8FDA02747

Status: 32

Priority: 1

Driver:

Phone:


ETA:

Chronology		
Reported	Dec 4, 2018	12:00 PM
Started	Dec 4, 2018	
Completed	Dec 5, 2018	12:03 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	219,437	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMB CAUSE: Service CORRECTION:Perform pmB Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10  **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued


Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
04-Dec-18	Gaspard,Ronald	1.55	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.55	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20  **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
04-Dec-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

**WorkOrder**55345 Palm Tran Connection
v 2.2

Page 1 of 9

**WorkOrder: 52368953****Invoice Number: 55345-52368953****Client Department:****MRC:** 55345M**Equipment:** 5446**WO Desc:**

PM B

Requested By:

DARTHURS

VIN: Ford E350 Champion Crusaders**Created By:**

DARTHURS

Status: 40**Class:**

WO

Priority: 1**Arrangement:**

Unassigned

Driver:**Potential Warranty:**

No

Phone:**ETA:**

Chronology		
Reported	May 21, 2019	12:00 AM
Started		
Completed	May 22, 2019	8:14 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	244,768	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMB CAUSE: Service due CORRECTION: Performed And Completed PMB Changed engine oil and replaced engine oil filter

Activity: 10 **999 TOTAL VEHICLE****Activity Note:** Light Medium Duty PMI**Reason for Repair:** 08 - Preventive Maintenance**Work Accomplished:** 06 - Inspect**Part Failure:** -**Activity Comments****Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE****Activity Note:** PM B**Reason for Repair:** 08 - Preventive Maintenance**Work Accomplished:** B - PM Level B**Part Failure:** -**Activity Comments****Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
21-May-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

**WorkOrder**55345 Palm Tran Connection
v 2.2

Page 1 of 9

**WorkOrder: 52903625****Invoice Number: 55345-52903625****Client Department:**

MRC: 55345M
WO Desc: PM B
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5446
Ford E350 Champion Crusaders
1FDEE3FL8FDA02747
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Nov 14, 2019	12:00 AM
Started	Nov 15, 2019	
Completed	Nov 17, 2019	1:14 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	270,834	DH
System	270,834	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMB CAUSE: Service Due CORRECTION: Performed and completed PMB

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Nov-19	Delva,Terry	1.95	65.00	126.75

Activity 10 Sub Total

Parts: 0.00
Labor: 126.75
Labor Hours: 1.95
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 126.75

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
15-Nov-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51623013
Invoice Number: 55345-51623013

Client Department:

MRC:	55345M	Equipment:	5446
WO Desc:			Ford E350 Champion Crusaders
PM C		VIN:	1FDEE3FL8FDA02747
Requested By:	TDELVA	Status:	32
Created By:	TDELVA	Priority:	1
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology		
Reported	Sep 11, 2018	8:25 AM
Started	Sep 11, 2018	
Completed	Sep 11, 2018	11:13 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	206,907	DH

WorkOrder Notes

Line	Comment
10	COMPLAINTS: PM C CAUSE: Service due CORRECTION: Performed and completed PMC Changed engine oil and replaced engine oil filter Lube all Pivoting Points

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
11-Sep-18	Delva, Terry	1.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
11-Sep-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52131036
Invoice Number: 55345-52131036

Client Department:

MRC: 55345M
WO Desc:
PM C
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5446
Ford E350 Champion Crusaders
1FDEE3FL8FDA02747
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Feb 27, 2019	10:22 AM
Started	Mar 1, 2019	
Completed	Mar 1, 2019	9:53 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	231,933	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMC CAUSE: PmC Service due CORRECTION: performed and Completed PMC.... Changed engine oil and replaced engine oil filter Changed transmission fluid Changed differential fluid Lube all Pivoting Points

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
01-Mar-19	Delva, Terry	1.95	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.95
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52621845
Invoice Number: 55345-52621845

Client Department:

MRC: 55345M

Equipment: 5446

WO Desc:

Ford E350 Champion Crusaders

PM C

VIN: 1FDEE3FL8FDA02747

Requested By:

RRENE

Status: 40

Created By:

RRENE

Priority: 1

Class:

WO

Driver:

Arrangement:

Unassigned

Phone:

Potential Warranty:

No

ETA:

Chronology		
Reported	Aug 20, 2019	12:00 AM
Started	Aug 20, 2019	
Completed	Aug 21, 2019	12:12 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	257,721	DH

WorkOrder Notes

Line	Comment
10	PMC Service Perform PMC Service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts Gear Oil 80w90 qty 4 Qts Replaced AC filter

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
20-Aug-19	Gaspard,Ronald	1.63	65.00	106.17

Activity 10 Sub Total

Parts: 0.00
Labor: 106.17
Labor Hours: 1.63
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 106.17

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
20-Aug-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 53235470
Invoice Number: 55345-53235470

Client Department:

MRC: 55345M
WO Desc: PM C
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5446
Ford E350 Champion Crusaders
1FDEE3FL8FDA02747
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	May 6, 2020	11:19 AM
Started	May 8, 2020	
Completed	May 8, 2020	3:34 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	283,522	DH

WorkOrder Notes

Line	Comment
10	Complaint: PMC CAUSE: service due Correction: Performed and completed PMC

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
08-May-20	Delva,Terry	2.55	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 2.55
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
08-May-20	65266	PLUG, DRAIN, OIL, ENGINE	1.00	4.25	4.25