

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10169638

3007DOOC 2003 GATOR ATV 6X4

Workorder: V15657

In Date: Close Date: Meter Reading:

Problem? B INSPECTION AND REPAIRS AS NEEDED

06/10/2008

07/01/2008

Task performed:	Parts	Quantity
1. change air filter, replace battery, "b" inspection.	33262FUEL FILTER JOHN DEERE	1
2. change fuel fitr. change oil and filter	46449AIR FILTER GENERATOR LAF8388 ONAN	1
	51365OIL FILTER KUBOTA	1
	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	1
	GT-HBATTERY NS	1
 change air filter, replace battery, "b" inspection. change fuel fitr. change oil and filter 	46449AIR FILTER GENERATOR LAF8388 ONAN 51365OIL FILTER KUBOTA BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	1 1 1 1

Workorder: V19439

In Date:	12/02/2008	Meter Reading:
Close Date:	12/10/2008	
Problem?		
A inspectio	on- lube, oil, filte	r (gator atv)

Task performed: 1. Test drive, inspect, change oil/filter. 2. Rep turn signals & flasher. j			Parts	Quantity
			51365OIL FILTER KUBOTA	1
Workorder:	V20390			
In Date: Close Date: Problem?	01/15/2009 02/09/2009	Meter Reading: AIRS AS NEEDED BATT 7	7 GATOR 6X	
B INSPEC				
B INSPEC			Parts	Quantity

Workorder: V	310	13
--------------	-----	----

In Date:	03/24/2010	Meter Reading:
Close Date:	05/05/2010	······································
Problem?		
Mule has de	ead battery, Brok	en battery cable, and will not start Needs new battery at training

Task performed:	Parts	Quantity
Replc btry & rewired btry cables. j	58-60BATTERY GROUP 58	1
	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	1



Palm Beach County Fire Rescue Fleet Maintenance Asset History

10169638

3007DOOC 2003 GATOR ATV 6X4

Workorder:	V32114			
In Date: Close Date: Problem?	05/10/2010 06/03/2010	Meter Reading:		
Driver side	rear tire has a	nail, needs repair! Gator ATV.		
Task perforr	med:		Parts	Quantity
chk one at 74	4. tires on L/side;	one at 72 10169731; need to no nail fnd; ok at this time;	NO PARTS USED	
Workorder:	V38559			
In Date: Close Date: Problem? Right rear t	02/16/2011 03/09/2011 tire is flat	Meter Reading:		
Task perforr	med:		Parts	Quantity
Rep flat & roa	ad tested. j		FD176CAP	1
			FD315ROTOR	1



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10169638) 2004 - GATOR HPX John Deere Hpx 4X4 Gator

ied: 9-24-2019	Date Finished	9-25-2019	Meter 1 Reading:	0	
		NO PARTS USED	-		
JIPMENT					
J			NO PARTS USED JIPMENT	NO PARTS USED JIPMENT	NO PARTS USED JIPMENT