

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10193013    2013 CET DIPFP20HPKHLRM Pump, 300 Gallon, Fire, Skid Mounted, Foam System**

**Workorder:** 1312707    **Meter:** 0    **In Date:** 12/19/2013    **Closed:** 12/19/2013  
**Problem:** 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00    Labor: 120.00    Parts: 0.00    Total: 120.00  
:

**Workorder:** 1412203    **Meter:** 0    **In Date:** 12/05/2014    **Closed:** 12/16/2014  
**Problem:** pm/ see multiple note

- Pm  
- Clean mounting holes Replace pressure gauge hardware remount and lock tight bolts  
- Replace elec. pigtails for battery diagnose-elec breaker rewire truck-replace all end  
- Ign sys service tune up  
- Clean fuel lines replace fuel and flush fuel sys fuel sys service  
- Shop Supplies

**Parts List**

	<b>Qty</b>
Oil Fil	1.00
10w30 Motor Oil	2.00
Brake Cleaner	1.00
Napagold Fuel Filter	1.00
Ptex Thrd Lck Red Lg	1.00
Spark Plug	2.00
Startron 8oz Fuel Trt	1.00
Batt Cable Connector	1.00
Shop Supplies	1.00

Hours 7.50    Labor: 450.00    Parts: 125.93    Total: 575.93  
:

**Workorder:** 1503882    **Meter:** 0    **In Date:** 04/15/2015    **Closed:** 04/27/2015  
**Problem:** reel button inop/ move lower

- Trace sgirtm replace replace fuse link relocate reel button, make new harness  
- Shop Supplies

**Parts List**

	<b>Qty</b>
Fuse Holder	1.00
Shop Supplies	1.00

Hours 2.50    Labor: 150.00    Parts: 5.29    Total: 155.29  
:

**Workorder:** 1505142    **Meter:** 0    **In Date:** 05/20/2015    **Closed:** 05/29/2015  
**Problem:** foamer inop

- ck foamr operation r&r ck valve clean and test run  
- Shop Supplies

**Parts List**

	<b>Qty</b>
Shop Supplies	1.00

Hours 1.00    Labor: 60.00    Parts: 2.00    Total: 62.00  
:

**Workorder:** 1510422    **Meter:** 0    **In Date:** 10/15/2015    **Closed:** 10/27/2015  
**Problem:** replace battery connection

- Replace battery cable connector slip  
- Shop Supplies

**Parts List**

	<b>Qty</b>
Batt Cable Connector	1.00
Shop Supplies	1.00

Hours 1.00    Labor: 60.00    Parts: 56.06    Total: 116.06  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1512222	<b>Meter:</b> 0	<b>In Date:</b> 12/03/2015	<b>Closed:</b> 12/09/2015
<b>Problem:</b> pm service			
- Pm and test run	<b>Parts List</b>	<b>Qty</b>	
- Ign Servic	Oil Fil	1.00	
- Shop Supplies	10w30 Motor Oil	2.00	
	Napagold Fuel Filter	1.00	
	Spark Plug	2.00	
	Shop Supplies	1.00	
Hours 4.50	Labor: 270.00	Parts: 31.36	Total: 301.36
:			
<b>Workorder:</b> 1611036	<b>Meter:</b> 0	<b>In Date:</b> 10/26/2016	<b>Closed:</b> 11/15/2016
<b>Problem:</b> broken hose reel, bent sprocket			
- R/r hose reel replace sprocket	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Reel Sprocket	1.00	
	Shop Supplies	1.00	
	Freight Charge	1.00	
	Freight Charge	1.00	
Hours 4.00	Labor: 240.00	Parts: 1,634.18	Total: 1,874.18
:			
<b>Workorder:</b> 1613119	<b>Meter:</b> 0	<b>In Date:</b> 12/28/2016	<b>Closed:</b> 01/06/2017
<b>Problem:</b> pm service			
- Pm	<b>Parts List</b>	<b>Qty</b>	
- Ign Service	10w30 Motor Oil	2.00	
- Shop Supplies	Oil Fil	1.00	
	Napagold Fuel Filter	1.00	
	Spark Plug	2.00	
	Shop Supplies	1.00	
Hours 4.00	Labor: 240.00	Parts: 31.78	Total: 271.78
:			
<b>Workorder:</b> 1700974	<b>Meter:</b> 0	<b>In Date:</b> 01/31/2017	<b>Closed:</b> 02/28/2017
<b>Problem:</b> foam inop/ gauge/ foam knob/ see notes			
- R/r pressure guage	<b>Parts List</b>	<b>Qty</b>	
- Diag no foam, r/r foamer lentz sender control panel, fill and test run	Press Gauge 0.300 Oil Filled	1.00	
	Foamer Tank Sender	1.00	
- Shop Supplies	Control, Aquis 1.5 Oit Assy	1.00	
	Shop Supplies	1.00	
Hours 2.50	Labor: 150.00	Parts: 2,860.94	Total: 3,010.94
:			
<b>Workorder:</b> 1703762	<b>Meter:</b> 0	<b>In Date:</b> 04/13/2017	<b>Closed:</b> 04/19/2017
<b>Problem:</b> freight charges from work order #1700974			
- Freight Charges	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Freight Charges That Should Of Been Billed To W/o 17009	1.00	
	Shop Supplies	1.00	
Hours 0.00	Labor: 0.00	Parts: 83.60	Total: 83.60
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1708332	<b>Meter:</b> 0	<b>In Date:</b> 08/23/2017	<b>Closed:</b> 08/29/2017
<b>Problem:</b> foamer inop			
- Engine hydro locked- remove spark plug to clear out fuel in cylinders, test run pump and foamer working normally	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
<b>Workorder:</b> 1710331	<b>Meter:</b> 0	<b>In Date:</b> 10/20/2017	<b>Closed:</b> 10/31/2017
<b>Problem:</b> wont start			
- R/r fouled plugs and air filter	<b>Parts List</b>		<b>Qty</b>
- r/r carb clean and adjust	Air Filter		1.00
- Make and reapply asset numbers	Spark Plug		2.00
- Shop Supplies	Shop Supplies		1.00
Hours 3.50	Labor: 210.00	Parts: 29.75	Total: 239.75
:			
<b>Workorder:</b> 1712560	<b>Meter:</b> 0	<b>In Date:</b> 12/20/2017	<b>Closed:</b> 01/18/2018
<b>Problem:</b> pm/ not running properly			
- Pm	<b>Parts List</b>		<b>Qty</b>
- Ck Eng frt cyl-no compression-found blown head-r/r head to replace gasket-ck block and head surface for flatness-ok	Cylinder Head Gasket Kit		1.00
- R&r carb to dissemble and clean out	Oil Fil		1.00
- Shop Supplies	Napagold Fuel Filter		1.00
	Napa 10w30 Qt		2.00
	Shop Supplies		1.00
Hours 9.50	Labor: 570.00	Parts: 56.23	Total: 626.23
:			
<b>Workorder:</b> 1808664	<b>Meter:</b> 0	<b>In Date:</b> 08/22/2018	<b>Closed:</b> 09/10/2018
<b>Problem:</b> not running			
- diagnose engine and replace rear cyl head and test run	<b>Parts List</b>		<b>Qty</b>
- replace ignition switch and repair wiring	Switch Key Assy		1.00
- Shop Supplies	Spark Plug		4.00
	Cylinder Head Gasket Kit		1.00
	Switch Key Assy		1.00
	Cylunder Head		1.00
	Shop Supplies		1.00
Hours 5.50	Labor: 330.00	Parts: 358.16	Total: 688.16
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1901197	<b>Meter:</b> 0	<b>In Date:</b> 01/31/2019	<b>Closed:</b> 03/11/2019
<b>Problem:</b> pm/ missing dipstick			
- Pm Service	<b>Parts List</b>	<b>Qty</b>	
- R/r dipstick & dipstick tube	Oil Fil	1.00	
- Diag. no foam, research, R/r crankshaft sensor on foam pump; repair wiring & R/r foamer solenoid; test run	Napagold Fuel Filter	1.00	
- Shop Supplies	10w30 Motor Oil	2.00	
	Air Filter	1.00	
	Spark Plug	2.00	
	Fuel Line Hose	1.00	
	Dipstick	1.00	
	Dipstick Kit	1.00	
	Solenoid	1.00	
	Inductive Sensor	1.00	
	Shop Supplies	1.00	
	Freight Charge	1.00	
Hours 8.00	Labor: 536.00	Parts: 359.31	Total: 895.31
:			
<b>Workorder:</b> 1903012	<b>Meter:</b> 0	<b>In Date:</b> 03/19/2019	<b>Closed:</b> 04/02/2019
<b>Problem:</b> wont run/ start			
- Check "no start" - no compression on front cylinder; R/r both heads to repl. front head and both gaskets; rebuild carburetor; test run	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Exhaust Gasket	2.00	
	Cylinder Head #2	1.00	
	Cylinder Head Gasket Kit	2.00	
	Shop Supplies	1.00	
Hours 10.00	Labor: 670.00	Parts: 301.59	Total: 971.59
:			
<b>Workorder:</b> 1904521	<b>Meter:</b> 0	<b>In Date:</b> 04/25/2019	<b>Closed:</b> 04/26/2019
<b>Problem:</b> reel chain coming off/ bent			
- Repair bent hose reel	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Shop Supplies	1.00	
Hours 2.00	Labor: 134.00	Parts: 3.00	Total: 137.00
:			
<b>Workorder:</b> 2002907	<b>Meter:</b> 0	<b>In Date:</b> 03/23/2020	<b>Closed:</b> 03/23/2020
<b>Problem:</b> Transition Prep Charge			
- Transition Prep Charge			
Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00
:			