10180762 2010 FORD RANGER Pickup, Compact

Workorder:										
Problem:	1003027 Pre Delivery Ir	Meter:	0			In Date:	03/25/2010	Closed:	03/25/20	010
- Pre Delivery	y Inspection									
·	•	s 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	1003076 make duplicat	Meter: e key	16			In Date:	03/26/2010	Closed:	03/31/20	010
- cut key blan	nk and program	test ok			Parts Li	st				Qty
- Shop Suppl	ies				164-r047	75 Ign Key 2	2010-earlier (don't Reorde	er)	1.00
					Shop Su	ıpplies				1.00
	Hours :	s 1.00		Labor:	60.00	Parts:	23.45	Total:	83.45	
Workorder: Problem:	1003952 BRAKES OR	Meter: BEARING	310 NOISE ?			In Date:	04/16/2010	Closed:	04/27/20	010
	pick up vehicle	at dealer.	(defective t	front	Parts Li	st				Qty
wheel bearing	,				Shop Su	ıpplies				1.00
- Shop Suppl		0.00			100.00	5 /	0.00	.	400.00	
	Hours	s 2.00		Labor:	120.00	Parts:	2.00	l otal:	122.00	
Workorder: Problem:	1008631 P. M. SERVIC	Meter:	1971 s washer flu	id		In Date:	08/10/2010	Closed:	08/17/2	310
		L, a neca	3 Washer na	iiu						
- P. M. Servic	ce.	ie, a noca	s washer nu	ilu	Parts Li					-
- P. M. Servic - Shop Suppl	ce.	z, a noca	s washer hu	iu	Shop Su	ıpplies	DI coda Mi	54040		1.00
	ce.	, a 1100a	3 washer hu	iu	Shop Su 1348 Oil	ipplies Filter Frm	Ph3614 Wix	51348		1.00
	ce. ies	s 2.00	3 washer hu		Shop Su	ipplies Filter Frm ngine Oil	Ph3614 Wix 28.78		148.78	1.00 1.00
- Shop Suppl Workorder:	ce. ies	s 2.00 Meter:	5032	Labor:	Shop Su 1348 Oil 5w20 Er	ipplies Filter Frm ngine Oil			148.78	1.00 1.00 5.00
- Shop Suppl Workorder: Problem:	Hours : 1101489 P. M. SERVIC	s 2.00 Meter:	5032	Labor:	Shop Su 1348 Oil 5w20 Er 120.00	ipplies Filter Frm ngine Oil Parts: In Date:	28.78	Total:		1.00 1.00 5.00
- Shop Suppl Workorder: Problem: - P. M. Service	ce. ies Hour : 1101489 P. M. SERVIC	s 2.00 Meter:	5032	Labor:	Shop Su 1348 Oil 5w20 Er 120.00	ipplies Filter Frm ngine Oil Parts: In Date:	28.78	Total:		1.00 1.00 5.00
- Shop Suppl Workorder: Problem:	ce. ies Hour : 1101489 P. M. SERVIC	s 2.00 Meter:	5032	Labor:	Shop Su 1348 Oil 5w20 Er 120.00 Parts Li Shop Su	ipplies Filter Frm ngine Oil Parts: In Date: st	28.78	Total:		1.00 1.00 5.00 011 Qty 1.00
- Shop Suppl Workorder: Problem: - P. M. Service	ce. ies Hour : 1101489 P. M. SERVIC	s 2.00 Meter:	5032	Labor:	Shop Su 1348 Oil 5w20 Er 120.00 Parts Li Shop Su 3424 Fu	ipplies Filter Frm ngine Oil Parts: In Date: st ipplies el Filter Fri	28.78	Total: Closed:		Qty 1.00 1.00 5.00 011 Qty 1.00 1.00
- Shop Suppl Workorder: Problem: - P. M. Service	ce. ies Hour : 1101489 P. M. SERVIC	s 2.00 Meter:	5032	Labor:	Shop Su 1348 Oil 5w20 Er 120.00 Parts Li Shop Su 3424 Fu	ipplies Filter Frm rigine Oil Parts: In Date: st ipplies el Filter Frm	28.78 02/08/2011 m 3424 Wix 3	Total: Closed:		1.00 1.00 5.00 011 Qty 1.00 1.00
- Shop Suppl Workorder: Problem: - P. M. Service	ce. ies Hour : 1101489 P. M. SERVIC	s 2.00 Meter:	5032	Labor:	Shop Su 1348 Oil 5w20 Er 120.00 Parts Li Shop Su 3424 Fu 1348 Oil 5w20 Er	ipplies Filter Frm ngine Oil Parts: In Date: st ipplies el Filter Frm ngine Oil	28.78 02/08/2011 m 3424 Wix 3	Total: Closed: 3424 51348		1.00 1.00 5.00 011 Qty 1.00 1.00
- Shop Suppl Workorder: Problem: - P. M. Service	Hours : 1101489 P. M. SERVIC	s 2.00 Meter:	5032	Labor:	Shop Su 1348 Oil 5w20 Er 120.00 Parts Li Shop Su 3424 Fu 1348 Oil 5w20 Er	Ipplies I Filter Frm Ingine Oil Parts: In Date: st Ipplies In Filter Frm I Filter Frm Ingine Oil Wiper Blade	28.78 02/08/2011 m 3424 Wix 3 Ph3614 Wix	Total: Closed: 3424 51348		1.00 1.00 5.00 011 Qty 1.00 1.00 5.00
- Shop Suppl Workorder: Problem: - P. M. Service - Shop Suppl	Hours : 1101489 P. M. SERVIC	s 2.00 Meter: EE, needs viscos 2.00 Meter:	5032	Labor:	Shop Su 1348 Oil 5w20 Er 120.00 Parts Li Shop Su 3424 Fu 1348 Oil 5w20 Er Nb-18 V	Ipplies I Filter Frm Ingine Oil Parts: In Date: st Ipplies In Filter Frm I Filter Frm Ingine Oil Wiper Blade	28.78 02/08/2011 m 3424 Wix 3 Ph3614 Wix s 18" Anco 3	Total: Closed: 3424 51348	02/18/20	1.00 1.00 5.00 5.00 011 1.00 1.00 5.00 2.00
- Shop Suppl Workorder: Problem: - P. M. Servic - Shop Suppl Workorder: Problem:	Hours 1101489 P. M. SERVIC ce ies Hours 1102048 canciever refla	s 2.00 Meter: EE, needs versions 2.00 Meter: ash	5032 washer fluid.	Labor:	Shop Su 1348 Oil 5w20 Er 120.00 Parts Li Shop Su 3424 Fu 1348 Oil 5w20 Er Nb-18 V 120.00	Ipplies I Filter Frm Ingine Oil Parts: In Date: st Ipplies In Filter Frm I Filter Frm I Filter Frm I Filter Blade Parts: In Date:	28.78 02/08/2011 m 3424 Wix 3 Ph3614 Wix s 18" Anco 3 47.23	Total: Closed: 3424 51348 31-18 Total:	02/18/20	1.00 1.00 5.00 011 Qty 1.00 1.00 5.00 2.00
- Shop Suppl Workorder: Problem: - P. M. Servic - Shop Suppl Workorder: Problem:	Hours 1101489 P. M. SERVIC De ies Hours 1102048 canciever refla	s 2.00 Meter: EE, needs versions 2.00 Meter: ash	5032 washer fluid.	Labor:	Shop Su 1348 Oil 5w20 Er 120.00 Parts Li Shop Su 3424 Fu 1348 Oil 5w20 Er Nb-18 V	Ipplies I Filter Frm Ingine Oil Parts: In Date: st Ipplies el Filter Frm Ingine Oil Viper Blade Parts: In Date:	28.78 02/08/2011 m 3424 Wix 3 Ph3614 Wix s 18" Anco 3 47.23	Total: Closed: 3424 51348 31-18 Total:	02/18/20	1.00 1.00 5.00 011 Qty 1.00 1.00 5.00 2.00

Problem: R/FRONT TIRE LOW	In Dat	e: 07/13/2011	Closed:	07/15/20)11	
- C/c: R/f tire. Dismount, patch, mount, balance, add N2.	Parts List				Qty	
- Shop Supplies	Shop Supplies				1.00	
Hours 1.00 Labo	r: 60.00 Pa	arts: 2.00	Total:	62.00		
Workorder: 1108972 Meter: 8645 Problem: P. M. SERVICE	In Dat	e: 08/24/2011	Closed:	08/26/20)11	
- P. M. Service.	Parts List				Qty	
- Nail in front right tire. Dismount, patch, mount, balance, a	dd Shop Supplies				1.00	
N2, rotate to right rear.	1348 Oil Filter I	Frm Ph3614 Wix	51348		1.00	
- Shop Supplies	5w20 Engine Oi	il			5.00	
	05023 Battery C	Cleaner			1.00	
Hours 3.00 Labo	r: 180.00 Pa	arts: 31.79	Total:	211.79		
Workorder: 1201095 Meter: 11376 Problem: P.M., Driver's side seat belt won't retract, &	In Date ee notes.	e: 02/01/2012	Closed:	02/08/20)12	
- P. M. Service.	Parts List				Qty	
- Add nitrogen to all new tires.	Shop Supplies		1.00			
- Verify needs four tires. Dismount, ,mount, & balance.	3424 Fuel Filter		1.00			
- Transport & pick up vehicle at dealer. (recall # 11s17 fuel	1348 Oil Filter I	1348 Oil Filter Frm Ph3614 Wix 51348				
line).	5w20 Engine Oi	il			5.00	
- Dealer to replace driver's seat belt retractor.	Nb-18 Wiper Bl		2.00			
Chan Cunnlina						
- Shop Supplies	Tire Disposal Fe				4.00	
	183482418 P22	25/70r15 Wrangle			4.00 4.00	
	183482418 P22			899.07		
	183482418 P22	25/70r15 Wrangle arts: 509.07		899.07	4.00	
Hours 6.50 Labor: Workorder: 1203776 Meter: 12908 Problem: DRIVER SEAT TORN - transpoort and pick up vehicel at dealer (defective I/f	183482418 P22 r: 390.00 Pa	25/70r15 Wrangle arts: 509.07	Total:		4.00	
Hours 6.50 Laboration: Workorder: 1203776 Meter: 12908 Problem: DRIVER SEAT TORN - transpoort and pick up vehicel at dealer (defective I/f backrest cover)	183482418 P22 r: 390.00 Pa	25/70r15 Wrangle arts: 509.07	Total:		4.00	
Hours 6.50 : Workorder: 1203776 Meter: 12908 Problem: DRIVER SEAT TORN - transpoort and pick up vehicel at dealer (defective I/f backrest cover) - dealer to replace dirver seat back rest cover	183482418 P22 r: 390.00 Pa In Dat	25/70r15 Wrangle arts: 509.07	Total:		4.00 012 Qty	
Hours 6.50 : Workorder: 1203776 Meter: 12908 Problem: DRIVER SEAT TORN - transpoort and pick up vehicel at dealer (defective I/f backrest cover) - dealer to replace dirver seat back rest cover - Shop Supplies	183482418 P22 r: 390.00 Pa In Date Parts List Shop Supplies	25/70r15 Wrangle arts: 509.07 re: 04/20/2012	Total:	04/30/20	4.00 012 Qty	
Hours 6.50 : Workorder: 1203776 Meter: 12908 Problem: DRIVER SEAT TORN - transpoort and pick up vehicel at dealer (defective I/f backrest cover) - dealer to replace dirver seat back rest cover - Shop Supplies	183482418 P22 r: 390.00 Pa In Date Parts List Shop Supplies	25/70r15 Wrangle arts: 509.07	Total:		4.00 012 Qty	
Hours 6.50 : Workorder: 1203776 Meter: 12908 Problem: DRIVER SEAT TORN - transpoort and pick up vehicel at dealer (defective I/f backrest cover) - dealer to replace dirver seat back rest cover - Shop Supplies	183482418 P22 r: 390.00 Pa In Date Parts List Shop Supplies	25/70r15 Wrangle arts: 509.07 re: 04/20/2012	Total:	04/30/20	4.00 012 Qty 1.00	
Hours 6.50 : Workorder: 1203776 Meter: 12908 Problem: DRIVER SEAT TORN - transpoort and pick up vehicel at dealer (defective I/f backrest cover) - dealer to replace dirver seat back rest cover - Shop Supplies Hours 2.00 Eabor: Workorder: 1204910 Meter: 13343	183482418 P22 r: 390.00 Pa In Date Parts List Shop Supplies r: 120.00 Pa In Date Parts List	25/70r15 Wrangle arts: 509.07 re: 04/20/2012	Total: Closed: Total:	04/30/20	4.00 012 Qty 1.00	
Hours 6.50 : Workorder: 1203776 Meter: 12908 Problem: DRIVER SEAT TORN - transpoort and pick up vehicel at dealer (defective I/f backrest cover) - dealer to replace dirver seat back rest cover - Shop Supplies Hours 2.00 : Workorder: 1204910 Meter: 13343 Problem: WONT START - Jump start at Wud Meter Dept. Recharge & test battery.	183482418 P22 r: 390.00 Pa In Date Parts List Shop Supplies r: 120.00 Pa In Date	25/70r15 Wrangle arts: 509.07 re: 04/20/2012	Total: Closed: Total:	04/30/20	4.00 012 Qty 1.00	

Workorder: Problem:	1208415 pm	Meter:	15177			In Date:	09/05/2012	Closed:	09/12/2	012
- pm					Parts Li	st				Qty
- Shop Suppli	es				Shop Su	pplies				1.00
					•	• •	Ph3614 Wix	51348		1.00
					5w20 Er	naine Oil				5.00
	Ho :	ours 2.00		Labor:	120.00	•	23.99	Total:	143.99	
Workorder: Problem:	1211154 left rer flat ,	Meter: nail	16573			In Date:	11/16/2012	Closed:	11/26/2	012
- Ck Left Rea		erify Nail In L	/r Tire Dism	ount Patch	Parts Li	st				Qty
Mount Balance - Shop Suppli					Shop Su	ipplies				1.00
	Ho	ours 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1302956 pm, wiper fl	Meter:	17738			In Date:	03/26/2013	Closed:	04/09/20	013
- pm					Parts Li	st				Qty
- Shop Suppli	es				Filter					1.00
					Napa Qı	uart 5w20				5.00
					Napagol	d Fuel Filte	r			1.00
					Wiper B	ade				2.00
					Mac Wit	e Lithium G	res			1.00
					Ca8243	Air Filter Lb	of			1.00
					Shop Su	pplies				1.00
	Ho	ours 2.00		Labor:	120.00	Parts:	64.19	Total:	184.19	
Workorder: Problem:	1308627 nail in rt from	Meter:	18779			In Date:	08/27/2013	Closed:	08/27/20	013
- repair nail in	r front tire				Parts Li	st				Qty
- Shop Suppli					Shop Su					1.00
		ours 1.00		Labor:	•	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1309742 rr tire flat	Meter:	19350			In Date:	09/26/2013	Closed:	09/27/2	013
- ck right rear	tire flat dism	ount patch n	nount balan	ce add n2	Parts Li	st				Qty
- Shop Suppli	es				Shop Su	pplies				1.00

Labor: 60.00

Parts: 2.00

Total: 62.00

Hours 1.00

Workorder: Problem:	1309782 pm		Meter:	19378			In Date:	09/27/2013	Closed:	10/04/2013
- pm	r					Parts L	ist			Qty
- Shop Suppli	es						ld Oil Filter			1.00
Chop Cappii							uart 5w20			5.00
						Wiper E				2.00
						Shop S				1.00
		Hours	2.00		Lahor:	120.00		32.24	Total	152.24
		: 10ui 5	2.00		Labor.	120.00	raits.	32.24	Total.	132.24
Workorder: Problem:	1309862 rr tire flat		Meter:	19350			In Date:	09/26/2013	Closed:	09/30/2013
- Tow From: 9	9045 jog ro	ad bo	ynton To	o: sr delray						
		Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1401593 need spa	re key	Meter:	22388			In Date:	02/19/2014	Closed:	02/25/2014
- Make and p	rogram on	e key				Parts L	ist			Qty
- Shop Suppli	- Make and program or - Shop Supplies					Ford Igi	nition Key B	lank		1.00
	- Shop Supplies					Shop S	upplies			1.00
		Hours	1.00		Labor:			28.61	Total:	88.61
Workorder: Problem:	1401914 pm, powe	er stee	Meter: ering mak	22767 ing noise			In Date:	02/27/2014	Closed:	03/27/2014
- pm						Parts L	ist			Qty
- ck power ste	ering mak	king no	oise verifi	ed custoimer	concer	Napa Q	uart 5w20			5.00
found rack and	d pinion le	aking ı	rr rack ar	nd pinion assy	flush ps	Napago	ld Oil Filter			1.00
sys test drive						Napago	old Fuel Filte	er		1.00
- replace 4 tire			(- (l- P-	1.6		Rack A	nd Pinion			1.00
- replace and	-		-	•	_	Brake C	Cleaner			2.00
- resurface fro			•			Pwr Ste	ering Fl-qua	art		3.00
- replace brok			er busnin	gs tube and is	ever	183482	418 P225-7	0r15		4.00
- replace 3rd	_					Vtx6090	Led Strobe	e CI		1.00
- fill all tires w	•	n				Brake F	ads			1.00
- Shop Suppli	es					Spring				1.00
						Gear Lu	ınger			1.00
						Pin				1.00
						Pin				1.00
						Tube				1.00
						F3tz7l2	78a Bushing	g Sh		2.00
						Lever				1.00
						Dampe	r Assy			1.00
						Shop S	-			1.00
						•	posal Fee			4.00
		Hours :	17.50		Labor:	1,050.0 0	•	1,515.97	Total:	2,565.97

Workorder: Problem:	1402739 NEEDS A	Meter: LIGNMENT	22671			In Date:	03/21/2014	Closed:	03/24/20)14
- commercial	repair				Parts Lis	st				Qty
- transport an	d pick up v	ehicle at elpex	for alignment		Shop Sup	oplies				1.00
- Shop Suppli	es									
	 	Hours 2.00		Labor:	120.00	Parts:	2.00	Total:	122.00	
Workorder: Problem:	1408537 no power	Meter: steering	26025			In Date:	08/26/2014	Closed:	09/08/20)14
- replace leak	ing high pr	essure hose fr	om pump to ra	ack	Parts Lis	st				Qty
- replace bad	replace bad battery					eering Hos	se			1.00
- Shop Suppli	- Shop Supplies					ring Fl-qua	ırt			2.00
					Brake Cle	eaner				1.00
					Battery					1.00
					Shop Sup	oplies				1.00
		Hours 3.00		Labor:	180.00	Parts:	157.09	Total:	337.09	
Workorder: Problem:	1410340 P.M.SER	Meter: VICE	27152			In Date:	10/15/2014	Closed:	10/21/20)14
- pm					Parts Lis	st				Qty
	ayers not v	working remov	e hoses clear l	lines and	Pwr Stee	ring Fl-gua	rt			
										1.00
spray tips flush		ssemble				d Oil Filter				1.00 1.00
- Shop Suppli		ssemble				d Oil Filter				
		ssemble			Napagolo	d Oil Filter art 5w20				1.00
		ssemble			Napagolo Napa Qu	d Oil Filter art 5w20 ade				1.00 5.00
		ssemble			Napagolo Napa Qu Wiper Bla	d Oil Filter art 5w20 ade				1.00 5.00 2.00
	es	Hours 4.00		Labor:	Napagolo Napa Qu Wiper Bla Washer F	d Oil Filter art 5w20 ade		Total:	281.29	1.00 5.00 2.00 1.00
- Shop Suppli Workorder:	es 		30299	Labor:	Napagold Napa Qu Wiper Bla Washer F Shop Sup 240.00	d Oil Filter art 5w20 ade Fl		Total:	281.29	1.00 5.00 2.00 1.00
- Shop Suppli Workorder: Problem:	1503266 screw in I	Hours 4.00		Labor:	Napagold Napa Qu Wiper Bla Washer F Shop Sup 240.00	d Oil Filter art 5w20 ade Fl oplies Parts:	41.29			1.00 5.00 2.00 1.00
- Shop Suppli Workorder: Problem:	es 1503266 screw in I	Hours 4.00 Meter: eft front tire		Labor:	Napagold Napa Qu Wiper Bla Washer F Shop Sup 240.00	d Oil Filter art 5w20 ade Fl oplies Parts:	41.29 03/30/2015			1.00 5.00 2.00 1.00 1.00
- Shop Suppli Workorder: Problem: - ck screw in f	es 1503266 screw in I	Hours 4.00 Meter: eft front tire		Labor:	Napagold Napa Qu Wiper Bla Washer F Shop Sup 240.00	d Oil Filter art 5w20 ade Fl oplies Parts: In Date: 18 P225-70	41.29 03/30/2015			1.00 5.00 2.00 1.00 1.00
- Shop Suppli Workorder: Problem: - ck screw in f	es 1503266 screw in I	Hours 4.00 Meter: eft front tire		Labor:	Napagold Napa Qu Wiper Bla Washer F Shop Sup 240.00	d Oil Filter art 5w20 ade Fl oplies Parts: In Date: 18 P225-70 oplies	41.29 03/30/2015			1.00 5.00 2.00 1.00 1.00 015 Qty 1.00

Workorder:	1504670	Meter:	30959			n Date:	05/07/2015	Closed:	05/19/20	015
Problem:	pm, ck srobe t	flashers le	ft high beam o	out lube d	loor hiinges	and lock	S			
- pm					Parts List	:				Qty
- repair left he	ead light				Napa Qua	rt 5w20			5.00	
- replace and	rewire left fron	t strobe lig	ht		Napagold	Oil Filter				1.00
- replace both	front lower ba	ll joints			Wiper Blad	de			2.00	
- Shop Suppli	es				Washer Fl				1.00	
					Napagold	Fuel Filte	er			1.00
					Napagold	Air Filter				1.00
					Halogen C	Capsule				1.00
					Vtx609c L	ed Strobe	e CI			1.00
					Lower Bal	l Joint				2.00
					Shop Sup	plies				1.00
	Hour	s 7.25		Labor:	435.00	Parts:	254.56	Total:	689.56	
Workorder: Problem:	1511406 P.M.SERVICE	Meter:	34879		I	n Date:	11/06/2015	Closed:	11/30/20	015
- pm					Parts List					Qty
- replace two	front tires				Napagold	Oil Filter				1.00
- replace brok	cen radio				Napa Qua		5.00			
- Shop Suppli	es				Napagold Fuel Filter					2.00
					Washer Fl	uid Conc	entr			1.00
					Tire /p225	/70/15 / H	lankook			2.00
					Radio					1.00
					Shop Sup	plies				1.00
					Tire Dispo	sal Fee				2.00
	Hour	s 4.50		Labor:	270.00	Parts:	435.11	Total:	705.11	
Workorder: Problem:	1601329 strobes not wo	Meter: orking flasl	36229 her not workin	ng, runs ro		n Date:	02/08/2016	Closed:	02/10/20	016
	nd hazard inop i				Parts List	:				Qty
•	maltifunction sv		•		Bulb					1.00
_	h replace 4 spa	ark plugs v	vires and ign (COII	multi funct	ion switcl	h			1.00
- Shop Suppli	es				Vtx609c L	ed Strobe	e CI			2.00
					Spark Plug	g				4.00
					Ignition Co	oil Pack				1.00
					Wire Asy					1.00
					Shop Sup	plies				1.00
	Hour	s 8.75		Labor:	525.00	Parts:	480.80	Total:	1,005.80	0
	•									

Workorder: 1605012 Meter: 38423 Problem: Pm service.Gear shift indicator.	In Date:	05/13/2016	Closed:	05/25/2016
- Pm service.	Parts List			Qty
- Replace broken shifter indicator.	Napagold Oil Filter			1.00
- Replace both tag light assemblies.	Napa Quart 5w20	5.00		
- Replace leaking windshield washer pump.	Tag Lamp	2.00		
- Replace both outer stablizer bar links.	Washer Fluid Conc	entr		1.00
- Replace right rear tire.rotate and balance all four.	18" wiper blades			2.00
- Shop Supplies	Shift indicator			1.00
	Bulb			2.00
	Washer Pump			1.00
	Sway Bar Repair Ki	it		1.00
	183482418 P225-7			1.00
	Shop Supplies			1.00
	Tire Disposal Fee			1.00
Hours 10.25 Labor:	·	324.40	Total:	939.40
Workorder: 1611708 Meter: 42064 Problem: PM service.driver seat belt problem.Flasher pr	In Date: oblem.Check for reca	11/15/2016 all.	Closed:	12/12/2016
- Pm service	Parts List			Qty
- C/c hazards inop.replace signal flasher unit.	Buckle Assy			1.00
- C/c seat belt.verify d/s seat belt gets stuck.replace receiver	Radio			1.00
and harness	Napagold Oil Filter			1.00
- Vacume cab and clear debris from ac vent intake.	Napa Quart 5w20			5.00
- Repair left rear tire.rotate and balance all.add N2	Flasher			1.00
- Verify radio inop.replace radio.	Seat Belt			1.00
- Shop Supplies	Shop Supplies			1.00
Hours 8.50 Labor:	510.00 Parts:	840.17	Total:	1,350.17
Workorder: 1704979 Meter: 45296 Problem: Pm Service	In Date:	05/18/2017	Closed:	05/30/2017
- Pm Service.	Parts List			Qty
- Pm Service Replace four tires.	Parts List Napagold Oil Filter			Qty 1.00
				-
- Replace four tires.	Napagold Oil Filter	ır		1.00
Replace four tires.Replace both outer stabilizer bar links.	Napagold Oil Filter Napa Quart 5w20			1.00 5.00
Replace four tires.Replace both outer stabilizer bar links.Resurface front and rear rotors.service front and rear	Napagold Oil Filter Napa Quart 5w20 Napagold Fuel Filte			1.00 5.00 1.00
 Replace four tires. Replace both outer stabilizer bar links. Resurface front and rear rotors.service front and rear calipers.replace pads. 	Napagold Oil Filter Napa Quart 5w20 Napagold Fuel Filter Napagold Air Filter			1.00 5.00 1.00 1.00
 Replace four tires. Replace both outer stabilizer bar links. Resurface front and rear rotors.service front and rear calipers.replace pads. Test drive after repairs. 	Napagold Oil Filter Napa Quart 5w20 Napagold Fuel Filte Napagold Air Filter Washer Fluid Conc	entr		1.00 5.00 1.00 1.00
 Replace four tires. Replace both outer stabilizer bar links. Resurface front and rear rotors.service front and rear calipers.replace pads. Test drive after repairs. 	Napagold Oil Filter Napa Quart 5w20 Napagold Fuel Filter Napagold Air Filter Washer Fluid Conc Wiper Blade	entr 0r15		1.00 5.00 1.00 1.00 1.00 2.00
 Replace four tires. Replace both outer stabilizer bar links. Resurface front and rear rotors.service front and rear calipers.replace pads. Test drive after repairs. 	Napagold Oil Filter Napa Quart 5w20 Napagold Fuel Filter Napagold Air Filter Washer Fluid Conc Wiper Blade 183482418 P225-7	entr 0r15		1.00 5.00 1.00 1.00 1.00 2.00 4.00
 Replace four tires. Replace both outer stabilizer bar links. Resurface front and rear rotors.service front and rear calipers.replace pads. Test drive after repairs. 	Napagold Oil Filter Napa Quart 5w20 Napagold Fuel Filter Napagold Air Filter Washer Fluid Conc Wiper Blade 183482418 P225-7 Sway Bar Repair Ki	entr 0r15 it		1.00 5.00 1.00 1.00 2.00 4.00 1.00
 Replace four tires. Replace both outer stabilizer bar links. Resurface front and rear rotors.service front and rear calipers.replace pads. Test drive after repairs. 	Napagold Oil Filter Napa Quart 5w20 Napagold Fuel Filter Napagold Air Filter Washer Fluid Conc Wiper Blade 183482418 P225-7 Sway Bar Repair Ki Disc Brake Pads Disc Brake Pad Set	entr 0r15 it		1.00 5.00 1.00 1.00 2.00 4.00 1.00
 Replace four tires. Replace both outer stabilizer bar links. Resurface front and rear rotors.service front and rear calipers.replace pads. Test drive after repairs. 	Napagold Oil Filter Napa Quart 5w20 Napagold Fuel Filter Napagold Air Filter Washer Fluid Conc Wiper Blade 183482418 P225-7 Sway Bar Repair Ki Disc Brake Pads	entr 0r15 it		1.00 5.00 1.00 1.00 2.00 4.00 1.00 1.00

Workorder: Problem:	1705952 DEAD BATTI	Meter: ERY	45733			In Date:	06/15/2017	Closed:	06/26/2017	7
- C/c battery.	test battery ba	d.replace b	attery.che	ck charging	Parts L Battery	ist				Qty .00
- Shop Suppl	ies				Shop S	upplies			1	.00
	Hou	rs 0.75		Labor:	45.00		118.76	Total:	163.76	
Workorder: Problem:	1710144 Driver Front	Meter: Accident Da	48134 amage			In Date:	10/16/2017	Closed:	10/16/2017	7
- Tow From: 9 Accident Line	9524 Richmon	d Circle, Bo	oca Raton	FI To:						
	Hou :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1710902 Check lights	Meter: and brakes	48251 noisey an	d hard to sh	ift.	In Date:	11/02/2017	Closed:	11/16/2017	7
- P.m. service	Э.				Parts L	ist			(Qty
	ht headlamp bi	ulb.replace	right rear	taillamp	Napago	old Oil Filter			1	.00
bulb.		_			5w20 E	ngine Oil			5	.00
 Remove ste assembly and 	ering column t	o replace s	hifter and	shifter rod	18" wip	er blades			2	.00
-	rear tire .rotate	a and halar	nce all four	tires nitro	Halogei	n Capsule			1	.00
service.	rear the hotat	e and balai	ice all loui	1163.11110	Bulb				1	.00
- Service fron	it and rear brak	kes Test dri	ive.		Tube				1	.00
- Shop Suppl	ies				Lever				1	.00
					F3tz7l2	78a Bushing	g Sh		2	.00
					Pin				1	.00
					Gear Lu	unger			1	.00
					Spring				1	.00
					Shop S	upplies			1	.00
	Hou	rs 8.80		Labor:	528.00	Parts:	194.60	Total:	722.60	
	1711050 Damage to le			der		In Date:	10/18/2017	Closed:	11/07/2017	7
- 9 - 10						_				

Labor: 0.00 Parts: 0.00

Total: 0.00

Hours 0.00

Workorder: 1804546 Meter: 52088 Problem: P.M. service and check brakes.		In	Date:	05/01/2018	Closed:	05/17/2018
- P.m. service.		Parts List				Qty
- Replace both front brake rotors ,calipers and pads	. Repack	5w20 Engir	ne Oil			5.00
front wheel bearings and replace seals . Flush and b	oleed	Napagold C	1.00			
brake system .test drive.		18" wiper b		2.00		
- R&r seat assembly for repair.		Napagold F	1.00			
- Rotate and high speed balance all four tires.		Brake Roto	r Hub			2.00
- Transport to and from dealer for recall 17s26.		Napa Oil S	eal			2.00
- Shop Supplies		Reman Bra	ke Calip	er		1.00
		Reman Bra	ke Calip	er		1.00
		B Fluid Dot	3-32oz			1.00
		Non-chlor E	Brake Clr	nr		2.00
		Seat R And	l R			1.00
		Pedal Pad				1.00
		Shop Supp	lies			1.00
Hours 9.50 :	Labor:	570.00	Parts:	680.02	Total:	1,250.02
Workorder: 1807245 Meter: 53857 Problem: Shift indicator inop.Airbag light on.		In	Date:	07/17/2018	Closed:	07/24/2018
- Remove cluster to replace defective shift indictor a	assembly	Parts List				Qty
adjust and retest.		Shift indica	tor			1.00
 Computer diagnose airbag light ,code B1212 . Per pinpoint test . Remove left front seat assembly to rep 		Buckle Assy				1.00
belt pretensioner. Clear codes and retest. Install floo		Ford Triton	Pvc Sw	С		1.00
and steering wheel cover.		Floor Mat-2	pc Rub	Bk		1.00
- Shop Supplies		Shop Supp	lies			1.00
Hours 3.50 :	Labor:	210.00	Parts:	305.30	Total:	515.30
Workorder: 1809818 Meter: 55791 Problem: Towed in right rear tire going flat and	will not co		Date:	09/24/2018	Closed:	09/28/2018
- Replace both rear tires and balance . Nitrogen fill	tires .	Parts List				Qty
- Test and cut down spare tire lift . Replace and rem		183482418	P225-70	0r15		2.00
spare.		Lift Asy				1.00
- Shop Supplies		Shop Supp	lies			1.00
		Tire Dispos				2.00
Hours 1.80 :	Labor:	108.00		448.83	Total:	556.83
Workorder: 1809819 Meter: 55791		In	Date:	09/24/2018	Closed:	09/24/2018
Problem: Tow in because TIre company could	not remov	e spare for p	o/f flat tir	е		
- Tow From: 8100 Forest hill blvd						
Hours 0.00 :	Labor:	0.00	Parts:	0.00	Total:	0.00

Workorder: Problem:	1809868 Passenger R	Meter: Rear tire flat	55791			In Date:	09/24/2018	Closed:	09/25/2018
- Tire Service Passenger Rea		ouilding, key	ys on floor bo	oard -					
r acconger rec		urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder:	1811053	Meter:	56693			In Date:	10/26/2018	Closed:	11/06/2018
Problem:	PM Service,	Fuel pump	sensor.						
- P.m. service					Parts L	ist			Qty
- Inspect and	replace serpe	entine belt.			Napa Q	uart 5w20			5.00
- Service and	inspect trans	mission . Re	eplace leakir	ng output	Napago	ld Oil Filter			1.00
shaft seal and	dipstick tube	seal . Repla	ace filter . Flu	ush and	18" wip	er blades			2.00
refill Replace two	tiros Potato	and halan	oo all faur tire	20	V Belt				1.00
Nitrofill and res		; and Daland	e all lour tire	35.	dip stick	seal			1.00
- Perform from	-	ent and road	d test.		Screen	Asy			1.00
- Shop Supplie	es				gasket f	ilter transmi	ssion		1.00
					Rear Tr	ans Seal			1.00
					Syn-atf	Trans Fluid	S		16.00
					P225/70	· ·			2.00
					Shop S				1.00
						posal Fee			2.00
	Ηοι :	urs 10.50		Labor:	703.50	Parts:	600.39	Total:	1,303.89
Workorder: Problem:	1811310 fueling proble	Meter: ems	56685			In Date:	11/01/2018	Closed:	11/02/2018
- test and rem	ove caceiver.	. issue fuel (card		Parts L	ist			Qty
- Shop Supplie	es				Shop S	upplies			1.00
	Hou :	urs 1.00		Labor:	67.00	Parts:	3.00	Total:	70.00
Workorder:									
	1813088 A/C not cold	Meter:	58465			In Date:	12/28/2018	Closed:	01/10/2019
Problem:	A/C not cold			a liquid	Porto I		12/28/2018	Closed:	
Problem: - A/c performa	A/C not cold ance test . Lea	ak test . Re _l	place leaking		Parts L	ist	12/28/2018	Closed:	Qty
Problem: - A/c performa line from comp Replace accum	A/C not cold ance test . Lea pressor to con mulator and o	ak test . Rep ndensor and rifice tube .	place leaking I to oriface tu Complete re	ibe .	Indicato	ist r Oil	12/28/2018	Closed:	Qty 1.00
Problem: - A/c performa line from comp Replace accum vacuum and re	A/C not cold ance test . Lea pressor to con mulator and o echarge . Rete	ak test . Rep ndensor and rifice tube .	place leaking I to oriface tu Complete re	ibe .	Indicato Freon L	ist	12/28/2018	Closed:	Qty 1.00 2.00
Problem: - A/c performa line from comp Replace accum	A/C not cold ance test . Lea pressor to con mulator and o echarge . Rete	ak test . Rep ndensor and rifice tube .	place leaking I to oriface tu Complete re	ibe .	Indicato Freon L Frig Oil	ist r Oil	12/28/2018	Closed:	Qty 1.00 2.00 1.00
Problem: - A/c performa line from comp Replace accum vacuum and re	A/C not cold ance test . Lea pressor to con mulator and o echarge . Rete	ak test . Rep ndensor and rifice tube .	place leaking I to oriface tu Complete re	ibe .	Indicato Freon L Frig Oil Tube	ist r Oil v Shop 2		Closed:	Qty 1.00 2.00 1.00
Problem: - A/c performa line from comp Replace accum vacuum and re	A/C not cold ance test . Lea pressor to con mulator and o echarge . Rete	ak test . Rep ndensor and rifice tube .	place leaking I to oriface tu Complete re	ibe .	Indicato Freon L Frig Oil Tube A/c Line	ist r Oil v Shop 2 • Compresso		Closed:	Qty 1.00 2.00 1.00
Problem: - A/c performa line from comp Replace accum vacuum and re	A/C not cold ance test . Lea pressor to con mulator and o echarge . Rete	ak test . Rep ndensor and rifice tube .	place leaking I to oriface tu Complete re	ibe .	Indicato Freon L Frig Oil Tube	ist r Oil v Shop 2 · Compresso		Closed:	Qty 1.00 2.00 1.00 1.00
Problem: - A/c performa line from comp Replace accum vacuum and re	A/C not cold ance test . Lea pressor to con mulator and o echarge . Rete	ak test . Rep ndensor and rifice tube .	place leaking I to oriface tu Complete re	ibe .	Indicato Freon L Frig Oil Tube A/c Line Tube As Accumu	ist r Oil v Shop 2 · Compresso		Closed:	Qty 1.00 2.00 1.00 1.00 1.00
Problem: - A/c performa line from comp Replace accum vacuum and re	A/C not cold ance test . Lea pressor to con mulator and o echarge . Rete	ak test . Rep ndensor and rifice tube .	place leaking I to oriface tu Complete re	ibe .	Indicato Freon L Frig Oil Tube A/c Line Tube As Accumu	ist r Oil v Shop 2 Compresso sy llator		Closed:	Qty 1.00 2.00 1.00 1.00 1.00 1.00
Problem: - A/c performa line from comp Replace accum vacuum and re	A/C not cold ance test . Lea pressor to con nulator and o echarge . Rete es	ak test . Rep ndensor and rifice tube .	place leaking I to oriface tu Complete re	be . cover and	Indicator Freon L Frig Oil Tube A/c Line Tube As Accumu	ist r Oil v Shop 2 Compresso sy llator Tube Filter upplies			Qty 1.00 2.00 1.00 1.00 1.00 1.00 1.00

Workorder: Problem:	1901262 A/C not blow	Meter: ving cold.	59014			In Date:	02/01/2019	Closed:	02/13/20	019
- A/c performa	ance test . Le	ak test . Re	cover froen . F	₹&r	Parts Li	st				Qty
leaking evapo			. Evucuate a	nd	Freon L	/ Shop 1				2.00
complete rech		. retest .			A/c Eva	oorator				1.00
- Shop Suppli	ies				Orifice T	ube Filter				1.00
					Seal					3.00
					O-ring					3.00
					O Ring					3.00
					Shop Su	ıpplies				1.00
	Ho :	urs 6.50		Labor:	435.50	Parts:	355.49	Total:	790.99	
Workorder: Problem:	1904531 PM Service,	Meter: Accident da	60952 amage.			In Date:	04/26/2019	Closed:	05/06/20)19
- P.m. service	Э.				Parts Li	st				Qty
- Test and rep	place left rear	strobe bulb	assembly and	d retest.	Napago	d Oil Filter				1.00
-	Test and replace left rear strobe bulb assembly and retest Rotate and high speed balance all four tires. Nitrofill all.					ngine Oil				5.00
- Shop Suppli	ies				18" wiper blades					2.00
					Napago	d Fuel Filte	r			1.00
					Mnt Cor	c Led Clea	r			1.00
					Clr Rtv S	Silcn Sealar	nt			1.00
					Shop Su	ıpplies				1.00
	Ho :	urs 4.00		Labor:	268.00	Parts:	146.55	Total:	414.55	
Workorder: Problem:	1905562 Damage to	Meter: right side of	60952 bed, cab & riç	ght door		In Date:	05/02/2019	Closed:	05/28/20	019
- Damage to	•		ght door			_				
	Ho :	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1911292 P.M. Service	Meter:	61435			In Date:	10/30/2019	Closed:	11/07/20	019
- P.m. service	Э.				Parts Li	st				Qty
- Test and rep		e blower res	sistor and corr	oded	Blower I	Motor Resis	tor			1.00
connector pigt		_			Napago	d Oil Filter				1.00
 Check batte battery . Batte 					5w20 Er	ngine Oil				5.00
- Balance and	•			. , .	18" wip	er blades				2.00
- Shop Suppli		55 . 14101	un		Battery					1.00
Chap Cappi					Connect					1.00
					Shop Su	ıpplies				1.00
	Но	urs 5.50		Labor:	401.50	Parts:	200.62	Total:	602.12	

Workorder: Problem:	2005929 P.M. Service.	Meter:	61435			In Date:	06/16/2020	Closed:	06/23/2020
- P.m. Service	Э.				Parts Li	st			Qty
- Rotate and I	Rotate and balance tires.				Napago		1.00		
- Shop Suppli	Shop Supplies				5w20 Engine Oil				
	- Snop Supplies				18" wip	er blades			2.00
					Washer	Fluid Conc	entr		1.00
					Shop St	upplies			1.00
	Hour :	s 3.00		Labor:	219.00	Parts:	30.72	Total:	249.72
Workorder: Problem:	2009451 Transition Pre	Meter: p Charge	61435			In Date:	09/18/2020	Closed:	09/18/2020
- Transition P	rep Charge								
	Hour :	s 2.00		Labor:	146.00	Parts:	0.00	Total:	146.00