10192679 2013 FORD F350 Pickup, 1 Ton, 4X4

Workorder: 1307741 Meter: 309 In Date: 08/02/2013 Closed: 08/02/2013 **Problem:** 1061 - Pre Delivery Inspection - Pre Delivery Inspection Labor: 120.00 Total: 120.00 Hours 2.00 Parts: 0.00 Workorder: 1307871 Meter: 774 In Date: 08/06/2013 Closed: 08/20/2013 Problem: Remove transfer fuel tank and tool box from asset# 10156396 and install both into 10192679 - Remove aux, fuel tank and tool box from 10156396 and **Parts List** Qty install in new truck and rewire pump. Floor Mat-2pc Rub Bk 1.00 - Shop Supplies **Shop Supplies** 1.00 Labor: 390.00 Hours 6.50 Parts: 29.69 Total: 419.69 1400287 Workorder: Meter: 6866 In Date: 01/09/2014 Closed: 01/22/2014 Problem: Pm service - P.m. Service. **Parts List** Qty 5w20 Engine Oil - Inspect and service aux. fuel system. 7.00 - Rotate and balance all tires. Napagold Oil Filter 1.00 - Shop Supplies Washer Fluid Concentr 1.00 Napagold Fuel Filter 1.00 Napagold Fuel Filter 1.00 **Shop Supplies** 1.00 Hours 4.75 Labor: 285.00 Parts: 36.80 Total: 321.80 Workorder: 1405243 Meter: 12162 In Date: 05/29/2014 Closed: 06/11/2014 Problem: P.M. service. - P.m. Service. **Parts List** Qty - Inspect and service aux fuel system. 5w20 Engine Oil 8.00 Napagold Oil Filter - Replace tag lamp. 1.00 - Rotate and balance all tires. Wiper Blade 2.00 - Shop Supplies Napagold Fuel Filter 1.00 Lamp Asy 1.00 **Shop Supplies** 1.00

Labor: 315.00

Parts: 54.83

Total: 369.83

Hours 5.25

Workorder: 1411921 Meter: 17200 Problem: P.M. Service.		In Date:	11/25/2014	Closed:	12/04/2014
- Pm service.		Parts List			Qty
- Inspect and service auxiliary fuel tank.	5w20 Engine Oil			7.00	
- Rotate and balance all four tires.	Napagold Oil Filte	r		1.00	
- Shop Supplies	Napagold Air Filte	er		1.00	
		Wiper Blade			2.00
		Used Fire X Refu	bished		1.00
		Napagold Fuel Fil	ter		1.00
		Shop Supplies			1.00
Hours 6.00 :	Labor:	360.00 Parts	s: 62.80	Total:	422.80
Workorder: 1506575 Meter: 22805 Problem: P.M. Service.		In Date:	06/30/2015	Closed:	07/09/2015
- Pm service.		Parts List			Qty
- Replace and balance four tires.		5w20 Engine Oil			7.00
- Inspect and service auxiliary fuel tank.		Napagold Oil Filte	r		1.00
- Complete front end alignment.		Wiper Blade	2.00		
- Shop Supplies		Lt245 75r17			4.00
		Shop Supplies			1.00
		Tire Disposal Fee			4.00
Hours 8.25 :	Labor:	495.00 Parts	s: 1,262.32	Total:	1,757.32
Workorder: 1600759 Meter: 28657		In Date:	01/22/2016	Closed:	02/08/2016
Problem: P.M. Service.Check aux fuel tank m	eter.				
D '					
- Pm service.		Parts List			Qty
- Pm service.- Test starting and charging system.battery failed longer	oadtest	Parts List 5w20 Engine Oil			Qty 7.00
- Test starting and charging system.battery failed leafter recharge.replace defective battery.			r		-
 Test starting and charging system.battery failed leafter recharge.replace defective battery. Replace defective auxiliary fuel tank pump meter 		5w20 Engine Oil			7.00
 Test starting and charging system.battery failed leafter recharge.replace defective battery. Replace defective auxiliary fuel tank pump meter service fuel tank. 		5w20 Engine Oil Napagold Oil Filte			7.00 1.00
 Test starting and charging system.battery failed leafter recharge.replace defective battery. Replace defective auxiliary fuel tank pump meter service fuel tank. Rotate and balance all four tires. 		5w20 Engine Oil Napagold Oil Filte Napagold Air Filte	er		7.00 1.00 1.00
 Test starting and charging system.battery failed leafter recharge.replace defective battery. Replace defective auxiliary fuel tank pump meter service fuel tank. 		5w20 Engine Oil Napagold Oil Filte Napagold Air Filte 22" Wiper Blade	er bished		7.00 1.00 1.00 2.00
 Test starting and charging system.battery failed leafter recharge.replace defective battery. Replace defective auxiliary fuel tank pump meter service fuel tank. Rotate and balance all four tires. 		5w20 Engine Oil Napagold Oil Filte Napagold Air Filte 22" Wiper Blade Used Fire X Refu	er bished Ford		7.00 1.00 1.00 2.00 1.00
 Test starting and charging system.battery failed leafter recharge.replace defective battery. Replace defective auxiliary fuel tank pump meter service fuel tank. Rotate and balance all four tires. 		5w20 Engine Oil Napagold Oil Filte Napagold Air Filte 22" Wiper Blade Used Fire X Reful Stg Wheel Cov - F	er bished Ford		7.00 1.00 1.00 2.00 1.00 1.00
 Test starting and charging system.battery failed leafter recharge.replace defective battery. Replace defective auxiliary fuel tank pump meter service fuel tank. Rotate and balance all four tires. 		5w20 Engine Oil Napagold Oil Filte Napagold Air Filte 22" Wiper Blade Used Fire X Reful Stg Wheel Cov - F	er bished Ford ze		7.00 1.00 1.00 2.00 1.00
 Test starting and charging system.battery failed leafter recharge.replace defective battery. Replace defective auxiliary fuel tank pump meter service fuel tank. Rotate and balance all four tires. 		5w20 Engine Oil Napagold Oil Filte Napagold Air Filte 22" Wiper Blade Used Fire X Reful Stg Wheel Cov - F Ford Red Antifree Battery 65	er bished Ford ze		7.00 1.00 1.00 2.00 1.00 1.00 1.00
 Test starting and charging system.battery failed leafter recharge.replace defective battery. Replace defective auxiliary fuel tank pump meter service fuel tank. Rotate and balance all four tires. 	and	5w20 Engine Oil Napagold Oil Filte Napagold Air Filte 22" Wiper Blade Used Fire X Reful Stg Wheel Cov - F Ford Red Antifree Battery 65 Napagold Fuel Fil	er bished Ford ze		7.00 1.00 1.00 2.00 1.00 1.00 1.00

Workorder: Problem:	1607607 P.M. service.	Meter:	34439		lr	n Date:	07/26/2016	Closed:	07/29/2016
- P.m. Service) .				Parts List				Qt
- Inspect and service aux. fuel system.				5w20 Engi	ne Oil			7.0	
- Rotate and balance all tires.					Napagold (Oil Filter			1.0
- Shop Supplies					22" Wiper	Blade			2.0
					Free Repla	aces Pen	tron		1.0
					Napagold I	Fuel Filte	er		1.0
					Shop Supp	olies			1.0
	Hours :	s 6.00		Labor:	360.00	Parts:	54.40	Total:	414.40
Workorder:	1613163	Meter:	38838			Date:	12/29/2016	Closed:	01/25/2017
	Right side mir					nd P.M.	service.		
	r panel and rep		_		Parts List				Qt
 Inspect and meter. 	service aux. fu	el system.i	eplace defe	ctive	Mirror				1.0
- P.m. Service	2				Fuel Meter				1.0
	st and inspect c	ooling sys	tem flush an	d refill	Napagold Fuel Filter				1.0
system.	it and mopeot o	oomig sys	ioni.naon an	a roilli	Napagold Oil Filter				1.0
- Resurface fr	ont brake rotor	s,replace f	ront pads.se	rvice and	5w20 Engi				7.0
lube calipers.fl	ush and bleed	system.			22" Wiper Blade Washer Fluid Concentr				2.0
- Shop Suppli	es								1.0
					Wd40 8oz				1.0
					Used Fire				1.0
					Anti Freeze		ratt		2.0
					Front Brak				1.0
		40.50			Shop Supp		4 000 00	.	1.0
	Hours :	s 13.50		Labor:	810.00	Parts:	1,093.22	l otal:	1,903.22
Workorder: Problem:	1706546 P.M. service.	Meter:	43839		lr	n Date:	07/03/2017	Closed:	07/10/2017
- P.m. service					Parts List				Qt
- Inspect and service auxiliary fuel system.				5w20 Engine Oil			7.0		
- Rotate and high speed balance all four wheels.nitro fill all.				Napagold (Oil Filter			1.0	
- Shop Supplies				22" Wiper Blade				2.0	
					Washer Flu	uid Conc	entr		1.0
					Stg Wheel	Cov - Fo	ord		1.0
					Napagold I	Fuel Filte	er		1.0
					Shop Supp	olies			1.0
	Hours	s 6.00		Lahor.	360.00	Parte:	50.90	Total:	410.90

Workorder: Problem:	1800567 P.M. service.	Meter:	48997		In	Date:	01/17/2018	Closed:	01/25/20	18
- P.m. service	e.				Parts List					Qty
- Broken pintle pin .replace with new.				5w20 Engin	e Oil				7.00	
 Inspect and service transfer case.drain and refill. Test battery and charging system.battery failed load test .r&r with new .remove and replace badly corroded battery terminal with cable with new. 					Napagold O		1.00			
					Napagold A	ir Filter				1.00
					22" Wiper Blade				2.00	
- Inspect and	service auxilia	ry fuel tank	, 		Pintle Pin W	•			1.00 3.00	
- Rotate and I	high speed bal	ance all fou	ur tires.		Ford Transf	er Case	Fluid			
- Shop Suppli	• .				Battery					1.00
					Napagold F	uel Filte	r			1.00
					Cable Asy					1.00
					Used Fire X		shed			1.00
					Shop Suppli					1.00
	Hou	rs 9.30		Labor:	558.00	Parts:	365.75	Total:	923.75	
Workorder: Problem:	1807475 P.M. service.	Meter:	54507		In	Date:	07/23/2018	Closed:	07/31/20	10
	P.M. service.		54507		In Parts List	Date:	07/23/2018	Closea:	07/31/20	
Problem: - P.m. service	P.M. service.			es.				Ciosea:	07/31/20	Qty
Problem: - P.m. service - Replace all	P.M. service.	ance and ni	trogen fill tire	es.	Parts List	uel Filte		Closea:	07/31/20	Qty 1.00
Problem: - P.m. service - Replace all - Inspect and	P.M. service. e. four tires . Bala	ance and ni	trogen fill tire	es.	Parts List Napagold F	uel Filte Dil Filter		Closed:	07/31/20	Qty 1.00
Problem: - P.m. service - Replace all - Inspect and	P.M. service. e. four tires . Bala service auxilar mplete front en	ance and ni	trogen fill tire	es.	Parts List Napagold F Napagold O	uel Filte Dil Filter e Oil	r	Closed:	07/31/20	Qty 1.00 1.00 7.00 1.00
Problem: - P.m. service - Replace all - Inspect and - Perform con	P.M. service. e. four tires . Bala service auxilar mplete front en	ance and ni	trogen fill tire	es.	Parts List Napagold Fr Napagold O 5w20 Engine	uel Filte il Filter e Oil id Conce	r	Closed:	07/31/20	Qty 1.00 1.00 7.00
Problem: - P.m. service - Replace all - Inspect and - Perform con	P.M. service. e. four tires . Bala service auxilar mplete front en	ance and ni	trogen fill tire	es.	Parts List Napagold For Napagold O 5w20 Engine Washer Flui	uel Filte bil Filter e Oil id Conce Blade	r	Closed:	07/31/20	Qty 1.00 1.00 7.00 1.00
Problem: - P.m. service - Replace all - Inspect and - Perform con	P.M. service. e. four tires . Bala service auxilar mplete front en	ance and ni	trogen fill tire	es.	Parts List Napagold Fi Napagold O 5w20 Engine Washer Flui 22" Wiper B	uel Filte Dil Filter De Oil Did Conce Blade	r	Closed:	07/31/20	Qty 1.00 1.00 7.00 1.00 2.00
Problem: - P.m. service - Replace all - Inspect and - Perform con	P.M. service. e. four tires . Bala service auxilar mplete front en	ance and ni	trogen fill tire	es.	Parts List Napagold Fi Napagold O 5w20 Engine Washer Flui 22" Wiper B Lt245 75r17	uel Filte Dil Filter e Oil id Conce Blade , ies	r	Closed:	07/31/20	Qty 1.00 1.00 7.00 1.00 2.00 4.00 1.00
Problem: - P.m. service - Replace all - Inspect and - Perform con	P.M. service. e. four tires . Bala service auxilar mplete front end ies	ance and ni	trogen fill tire		Parts List Napagold Fr Napagold O 5w20 Engin Washer Flui 22" Wiper B Lt245 75r17 Shop Suppli	uel Filte Dil Filter e Oil id Conce Blade dies	r		1,687.69	Qty 1.00 1.00 1.00 2.00 4.00 4.00 4.00
Problem: - P.m. service - Replace all - Inspect and - Perform con - Shop Suppli	P.M. service. e. four tires . Bala service auxilar mplete front end ies	ance and ni ry fuel tank d alignmen rs 9.50	trogen fill tire		Parts List Napagold Fi Napagold O 5w20 Engin Washer Flui 22" Wiper B Lt245 75r17 Shop Suppli Tire Disposa 570.00	uel Filte Dil Filter e Oil id Conce Blade dies	r entr			Qty 1.00 1.00 7.00 1.00 2.00 4.00 1.00 4.00
Problem: - P.m. service - Replace all - Inspect and - Perform con - Shop Suppli	P.M. service. four tires . Balaservice auxilar implete front end ies Hou : 1809914 Clean fuel tar	ance and ni ry fuel tank d alignmen rs 9.50	trogen fill tire t. Road test.		Parts List Napagold Fi Napagold O 5w20 Engin Washer Flui 22" Wiper B Lt245 75r17 Shop Suppli Tire Disposa 570.00	uel Filter e Oil id Conce slade ies al Fee Parts:	r entr 1,117.69	Total:	1,687.69	Qty 1.00 1.00 7.00 1.00 2.00 4.00 1.00 4.00
Problem: - P.m. service - Replace all - Inspect and - Perform con - Shop Suppli Workorder: Problem:	P.M. service. four tires . Balaservice auxilar mplete front end ies Hou : 1809914 Clean fuel tar	ance and ni ry fuel tank d alignmen rs 9.50	trogen fill tire t. Road test.		Parts List Napagold Fi Napagold O 5w20 Engine Washer Flui 22" Wiper B Lt245 75r17 Shop Suppli Tire Disposa 570.00	uel Filter e Oil id Conce Blade ies al Fee Parts:	r entr 1,117.69 09/25/2018	Total:	1,687.69	Qty 1.00 1.00 7.00 1.00 2.00 4.00 1.00 4.00
Problem: - P.m. service - Replace all - Inspect and - Perform con - Shop Suppli Workorder: Problem: - Polish Aux.	P.M. service. four tires . Balaservice auxilar mplete front end ies Hou : 1809914 Clean fuel tar	ance and ni ry fuel tank d alignmen rs 9.50	trogen fill tire t. Road test.		Parts List Napagold For Napagold Of Sw20 Engine Washer Fluit 22" Wiper B Lt245 75r17 Shop Supplit Tire Disposation 570.00 In Parts List	uel Filter ie Oil id Conce Blade ies al Fee Parts: Date:	r entr 1,117.69 09/25/2018	Total:	1,687.69	Qty 1.00 1.00 7.00 1.00 2.00 4.00 4.00

Workorder: 1901268 Meter: 59957 Problem: PM Service	In Date: 02/01/2019 Closed:	02/20/2019
- P.m. service.	Parts List	Qty
- Inspect and service auxillary fuel tank .	Napagold Oil Filter	1.00
- Replace cracked right rear tail lamp lens and mount strobe	5w20 Engine Oil	8.00
bulb .	22" Wiper Blade	2.00
- Replace all sixteen spark plugs and wire set .	Washer Fluid Concentr	1.00
 Perform complete air intake decarb cleaning and flush injectors. 	Ford Triton Pvc Swc	1.00
- Rotate and balance all four tires . Nitrofill all.	Used Fire X Refurbished	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
- Shop Supplies	Lamp Asy	1.00
	Espak Plug Wire	4.00
	Espak Plug Wire	4.00
	Spark Plug	16.00
	Intake Cleaner Kit	1.00
	Injector Cleaner	1.00
	Shop Supplies	1.00
11 40.00	074.00 Danta: 400.70 Tatal:	4 00 4 70
Hours 13.00 Labor:	871.00 Parts: 433.76 Total:	1,304.76
Workorder: 1907243 Meter: 64499 Problem: P.M. service and sadle tank leaking .	In Date: 07/15/2019 Closed:	07/30/2019
: Workorder: 1907243 Meter: 64499		
: Workorder: 1907243 Meter: 64499 Problem: P.M. service and sadle tank leaking . - P.m. service Check and replace all four defective body mounts , two	In Date: 07/15/2019 Closed:	07/30/2019
: Workorder: 1907243 Meter: 64499 Problem: P.M. service and sadle tank leaking P.m. service.	In Date: 07/15/2019 Closed: Parts List	07/30/2019 Qty
: Workorder: 1907243 Meter: 64499 Problem: P.M. service and sadle tank leaking. - P.m. service. - Check and replace all four defective body mounts, two fronts and two rear. - Check auxilary fuel tank for leaks. Clean bed of truck.	In Date: 07/15/2019 Closed: Parts List Napagold Oil Filter	07/30/2019 Qty 1.00
: Workorder: 1907243 Meter: 64499 Problem: P.M. service and sadle tank leaking. - P.m. service. - Check and replace all four defective body mounts, two fronts and two rear. - Check auxilary fuel tank for leaks. Clean bed of truck. Replace leaking hose and nozzle Retest.	In Date: 07/15/2019 Closed: Parts List Napagold Oil Filter 5w20 Engine Oil	07/30/2019 Qty 1.00 7.00
: Workorder: 1907243 Meter: 64499 Problem: P.M. service and sadle tank leaking. - P.m. service. - Check and replace all four defective body mounts, two fronts and two rear. - Check auxilary fuel tank for leaks. Clean bed of truck.	In Date: 07/15/2019 Closed: Parts List Napagold Oil Filter 5w20 Engine Oil 22" Wiper Blade	07/30/2019 Qty 1.00 7.00 2.00
: Workorder: 1907243 Meter: 64499 Problem: P.M. service and sadle tank leaking. - P.m. service. - Check and replace all four defective body mounts, two fronts and two rear. - Check auxilary fuel tank for leaks. Clean bed of truck. Replace leaking hose and nozzle Retest. - Computer diagnose misfire. Replace defective number one	In Date: 07/15/2019 Closed: Parts List Napagold Oil Filter 5w20 Engine Oil 22" Wiper Blade Ford Triton Pvc Swc	07/30/2019 Qty 1.00 7.00 2.00 1.00
: Workorder: 1907243 Meter: 64499 Problem: P.M. service and sadle tank leaking. - P.m. service. - Check and replace all four defective body mounts, two fronts and two rear. - Check auxilary fuel tank for leaks. Clean bed of truck. Replace leaking hose and nozzle Retest. - Computer diagnose misfire. Replace defective number one coil and retest. - Balance and rotate all four tires. Nitrofill all.	In Date: 07/15/2019 Closed: Parts List Napagold Oil Filter 5w20 Engine Oil 22" Wiper Blade Ford Triton Pvc Swc Body Mount Kit	07/30/2019 Qty 1.00 7.00 2.00 1.00 2.00
: Workorder: 1907243 Meter: 64499 Problem: P.M. service and sadle tank leaking. - P.m. service. - Check and replace all four defective body mounts, two fronts and two rear. - Check auxilary fuel tank for leaks. Clean bed of truck. Replace leaking hose and nozzle Retest. - Computer diagnose misfire. Replace defective number one coil and retest.	In Date: 07/15/2019 Closed: Parts List Napagold Oil Filter 5w20 Engine Oil 22" Wiper Blade Ford Triton Pvc Swc Body Mount Kit Body Mount Kit	07/30/2019 Qty 1.00 7.00 2.00 1.00 2.00 2.00
: Workorder: 1907243 Meter: 64499 Problem: P.M. service and sadle tank leaking. - P.m. service. - Check and replace all four defective body mounts, two fronts and two rear. - Check auxilary fuel tank for leaks. Clean bed of truck. Replace leaking hose and nozzle Retest. - Computer diagnose misfire. Replace defective number one coil and retest. - Balance and rotate all four tires. Nitrofill all.	In Date: 07/15/2019 Closed: Parts List Napagold Oil Filter 5w20 Engine Oil 22" Wiper Blade Ford Triton Pvc Swc Body Mount Kit Body Mount Kit 3/4" X 12 ' Hardwall Ul330&ulc	07/30/2019 Qty 1.00 7.00 2.00 1.00 2.00 2.00 1.00
: Workorder: 1907243 Meter: 64499 Problem: P.M. service and sadle tank leaking. - P.m. service. - Check and replace all four defective body mounts, two fronts and two rear. - Check auxilary fuel tank for leaks. Clean bed of truck. Replace leaking hose and nozzle Retest. - Computer diagnose misfire. Replace defective number one coil and retest. - Balance and rotate all four tires. Nitrofill all.	In Date: 07/15/2019 Closed: Parts List Napagold Oil Filter 5w20 Engine Oil 22" Wiper Blade Ford Triton Pvc Swc Body Mount Kit Body Mount Kit 3/4" X 12 ' Hardwall Ul330&ulc Nozzle	07/30/2019 Qty 1.00 7.00 2.00 1.00 2.00 1.00 1.00 1.00
: Workorder: 1907243 Meter: 64499 Problem: P.M. service and sadle tank leaking. - P.m. service. - Check and replace all four defective body mounts, two fronts and two rear. - Check auxilary fuel tank for leaks. Clean bed of truck. Replace leaking hose and nozzle Retest. - Computer diagnose misfire. Replace defective number one coil and retest. - Balance and rotate all four tires. Nitrofill all.	In Date: 07/15/2019 Closed: Parts List Napagold Oil Filter 5w20 Engine Oil 22" Wiper Blade Ford Triton Pvc Swc Body Mount Kit Body Mount Kit 3/4" X 12 ' Hardwall Ul330&ulc Nozzle Napagold Fuel Filter	07/30/2019 Qty 1.00 7.00 2.00 1.00 2.00 1.00 1.00 1.00

Workorder: 2001678 Meter: 69934	In Date: 02/18/2020	Closed: 02	2/20/2020	
Problem: P.M. service and meter hard to read on auxilia	ry fuel pump .			
- P.m.service .	Parts List		Qty	
- Inspect and service front differential.	Napagold Oil Filter		1.00	
- Inspect and service rear differential .	5w20 Engine Oil		7.00	
- Remove meter lens and polish .reinstall . Inspect and	22" Wiper Blade		2.00 2.00 1.00	
service auxiliary fuel tank .	Non-chlor Brake Clnr			
- Repair right rear tire . Rotate and balance all four tires .	Px Grey Rtv Silicone			
Nitrofill all.	Napa Gear 80w-90 Qt		3.00	
- Shop Supplies	Friction Modifier		2.00	
	75w140 Ford Axle Lube		3.00	
	Napagold Fuel Filter		1.00	
	Shop Supplies		1.00	
Hours 10.00 Labor:	730.00 Parts: 183.51	Total: 91	13.51	
Workorder: 2009418 Meter: 74851 Problem: Transition Prep Charge	In Date: 09/18/2020 (Closed: 09	9/18/2020	
- Transition Prep Charge				
Hours 2.00 Labor:	146.00 Parts: 0.00	Total: 14	16.00	