10183729 2012 FORD F250 Pickup, 3/4 Ton, Crew Cab

Workorder: Problem:	1111836 Pre Delivery	Meter: Inspection	0			In Date:	11/03/2011	Closed:	11/03/20	011
- Pre Delivery	•	·								
. To Delivery	•	rs 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	1112653 need 2 extra	<b>Meter:</b> keys	314			In Date:	11/30/2011	Closed:	11/30/20	011
- Make and pr	ogram 2 extra	a keys			Parts Li	st				Qty
- Shop Suppli	es				164-r80	40 Ignition k	Key 2011- Nev	wer (ford)		2.00
					Shop Su	ıpplies				1.00
	Hou :	rs 1.00		Labor:	60.00	Parts:	48.50	Total:	108.50	
Workorder: Problem:	1113165 Install air con	Meter: npressor, fr	1938 ont hitch			In Date:	12/14/2011	Closed:	05/10/20	012
- Installed fue	l tank,grounde	ed, wired to	pilot light & to	oggle	Parts Li	st				Qty
switch		1.14			Shop Su	ıpplies				1.00
- Installed tow					1372 O	il Filter Frm	Ph2 Wix 51	372		1.00
- Installed air screen	compressor &	modified b	racket, install	ea bug		Adapter Kit				1.00
- Toped off fu	el in auxilarv t	ank					ith Pintle Ring	)		1.00
- Pm Service	,				5w20 Er	•				7.00
- Shop Suppli	es					_	n / 730-4097			1.00
						Red Pilot Li	_	1)		1.00
	Цал	uro 11 OF		Lobori		-	ch (standard	•	2.750.2	1.00
	Hou :	irs 11.25		Labor:	675.00	Parts:	2,075.24	Total:	2,750.2	4
Workorder: Problem:	1202268 2 - Key(s) iss	Meter: sued	771			In Date:	03/06/2012	Closed:	03/06/20	012
- 2 - Key(s) is:	sued				Parts Li	st				Qty
					Duplicat	e Vehicle K	eys			2.00
	Hou	irs 0.40		Labor:	24.00	Parts:	6.00	Total:	30.00	
Workorder: Problem:	1204468 Fabricate a n	Meter: nount to sto	2047 ore the tow ba	ır		In Date:	05/10/2012	Closed:	05/11/20	012
- fab /weld bra	acket to hold to	ow bar up			Parts Li	st				Qty
- Shop Suppli		•			Shop Su	ıpplies				1.00
·						k Paint Glo	ss			1.00
	Hou	rs 3.50		Labor:	210.00	Parts:	8.77	Total:	218.77	

Workorder: 1302387 Meter: 9763 In Date: 03/11/2013 Closed: Problem: Pm service  - Pm service - Replace aps fuel filter - Replace aps fuel filter - Battery failed load test. Replace battery and check charging 1372 Oil Filter system Rotate and balance tires - Rotate and balance tires - Test drive - Shop Supplies  Shop Supplies	Qty 1.00 1.00 7.00 2.00 327.54  03/12/2013  Qty 7.00 1.00 2.00 1.00 1.00 537.43
- Pm Service On Air Compressor - Shop Supplies - Shop Supplies - Shop Supplies - Shop Supplies - Hours 4.75 - Labor: - Battery failed load test. Replace battery and check charging system Rotate and balance tires - Test drive - Shop Supplies - Hours 5.75 - Shop Supplies - Removed and straightened bent lock rod spring Pm Service - Parts List - Napa Quart 5w20 - Parts: - Viving Blades 22" Wiper Blades - Viving Blades - Vivi	1.00 1.00 7.00 2.00 327.54  03/12/2013  Qty 7.00 1.00 2.00 1.00 1.00 1.00 537.43
- Shop Supplies	7.00 2.00 327.54  03/12/2013  Qty 7.00 1.00 2.00 1.00 1.00 537.43
Hours 4.75   Labor: 285.00   Parts: 42.54   Total: 285.00   Parts: 42.54   Part	2.00 327.54 03/12/2013 Qty 7.00 1.00 2.00 1.00 1.00 537.43
Workorder: 1302387 Meter: 9763 In Date: 03/11/2013 Closed: Problem: Pm service  - Pm service - Replace aps fuel filter - Replace aps fuel filter - Battery failed load test. Replace battery and check charging system Rotate and balance tires - Test drive - Shop Supplies - Shop Supplies - Hours 5.75 - Labor: 345.00 Parts: 192.43 Total:  Workorder: 1304196 Meter: 10823 In Date: 04/29/2013 Closed: Problem: Tow bar not locking.	327.54 03/12/2013 Qty 7.00 1.00 2.00 1.00 1.00 537.43
Workorder: 1302387 Meter: 9763 In Date: 03/11/2013 Closed: Problem: Pm service  - Pm service - Replace aps fuel filter - Battery failed load test. Replace battery and check charging system Rotate and balance tires - Test drive - Shop Supplies  Hours 5.75 Labor: 345.00 Parts: 192.43 Total:  Workorder: 1304196 Meter: 10823 In Date: 04/29/2013 Closed: Problem: Tow bar not locking.	03/12/2013 Qty 7.00 1.00 2.00 1.00 1.00 537.43
Problem: Pm service - Pm service - Replace aps fuel filter - Replace aps fuel filter - Battery failed load test. Replace battery and check charging system Rotate and balance tires - Test drive - Shop Supplies - Shop Supplies - Hours 5.75 - Labor: 345.00 - Removed and straightened bent lock rod spring.  Parts List  Parts List  Napa Quart 5w20  1372 Oil Filter  31-22 Wiper Blades 22  Element  Battery 65  Shop Supplies  Shop Supplies  In Date: 04/29/2013  Closed:  Parts List	Qty 7.00 1.00 2.00 1.00 1.00 537.43
- Replace aps fuel filter - Battery failed load test. Replace battery and check charging system Rotate and balance tires - Test drive - Shop Supplies  Hours 5.75 Labor: 345.00 Parts: 192.43  Workorder: 1304196 Meter: 10823 Problem: Tow bar not locking.  Removed and straightened bent lock rod spring.  Napa Quart 5w20 1372 Oil Filter 31-22 Wiper Blades 22 Element Battery 65 Shop Supplies  Shop Supplies  In Date: 04/29/2013 Closed: Parts List	7.00 1.00 2.00 1.00 1.00 1.00
- Battery failed load test. Replace battery and check charging system.  - Rotate and balance tires  - Test drive  - Shop Supplies  Hours 5.75  Labor: 345.00  Workorder: 1304196  Meter: 10823  Problem: Tow bar not locking.  - Removed and straightened bent lock rod spring.  1372 Oil Filter  31-22 Wiper Blades 22  Element  Shop Supplies  Shop Supplies  In Date: 04/29/2013  Closed:  Parts List	1.00 2.00 1.00 1.00 1.00 537.43
system.  - Rotate and balance tires  - Test drive  - Shop Supplies  Hours 5.75  Labor: 345.00  Workorder: 1304196  Meter: 10823  Problem: Tow bar not locking.  - Removed and straightened bent lock rod spring.  31-22 Wiper Blades 22  Element  Battery 65  Shop Supplies  Shop Supplies  In Date: 04/29/2013  Closed:  Parts List	2.00 1.00 1.00 1.00 537.43
- Rotate and balance tires  - Rotate and balance tires  - Test drive  - Shop Supplies  - Shop Supplies  - Hours 5.75  - Labor: 345.00  - Parts: 192.43  - Total:  Workorder: 1304196  - Meter: 10823  - Problem: Tow bar not locking.  - Removed and straightened bent lock rod spring.  Parts List	1.00 1.00 1.00 537.43
- Test drive - Shop Supplies  Hours 5.75 Labor: 345.00 Parts: 192.43 Total:  Workorder: 1304196 Problem: Tow bar not locking.  Removed and straightened bent lock rod spring.  Parts List	1.00 1.00 537.43
- Shop Supplies  Hours 5.75 Labor: 345.00 Parts: 192.43 Total:  Workorder: 1304196 Meter: 10823 Problem: Tow bar not locking.  - Removed and straightened bent lock rod spring.  Parts List	1.00 537.43
Hours 5.75 Labor: 345.00 Parts: 192.43 Total:  Workorder: 1304196 Meter: 10823 In Date: 04/29/2013 Closed: Problem: Tow bar not locking.  - Removed and straightened bent lock rod spring.  Parts List	537.43
: Workorder: 1304196 Meter: 10823 In Date: 04/29/2013 Closed: Problem: Tow bar not locking.  - Removed and straightened bent lock rod spring.  Parts List	
Problem: Tow bar not locking.  - Removed and straightened bent lock rod spring.  Parts List	04/29/2013
- Shop Supplies Shop Supplies	Qty
	1.00
Hours 1.00 Labor: 60.00 Parts: 2.00 Total:	62.00
Workorder: 1305306 Meter: 11986 In Date: 05/30/2013 Closed: Problem: Replace hitch.	06/18/2013
- Install new tow hitch. Parts List	Qty
- Shop Supplies Blue Ox 20k Draw Bar	1.00
Shop Supplies	1.00
Freight Charge	1.00
Hours 2.00 Labor: 120.00 Parts: 2,343.80 Total:	2,463.80
Workorder: 1307439 Meter: 13394 In Date: 07/25/2013 Closed: Problem: fuel pump not pumping	07/29/2013
- Check Aps fuel pump. Inlet screen clogged.removed and Parts List	Qty
cleaned screen. Changed fuel filter. Element	1.00
- Shop Supplies Shop Supplies	1.00
Hours 2.00 Labor: 120.00 Parts: 6.68 Total:	126 68

Workorder: Problem:	1308554 Pm service.	Meter:	14562			In Date:	08/26/2013	Closed:	09/04/2013
- Pm service.					Parts Li	st			Q
- Aps. Service	e fuel filter.				Napa Qu	uart 5w20			7.0
- Service air o	compressor.				Napagol	d Oil Filter			1.0
- Rotate and	balance tires.				Washer	Fluid Conc	entr		1.0
- Test drive.					Wiper BI	ade			2.0
- Shop Suppli	ies				Element				1.0
					Napa 10	w30 Qt			1.0
					Shop Su	pplies			1.0
	Ho :	urs 5.75		Labor:	345.00	Parts:	50.08	Total:	395.08
Workorder: Problem:	1402351 Pm service.	Meter:	18746			In Date:	03/10/2014	Closed:	03/24/2014
- Pm service.					Parts Li	st			Q
- Replace fue	l filter,clean s	screen.			Napa Qu	uart 5w20			7.0
- Pm compres					Napagol	d Oil Filter			1.0
- Rotate and	balance tires.				Wiper BI	ade			2.0
- Test drive.					Element				2.0
- Shop Suppli	ies				Shop Su	pplies			1.0
	Ho	urs 6.25		Labor:	375.00	Parts:	50.24	Total:	425.24
Workorder: Problem:	1408156 Pm service.	Meter: Check rear	23460 brakes.			In Date:	08/18/2014	Closed:	08/19/2014
- Pm service.					Parts Li	st			Q
- Replace fue	l filter elemer	nt.			Napagol	d Air Filter			1.0
- Pm compres	ssor.				5w20 Oi	l Bulk			7.0
- Rear brakes					Napagol	d Oil Filter			1.0
rocks stuck be reassemble.	etween backir	ng plate and	rotor. Clean	and	Wiper BI	ade			2.0
- Test drive.					Washer	Fluid Conc	entr		1.0
- Shop Suppli	ioc				Element				1.0
- Shop Suppli	162				Napa 10	w30 Qt			1.0
					Brake Cl	eaner			1.0
					Shop Su	pplies			1.0
	Ho :	urs 9.25		Labor:	555.00	Parts:	55.45	Total:	610.45
Workorder: Problem:	1409366 Replace bro	Meter: oken bolt in h	24475 nitch.			In Date:	09/18/2014	Closed:	09/22/2014
- Replace bro	ken bolt in tr	ailer hitch.							
		urs 0.50		Labor:	30.00	Parts:	0.00	Total·	30.00
		G.O 0.00		Labor.	55.50	. 4113.	5.00	i otai.	50.00

Problem:	1411364 Aps fuel pur	<b>Meter:</b> np not runni	26236 ng.		In	Date:	11/14/2014	Closed:	11/26/20	014
- Diagnose Ap	os fuel pump	power circu	it.		Parts List					Qty
- Replace Sho		•			Max-40 Fus	е				5.00
- Shop Suppli	•				12 Vdc Pum	np 15 Gr	om			1.00
отор очррт					Solenoid	ام د. م.				1.00
					Shop Suppli	ies				1.00
	Ho	urs 4.00		Labor:	240.00		611.65	Total:	851.65	1100
Workorder: Problem:	1412174 Repair hitch	Meter:	26284		In	Date:	12/04/2014	Closed:	12/09/20	)14
- Straighten b as needed.	ent hitch arm	. Replace m	issing bolts	and pins	Parts List					Qty
- Shop Suppli	es				Shop Suppli	ies				1.00
Chop Cuppii		urs 2.00		Labor:	120.00	Parts:	2.00	Total:	122.00	
Workorder: Problem:	1412518 Won't start.	Meter:	26506		In	Date:	12/15/2014	Closed:	12/17/20	014
- Check start	circuit. Repla	ce start rela	V.		Parts List					Qty
- Shop Suppli		00 010	, .		Shop Suppli	ies				1.00
опор опрри		urs 1.00		Labor:		Parts:	2.00	Total:	62.00	
Workorder: Problem:	1500108 Replace bat	Meter: tery.	26586		In	Date:	01/06/2015	Closed:	01/08/20	)15
- Replace dea	ad batterv.				Parts List					Qty
- Shop Suppli	•				Batterv					-
- Shop Suppli	•				Battery Shop Suppli	ies				1.00
- Shop Suppli	ies	urs 1.00		Labor:	Shop Suppli		121.61	Total:	181.61	-
Workorder:	ies	Meter:	27279	Labor:	Shop Suppli 60.00		121.61 02/11/2015	Total:	181.61	1.00
Workorder: Problem:	Hoi : 1501557	Meter:	27279	Labor:	Shop Suppli 60.00	Parts:				1.00 1.00
Workorder: Problem: - Pm service	Hongian Hongia	Meter:		Labor:	Shop Suppli 60.00 In	Parts:	02/11/2015			1.00 1.00
Workorder: Problem: - Pm service - Replace Tpr	Hongian Hongia	Meter:		Labor:	Shop Suppli 60.00 In Parts List Tpms12 Ser	Parts:  Date:	02/11/2015			1.00 1.00 015 Qty 1.00
Workorder: Problem: - Pm service - Replace Tpr - Test drive	Honging Hongin Honging Honging Honging Honging Honging Honging Honging Honging	Meter:		Labor:	Shop Suppli 60.00  In  Parts List Tpms12 Ser 5w20 Oil Bu	Parts:  Date:  nsor Tire	02/11/2015			1.00 1.00 015 Qty 1.00 7.00
Workorder: Problem: - Pm service - Replace Tpr - Test drive	Honging Hongin Honging Honging Honging Honging Honging Honging Honging Honging	Meter:		Labor:	Shop Suppli 60.00  In  Parts List Tpms12 Ser 5w20 Oil Bu Napagold O	Parts:  Date:  nsor Tire ilk il Filter	02/11/2015			1.00 1.00 1.00 015 Qty 1.00 7.00 1.00
Workorder: Problem: - Pm service - Replace Tpr - Test drive	Honging Hongin Honging Honging Honging Honging Honging Honging Honging Honging	Meter:		Labor:	Shop Suppli 60.00  In  Parts List Tpms12 Set 5w20 Oil But Napagold O Napagold A	Parts:  Date:  nsor Tire Ilk Il Filter Ir Filter	02/11/2015			1.00 1.00 1.00 015 Qty 1.00 7.00 1.00
Workorder: Problem:	Honging Hongin Honging Honging Honging Honging Honging Honging Honging Honging	Meter:		Labor:	Shop Suppli 60.00  In  Parts List Tpms12 Ser 5w20 Oil Bu Napagold O Napagold A Wiper Blade	Parts:  Date:  nsor Tire lk il Filter ir Filter	02/11/2015			1.00 1.00 1.00 015 Qty 1.00 7.00 1.00 1.00 2.00
Workorder: Problem: - Pm service - Replace Tpr - Test drive	House 1501557 Pm service. ms sensor no	Meter: t transmittin			Shop Suppli 60.00  In  Parts List Tpms12 Set 5w20 Oil Bu Napagold O Napagold A Wiper Blade Shop Suppli	Parts:  Date:  nsor Tire ilk il Filter ir Filter e	02/11/2015 e Pr	Closed:	02/12/20	1.00 1.00 1.00 015 Qty 1.00 7.00 1.00
Workorder: Problem: - Pm service - Replace Tpr - Test drive - Shop Suppli	House 1501557 Pm service. ms sensor no	Meter:			Shop Suppli 60.00  In  Parts List Tpms12 Ser 5w20 Oil Bu Napagold O Napagold A Wiper Blade	Parts:  Date:  nsor Tire ilk il Filter ir Filter e	02/11/2015	Closed:		1.00 1.00 1.00 015 Qty 1.00 7.00 1.00 1.00 2.00
Workorder: Problem: - Pm service - Replace Tpr - Test drive - Shop Suppli	House 1501557 Pm service. ms sensor no	Meter: t transmittin urs 3.75 Meter:			Shop Suppli 60.00  In  Parts List Tpms12 Ser 5w20 Oil Bu Napagold O Napagold A Wiper Blade Shop Suppli 225.00	Parts:  Date:  nsor Tire ilk il Filter ir Filter e	02/11/2015 e Pr	Closed:	02/12/20	1.00 1.00 1.00 1.00 7.00 1.00 2.00 1.00
Workorder: Problem: - Pm service - Replace Tpr - Test drive - Shop Suppli	Holican Holica	Meter: t transmittin urs 3.75 Meter:	g.		Shop Suppli 60.00  In  Parts List Tpms12 Ser 5w20 Oil Bu Napagold O Napagold A Wiper Blade Shop Suppli 225.00	Parts:  Date:  Insor Tire Ilk Ill Filter Ir Filter Ill Insor Tire Insor Tire Ill Insor Tire Ill Insor Tire Ins	02/11/2015 Pr 119.89	Closed:	02/12/20	1.00 1.00 1.00 1.00 7.00 1.00 2.00 1.00
Workorder: Problem: - Pm service - Replace Tpr - Test drive - Shop Suppli  Workorder: Problem:	Hotels  1501557 Pm service.  ms sensor notices  Hotels  1502678 Trailer plug.  diler plug to fractices	Meter: t transmittin urs 3.75 Meter:	g.		Shop Suppli 60.00  In  Parts List Tpms12 Ser 5w20 Oil Bu Napagold O Napagold A Wiper Blade Shop Suppli 225.00  In	Parts:  Date:  nsor Tire ilk il Filter ir Filter ies Parts:  Date:	02/11/2015 Pr 119.89	Closed:	02/12/20	1.00 1.00 1.00 1.00 7.00 1.00 2.00 1.00

Workorder: Problem:	1505056 Fuel pum	Meter: p hose leaking	29624		In I	Date:	05/19/2015	Closed:	05/26/20	015
- Replace lea	ıkina fuel ho	ose on aux. fue	el tank.		Parts List					Qty
- Shop Suppli	Ū				Shop Supplie	es				1.00
	ŀ	Hours 1.00		Labor:		Parts:	2.00	Total:	62.00	
	:									
Workorder:	1506466	Meter:	30968		In [	Date:	06/29/2015	Closed:	07/01/20	015
Problem:	APS fuel p	oump not work	ıng.							
- Replace clo	gged fuel fi	lter. Clean inta	ike screen.		Parts List					Qty
- Shop Suppli	ies				Element					1.00
					Shop Supplie	es				1.00
	} :	Hours 1.50		Labor:	90.00	Parts:	6.86	Total:	96.86	
Workorder: Problem:	1509487 Pm servic	Meter: e.	33164		In [	Date:	09/21/2015	Closed:	09/24/20	015
- Pm service.					Parts List					Qty
- Rotate and	balance tire	es.			5w20 Oil Bul	k				7.00
- Replace aps	s fuel filter a	and clean scre	en.		Napagold Oi	l Filter				1.00
- Service air o	-				Wiper Blade					2.00
<ul> <li>Check engir present. Could</li> </ul>		Check and cle e problem.	ar codes. p	00455	Washer Fluid	d Conc	entr			1.00
- Replace bro	ken pull ro	pe on compres	ssor.		Napa 10w30	Qt				1.00
- Test drive.					Brake Clean					1.00
- Shop Suppli	ies				Shop Supplie	es				1.00
	H :	Hours 8.25		Labor:	495.00	Parts:	47.00	Total:	542.00	
Workorder: Problem:	1600027 RR tire fla	Meter:	35401		In [	Date:	01/04/2016	Closed:	01/05/20	016
- Repair Rr tir	re.				Parts List					Qty
- Shop Suppli					Shop Supplie	es				1.00
	H ·	Hours 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1603749 Pm service	Meter:	37575		In [	Date:	04/11/2016	Closed:	04/18/20	016
- Pm service.					Parts List					Qty
- Replace all	tires,nitro fi	II and balance			5w20 Oil Bul	k				7.00
- Service com	npressor.				Napagold Oi	l Filter				1.00
- Replace aux	x. fuel tank	filter and clear	n intake scr	een.	Napagold Air	r Filter				1.00
- Test drive.					22" Wiper Bla	ade				2.00
- Shop Suppl	ies				Washer Fluid	d Conc	entr			1.00
					4700004001	+01E 7	5r17			4.00
					179636492 L	_1245-7	3117			
					Element		3117			1.00
					Element Napa 10w30	Qt	3117			1.00 1.00
					Element Napa 10w30 Shop Supplie	Qt es	3117			1.00 1.00 1.00
		Hours 6.75		1	Element Napa 10w30	Qt es I Fee	1,057.86	+	1,462.86	1.00 1.00 1.00 4.00

Workorder: 1604644 Meter: 38271 Problem: No Start			In Date:	05/03/2016	Closed:	05/10/20	)16
- Replace battery		Parts Li	st				Qty
- Check charging system		Battery					1.00
- Shop Supplies		Shop Su	pplies				1.00
Hours 2.00	Labor:	120.00	• •	120.41	Total:	240.41	
Workorder: 1607581 Meter: 40560 Problem: Check air compressor			In Date:	07/25/2016	Closed:	07/26/20	)16
- Aux compressor wouldn't run. Clean dirty carb.		Parts Li	st				Qty
- Test run.		Shop Su	pplies				1.00
- Shop Supplies							
Hours 1.50	Labor:	90.00	Parts:	2.00	Total:	92.00	
Workorder: 1705544 Meter: 47557			In Date:	06/05/2017	Closed:	06/08/20	)17
<b>Problem:</b> Pm service, power outlet not working.							
- Pm service.		Parts Li	st				Qty
- Rotate and balance tires.		5w20 Oi	l Bulk				7.00
- Power outlets not working. Replaced shorted fuses.		Napagol	d Oil Filter				1.00
Replace shorted Hmsl bulb.		Napagol	d Air Filter				1.00
- Replace aux. fuel tank filter and clean screen.		22" Wipe	er Blade				2.00
- Service compressor.		Washer	Fluid Conc	entr			1.00
- Shop Supplies		Used Fir	e X Refurb	ished			1.00
		Element					1.00
		Napa 10	w30 Qt				1.00
		Bp Fmx-	lp F Mx Fu	se			4.00
		Syn Atf E	Bulk Pahok	ee			2.00
		Shop Su	pplies				1.00
Hours 7.75	Labor:	465.00	Parts:	93.79	Total:	558.79	
Workorder: 1705675 Meter: 47479 Problem: 1 - Key(s) issued			In Date:	06/07/2017	Closed:	06/07/20	)17
- 1 - Key(s) issued		Parts Li	st				Qty
		Duplicate	e Vehicle K	eys			1.00
Hours 0.30	Labor:	18.00	Parts:	3.00	Total:	21.00	
Workorder: 1709308 Meter: 50743 Problem: Repair aux. Air compressor			In Date:	09/25/2017	Closed:	10/02/20	)17
- Air compressor leaking at regulator. Unloader valve	froze	Parts Li	st				Qty
up. Replace unloader valve		Unloade	r Pilot Valv	е			1.00
- Shop Supplies		Shop Su	pplies				1.00
Hours 2.50	Labor:	150.00		35.27	Total:	185.27	

Workorder: Problem:	1803117 Pm service.	Meter:	54603			In Date:	03/26/2018	Closed:	03/28/20	018
- Pm service.					Parts Li	st				Qty
- Replace Ap	s fuel filter and	clean scre	en.		5w20 Oi	l Bulk				7.00
- Service com	pressor.				Napago	ld Oil Filter				1.00
- Rotate and I	balance tires.				1qt Syn	gear Oil 75-	90			1.00
- Test drive.					22" Wipe	er Blade				2.00
- Shop Suppli	ies				Washer	Fluid Conc	entr			1.00
					Used Fi	re X Refurb	ished			1.00
					Element					1.00
					10w30 N	Notor Oil				1.00
					Shop Su	ıpplies				1.00
	Hou	rs 5.50		Labor:	330.00	Parts:	66.10	Total:	396.10	
Workorder: Problem:	1810376 Flat tire.	Meter:	59705			In Date:	10/09/2018	Closed:	10/11/20	018
- Repair Lr tir	e.				Parts Li	st				Qty
- Shop Suppli					Shop Su					1.00
		rs 1.00		Labor:		Parts:	3.00	Total:	70.00	
Workorder: Problem:	1810576 Pm service.	Meter:	60626			In Date:	10/15/2018	Closed:	10/30/20	018
- Pm service.					Parts Li	st				Qty
- Replace aps	s fuel filter and	clean intal	ke screen.		Napago	ld Oil Filter				1.00
- Rotate and I	balance tires.				5w20 Oi	l Bulk				7.00
- Test drive.					Napago	ld Air Filter				1.00
- Shop Suppli	ies				Washer	Fluid Conc	entr			1.00
					22" Wipe	er Blade				2.00
					Mac Wit	e Lithium G	ires			1.00
					Element					1.00
					Shop Su	upplies				1.00
	Hou	rs 5.25		Labor:	351.75	Parts:	50.64	Total:	402.39	
Workorder: Problem:	1812414 Flat tire.	Meter:	61405			In Date:	12/06/2018	Closed:	12/13/20	018
- Repair Rr tir	e.				Parts Li	st				Qty
	d load test. Re	place batte	ery. Test char	ging	Battery					1.00
•	hicle on side of	road.			Shop Su	ıpplies				1.00
- Shop Suppli							40=0-			
	Hou	rs 3.00		Labor:	201.00	Parts:	135.27	Total:	336.27	

Workorder: 19 Problem: Re	02032 place dama	Meter: aged front	62810 bumper and g	grille	ı	n Date:	02/22/2019	Closed:	03/14/20	19
- Replaced dama	ged front bi	umper ass	sy, tow hitch a	nd	Parts Lis	t				Qty
mounting brackets					Name Pla	te				1.00
- Blow out radiato	r and cond	ensor, clo	gged with gras	SS.	Grille					1.00
- Shop Supplies					Bumper A	ssy				1.00
					Bolt 1/2-1	3 X4				2.00
					Bumper B	lack				2.00
					Blue Ox 2	0k Draw E	3ar			1.00
					Blue Ox F	250 Base	Plate			1.00
					Blue Ox L	•				1.00
					Shop Sup	•				1.00
	Hour :	s 9.50		Labor:	636.50	Parts:	4,919.66	Total:	5,556.16	i
Workorder: 19 Problem: Pri	05163 n service.	Meter:	64601		I	n Date:	05/13/2019	Closed:	05/15/20	19
- Pm service.					Parts Lis	t				Qty
- Replace aux. fu	el tank and	clean inta	ke screen.		Napagold	Oil Filter				1.00
- Rotate and bala	nce tires.				5w20 Oil I	Bulk				7.00
- Test drive.					Napagold	Air Filter				1.00
- Shop Supplies					Washer F	luid Conce	entr			1.00
					22" Wiper	Blade				2.00
					Element					1.00
					Shop Sup	•				1.00
	Hour :	s 5.25		Labor:	351.75	Parts:	47.42	Total:	399.17	
Workorder: 19 Problem: Ch	07263 eck A/C	Meter:	66683		ı	n Date:	07/16/2019	Closed:	07/29/20	19
- Check a/c syste	m performa	ance. Evar	clegged. Cle	aned	Parts Lis	t				Qty
evap.					Shop Sup	plies				1.00
-						p00				
- Shop Supplies						p00				
-	Hour :	s 2.00		Labor:	134.00	Parts:	3.00	Total:	137.00	
- Shop Supplies  Workorder: 19	: 12316	Meter:	69789 ne light.	Labor:	134.00		3.00	Total:	137.00	
- Shop Supplies	: 12316	Meter:		Labor:	134.00	Parts:				19
- Shop Supplies  Workorder: 19 Problem: Pro-	: 12316 n service, cl	<b>Meter:</b> heck engir	ne light.		134.00	Parts:				
- Shop Supplies  Workorder: 19 Problem: Pro	: 12316 n service, cl el tank filter	<b>Meter:</b> heck engir	ne light.		134.00  Parts Liss 5w20 Oil	Parts: In Date: t Bulk				19 <b>Qty</b>
- Shop Supplies  Workorder: 19 Problem: Pm - Pm service Replace aux. fu	: 12316 n service, cl el tank filter	<b>Meter:</b> heck engir	ne light.		134.00	Parts: In Date: t Bulk Oil Filter				19 <b>Qty</b> 7.00
- Shop Supplies  Workorder: 19 Problem: Pm - Pm service Replace aux. fu - Rotate and bala - Test drive.	: 12316 n service, cl el tank filter nce tires.	<b>Meter:</b> heck engir r and clear	ne light. n intake scree	n.	134.00  Parts List 5w20 Oil I Napagold	Parts: In Date:  t Bulk Oil Filter Blade	12/02/2019			19 <b>Qty</b> 7.00 1.00
- Shop Supplies  Workorder: 19 Problem: Pro - Pm service Replace aux. fu - Rotate and bala	: 12316 In service, cl el tank filter Ince tires.	<b>Meter:</b> heck engir r and clear	ne light. n intake scree	n.	134.00  Parts List 5w20 Oil I Napagold 22" Wiper	Parts: In Date:  t Bulk Oil Filter Blade luid Conce	12/02/2019 entr			19 <b>Qty</b> 7.00 1.00 2.00
- Shop Supplies  Workorder: 19 Problem: Pro - Pm service Replace aux. fu - Rotate and bala - Test drive Diagnose check	: 12316 In service, cl el tank filter Ince tires.	<b>Meter:</b> heck engir r and clear	ne light. n intake scree	n.	Parts List 5w20 Oil I Napagold 22" Wiper Washer F	Parts: In Date:  t Bulk Oil Filter Blade luid Conce	12/02/2019 entr			19 <b>Qty</b> 7.00 1.00 2.00 1.00
- Shop Supplies  Workorder: 19 Problem: Pm - Pm service Replace aux. fu - Rotate and bala - Test drive Diagnose check Tightened gas cap	: 12316 In service, cl el tank filter Ince tires.	<b>Meter:</b> heck engir r and clear	ne light. n intake scree	n.	134.00  Parts List 5w20 Oil I Napagold 22" Wiper Washer F Napagold	Parts:  In Date:  t Bulk Oil Filter Blade luid Conce	12/02/2019 entr			19 7.00 1.00 2.00 1.00

Workorder: Problem:	2004432 A/C not		Meter:	72367			In Date:	05/04/2020	Closed:	05/13/2020
- A/c evap lea	aking. Sen	t to Al	Packer fo	or repair.		Parts Li	ist			Qty
- Test drive.						Shop Su	upplies			1.00
- Check engir Repaired by A	l Packer.	. Po45	5 dtc pre	sent. Clea	red dtc's.					
- Shop Suppli	les	Hours :	2.00		Labor:	146.00	Parts:	4.00	Total:	150.00
Workorder: Problem:	2004739 Transmis		Meter: roblems	72367			In Date:	05/11/2020	Closed:	05/11/2020
- Tow From: F	Pa shop	Γο: Al F	Packer							
	·	Hours :			Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	2004867 Repair b		Meter: acker	72367			In Date:	05/13/2020	Closed:	07/15/2020
- Repair a/c b	y Al Pack	er.								
		Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	2005920 transpor		Meter:	72976			In Date:	06/15/2020	Closed:	06/15/2020
- Tow From: A	Al Packer	To: Pa	a shop							
		Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	2006781 Aux fuel		Meter: not pump	73895 ping.			In Date:	07/13/2020	Closed:	07/16/2020
- Clean aux fu	uel pump	intake s	screen ar	nd replace	filter.	Parts Li	ist			Qty
- Pm service.						Element	t			1.00
- Replace wo	rn tires.					Used Fi	re X Refurbi	shed		1.00
- Test drive.						5w20 O	il Bulk			7.00
- Wash.						Napago	ld Oil Filter			1.00
- Shop Suppli	es					Washer	Fluid Conce	entr		1.00
						22" Wip	er Blade			2.00
						Lt245/75	5r17 Mich D	efend Ltx		4.00
						Shop Su	upplies			1.00
						Tire Dis	posal Fee			4.00
		Hours :	5.50		Labor:	401.50	Parts:	1,073.18	Total:	1,474.68
Workorder: Problem:	2007562 Flat tire.		Meter:	74353			In Date:	08/03/2020	Closed:	08/04/2020
- Repair Lf tire	е.					Parts Li	ist			Qty
- Shop Suppli						Shop Su				1.00
,		Hours :	1.00		Labor:		Parts:	4.00	Total:	77.00

Workorder: Problem:	2012159 Won't start	Meter:	77914			In Date:	12/07/2020	Closed:	12/08/20	020
- Test battery	, it failed. Insta	alled new b	attery.		Parts L	ist				Qty
- Shop Suppli	es				Battery					1.00
					Shop Si	upplies				1.00
	Hou	rs 1.00		Labor:	73.00	Parts:	147.81	Total:	220.81	
Workorder: Problem:	2012282 Aux fuel pum	<b>Meter:</b> p not work	77914 ing.			In Date:	12/10/2020	Closed:	12/15/20	020
- Replaced sh	norted fuse.									
	Hou	rs 0.50		Labor:	36.50	Parts:	0.00	Total:	36.50	
Workorder: Problem:	2012866 pm service	Meter:	77914			In Date:	12/28/2020	Closed:	01/11/20	021
- pm service.					Parts L	ist				Qty
- washer spra	y nozzle broke	en. Replace	ed nozzle		22" Wip	er Blade				2.00
- Test drive					Washer	Fluid Conc	entr			1.00
- Rotate and I	balance tires.				Napago	ld Oil Filter				1.00
- Shop Suppli	es				5w20 O	il Bulk				7.00
					Napago	ld Air Filter				1.00
					Mac Wit	te Lithium G	ires			1.00
					Washer	Jet				2.00
					Shop St	upplies				1.00
	Hou	rs 2.00		Labor:	146.00	Parts:	65.43	Total:	211.43	
Workorder: Problem:	2102326 nail/screw in	Meter: right rear ti	79904 re			In Date:	03/02/2021	Closed:	03/04/20	021
- Tire Repair	patch passeng	jer rear tire			Parts L	ist				Qty
- Shop Suppli	es				Shop Si	upplies				1.00
	Hou :	rs 1.00		Labor:	73.00	Parts:	4.00	Total:	77.00	
Workorder: Problem:	2104135 Transition Pro	Meter: ep Charge	80741			In Date:	04/13/2021	Closed:	04/13/20	021
- Transition P	rep Charge									

Labor: 146.00 Parts: 0.00

Total: 146.00

Hours 2.00