



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V274

In Date: 10/18/2005 Meter Reading: 21,889.00
 Close Date: 12/02/2005

Problem?
 AXE HOLDER IN COMPT. BEHIND DRIVER BROKEN, AL-1

Task performed:	Parts	Quantity
	NO PARTS USED	

Workorder: V288

In Date: 10/18/2005 Meter Reading:
 Close Date: 12/02/2005

Problem?
 NEED MOUNT FOR AL1

Task performed:	Parts	Quantity
	NO PARTS USED	

Workorder: V811

In Date: 12/05/2005 Meter Reading:
 Close Date: 01/06/2006

Problem?
 wig-wags inoperative AL1

Task performed:	Parts	Quantity
	PR20SCCCUSE 02-382477-00	1

Workorder: V1036

In Date: 12/27/2005 Meter Reading: 22,278.00
 Close Date: 01/11/2006

Problem?
 B inspection

Task performed:	Parts	Quantity
	24232FILTER CAP FOR 33518 NEW FILTER # 33818 W/CAF	1
	FA1710AIR FILTER 46728	1
	L4596FFUEL FILTER NEW # 33818	1
	PH3786WIX 51734 OIL FILTER LF-LFP2286	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V1635

In Date: 02/24/2006
Close Date: 04/03/2006

Meter Reading:

Problem?

REPLACE TIRES AL1

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1870

In Date: 03/16/2006
Close Date: 04/03/2006

Meter Reading:

Problem?

AL! won't start Sta 81

Task performed:

Parts

Quantity

353R023HURST HOSE W/O SWIVEL

2

65-72BXT65750 BATTERY

2

Workorder: V1987

In Date: 03/28/2006
Close Date: 04/03/2006

Meter Reading:

Problem?

HOSE ON HURST RAM BROKEN, AL-1

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2441

In Date: 05/01/2006
Close Date: 05/16/2006

Meter Reading:

Problem?

HURST TOOL HOSES WILL NOT CONNECT AL-1

Task performed:

Parts

Quantity

180R002HURST HYD. FLUID QT

2



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V3405

In Date: 07/11/2006

Meter Reading:

Close Date: 07/21/2006

Problem?

CHECK ENGINE LIGHT ON, AL-1

Task performed:

Parts	Quantity
TB510AX HOLDER ZA115101C	1

Workorder: V3559

In Date: 07/20/2006

Meter Reading:

Close Date: 07/28/2006

Problem?

B inspection AL1 at sta 81

Task performed:

Parts	Quantity
3157NAAMBER BULB	2
35200-RLIGHT MARKER LED RED	1
F65B13350AAFLASHER FORD 5C3Z13350AA	1
H27W12VMH27W12VM BULB	1
L4596FFUEL FILTER NEW # 33818	1
PH3786WIX 51734 OIL FILTER LF-LFP2286	1

Workorder: V3944

In Date: 08/15/2006

Meter Reading:

Close Date: 08/28/2006

Problem?

engine sounds like it running rough. Please check AL1

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V3444

In Date: 07/13/2006

Meter Reading:

Close Date: 09/06/2006

Problem?

replace hose bed cover at central auto trim

Task performed:

Parts	Quantity
NO PARTS USED	

Vendor?: CENT0002



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V4214

In Date: 09/01/2006
Close Date: 09/07/2006

Meter Reading: 25,434.00

Problem?

replace hose bed cover (outside agency-central auto trim)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: CENT0002

Workorder: V4385

In Date: 09/11/2006
Close Date: 09/26/2006

Meter Reading: 25,584.00

Problem?

service hurst power unit AL1

Task performed:

Parts

Quantity

1. SERVICE HURST TOOLS. CHANGE OIL, SPARK PLUG, AIR FILTER. INSPECT ALL TOOL HOSES. TIME ALL TOOLS ADD HURST OIL TO POWER UNIT.

NO PARTS USED

Workorder: V5147

In Date: 10/30/2006
Close Date: 11/07/2006

Meter Reading: 2,900.00

Problem?

al1 is leaking diesel fuel AL1

Task performed:

Parts

Quantity

1. diagnose fuel leak
2. remove gear locker
3. renew airport id badge

NO PARTS USED

Workorder: V5263

In Date: 11/06/2006
Close Date: 11/09/2006

Meter Reading: 25,584.00

Problem?

repair fuel leak at al packer PO FOR WARRANTY REPAIR AL1

Task performed:

Parts

Quantity

1. UNIT SENT TO AL PACKER FORD FOR FUEL LEAK REPAIR.

NO PARTS USED

Vendor?: AL PACKER FORD



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V5310

In Date: 11/08/2006
Close Date: 11/17/2006

Meter Reading: 25,584.00

Problem?

BATTERY CHARGER 10-7 AL-1

Task performed:

Parts

Quantity

1. repair on board battery charger
2. pick up vehical at ford dealer
3. pick up bc-8 from seeboks

NO PARTS USED

Workorder: V5862

In Date: 12/18/2006
Close Date: 12/21/2006

Meter Reading: 3,006.00

Problem?

Right rear marker light out. AL1

Task performed:

Parts

Quantity

1. replaced marker lens

NO PARTS USED

Workorder: V5921

In Date: 12/22/2006
Close Date: 12/29/2006

Meter Reading: 3,006.00

Problem?

REAR DOOR LATCH NEEDS ADJUSTMENT

Task performed:

Parts

Quantity

1. Disassemble latch assy.bend latcharm reassemble and adjust detent tension

NO PARTS USED

Workorder: V6384

In Date: 01/21/2007
Close Date: 01/29/2007

Meter Reading: 3,055.10

Problem?

power steering dip stick not registering fluid AL1

Task performed:

Parts

Quantity

1. FILL POWER STEERING RES TO FULL MARK . INSPECT PUMP HOSES STEERING BOX & HYDRO BOOST UNIT NO LEAKS FOUND.

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V6446

In Date: 01/24/2007 Meter Reading: 3,066.00
Close Date: 01/29/2007

Problem?

Lightbar on AL1 has a bulb out (far righthand side)

Task performed:

1. CHECK LIGHT BAR POWER SUPPLY-OK R/R 2
CORNER STROBE ASSYS.

Parts	Quantity
02036273300 TURBO94 CORNERLINEAR REFLECTOR	2

Workorder: V6680

In Date: 02/08/2007 Meter Reading: 27,413.00
Close Date: 02/21/2007

Problem?

several step lights innoperative (AL1)

Task performed:

1. check step lights. R & R 2 step light lenses, r&r bulbs

Parts	Quantity
NO PARTS USED	

Workorder: V6834

In Date: 02/20/2007 Meter Reading: 27,413.00
Close Date: 03/07/2007

Problem?

B inspection and related repairs AL1

Task performed:

- B Inspection
- R&R batteries and checked battery charger
- R&R fan belt and idler pulley
- R&R oil filler cap on engine
- Pick up vehicle at 81 and bring to shop. Replaced rear brakes
- R&R rear tires
- Meeting with tim after lunch

Parts	Quantity
65-72BXT65750 BATTERY	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2
F3AZ6766BOIL FILLER CAP	1
F81Z2001CAREAR PADS F550	1
F8TZ8678FAPULLY	1
FA1710AIR FILTER 46728	1
L4596FFUEL FILTER NEW # 33818	1
PH3786WIX 51734 OIL FILTER LF-LFP2286	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V6936

In Date: 02/26/2007 Meter Reading: 27,413.00
Close Date: 03/23/2007

Problem?

replace tires at shop callaghan ent

Task performed:

Parts

Quantity

Replaced tires at shop Callaghan Ent

NO PARTS USED

Vendor?: CALLAGHAN ENT

Workorder: V7247

In Date: 03/18/2007 Meter Reading: 3,124.10
Close Date: 04/18/2007

Problem?

AL1 BACK UP CAMERA FOR AL1 MALFUNCTION ON/OFF AL1

Task performed:

Parts

Quantity

Check video screen for camera dc input ok. Camera input intermittent. Problem is inside display connections

NO PARTS USED

Workorder: V8319

In Date: 05/17/2007 Meter Reading: 28,769.00
Close Date: 06/05/2007

Problem?

foreign material stuck between tandems AL1

Task performed:

Parts

Quantity

1. jack up vehicle. remove outer r/r wheel to remove chunk of concrete stuck btwn wheels.

NO PARTS USED

Workorder: V8161

In Date: 05/08/2007 Meter Reading: 28,654.00
Close Date: 06/07/2007

Problem?

WATER LEAK AL-1

Task performed:

Parts

Quantity

1. Driver reported O.D. light on shifter blinking. Road test veh & checked operation of O.D. light OK now, no problem found
2. Check all water level control rods - clean all, need tank to pump valve rebuild
3. R&R tank to pump valve & rebuild
4. Gated Y, ordered parts to rebuild

91398907 VALVE KIT 3 IN AKRON

1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V8218

In Date: 05/12/2007 Meter Reading: 3,221.50
Close Date: 06/07/2007

Problem?

when in pump gear, pump sound rough. AL-1

Task performed:

Parts

Quantity

1. Meet with Ed Orlando in AM, tell him my days itinerary. then drive to St 81 from C/S
2. Check pump, trans oil level & color, Check driveshafts, put the veh in pump and run at different pressures. No unusual noises heard

NO PARTS USED

Workorder: V8219

In Date: 05/12/2007 Meter Reading: 3,221.50
Close Date: 06/07/2007

Problem?

small speaker under diver side dash board broke off mount. I was unable to enter this under comm. shop. that is why i sent it to vehicle shop. AL-1

Task performed:

Parts

Quantity

1. Looked at speaker - mounting bracket broken & clicking noise coming from speaker even with power off - called radio shop about repairs

NO PARTS USED

Workorder: V8500

In Date: 05/30/2007 Meter Reading: 3,246.80
Close Date: 06/20/2007

Problem?

MOUNT HALLIGAN TOOL ON THIS VEHICLE a11

Task performed:

Parts

Quantity

1. Find good location for mounting of tool. drill & tap holes & install brackets for haligan tool

5269LPVM-5 SM MOUNT

2

Workorder: V8572

In Date: 06/04/2007 Meter Reading: 3,246.80
Close Date: 06/20/2007

Problem?

Right running board turn signal flasher inop.

Task performed:

Parts

Quantity

1. Check 12V & ground at light - OK needs new light assy. Drive to C/S get part return to sta 81 r/r light assy
2. Remove dipstick from tube order new one drive to c/s from sta 81 get part install new dipstick assy

35200-YLIGHT MARKER LEDAMBER

1

F81Z6750DADIP STICK

1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V9407

In Date: 07/18/2007
Close Date: 08/14/2007

Meter Reading: 29,528.00

Problem?

repair gated y al1

Task performed:

1. Rem gated "Y" ; install steamer cap; diss "Y"; cld not get seat retainers apart; ordered additional parts; reassemble & reinstalled on vehicle
2. (2) nailes in R/F tire; rem both; soap test - ok no leaks

Parts	Quantity
17303000ELKHART BALL 2 1/2	2
80671001SEAL KIT ELKHART	2

Workorder: V10205

In Date: 08/31/2007
Close Date: 09/26/2007

Meter Reading: 3,372.20

Problem?

AL1's cattle catcher is loose, and making noise when driving.

Task performed:

1. TRAVEL TO STA 81 FROM NEW CENTRAL SHOP.
2. DISASSEMBLE R/S CHROME ADD ON GRILLE AND LIGHT ASSEMBLY IN ORDER TO TIGHTEN BOLTS IN CROSS BAR. REASSEMBLE R/S CORNER AND LIGHT ASSEMBLY.
3. REPAIR LOOSE BACK UP CAMERA MONITOR IN CAB.

Parts	Quantity
NO PARTS USED	

Workorder: V10385

In Date: 09/11/2007
Close Date: 09/26/2007

Meter Reading: 30,028.00

Problem?

gated wye leaking-needs rebuilt

Task performed:

1. meeting at CS
2. Get parts & travel to Stn81 from CS
3. Rem gated "Y" from veh; overhaul both 2" valves on "Y"

Parts	Quantity
57273001LOCK RING ELKHART	2
58886001SEAT ELKHART	2



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V10482

In Date: 09/17/2007 Meter Reading: 3,372.20
Close Date: 09/27/2007

Problem?

rr lower clearance light is not working. al1

Task performed:

1. Get parts; drive to St81 from CS
2. R/R R/S rear marker lighte
3. meeting w/Tim Calhoun & Chuck about airport veh mntce bay at County Shop Facility

Parts	Quantity
35200-RLIGHT MARKER LED RED	1

Workorder: V10455

In Date: 09/14/2007 Meter Reading: 30,028.00
Close Date: 10/02/2007

Problem?

B inspection and related repairs (AL1)

Task performed:

1. GET PARTS AND TRAVEL TO STATION 81 FROM CENTRAL SHOP
2. "B" INSPECTION
3. R/R 2 MARKER LIGHTS ON TOP REAR, BODY EXTENSSSIONS RIGHT AND LEFT SIDE
4. R/R LENS, R/R BULB IN TAG LIGHT
5. TIGHTEN ALL BOLTS ON RIGHT AND LEFT SIDE REAR STEPS UP TO HOSE BED
6. TIGHTEN ALL DRIVE SHAFT FLANGE BOLTS
7. R/R BACKUP CAMERA MONITORIN CAB, ADJUST AND TIGHTEN MOUNT ASSEMBLY UNTIL CORRECT AND STABLE
8. DRIVE VEHICLE TO CALLAGHAN TIRE FOR THEM TO MOUNT AND BALANCE 2 NEW FRONT TIRES. RETURN TO STATION 81

Parts	Quantity
35200-RLIGHT MARKER LED RED	2
L4596FFUEL FILTER NEW # 33818	1
PH3786WIX 51734 OIL FILTER LF-LFP2286	1

Workorder: V10677

In Date: 09/26/2007 Meter Reading: 30,028.00
Close Date: 10/23/2007

Problem?

replace 2 tires AL1 sta 81 (outside agency-callaghan tire)

Task performed:

Replace (2) tires - Callaghan

Parts	Quantity
NO PARTS USED	

Vendor?: CALLAGHAN



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V11312

In Date: 10/29/2007 Meter Reading: 30,416.00
Close Date: 11/07/2007

Problem?

foam metering valve stuck AL1

Task performed:

Parts

Quantity

1. Used wrench to free up valve; valve needs to be rem/overhauled
2. Get parts/travel to St81 from C/S
3. R/R/ L/S pump panel; R/R/ foam metering valve; diss/cln all parts; lube/reassemble

NO PARTS USED

Workorder: V11376

In Date: 11/01/2007 Meter Reading: 3,416.90
Close Date: 11/15/2007

Problem?

Overdrive on/off light flashes on/off at start up. Not normal operation. STA 81

Task performed:

Parts

Quantity

1. R+R all electrical connections on Trans. and Transfer case, Inspect all terminals. Road test Veh. shifts through all gears.
2. Renew airport ID badge at terminal. Need additional ID will bring Monday.
3. Go to airport terminal badge office, supply Soc. Sec. card for them

NO PARTS USED

Workorder: V11642

In Date: 11/16/2007 Meter Reading: 34,532.00
Close Date: 11/26/2007

Problem?

left side battery has no access & need servicing because right side battery with access was low. ALI1

Task performed:

Parts

Quantity

1. Get parts/travel to St81 from C/S (batteries)
2. Get parts/travel to St81 from C/S(new onboard charger assy)
3. R/R both btrys; both very low on water; (1) btry test bad
4. Test onboard charger assy-seems ok; R/R display panel on rear of veh; rep connector at display panel

091-39-INDAUTO CHARGER INDICATOR

1

65-72BXT65750 BATTERY

2

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY

2



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V11750

In Date: 11/26/2007
Close Date: 12/04/2007

Meter Reading: 3,471.10

Problem?

warning light on dash continuously illuminated. a1

Task performed:

1. Check operation of glow plug system checks all wires on glow plug and control solenoids all OK. worker OK for me.

Parts

NO PARTS USED

Quantity

Workorder: V13836

In Date: 03/12/2008
Close Date: 04/02/2008

Meter Reading: 31,767.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED AL1

Task performed:

1. Travel to St 81 from C/S and return following maintenance
2. "B" inspection
3. Service transfer case

Parts

15W40BSYN OIL BULK QTS
FA1710AIR FILTER 46728
L4596FFUEL FILTER NEW # 33818
PH3786WIX 51734 OIL FILTER LF-LFP2286

Quantity

16
1
1
1

Workorder: V14136

In Date: 03/27/2008
Close Date: 04/18/2008

Meter Reading: 32,057.00

Problem?

replace tires at shop callaghan

Task performed:

Replace tires at shop - Callghan j

Parts

NO PARTS USED

Quantity

Vendor?: CALLGHAN

Workorder: V14276

In Date: 04/03/2008
Close Date: 06/17/2008

Meter Reading: 3,665.20

Problem?

AL1 LEFT REAR PLUG WAS DISCOVERED TO BE SMOKING APPROX: AT 21:45, IT WAS UNPLUGGED. THERE IS AN ELECTRICAL ODOR PRESENT. THE VEHICLE IS ABLE TO START. a1

Task performed:

1. r/r access panel at l/r comp. inspect plug on shore line =bad plug. r/r 110 plug on shoreline test operation and reinstall panel.

Parts

5-20PH1PGK4 CONNECTOR 120V 20A FEMALE

Quantity

2



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V16499

In Date: 07/21/2008
Close Date: 08/04/2008

Meter Reading: 33,219.00

Problem?

install seat cover al1

Task performed:

- 1. Install seat covers.
 - 2. Cln mechanics bay at Stn81; empty waste oil container; crush/dispose of all filters; refill oil containers.
- j

Parts

NO PARTS USED

Quantity

Workorder: V16640

In Date: 07/28/2008
Close Date: 08/04/2008

Meter Reading: 3,796.30

Problem?

Assist with pump test RP-81

Task performed:

Assist with pump test on AL-1. j

Parts

NO PARTS USED

Quantity

Workorder: V16743

In Date: 07/31/2008
Close Date: 08/04/2008

Meter Reading: 3,796.30

Problem?

Several lights out on light bar. STA-81

Task performed:

- Diss light bar to diagnose; drive to CS to get parts; R/R P/C matric board inside light bar; R/R (1) front strobe; R/R/ (1) corner strobe; rep wiring to center stinger lights.
- j

Parts

01026814300BOARD 94 EDGE MATRIX 1
 02036273300 TURBO94 CORNERLINEAR REFLECTOR 1
 7ELTUBE7ELTUBE LINEAR STROBE REF 1

Quantity

Workorder: V17296

In Date: 08/25/2008
Close Date: 09/02/2008

Meter Reading: 3,822.70

Problem?

hose on hurst power unit is leaking AL1

Task performed:

r/r a leaking hurst hose.

Parts

3530033USE 353R222 HOSE HURST SWIVEL/ORING

Quantity

2



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V17164

In Date: 08/20/2008

Meter Reading: 3,822.70

Close Date: 09/08/2008

Problem?

PA / siren system out. AL1

Task performed:

Parts

Quantity

diagnose why siren and pa do not work. r/r connection at plug in rear of siren head. r/r console top to access siren.

NO PARTS USED

Workorder: V17927

In Date: 09/24/2008

Meter Reading: 3,852.20

Close Date: 09/25/2008

Problem?

TOWER COMPLAINED OF NOISE AND STATIC OF VHF COM RADIO

Task performed:

Parts

Quantity

CONTACTED STEVEN LEE IN RADIO SHOP 9/25

NO PARTS USED

Workorder: V17468

In Date: 09/02/2008

Meter Reading: 3,837.60

Close Date: 09/30/2008

Problem?

R battery 3rd cell plates visible-needs water & 2nd battery should be checked. 2nd battery not accessible. al1

Task performed:

Parts

Quantity

1. added water to battery-cell smoking-test battery (N/G). Go to shop to get (2) new batteries. R & R batteries (2) clean connections. Test charging system.
2. Diagnose on board charger to see if its overcgarging batteries, checked wiring, connections.
3. Deliver Hurricane supplies to St-81 for hurricane Ike.

0913912CHARGER 2000

1

65-72BXT65750 BATTERY

2

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

2

(R.T.)



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V17491

In Date: 09/03/2008

Meter Reading: 33,558.00

Close Date: 09/30/2008

Problem?

B inspection and related repairs AL-1

Task performed:

- B-Inspection
- 2. R/R coolant hoses; drain coolant; R/R T-state & gasket; R/R water pump inlet fitting incorrect; R/R gasket.
- 3. R/R fan belt
- 4. Washout coolant reservoir tank stained from original coolant.
- 5. R/R wipereblades.
- 6. Drain fuel filter housing; R/R fule heater; drdy & clean out all debris & carbon like material; fill hsneg with fuel; install filter & cover.
- 7. R/R relief valve strainer from pump panel control; cln strainer.
- 8. Rem stinger Lt asy frm center of light bar; R/S bulb had broken con nector; no new conn term in stock; rem old wire & solder wire out to term; reinstall & test ok.

Parts	Quantity
11305-1THERMOSTAT GASKET F550 AIRPORT	1
14269THERMOSTAT 02 F550 AIRPORT	1
1C3Z8286CARADIATOR HOSE	1
91-20WIPER BLADE 20 IN	2
CYBS15165011USE UMVS111611 STRAP	2
CYBS18206011STRAP	1
F81A-8C351-ADCOOLANT FILTER F550 AIRPORT	1
F81A-8W005-ABCOOLANT HOSE F550 AIRPORT	1
F81Z18472MAALOWER HEATER HOSE	1
F81Z8255AAGASKET INLET PIPE	1
F81Z8260CAHOSE ASY	1
F8TZ8620GCBELT	1
L4596FFUEL FILTER NEW # 33818	1
PH3786WIX 51734 OIL FILTER LF-LFP2286	1
YC3Z18472GAHEATER HOSE UPPER	1

Workorder: V17813

In Date: 09/19/2008

Meter Reading: 3,852.20

Close Date: 09/30/2008

Problem?

shoreline ejector not working MINI-PUMPER

Task performed:

- Dia problem; needs new auto-eject; non i stock at airport; drive to C/S to get new part; return to stn81; R/R super auto-eject & test. j

Parts	Quantity
0915520120AUTO EJECT 20 AERO OTL3925	1

Workorder: V18570

In Date: 10/24/2008

Meter Reading: 3,870.90

Close Date: 11/03/2008

Problem?

shore line system : light not functioning rp81

Task performed:

- 1. travel to St81 from C/S; travel to C/S from St81.
- 2. Dia whether or not 110V or btry charger or function display bad; R/R display panel. j

Parts	Quantity
032-0116549297 BATTERY INDICATOR	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V19177

In Date: 11/19/2008
Close Date: 11/19/2008

Meter Reading: 3,914.50

Problem?

computer system would not let me enter under comm. Please pass on feedback on ground radio.

Task performed:

CONTACTED STEVEN LEE 11/19/08

Parts

NO PARTS USED

Quantity

Workorder: V19114

In Date: 11/17/2008
Close Date: 12/02/2008

Meter Reading: 3,914.50

Problem?

repair tag light

Task performed:

R/R lens & bulb. j

Parts

NO PARTS USED

Quantity

Workorder: V19176

In Date: 11/19/2008
Close Date: 12/02/2008

Meter Reading: 3,914.50

Problem?

engine light came on. AL1

Task performed:

1. Travel to Stn81 from C/S; to C/S from Stn81.
2. Hookup eng code scanner; says "O" codes stored in computer; chid all fluids under hood. j

Parts

NO PARTS USED

Quantity

Workorder: V19265

In Date: 11/21/2008
Close Date: 12/02/2008

Meter Reading: 3,914.50

Problem?

SMALL DENT CAUSED BY HYPEREXTENSION OF DOOR ON FRONT SIDE OF DOOR.AL1

Task performed:

Sebok put Bondo on dent area of door instead of straightening metal; Bondo fell off; needs body work to repair. j

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V19734

In Date: 12/14/2008
Close Date: 12/31/2008

Meter Reading: 3,947.60

Problem?

fuelled truck very slowly-fuel overflowed a little. gauge is still registering 1/4 low. used brakes to try to get gauge to register & it did not work. RP-81

Task performed:

Chkd fuel gauge; reads full; NPF. j

Parts

Quantity

NO PARTS USED

Workorder: V20333

In Date: 01/13/2009
Close Date: 01/26/2009

Meter Reading: 34,783.50

Problem?

bent handle on hurst cutters (AL1)

Task performed:

1- Spare cutters issued to sta 81 form shop, has handle falling off 2 screw missing and other loose. Match thread install 2 new screws tighten others.

Parts

Quantity

NO PARTS USED

Workorder: V20339

In Date: 01/13/2009
Close Date: 01/26/2009

Meter Reading: 3,971.40

Problem?

HANDLES ON SHEARS FOR HURST TOOL ARE BENT. AL1

Task performed:

1- Travel to st 81 from c/s and travel to c/s from 81
2- R&R handle assy on hurst cutter toll. took handle off old spared cutter because none in stock.

Parts

Quantity

NO PARTS USED

Workorder: V20055

In Date: 12/31/2008
Close Date: 02/06/2009

Meter Reading: 3,967.00

Problem?

Light bar - center right rotating white beacon out.

Task performed:

1. R/R center stinger light asy from light bar; rep brkn wire at light bulb; needs new wire term; special kind; will order.
2. Get model/serial numbers off light bar for Woodland to order parts. j

Parts

Quantity

H27W12VMH27W12VM BULB

1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V20412

In Date: 01/16/2009
Close Date: 02/06/2009

Meter Reading: 34,906.00

Problem?

fuel leak AL1

Task performed:

1. Find source of leak; drive to C/S for parts & return to St81; R/R fuel filter, cover & gasket asy; cln eng valley of accumulated fuel; cln bay floor of fuel.
2. Fnd 2nd leak; R/R fuel filter hsng water drain valve asy.

Parts	Quantity
L4596FFUEL FILTER NEW # 33818	1

Workorder: V20613

In Date: 01/26/2009
Close Date: 02/06/2009

Meter Reading: 34,906.00

Problem?

replace water pump al1

Task performed:

1. R/R water pump drain & refill cooling sys; get new part at C/S.
2. Travel to St81 from C/S; travel to C/S from St81.
3. R/R T-stat hsng & ring seal; leaked after doing water pump; drain/refill cooling sys in order to do above job.
4. Empty waste on container crush oil filters & cln mech bay at St81. j

Parts	Quantity
F4TZ8255AGASKET	2
F81Z-8501-FAWATER PUMP	1
F81Z8592AACONNECTION WATER	1

Workorder: V20709

In Date: 01/30/2009
Close Date: 02/25/2009

Meter Reading: 3,995.00

Problem?

Headlight selector knob broken. al1

Task performed:

- Inspect part; ordered part; PU part from Woodland; install part. j

Parts	Quantity
3L3Z11661AAKNOB HEADLIGHT	1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V20769

In Date: 02/01/2009 Meter Reading: 3,995.00
Close Date: 02/25/2009

Problem?

power steering fluid low on AL1

Task performed:

Add small amt of correct P/S fluid to full mark. j

Parts

Quantity

NO PARTS USED

Workorder: V19343

In Date: 11/25/2008 Meter Reading: 3,929.10
Close Date: 03/02/2009

Problem?

REPLACE FRONT TIRES AL1

Task performed:

Replace front tires - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLGHAN

Workorder: V21654

In Date: 03/09/2009 Meter Reading: 4,039.20
Close Date: 03/25/2009

Problem?

Ken, Please confirm tire pressure for the AL1 truck.

Task performed:

Chk air in all (6) tires; adj to correct pressure. j

Parts

Quantity

NO PARTS USED

Workorder: V21887

In Date: 03/17/2009 Meter Reading: 35,251.00
Close Date: 04/07/2009

Problem?

pump test with crew AL-1

Task performed:

1. Travel to Stn81 from C/S; travel to C/S from Stn81.
2. Set up veh at test site & perform annual pump test.

j

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V22197

In Date: 03/30/2009
Close Date: 04/20/2009

Meter Reading: 4,072.70

Problem?

FAILED VAC TEST WHEN PUMP TESTED sup 81

Task performed:

1. Test pump, plumbing & valves under vac & under press to find leaks.
 2. Rem primer valve from veh; overhaul valve & reinstall.
- j

Parts

Quantity

PVG-KITORING KIT

1

Workorder: V22198

In Date: 03/30/2009
Close Date: 04/23/2009

Meter Reading: 4,072.70

Problem?

FAN CLUTCH MAKING NOISE PLEASE CHECK sup 81

Task performed:

1. Rem fan belt; ck fan clutch, belt tensioner & (3) idler pulleys; record vin # to order parts.
 2. R/R fan belt in order to R/R (2) idler pulley asys & (1) belt. tensioner.
- j

Parts

Quantity

F8TZ8678FAPULLY

2

F8UZ6B209CATENSONER

1

Workorder: V22327

In Date: 04/05/2009
Close Date: 04/23/2009

Meter Reading: 4,085.00

Problem?

PUMP PRIMER IS NOT WORKING. AL1

Task performed:

1. R/R primer pump asy on veh.
 2. Escort tech from paint shop into, then out of airport for color match pictures on DR-1 & DR-5.
- j

Parts

Quantity

501-3090-00PRIMER PUMP MOTOR

1

Workorder: V24083

In Date: 06/15/2009
Close Date: 06/18/2009

Meter Reading: 4,160.80

Problem?

oil leaking from near engine rear seal. puddle of oil under truck & quart of oil added back into engine. check history-ford recall. AL1

Task performed:

1. Travel to Stn81 from C/S.
 2. Chk for svc of oil leak; solenoid at inj pump leaking; was just at Al Packer Ford for this same complaint; return veh to Al Packer for rep.
- j

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V23761

In Date: 06/02/2009
Close Date: 06/20/2009

Meter Reading: 36,207.00

Problem?

C INSPECTION AND REPAIRS AS NEEDED AL1

Task performed:

- Perform C-Service.
- 2. Replcd strobe light in roof light bar.
- 3. Replcd left/right flag stickers.
- 4. Replcd wiper blades.
- 5. Replcd eng air filter.
- 6. Cln shop after PM. j

Parts	Quantity
02034036200CLIGHT ASSY STROBE	1
15W40BSYN OIL BULK QTS	8
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
87401RY-30T RELAY 5 PIN 12V	1
91-20WIPER BLADE 20 IN	2
FA1710AIR FILTER 46728	1
L4596FFUEL FILTER NEW # 33818	1
PH3786WIX 51734 OIL FILTER LF-LFP2286	1

Workorder: V23838

In Date: 06/04/2009
Close Date: 06/24/2009

Meter Reading: 36,207.00

Problem?

REPAIR OIL LEAK AL1

Task performed:

- Bad oil leak; told to take it to Ford; they would repair it. j

Parts	Quantity
NO PARTS USED	

Workorder: V24141

In Date: 06/16/2009
Close Date: 06/24/2009

Meter Reading: 4,160.80

Problem?

When starting cold engine. The engine is running rough and wanting to stall. Engine stalled several times. When you push on gas pedal the engine will not increase rpm's. If the engine is warm there is not a problem. al1

Task performed:

- REPAIRED BY AL PACKER

Parts	Quantity
NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V23954

In Date: 06/09/2009 Meter Reading: 36,207.00
Close Date: 07/08/2009

Problem?

replace high pressure oil pump al apacker

Task performed:

Parts

Quantity

Replace high pressure oil pump - Al Packer j

NO PARTS USED

Vendor?: AL PACKER FORD

Workorder: V23762

In Date: 06/02/2009 Meter Reading: 36,207.00
Close Date: 07/09/2009

Problem?

replace rear tires at shop callaghan

Task performed:

Parts

Quantity

Replace rear tires at shop - Callghan j

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V25095

In Date: 07/27/2009 Meter Reading: 36,737.00
Close Date: 08/03/2009

Problem?

error code on master discharge guage AL-1

Task performed:

Parts

Quantity

1. Travel to Stn81 from C/S; travel to C/S from Stn81.
2. Dia error code (E-6)on FRC master pressure gauge; R/R intake pressure transducer.

I03100PT-2XE-IO3100PT3-S0B 600 TRANSDUCER INT

1

j

Workorder: V24683

In Date: 07/10/2009 Meter Reading: 4,160.80
Close Date: 08/05/2009

Problem?

12 volt in dash accessory plug INOP. AL1

Task performed:

Parts

Quantity

Test 12V ACC outlet; R/R dash panel; R/R fuse. j

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V25648

In Date: 08/19/2009
Close Date: 08/26/2009

Meter Reading: 4,197.90

Problem?

One battery showing not charging when plugged in. al1

Task performed:

One btry not showing a charge on shoreline indicator;
(1) btry bad; replc btrys; shoreline is charging - cld not
find draw w/ charger; chkd fuses & tightened grnds. j

Parts	Quantity
65-72BXT65750 BATTERY	2
BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY	2

Workorder: V25826

In Date: 08/27/2009
Close Date: 09/02/2009

Meter Reading: 4,197.90

Problem?

NOISE IN FRONT END ON DRIVERS SIDE PLEASE CHECK TO DETERMINE THE CAUSE AND REPAIR

Task performed:

1. Road test veh; chk all front end parts; stabilizer bad; links defective; will order.
 2. Travel to Stn81 frm C/S; travel to C/S frm Stn81.
 3. R/R (2) front sway bar stabilizer links.
 4. Rem old velcro; cln surface, attach new velcro.
- j

Parts	Quantity
1C3Z5K483BBSTABILIZER BAR	1
C3Z5K483BALINK	1

Workorder: V25825

In Date: 08/27/2009
Close Date: 09/11/2009

Meter Reading: 4,197.90

Problem?

BACK-UP MONITOR NEEDS REPLACED MONITOR SHUTS DOWN ON ITS OWN

Task performed:

Rem monitor; chk 12V & grnd connections; chk video input connectors; ____ video input on o=monitor bad; needs new monitor. j

Parts	Quantity
NO PARTS USED	

Workorder: V25345

In Date: 08/06/2009
Close Date: 09/14/2009

Meter Reading: 36,737.00

Problem?

repair engine (outside agency-al packer ford)

Task performed:

Repair engin - Al Packer Ford j

Parts	Quantity
NO PARTS USED	

Vendor?: AL PACKER



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V26652

In Date: 10/03/2009
Close Date: 10/27/2009

Meter Reading: 4,227.00

Problem?

Headlight High Beams would go off intermittently when driving. Low beams are operational. AL1

Task performed:

1. Travel to Stn81 from C/S; travel to C/S from Stn81.
2. Chk wiring, connectors at hdlight sw & multifunction sw on steering column; no hot or burnt wires on connections; fuses look good; ran veh lights for (1) hour; lights never went off - NPF; told driver to use veh at night & let me know.
3. Travel to Stn81 from C/S; travel to C/S from Stn81.
4. Rem gear frm compt R-1; rem elect panel access cover; chk all connections & brkrs; R/R ckt brkr at wigwag control; test lights for long time - ok; reassemble all. j

Parts

Quantity

54-51554-515 CIRCUIT BREAKER

1

Workorder: V27635

In Date: 11/13/2009
Close Date: 11/23/2009

Meter Reading: 38,538.50

Problem?

dash strobe innop

Task performed:

1. Dash strobe innop; fuse blown; replcd fuse; tested ok. j

Parts

Quantity

NO PARTS USED

Workorder: V28591

In Date: 12/26/2009
Close Date: 01/06/2010

Meter Reading: 4,358.60

Problem?

slight smell of burning oil, dipstick in crankcase reads low Sta81

Task performed:

1. Add oil until full; chk for leaks; cln L/S of eng near oil filter, oil senders & oil cooler; run veh to chk for leaks; none fnd; will rechk in few days.
2. Travel to Stn81 from C/S; travel to C/S frm Stn81.
3. Travel to Callaghan tires from Stn81; pu ESC1 tires & align; return to Stn81 frm Callaghan. j

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V28604

In Date: 12/28/2009
Close Date: 01/06/2010

Meter Reading: 4,358.60

Problem?

Foam system is not working properly, metering valve needs a wrench to be turned.sta81

Task performed:

Parts

Quantity

Rem manual metering valve frm pump panel; diss, cin;lube valve asy; reinstall. j

NO PARTS USED

Workorder: V28606

In Date: 12/28/2009
Close Date: 01/06/2010

Meter Reading: 4,358.60

Problem?

possibly burning oil, level is low again after filling. esc 1

Task performed:

Parts

Quantity

See W/O 28591. j

NO PARTS USED

Workorder: V28324

In Date: 12/14/2009
Close Date: 01/20/2010

Meter Reading: 4,310.00

Problem?

Vehicle needs 2 new front tires R81 (outside agency-callaghan tire)

Task performed:

Parts

Quantity

Vehicle needs (2) new front tires R81 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V28371

In Date: 12/15/2009
Close Date: 01/20/2010

Meter Reading: 4,310.00

Problem?

alignment R81 (outside agency-callaghan tire)

Task performed:

Parts

Quantity

Alignment R81 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V29410

In Date: 01/25/2010
Close Date: 02/11/2010

Meter Reading: 4,412.80

Problem?

Wheel is missing a lug nut. esc 1

Task performed:

Drive to Stn81 frm shop; mov veh to mech bay; jackup veh install msng lugnut & chkd/tighten all lugnuts on both frnt wheels.
j

Parts

Quantity

F81Z1012AALUG NUT FORD F350

1

Workorder: V29370

In Date: 01/22/2010
Close Date: 03/02/2010

Meter Reading: 4,412.80

Problem?

Rear bumper driver side emergency red light has a short RP81

Task performed:

R/R light asty - rep wiring.
j

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V30033

In Date: 02/17/2010
Close Date: 03/10/2010

Meter Reading: 41,197.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED ESC 1

Task performed:

- B-Inspection
- 2. Svc L/WD T-cas; oil, change, etc.
- 3. Svc pump trans - oil change, etc.
- 4. Svc rear axle asy; change oil.
- 5. Svc frt axle asy; pan style; R/R pan, scrape sealant/cln surfaces; install new sealer & let dry; refill w/oil.
- 6. R/R (2) btrys.
- 7. R/R primer motor & pump asy.
- 8. R/R lens/bulb in compt lite R-3.
- 9. R/R lens & bulb in R/S upper rear warning lite.
- 10. R/R end cap/lens in order to R/R L/S strobe asy in cab roof light bar.
- 11. R/R center stinger asy on cab roof light bar; diss motor/gear section; R/R bulb.
- 12. R/R center console top; R/R bulb sckt frm guage; R/R bulb.
- 13. Can't put tire gauge onto rear dual wheels; try assorted lengths of valve extensions til correct fit; add air to proper press to all tires.
- 14. Eng oil leak; dia source of leak; bad eng oil cooler asy; will send to Ford for repairs. j

Parts

Quantity

1156BULB	1
15W40BSYN OIL BULK QTS	12
501-3090-00PRIMER PUMP MOTOR	1
600-802600-802 BULB TAG LIGHT	1
65-72BXT65750 BATTERY	2
7ELTUBE7ELTUBE LINEAR STROBE REF	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2
H27W12VH27W12V BULB	1
H50SN12BULB	1
L4596FFUEL FILTER NEW # 33818	1
PH3786WIX 51734 OIL FILTER LF-LFP2286	1

Workorder: V30135

In Date: 02/22/2010
Close Date: 03/18/2010

Meter Reading: 41,197.00

Problem?

repair backup camera ESC 1

Task performed:

R/R backup camera monitor in cab; diss/rep swivel mnt & solid mnt section. j

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V30254

In Date: 02/25/2010 Meter Reading: 41,283.30
Close Date: 03/19/2010

Problem?

tow to al packer from Vista (outside agency-sister's towing)

Task performed:

Tow to Al Packer from Vista - Sisters Towing j

Parts

NO PARTS USED

Quantity

Vendor?: SISTERS TOWING

Workorder: V28605

In Date: 12/28/2009 Meter Reading: 4,358.60
Close Date: 03/22/2010

Problem?

brakes are squeaking badly esc1

Task performed:

1. Inspect all brake pads; needs front.
2. Chk frnt end ball joints for play before wheel alignment.
3. R/R frnt disc brake pads. j

Parts

BR1269FRONT BRAKE PADS F550 K11078

Quantity

1

Workorder: V27608

In Date: 11/12/2009 Meter Reading: 4,290.80
Close Date: 04/14/2010

Problem?

Pressure gauge on discharge #1 not working. al 1

Task performed:

Dia why #1 discharge gauge not working; electronic gauges; test gauge/wiring; R/R trainsducer; test now ok. j

Parts

I03100PT-2XE-IO3100PT3-S0B 600 TRANSDUCER INT

UMVS111611STRAP

Quantity

1

2

Workorder: V31105

In Date: 03/29/2010 Meter Reading: 41,411.80
Close Date: 04/20/2010

Problem?

left outside rear tire flat Sta81

Task performed:

Called Boulevard Tire for repair. j

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V30255

In Date: 02/25/2010
Close Date: 04/22/2010

Meter Reading: 41,283.30

Problem?

repair engine oil leak (outside agency-al packer ford)

Task performed:

Repair engine oil leak - Al packer j

Parts

NO PARTS USED

Quantity

Vendor?: AL PACKER FORD

Workorder: V31102

In Date: 03/28/2010
Close Date: 04/22/2010

Meter Reading: 41,411.80

Problem?

left outside rear tire flat Sta81

Task performed:

Left outside rear tire flat Stn81 - Boulevard j

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD

Workorder: V31327

In Date: 04/07/2010
Close Date: 04/27/2010

Meter Reading: 42,251.90

Problem?

Battery #1 shows low charge. ESC 1

Task performed:

C/O - fnd only one of the btry level gauges on hookup for both btrys; Boike said that is normal. j

Parts

NO PARTS USED

Quantity

Workorder: V31494

In Date: 04/13/2010
Close Date: 05/07/2010

Meter Reading: 42,251.90

Problem?

Vehicle shut down while doing annual pump test. Will not start back up. ESC 1

Task performed:

1. Annual pump test; *veh shut down midway thru test; call towing svc.
2. Assist Sisters Towing to get veh on wrecker at test site.
3. Finish annual pump test.
4. Rep vac leak at fitting end of 4" suction hose used for pump testing & drafting. j j

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V31496

In Date: 04/13/2010 Meter Reading: 42,251.90
Close Date: 05/12/2010

Problem?

TOW UNIT FROM AIRPORT TO AL PACKER

Task performed:

Tow unit from airport to Al Packer - Sisters j

Parts

NO PARTS USED

Quantity

Vendor?: SISTERS TOWING

Workorder: V31905

In Date: 05/01/2010 Meter Reading: 42,738.70
Close Date: 05/21/2010

Problem?

BACK UP MONITOR SCREEN BROKEN. Station 81.

Task performed:

1. Cnhk all connections monitor; haspower; needs new monitor.
2. Rem camera montiro; mntng brkts, cable & wiring; travel to stn81 frm veh that is going to surplus (van).
3. Rem camera monitor cables, controller, etc. frm veh; route new cable, mnt camera, monitor, controller & wire u0p sys; fab a new monitor brkt, etc.
4. See above - continued install.
5. Finish installation of camera & monitor sys. j

Parts

NO PARTS USED

Quantity

Workorder: V32099

In Date: 05/10/2010 Meter Reading: 42,993.00
Close Date: 05/21/2010

Problem?

A.C. BLOWER MOTOR MAKING NOISE RP81

Task performed:

1. Dia noise with A/C on; ordered partr.
2. Rem blower motor asy; fnd fan defective; ordered fan; went to central shop to get fan (said dlvry after lunch - part never showed up).
3. Get part, went to St81; isntalled blower motor & fan. j

Parts

2C3Z19834AABLOWER WHEEL
XC3Z19805CABLOWER MOTOR

Quantity

1
1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V32423

In Date: 05/25/2010
Close Date: 06/08/2010

Meter Reading: 43,248.50

Problem?

Mount new halatron extinguisher in vehicle ESC1

Task performed:

Find suitable lcn; drill/tap; mnt ext. j

Parts

Quantity

NO PARTS USED

Workorder: V32480

In Date: 05/27/2010
Close Date: 06/11/2010

Meter Reading: 41,411.80

Problem?

replace 3 rear tires (outside agency-Boulevard tire) Sta81

Task performed:

Replace (3) rear tires - Boulevard Tire Stn81 j

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE

Workorder: V32597

In Date: 06/02/2010
Close Date: 06/18/2010

Meter Reading: 43,388.00

Problem?

LOW OIL esc 1

Task performed:

Added (2) qts oil to eng. j

Parts

Quantity

NO PARTS USED

Workorder: V32787

In Date: 06/10/2010
Close Date: 06/18/2010

Meter Reading: 43,532.00

Problem?

repair light sec1

Task performed:

Get parts; travel to Stn81 from C/S install glove box switch & light asy. j

Parts

Quantity

E7DZ14413ASWITCH ASSY

1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V33177

In Date: 06/27/2010
Close Date: 07/20/2010

Meter Reading: 44,019.50

Problem?

Front end on mini pumper vibrates when speeds reach 35-40 ESC 1

Task performed:

Travel to Stn81 frm C/S; chk lugnuts, ball joints, frnt steering for play; adj steering box; road test; R/S spring perch crckd; needs welding; wheels have internal balance that may not have worked; travel back to C/S frm Stn81. j

Parts

NO PARTS USED

Quantity

Workorder: V33978

In Date: 08/02/2010
Close Date: 08/03/2010

Meter Reading: 44,836.00

Problem?

repair engine esc1 (outside agency-AI packer ford)

Task performed:

Repair engine ESC1 - AI Packer ja

Parts

NO PARTS USED

Quantity

Vendor?: AL PACKER FORD

Workorder: V33605

In Date: 07/18/2010
Close Date: 08/11/2010

Meter Reading: 44,556.60

Problem?

wig wag lights INOP. ESC1

Task performed:

1. R/R stinger lgyt asy frm center of light bar for dia; needs new rotator asy; travel to C/S for parts & back to Stn81; install new stinger light asy & test.
2. R/R hurst hoses on cutter tool & test; fill power uinit with oil until full. ja

Parts

02038247700OBSOLETE OCSILLATER PIERCER ALERT
353R023HURST HOSE W/O SWIVEL

1
2

Workorder: V33665

In Date: 07/20/2010
Close Date: 08/11/2010

Meter Reading: 44,556.60

Problem?

hose broken on cutters on hurst tool ESC1

Task performed:

Already rep; see W/O 33605 ja

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V33715

In Date: 07/21/2010
Close Date: 08/11/2010

Meter Reading: 44,648.00

Problem?

Engine light comes on intermediately. esc1

Task performed:

1. Travel to Stn81 frm CV/S; put code scanner on veh; road test veh until light came on; read codes again; no codes??
2. Travel to Stn81 frm C/S; chk wiring to O.D. switch on shift lever on steering column; chk parking brake switch/wiring; road test veh; chk eng wiring harness & connectors.
3. Continue dia of veh not running right; R/R fuel filter & road test; R/R eng oil/filter then road test; still NG; needs to go to Ford. ja

Parts	Quantity
L4596FFUEL FILTER NEW # 33818	1
PH3786WIX 51734 OIL FILTER LF-LFP2286	1

Workorder: V33751

In Date: 07/23/2010
Close Date: 09/10/2010

Meter Reading: 44,648.00

Problem?

replace 2 front tires (outside agency-boulevard tire)

Task performed:

Replc (2) frnt tires - Boulevard j

Parts	Quantity
NO PARTS USED	

Vendor?: BOULEVARD TIRE

Workorder: V34839

In Date: 09/09/2010
Close Date: 09/28/2010

Meter Reading: 45,431.50

Problem?

REPLACE LR OUTER TIRE ESC 1

Task performed:

Replc LR outer tire ESC1 - Boulevard j

Parts	Quantity
NO PARTS USED	

Vendor?: BOULEVARD TIRE



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V35164

In Date: 09/24/2010 Meter Reading: 46,274.90
Close Date: 10/06/2010

Problem?

The right side forward quartz light is out. sta 81

Task performed:

This veh has no qtz lights NPF. j

Parts

Quantity

NO PARTS USED

Workorder: V35060

In Date: 09/20/2010 Meter Reading: 46,085.70
Close Date: 10/07/2010

Problem?

low oil level, light on dash for fuel prob ESC 1

Task performed:

1. travel to station 81; check and add 1.5 quarts of oil, also drain fuel water seperator filter, check ok. j

Parts

Quantity

SA28014STRAP OXYGEN RATCHET TYPE

2

Workorder: V35683

In Date: 10/15/2010 Meter Reading: 46,761.00
Close Date: 10/27/2010

Problem?

Will not shift into pump.

Task performed:

1. Dia why veh wont go into pump; ordered parts.
2. Travel to Stn81; R/R pump/read switch; new switch diff; had to mk mod; also R/R park brake switch & (2) into one connector at switch. j

Parts

Quantity

F2UZ15A851APARK BK SW

2

Workorder: V35983

In Date: 10/28/2010 Meter Reading: 47,162.70
Close Date: 11/18/2010

Problem?

Compartment mounted handlight not charging. ESC1

Task performed:

Test handlight charger; charger ok; replc handlight w/spare. j

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V36947

In Date: 12/07/2010
Close Date: 12/09/2010

Meter Reading: 47,399.00

Problem?

blown fuse esc 1

Task performed:

1. R/R fuse for gauges & foot throttle
2. Travel to Stn81 frm C/S; veh lost foot throttle again outside airport; meet driver at FI Mango rd; install fuse & follow to Stn81.
3. Start dia for short in wiring harness.
4. Chk - continue chkng all _____, chassis & fire pump wiring sys for chafe or short; road test veh sev times; never lost foot throttle.

Parts

Quantity

F81Z3E651DASHOCK ABSORBER STABILIZER

1

Workorder: V31498

In Date: 04/13/2010
Close Date: 12/22/2010

Meter Reading: 42,251.90

Problem?

REPAIR UNIT WONT START AL PACKER

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V36286

In Date: 11/08/2010
Close Date: 12/22/2010

Meter Reading: 47,399.00

Problem?

REPLACE FRONT AXLE ESC 1 AL PACKER FORD

Task performed:

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V36469

In Date: 11/15/2010
Close Date: 12/22/2010

Meter Reading: 47,399.00

Problem?

C INSPECTION AND REPAIRS AS NEEDED ESC 1

Task performed:

Parts	Quantity
15W40BSYN OIL BULK QTS	16
435 VALVE CAP	1
440STEM EXTENSION	1
65-72BXT65750 BATTERY	2
91-20WIPER BLADE 20 IN	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2
FA1710AIR FILTER 46728	1
L4596FFUEL FILTER NEW # 33818	1
PH3786WIX 51734 OIL FILTER LF-LFP2286	1

Workorder: V36967

In Date: 12/07/2010
Close Date: 12/22/2010

Meter Reading: 47,399.00

Problem?

blowing fuse,looses throttle and dash (outside agency-al packer ford)

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V37012

In Date: 12/08/2010
Close Date: 12/22/2010

Meter Reading: 47,399.00

Problem?

Please have Ken evaluate this vehicle for poss. refirb or replacement. esc 1

Task performed:

Parts	Quantity
NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V36016

In Date: 10/28/2010
Close Date: 01/10/2011

Meter Reading: 47,321.00

Problem?

Fuel compartment door latch broken. Sta 81

Task performed:

Parts

Quantity

1. Chk fuel fill compt door - needs parts, will order.
2. R/R steering stabilizer asy.
3. Dia oil leak; cln affected area; run veh on lift rear; main seal must be leaking.
4. Dia no tachometer on pump panel gauge; appears it was never hooked up frm mfr. j

NO PARTS USED

Workorder: V37329

In Date: 12/21/2010
Close Date: 01/11/2011

Meter Reading: 47,399.00

Problem?

replace all 6 tires (outside agency-TCI Tire)

Task performed:

Parts

Quantity

Replace all (6) tires - TCI j

NO PARTS USED

Vendor?: TCI

Workorder: V37972

In Date: 01/21/2011
Close Date: 01/25/2011

Meter Reading: 48,707.20

Problem?

Ground radio working improperly on AL1

Task performed:

Parts

Quantity

REPORTED TO RADIO SHOP 01/24

NO PARTS USED

Chkd power/grnd cable/connections; chkd antenna connection; chkd spkr splitter conections; NPF; radio works fine. (1/25/11) jj



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V38248

In Date: 02/03/2011 Meter Reading: 48,952.40
Close Date: 02/14/2011

Problem?

FUEL WATER SENSOR LIGHT ON.

Task performed:

Parts

Quantity

Attach drain hose to fuel filter hsng drain pipe; drain
hsng & chk amnt of water in fuel; road test veh. j

NO PARTS USED

Workorder: V38310

In Date: 02/06/2011 Meter Reading: 49,018.00
Close Date: 02/14/2011

Problem?

truck leaking water, source unknown ESC1

Task performed:

Parts

Quantity

Travel to Stn81 from C/S; fill wtr tank to find leak; down
in tank rem rusted pipe & fittings; go to shop; don't have;
go to Make hose for parts; back to tn81;assemble veh &
test. j

375914FITTING

1

7001-15EG150T SEAL

1

Workorder: V38320

In Date: 02/07/2011 Meter Reading: 49,018.00
Close Date: 02/14/2011

Problem?

bad water leak ESC1 (on-call)

Task performed:

Parts

Quantity

Drive to Stn81; C/O ESC1, has hole in elbow pipe
coming out of wtr tank. j

NO PARTS USED

Workorder: V38679

In Date: 02/22/2011 Meter Reading: 49,391.00
Close Date: 03/02/2011

Problem?

Far right roof marker light out. esc1

Task performed:

Parts

Quantity

R/R R/S frt marker lt; also (2) marker lts on cab roof.
j

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V39768

In Date: 04/07/2011

Meter Reading: 50,098.00

Close Date: 04/19/2011

Problem?

OIL LEVEL BELOW FILL LINE. ESC1

Task performed:

Add (1) qt eng oil. j

Parts

NO PARTS USED

Quantity

Workorder: V40881

In Date: 05/26/2011

Meter Reading: 51,397.50

Close Date: 06/01/2011

Problem?

WATER LEAK FROM TANK AREA. DROPE APOX 1/8 OF A TANK THROUGHOUT DAY.

Task performed:

Went to 81 - ESC1 thermal protection valve leaking; came back to shop for part; went back to 81; had to rem shelves in R1 compt to open access panel to pump area; R/R thermal valve; test for leaks. j

Parts

538-1260-00VALVE THERMAL RELIEF

Quantity

1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V41321

In Date: 06/14/2011

Meter Reading: 51,552.30

Close Date: 07/01/2011

Problem?

A/C BLOWING HOT...ALMOST LIKE IT'S STUCK IN HEATER MODE... Sta 81.

Task performed:

travel to st 81
diagnose why no a/c charging system not working
causing a/c to shut down
ordered 2 alternators

Parts

Quantity

2C3Z10V346BARMALTERNATOR

1

2C3Z10V346CARMALTERNATOR

1

F81Z10V346EARMALTERNATOR

1

F81Z10V346GARMALTERNATOR LOWER

1

R&R 2 alternators

one new a lt smoking remove cables check with ford
wrong niv given sent 2 new alternators remove other 2
alts still a problem called ford again

continue diagnosis of charging system

charging system diagnosis

alternator repair charging system diagnosis

alternator repair charging system diagnosis

alternator repair charging systeme diagnosis

alternator repair charging systeme diagnosis

quick check of vhe after coming back from ford deliver
veh to st 81 ak

Workorder: V41490

In Date: 06/21/2011

Meter Reading: 51,884.00

Close Date: 07/08/2011

Problem?

B Inspection @ Al Packer. Alternator stays energized even when the vehicle is off.

Task performed:

B-Inspection - Al Packer

Parts

Quantity

NO PARTS USED

Alt stays energized even when the vehi is off. j

Vendor?: AL PACKER



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V41727

In Date: 07/01/2011 Meter Reading: 51,909.00
Close Date: 07/12/2011

Problem?

POWER STEERING MAKING NOISE. Sta 81.

Task performed:

Travel to Stn81 frm C/S; chk fluid level slightly low; add fluid; road test veh; sounds ok. j

Parts

Quantity

NO PARTS USED

Workorder: V42075

In Date: 07/17/2011 Meter Reading: 52,349.00
Close Date: 08/02/2011

Problem?

pump makes clunking noise when taking it out of pump. It takes numerous times for it to get out of pump. ESC 1

Task performed:

travel to st 81 check pump shift operation no problem found chekc all wiring and switches

Parts

Quantity

NO PARTS USED

try pump shift again works normally advised shift capatian ak

Workorder: V42818

In Date: 08/15/2011 Meter Reading: 53,196.00
Close Date: 08/15/2011

Problem?

B Inspection @ Al Packer

Task performed:

B Inspection @ Al Packer

Parts

Quantity

NO PARTS USED

Vendor?: AL PACKER

Workorder: V42769

In Date: 08/12/2011 Meter Reading: 53,161.00
Close Date: 08/16/2011

Problem?

Piercer inop.

Task performed:

R/R piercer light asy in frt light bar to replc shattere light bulb. j

Parts

Quantity

H20W12VH20W12V BULB KIT

1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V43773

In Date: 09/19/2011

Meter Reading: 54,173.00

Close Date: 10/17/2011

Problem?

Nail in left rear outside tire. Also loose muffler on Hurst Power Unit. Sta 81

Task performed:

Parts

Quantity

travel to st 81 from shop check tire, remove screw soap test ok no leak

NO PARTS USED

check muffler on hurst tool power unit, bad, needs to be replaced, attached wire to secure until new part installed, ordered part

r&r muffler spark arrestor and heat shields on small engine

Workorder: V44129

In Date: 10/04/2011

Meter Reading: 1.00

Close Date: 10/17/2011

Problem?

ES1 lightbar center light out.....emergency light switch is slowly breaking needs replaced....., Sta 81.

Task performed:

Parts

Quantity

TRAVEL TO STAT 81 REMOVE CENTER STINGER LT ADDY FROM LIGHT BAR, DISASSEMBLE, R&R BULB

H20W12VH20W12V BULB KIT

1

R&R CENTER CONSOLE, R&R EMER LT SWITCH

REPAIR 110V SHORELINE TO VEH, RESET AND ATTACH STRAIN RELIEF CABLE TO 110V --WITH NEW TYWRAPS RECRIMP END OF STRAIN RELEIF TO PLUG

Workorder: V44466

In Date: 10/18/2011

Meter Reading:

Close Date: 10/21/2011

Problem?

Gas pedel not responding every so often. Already spoke to Ken about the problem. Sta 81.

Task performed:

Parts

Quantity

test throttle pedal, rheostat, check all connections at fast idle module interface, no problems found

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V43911

In Date: 09/25/2011

Meter Reading: 54,240.80

Close Date: 10/24/2011

Problem?

Alternator, fan belt edge is torn. Sta 81

Task performed:

TRAVEL TO ST 21 R&R FANBELT CHECK ALL ACC DRIVES, ONE IDLER BAD---BELT TO SHREAD, NO PART IN STOCK FOR PULLEY, R&R BRING IN PULLEY REINSTALL AND INSTALL BELT, ORDERED 2 NEW IDLER PULLEYS

Parts

Quantity

1C3Z2A934AABOLT PULLEY

1

F8TZ8620GCBELT

1

F8TZ8678FAPULLY

2

YC3Z8678ABPULLEY SMOOTH

1

TRIED TO INSTALL NEW PULLEYS, WRONG PARTS, HAVE TO REORDER

HAD TO VERIFY ALL INFO TO WOOLAND TO SEE WHY WRONG PARTS

R&R FANBELT INORDER TO R&R 2 IDELER PULLEYS FOR BELT, INCLUDES TRAVEL TO ST 81 AND BACK TO SHOP

Workorder: V44261

In Date: 10/10/2011

Meter Reading: 54,703.40

Close Date: 10/24/2011

Problem?

scott scout monitor is not working properly. CO2 reading too high. esc1

Task performed:

1. Get unit off veh & tag for repair; bring to C/S.
2. Give unit to SCBA tech.
3. Return unit to Stn81. j

Parts

Quantity

NO PARTS USED

Workorder: V44664

In Date: 10/25/2011

Meter Reading:

Close Date: 10/27/2011

Problem?

When starting engine. The engine is not turning over all the way and/or stopping. Possible starter going bad? Something is not right. It's doing it every other start or so. Sta 81.

Task performed:

Travel to 81; Replc dead btrys & tried to start; starter 10-7; bumped starter several times; got to start & sent to shop. j

Parts

Quantity

65-72BXT65750 BATTERY

2

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

2



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V44705

In Date: 10/26/2011

Meter Reading: 55,029.00

Close Date: 10/31/2011

Problem?

Won't start.

Task performed:

Dia/replc starter motor & replc both btrys. j

Parts

Quantity

2C3Z11002AASTARTER 7.3 MINI PUMPER 6669

1

65-72BXT65750 BATTERY

2

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

2

Workorder: V44375

In Date: 10/13/2011

Meter Reading:

Close Date: 11/15/2011

Problem?

right front tire tread is low. ESC 1

Task performed:

get tire size and info to order tires

Parts

Quantity

NO PARTS USED

check steering linkage and suspension, tightened bolts on front sway bar links

Workorder: V45190

In Date: 11/15/2011

Meter Reading:

Close Date: 11/15/2011

Problem?

right front tire tread is low. ESC 1

Task performed:

duplicate of 44375

Parts

Quantity

NO PARTS USED

Workorder: V45457

In Date: 11/28/2011

Meter Reading:

55,370.00

Close Date: 12/05/2011

Problem?

REPAIR UNINT WONT START

Task performed:

REPAIR UNIT WON'T START.

Parts

Quantity

NO PARTS USED

Vendor?: AL PACKER FORD



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V45125

In Date: 11/12/2011

Meter Reading:

Close Date: 12/08/2011

Problem?

Ck. eng. light on. ESC 1

Task performed:

Parts

Quantity

INSTALL CODE READER - NO PRESENT FAULTS STORED. CHECK ALL FLUIDS ROAD TEST VEHICLE. NO CHECKING LT. ON.

NO PARTS USED

Workorder: V45200

In Date: 11/15/2011

Meter Reading:

Close Date: 12/08/2011

Problem?

Ck eng light came on while driving to a call. The Vehicle had a hard time getting up to speed. Not sure if it is a transmission problem or engine? ESC1

Task performed:

Parts

Quantity

ROAD TEST VEHICLE FORD DIAGNOSIS. CHECK ENG. LT. WILL COME ON IF DRIVEN HARD. ENG. SEEMS SLUGGISH AND FULL VEHICLE SPEED NOT ATTAINED. CALLED STEVE REINES. TOOK VEHICLE TO AL PACKER FORD AND RETURN TO ST-81.

NO PARTS USED

Workorder: V45731

In Date: 12/08/2011

Meter Reading: 55,603.40

Close Date: 12/12/2011

Problem?

Weigh and evaluate

Task performed:

Parts

Quantity

ASSIST WITH WEIGHING;

NO PARTS USED

TEST DRIVE, CHECK OUT TRUCK.

Workorder: V45997

In Date: 12/21/2011

Meter Reading: 55,911.20

Close Date: 12/21/2011

Problem?

Starter/flywheel making a lot of noise, sometimes not starting.

Task performed:

Parts

Quantity

starter faulty. checked all teeth on flywheel. r&r starter

NO PARTS USED

Vendor?: AL PACKER



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V46026

In Date: 12/22/2011
Close Date: 12/28/2011

Meter Reading: 55,991.00

Problem?

Yellow(clearance lamp) roof light on driver side out, Sta 81

Task performed:

R&R ROOF CLEARANCE LT. BULB - CK. OK.

Parts

NO PARTS USED

Quantity

Workorder: V46056

In Date: 12/24/2011
Close Date: 12/29/2011

Meter Reading: 55,991.00

Problem?

Hurst Spreader assigned to Escort 1 is leaking from one of the hoses under pressure. Asset number G2199 not found in system.

Task performed:

WENT TO ST-81 - FOUND HOSESLEAKING - R&R 2
HOSES - SWAPTED FITTINGS - CK O.K.

Parts

3530033USE 353R222 HOSE HURST SWIVEL/ORING

2

Quantity

Workorder: V46214

In Date: 01/02/2012
Close Date: 01/04/2012

Meter Reading:

Problem?

hurst power unit keeps shutting down after a few min's of use.

Task performed:

LOAD SHOP SPARE IN SERVICE TRUCK, TEST ST 81
POWER UNIT, STARTED AND RAN FOR SHORT TIME
THEN STALLED (FUEL PROBLEM) SWAP OUT UNIT

Parts

NO PARTS USED

Quantity

Workorder: V47213

In Date: 02/10/2012
Close Date: 03/07/2012

Meter Reading: 57,115.20

Problem?

The bottom "pole" on the front extended bumper is loose and probably going to fall off if not fixed soon

Task performed:

REMOVED POLE FROM PUSH BUMPER REWELDED
BACK AT SHOP.

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V44325

In Date: 10/12/2011
Close Date: 03/09/2012

Meter Reading: 54,760.00

Problem?

C Inspection - Minipumper

Task performed:

- 1. C-Inspection
 - 2. Rep cab roof marker light.
 - 3. Rep L/R upper marker light - loose grd.
 - 4. Dia/rep R/S under truck light; fnd defective light asy & defective switch.
 - 5. Cln/dry all diesel fuel frm eng valley below manifold; run veh to look for leak; none fnd; will chk again.
- j

Parts	Quantity
4020362171 GRO LAMP DOME 4 IN	1
52-624SWITCH DOOR	1

Workorder: V44506

In Date: 10/19/2011
Close Date: 03/09/2012

Meter Reading: 54,888.00

Problem?

Replace all tires and alignment.

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V47699

In Date: 03/01/2012
Close Date: 03/30/2012

Meter Reading: 57,465.30

Problem?

shoreline ejector inop esc 1

Task performed:

REMOVE INOP EJECTOR INSTALLED NEW SUPER 20 AUTO EJECT.

Parts	Quantity
091-20WP-120AUTO EJECT	1

Workorder: V48483

In Date: 04/06/2012
Close Date: 04/30/2012

Meter Reading: 58,438.80

Problem?

low oil, Sta 81

Task performed:

CHECKED OIL CORRECTED LEVER.

Parts	Quantity
NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V49097

In Date: 05/04/2012
Close Date: 05/14/2012

Meter Reading: 59,047.90

Problem?

low on engine oil

Task performed:

corrected oil level.

Parts

Quantity

15W40QSYN OIL QT

12

337R017337R017 O RING

2

Workorder: V49251

In Date: 05/10/2012
Close Date: 05/29/2012

Meter Reading: 59,047.90

Problem?

A/C stops blowing cold when the engine comes to an idle. Stays warm for a few minutes and then gets cold again. This keeps repeating (cold/hot/cold/hot etc.) esc 1

Task performed:

INSTALLED GAUGES ON TRUCK CHECKS PRESSURE SWITCHES. ADDED FREON CHECKED OK.

Parts

Quantity

NO PARTS USED

Workorder: V50436

In Date: 06/27/2012
Close Date: 07/09/2012

Meter Reading: 60,417.20

Problem?

Test ports for vacuum and pressure gauges not working. During pump test, test gauges did not get a reading. esc 1

Task performed:

- 1. CLEANED PARTS CHECKED OK.
- 2. PUMP TESTED TRUCK WITH CREW.

Parts

Quantity

NO PARTS USED

Workorder: V50727

In Date: 07/10/2012
Close Date: 07/10/2012

Meter Reading: 60,702.00

Problem?

pump test unit

Task performed:

PUMP TESTED TRUCK AT AIRPORT.

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V51171

In Date: 07/27/2012
Close Date: 07/30/2012

Meter Reading: 60,845.60

Problem?

engine low on oil.

Task performed:

OIL LEVEL FILLED BY CREW ST 81.

Parts

NO PARTS USED

Quantity

Workorder: V51246

In Date: 07/31/2012
Close Date: 08/02/2012

Meter Reading: 60,845.60

Problem?

REPLACE ALL TIRES

Task performed:

REPLACE ALL TIRES.

Parts

NO PARTS USED

Quantity

Vendor?: ELPEX

Workorder: V51134

In Date: 07/25/2012
Close Date: 08/03/2012

Meter Reading: 60,845.60

Problem?

Shifter very loose. getting worn.

Task performed:

TIGHTENED SHIFTER BOLTS AND ADJUSTED CABLE FOR CORRECT INDICATION.

Parts

NO PARTS USED

Quantity

Workorder: V51763

In Date: 01/01/2012
Close Date: 09/10/2012

Meter Reading: 61,919.80

Problem?

SEATBELT BROKEN

Task performed:

1. INSTALLED NEW SEAT BELT- REMOVED SEAT TO GET TO BOLT TO SEAT BELT BECAUSE OF CENTER CONSOLE.

Parts

1C3Z25611B09SEAT BELT ASSY L/S 1C3Z25611B09AAF
1C3Z2561203BACSEAT BELT RECIEVER

Quantity

1
1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V51536

In Date: 08/11/2012

Meter Reading:

Close Date: 09/14/2012

Problem?

low on anti-freeze Sta 81

Task performed:

Parts

Quantity

1. ADDED COOLANT TO CORRECT LEVEL.

NO PARTS USED

Workorder: V51628

In Date: 08/15/2012

Meter Reading:

Close Date: 09/17/2012

Problem?

Fuel cap missing. ESC 1

Task performed:

Parts

Quantity

INSTALLED NEW FUEL CAP.

F4TZ9030C FUEL CAP

1

Workorder: V51724

In Date: 08/20/2012

Meter Reading:

Close Date: 09/17/2012

Problem?

missing fuel cap for the fuel tank. esc 1

Task performed:

Parts

Quantity

INSTALLED FUEL CAP ON TRUCK DONE ON WO #51628

NO PARTS USED

Workorder: V52505

In Date: 09/19/2012

Meter Reading:

Close Date: 09/24/2012

Problem?

radiator leak, freon leak and very low oil level. below add mark.

Task performed:

Parts

Quantity

COOLANT LEAK/ REPAIR LEAK/TOPPED OFF COOLANT AND PRESSURE TEST NEEDS A NEW RADIATOR WILL SEND TO DEALER TECHNICIAN.

15W40BSYN OIL BULK QTS

4



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V52693

In Date: 09/28/2012
Close Date: 09/28/2012

Meter Reading: 62,687.40

Problem?

replace radiator and water pump

Task performed:

replace radiator and water pump
replace leaking a/c line

Vendor?: AL PACKER

Parts

NO PARTS USED

Quantity

Workorder: V53317

In Date: 10/26/2012
Close Date: 11/28/2012

Meter Reading:

Problem?

Master switch becoming difficult to move on and off. 81

Task performed:

REMOVED BATTERY SWITCH AND INSTALLED NEW ONE.

Parts

51-30219-1045 MASTER SWITCH 175 AMP

2

Quantity

Workorder: V54054

In Date: 11/28/2012
Close Date: 11/28/2012

Meter Reading: 64,056.00

Problem?

B inspection

Task performed:

oil and filter change
multi point
replace fuel filter
replaced wiper blades
replaced air filter
leaking fuel filter housing, replaced housing

Vendor?: AL PACKER

Parts

NO PARTS USED

Quantity

Workorder: V53596

In Date: 11/07/2012
Close Date: 12/10/2012

Meter Reading:

Problem?

Right rear bottom step light INOP.

Task performed:

STEP LIGHT GROUND NOT GOOD, REPAIRED.

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V54339

In Date: 12/10/2012

Meter Reading:

Close Date: 12/18/2012

Problem?

Power steering fluid low. esc 1

Task performed:

Parts

Quantity

CORRECTED FLUID LEVEL.

NO PARTS USED

Workorder: V54341

In Date: 12/10/2012

Meter Reading:

Close Date: 12/18/2012

Problem?

Battery 1 indicator on rear of truck , shows Battery 1 with only one bar. When plugged in. esc 1

Task performed:

Parts

Quantity

WIRED THAT WAY SYSTEM IS GOOD.

NO PARTS USED

Workorder: V54342

In Date: 12/10/2012

Meter Reading:

Close Date: 12/18/2012

Problem?

loud clunking sound when taking pump out of gear. During pumping operations. esc 1

Task performed:

Parts

Quantity

CHECKED TRUCK FOUND TRANSMISION BRAKE NOT HOLDING OUTPUT SHORT TO ALLOW SHIFT TO ROAD MODE INFORMED CREW TO SHUT OFF TRCUK BEFORE SHIFTING.

NO PARTS USED

Workorder: V54449

In Date: 12/15/2012

Meter Reading: 64,482.00

Close Date: 12/27/2012

Problem?

water level gauge on structural panel malfunction ESC 1

Task performed:

Parts

Quantity

CHECKED UNIT FOUND GAUGE CONNECTION AT REAR OF MONITOR LOOSE.

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V55209

In Date: 01/22/2013

Meter Reading:

Close Date: 02/01/2013

Problem?

AXE head storage caddie/bracket broken in L-1 compartment.

Task performed:

Parts

Quantity

INSTALLED NEW HOKDER IN COMPRESOR.

NO PARTS USED

Workorder: V55495

In Date: 02/02/2013

Meter Reading: 65,514.00

Close Date: 02/07/2013

Problem?

screw in Drivers side, outside rear tire.ESC 1

Task performed:

Parts

Quantity

REMOVED SCREW CHECKED FOR LEAKS
RETURNED TO SERVICE.

NO PARTS USED

Workorder: V55873

In Date: 02/20/2013

Meter Reading:

Close Date: 02/25/2013

Problem?

missing fuel cap

Task performed:

Parts

Quantity

PARTS ONLY NO LABOR.

F4TZ9030C FUEL CAP

1

Workorder: V54340

In Date: 12/10/2012

Meter Reading:

Close Date: 02/26/2013

Problem?

Air conditioning blows hot and cold. compresspor coming on and off, intermitently while you drive. esc 1

Task performed:

Parts

Quantity

INSTALLED SWITCH CHECKED OK.

6L3Z-19D594-ASWITCH A/C PRESSURE HIGH

1

F6RZ19E561AAA/C SWITCH

1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V55178

In Date: 01/20/2013
Close Date: 02/28/2013

Meter Reading: 65,162.00

Problem?

one red light inop. on light bar.

Task performed:

TRAVEL TO ST 81 CHECK OUT LT BAR R&R STROBE LIGHT TEST OK.

Parts

Quantity

7ELTUBE7ELTUBE LINEAR STROBE REF

1

TURB6KITTURB6KIT LINEAR STROBE/REPLACES 02-0362

1

Workorder: V55961

In Date: 02/23/2013
Close Date: 02/28/2013

Meter Reading: 66,037.00

Problem?

Rear outside tires need replaced, they are wore down. Also front driver seat cover ripped and tathered. ESC 1

Task performed:

1. CHECK TIRES AND ORDER ALL 6.
2. CHECK SEAT COVERS ORDER NEW ONES.

Parts

Quantity

NO PARTS USED

Workorder: V55962

In Date: 02/23/2013
Close Date: 02/28/2013

Meter Reading: 66,037.00

Problem?

a/c kicks on and off , the compressor that is. always blows, the compressor just cycles on and off. ESC 1

Task performed:

CHECK OUT A/C SYSTEM CHECK SWITCHES FREON ETC. PAST BAD CONNECTION ON PLUG FOR PRESSURE SWITCH.

Parts

Quantity

NO PARTS USED

Workorder: V56053

In Date: 02/27/2013
Close Date: 02/28/2013

Meter Reading: 66,037.00

Problem?

REPLACE TIRES

Task performed:

REPLACE TIRES.

Parts

Quantity

NO PARTS USED

Vendor?: ELPEX



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V56254

In Date: 03/08/2013
Close Date: 03/14/2013

Meter Reading: 66,364.50

Problem?

replace seat covers

Task performed:

TRAVEL TO ST 81 R&R FRONT SEAT COVER.

Parts

F58-H8SEAT COVER

Quantity

1

Workorder: V56398

In Date: 03/14/2013
Close Date: 03/19/2013

Meter Reading: 66,536.00

Problem?

Dome light is out..need bulb Escort-1

Task performed:

CHECK OUT DOME LIGHT TEST POWER AND GROUND R&R BULB.

Parts

NO PARTS USED

Quantity

Workorder: V56484

In Date: 03/18/2013
Close Date: 03/22/2013

Meter Reading: 66,536.00

Problem?

low on engine oil,none in station. box light is missing nut for on/off switch. esc 81

Task performed:

DELIVERED 1 CASE OF OIL AND INSTALLED NEW SWITCH NUT ON BOX LIGHT.

Parts

NO PARTS USED

Quantity

Workorder: V46474

In Date: 01/10/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

powersteering not right, and noted a burning smell today. Sta 81

Task performed:

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V56865

In Date: 04/06/2013
Close Date: 04/16/2013

Meter Reading: 67,061.80

Problem?

engine oil level low tranny fluid low

Task performed:

ADD OIL AND TRANSFLUID.

Parts

7001-30ESEAL

Quantity

1

Workorder: V56933

In Date: 04/10/2013
Close Date: 04/16/2013

Meter Reading: 67,061.80

Problem?

Left wigwag bulb out. RP-81

Task performed:

- CHECK OUT WIG WAG PIERCER LIGHT BAD ORDER NEW LIGHT.
- TRAVEL TO ST 81 REPLACE AND WIRE UP NEW PIERCER LIGHT IN LIGHT BAR.

Parts

02038247700OBSOLETE OCSILLATER PIERCER ALERT
H27W12VH27W12V BULB

Quantity

1

1

Workorder: V57011

In Date: 04/13/2013
Close Date: 04/30/2013

Meter Reading:

Problem?

Backup(reverse alarm) not working. Mini pumper

Task performed:

- TRAVEL TO ST 81 CHECK BACK UP ALARM AND BACK UP LIGHTS R&R ALARM.
- CHECK OUT A/C SYSTEM FREON LEVEL GOOD, OK.

Parts

575BACKUP ALARM ECCO 107 DEC

Quantity

2

Workorder: V58854

In Date: 07/04/2013
Close Date: 07/12/2013

Meter Reading: 68,046.50

Problem?

-door locks not working correctly -shoreline charging system needs checked

Task performed:

CHECKED SHORELINE AND BATTERY CHARGER FOUND STATION WIRING BAD AT PLUG INFORMED STATION OFFICER TO CONTACT AIRPORT ELECTRICIAN.

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V58879

In Date: 07/05/2013
Close Date: 07/19/2013

Meter Reading: 68,046.50

Problem?

AC WORKING INTERMINTED. AFTER TRUCKS RUNS A BIT THE AC STOPS BLOWING COLD AIR. Eng. has to run at high speed to work. very hot.

Task performed:

1. TRAVEL TO ST 81 R&R A/C PRESSURE AND SWITCHES ON UNIT TEST OK.

Parts	Quantity
6L3Z-19D594-ASWITCH A/C PRESSURE HIGH	1
7C3Z9H465AVALVE ASSY	1
F6RZ19E561AAA/C SWITCH	1

Workorder: V58989

In Date: 07/10/2013
Close Date: 07/19/2013

Meter Reading: 68,046.50

Problem?

battery or alternator may be bad. need to be checked.

Task performed:

TRAVEL TO ST 81 CHECK CHARGE SYSTEM AND 110V. TEST BATT. R&R BATT.

Parts	Quantity
65-72BXT65750 BATTERY	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2

Workorder: V59623

In Date: 08/06/2013
Close Date: 08/15/2013

Meter Reading: 69,825.30

Problem?

All interior compartment lights not working.

Task performed:

TRAVEL TO ST 81 CHECK OUT COMPT LIGHTS NO POWER PULL CLASS ONE BOARD CHECK SWITCHES RELAYS ETC. WIRING NO POWER TO RELAY CONTROLL FOUND BAD CONNECTION ON PARK BK SWITCH REPAIR TEST OK.

Parts	Quantity
NO PARTS USED	

Workorder: V59624

In Date: 08/06/2013
Close Date: 08/28/2013

Meter Reading: 69,825.30

Problem?

The digital numbers on the RPM/Tach + gauge are buring out/ becoming illegible to read on the pump panel.

Task performed:

1. TRY TO INSTALL TACH-PLUS 400 WIRING NOT THE SAME ORDER 450.
2. TRAVEL TO ST 81 TO INSTALL NEW TACH-PLUG 450 STILL WRONG PART WILL ORDER NEW ONE.

Parts	Quantity
NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V60206

In Date: 09/01/2013 Meter Reading: 70,450.90
Close Date: 09/04/2013

Problem?

Rear scene lights inop.. side compartment lights inop.. ESC 1

Task performed:

TRAVEL TO AIRPORT CHECKOUT LIGHTS WORKING
OK SWITCHES ETC. PARKING HAS TO BE SET LET
CAP. KNOW TO PAST DOWN.

Parts

NO PARTS USED

Quantity

Workorder: V59625

In Date: 08/06/2013 Meter Reading: 69,825.30
Close Date: 09/12/2013

Problem?

The LED on the Foam Tank gauge at the 75% full level mark is burnt out or not working.

Task performed:

TRAVEL TO ST 81 CHECK GAUGE R&R LEVEL GAUGE
AND SET UP.

Parts

WLA260-A00FOAM TANK INDICATOR

Quantity

1

Workorder: V60443

In Date: 09/11/2013 Meter Reading: 70,598.90
Close Date: 09/20/2013

Problem?

LEFT SIDE OF LIGHT BAR ON ROOF IS OUT.

Task performed:

R&R TWO BULB IN LIGHT BAR.

Parts

NO PARTS USED

Quantity

Workorder: V60550

In Date: 09/17/2013 Meter Reading: 70,598.90
Close Date: 09/23/2013

Problem?

B inspection Escort 1 (mini pumper)

Task performed:

B-INSPECTION.

Parts

- F81Z5484MABUSHING SWAY BAR FORD REAR
- F81Z5486CABRACKET SWAY BAR REAR
- FA1710AIR FILTER 46728
- L4596FFUEL FILTER NEW # 33818
- PH3786WIX 51734 OIL FILTER LF-LFP2286

Quantity

- 1
- 1
- 1
- 1
- 1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V60365

In Date: 09/08/2013
Close Date: 10/09/2013

Meter Reading: 70,598.90

Problem?

passenger door lock not working with unlock button ESC 1

Task performed:

CHECK DOOR LOCK AND BOTH SIDE ARE NOT WORKING SOUND LIKE PULLUGER ARE BAD WILL ORDER PULUGES.

Parts

Quantity

6L3Z25218A42AACTUATOR DOOR LOCK R/S FORD F550

1

6L3Z25218A43AACTUATOR DOOR LOCK L/S FORD F550

1

Workorder: V60811

In Date: 09/26/2013
Close Date: 10/09/2013

Meter Reading: 70,895.60

Problem?

AC stops working after trucks warms up again.

Task performed:

CHECK A/C FOUND PRESSURE A LITTLE LOW SO I ADD FREON.

Parts

Quantity

NO PARTS USED

Workorder: V61281

In Date: 10/15/2013
Close Date: 10/15/2013

Meter Reading: 71,335.60

Problem?

Align front end

Task performed:

Align front end and repair as needed

Parts

Quantity

NO PARTS USED

Vendor?: ELPEX TIRESOLES

Workorder: V61873

In Date: 11/07/2013
Close Date: 11/14/2013

Meter Reading: 71,609.10

Problem?

Check a/c

Task performed:

CHECK A/C AND PRESSURE LOOK GOOD.

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V62019

In Date: 11/14/2013
Close Date: 11/14/2013

Meter Reading: 72,505.00

Problem?

Power steering leak

Task performed:

Replaced power steering hose

Parts

Quantity

NO PARTS USED

Vendor?: AL PACKER

Workorder: V61919

In Date: 11/10/2013
Close Date: 11/21/2013

Meter Reading:

Problem?

power steering hose is leaking bad. also large screw in left rear outside tire. ESC 1

Task performed:

TRAVEL TO ST-81 CHECK OUT LEAK- CHECK FOR LEAKS LOOKS LIKE NEW HOSE ON BRAKE BAXTER NO LEAKS GEN FLUID RE ROUTE LINE ON STEERING SHAFT CHECK FOR BOLTS IN TIRES DIDNT FIND SCREW UNFOUNDED.

Parts

Quantity

NO PARTS USED

Workorder: V62100

In Date: 11/18/2013
Close Date: 11/26/2013

Meter Reading:

Problem?

Eecsort 1 is not able to go into pump.

Task performed:

1. WENT TO AIRPORT CHECK PUMP SHIFT FUND IT WOULD BY HAND (BUT WAS VERY HARD TO SHIFT) BUT NOT WITH PUMP SHIFT SWITCH DROVE TRUCK TO SHOP TO LIFT, PICK TRACK UP AND FOUND LINKAGE IN A BIND FOUND BRACKET BEND SO WE STRAIGHTEN BRACKET OUT AND LUBED SHAFT AT SLIDES AND PUMP SHIFT SWITCH WORKED SO I TOOK TRACK BACK TO AIRPORT AND GOT SERGICE TRUCK TO GO BACK TO SHOP.
2. ASSIST WITH PUMP SHAFT.

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V62331

In Date: 11/28/2013

Meter Reading: 72,084.00

Close Date: 12/06/2013

Problem?

transmission indicator not moving when shifting transmission. ESC 1

Task performed:

1. TRANS INDICATOR INOP CHECK OUT SHIFT LEVER BROKE IN COLLUM WILL ORDER NEW CABLE.
2. CHECK LIGHTS OUT IN LIGHT BAR REPAIR WIRING ON ONE LIGHT REPLACE LIGHT ON DRIVER SIDE BAR TEST OK.
3. CHECK OUT BRAKE LIGHT ON CHECK FLUID BRAKER FTC. DIDN'T FIND LIGHT PARK BRAKE COULD HAVE BEEN ON A LITTLE CAUSING LIGHT TO BE ON.

Parts

Quantity

- 7ELTUBE7ELTUBE LINEAR STROBE REF
- F81Z7A110CATRANS POINTER KIT

- 1
- 1

Workorder: V62557

In Date: 12/07/2013

Meter Reading: 72,084.40

Close Date: 12/12/2013

Problem?

REPAIR A/C

Task performed:

WENT TO AIRPORT TO PICK UP TRUCK BROUGHT BACK TO SHOP RECOVER AC SYSTEM AND INSTALL DRYER FOR FACE TUBE VACUUM SYSTEM AND CHARGE SYSTEM AND TOOK BACK TO THE AIRPORT, FOUND METAL IN AIRFIRE SO I ORDRED A COMPRESSOR.

Parts

Quantity

- 5U2Z19V703FECOMPRESSOR A/C
- 6C3Z19C836AACCUM/DRIER
- 8201L17-3428 ESTER OIL E7
- F5UZ19D990ABEXPANSION TUBE

- 1
- 2
- 1
- 2

Workorder: V62397

In Date: 12/02/2013

Meter Reading:

Close Date: 12/16/2013

Problem?

l/s middle strobe light out. wig wag light out on lightbar. brake light stays on. shift indicator inop

Task performed:

1. WENT TO AIRPORT AND SAT TRUCK, REMOVE STEERING COLUMN AND REPLACE GEAR SELECTOR.
2. CHECK AC SYSTEM VACUUM AND CHARGE TO PROPER SPECS TEST FOR OPERATION IS WORKING GOOD NOW.
3. R&R BULB IN LIGHT BAR.
4. TOOK TRUCK BACK TO AIRPORT.

Parts

Quantity

- H20W12VH20W12V BULB KIT
- VC7BANTIFREEZE MOTORCRAFT PREMIUN GOLD

- 1
- 1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V63832

In Date: 01/29/2014

Meter Reading:

Close Date: 03/10/2014

Problem?

power steering fluid low

Task performed:

Parts

Quantity

CHECK POWER STEERING FLUID IT WAS A LITTLE LOW SO I TOPPED IT OFF.

NO PARTS USED

Workorder: V64607

In Date: 03/01/2014

Meter Reading:

Close Date: 03/10/2014

Problem?

headlight is out and oil gauge on pump panel does not work. ESC 1

Task performed:

Parts

Quantity

CHECK HEADLIGHTS AND NO PROBLEM FOUND SO I PUT HEADLIGHT BULB IN CABIN AT AIRPORT AND CHECK OIL GUAGE. LOOKS GOOD.

9007H9007 BULB ASSY

1

Workorder: V64610

In Date: 03/01/2014

Meter Reading:

Close Date: 03/10/2014

Problem?

Interior compartment lights do not work. (Master Switch & Compoartment Switch are in the ON Position.) ESC 1

Task performed:

Parts

Quantity

XHECK ALL COMPARTMENT LIGHTS. ALL WORKING

NO PARTS USED

Workorder: V63252

In Date: 01/09/2014

Meter Reading:

Close Date: 03/11/2014

Problem?

Al packer, replace a/c compressor.

Task performed:

Parts

Quantity

AL PACKER, REPLACE A/C COMPRESSOR.

NO PARTS USED

Vendor?: AL PACKER



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V63807

In Date: 01/29/2014

Meter Reading:

Close Date: 03/18/2014

Problem?

Jump line hose cover worn. Needs replacement.

Task performed:

Parts

Quantity

REMOVE HOSE COVER TO SEND TO BE REPAIRED.

NO PARTS USED

Workorder: V65015

In Date: 03/18/2014

Meter Reading: 74,968.00

Close Date: 03/18/2014

Problem?

A/C inop intermittent

Task performed:

Parts

Quantity

Replaced a/c compressor, accumulator, orifice tube

NO PARTS USED

Vendor?: AL PACKER

Workorder: V63115

In Date: 01/03/2014

Meter Reading:

Close Date: 03/19/2014

Problem?

lock on the rear left door is binding.ESC 1

Task performed:

Parts

Quantity

1. LOOKED AT LOCK, LOOKS LIKE IS BEND AND BINDING NEEDS NEW LOCK., WENT BACK TO SHOP.

1250K D-RING 7 1/6" LOCKING

1

2. REMOVE LOCK AND FOUND THE NEW LOCK ASSY WAS WRON.

3. SHOWED ED A PICTURE OF BACK SIDE OF LOCK AND HAD THE RIGHT ONE IN STOCK.

4. REMOVED COVER LUBED LOCK AND CONTROL ROPE CHECKED OK.



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V63805

In Date: 01/29/2014

Meter Reading:

Close Date: 03/19/2014

Problem?

Right rear bottom step light out.

Task performed:

1. TOOK APART BULB LOOSE IN ASSEMBLY NEED NEW LIGHT ASSY, MAKE ASSY WORK BUT BROKEN SCREW OFF IN STEP NEED TO ORDER NEW STEP AND STEP LIGHT ASSY.
2. FOUND TAG LIGHT OUT CHECK LIGHT AND FOUND BAD BULB.
3. REMOVED STEP AND LIGHT FROM REAR OF TRUCK INSTALLED NEW COMPARTMENTS.

Parts

Quantity

120257100C2030-7110-30 CLEAR DOME STEP

1

Workorder: V64948

In Date: 03/15/2014

Meter Reading:

Close Date: 03/20/2014

Problem?

shifter bushings on steering column worn out. left rear running light. under rotating light burned out. rear running lights, 3 middle under bumper, 1 burned out. engine oil low, some oil added. ESC 1

Task performed:

1. DROVE R-3 TO AIRPORT AND CHECK SHIFTER ON MINI-PUMP OR IT IS LOOSE BUT WORKS GOOD.
2. CHECK LEFT REAR RUNNING LIGHT AND FOUND BAD BULB R&R LIGHT CHECK 3 MIDDLE UNDER BUMPER FOUND ONE BAD BULB BUT DID NOT HAVE ANYMORE ON TRUCK.
3. WENT BACK TO SHOP AND PUT MORE CLEARANCE LIGHT ON TRUCK.

Parts

Quantity

35200-RLIGHT MARKER LED RED

2

Workorder: V65855

In Date: 04/21/2014

Meter Reading:

Close Date: 04/29/2014

Problem?

small hose fell off from under truck. Might be conected to a bypass valve for the #1 discharge. ESC1

Task performed:

PUT TRUCK IN MECHANICS BAY GOT UNDER TRUCK, FOUND DRAIN LINE OFF REPAIRED OK.

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V65954

In Date: 04/24/2014

Meter Reading: 75,087.70

Close Date: 05/08/2014

Problem?

Replace R/R/I and R/R/O

Task performed:

Parts

Quantity

Replace R/R/I and R/R/O

NO PARTS USED

Vendor?: ELPEX

Workorder: V66519

In Date: 05/16/2014

Meter Reading:

Close Date: 05/21/2014

Problem?

front breaks feel like they are rubbing metal against metal.

Task performed:

Parts

Quantity

GOT TOOL TO GO TO AIRPORT GOT TO AIRPORT AND CHECK BRAKES ON TRACK FOUND RIGHT REAR BRAKES ARE ARE BAD SO I CALL JOHN MURRAY HE SEND ME TO AL PACKER DROP OFF K11078 AND PICKED UP AT TRUCK AND WENT TO THE SHOP.

NO PARTS USED

Workorder: V66672

In Date: 05/22/2014

Meter Reading: 75,771.00

Close Date: 05/22/2014

Problem?

B-inspection Brakes metal to metal

Task performed:

Parts

Quantity

B-inspection
Replace front and rear calipers
Replaced rear oil seals
Complete brake job w/ rotors
Replaced weatherstrip
Replaced brake booster
Replaced batteries

NO PARTS USED

Vendor?: AL PACKER



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V65176

In Date: 03/24/2014

Meter Reading:

Close Date: 06/10/2014

Problem?

Please add mounting "clamps" for sledge hammer in L-1 compartment next to haligan. Thanks ESC 1

Task performed:

Parts

Quantity

Repaired on another Wo #

NO PARTS USED

Workorder: V66665

In Date: 05/22/2014

Meter Reading:

Close Date: 06/18/2014

Problem?

Left rear brake light/turn signal INOP.

Task performed:

Parts

Quantity

installed new bulb.

NO PARTS USED

Workorder: V68809

In Date: 08/19/2014

Meter Reading: 77,535.00

Close Date: 08/25/2014

Problem?

Check eng. light turned on while on airfield patrol. Transmission had trouble shifting into high gear.

Task performed:

Parts

Quantity

Travel to station 81. Check truck engine light on. Check trans fluid level , ok. Check for code and on truck. All codes are trans. related needs to go to Ford test drive unit not shifting at the right rpm.

NO PARTS USED

Workorder: V69052

In Date: 08/29/2014

Meter Reading: 77,671.00

Close Date: 08/29/2014

Problem?

Problem shifting into hight Problems when in pump with throttle

Task performed:

Parts

Quantity

Check for codes
Cleared codes only come back when PTO is activated
Road test no problems found

NO PARTS USED

Vendor?: AL PACKER



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V68406

In Date: 08/04/2014

Meter Reading:

Close Date: 09/02/2014

Problem?

Two nails in right front tire.

Task performed:

Parts

Quantity

Nails were removed no repair needed

NO PARTS USED

Workorder: V67696

In Date: 07/05/2014

Meter Reading:

Close Date: 09/10/2014

Problem?

Nail in right front tire. Near outside edge of tire.

Task performed:

Parts

Quantity

tires ck, on ticket was complete on w/o 68406

NO PARTS USED

Workorder: V68554

In Date: 08/10/2014

Meter Reading:

Close Date: 09/11/2014

Problem?

Pump operation problems. Fluctuating pump pressures and RPM's. The pump was primed and the pressure relief valve was set properly but still had fluctuations. ESC1

Task performed:

Parts

Quantity

order new throttle control.

NO PARTS USED

Workorder: V68272

In Date: 07/30/2014

Meter Reading:

Close Date: 10/22/2014

Problem?

Right and left side forward marker lights out or partially out.

Task performed:

Parts

Quantity

Installed new lights.

35200-YLIGHT MARKER LEDAMBER

2

FRT V28260FREIGHT CHARGE

1

T500076THROTTLE COMMANDER VMAC

1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V70031

In Date: 10/09/2014
Close Date: 11/04/2014

Meter Reading: 77,817.00

Problem?

shore line charging not charging.

Task performed:

Prep for airport repairs , drive to airport. Check unit short line charger-found charger is working, but just one line is connected. Connect a second line, replace charging display panel-test for operation it's working good now.

Parts	Quantity
091-39-INDAUTO CHARGER INDICATOR	1
D3TZ-2457BBREAK PEDDEL PAD	1

Workorder: V70402

In Date: 10/23/2014
Close Date: 11/06/2014

Meter Reading: 78,148.20

Problem?

brake pedal replaced

Task performed:

1. Replace brake pedal pad.
2. Prep airport truck and parts. Drive to airport for repairs.

Parts	Quantity
NO PARTS USED	

Workorder: V71038

In Date: 11/18/2014
Close Date: 11/18/2014

Meter Reading: 78,595.50

Problem?

Check engine light on

Task performed:

Check for trouble codes, seem to be on customer side will chweck at shop
Purge air from p/s system
Vendor?: AL PACKER

Parts	Quantity
NO PARTS USED	

Workorder: V70794

In Date: 11/08/2014
Close Date: 11/20/2014

Meter Reading:

Problem?

sevice engine light on ESC 1

Task performed:

Delivered to Ford talked to technician there about issue-went through diagnostic test.

Parts	Quantity
NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V70824

In Date: 11/10/2014

Meter Reading:

Close Date: 11/20/2014

Problem?

Siamese on ES1's pump panel, gate valves are almost frozen.

Task performed:

Parts

Quantity

Could not find valve

NO PARTS USED

Workorder: V70843

In Date: 11/11/2014

Meter Reading:

Close Date: 11/20/2014

Problem?

Noise coming from power steering pump. ESC 1

Task performed:

Parts

Quantity

Done at Ford

NO PARTS USED

Workorder: V70888

In Date: 11/12/2014

Meter Reading:

Close Date: 11/20/2014

Problem?

Engine wont accelerate faster than 40mph and check engine light on ,power steering noisetype sound heard in engine compartment

Task performed:

Parts

Quantity

1. Check code-found many code for trans. so we send to AI packer
2. Come back from AI packer but still didn't ran right and engine light was still on, so we check code and cleared them and two engine code keep come back so we check wire harness no problem found. We disconnect governor and codes still come back so we took it back to AI packer
3. Assist with problem

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V71111

In Date: 11/21/2014

Meter Reading: 78,595.50

Close Date: 11/24/2014

Problem?

Repair throttle after repairs at dealer

Task performed:

Hooked throttle back up and ran pump-no check engine light. Truck runs good but hood shocks are bad order new shocks for hood.

Parts

Quantity

F81Z16C826ABHOOD STRUT S/O

1

F81Z16C826ADHOOD STRUT S/O

1

Workorder: V71177

In Date: 11/24/2014

Meter Reading: 78,735.00

Close Date: 12/05/2014

Problem?

B-inspection Repair check engine/power loss and trans problems

Task performed:

Check engine light
Repair and rebuild gear shifter
Fuel filter
Oil and filter change
B inspection
Wiperblades
Replaced diesel air filter
Vendor?: AL PACKER

Parts

Quantity

NO PARTS USED

Workorder: V71734

In Date: 12/18/2014

Meter Reading: 79,481.80

Close Date: 12/22/2014

Problem?

Battery dead

Task performed:

Installed new hood shocks
Checked battery charging system-found bad connection at charger plug-repaired

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V72123

In Date: 01/08/2015

Close Date: 01/16/2015

Meter Reading:

Problem?

Rt. front headlight out.

Task performed:

Installed new headlight bulb.

Parts

Quantity

9007H9007 BULB ASSY

1

Workorder: V72260

In Date: 01/12/2015

Close Date: 01/16/2015

Meter Reading:

Problem?

fuel cap missing

Task performed:

Installed new fuel cap.

Parts

Quantity

F4TZ9030C FUEL CAP

1

Workorder: V72209

In Date: 01/11/2015

Close Date: 01/21/2015

Meter Reading:

Problem?

ES1 Hurst unit leaking fuel from air intake Asset #B2953. Pulled unit off truck.

Task performed:

Ran unit with Captain. No problem found.

Parts

Quantity

NO PARTS USED

Workorder: V69961

In Date: 10/06/2014

Close Date: 01/23/2015

Meter Reading: 77,817.00

Problem?

Hurst Power unit carburetor float valve sticking open and leaking fuel when unit is off.

Task performed:

Drive to central shop for power unit hurst tool. Replace unit and test, it is good.

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V73121

In Date: 02/12/2015
Close Date: 02/12/2015

Meter Reading: 81,068.60

Problem?

replace 6 tires

Task performed:

replace 6 tires

Parts

Quantity

NO PARTS USED

Vendor?: ELPEX

Workorder: V72681

In Date: 01/28/2015
Close Date: 02/20/2015

Meter Reading:

Problem?

Right rear tail board metal was found to be bent and damaged. Damage found during morning truck check out/ washing.

Task performed:

Went to airport and looking at tailboard.

Parts

Quantity

NO PARTS USED

Workorder: V73136

In Date: 02/13/2015
Close Date: 03/09/2015

Meter Reading:

Problem?

High Idle not working with lights on. Panel showing 11.3 volts with lights on and low battery alert.

Task performed:

1. Went to airport chekc. Check track, found higt idle worked if you see emergency brake.
2. Drove D4 and assect with track.

Parts

Quantity

NO PARTS USED

Workorder: V74690

In Date: 04/15/2015
Close Date: 04/16/2015

Meter Reading:

Problem?

Asset works Rear of vehicle, center overhead door. door lock wont twist, feels jammed.

Task performed:

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

K11078

Mini-Pumper CRASH FIRE RESCUE VEHICLE

Workorder: V74419

In Date: 04/04/2015

Meter Reading:

Close Date: 06/17/2015

Problem?

shifter indicator is way off. park is reverse....etc. ESC 1

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V74498

In Date: 04/08/2015

Meter Reading:

Close Date: 06/17/2015

Problem?

Right rear marker light out.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V74652

In Date: 04/14/2015

Meter Reading:

Close Date: 07/07/2015

Problem?

Side view mirror adjustment switch INOP.

Task performed:

Parts

Quantity

NO PARTS USED



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (K11078) 2002 - EONE MINI PUMPER Crash Fire Rescue Vehicle

K11078

CSHOP-2015-1309

Comments: **MINI PUMPER NO START / TRAVEL TO STATION CHECK UNIT FOUND NEEDS ALTERNATORS REPLACED ALL TIRES TCI**

Date Opened: 6-22-2015 Date Finished: 8-25-2015 Meter 1 Reading: 85,159

TASKS PERFORMED

Q PARTS

ALTERNATOR-GENERATOR
TIRES ALL

1 ALTERNATOR SLAVE (LOWER)
1 ALTERNATOR
1 BELT; BELT
1 ALTERNATOR; ALTERNATOR

CSHOP-2015-2099

Comments: **ON CALL WONT RUN ESC 1**

Date Opened: 8-3-2015 Date Finished: 8-4-2015 Meter 1 Reading: 83,905

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
BATTERY
ALTERNATOR-GENERATOR

2 BATTERY; BXT65750 BATTERY
2 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY

CSHOP-2015-2420

Comments: **POWER MIRRORS INOP MINI PUMPER**

Date Opened: 8-20-2015 Date Finished: 8-21-2015 Meter 1 Reading: 85,159

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
MIRRORS

CSHOP-2015-272

Comments: **MINI PUMPER DISCHARGE ON PUMP PANEL LEAKS HEAVILY WHILE UNDER PRESSURE**

Date Opened: 4-24-2015 Date Finished: 6-15-2015 Meter 1 Reading: 83,422

DIS CHARGE LEAK

TASKS PERFORMED

Q PARTS

FIRE PUMP CONTROLS

1 SS NIPPLE FITTING

Asset Work Order History K11078

CSHOP-2015-2816

Comments: . MINI PUMPER FUEL CAP MISSING PUMP HAS A LONG DELAY IN SWITCHING ON TO "OKAY TO PUMP" TRUCK HAS TO BE RESTARTED TO ENGAGE.

Date Opened: 9-9-2015 Date Finished 9-24-2015 Meter 1 Reading: 85,936

REMOVE AND REPLACE SIREN CONTROL HEAD

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP CONTROLS
PUMP PANEL
FUEL SYSTEM
SIREN

1 FRS; TACH PLUS FIRE RESEARCH MECH
1 9IP; FUEL CAP
1 SIREN; SIREN

CSHOP-2015-3397

Comments: ABNORMAL NOISE HEARD FROM STARTER AREA WHEN CRANKING,SOUNDS LIKE SOMETHING LOOSE K11078 MINI PUMPER

Date Opened: 10-13-2015 Date Finished 10-15-2015 Meter 1 Reading: 85,936

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES

CSHOP-2015-3621

Comments: B-INSPECTION AND REPAIRS PACKER

Date Opened: 10-27-2015 Date Finished 10-27-2015 Meter 1 Reading: 86,334

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2015-662

Comments: MINI PUMPER DRIVER SEAT WON`T ADJUST FORWARD OR BACK NEEDS SCBA BRACKET ATTACHED TO CURRENT ONE IN L2 COMPARTMENT GET INFO FROM S. MIKHAIL

Date Opened: 5-15-2015 Date Finished 6-2-2015 Meter 1 Reading: 83,422

DRIVE SEAT WOULD ADJ.

TASKS PERFORMED

NO PARTS USED

EQUIPMENT MOUNTING BRACKETS
SEAT FRONT

CSHOP-2015-92

Date Opened: 4-16-2015 Date Finished 4-20-2015 Meter 1 Reading: 82,443

TASKS PERFORMED

NO PARTS USED

BODY EXTERIOR

Asset Work Order History K11078

CSHOP-2015-953

Comments: **ALL VALVES ON PUMP PANEL EXTREMELY HARD TO OPERATE MINI PUMPER**

Date Opened: 6-2-2015 Date Finished 6-16-2015 Meter 1 Reading: 83,905

TASKS PERFORMED

Q PARTS

FIRE PUMP PLUMBING	2	VALVE; 8905 VALVE KIT 2 IN AKRON
HOSE BED BODY	1	VALVE; 8906 VALVE KIT 2.5 IN AKRON
INSTRUMENTS-GAUGES-METERS	1	VALVE; 8930 AKRON 3 IN VALVE
	1	VALVE; 8904 VALVE KIT 1 1/2 IN
	4	CLIP; CLIPS NERF BAR PAD
	1	PAD; PAD NERF BAR
	1	NONSTOCK; TRANS POINTER KIT

CSHOP-2016-1529

Comments: **ON-CALL NO BRAKES UNIT WAS SENT TO PACKER TO REPAIR BRAKE LEAK**

Date Opened: 4-1-2016 Date Finished 4-12-2016 Meter 1 Reading: 89,880

TASKS PERFORMED

NO PARTS USED

TIRES ALL
BRAKES

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2016-216

Comments: **HEADLIGHT SWITCH/ A/C ONLY WORKS ON 2 SETTINGS**

Date Opened: 1-19-2016 Date Finished 2-19-2016 Meter 1 Reading: 88,694

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM	1	NEWPART; HEADLAMP SWITCH FORD F450
-----------------	---	------------------------------------

VENDOR? AL PACKER

Service Requests:

01/17/2016 BODY / 12: BROKEN / EXCHANGE - NEW
HEAD LIGHT KNOB IS BROKEN. SWITCH WORKS FINE, BUT IT NEEDS NEW KNOB.

01/31/2016 LIGHTS / 12: BROKEN / EXCHANGE - NEW
HEADLIGHTS ON/OFF SWITCH IS SLIDING IN FURTHER THAN ITS LIMITS. IT WILL BREAK SHORTLY.

CSHOP-2016-3167

Comments: **MINI PUMPER BROKEN GEAR SHIFT**

Date Opened: 7-1-2016 Date Finished 9-23-2016 Meter 1 Reading: 93,090

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
SHIFTER CONTROLS-SELECTOR

Service Requests:

07/01/2016 TRANSMISSION / 12: BROKEN / DROVE TO AND FROM STATION 81. PREFORMED INSPECTION. VI
ES1 GEAR SHIFTER IS BROKEN, UNABLE TO SELECT GEARS AND REMOVE THE KEY. (NEEDS TO BE FIXED OR
REPAIRED)

Asset Work Order History K11078

CSHOP-2016-3265

Date Opened: 7-6-2016 Date Finished 7-6-2016 Meter 1 Reading: 91,645

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2016-3846

Comments: **NO POWER BRAKES ESCORT 81**

Date Opened: 8-8-2016 Date Finished 8-8-2016 Meter 1 Reading: 92,037

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BRAKES

Service Requests:

08/07/2016 BRAKES / 18: LEAKING / A
LOST POWER BRAKES.

CSHOP-2016-3944

Date Opened: 8-11-2016 Date Finished 8-11-2016 Meter 1 Reading: 92,276

TASKS PERFORMED

NO PARTS USED

STEERING

VENDOR? AL PACKER

CSHOP-2016-4889

Comments: **K1078 MINI PUMPER POWER SWITHC WILL NOT SHUT OFF.**

Date Opened: 10-12-2016 Date Finished 10-28-2016 Meter 1 Reading: 93,862

TASKS PERFORMED

Q PARTS

SWITCH-ELECTRICAL

1 SWITCH; 19-1045 MASTER SWITCH 175 AMP

Service Requests:

10/12/2016 SERVICE REQUEST / 11: BINDS/STICKS / PREFORMED DIAGNOSTICS. FOUND BATTERY SWITCH

Asset Work Order History K11078

CSHOP-2016-5905

Comments: **NEED GATOR CAPS**

Date Opened: 12-19-2016

Date Finished

3-1-2017

Meter 1 Reading:

96,458

TASKS PERFORMED

Q PARTS

PARK-CLEARANCE LIGHTS
BATTERY
BODY DAMAGE ACCIDENT

2 9IP; 9IP
1 LIGHT; LIGHT MARKER LED RED
2 LIGHT; PIGTAIL LED MARKER LIGHTS
2 BATTERY; BXT65750 BATTERY
2 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY

Service Requests:

12/17/2016 SERVICE REQUEST / 44: WORN / TIRES REPLACED ON ANOTHER REPAIR ORDER.

12/19/2016 SERVICE REQUEST / 43: WEAK / PREFORMED BATTERY, CHARGING, AND STARTING DIAGNOSTI

CSHOP-2016-786

Date Opened: 2-19-2016

Date Finished

3-10-2016

Meter 1 Reading:

89,121

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

Service Requests:

02/18/2016 A/C / 49: CAN NOT DUPLICATE CONCERN / DUPLICATE SERVICE REQUEST. REPAIR PREFORME
FAN SELECTOR NOT WORKING. DOES NOT BLOW ANY AIR ON FIRST FEW LEVELS

CSHOP-2016-93

Comments: **MINI PUMPER A/C BLOWER ISSUE**

Date Opened: 1-7-2016

Date Finished

3-1-2016

Meter 1 Reading:

89,011

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SHIFTER CONTROLS-SELECTOR
BLOWER RESISTER

1 BLOWER; BLOWER MOTOR
1 NEWPART; CONNECTOR BLOWER RESISTER F550
1 BLOWER; BLOWER WHEEL
1 NONSTOCK; RESISTOR ASY
1 SWITCH; BLOWER SWITCH

Service Requests:

01/07/2016 A/C / 27: OVERHEATED / A/C BLOWER NOT OPERATIONAL ON FIRST 2 SPEEDS AND BLOWER MC
LEVELS 1 AND 2 OUT OF 4 FOR FAN SPEED NOT WORKING. SM5890

Asset Work Order History K11078

CSHOP-2017-1164

Comments: **FUEL LEAK RED BRAKE WARNING LAMP ON**

Date Opened: 2-24-2017 Date Finished 4-21-2017 Meter 1 Reading: 97,592

TASKS PERFORMED

Q PARTS

WATER TANK LEVEL LIGHTS	-4	5TN; 5TN
SCBA BRACKETS	4	5TN; 5TN
FUEL SYSTEM	1	2FR; 300 FRC WATER GAUGE
STROBE LIGHTS	1	2FR; FRC BEZEL BLUE
	1	FIL; NAPAGOLD FUEL FILTER
	5	LIGHT; 600 SERIES RED LED W/O FLANGE

CSHOP-2017-1166

Date Opened: 2-24-2017 Date Finished 2-24-2017 Meter 1 Reading: 96,458

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2017-1280

Date Opened: 3-2-2017 Date Finished 4-27-2017 Meter 1 Reading: 97,723

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER LIGHTING SYSTEM	1	5EF; ON/OFF ROCKER SWITCH 6P
	1	1FD; BRAKE SWITCH
	1	5EF; ROCKER SWITCH COVER RED

Service Requests:

03/01/2017 ALARMS / 19: NO EMERGENCY LIGHTING. INSPECTED AND FOUND WIRES PULLED OUT OF MAS ALARM SIGNALS LIGHT BAR STROBES DO NOT OPERATE

CSHOP-2017-1924

Date Opened: 3-31-2017 Date Finished 5-8-2017 Meter 1 Reading: 97,267

TASKS PERFORMED

NO PARTS USED

STEERING

VENDOR? AL PACKER

Service Requests:

03/31/2017 SERVICE REQUEST / 12: PREFORMED INSPECTION. FOUND ALTERNATOR PULLEY SHAFT NUT M AC CLUTCH BEARINGS SOUND ABNORMAL

03/31/2017 STEERING / 19: FOUND STEERING LOOSE. / SENT TO DEALER FOR REPAIRS. ESCORT 1 STEERING IS OUT OF ALIGNMENT AND THERE IS EXCESSIVE PLAY OVER 30 MPH.

Asset Work Order History K11078

CSHOP-2017-1946

Comments: **K11078 MINI PUMPER**

Date Opened: 4-3-2017 Date Finished 4-5-2017 Meter 1 Reading: 97,241

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SERPENTINE BELT

1 9AP; BELT

Service Requests:

04/03/2017 BRAKES / 12: FOUND LOWER ALTERNATOR PULLEY NUT MISSING, PULLEY FALLING OFF, AND AI
BRAKE ISSUES, SERPENTINE BELT CAME OFF, DON'T KNOW IF ONE OF THE PULLEYS IS BROKEN. THERE IS NO
BREAKS OR POWER STEERING

CSHOP-2017-2670

Date Opened: 5-8-2017 Date Finished 5-9-2017 Meter 1 Reading: 97,962

TASKS PERFORMED

NO PARTS USED

THROTTLE CONTROLS

Service Requests:

05/07/2017 ENGINE / 38: SHORTED / VERIFIED CONCERN. NO THROTTLE IN THE CAB. PULLED ECM CODES
ENGINE - NO THROTTLE

CSHOP-2017-2903

Comments: **FUSE BLOWING FOR THROTTLE**

Date Opened: 5-16-2017 Date Finished 5-18-2017 Meter 1 Reading: 98,039

TASKS PERFORMED

NO PARTS USED

THROTTLE CONTROLS

CSHOP-2017-3447

Date Opened: 6-12-2017 Date Finished 9-18-2017 Meter 1 Reading: 99,776

TASKS PERFORMED

NO PARTS USED

COMMERCIAL WORK - OUTSIDE AGENCY

VENDOR? REGANS SMALL ENGINE SERVICE

CSHOP-2017-346

Comments: **K11078**

Date Opened: 1-17-2017 Date Finished 2-3-2017 Meter 1 Reading: 95,984

TASKS PERFORMED

Q PARTS

OIL 1 9IP; MOTOR OIL

Service Requests:

01/17/2017 OIL / 17: INSUFFICIENT LUBRICANT / CHECKED OIL LEVEL. ADDED 1 QUART TO BRING TO THE FI
2 QTS. OF OIL ADDED

Asset Work Order History K11078

CSHOP-2017-434

Comments: **MINI PUMPER AT AIRPORT PUMP WONT ENGAGE**

Date Opened: 1-19-2017 Date Finished 1-30-2017 Meter 1 Reading: 95,968

TASKS PERFORMED

NO PARTS USED

FIRE PUMP CONTROLS

Service Requests:

01/19/2017 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / SPOKE WITH ARFF CAPTAIN ABOUT C
PUMP WILL NOT ENGAGE.

CSHOP-2017-5416

Date Opened: 9-18-2017 Date Finished 12-14-2017 Meter 1 Reading: 100,566

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE FIGHTING EQUIPMENT -1 1FD; ALTERNATOR
DISCHARGE GAUGE 1 1FD; ALTERNATOR
CRANKING SYSTEM 1 9AP; 9AP

Service Requests:

06/10/2017 SERVICE REQUEST / 12: BROKEN / VERIFIED CONCERN. DISPLAY DIGITS VERY HARD TO READ /
PUMP DISCHARGE GAUGE BROKEN

09/17/2017 STARTER / 38: SHORTED / VERIFIED CONCERN. PREFORMED DIAGNOSTICS. FOUND CHARGING
VEHICLE WILL NOT START, UNLESS JUMP STARTED USING JUMPER CABLES. LIKELY BAD ALTERNATOR. BATTERIES
ARE "NEW" DATED 12/20116

11/01/2017 LIGHTS / 49: CAN NOT DUPLICATE CONCERN / INSPECT. NO WORK PREFORMED.
EXTERIOR COMPARTMENT LIGHTS NOW WORKING.

CSHOP-2017-5920

Date Opened: 10-13-2017 Date Finished 10-16-2017 Meter 1 Reading: 100,106

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER 1 TWD; SWROTMAS DISC2POSLEV
CRANKING SYSTEM

Service Requests:

10/13/2017 SERVICE REQUEST / 38: SHORTED / VERIFIED CONCERN. PREFORMED DIAGNOSTICS. FOUND S
BATTERY SWITCH INOPERABLE. TRUCK BATTERY POWER REMAINS ON WITH THE SWITCH TURNED OFF.

CSHOP-2017-6008

Date Opened: 10-18-2017 Date Finished 10-18-2017 Meter 1 Reading: 100,106

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

Asset Work Order History K11078

CSHOP-2017-625

Comments: **AIRPORT MINI PUMPER NOT WORKING.**

Date Opened: 1-30-2017 Date Finished 3-1-2017 Meter 1 Reading: 96,458

TASKS PERFORMED

Q PARTS

TIRES & WHEELS

1 NOE; WHEEL NUT

Service Requests:

01/29/2017 TIRES / 29: PART OMITTED / INSTALLED 2 LUGNUTS
RIGHT FRONT WHEEL MISSING A LUG NUT.

01/29/2017 ENGINE / 49: CAN NOT DUPLICATE CONCERN / DUPLICATE CONCERN. INSPECTED ON ANOTHEF
ENGINE PUMP IS NOT WORKING.

CSHOP-2017-6520

Date Opened: 11-13-2017 Date Finished 12-14-2017 Meter 1 Reading: 100,566

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
ALARM-BUZZER-WARNING LIGHT

1 9IP; BACKUP ALARM ECCO 107 DEC

Service Requests:

11/13/2017 ALARMS / 12: BROKEN / VERIFIED CONCERN. PREFORMED DIAGNOSTICS. POWER AND GROUND
ALARM SIGNALS, BACK UP WARNING ALARM IS NOT WORKING

CSHOP-2017-665

Date Opened: 1-31-2017 Date Finished 2-3-2017 Meter 1 Reading: 96,087

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 SWITCH; 55014 SWITCH
1 SWITCH; 82-2106 TOGGLE GUARD
1 AVB; AVB

Service Requests:

01/31/2017 LIGHTS / 12: BROKEN / PREFORMED INSPECTION AND DIAGNOSTICS. FOUND RIGHT HEADLAMP
VEHICLE LIGHTS NOT WORKING, PUMP WATER LEVEL GAGE NOT WORKING

Asset Work Order History K11078

CSHOP-2017-735

Date Opened: 2-4-2017 Date Finished 2-13-2017 Meter 1 Reading: 96,143

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

02/04/2017 TIRES / 44: WORN / EXCHANGE - NEW
NAIL IN REAR PASSENGER SIDE

02/04/2017 TIRES / 44: WORN / EXCHANGE - NEW
BAD TIRES

CSHOP-2018-1296

Date Opened: 3-5-2018 Date Finished 3-13-2018 Meter 1 Reading: 101,269

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE FIGHTING EQUIPMENT

1 BK; FUSE HOLDER

Service Requests:

03/03/2018 SERVICE REQUEST / 29: PART OMITTED / INSTALLED 4 GAS CHARGER. FABRICATED HARNESSE
NEED CHARGER MOUNTED IN VEHICLE FOR DRAGER A-AM 2500 GAS METER

CSHOP-2018-171

Date Opened: 1-9-2018 Date Finished 2-13-2018 Meter 1 Reading: 100,861

TASKS PERFORMED

Q PARTS

CAB-INTERIOR ACCESSORIES

1 LMP; BULB
1 1FD; IGNITION SWITCH

Service Requests:

01/09/2018 SERVICE REQUEST / 12: BROKEN / VERIFIED NO DOME LIGHT, BUT COULD NOT DUPLICATE POV

CSHOP-2018-2881

Comments: **HOURLY METER INOP**

Date Opened: 5-24-2018 Date Finished 5-31-2018 Meter 1 Reading: 101,810

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
STEERING
CHECK ENGINE LIGHT

12 9IP; ATF DETRAN 3
1 8GR; 8GR

Service Requests:

05/24/2018 ENGINE / 17: INSUFFICIENT LUBRICANT / PREFORMED INSPECTION AND TEST DRIVE. FOUND P
ENGINE, POWER STEERING FLUID LOW,PUMP WHINING, NO P/S FLUID IN STATION.

Asset Work Order History K11078

CSHOP-2018-3150

Date Opened: 6-6-2018 Date Finished 6-21-2018 Meter 1 Reading: 101,810

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

06/05/2018 TIRES / 19: LOOSE / EXCHANGE - NEW
BAD TIRES CALLAGHAN TIRE WAS OUT TO REPLACE ONE TIRE DUE TO A BOLT AND HE STATES ALL OTHER 5 NEED REPLACEMENTS. NO TREAD LEFT AND DUE FOR NEW ONES

CSHOP-2018-3876

Date Opened: 7-9-2018 Date Finished 7-9-2018 Meter 1 Reading: 101,810

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2018-3979

Date Opened: 7-14-2018 Date Finished 7-14-2018 Meter 1 Reading: 102,012

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

CSHOP-2018-4286

Date Opened: 7-31-2018 Date Finished 8-27-2018 Meter 1 Reading: 102,124

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
WINDOW ELECTRIC MOTOR

Service Requests:

07/31/2018 SERVICE REQUEST / 12: BROKEN / REPAIR
TYPE PROBLEM INTO DESCRIPTION FUSE IS BLOWN FOR POWER WINDOWS. ONE IS STUCK UP, ONE DOWN.
PRESSURE AND VACUUM GAUGE HAS BEEN MISSING FOR A YEAR!

CSHOP-2018-4321

Date Opened: 8-1-2018 Date Finished 8-1-2018 Meter 1 Reading: 102,124

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

Asset Work Order History K11078

CSHOP-2018-4662

Date Opened: 8-20-2018 Date Finished 9-5-2018 Meter 1 Reading: 102,227

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
WINDOW ELECTRIC MOTOR

1 NCB; PL EPOXY SYRINGE 25ML
1 9AP; DASH CLUSTER REPAIR

Service Requests:

08/19/2018 SERVICE REQUEST / 12: BROKEN / VERIFIED CONCERN. PREFORMED DIAGNOSTICS. UNABLE T
RADIO AND WINDOW SWITCHES ARE NOT WORKING

CSHOP-2018-484

Date Opened: 1-22-2018 Date Finished 1-22-2018 Meter 1 Reading: 100,850

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2018-5152

Date Opened: 9-11-2018 Date Finished 9-13-2018 Meter 1 Reading: 102,291

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP PLUMBING

1 5SC; THREADED TRUNNION 2"
1 NONSTOCK; FREIGHT CHARGE
1 5AB; BALL VALVE KIT 2IN SS

Service Requests:

09/10/2018 SERVICE REQUEST / 12: BROKEN / PREFORMED DIAGNOSTICS. WATER WOULD NOT FLOW FRO
CANT FLOW WATER OUT OF PRECONNECT NUMBER 2. PRECONNECT NUMBER ONE WORKS.

CSHOP-2018-5154

Date Opened: 9-11-2018 Date Finished 9-11-2018 Meter 1 Reading: 102,291

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
CRANKING SYSTEM

2 1AD; 65 SERIES BATTERY

Service Requests:

09/11/2018 ENGINE / 43: WEAK / VERIFIED CONCERN. VERIFIED SHORE CHARGER OPERATION. CHARGED I
STARTED OUT BEING HARD TO START LAST NIGHT. NOW IT WILL NOT START THIS MORNING.

Asset Work Order History K11078

CSHOP-2018-5627

Date Opened: 10-3-2018 Date Finished 10-18-2018 Meter 1 Reading: 102,300

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
STEERING

Service Requests:

10/02/2018 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / PREFORMED INSPECTION. POWER S
LOW POWER STEERING FLUID

CSHOP-2018-6073

Date Opened: 10-25-2018 Date Finished 10-25-2018 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

FIRE FIGHTING EQUIPMENT

VENDOR? REGANS SMALL ENGINE SERVICE

Service Requests:

10/24/2018 FUEL / 12: BROKEN / N
HAZARDOUS ISSUE : HYDRAULIC ENG FOR HURST TOOLS IS OOS. IT WAS PASSED DOWN TO ME BY THE PERSON I
RELIEVED, THAT THE SHOP WAS ALREADY CONTACTED AND THAT THEY WERE INSTRUCTED TO REPORT THIS ITEM
IN THIS SECTION OF ASSET WORKS.

CSHOP-2018-6130

Date Opened: 10-29-2018 Date Finished 6-3-2019 Meter 1 Reading: 107,668

TASKS PERFORMED

NO PARTS USED

STEERING

Service Requests:

10/26/2018 STEERING / 49: CAN NOT DUPLICATE CONCERN / PREFORMED A TEST DRIVE AND VISUAL INSPE
STEERING/ALIGNMENT THERE IS LOTS OF PLAY IN THE STEERING WHEEL. AT MODERATE SPEEDS IT REQUIRES A
LOT OF CORRECTION

CSHOP-2018-928

Date Opened: 2-12-2018 Date Finished 3-6-2018 Meter 1 Reading: 101,187

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HOSES-LINES & FITTINGS

1 1FD; TUBE
2 1FD; O-RING

Service Requests:

02/11/2018 A/C / 18: LEAKING / VERIFIED CONCERN. PREFORMED A/C PERFORMANCE AND LEAK TESTS. FC
A/C BLOWS WARM AIR.

Asset Work Order History K11078

CSHOP-2019-105

Date Opened: 1-7-2019 Date Finished 1-8-2019 Meter 1 Reading: 104,523

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SERPENTINE BELT

1 1FD; ALTERNATOR
1 1FD; BELT

Service Requests:

01/06/2019 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
SERPENTINE BELT WAS THROWN

CSHOP-2019-1229

Date Opened: 3-7-2019 Date Finished 3-13-2019 Meter 1 Reading: 105,691

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SERPENTINE BELT TENSIONER
SERPENTINE BELT

1 6PH; TENSIONER
1 6PH; DETAIL WAX
1 6PH; BELT
1 6PH; RETRACTABLE

Service Requests:

03/07/2019 SERVICE REQUEST / 12: BROKEN / REPLACED
MAIN BELT IS OFF

CSHOP-2019-1400

Date Opened: 3-15-2019 Date Finished 3-19-2019 Meter 1 Reading: 102,600

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BRAKES

Service Requests:

03/15/2019 BRAKES / 49: CAN NOT DUPLICATE CONCERN / INSPECT
BRAKE ISSUES, ABS LIGHT ON AND BRAKES MAKING SQUEAKING SOUNDS

CSHOP-2019-1424

Date Opened: 3-18-2019 Date Finished 3-22-2019 Meter 1 Reading: 102,600

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
OIL
TIRES & WHEELS

Service Requests:

03/17/2019 ENGINE / 18: LEAKING / TOPPED OFF FLUID LEVEL
ENGINE-1-POWER STEERING FLUID LOW NONE IN STATION. 2-TWO QUARTS ENGINE OIL ADDED.

03/17/2019 SERVICE REQUEST / 33: REGISTERS WRONG / TIC REPLACED WITH FLIR ON ANOTHER TICKET ;
TIC ON ESCORT 1 NEEDS THE SCREEN REPLACED. THE CORNERS ARE STARTING FORM A FILM. ONCE THE FILM IS
PRESSED IT GOES AWAY, BUT RETURNS. ASSET NUMBER #11729 FOR MSA TIC

Asset Work Order History K11078

CSHOP-2019-1466

Comments: **INSTALL FLIR TIC RETURN OLD TIC TO ANGEL**

Date Opened: 3-19-2019 Date Finished 3-20-2019 Meter 1 Reading: 102,600

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE FIGHTING EQUIPMENT

CSHOP-2019-1989

Date Opened: 4-17-2019 Date Finished 4-17-2019 Meter 1 Reading: 106,662

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
GLASS

1 1FD; WINDOWREGULATOR

Service Requests:

04/17/2019 WINDOW / 12: BROKEN / VERIFIED CONCERN. DISASSEMBLED DRIVER`S DOOR TO DIAGNOSE. I
DRIVERS SIDE DOOR WINDOW DOES NOT FULLY CLOSE. APPEARS THE WINDOW HAS SLID OFF OF THE INTERNAL
WINDOW TRACK.

CSHOP-2019-2529

Date Opened: 5-14-2019 Date Finished 5-15-2019 Meter 1 Reading: 107,208

TASKS PERFORMED

Q PARTS

CRANKING SYSTEM

2 1AD; 65 SERIES BATTERY

Service Requests:

05/13/2019 STARTER / 38: SHORTED / VERIFIED CONCERN. PREFORMED DIAGNOSTICS. FOUND POWER CC
VEHICLE WILL NOT START

CSHOP-2019-3456

Date Opened: 7-3-2019 Date Finished 7-3-2019 Meter 1 Reading: 108,318

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
COMPARTMENT LIGHT BODY
STEP
PARK-CLEARANCE LIGHTS
LIGHT BAR

2 LMP; LAMP
2 LMP; LAMP, RO BLISTER PK
3 LIT; LED M C LAMP
1 LIT; LED M C LAMP
1 1WL; LINEAR STROBE
2 LIT; LED FITN FORGET PLG

CSHOP-2019-3827

Comments: **DUPLICATE**

Date Opened: 7-23-2019 Date Finished 1-4-2020 Meter 1 Reading: 108,294

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

Asset Work Order History K11078

CSHOP-2019-3840

Date Opened: 7-24-2019 Date Finished 7-24-2019 Meter 1 Reading: 108,294

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2019-4256

Comments: **REMOVE DIGITAL INTAKE AND DISCHARGE GAUGES FROM SPARE GOING TO SURPLUS (10155560) TO ESC-1. TO BE INSTALLED AT THE NEXT SERVICE INTERVAL.**

Date Opened: 8-14-2019 Date Finished 5-13-2020 Meter 1 Reading: 112,260

TASKS PERFORMED

Q PARTS

DISCHARGE GAUGE
MIRRORS

1 1FD; SWITCH MIRROR CONTROL

Service Requests:

09/06/2019 MIRROR / 12: BROKEN / REPLACED FAILED DOOR MIRROR CONTROL SWITCH.
MIRROR ISSUE....BUTTON TO ADJUST MIRROR IS OFF

CSHOP-2019-5062

Date Opened: 9-25-2019 Date Finished 12-23-2019 Meter 1 Reading: 108,370

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES
PARK-CLEARANCE LIGHTS

1 LMP; LAMP

Service Requests:

09/25/2019 SERVICE REQUEST / 12: BROKEN / REPLACED BURNED OUT BULB
SECOND FROM THE RIGHT TOP CLEARANCE LIGHT IS OUT ON ESCORT 1

09/25/2019 SERVICE REQUEST / 18: LEAKING / PREFORMED VISUAL INSPECTION AND CHECKED OIL LEVEL
OIL LEAK, CHECKED OIL AND LEVELS ARE GOOD

CSHOP-2019-559

Date Opened: 1-29-2019 Date Finished 2-7-2019 Meter 1 Reading: 102,300

TASKS PERFORMED

Q PARTS

OIL

24 NOL; NAPA QT 15W40

Service Requests:

01/28/2019 OIL / 17: INSUFFICIENT LUBRICANT / BROUGHT 2 CASES OF OIL TO STATION 81.
LOW ENGINE OIL.. WE HAVE NO SPARE OIL IN STATION

Asset Work Order History K11078

CSHOP-2019-5866

Date Opened: 11-8-2019 Date Finished 12-23-2019 Meter 1 Reading: 108,370

TASKS PERFORMED

NO PARTS USED

FIRE PUMP

Service Requests:

11/06/2019 SERVICE REQUEST / 11: BINDS/STICKS / DUPLICATE REQUEST. REPAIRS MADE ON RO# 2019-58
PUMP SWITCH ON CENTER CONSOLE, IN THE CAB DOESN'T ENGAGE THE PUMP. IT GOES IN MANUALLY AND AFTER
THE MANUAL MODE HAS BEEN WORKED. MAY HAVE AN ISSUE AT MANUAL SETTINGS AFTER DRIVEN OVER ROUGH
TERRAIN AND IT DISENGAGES????????? JUST GUESSING

CSHOP-2019-5889

Date Opened: 11-12-2019 Date Finished 11-18-2019 Meter 1 Reading: 108,355

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP

Service Requests:

11/10/2019 SERVICE REQUEST / 11: BINDS/STICKS / LUBBED
ESCORT 1 WILL NOT GO INTO PUMP GEAR.

CSHOP-2019-6028

Date Opened: 11-18-2019 Date Finished 11-22-2019 Meter 1 Reading: 108,355

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
BATTERY
ALTERNATOR-GENERATOR

1 6KU; AC2000 12V PLC TEN 8
2 1AD; BATTERY GROUP 65

Service Requests:

11/18/2019 STARTER / 44: WORN / REPLACED
VEHICLE WILL NOT START

CSHOP-2019-6131

Comments: **ELECTRICAL POWER UP AND DOWN ON VOLTAGE**

Date Opened: 11-23-2019 Date Finished 1-10-2020 Meter 1 Reading: 111,954

TASKS PERFORMED

Q PARTS

ELECTRICAL

1 1FD; PIG TAIL ALT

Asset Work Order History K11078

CSHOP-2019-6698

Date Opened: 12-30-2019 Date Finished 12-31-2019 Meter 1 Reading: 111,954

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
RADIO

Service Requests:

12/28/2019 ELECTRICAL / 49: CAN NOT DUPLICATE CONCERN / PREFORMED INSPECTION. COULD NOT FINI
ELECTRICAL SHORTAGE PROBLEM RADIO TURNING ON AND OFF .POSSIBLE HIGH VOLTAGE DUE TO SHORT

CSHOP-2020-1905

Date Opened: 4-8-2020 Date Finished 4-13-2020 Meter 1 Reading: 112,260

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

04/06/2020 TIRES / 18: LEAKING / EXCHANGE - NEW
BAD TIRES-LOW TIRE DEPTHS ON THE REAR TIRES. WORSE ON THE LEFT FOR ESCORT 1

CSHOP-2020-2556

Date Opened: 5-13-2020 Date Finished 5-13-2020 Meter 1 Reading: 112,260

TASKS PERFORMED

NO PARTS USED

SMALL ENGINE REPAIR

Service Requests:

05/13/2020 SERVICE REQUEST / 35: RUSTED/CORRODED / FOUND CARB BOWL CORRODED. CLEANED BOV
FRNA035 POWER UNIT WILL NOT START AND TOOLS ARE OOS.

CSHOP-2020-3753

Date Opened: 7-20-2020 Date Finished 8-7-2020 Meter 1 Reading: 115,774

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BATTERY

Service Requests:

07/17/2020 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / SPOKE WITH CURRENT SHIFT DRIVEI
NEED A NEW BATTERY- DOES NOT STAY ON

Asset Work Order History K11078

CSHOP-2020-3774

Date Opened: 7-21-2020 Date Finished 8-4-2020 Meter 1 Reading: 115,774

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

Service Requests:

07/20/2020 LIGHTS / 49: CAN NOT DUPLICATE CONCERN / CHECKED THE ENTIRE LIGHTING SYSTEM ON TH
FRONT RIGHT HAZARD LIGHT IS NOT FLASHING

CSHOP-2020-5177

Date Opened: 10-2-2020 Date Finished 10-19-2020 Meter 1 Reading: 117,119

TASKS PERFORMED

NO PARTS USED

REPAIR FROM PM - PUMP PANEL CONTROLS

Service Requests:

10/02/2020 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / ATTEMPTED TO VERIFY CONCERN B)
PUMP PRESSURE FLUCTUATES AND PRESSURE PSI GAUGES EITHER ARE NOT WORKING ON SOME AND OTHER
DROP OFF IN PSI.

CSHOP-2020-53

Date Opened: 1-5-2020 Date Finished 1-9-2020 Meter 1 Reading: 112,072

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES

1 1FD; PIG TAIL ALTERNATOR
1 1FD; ALTERNATOR
1 1FD; BELT

Service Requests:

01/05/2020 ENGINE / 12: BROKEN / REPLACED
ENGINE ENGINE IS VERY NOISY WITH A BURNING ODOR

CSHOP-2020-5327

Date Opened: 10-9-2020 Date Finished 10-14-2020 Meter 1 Reading: 115,810

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SERPENTINE BELT

1 1FD; BELT
1 1FD; PULLEY SMOOTH

Asset Work Order History K11078

CSHOP-2020-5342

Date Opened: 10-10-2020 Date Finished 10-16-2020 Meter 1 Reading: 117,119

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP PLUMBING

Service Requests:

10/10/2020 SERVICE REQUEST / 18: LEAKING / VERIFIED CONCERN. PREFORMED DIAGNOSTICS. FOUND A
LEAKING STEADY WATER FLOW WHEN TANK TO PUMP IS OPEN AND IT LEAKS WHEN GOING OUT OF PUMP AND THE
TRUCK IN NEUTRAL.

CSHOP-2020-5448

Date Opened: 10-15-2020 Date Finished 10-16-2020 Meter 1 Reading: 117,119

TASKS PERFORMED

NO PARTS USED

CRANKING SYSTEM

Service Requests:

10/15/2020 STARTER / 43: WEAK / VERIFIED CONCERN. ON-BOARD BATTERY CHARGER NOT CHARGING. CH
VEHICLE WILL NOT START

CSHOP-2020-590

Date Opened: 2-3-2020 Date Finished 2-3-2020 Meter 1 Reading: 112,136

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2020-6235

Date Opened: 11-30-2020 Date Finished 12-21-2020 Meter 1 Reading: 117,130

TASKS PERFORMED

Q PARTS

BATTERY

2 1AD; BATTERY GROUP 65

Service Requests:

11/29/2020 SERVICE REQUEST / 43: WEAK / VERIFIED CONCERN. BATTERIES FAILED LOAD TESTS. REPLAC
TYPE PROBLEM INTO DESCRIPTION BATTERY ISSUES -- NEEDING A JUMP IF LEFT OUT ON APRON

Asset Work Order History K11078

CSHOP-2020-6371

Date Opened: 12-7-2020 Date Finished 12-21-2020 Meter 1 Reading: 117,130

TASKS PERFORMED

NO PARTS USED

HANDLIGHT

Service Requests:

12/03/2020 SERVICE REQUEST / 12: BROKEN / VERIFIED CONCERN. PREFORMED DIAGNOSTICS. FOUND OI
HAND LIGHT CHARGER NOT WORKING

12/05/2020 STARTER / 43: WEAK / REPAIR MADE ON RO# 2020-6235
VEHICLE WILL NOT START BATTERY WILL NOT HOLD ITS CHARGE

CSHOP-2020-743

Date Opened: 2-10-2020 Date Finished 4-15-2020 Meter 1 Reading: 112,260

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

02/09/2020 SERVICE REQUEST / 18: LEAKING / PREFORMED INSPECTION. CLASS 3 NOTICED. SPOKE WITH
OIL LEAK ON ESCORT 1. LEVELS ARE GOOD, BUT A BAD LEAK

CSHOP-2021-130

Comments: **INSPECT AT STATION**

Date Opened: 1-8-2021 Date Finished 1-14-2021 Meter 1 Reading: 118,731

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

CSHOP-2021-135

Comments: **LUBE OIL FILTER AND PM FOLLOW UPS REPLACE FRONT BRAKE PADS ASAP ALMOST AT ROTOR REPLACE WIPERS
CK ENGINE OIL LEAKS TRANS LINE LEAKING AT RAD CK TRANS LEAK KARL- TRUCK TO BE SURPLUSED. NO WORK
PREFORMED.**

Date Opened: 1-8-2021 Date Finished 3-29-2021 Meter 1 Reading: 118,868

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

CSHOP-2021-739

Date Opened: 2-9-2021 Date Finished 2-9-2021 Meter 1 Reading: 118,868

TASKS PERFORMED

NO PARTS USED

EQUIPMENT MOUNTING BRACKETS

Asset Work Order History K11078

RADIO-2020-832

Comments: **RUMPER GROUND RADIO**

Date Opened: 10-6-2020

Date Finished

10-6-2020

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

10/04/2020

RADIO / /

RADIO ISSUES, RECEIVER CAN NOT HEAR ES#1 ON THE GROUND RADIO
