



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V366

In Date: 10/21/2005
Close Date: 11/07/2005

Meter Reading:

Problem?

CHECK ENGINE LITE ON E-14

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V587

In Date: 11/15/2005
Close Date: 11/17/2005

Meter Reading:

Problem?

A INSPECTION E14

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V640

In Date: 11/21/2005
Close Date: 11/22/2005

Meter Reading: 18,915.00

Problem?

PUMP PANEL THROTTLE INOP, E-14

Task performed:

Parts

Quantity

55790-135000008 ELECTRONIC THROTTLE 100076 FELS

1

Workorder: V900

In Date: 12/13/2005
Close Date: 12/14/2005

Meter Reading:

Problem?

AIR HORN INOP, E-14

Task performed:

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V1045

In Date: 12/28/2005
Close Date: 01/05/2006

Meter Reading:

Problem?

D/SIDE SPOT LIGHT INOP, E-14

Task performed:

Parts	Quantity
4435HEADLIGHT	1
LB-D30BULB QUARTZ HAL. 12V 150W	1

Workorder: V1140

In Date: 01/09/2006
Close Date: 01/20/2006

Meter Reading:

Problem?

D/SIDE SCENE LIGHT INOP, E-14

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V1201

In Date: 01/17/2006
Close Date: 01/23/2006

Meter Reading:

Problem?

THOTTLE PROBLEM E14

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V1212

In Date: 01/18/2006
Close Date: 01/24/2006

Meter Reading:

Problem?

DECK GUN VALVE LEAKING, E-14

Task performed:

Parts	Quantity
NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V1396

In Date: 02/03/2006
Close Date: 02/08/2006

Meter Reading: 20,412.00

Problem?

QUARTZ LITE INOP, E-14

Task performed:

Parts	Quantity
LB-D30BULB QUARTZ HAL. 12V 150W	2

Workorder: V2030

In Date: 03/29/2006
Close Date: 04/04/2006

Meter Reading:

Problem?

FAILED VACUM TEST, E-14

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V1924

In Date: 03/22/2006
Close Date: 04/06/2006

Meter Reading:

Problem?

REAR NUMBER PLATE FELL OFF OF TRUCK, E-14

Task performed:

Reinstall number plate

Parts	Quantity
NO PARTS USED	

Workorder: V2158

In Date: 04/10/2006
Close Date: 04/18/2006

Meter Reading:

Problem?

D/SIDE REAR SOPT LIGHT INOP, E-14

Task performed:

Parts	Quantity
44364436 BULB	3



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V2277

In Date: 04/18/2006

Meter Reading:

Close Date: 04/21/2006

Problem?

REAR SPOT LIGHT INOP, E-14

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1090

In Date: 01/03/2006

Meter Reading:

Close Date: 05/11/2006

Problem?

D/SIDE HALOGEN LIGHT INOP, E-14

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1727

In Date: 03/03/2006

Meter Reading:

Close Date: 05/11/2006

Problem?

float pump engine knocking E14 (outside agency repair) Regan's small engine service

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2602

In Date: 05/12/2006

Meter Reading:

Close Date: 05/16/2006

Problem?

extension scene litght innoperative E14

Task performed:

Parts

Quantity

LB-D30BULB QUARTZ HAL. 12V 150W

4



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V2722

In Date: 05/23/2006

Close Date: 06/12/2006

Meter Reading: 23,519.00

Problem?

B INSPECTION E-14

Task performed:

Parts

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

See B Inspection pre-printed form

01-06635060-C90PSC0CDCR STRIP LIGHT STEADY WHITE	1
038-1550-00VALVE CHECK HALE 1/4"	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
14-7014HGR-1 HELMET HOOK	1
300634040 AMP CIRCUIT BK RUBBERIZED 30063-40	2
30276RLIGHT KIT STANTION KIT 10276R LED 47222 GRO	2
35200-RLIGHT MARKER LED RED	3
372000030BATTERY ON DISPLAY	1
52-24WIPER BLADES ANCO 24	2
5462300020VALVE KIT SS VALVE 3 IN	1
5499FRE801910 REPAIR BRACKET A/C COMPRESSOR	1
55790-1350000008 ELECTRONIC THROTTLE 100076 FELS	1
6808300174VENT A/C RH	1
6809880678STUD DZ	1
6809940145CLIP	2
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
91513AMBER LENS	2
9440BELT	1
9480BELT	1
94862PIGTAIL LED MARKER LIGHTS	2
98032R 41032-3 RED REFLECTOR OVAL REFLECTOR	1
A0631087000CABLE BATT. POS.	1
A0631088000CABLE BATT. NEG.	1
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1
ACX-8453LUG CAPS WHEELED COACH # CH27321 OLD	2
B480AREFLECT-AMBER	1
CA8193AIR FILTER 46744 WIX	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
K080716BELT	1
R90PFILTER FUEL 33231	1
S775COUPLER	6
S777COUPLING NIPPLE	1

Vendor?: CENT0002



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V2932

In Date: 06/10/2006

Meter Reading:

Close Date: 06/13/2006

Problem?

Air horn not working properly. Spot light not working properly

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2421

In Date: 04/28/2006

Meter Reading:

Close Date: 06/23/2006

Problem?

REPAIR TRANSMISSION AT STA-14 E-14 (FLORIDA DETROIT- ALLISON)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: FLOR0311B

Workorder: V3140

In Date: 06/26/2006

Meter Reading:

Close Date: 07/06/2006

Problem?

status center 10-7 E 14

Task performed:

Parts

Quantity

101847ENGINE STATUS CTR

1

Workorder: V3607

In Date: 07/24/2006

Meter Reading:

Close Date: 07/27/2006

Problem?

Front A/C blowing warm air or fan doesn't blow at all.

Task performed:

Parts

Quantity

NO PARTS USED

0



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V3758

In Date: 08/03/2006

Meter Reading:

Close Date: 08/10/2006

Problem?

RELIEF VALVE NOT WORKING PROPERLY E14

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3886

In Date: 08/11/2006

Meter Reading:

Close Date: 08/18/2006

Problem?

right headlight is out, we have no bulbs. we can install light if you can get us one.

Task performed:

Parts

Quantity

H6054USE CV TYPE SEALED BEAM

2

Workorder: V4563

In Date: 09/23/2006

Meter Reading:

1,130.00

Close Date: 10/03/2006

Problem?

rt scene light 1of 2 bulbs burn't out, rt strobe between officer door and back door of cab not working. E14

Task performed:

Parts

Quantity

1. TRAVELED TO STN 14 REPLACED R SCENE LIGHT. TEST/OK

LB-D30BULB QUARTZ HAL. 12V 150W

1

2. LED FOR OFFICER DOOR ON ORDER.

Workorder: V4859

In Date: 10/11/2006

Meter Reading:

1,130.00

Close Date: 10/26/2006

Problem?

pressure relief valve light doesnt go off....valve seems to be working.. E-14

Task performed:

Parts

Quantity

1. TRAVELED TO STN 14. INSTALLED NEW SENDER, TEST/OK.

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V5061

In Date: 10/24/2006 Meter Reading: 1,130.00

Close Date: 10/30/2006

Problem?

low beam head light drivers side 10/7. high beam still works. E-14

Task performed:

Parts

Quantity

1. TRAVELED TO STN 14. R/R HED LIGHT, TEST/ OK.

NO PARTS USED

Workorder: V5137

In Date: 10/29/2006 Meter Reading: 1,130.00

Close Date: 11/08/2006

Problem?

spotlight not working E14

Task performed:

Parts

Quantity

1. TRAVELED TO STN 14. FOUND A BAD GROUND ON SPOT LIGHT. REPAIRED, TEST/ OK.

NO PARTS USED

Workorder: V5641

In Date: 12/02/2006 Meter Reading: 27,493.00

Close Date: 12/07/2006

Problem?

Hurst manifold leaking. out of service. need a new one. E14

Task performed:

Parts

Quantity

1. TRAVELED TO STN 14. PICK UP MANIFOLD AND BRING BACK TO SHOP.
2. TRAVELED TP STN 14. DROP OFF LOANER MANIFOLD.

NO PARTS USED

Workorder: V5989

In Date: 12/28/2006 Meter Reading: 1,019.00

Close Date: 01/03/2007

Problem?

E-6 failure code on intake gauge E14

Task performed:

Parts

Quantity

1. R&R intake sender and rear light

FP4000PT-1TRANSDUCER DISCHARGE DIG. MASTER PU 1

H50SN12BULB 2

IO3100PT-2XE-IO3100PT3-S0B 600 TRANSDUCER INT 1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V6269

In Date: 01/14/2007 Meter Reading: 1,091.00
Close Date: 01/25/2007

Problem?

pass.side,cab strobe(red)not working. E14

Task performed:

1. TRAVELED TO STN 14. R/R LED LIGHT. TEST/ OK.

Parts

40R00FCR400 SER CLEARANCE LITE

Quantity

1

Workorder: V6708

In Date: 02/12/2007 Meter Reading: 11,390.00
Close Date: 02/13/2007

Problem?

check eng lite on dash on 9:30 pm 2/11/07 E14

Task performed:

Drive to station wait for truck to come back from a call.
Code 115 sender bad. R&R
sender and test ok

Parts

4921597OUTBOARD SPEED SENSOR

Quantity

1

Workorder: V6985

In Date: 02/28/2007 Meter Reading: 1,130.00
Close Date: 03/06/2007

Problem?

e14/ pump panel eng. temp gauge not working / pump panel volt gauge 1 1/2 volts differant than cab volt gauge. t14

Task performed:

1. Drive to station clean connection and reprogram
engine status center. Tested ok

Parts

NO PARTS USED

Quantity

Workorder: V7098

In Date: 03/07/2007 Meter Reading: 30,189.00
Close Date: 03/09/2007

Problem?

deck gun alarm won't shut off E14 (At sta 18)

Task performed:

Replaced sender for deck gun

Parts

XG840-KITEXTENDA GUN SWITCH

Quantity

1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V6988

In Date: 02/28/2007

Close Date: 03/14/2007

Meter Reading: 1,130.00

Problem?

air leak t14

Task performed:

Repaired by Ferrara

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V7384

In Date: 03/26/2007

Meter Reading: 30,930.00

Close Date: 04/06/2007

Problem?

b inspection and repairs as needed E14

Task performed:

B-Inspection

1. Tighten induction hose clamp; replc rear A/C filter; tighten btry switch; replc oil plug & gasket.
2. Replc btrys; clean: term, cables, btry box & holddown; Add wtr to new btrys, protect term; test btrys.
3. Chngc Chief Baker's L. rear tire; isntall; rem wheel in in spare veh
4. Change out 90W oil drum & diesel can for filters; rep grease gun hose reel stop; rep air water separator for coolant drum.
5. Torque U-bolts.
6. Drill holes in pullout stop brkt; install 4" clmp to hold tail pipe; cutoff ends of clmp bolts; tighten exh to muffler clmp; tighten brkt to compt & add fender washers.
7. Lube door latches, tighten loose strkers; trim screws & holdopen shcks; rem L. rear Hurst tray & shock; rep track slides; install msng pin R. rear gen track slide.
8. Rebuld dryer & purge valave
9. Svc rear axle.
10. Svc T-case.
11. Svc cooling sys; replc d reservoir sight glass; press chk, tighten hose clmps.
12. Rep cable end on foam pump for Eng 19; tighten backup nut.
13. Cut (8) cables to 30" length for fire fighters
14. Svc small eqmt; change oil in gen & Hurst power unit; replc spark plugs; drain fuel tanks, refill; add stabilizer; chk volt press & eng RPM; replc (2) Hurst hoses; tighten cutter hndle bolts; add Hurst fluid.
15. Dry vac test-fail; rebuild tank to pump tank fil;; & deck gun valve; replc chk valve twice; rebuild intake relief valve; primer pump; rebuild press relief valve & second primer vlave; replc foam hose; adj relief swtch.
16. R/R discharge cup chains.
17. Replc tail board mrkr lighte R. rear side & keep back light bulb.
18. Adj air horns

Parts	Quantity
0100080010STRAINER	2
042-0091-00SPRING PRIMER	2
042-0550-00SPRING-VALVE QG RELIEF VALVE	1
100R4FOAM HOSE AS PER SAMPLE	1
107796DRYER KIT AD9 -NEW	1
180R014HURST HYD. FLUID GAL	1
35200-RLIGHT MARKER LED RED	2
3530016HOSE HURST 16 ORANGE	2
3911638PLUG OIL DRAIN C	1
3920773WASHER DRAIN PLUG	1
5005037KIT MAINT. AD-9	1
538-1400-00QG VALVE	1
546-0200-50QD REL.VALVE KIT	1
546126000TPM/QG HALE REPAIR KIT	1
5462270020VALVE KIT SS 546-2270-02-0	1
5462300020VALVE KIT SS VALVE 3 IN	2
6535SPARK PLUG CR5HSB	1
78R536078R5360M 2PK FILTER AIR COND	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
BPR5ESSPARK PLUG 7734	2
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
PR338324070 WIX FILTER WATER	1
PVG-KITORING KIT	2
R90PFILTER FUEL 33231	1
VML-T1413T3248 SIGHT GLASS	1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V7481

In Date: 04/02/2007 Meter Reading: 30,930.00

Close Date: 04/12/2007

Problem?

REPLACE HOSE BED COVER E14 CENTRAL AUTO TRIM

Task performed:

Parts

Quantity

Replace hose bed cover E14 Central Auto Trim

NO PARTS USED

Vendor?: CENTRAL AUTO TRIM

Workorder: V8065

In Date: 05/03/2007 Meter Reading: 31,530.00

Close Date: 05/08/2007

Problem?

rocks in pump E14

Task performed:

Parts

Quantity

Back flush pump; test ok

NO PARTS USED

Workorder: V8355

In Date: 05/21/2007 Meter Reading: 31,809.00

Close Date: 06/05/2007

Problem?

CHECK AND REPAIR CHARGING SYSTEM E14

Task performed:

Parts

Quantity

1. drive to sta. tighten loose wires and cable. test ok

NO PARTS USED

Workorder: V8451

In Date: 05/28/2007 Meter Reading: 32,371.00

Close Date: 06/13/2007

Problem?

BRAKE RETARDER NOT WORKING E-14

Task performed:

Parts

Quantity

1. drive to sta, check connection, test drive OK

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V8534

In Date: 06/01/2007 Meter Reading: 107.70
Close Date: 06/28/2007

Problem?

pump dripping (relief check valve) e14

Task performed:

1. Drive to sta, installed rebuild primer. Primer bad, call shop let them know. Sent me to 73 for door open alarm
2. Went to station 14. Replaced bad primer and installed new primer

Parts	Quantity
2000071102000072100 SOLENOID HALE PRIMER	1
501-3090-00PRIMER PUMP MOTOR	2

Workorder: V9053

In Date: 06/28/2007 Meter Reading: 32,893.00
Close Date: 07/03/2007

Problem?

repair drain valve e14

Task performed:

1. DRIVE TO STATION. REPAIR DRAIN VALVE. TESTED-OK.

Parts	Quantity
NO PARTS USED	

Workorder: V9339

In Date: 07/16/2007 Meter Reading: 1,130.00
Close Date: 07/19/2007

Problem?

right head light 10-7 E14

Task performed:

1. SEE W.O. #9372.

Parts	Quantity
NO PARTS USED	

Workorder: V9372

In Date: 07/17/2007 Meter Reading: 33,420.00
Close Date: 07/19/2007

Problem?

REPLACE HEADLIGHT E14

Task performed:

1. DRIVE TO STA. R&R HEAD LIGHT. TEST-OK.

Parts	Quantity
H6054USE CV TYPE SEALED BEAM	1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V9796

In Date: 08/09/2007 Meter Reading: 33,889.00
Close Date: 08/13/2007

Problem?

repair broken mounts on hurst unit e14

Task performed:

repair/replace motor mounts on hurst tool, tested ok

Parts

Quantity

4626BPMR7A SPARK PLUG
BPR5ESSPARK PLUG 7734

1
1

Workorder: V9954

In Date: 08/16/2007 Meter Reading: 33,889.00
Close Date: 08/31/2007

Problem?

Hurst Generator leaking oil from a crack in the housing, Also leaking gas out of carb. e14

Task performed:

Drive to Stn; chk carb & adj; top of lid cracked

Parts

Quantity

NO PARTS USED

Workorder: V9985

In Date: 08/17/2007 Meter Reading: 33,889.00
Close Date: 09/18/2007

Problem?

repair hurst power unit E14 (outside agency-Regan's small engine service)

Task performed:

Repair Hurst power unit - Regans Small Engine

Parts

Quantity

NO PARTS USED

Vendor?: REGAN SMALL

Workorder: V10316

In Date: 09/10/2007 Meter Reading: 34,435.00
Close Date: 09/28/2007

Problem?

replace tires at sta 14 callaghan ent e14

Task performed:

REPLACEMENT TIRES

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN TIRE



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V10906

In Date: 10/09/2007
Close Date: 10/25/2007

Meter Reading: 34,856.00

Problem?

install crosslay nets e14

Task performed:

Parts

Quantity

1. drive to station. installed nets. had to redo crosslay to fit.

NO PARTS USED

Workorder: V11776

In Date: 11/27/2007
Close Date: 11/30/2007

Meter Reading: 35,873.00

Problem?

repair electrical problem e14

Task performed:

Parts

Quantity

Drive to Stn; chk all conn nodes; ground; FNP
j

NO PARTS USED

Workorder: V11558

In Date: 11/10/2007
Close Date: 12/04/2007

Meter Reading: 1,135.00

Problem?

Red strob light (back drivers side) is not flashing . R14

Task performed:

Parts

Quantity

1. Drive to stn; replc rear LED light; take dash apart; buzzer bd; did not have on truck; will install on 11/16/07
2. Drive to Stn; install new buzzer; test ok j

60R00FRR600 SERIES RED LED W/O FLANGE
M4099BUZZER 52-400

1
1

Workorder: V11888

In Date: 12/03/2007
Close Date: 12/05/2007

Meter Reading: 36,470.00

Problem?

check eng lt on e14

Task performed:

Parts

Quantity

Check eng light on; R/R cam sensor j

4921597OUTBOARD SPEED SENSOR

1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V10546

In Date: 09/19/2007

Meter Reading: 34,856.00

Close Date: 12/07/2007

Problem?

B inspection and repairs as needed E14 replace rt rear discharge with akron valve

Task performed:

Parts

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

1. b inspection on service truck.
2. jack up front end. remove tires and brake check for loose end or brush install tire. test drive.
3. clean and wash truck. get ready for on call.
4. r/r trans accumulator + rebuild
5. clean out and lube left side step compartment - not opening.
6. r/r right side cab lights inside
7. r/r rear pinsion seal. hold on new unit until 10:a.m.
8. r/r rear compartment shock on door.
9. service hurst tools and power unit.
10. service generator and check fan/lights
11. check ladder found heat sensor need replace by dec 07. no sensor in stock. replace later
12. r/r a/c filter in rear of cap
13. check all pump seal and gasket intake screen. lube and grease valve.
14. r/r right rear discharge valve. fit and modify linkage and valves hoses.
15. installed strap pn back of truck for cones.
16. repair hose bed cover strap.
17. repair vac valve back at check valve. gate valves repaired.
18. check pump and relief valve. need relief valve. rebuild.
19. work on computer. enter new password to work on computer.
20. repair vac leaks and pressure leaks in the fire pump. road test. found relief valve not working right.
21. r/r dump valve and rebuild dump valve and diaphragm to dump.
22. rebuild tank to pump valve. vac test. pump o.k.
23. meeting in break room after 2:30 break. went home at 4:00.
24. pump. check all valves for leaks. check relief valve for proper operation. back flush out tank and pump. sand in system
25. repair r side dome light. bolt tighten. remove and lube. o.k.
26. meeting in breakroom.
27. computer class on cummin, allison and v-max.
28. installed msa unit wire to power. move stream lights wire to power.
29. cpr class at shop.
30. repair wires on right rear stream light. wire short to ground blowing fuses. repair.
31. clean up.
32. b service
33. b service
34. installed all belts on engine.
35. r/r coolant fiter. add coolant and r/r radiator cap. pressure check.

0100080010STRAINER	3
038-1550-00VALVE CHECK HALE 1/4"	1
05-17223-000CAP RADIATOR 10 LB	1
100557SEAL OLD STYLE PINON	1
1160033 IN FLANGE ADPT W/ HOLES P2S	1
17211ZG98000AIR FILTER HONDA	1
180R002HURST HYD. FLUID QT	1
211-2BULB	1
2952271729552377 VALVE ASSY.ACCUM	1
29535973ACCUM.KIT	1
3530016HOSE HURST 16 ORANGE	1
538-1400-00QG VALVE	1
5460990500GASKET SEAL KIT P25/30	1
546126000TPM/QG HALE REPAIR KIT	1
5462300020VALVE KIT SS VALVE 3 IN	1
78R536078R5360M 2PK FILTER AIR COND	1
883088301201 3 IN SLO-CLOZ W/R1 HANDLE	1
9440BELT	1
9480BELT	1
BPR6ESSPARK PLUG 7131	1
EAA-8350-60UGSS6557UP STRUT-LIFT	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
K080716BELT	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
TDA/40X1233USE KIT2628 PINION SEAL NUT	1
UMVS162511STRAP	1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V12660

In Date: 01/17/2008
Close Date: 01/18/2008

Meter Reading: 37,294.00

Problem?

repair saw e14

Task performed:

Repair saw E14 - Regans Small Engine

j

Parts

NO PARTS USED

Quantity

Vendor?: REGANS SMALL ENG

Workorder: V12383

In Date: 01/06/2008
Close Date: 01/24/2008

Meter Reading: 381.00

Problem?

spot light not working. E22

Task performed:

1. Drive to Sta. Installed two lites and clean ground.
Test OK.

Parts

LB-D30BULB QUARTZ HAL. 12V 150W

Quantity

2

Workorder: V12294

In Date: 12/31/2007
Close Date: 02/04/2008

Meter Reading: 37,294.00

Problem?

repair ok to pump light e14

Task performed:

1. Installeed light in panel for OK to pump.

Parts

1893BULB

Quantity

1

Workorder: V10459

In Date: 09/15/2007
Close Date: 02/07/2008

Meter Reading: 1,134.00

Problem?

right rear discharge valve will not open while pump has pressure on it. will only open after pressure is released from pump and though preconnect #2 E14

Task performed:

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V13409

In Date: 02/21/2008
Close Date: 02/25/2008

Meter Reading: 38,711.00

Problem?

PRIMER MOTOR INOP, E-14

Task performed:

1. Drive to station, R & R solenoid (on primer motor), test OK

Parts

Quantity

2000071102000072100 SOLENOID HALE PRIMER

1

Workorder: V13468

In Date: 02/25/2008
Close Date: 02/27/2008

Meter Reading: 39,034.00

Problem?

pump and/or cooling system overheat E14 (on-call)

Task performed:

Drive to Stn14; chk pump; chk engine cooling sys; all working properly; return to svc. j

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V14355

In Date: 04/08/2008

Meter Reading: 39,519.00

Close Date: 04/24/2008

Problem?

B INSPECTION AND REPAIRS AS NEEDED E14

Task performed:

1. B INSPECTION
2. INSTALL MASTER POWER SWITCH IN FLOOR BOARD.
3. CUT FILTER SCREEN FROM EXPANDED ALUMRUM SHEET.
4. INSTALL R L.E.D. MARKER LIGHT
5. FREE UP BATTERY TRAY LATCHES FROM DIRT AND WBE
6. TIGHTEN EXHAUST CLAMP
7. TRANS SERVICE-FILTER AND FLUID
8. REMOUNT AND TIERAP WIREING ON REAR TAIL BOARD FOR MARKERS.
9. EXTEND ENGINE DRAFT TUBE AND CLEAN OIL ON PAN
- 10 REPLACE CHECK VALVE ON RELIEFE VALVE

Parts

Quantity

038-1550-00VALVE CHECK HALE 1/4"	1
14-7014HGR-1 HELMET HOOK	1
15W40BSYN OIL BULK QTS	24
29526898 29548988 TRANS FILTER ALLISON	1
35200-RLIGHT MARKER LED RED	1
3818885O-RING WATER SHUT OFF	2
3937367GASKET 4942874	1
39437394940547 SHAFT SHUT-OFF VALVE	1
3943740SHAFT SHUT-OFF VALVE	1
39438574989614 SEAL O-RING SHUT-OFF VALVE	1
39444543977737 SCREW SHUTOFF VALVE	1
6808200020LIGHT ASSY. TURN SIGNAL	1
75908SWITCH BATTERY MASTER 300A	1
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1

Workorder: V14483

In Date: 04/15/2008

Meter Reading: 39,519.00

Close Date: 04/30/2008

Problem?

REPLACE TIRES AT SHOP E 14

Task performed:

Replace tires E14 - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V14569

In Date: 04/20/2008
Close Date: 05/02/2008

Meter Reading: 515.00

Problem?

drain leaking small drip. E14

Task performed:

Parts

Quantity

1. Drive to station 14, back flush pump, inlet valve had trash in it, test - ok

NO PARTS USED

Workorder: V14852

In Date: 05/04/2008
Close Date: 06/02/2008

Meter Reading: 1,137.00

Problem?

top rear left running light burned out. E14

Task performed:

Parts

Quantity

Drive to stn; R/R/ light; test - ok. j

372000084MARKER LIGHT

1

Workorder: V13692

In Date: 03/05/2008
Close Date: 06/17/2008

Meter Reading: 39,034.00

Problem?

Station requests new chain saw E14

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V15951

In Date: 06/24/2008
Close Date: 07/17/2008

Meter Reading: 1,137.00

Problem?

One of the two rubber feet on the PPE Fan is broken off. Cannot find assest # on fan. Please send one to FS14 and we can put it on. Thanx E14

Task performed:

Parts

Quantity

drive to Stn; installed new feet on tool. j

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V16431

In Date: 07/18/2008

Meter Reading: 40,492.00

Close Date: 07/23/2008

Problem?

repair electrical problem e14

Task performed:

Parts

Quantity

Drive to Stn; fnd node 4 & 5 off line; rework power supply for nodes; test ok. j

NO PARTS USED

Workorder: V16795

In Date: 08/04/2008

Meter Reading: 2,391.60

Close Date: 08/07/2008

Problem?

E14's siren was not working last night. While responding to a call it would not work, only coming on twice for aprox. 1 second each time.

Task performed:

Parts

Quantity

1. drive to station loose connection in cntr console tighten, test = ok

NO PARTS USED

Workorder: V17199

In Date: 08/21/2008

Meter Reading: 2,391.60

Close Date: 08/28/2008

Problem?

Left front turn signal on fender of engine, the mount is broke. Light is still connected by wires but is dangling. E14

Task performed:

Parts

Quantity

Drive to Stn; installed new turn signal; test ok. j

6808200020LIGHT ASSY. TURN SIGNAL

1

Workorder: V18217

In Date: 10/08/2008

Meter Reading: 43,828.00

Close Date: 10/17/2008

Problem?

REPAIR SAW E14

Task performed:

Parts

Quantity

Repair saw E14 - Regans Small Eng j

NO PARTS USED

Vendor?: REGAN SMALL ENG



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V19273

In Date: 11/22/2008
Close Date: 11/26/2008

Meter Reading: 44,830.00

Problem?

relief valve not working ON CALL

Task performed:

drive to Stn14; fnd pump rel valv very slow & inaccurate; replcd pump line screen; ck other screen ok; ran & ck pump rel valve opn; ck ok; retruned to WPB. j

Parts

0100080010STRAINER

Quantity

1

Workorder: V19345

In Date: 11/25/2008
Close Date: 12/02/2008

Meter Reading: 792.00

Problem?

clear plastic glove box holder for rear of E14 cab is broke in multiple places, is unusable, needs replacement.

Task performed:

drive to stn; installed glove holder; driver advsd A/C inop; filled; chkd for leak; fnd in rear A/C evp; take apart; order parts. j

Parts

A0631087000CABLE BATT. POS.

A0631088000CABLE BATT. NEG.

Quantity

1

1

Workorder: V19403

In Date: 12/01/2008
Close Date: 12/16/2008

Meter Reading: 44,830.00

Problem?

a/c innop E14

Task performed:

drive to Stn; rem rear seal & A/C evap; install new; vac down; fill; test ok. j

Parts

76R7070EVAPORATOR RD2-1370-OP R5075 BACK CAB UN

8201L17-3428 ESTER OIL E7

FREIGHTSHIPPING CHARGES

Quantity

1

1

1

Workorder: V19368

In Date: 11/27/2008
Close Date: 12/23/2008

Meter Reading: 792.00

Problem?

ff seat belt not latching. E-14

Task performed:

drive to Stn; installed new seat belt; test ok. j

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V19371

In Date: 11/27/2008
Close Date: 01/02/2009

Meter Reading: 44,830.00

Problem?

installed headlight in E14, need spare bulb #6054 for station supply

Task performed:

Drop off headlights. j

Parts

Quantity

H6054USE CV TYPE SEALED BEAM

1

Workorder: V19437

In Date: 12/02/2008
Close Date: 01/02/2009

Meter Reading: 44,830.00

Problem?

REPAIR AIR LEAK E 14

Task performed:

Drive to Stn; rebuild air dryer & chk for more air leaks;
fnd bulkhead fitting bad; replcd; test ok. j

Parts

Quantity

800405PURGE VALVE KIT

1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V19539

In Date: 12/04/2008

Meter Reading: 44,830.00

Close Date: 01/13/2009

Problem?

C INSPECTION AND REPAIRS AS NEEDED E 14

Task performed:

1. C-Inspection.
2. Replcd all (4) btrys; clnd all term; replcd pos/neg jumper cables.
3. Perform low voltage electrical test.
4. Painted fuel cap.
5. Svc T-Case.
6. Svc cooling sys.
7. Rebuilt air dryer.
8. Replcd air tank pull c ord drains petcocks; (leaking/hanging down).
9. Replcd cooling sys reservoir sight glass (leaking).
10. Replcd wiper blades.
11. Replce flag stickers.
12. Replcd belts.
13. Replcd eng air filter.
14. Relocated to far end of shop; clnd bay floor; clnd bench & mnted new vice; mov computer, clnd out/mov storage cabinet.
15. Ladder compt trim bent & falling off; rem trim, straightened; drilled new mntng holes & reattached.
16. Replcd intake relief valve, inline screen fittings.
17. Replcd (3) door weatherstips (torn).
18. Replcd (3) door trims, (2) left, (1) right (broken).
19. Drained cooling sys; rem fuel filter; replcd air brake compressor coolant supply line (leaking). Reinstalled fuel filter/refilled cooling sys; pressure tested.
20. Rebuilt intake relief valve.
21. Rebuilt internal relief valve; connected truck to hyd & back flushed sand from pump & all valves.
22. Rebuilt deck gun valve (leaking). mounting bolts were rusted solid. changed valve over from Hale to Akron valve.
23. Shop meeting.
24. Rebuilt #1 discharge valve.
25. Rebuilt #3 discharge valve.
26. Replcd digital pressure read out on pump panel; (broken face plate).
27. Rebuilt #2 discharge valve (leaking).
28. Rebuilt #4 discharge valve & installed missing drain pull knob.
29. Rem intake relief valve a second time; clnd sand & rocks out of valve & reinstalled (leaking).
30. Replcd intake relief valve; chk valve.
31. Cln shop after PM.

Parts	Quantity
0100080010STRAINER	2
012-0010-00KNOB DRAIN	1
038-1010-01HALE RELIEF VALVE W/ VULCANIZED SEAT	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
15W40BSYN OIL BULK QTS	24
3944496COMPRESSOR INLET TUBE	1
52-24WIPER BLADES ANCO 24	2
546126000TPM/QG HALE REPAIR KIT	2
5462290020VALVE KIT SS VALVE 2 1/2 546-2290-02-0	4
5462300020VALVE KIT SS VALVE 3 IN	1
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
6806970098SEAL DOOR	1
800405PURGE VALVE KIT	1
883088301201 3 IN SLO-CLOZ W/R1 HANDLE	1
9440BELT	1
9480BELT	1
A0631087000CABLE BATT. POS.	1
A0631088000CABLE BATT. NEG.	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
IOA200A00DISPLAY MODULE REBUILD ONLY SEND IN	1
K080716BELT	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
VML-T1413T3248 SIGHT GLASS	1
HP-31DBATTERY 950CCA HP-31D	4



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V19849

In Date: 12/18/2008
Close Date: 01/13/2009

Meter Reading: 44,830.00

Problem?

replace hose bed cover e 14

Task performed:

Replace hose bed cover E14 - Central Auto j

Parts

NO PARTS USED

Quantity

Vendor?: CENTRAL AUTO

Workorder: V20079

In Date: 01/02/2009
Close Date: 02/04/2009

Meter Reading: 792.00

Problem?

water leaking from pump. e14

Task performed:

drive to stn; replace master drain; test ok. j

Parts

0100080010STRAINER

104967DIAPHRAM FOR 6 PORT DUMP VALVE

Quantity

1

1

Workorder: V20150

In Date: 01/06/2009
Close Date: 02/05/2009

Meter Reading: 44,830.00

Problem?

DRAIN VALVE LEAKING, E-14

Task performed:

Went to Stn14; backlused pump; fnd drain valve leaking; rep leak at fitting. j

Parts

NO PARTS USED

Quantity

Workorder: V20457

In Date: 01/20/2009
Close Date: 02/09/2009

Meter Reading: 45,920.00

Problem?

PUMP SHUT OFF WHILE PUMPING, E-14

Task performed:

Fnd pump panel shutting off while pumping; swapped T-case swtchs; no change; rem dash panel; fnd bad air swtch; R/R swtch; ran & ck opn; ck ok; reassembled all parts. j

Parts

76072-15-DC76072-15-DC SWITCH SW76072

Quantity

1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V18762

In Date: 10/31/2008
Close Date: 03/02/2009

Meter Reading: 1,138.40

Problem?

fire fighter seat belt latch not working properly. E14

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V21540

In Date: 03/04/2009
Close Date: 03/04/2009

Meter Reading: 1,138.00

Problem?

24 ft. extension has a dog that will not lock also if dog happened to catch the clip to lower ladder is not working and ladder would lower. This is an unsafe ladder and needs to be fixed or replaced asap E14

Task performed:

Parts

Quantity

CONTACTED CHIEF WELLS TO GET NEW LADDER FROM WAYNE

NO PARTS USED

Workorder: V21615

In Date: 03/07/2009
Close Date: 03/13/2009

Meter Reading: 1,138.00

Problem?

24' extension ladder broken. taken o.o.s. lock right side on fly not working. appears spring is broken. spare from batt.1 eng. borrowed until replaced or fixed. ladder behind sta. for pick up. E 14

Task performed:

Parts

Quantity

Told Captain to have S/S pickup. j

NO PARTS USED

Workorder: V21667

In Date: 03/09/2009
Close Date: 03/13/2009

Meter Reading: 46,660.00

Problem?

E-14 FAILED PUMP TEST ON 3/09/09. FAILED VACUUM TEST 13HG AND DROPPED QUICKLY/FAILED 100% CAP. TEST,WOULDNT HOLD DRAFT OR PUMP CAP.

Task performed:

Parts

Quantity

Drive to Stn; go to pump site with eng; pump eng passed pump test. j

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V21697

In Date: 03/10/2009 Meter Reading: 1,138.00
Close Date: 03/17/2009

Problem?

Rt. intake valve leaking during pump vacum test. Also pressure relief valve under E14 leaked during vacum test.

Task performed:

Drive to Stn; installed check valve & adj; c/n ball valve;
test ok. j

Parts

038-1550-00VALVE CHECK HALE 1/4"

Quantity

1

Workorder: V22048

In Date: 03/24/2009 Meter Reading: 1,138.00
Close Date: 03/30/2009

Problem?

Right frount hood strobe lens broken. E14

Task performed:

Drive to Stn; installed lens; test ok. j

Parts

NO PARTS USED

Quantity

Workorder: V22367

In Date: 04/07/2009 Meter Reading: 1,138.00
Close Date: 04/16/2009

Problem?

knob used to pull drain on the right intake striped. alum. cast bracket inside drivers door broken. need new.(axe falls when openec
e14

Task performed:

Drive to Stn; replcd knob & axe bracket. j

Parts

012-0010-00KNOB DRAIN

Quantity

2

Workorder: V22476

In Date: 04/12/2009 Meter Reading: 1,138.00
Close Date: 04/22/2009

Problem?

quartz lights buzzer going off when lights are in down postion. e14

Task performed:

Drive to Stn; adj collar on light; test ok. j

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V22650

In Date: 04/20/2009
Close Date: 04/28/2009

Meter Reading: 1,138.00

Problem?

Driver's seat belt latch works but, doesn't feel like it's operating properly. Feels like the spring in side is broken. E-14

Task performed:

Drive to Stn; installed new seat belt; test ok. j

Parts

NO PARTS USED

Quantity

Workorder: V23078

In Date: 05/05/2009
Close Date: 05/18/2009

Meter Reading: 48,418.90

Problem?

the deck gun valve linkage is not attached due to missing nut. noticed 5/6/09 e14

Task performed:

Drive to Stn14; reinstall deck gun linkage. j

Parts

NO PARTS USED

Quantity

Workorder: V23223

In Date: 05/12/2009
Close Date: 05/19/2009

Meter Reading: 48,418.90

Problem?

rear red warning light bulb burnt out. e 14

Task performed:

Drive to Stn; replcd light; test ok. j

Parts

NO PARTS USED

Quantity

Workorder: V23413

In Date: 05/20/2009
Close Date: 05/26/2009

Meter Reading: 48,418.90

Problem?

E14= front passenger seat, air bag won't hold seat up. seat falls down in very short time

Task performed:

Fnd pass seat leaking; rem seat; cut air line & rep leak at bladder; ck for leak; ck ok; reinstalled seat; went to Stn16. j

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V23787

In Date: 06/03/2009
Close Date: 06/04/2009

Meter Reading: 49,340.00

Problem?

repair float pump E14 (outside agency-regan's small engine service)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: REGANS

Workorder: V23574

In Date: 05/26/2009
Close Date: 06/12/2009

Meter Reading: 49,340.00

Problem?

floata pump on B14 quits running after 3-4 minutes. old fuel drained, new fuel added. motor runs after sitting a few minutes but die again e14

Task performed:

Parts

Quantity

drive to Stn; adj & cln carb; ran; still shut off; called Regan to rep. j

NO PARTS USED

Workorder: V24121

In Date: 06/16/2009
Close Date: 06/23/2009

Meter Reading: 49,340.00

Problem?

rotator light out e14

Task performed:

Parts

Quantity

Go to Stn14; replcd R/rear rotator light & chk opn. j

RB6DRPRB6PRP RED ROTATING BEACON

1

W/O 24129 Dupe W/O

Workorder: V24129

In Date: 06/16/2009
Close Date: 06/23/2009

Meter Reading: 49,340.00

Problem?

E14 R. REAR WARNING LIGHT IS OUT. THIS IS A ONGOING PROBLEM. SOME TIMES IT DOESN'T SPIN, OTHER TIMES BL IS OUT. PLEASE REPLACE WHOLE LIGHT ASSEMBLY IF POSSIBLE

Task performed:

Parts

Quantity

1. Go to Stn14 & replc R/rear red rotator light;

NO PARTS USED

DUPLICATED WORK ORDER (W/O 24121) j



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V24750

In Date: 07/13/2009 Meter Reading: 1,146.00
Close Date: 07/27/2009

Problem?
officer side rear window will not go up or down. Handal is striped. e14

Task performed:	Parts	Quantity
drive to Stn; take drivr's door & pass door apart; lube & test ok. j	A1818557002HANDLE-WINDOW	1

Workorder: V25258

In Date: 08/03/2009 Meter Reading: 1,146.00
Close Date: 08/10/2009

Problem?
A/C NOT WORKING. NEED WINDSHELD WIPERS. E-14

Task performed:	Parts	Quantity
ran A/C; installed gauges; fnd comp not engaging; got clutch to engage on speed 2 but not speed 3; needs switch replcd; truck A/C does work for now; returned to shop.	52-24WIPER BLADES ANCO 24	2

*Needs blower control switch replcd; does not work on high speed. j

Workorder: V25268

In Date: 08/04/2009 Meter Reading: 50,493.00
Close Date: 08/10/2009

Problem?
REPLACE A/C BLOWER SWITCH, E-14

Task performed:	Parts	Quantity
drive to Stn; replc blower swtch; test ok. j	52-24WIPER BLADES ANCO 24	2
	ABPN8332229011-3050 SWITCH BLOWER	1

Workorder: V25398

In Date: 08/09/2009 Meter Reading: 1,146.00
Close Date: 08/13/2009

Problem?
e14 spotlight has short in it. spotlight working intermitinly

Task performed:	Parts	Quantity
Drive to Stn; rework grnd; test ok. j	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V25572

In Date: 08/17/2009
Close Date: 08/27/2009

Meter Reading: 50,493.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED E 14

Task performed:

- B-Inspection
- 2. Free up btry tray.
- 3. Svc btrys.
- 4. Chk all computer codes.
- 5. Replcd R-side mid side marker/turn fixture.
- 6. Replcd #1 discharge cap/chain.
- 7. Tighten A/C belts.
- 8. Chk A/C sys for leaks; fnd small leak at hi-side Schrader core; evac sys; install new Schrader core; vac sys; charge/leak test.
- 9. Chk veh for air leaks; fnd leak at gov gsct; rem gov; mk new gsct frm stock material; install gov/leak chk - ok.
- 10. Press chk cooling sys; fnd leaks at air compressor cooling to be fittings; rem fuel filtr/hsn; tightened lines & rech ok.
- 11. tighten mansaver fasteners.
- 12. Adj air horns; freeup frozen R-side air horn & install horn kit.
- 13. Dia no air horn frm dash mode switch; rem dash; fnd wire off back of switch. j

Parts

Quantity

1094KIT-AIR HORN-GROVER	1
15W40BSYN OIL BULK QTS	4
16-31438915 VALVE CORE A/C 3544706C1	1
35200-YLIGHT MARKER LEDAMBER	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1

Workorder: V25694

In Date: 08/21/2009
Close Date: 09/14/2009

Meter Reading: 50,493.00

Problem?

replace 4 rear tires E14 (outside agency-tiresoles)

Task performed:

Replace (4) rear tires E14 - Tiresoles j

Parts

Quantity

NO PARTS USED

Vendor?: TIRESOLES



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V25744

In Date: 08/24/2009 Meter Reading: 50,493.00
Close Date: 09/14/2009

Problem?

repair hose bed cover central auto trim

Task performed:

Repair hose bed cover - Central Auto Trim j NO PARTS USED

Parts

Quantity

Vendor?: CENTRAL AUTO TRIM

Workorder: V26416

In Date: 09/23/2009 Meter Reading: 1,148.00
Close Date: 09/29/2009

Problem?

While on an emergency call the right rear emergency flashing light caught fire. the light is totally destroyed R14

Task performed:

R/R LED melted; repld LED & one lens below car; clnd area; ok. j 60R00FRR600 SERIES RED LED W/O FLANGE 1
68318341650AUSE 602000RU COMPLETE UNIT 1

Parts

Quantity

Workorder: V26715

In Date: 10/06/2009 Meter Reading: 1,148.00
Close Date: 10/21/2009

Problem?

Recieved 3 long velcro straps for coil pack. e14

Task performed:

Drive to Stn; installed straps for coil pack. j UMVS254411STRAP 46 IN 4

Parts

Quantity

Workorder: V27239

In Date: 10/28/2009 Meter Reading: 53,376.60
Close Date: 11/05/2009

Problem?

driver complaint intermitent low power E14

Task performed:

Drive to Stn; chk trans codes, eng codes, tighten fuel filters; test drive;run good; talk w/drivers to report it if happens again. j NO PARTS USED

Parts

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V27538

In Date: 11/09/2009
Close Date: 11/18/2009

Meter Reading: 1,148.40

Problem?

E14 BRAKES HAVE AIR LEAK

Task performed:

Parts

Quantity

1. Went to Stn14; ck for air leaks; fnd (2) air tank drainis leaking; R/R drain valves; ran/ck for leaks; ck ok.
2. Ck for eng/trans codes; no codes fnd. j

NO PARTS USED

Workorder: V27491

In Date: 11/07/2009
Close Date: 11/20/2009

Meter Reading: 1,148.40

Problem?

slow air leak.

Task performed:

Parts

Quantity

repairs done on W/O 25738 j

NO PARTS USED

Workorder: V27654

In Date: 11/14/2009
Close Date: 11/30/2009

Meter Reading: 1,148.40

Problem?

There is an air leak from the tank - Driver side under cab. Tank tops off, but takes 3 to 4 minutes. e14

Task performed:

Parts

Quantity

Ran truck; fnd purge valve on dryer leaking; R/R valve asy; ran/ck opn; ck ok. j

800405PURGE VALVE KIT

1

Workorder: V27684

In Date: 11/16/2009
Close Date: 11/30/2009

Meter Reading: 1,148.40

Problem?

pump throttle works intermittently. E14

Task performed:

Parts

Quantity

Went to Stn14; fnd throttle not working properly; R/R throttle asy; ran/ck opn; ck ok. j

55790-135000008 ELECTRONIC THROTTLE 100076 FELS

1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V27851

In Date: 11/22/2009
Close Date: 11/30/2009

Meter Reading: 1,148.70

Problem?

pump throttle did not work, turned off engine and power, turned power and engine back on and pump throttle worked. this is an ongoing problem.

Task performed:

Went to Stn14; w/eng to come back frm brush fire; ck/ran pump; fnd throttle ck ok; opr described problem; fnd throttle not all the way off when pump was engaged.
j

Parts

Quantity

NO PARTS USED

Workorder: V28022

In Date: 11/30/2009
Close Date: 12/16/2009

Meter Reading: 1,148.70

Problem?

air leak and engine slow to take off when cold E14

Task performed:

1. Ck for air leaks; R/R drain valve on tank; fnd UPS leaking fitting on cvr leaking; had to drill & e-z out fitting; diss valve shifter; R/R seals/fitting; ran & chk ok.
2. Ck for eng slow when cold; ck for eng/trans codes; ck ok; poss injection pump going bad. j

Parts

Quantity

5460370530VPS SHIFT KIT 546-0370-53-0

1

Workorder: V28401

In Date: 12/15/2009
Close Date: 01/05/2010

Meter Reading: 54,480.00

Problem?

AIR LEAK ON ENGINE E14

Task performed:

Chkd veh for air leaks; fnd one small air leak at tank valve; replc valve. j

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V28531

In Date: 12/22/2009
Close Date: 01/05/2010

Meter Reading: 1,148.80

Problem?

right rear strobe light is burned out. E14

Task performed:

1. Replcd rear strobe. j
2. Complete installation of exh sys; wrap exh pipe w/heat shield tape.
3. Hyd leak - assist Jeff in dia & rep hyd leak.
4. Top off hyd tank.
5. Fab support/latches, install, generator cvr. j

Parts

Quantity

H50SN12BULB

1

Workorder: V28164

In Date: 12/07/2009
Close Date: 01/14/2010

Meter Reading: 1,148.70

Problem?

pump throttle cuts off, air leak, slow on take off.

Task performed:

Unit was rep by Cummins. j

Parts

Quantity

NO PARTS USED

Workorder: V28156

In Date: 12/07/2009
Close Date: 01/15/2010

Meter Reading: 53,999.00

Problem?

repair engine E14 (outside agency-cummins)

Task performed:

Repair engine E14 - Cummins j

Parts

Quantity

NO PARTS USED

Vendor?: CUMMINS

Workorder: V29031

In Date: 01/12/2010
Close Date: 02/25/2010

Meter Reading: 55,259.00

Problem?

REPAIR FLAT CALLAGHAN

Task performed:

Replcd switch at T-case; chkd relays in cab. j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V29317

In Date: 01/21/2010
Close Date: 02/25/2010

Meter Reading: 55,259.00

Problem?

replace 1 tire at sta 14 E14 (outside agency-callaghan tire)

Task performed:

Replace (1) tire at Stn14 E14 - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V31069

In Date: 03/26/2010
Close Date: 04/20/2010

Meter Reading: 56,682.00

Problem?

emer. lights did not turn off at the panel, had to turn off truck and power to reset. e14

Task performed:

went to Stn14; ck emerg lites; ran lites; ck opn; ck ok; NPF; no problems for (2) shifts; rep done. j

Parts

Quantity

NO PARTS USED

Workorder: V31110

In Date: 03/29/2010
Close Date: 04/21/2010

Meter Reading: 56,682.00

Problem?

no emergency lights (on-call) e14

Task performed:

Went to Stn14; ping nodes; chk all comm connectors for water & dry out; now ok. j

Parts

Quantity

NO PARTS USED

Workorder: V31656

In Date: 04/20/2010
Close Date: 05/12/2010

Meter Reading: 57,300.00

Problem?

HOSE BED central

Task performed:

Hose bed - Central j

Parts

Quantity

NO PARTS USED

Vendor?: CENTRAL AUTO



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V31491

In Date: 04/13/2010

Meter Reading: 57,300.00

Close Date: 05/18/2010

Problem?

C INSPECTION AND REPAIRS AS NEEDED E14

Task performed:

Parts

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

C-Inspection	0100030000SCREEN 6 IN	2
2. Svc rear diff.	0100080010STRAINER	2
3. Svc T-case.	038-1010-01HALE RELIEF VALVE W/ VULCANIZED SEAT	1
4. R/R toggle switch boot for foam fill.	038-1290-00VALVE-SENSING NEEDLE	1
5. R/R rear A/C filter.	038-1760-00-AIR VALVE MIV	1
6. R/R A/C vents - (1) dvr side, (1) pass side.	040-1130-03RING-PISTON SEAL (QG RELIEF VALVE)	1
7. L-1/2 door striker pin bolt; rem S/S trim, srtrip; mk hole in door to nut to hold in bolts; drill out old spot on trim; replc bolts; install nuts in door.	042-0091-00SPRING PRIMER	1
8. L-3 compt door lower striker pin bolts loose; readj striker lock tite bolts.	042-0550-00SPRING-VALVE QG RELIEF VALVE	1
9. Cln/lube drawer slides/latches on btry box.	042002000SPRING RELIEF VALVE HALE	1
10. Cln/lube drawer slides/latches on tray for trash line; adj door latches on side door of tray.	05-16423-000HOSE LOWER RADIATOR	2
11. Pass door lite out; rep grommet & reinstall lite.	05-17223-000CAP RADIATOR 10 LB	1
12. Washer tank cvr loose; tighten up panel bolts.	073-0010-00PISTON RELIEF VALVE HALE	1
13. Cln/lube all under body slide steps.	073004100PISTON	1
14. Lube all EZ locks on truck, old ones were sticking.	082-2007-00-0GREASE ZERK W/CHECK VLV	3
15. C/O ladders; rem old heat sensors; cln ladders; install new sensors.	097-0990-00WASHER	2
16. Rem stainless trim arnd ladder compt; straighten trim; reinstall/add extra bolts; also glue down.	101280017DOOR HANDLE W/LOCK	2
17. R/R wiper blades.	15W40BSYN OIL BULK QTS	24
18. Replc marker lites out in rear tailboard.	203FFBEARING PULLEY	1
19. Straighten rear tailboard-bent under & side bent up.	20A-400CLAMP 4" 33969	2
20. Replc master intake valve bolt - falling off.	3938160OIL PAN GASKET C SREIES	1
21. Replc crosslay net - old one clip bad.	39768315259022 GROOVED TENSIONER OLD#3936213	1
22. Svc P/S sys; R/R filter.	4024883FRONT CRANK SEAL 6C	1
23. Send out hose bed cvr - had hole in it.	40896474309418 PUMP-WATER ISC REBUILT	1
24. R/R dvr side seat for repair.	519007110SLIDE CONTROL 519-0071-10	1
25.R/R 1/L & 2/R side outer door handles.	52-24WIPER BLADES ANCO 24	2
26. R/R window crank handle.	538-1400-00QG VALVE	1
27. R/R belts.	546085303NC SWITCH/BRACKT	1
28. R/R tensioner.	546126000TPM/QG HALE REPAIR KIT	1
29. R/R frnt cvr _____ & frnt main seal.	562008002PM CONTROL 562-0080-02	2
30. R/R rad & send out to be rep; reinstall rad.	60R00FRR600 SERIES RED LED W/O FLANGE	1
31. R/R wtr pump - leaking.	6807200253GUIDE METAL	1
32. R/R hood lite "side".	6807600070HANDLE DOOR EXT L/H	1
33.R/R outer door handle on L-1 compt; return spring msng.	6807600170HANDLE DOOR EXT. R/H	2
34. R/R outer door handle on L-3 compt; return spring brkn.	75W90GEAR OIL SYN QT	26
35. Replc shocks on L-1 door; old one is dead.	800405PURGE VALVE KIT	1
36. Replc door shocks on L-3 door; old ones dead.	101281012GSS6298UH STRUTS 90#	1
37. R/R door shocks on R-1 compt - old ones bad.	107796DRYER KIT AD9 -NEW	1
38. R/R door shocks on R-3 compt - old ones bad.	107800VALVE CHECK AD9	1
39. R/R door shocks on lower rear compt - old ones bad.	35200-RLIGHT MARKER LED RED	2
40. R/R door shocks on hose reel compt - old ones bad.	6808300074VENT A/C LH	1
41. Install new drawer slids in rear Hurst comp - oold one bearings gone; don't have that style; rework new style slides; remnt new ones.	6808300174VENT A/C RH	1
42. Install traip in dvr side well - hose had backboard strap on it.	78R536078R5360M 2PK FILTER AIR COND	1
	14022-1-5COOLER 14032	1
	5462290020VALVE KIT SS VALVE 2 1/2 546-2290-02-0	2
	6808310398SEAL AIR DUCT	1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

43. R/R exh clamps on muffler cut off - old ones rusted.	68318358710600 SER NON OPTIC AMBER	1
44. R/R trans cooler.	68318358730600 SER LENS NON OPTIC	1
45. R/R oil pan gskt.	68318358750600 NON OPTIC RED LENS	1
46. R/R dryer - rebuild unit.	8126482-2106 TOGGLE GUARD	1
47. R/R sensor valve - rebuild; R/R intake relief valve-rebuild; replc switch & adj.	9440BELT	1
48. R/R lower rad hoses.	9480BELT	1
49. Svc cooling sys; change filter.	94862PIGTAIL LED MARKER LIGHTS	1
50. R/R relief valve; rebuild unit; replc worn parts; still wont pass dry vac test.	A1818557002HANDLE-WINDOW	1
51. R/R brake lite lens.	A1834388002MOLD L/H	1
52. R/R backup lite lens.	C938-22AH7600-22 TRAY SLIDES 22 IN HD	2
53. R/R t-signal lens.	CA8193AIR FILTER 46744 WIX	1
54. R/R relief valve control asy & rebuild; cld not get new valve to seal; replc new one; still not pass dry vac pull; chk valve & test ok.	CLEAN AND TESTCOOLER/RADIATOR	3
55. R/R air bleeder for master intake valve; replc hose ends.	CYBS12134011USE UMVS111611 STRAP	3
56. Still leaking, vac out master intake valve; pull appart; rechk; C/O chk valve again; press test unit fittings leaking on valve; replc fittings readj swtich on valve; retest-ok; no leak at valve discharge & intake valves leaking.	EAA-8350-30UGSS1783UQ STRUT-LIFT	11
57. R/R #1 discharge valve & rebuild; retest vac fail.	EAA-8700-120EAA-8700-120U GAS SUPPORT	1
58. Vac test fail; R/R right intake valve & rebuild; retest-ok; pass 22 to 15.	FG87904MFG3937557S FILTER P/S NEW STYLE	1
59. Rebuild primer valve sticking; upper lower ok.	FGQ79699GASKET-P/S FILTER NEW STYLE	1
60. Set up rear tailboard & back for new hose lay, etc.; mnt HWR brkts, etc.	FLF/FRE1020-0001TURBO HOSE	2
61. R/R intake screens on pump.	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
62. R/R frnt bumper intake screen.	HPH6349AOIL FILTER 51748	1
63. Fill wtr tank; reseal test port on P/P.	IMMF11358SEAT BELTS	1
64. R/R brkn heater control cable.	K080716BELT	1
65. Adj heater cable & defroster cable - leaking too much.	LPVM-7LG MOUNT	1
66. Intake relief valve dripping; try to flush out; pull appart; rechk stem seal; add washer to end to increase spring press; put back tog; retest ok; no leaks; refill tank. j	PR338324070 WIX FILTER WATER	1
	PVG-KITORING KIT	1
	S775COUPLER	1
	SAHSVS2510STRAP	1
	WAT61403STRAINER 6 IN	1
	R90PFILTER FUEL 33231	1

Workorder: V32233

In Date: 05/16/2010 **Meter Reading:** 57,300.00
Close Date: 05/28/2010

Problem?

discharge #1 gauge does not register pressure.(The gauge maybe broken) The valve and discharge works. Troubleshoot with no change. E14

Task performed:

Went to Stn14; run pump ck # discharge gauge; R/R fitting at pipe & ran; ck pump opn; ck ok. j

Parts ----- Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V32726

In Date: 06/07/2010
Close Date: 06/21/2010

Meter Reading: 57,300.00

Problem?

headlight out left side E14

Task performed:

Installed L/frnt headlight 6054. j

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

1

Workorder: V32843

In Date: 06/12/2010
Close Date: 06/21/2010

Meter Reading: 58,104.00

Problem?

cigarette / 12 volt outlet on dash 10-7, plug on side of engine cover intermittent. unable to use Q-beam light when needed E14

Task performed:

Fnd both plugs inop; rem center cvr; rem line/connection; R/R fuse for dash; rem dash panels; rep term on plug; ck ok. j

Parts

NO PARTS USED

Quantity

Workorder: V32842

In Date: 06/12/2010
Close Date: 06/22/2010

Meter Reading: 58,104.00

Problem?

roof spot light on E14 stops working after about one minute(when it gets hot) but works again once it cools.

Task performed:

Fnd roof spot bulb bad; R/R bulb; ck ok. j

Parts

H3-100WBP1210H3 BULB

Quantity

1

Workorder: V33275

In Date: 07/01/2010
Close Date: 07/28/2010

Meter Reading: 58,104.00

Problem?

PUMP PANEL DIGITAL PRESS./VAC GAUGE, FOAM CONTROL, AND GREEN PUMP OK LIGHT 10-7 E14

Task performed:

Went to 14; Ran/ck opn;s NPF; ck "Y" connectors at pump panel; greased conn; ck relays in center sconsole; ck ok; ran unit six times; ck ok. j

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V34433

In Date: 08/22/2010 Meter Reading: 58,595.50
Close Date: 09/15/2010

Problem?

right scene light is not working. E14

Task performed:

Went to 14; fnd no power to light; traced/rep wires; R/R bulb; ck ok. j

Parts	Quantity
LB-D30BULB QUARTZ HAL. 12V 150W	1

Workorder: V34589

In Date: 08/29/2010 Meter Reading: 59,889.30
Close Date: 09/15/2010

Problem?

Fan for A/C in front of cab is not working. E14

Task performed:

Went to 14 from 27; ran A/C; fnd blower switch bad; rem dash panels; R/R switch; rep connector; ran/ck ok. j

Parts	Quantity
ABPN8332229011-3050 SWITCH BLOWER	1

Workorder: V34255

In Date: 08/13/2010 Meter Reading: 58,595.50
Close Date: 10/01/2010

Problem?

right front head light out. e14

Task performed:

Went to 14; R/R headlight; ck ok; gave stn a spare bulb. j

Parts	Quantity
H6054USE CV TYPE SEALED BEAM	2

Workorder: V36277

In Date: 11/08/2010 Meter Reading: 60,844.00
Close Date: 11/19/2010

Problem?

roof spot light. scene light out. red lenz covers on grill right and left and left hood. male clip for pre connect webbing. pre connect nozzle velco straps right and left. air leak. pump shift. E 14

Task performed:

1. r&r pre connect net, r&r velcro straps, nozzles, order lens covers.
2. roof light spot inop, r&r spot light. jab

Parts	Quantity
620122SPOT LIGHT REMOTE	1
68318358730600 SER LENS NON OPTIC	3
SAHSVS2510STRAP	2



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V36240

In Date: 11/06/2010
Close Date: 11/30/2010

Meter Reading: 60,844.00

Problem?

Main spotlight on light bar is out. Also ONE of the two halogen telescopic bulbs is out on the driver's side. E22

Task performed:

Parts

Quantity

(1) TRAVELED TO ST22 TO REPAIR A SPOT LIGHT ON E22. CHECKED AND FOUND PROBLEM OF A LOOSE PLUG AT THE CONTROLLER. DONE.
(2) REPLACED BULB IN SCENE LIGHT FIXTURE. OK.
J.W.

NO PARTS USED

Workorder: V31652

In Date: 04/20/2010
Close Date: 12/22/2010

Meter Reading: 57,300.00

Problem?

repair seat central

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V37178

In Date: 12/15/2010
Close Date: 01/03/2011

Meter Reading: 62,073.00

Problem?

CHECK FUEL LEAK E 14

Task performed:

Parts

Quantity

(1) TRAVELED TO ST-14 TO REPAIR FUEL LEAK ON E14. TIGHTENED PRIMARY FUEL FILTER BOWL. CHECKED # 5 INJECTOR LINE,OK. LIFT PUMP LINES NEED TO BE CHECKED.
(2) TRAVELED TO ST-14 TO REPAIR A FUEL LEAK THAT WASN'T FINISHED THE DAY BEFORE. FOUND THE FITTING @ THE LIFT PUMP LOOSE. TIGHTENED THE FITTING, NO MORE LEAKAGE. J.W.

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V36556

In Date: 11/18/2010 Meter Reading: 60,844.00
Close Date: 01/05/2011

Problem?

E14 needs the tips for the hurst spreader that allows you to hook chains to each tip of the spreader. Also E14 is missing 1 pin from the hurst kit thats in the small yellow plastic box.

Task performed:

Travel to stan; Hurst spreader chain tips missing; fnd used tips & brought to stn. j

Parts	Quantity
NO PARTS USED	

Workorder: V36282

In Date: 11/08/2010 Meter Reading: 60,844.00
Close Date: 01/06/2011

Problem?

LDH has three pin holes near hydrant connection. E14

Task performed:

1. Replc fill hose - leaking; got new large diameter fill hose.
2. L/spotlight inop; - poor contact; clnd contact. j

Parts	Quantity
NO PARTS USED	

Workorder: V37419

In Date: 12/27/2010 Meter Reading: 62,073.00
Close Date: 01/11/2011

Problem?

red flashing hazard light not flashing. located on the drivers side engine compartment cover (in ft. of horn) E14

Task performed:

(1) TRAVELED TO ST-14 TO REPAIR THE RED FLASHING HAZARD LIGHT LOCATED ON THE DRIVER SIDE IN FRONT OF THE HORN ON E14. REPLACED THE LAMP ASSEMBLY. OK. J.W.

Parts	Quantity
60R00FRR600 SERIES RED LED W/O FLANGE	1

Workorder: V37834

In Date: 01/16/2011 Meter Reading: 62,073.00
Close Date: 01/25/2011

Problem?

four warning light lens covers. E14

Task performed:

Drive to stn; emeergency light cvrs worn; replc cvrs. j

Parts	Quantity
1891BULB	11
68118358150600 SER OPTIC RED	3



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V37934

In Date: 01/20/2011

Meter Reading: 63,310.00

Close Date: 01/31/2011

Problem?

B INSPECTION AND REPAIRS AS NEEDED E14

Task performed:

- B-Inspection
 - 2. Adj washer nozzles.
 - 3. Install wiper refills.
 - 4. Btrys failed load test; replc all (4) btrys; rep btry hold down.
 - 5. Replc both R/side cab door light asys.
 - 6. All tire press way low; try to adj & had problems to get air up to proper level; fnd that shop air was set too low; will adj when shop air is set properly.
 - 7. Replc (2) frnt shocks; lower mntng bolts frzn in spring hangers & spacer frzn to bolt; free up component parts; lube/reassemble.
 - 8. Rem deriver door panel & replc internal door hold open; replc panel.
 - 9. Pry open btry tray drawer & also trash line drawer; blow out sand & road debris from drawer slides; spray down w/anti-rust & work drawers to free up; after loose, blow out slides again & lube; work drawers again.
 - 10. Start relay acting up & does not always engage starter; test power to relay; power in ok; power out - NG; replc power relay & rep some bad wiring.
 - 11. Install btry charger sys & auto-eject sys.
 - 12. L/Frnt tire marginal; spoke w/supt & he decided to monitor a ware at this time; if need be, will replc at stn.
- j

Parts

Quantity

0106837849C8COMP LIGHT WHITE LED 200	2
0913912CHARGER 2000	1
0915520120AUTO EJECT 20 AERO OTL3925	1
15W40BSYN OIL BULK QTS	24
440-44 1/8 IN VALVE EXT	1
6803230300 65482 SHOCK FRONT ENGINE	2
6807200216DOOR CHECK ASSY	1
698698 CHUCK	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
ESX120105112STARTER RELAY ESX-120-105112	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1
U-24RWIPER REFILL	1

Workorder: V38532

In Date: 02/15/2011

Meter Reading: 63,559.00

Close Date: 02/23/2011

Problem?

left scene light not working. E14

Task performed:

- Travel to stn; Left scene light inop; poor contact at bulb; clnd contact. j

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V38587

In Date: 02/17/2011 Meter Reading: 63,559.00
Close Date: 02/23/2011

Problem?
LEFT TELESCOPING LIGHT NOT WORKING e14

Task performed:	Parts	Quantity
Travel to stn; Left telescoping light inop; wiring shorted to light; rep shorted wiring. j	NO PARTS USED	

Workorder: V38656

In Date: 02/21/2011 Meter Reading: 63,559.00
Close Date: 02/24/2011

Problem?
foam system turns off when flowing foam.need fluid for hurst tool.....two quarts E14

Task performed:	Parts	Quantity
1. Flushed foam sys & ran ok. 2. Assist - Murray. j	NO PARTS USED	

Workorder: V38676

In Date: 02/22/2011 Meter Reading: 63,784.90
Close Date: 02/24/2011

Problem?
headlights turning off intermittently e14

Task performed:	Parts	Quantity
1. Traveled to 14 & rep grnd to headlights. 2. Assist - Murray j	NO PARTS USED	

Workorder: V37326

In Date: 12/21/2010 Meter Reading: 62,073.00
Close Date: 03/08/2011

Problem?
lightbox not holding charge e14

Task performed:	Parts	Quantity
(1) TRAVELED TO ST-14 TO REPAIR THE LIGHT BOX ON E14 NOT CHARGING. FOUND THAT THE REPAIR HAD ALREADY BEEN DONE. J.W.	NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V38981

In Date: 03/05/2011

Meter Reading: 64,341.70

Close Date: 03/21/2011

Problem?

transmission shifts rough when putting into drive. spot light works intermittently. small amount of radiator fluid on bay floor. E14

Task performed:

Parts

Quantity

1. Went to 14; stopped & called in veh; fire on indiantown Rd; arrived at 14; ck coolant leak; press test; tightened all clamps; ck ok.

NO PARTS USED

2. Ck trans noise; ok for codes; ck for codes; ck u-joints & drive line - ck ok; normal backlash in rear diff; ck ok.

3. Ck spotlight; R/R connections at light asy; ck ok.

j

Workorder: V38906

In Date: 03/02/2011

Meter Reading: 63,784.90

Close Date: 03/22/2011

Problem?

This is not for the vehicle, this is for the Ramfan. I CANNOT find an asset # for the Ramfan. The fan is running poorly, needs a new filter. Old filter is dirty and falling apart. It is a Turboventilator GF 165. E14

Task performed:

Parts

Quantity

1. Travel to 14; chkd ram fan; cld out carb still runs rough; will swap w/spare.

NO PARTS USED

2. PU fan for repair. j

Workorder: V39494

In Date: 03/28/2011

Meter Reading: 64,599.00

Close Date: 04/04/2011

Problem?

chain saw would not start. sta 14.

Task performed:

Parts

Quantity

Travel to 14 & rep chain saw. j

NO PARTS USED

Workorder: V39606

In Date: 04/01/2011

Meter Reading: 64,599.00

Close Date: 04/13/2011

Problem?

need spare light bulb.

Task performed:

Parts

Quantity

Travel to 14; installed headlight.

H6054USE CV TYPE SEALED BEAM

1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V40224

In Date: 04/28/2011
Close Date: 05/03/2011

Meter Reading: 65,688.90

Problem?

E14 map light 10-7, also need to move mdc power unit which is blocking 12 volt DC port for spotlight, sta 14.

Task performed:

- 1. Rep maplight; mov power supply so 12 volt plug cld be used.
- 2. R/R maplight. j

Parts

Quantity

LF18TS-LEDMAP LIGHT LED 18 IN

1

Workorder: V40290

In Date: 04/30/2011
Close Date: 05/03/2011

Meter Reading: 65,688.90

Problem?

siren not working. E14

Task performed:

- Travel to 14; fnd siren inop; fnd bad electrical connection; secured connection & test ok; travel home. j

Parts

Quantity

NO PARTS USED

Workorder: V40011

In Date: 04/19/2011
Close Date: 05/09/2011

Meter Reading: 65,388.20

Problem?

Needs two front tires. Sta 14.

Task performed:

- Need (2) frnt tires Stn14 - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD

Workorder: V40548

In Date: 05/11/2011
Close Date: 05/16/2011

Meter Reading: 65,688.90

Problem?

no back-up alarm on e-14, Sta 14.

Task performed:

- Installed new backup alarm under truck. j

Parts

Quantity

575BACKUP ALARM ECCO 107 DEC

1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V40319

In Date: 05/02/2011
Close Date: 05/27/2011

Meter Reading: 65,688.90

Problem?

REPLACE TIRES E28

Task performed:

Replace tires E14 - Tiresole

j

Parts

NO PARTS USED

Quantity

Vendor?: TIRESOLE

Workorder: V40943

In Date: 05/28/2011
Close Date: 06/06/2011

Meter Reading: 66,196.80

Problem?

engine status center and message center on pump panel not working. E14

Task performed:

Replc eng status center.

j

Parts

NO PARTS USED

Quantity

Workorder: V41011

In Date: 06/01/2011
Close Date: 06/06/2011

Meter Reading: 66,196.80

Problem?

dash mount map light on officers side not working E 14

Task performed:

Travel to 14; replc maplight.

j

Parts

101847ENGINE STATUS CTR
LF18TS-LEDMAP LIGHT LED 18 IN

Quantity

1
1

Workorder: V41675

In Date: 06/29/2011
Close Date: 07/01/2011

Meter Reading: 67,770.00

Problem?

E-14 siren not working, Sta 14.

Task performed:

travel to 14 gound siren head with blown fuse and one speaker shorted
replaced lose fuse and speaker ak

Parts

SD-210RXSIREN DRIVER SMALL

Quantity

1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V41899

In Date: 07/09/2011

Meter Reading: 67,770.00

Close Date: 07/13/2011

Problem?

E14 SIREN NOT WORKING.

Task performed:

Chkd siren - works fine.

j

Parts

NO PARTS USED

Quantity

Workorder: V41905

In Date: 07/10/2011

Meter Reading: 67,770.00

Close Date: 07/13/2011

Problem?

E14 has an air leak. Drains down completely in about 8 hours.

Task performed:

Travel to 14; replc petcocks in air tanks w/cable drains.

j

Parts

12105QUICK DRAIN

Quantity

2

Workorder: V41934

In Date: 07/11/2011

Meter Reading: 67,770.00

Close Date: 07/14/2011

Problem?

ALL EMERGENCY LIGHTS 10-7, ALSO REAR HAZARD LIGHTS..... WAS OPERATING IN A.M. E14

Task performed:

1. Fnd blown fuse at siren head; replc fuse; head still inop; replc head - all ok.

2. Emergency lights inop; working fine, cld not dupe concern; chkd multiplexing; chkd btry connections & alt charging.

j

Parts

NO PARTS USED

Quantity

Workorder: V42173

In Date: 07/20/2011

Meter Reading: 68,188.00

Close Date: 07/22/2011

Problem?

on call deck gun buzzer going off E 14

Task performed:

Went to 14; ck deckgun svc - ck ok; ck all door alarms & quartz light switches; ck ok; return home.

j

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V42201

In Date: 07/21/2011 Meter Reading: 68,188.00
Close Date: 07/22/2011

Problem?

warning buzzer for deck gun going off when deck gun is in down position. Sta 14.

Task performed:

TRAVEL TO 14 REPAIRED SHORTED WIRE TO DECK
GUN SWITCH AK

Parts

NO PARTS USED

Quantity

Workorder: V42252

In Date: 07/24/2011 Meter Reading: 68,915.00
Close Date: 07/26/2011

Problem?

HF siren (steering wheel control) not working properly. contacts need to be cleaned. E 14

Task performed:

Replc horn ring contact in column. j

Parts

6804640043HORN CONTACT

Quantity

1

Workorder: V42253

In Date: 07/24/2011 Meter Reading: 68,915.00
Close Date: 07/26/2011

Problem?

right-side rear cab door (behind officer) locking mechanism hard to close door. E 14

Task performed:

Replc & adj door latch. j

Parts

18-29935-001RH DOOR LATCH NEW
18-45484-000LATCH L/H

Quantity

1

1

Workorder: V42254

In Date: 07/24/2011 Meter Reading: 68,915.00
Close Date: 07/26/2011

Problem?

cab warning light "Extenda Gun" flashing and buzzing while driving. deck gun has been checked out, it is secure. E 14

Task performed:

Travel to 14; traced/rep shorted wire to extended gun
light. j

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V42401

In Date: 07/30/2011
Close Date: 08/03/2011

Meter Reading: 68,915.00

Problem?

TANK TO PUMP NUT FELL OF LEVER...REPLACED WITH DISCHARGE 2, BUT STILL NEED A NUT FOR DISCHARGE 2 E14

Task performed:

REPLACED ROD ON DISCHARGE VALVE AK

Parts

NO PARTS USED

Quantity

Workorder: V42889

In Date: 08/18/2011
Close Date: 08/19/2011

Meter Reading: 68,915.00

Problem?

Replace hurst hose.

Task performed:

Parts only - no labor j

Parts

3530016HOSE HURST 16 ORANGE

Quantity

1

Workorder: V42944

In Date: 08/20/2011
Close Date: 08/30/2011

Meter Reading: 68,915.00

Problem?

rear yellow flasher lights on all the time with batterys on. B 14

Task performed:

TRAVEL TO 14 DIAGNOSE AND TROUBLE SHOOT REAR SIGNAL LIGHTS REPLACE REAR NODE AND CHECKED NODES 4 & 1

TRAVEL TO 14 REPLACED MINI NODE PROBLEM STILL EXISTS WILL SCHEDULE TO BRING TO SHOP

REAR T SIGNALS STAY ON

REAR TURN SIGNALS STAY ON STARTED TRACING WIRES ON FREIGHTLINER SIDE TO FIND SHORT

PANEL FOR REAR NODE MISSING INSTALLED NEW PANEL

FINISHED TRACING WIRES AND FOUND SHORT CORROSION IN HARNESS AT PLUG CORRECTED PROBLEM

Parts

44530FLASHER ELECTRONIC

600000003NODE HERCULES V-MUX

601000000NODE MINI V-MUX 6010-0000-00

DT043PP007DEUTSCH RECEPTACLE

Quantity

1

1

1

2



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V43018

In Date: 08/24/2011

Meter Reading: 68,915.00

Close Date: 09/06/2011

Problem?

E-14 passenger side headlight stays on high beam. Sta 14.

Task performed:

Chkd headlights for opn/adjustment. j

Parts

NO PARTS USED

Quantity





4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V43132

In Date: 08/29/2011

Meter Reading: 68,915.00

Close Date: 09/13/2011

Problem?

C INSPECTION AND REPAIRS AS NEEDED E 14

Task performed:

- Perform "C" svc.
- 2. Replc oil pan gskt - leaking.
- 3. Svc trans.
- 4. Svc air brake dryer.
- 5. Replc air hoses for rear brakes - emerg side worn through.
- 6. Svc T-case.
- 7. installed asset sticker on frt windshield.
- 8. Replc wiper blades.
- 9. Replc Left/right frt t-signal side marker lenses - brkn.
- 10. Replc rear A/C filter.
- 11. Fab/install (2) shelves in R-1 compt.
- 12. Replc eng air filter.
- 13. Painted fuel cap.
- Painted fuel cap.
- 14. Flushed rust/debris from intake relief valve w/hydrant press; perform vac test; fnd intake relief still leaking; rebuilt intake relief valve.
- 15. replc chk valve at diaphragm valve - seized.
- 16. Search for air leak in air brake sys; replc pull cord air tank bleeders w/Petcock style.
- 17. Cind/lubed master intake valve - hard to open/close.
- 18. T-shoot intake relief valve indicator light inop; traced problem to faulty relay/flasher at intake relief valve; replc relay flasher.
- 19. Rebuilt master drain valve - frzn/siezed.
- 20. Vac test pump after above repairs; now passes vac; test start: 23"; test finish: 20".
- 21. Replc triple lock hose adapter mnts on tailboard & R/side pump panel step.
- 22. Installed left mid body reflector at step - msgng.
- 23. Lube/adj/tighten all door hinges/latches/hold opens on cab & body.
- 24. R/R all (4) cab door panels to lube/adj window regulator - seized/rusted; also lube door checks & replc all (4) door trims-brkn.
- 25. Cind/lubed trash line drawer slides - seized/binding.
- 26. Drilled/tapped new mntng holes for btry switch access cvr on cab - loose/stripped out.
- 27. Svc P/S.
- 28. Quality check.

Parts	Quantity
0460050000GASKET	4
103385NDRAIN COCK	3
104967DIAPHRAM FOR 6 PORT DUMP VALVE	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
15W40BSYN OIL BULK QTS	24
29526898 29548988 TRANS FILTER ALLISON	1
390439HOSE AND FITTING	1
3938160OIL PAN GASKET C SREIJS	1
546085303NC SWITCH/BRACKT	1
546126000TPM/QG HALE REPAIR KIT	1
75W90GEAR OIL SYN QT	4
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
91-22WIPER BLADE	2
91513AMBER LENS	2
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
B480AREFLECT-AMBER	1
CA8193AIR FILTER 46744 WIX	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
TRANSYNDALLISON TRANS FLUID GAL	5



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V43546

In Date: 09/09/2011
Close Date: 09/14/2011

Meter Reading: 68,915.00

Problem?

adjust brakes.

Task performed:

check brake pedal adjusted puh rod at brake pedal to foot --

Parts

Quantity

NO PARTS USED

Workorder: V43568

In Date: 09/10/2011
Close Date: 09/15/2011

Meter Reading: 69,126.00

Problem?

power unit for the jaws will not run in bunny mode only in choke mode. E14

Task performed:

ran power unit runs fine
added fuel additive

Parts

Quantity

NO PARTS USED

Workorder: V43056

In Date: 08/25/2011
Close Date: 09/16/2011

Meter Reading: 68,915.00

Problem?

Replace rear tires, At boulevard.

Task performed:

Replace rear tires - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD

Workorder: V43730

In Date: 09/17/2011
Close Date: 09/20/2011

Meter Reading: 69,126.00

Problem?

rear yellow emergency light out, Sta 14.

Task performed:

travel to 14 replaced bulb in rotator

Parts

Quantity

H50SN12BULB

2



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V43729

In Date: 09/17/2011

Meter Reading: 69,126.00

Close Date: 10/13/2011

Problem?

no high beams. Sta 14.

Task performed:

No hi-beams; chkd switch/relay; both working; will get diagrams for repair. k

Parts

NO PARTS USED

Quantity

Workorder: V44232

In Date: 10/08/2011

Meter Reading: 69,473.00

Close Date: 10/13/2011

Problem?

high beams not working. spot light works intermitently. E14

Task performed:

Parts

030126FLASHER SHO-ME

620122SPOT LIGHT REMOTE

Quantity

1

1

Workorder: V44551

In Date: 10/20/2011

Meter Reading: 69,825.30

Close Date: 10/21/2011

Problem?

E-14 needs hurst tool oil

Task performed:

Drop off Hurst oil Stn14. j

Parts

180R002HURST HYD. FLUID QT

Quantity

2

Workorder: V44606

In Date: 10/22/2011

Meter Reading:

Close Date: 10/26/2011

Problem?

quartz work light out. need chain for chain saw. Sta 15

Task performed:

replaced quartz light bulb

replaced chain saw chain

Parts

LB-D30BULB QUARTZ HAL. 12V 150W

Quantity

1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V44613

In Date: 10/23/2011

Meter Reading:

Close Date: 10/26/2011

Problem?

hand light doesn't work on E14

Task performed:

travel to 14 swapped hand light

Parts

Quantity

NO PARTS USED

Workorder: V45073

In Date: 11/09/2011

Meter Reading:

Close Date: 11/15/2011

Problem?

pump leaking E 14

Task performed:

found leak to be a plug in bottom of valve corroded through removed and replaced

Parts

Quantity

NO PARTS USED

Workorder: V45291

In Date: 11/18/2011

Meter Reading:

Close Date: 11/29/2011

Problem?

left turn signal not working. smell or raw fuel in cab.

Task performed:

Travel to Station 14; Replaced left front signal and checked for fuel leak; none found. bp

Parts

Quantity

NO PARTS USED

Workorder: V45396

In Date: 11/23/2011

Meter Reading:

Close Date: 11/29/2011

Problem?

Left front blinker light out, Sta 14

Task performed:

Replaced signal light.bp

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V45676

In Date: 12/06/2011 Meter Reading:
Close Date: 12/09/2011

Problem?
officer door handle broken. Sta 14

Task performed:	Parts	Quantity
TRAVEL TO STA 14 REPLACED OFFICERS DOOR HANDLE	6807200575HANDLE DOOR	1

Workorder: V46399

In Date: 01/07/2012 Meter Reading: 71,704.30
Close Date: 01/10/2012

Problem?
fuel smell inside the cab E14

Task performed:	Parts	Quantity
TRAVEL TO 14 SECURED 3 LEAKING FUEL LINES CLEANED TOP OF HEAD AND TESTED OK.	NO PARTS USED	

Workorder: V46410

In Date: 01/09/2012 Meter Reading: 71,704.30
Close Date: 01/10/2012

Problem?
warning buzzer for quartz lights and driver compartmentdoors won't shut off driver side quartz light one bulb out TIC charger spare battery strap missing won't charge(CRS...#8242), Sta 14

Task performed:	Parts	Quantity
1. COULD NOT DUPLICATE PROBLEM WITH DOOR AJAR CIRCUIT 2. FOUND NO PROBLEM WITH QUARTZ LIGHTS 3. WILL BRING UP TIC CHARGER WHEN ONE COMES AVAILABLE	NO PARTS USED	

Workorder: V47022

In Date: 02/01/2012 Meter Reading: 72,483.00
Close Date: 02/02/2012

Problem?
Engine light on E14

Task performed:	Parts	Quantity
CHECK OUT CHECK ENGINE LIGHT ON. FOUND CODE FOR ENGINE SPEED ERRATIC. REPLACED ENGINE SPEED/POSITION SENSORS. CLEARED CODE AND ROAD TESTED. NO FURTHER CODES SET.	4921597OUTBOARD SPEED SENSOR	2



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V48433

In Date: 04/04/2012 Meter Reading: 73,980.70
Close Date: 04/25/2012

Problem?

work light on drivers side out. door for shore power broken. E14

Task performed:

INSTALLED NEW LIGHT AND SHORELINE DOOR.

Parts

FCA100-V15LED SCENELIGHT HEAD

Quantity

1

Workorder: V48765

In Date: 04/19/2012 Meter Reading: 74,270.00
Close Date: 04/25/2012

Problem?

yellow handle air brake in cab leaking air. E14

Task performed:

TRAVEL TO 14 INSPECTED PARK BRAKE VALVE NO PROBLEM FOUND - AIR PRESSURE WAS LOW - CHECKED F OR SYSTEM AIR LEAK AND REPAIRED LEAK AT GOVERNER.

Parts

800034VALVE PARKING BRK.

Quantity

1

Workorder: V49245

In Date: 05/10/2012 Meter Reading: 74,790.60
Close Date: 05/18/2012

Problem?

cross lay net needs to be replaced. E 14

Task performed:

REPLACED WORN AND BROKEN CROSSLEY NETS.

Parts

NO PARTS USED

Quantity

Workorder: V49419

In Date: 05/17/2012 Meter Reading: 75,145.00
Close Date: 05/18/2012

Problem?

officers seat has a leak, doesn't hold air very long and drops to the floor. E 14

Task performed:

TRAVEL TO 14 REPAIRED AIR LINE LEAK ON OFFICERS SEAT.

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V49420

In Date: 05/17/2012
Close Date: 05/18/2012

Meter Reading: 75,145.00

Problem?

R. SIDE HEAD LIGHT (LOW BEAM) BURNED OUT. TOP SPOT LIGHT FLICKERS WHEN IN USE E 14

Task performed:

REPLACED BLOWN HEADLIGHT RF LEFT STATION WITH EXTRA LIGHT.

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

2

Workorder: V49488

In Date: 05/19/2012
Close Date: 05/29/2012

Meter Reading: 75,145.00

Problem?

warning buzzer will not stop buzzing. E14

Task performed:

TRAVEL TO 14 CHECKED BUZZING NO PROBLEM FOUND

Parts

NO PARTS USED

Quantity

Workorder: V49506

In Date: 05/19/2012
Close Date: 05/29/2012

Meter Reading: 75,145.00

Problem?

warning buzzer will not stop buzzing. E14

Task performed:

PHONE CALL ONLY.

Parts

NO PARTS USED

Quantity

Workorder: V49721

In Date: 05/29/2012
Close Date: 05/30/2012

Meter Reading:

Problem?

E14 is ready to be picked up.

Task performed:

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V49864

In Date: 06/04/2012 Meter Reading: 75,260.30
Close Date: 06/06/2012

Problem?

Need #6 containers of 2 cycle oil.

Task performed:

DROPPED OFF 2 CYCLE OIL TO TRUCK

Parts

NO PARTS USED

Quantity

Workorder: V49708

In Date: 05/29/2012 Meter Reading: 75,260.30
Close Date: 06/07/2012

Problem?

B INSPECTION E 14

Task performed:

1. B INSPECTION
2. B INSPECTION
3. R&R RIGHT REAR LOWER MARKER LIGHT AND LEFT SIDE CENTER LOWER MARKER LIGHT.
4. TIGHTEN EXHAUST HANGERS.
5. FREE UP, CLEAN AND LUBE BATTERY SLIDE OUT AND TRASH LINE SLIDE OUT.
6. CHECK FOR AIR LEAKS, REPLACE FITTINGS ON GOVERNOR.
7. FREE UP RIGHT REAR SLIDE OUT STEP, CLEAN AND LUBE ROLLERS, FULL OF SAND AND ROCKS.
8. REPLACE REAR REFLECTORS.
9. R&R REAR UPPER PULL OFF MARKER LIGHTS.

Parts

35200-RLIGHT MARKER LED RED 2
 35200-YLIGHT MARKER LEDAMBER 1
 372000084MARKER LIGHT 1
 98032R 41032-3 RED REFLECTOR OVAL REFLECTOR 2
 FS1022FILTER FUEL WIX 33422 PS8689 FRAM 1
 HPH6349AOIL FILTER 51748 1
 R90PFILTER FUEL 33231 1

Quantity

Workorder: V50498

In Date: 06/29/2012 Meter Reading: 75,691.50
Close Date: 07/02/2012

Problem?

EME LTS INOP E 14

Task performed:

TRAVEL TO 14 REPLACED MINI NODE #3 AND REPROGRAMMED.

Parts

601000000NODE MINI V-MUX 6010-0000-00

Quantity

1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V50532

In Date: 07/02/2012 Meter Reading: 75,691.50
Close Date: 07/03/2012

Problem?

No Nut on tank to pump valve.

Task performed:

TRAVEL TO 14 REPLACED NUT AND LOCK WASHER
ON TANK TO PUMP HANDLE.

Parts

NO PARTS USED

Quantity

Workorder: V50585

In Date: 07/03/2012 Meter Reading: 760,112.00
Close Date: 07/06/2012

Problem?

right front blinker on top of the fender is broke and hanging on. E 14

Task performed:

TRAVEL TO 14 REPLACED L/F SIGNAL LIGHT.

Parts

6808200020LIGHT ASSY. TURN SIGNAL

Quantity

1

Workorder: V50680

In Date: 07/08/2012 Meter Reading: 760,112.00
Close Date: 07/12/2012

Problem?

ROOF SPOT LIGHT NOT MOVING FOR POSITIONING..... LIGHT DOES COME ON. E14

Task performed:

REPLACED BULB IN SPOT LIGHT.

Parts

H3-100WBP1210H3 BULB

Quantity

1

Workorder: V51051

In Date: 07/23/2012 Meter Reading: 76,543.40
Close Date: 07/25/2012

Problem?

right side spot light is out E14

Task performed:

REPLACED SPOT LIGHT BULB.

Parts

4435HEADLIGHT

Quantity

1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V51030

In Date: 07/21/2012
Close Date: 07/27/2012

Meter Reading: 76,543.40

Problem?

right scene light out not working. E 14

Task performed:

1. TRAVEL TO 14 REPAIRED MELTED WIRES TO SIDE SCENE LIGHT.
2. REPLACED SCENE LIGHT HEAD.

Parts

Quantity

FCA100-V15LED SCENELIGHT HEAD

1

Workorder: V52289

In Date: 09/10/2012
Close Date: 09/19/2012

Meter Reading: 77,783.00

Problem?

drain hose came off e 14

Task performed:

FOUND DECK GUN DRAIN HOSE PULLED OUT OF COMPRESSOR FITTING REINSTALLED HOSE AND TIGHTEN FITTINGS.

Parts

Quantity

NO PARTS USED

Workorder: V52362

In Date: 09/13/2012
Close Date: 09/24/2012

Meter Reading:

Problem?

E14 no rear lights.

Task performed:

TRVL TO 14 REPLACED AND REPROGRAMMED NODES.

Parts

Quantity

600000003NODE HERCULES V-MUX

1

601000000NODE MINI V-MUX 6010-0000-00

1

Workorder: V52842

In Date: 10/04/2012
Close Date: 10/12/2012

Meter Reading:

Problem?

rear discharge leaks causing hose to fill in bed of truck E 14

Task performed:

TRVL TO 14 REBUILD AND TEST VALVE FOR REAR DISCHARGE

Parts

Quantity

91398907 VALVE KIT 3 IN AKRON

1



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10152028

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V53256

In Date: 10/23/2012

Meter Reading: 78,567.00

Close Date: 10/29/2012

Problem?

Replace handle for drain valve E14

Task performed:

TRAVEL TO ST 14 R&R DRAIN HANDLE ON PASS SIDE INTAKE VALVE.

Parts

012-0010-00KNOB DRAIN

Quantity

1

Workorder: V53849

In Date: 11/18/2012

Meter Reading:

Close Date: 11/28/2012

Problem?

Right siren is out on E14.

Task performed:

WENT TO 14- R/R RT SIREN DRIVER CH OK.

Parts

NO PARTS USED

Quantity

Workorder: V54051

In Date: 11/28/2012

Meter Reading:

Close Date: 11/29/2012

Problem?

While returning from call we heard a loud pressure relief sound. Checked under hood and found the cast 90 intake fitting appears to have had the flange broke off. E14

Task performed:

TRAVEL TO 14 CHECKED TRUCK FOUND TURBO 10-7 TOOK DRIVER TO 15 TO PACK UP SPARE TRUCK.

Parts

NO PARTS USED

Quantity

Workorder: V54145

In Date: 12/03/2012

Meter Reading: 79,334.00

Close Date: 12/17/2012

Problem?

replace turbo charger

Task performed:

1. REMOVE TURBO FROM ENGINE, TURBO COOLER REMOVED TO BE CLEAN.
2. COMPLETE WORK ON TURBO, INSTALLED INTERCOOLER HOSES CLEAN CHECK FOR LEAK DRIVE.
3. REPAIR HOSE BED CLIPS, BRAKES OF REPLACE A NEEDED REPLACE CLIPS ON TRUCK BODY DRIVE OUT 945 BAD ONE AND RIVET IN NEW ONE.

Parts

- 3818824TURBO NUT
- 3883284O-RING AIR INTAKE
- 3883977TURBO ELBOW
- 4955658RXTURBO REPLACES 3800401RX
- CLEAN AND TESTCOOLER/RADIATOR

Quantity

- 4
- 1
- 1
- 1
- 4



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V54485

In Date: 12/18/2012

Meter Reading:

Close Date: 12/20/2012

Problem?

pump on E14 leaking.

Task performed:

TRAVEL TO ST 14 CHECK OUT PUMP LEAKING AT FOAM CHECK VALVE IN PIPING R&R PIPE. CHECK RUSTED ON PIPE FLANGE R&R CHECK AND RE-INSTALLED PIPING AND BOLTS TEST OK.

Parts

Quantity

0381570000038-1570-06-0 VALVE CHECK 3 IN 9003-1

1

0460050000GASKET

4

Workorder: V54676

In Date: 01/02/2013

Meter Reading:

Close Date: 01/04/2013

Problem?

right side appliance holder is rusted and unable to use. e14

Task performed:

TRAVEL TO 21 REPLACED NADAR PIN.

Parts

Quantity

NO PARTS USED

Workorder: V55206

In Date: 01/22/2013

Meter Reading: 80,357.60

Close Date: 01/23/2013

Problem?

request a set of wiper blades sent to st14 for engine, priority 3.

Task performed:

REPLACED WIPER BLADES.

Parts

Quantity

52-24WIPER BLADES ANCO 24

2

Workorder: V55484

In Date: 02/01/2013

Meter Reading:

Close Date: 02/04/2013

Problem?

E14 COMPARTMENT LIGHTS OUT.

Task performed:

TRAVEL TO 14 L-1 AND L-1 AND R-1 LIGHTS OUT ONLY REPLACED NODE FOUR AND REPROGRAMMED.

Parts

Quantity

601000000NODE MINI V-MUX 6010-0000-00

1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V55596

In Date: 02/07/2013
Close Date: 02/11/2013

Meter Reading: 80,357.60

Problem?

COMPT LIGHTS OUT E 14

Task performed:

TRAVEL TO 14 REPROGRAMMED NEW U-MAX NOSE

Parts

NO PARTS USED

Quantity

Workorder: V55665

In Date: 02/08/2013
Close Date: 02/14/2013

Meter Reading:

Problem?

drivers side rea upper amber emer. light inop. E14

Task performed:

TRAVEL TO 14 REPLACED BULB IN ROTATOR.

Parts

H35SN12BULB
RB6PAPRB6PAP ROTATING BEACON AMBER

Quantity

1
1

Workorder: V55674

In Date: 02/10/2013
Close Date: 02/14/2013

Meter Reading:

Problem?

left top rear emergency light needs bulb. E14

Task performed:

CHECKED ALL LIGHTS OK.

Parts

NO PARTS USED

Quantity

Workorder: V51932

In Date: 08/27/2012
Close Date: 04/08/2013

Meter Reading: 77,292.70

Problem?

Door open alarm will not shut off, alarm disconnected. E 14

Task performed:

CHECKED OK.

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V56230

In Date: 03/07/2013

Close Date: 04/11/2013

Meter Reading: 81,227.90

Problem?

C inspection

Task performed:

Parts

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

1. C-INSPECTION - GREASE HALE VALVES. CUT AND FIT FRONT SUCTION STRAINER.
2. REPAIR VALVE CORE LEAKS. REPLACED VALVE STEM CORES AND AIR TIRES ON RRO AND LRO TIRES. REPAIR LEAK AT VALVE STEM ON RRI TIRE.
3. SERVICE AIR DRYER.
4. SERVICE TRANS.
5. REMOVE AND FREE UP MON PUMP DRAIN.
6. REMOVE AND REPAIR COOLANT FILTER HOUSING.
7. PRESSURE TEST SYSTEM, REPLACE SIGHT GLASS TIGHTEN ALL HOSES.
8. ADJUST FRONT BRAKES.
9. TIGHTEN ALL EXHAUST CLAMPS.
10. START TROUBLE SHOOT EXTENDA GUN WORKING INOP TOLD TO LEAVE ALONE PER ED E.
11. SERVICE T-CASE.
12. SERVICE DIFF.
13. TIGHTEN MAN SAVERS.
14. REPLACE CAB CLEARANCE LIGHT BULB AND LEFT REAR CAB DOOR FENTRY LIGHT.
15. REMOVE HOSE BED COVER.
16. R&R REAR BRAKES, DRUMS AND BUSHINGS.
17. CALIBRATE FOAM.
18. TIGHTEN AND ADJUST ALL COMP DOOR LATCHES.
19. REPLACE TOP PUMP PANEL PRIMER VALVE, REBUILD RIGHT SIDE PUMP PANEL PRIMER VALVE.
20. START TROUBLESHOOT FAILED DRY VAC. TEST. REPLACE INTAKE CHECK VALVE AND SENSE VALVE.
21. CONTINUE TROUBLESHOOT PUMP REBUILD INTAKE RELIEF VALVE AND CROSS LAY VALVES.
22. CONTINUE TROUBLE SHOOT PUMP VACUUM. REBUILD RE?? VALVE AND TANK TO PUMP.
23. TROUBLE SHOOT PUMP.
24. TROUBLE SHOOT PUMP.
25. TROUBLE SHOOT PUMP.
26. HELP BILL WITH RELIEF VALVE INSTALL.
27. TROUBLE SHOOT PUMP.
28. TROUBLE SHOOT PUMP.
29. TROUBLE SHOOT PUMP.
30. TROUBLE SHOOT PUMP.
31. TROUBLE SHOOT PUMP, FOUND PROBLEM THERE WAS AIR TRAPPED IN PUMP MANIFOLD CAUSING RELIEF VALVE TO OPEN.
32. RESCURE ALL PUMP LINES.
33. TROUBLE SHOOT REAR THREE COMPARTMENTS NOT WORKING DOOR ADJAR LIGHT.
34. CHASE AIR LEAKS.
35. TROUBLE SHOOT DOOR ADJAR LIGHT, REPAIR WIRES IN OVERHEAD FOR RELAY.
36. TROUBLESHOOT PRESSURE RELIEF VALVE AND LIGHT INOP.

0100080010	STRAINER	2
0106837849	C8COMP LIGHT WHITE LED 200	1
038-0191-00	CONTROL VALVE	1
038-1010-01	HALE RELIEF VALVE W/ VULCANIZED SEAT	1
038-1290-00	VALVE-SENSING NEEDLE	1
038-1550-00	VALVE CHECK HALE 1/4"	1
040-1130-03	RING-PISTON SEAL (QG RELIEF VALVE)	1
042002000	SPRING RELIEF VALVE HALE	1
073-0190-01	PISTON TPM RELIEF VALVE	1
082-2007-00-0	GREASE ZERK W/CHECK VLV	3
107796	DRYER KIT AD9 -NEW	1
107800	VALVE CHECK AD9	1
108-12	FBEADED CHAIN W/CONN 12	6
15W40	BSYN OIL BULK QTS	25
1893	BULB	2
200226200200-2262-50	SWITCH-PROXIMITY QG VALVE	1
29526898 29548988	TRANS FILTER ALLISON	1
39768315259022	GROOVED TENSIONER OLD#3936213	1
52-24	WIPER BLADES ANCO 24	2
538-1410-00	VALVE SENSING SV HALE	1
538028052	VALVE PRIMER PUMP W/HARDWARE	1
546-2210-02-0	LIGHT KIT HALE	1
546085303	NC SWITCH/BRACKT	1
546126000	TPM/QG HALE REPAIR KIT	3
5462270020	VALVE KIT SS 546-2270-02-0	3
5462300020	VALVE KIT SS VALVE 3 IN	1
715000000501	1/2 IN VALVE SS 715-0000-00-50	1
78R539018-2699	A/C FILTER	1
800405	PURGE VALVE KIT	1
9440	BELT	1
9480	BELT	1
EAA-8350-30	UGSS1783UQ STRUT-LIFT	1
FS1022	FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349A	OIL FILTER 51748	1
K080716	BELT	1
MJTV5	VALVE AIR CONTROL	1
PVG-KIT	ORING KIT	1
R90P	FILTER FUEL 33231	1
S777	COUPLING NIPPLE	2
WAT61403	STRAINER 6 IN	1
91-18	WIPER BLADE	2
3576	REAR BRAKE DRUMS	2
XK4034707	QPMHD SHOE KIT 3/8 BEAM	2
3937367	GASKET 4942874	1
PR338324070	WIX FILTER WATER	1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

- 37. TROUBLE SHOOT PRESSURE RELIEF VALVE 2 LIGHT.
- 38. TROUBLESHOOT PRESSURE RELIEF VALVE AND LIGHT, REPLACE SWITCH AND FLASHER.
- 39. TROUBLESHOOT PRESSURE RELIEF VALVE AND LIGHT, REBUILD VALVE.
- 40. TROUBLESHOOT FOUND BAD GROUND CONNECTION IN PLUG, INSIDE PUMP PANEL, REPAIR PLUG, REWIRE TI ALL WIRES CHECK OK.
- 41. TIGHTEN ALL DOOR LATCHES 2 STRUTS.
- 42. TROUBLE SHOOT AIR HORN NOT WORKING ON HORN PAD, REPAIR WIRE ON SWITCH.
- 43. Q. A. INSPECTION.

VML-T1413T3248 SIGHT GLASS	1
5462280020VALVE KIT 2 IN SS VALVE 546-2280-02-0	2
8126482-2106 TOGGLE GUARD	1

Workorder: V57212

In Date: 04/23/2013 Meter Reading: 81,925.00
 Close Date: 04/23/2013

Problem?
 quartz light up indicator going off

Task performed:	<u>Parts</u>	<u>Quantity</u>
WENT TO STATION FOUND COLLARS FOR LIGHTS SLIPPERS PAST MAGNETS ADJUSTED TESTED OK.	NO PARTS USED	

Workorder: V55595

In Date: 02/07/2013 Meter Reading: 80,357.60
 Close Date: 04/24/2013

Problem?
 on call no lights on rear e14

Task performed:	<u>Parts</u>	<u>Quantity</u>
NO LIGHT IN REAR OF TRUCK AT ALL EMS, LIGHT COMING ON ALL BY THEIRSELF.	601000000NODE MINI V-MUX 6010-0000-00	1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V56950

In Date: 04/10/2013
Close Date: 05/01/2013

Meter Reading: 81,227.90

Problem?

Flat repair l/f after hours

Task performed:

FLAT REPAIR L/F AFTER HOURS.

1. FOAM SYSTEM PURPOSLY DISABLED AND RE=ROUTED DUE TO FOAM TOO THICK FOR PUMP. RE-SEAL AND BOLT UP LOWER PANEL. DISABLED BY W.P.B.
2. NO DETROIT PROGRAM IN SHOP LAP TOP. BORROWED LAP TOP FROM ROB. ED AND I CHECKED ENGINE CODES AND TECH SUPPORT.
3. REPLACED L WINDOW SQUITER.
4. DIAGNOSE COOLANT LEAK - FOUND LEAK COMING FROM LINE CRIMP FOR AIR COMPRESSOR. DRAIN COOLING SYSTEM AND STARTED TO REMOVE LINE.

Vendor?: BOULEVARD TIRE CENTE

Parts

Quantity

NO PARTS USED

Workorder: V57588

In Date: 05/08/2013
Close Date: 05/13/2013

Meter Reading:

Problem?

TIC charger not working properly E14

Task performed:

TRAVEL TO 14 INSTALL TIC CHARGER.

Parts

Quantity

NO PARTS USED

Workorder: V58488

In Date: 06/17/2013
Close Date: 06/19/2013

Meter Reading: 83,205.20

Problem?

mount equip for 5 inch hose

Task performed:

MOUNT WRENCHES ON TRUCK FOR 5" HOSE.

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V58596

In Date: 06/21/2013

Meter Reading:

Close Date: 06/21/2013

Problem?

need hydrant bag since e14 bag has hole !!!

Task performed:

forwarded to Wayne

Parts

NO PARTS USED

Quantity

Workorder: V58501

In Date: 06/17/2013

Meter Reading: 83,205.20

Close Date: 07/03/2013

Problem?

Need to have a mounting bracket for the 5 inch attached to the back of E14. Thanks.

Task performed:

REMOUNTED AND MOVED BRACKETS FOR MOUNTING EQUIPMENT.

Parts

22635MUFFLER

3541435414 CLAMP 2 1/2"

Quantity

1

2

Workorder: V58786

In Date: 06/30/2013

Meter Reading: 83,523.00

Close Date: 07/03/2013

Problem?

Pressure relief valve will not disengage. E 14

Task performed:

TRAVEL TO 14 EXERCISED RELIEF VALVE WORKS FINE.

Parts

NO PARTS USED

Quantity

Workorder: V59027

In Date: 07/11/2013

Meter Reading: 83,523.00

Close Date: 07/12/2013

Problem?

VENTILATION FAN STILL NOT WORKING. SITTING IN BAY AREA. 2ND REQUEST

Task performed:

LIGHT DUTY DELIVERED.

Parts

NO PARTS USED

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V58859

In Date: 07/04/2013 Meter Reading: 83,523.00
Close Date: 07/15/2013

Problem?

unable to start the gas power fan/ram fan

Task performed:	Parts	Quantity
UNIT PICKED UP BY SHOP.	NO PARTS USED	

Workorder: V59157

In Date: 07/17/2013 Meter Reading: 83,523.00
Close Date: 07/19/2013

Problem?

Medical compartment door leaking from under hard suction hose into medical compartment. Notified shop.

Task performed:	Parts	Quantity
SEALED INNER COMPARTMENT WALLS.	NO PARTS USED	

Workorder: V59165

In Date: 07/17/2013 Meter Reading: 83,523.00
Close Date: 07/19/2013

Problem?

Water leak in medical compartment

Task performed:	Parts	Quantity
TRAVEL TO 14 RESEALED TOP OF COMPARTMENT AND SECURED SCREWS.	NO PARTS USED	

Workorder: V59287

In Date: 07/23/2013 Meter Reading: 83,965.30
Close Date: 07/29/2013

Problem?

The pressure relief valve is not working properly. The light will not shut off and it does not hold with a increase in pressure. The rear door in the back also has a broken hydraulic piston. E14

Task performed:	Parts	Quantity
1. TRAVEL TO 14 CHECKED RELIEF VALVE AND WORKS FINE NEEDS SENSOR FOR LIGHT ALL ELSE OK.	200226200200-2262-50 SWITCH-PROXIMITY QG VALVE	1
2. TRAVEL TO 14 REPLACED SENSOR IN RELIEF VALVE FOR WARNING LIGHT.	EAA-8350-30UGSS1783UQ STRUT-LIFT	2
3. REPLACED HOLD OPEN ON REAR COMPARTMENT DOOR.		



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V59397

In Date: 07/29/2013
Close Date: 07/31/2013

Meter Reading: 84,018.40

Problem?
air leak

Task performed:

CHECKED FOR AIR LEAKS FOUND BRAKE VALVE LEAKING. REPLACED PARKING BRAKE VALVE AND REPAIRED 2 LEAKS UNDER BODY. OK.

Parts

NO PARTS USED

Quantity

Workorder: V60042

In Date: 09/12/2013
Close Date: 09/18/2013

Meter Reading: 84,463.60

Problem?
ENGINE 14-TEMP GAUGE BROKEN ON PUMP PANEL.

Task performed:

TRAVEL TO 14 DRIVER COMPLAINT TEMP GAUGE BROKEN. FOUND LOOSE CONNECTION TO GAUGE AND REPAIRED.

Parts

NO PARTS USED

Quantity

Workorder: V61031

In Date: 10/05/2013
Close Date: 10/09/2013

Meter Reading:

Problem?
need power source for tablet on E14, tablet needs constant power source when vehical and power is off.

Task performed:

1. TRAVEL TO 14 DRIVER COMPLAINT OF NO POWER SERGE FOR TRIP TIX INSTALLED ADAPTOR TO BATTERY.

Parts

56415CIG. LIGHTER ACCES.

2

Quantity

Workorder: V61073

In Date: 10/07/2013
Close Date: 10/09/2013

Meter Reading:

Problem?
E14 front ac not functioning. Rear is functioning

Task performed:

DRIVER COMPLAINT A/C INOP IN CAB. CHECKED SYSTEM FOUND A/C SWITCH 10-7. REPLACED A/C SWITCH.

Parts

ABPN8332229011-3050 SWITCH BLOWER

1

Quantity



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V61072

In Date: 10/07/2013

Meter Reading:

Close Date: 10/10/2013

Problem?

The E14 cig lighter is not able to charge the new trip tix pad unless battery switch is on

Task performed:

Parts

Quantity

REPAIRS MODE ON TICKET V61031.

NO PARTS USED

Workorder: V64808

In Date: 03/10/2014

Meter Reading: 86,546.00

Close Date: 03/13/2014

Problem?

REPAIR PRIMER

Task performed:

Parts

Quantity

- CHECK OUT TRUCK, FOUND BAD PRIMER MOTOR. REPLACE AND WIRE IN NEW ON TO TRUCK.
- CHECK OUT TRUCK FOR RESERVE RESCUE UNIT READY FOR ON CALL REPLACEMENTS.

501-3090-00PRIMER PUMP MOTOR

1

Workorder: V62439

In Date: 12/03/2013

Meter Reading: 86,746.00

Close Date: 03/28/2014

Problem?

B inspection SE5

Task performed:

Parts

Quantity

b inspection
oil and filter

FS1022FILTER FUEL WIX 33422 PS8689 FRAM

1

HPH6349AOIL FILTER 51748

1

R90PFILTER FUEL 33231

1

Vendor?: OCS

Workorder: V64414

In Date: 02/20/2014

Meter Reading: 86,546.00

Close Date: 04/01/2014

Problem?

repairs from inspection

Task performed:

Parts

Quantity

- COOLANT LEAK- TIGHTEN FLARE FITTING AT REAR OF ENIGNE.
- TRANSMISSION NEEDED 1 QT- RETARTER NEEDED TO BE REBUILT.

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V65330

In Date: 03/31/2014
Close Date: 04/01/2014

Meter Reading: 86,546.00

Problem?
dead

Task performed:

1. JUMP STARTED TRUK IN PARKING LOT. BROUGHT TRUCK INSIDE TO REDUCE BATTERIES. FOUND BATTERY DRAW, REROUTED ALL ACCEORY WIRES AND CABLES TO BATTERY SWITCH OR FRAME RAIL. REPLACED NUMEROUS TERMNAL ENDS. ALSO CHECKED CHARGING SYSTEM. ALL GOOD. DRAW IS LONGER A PROBLEM.
2. RECHECKED TRUCK FOR VOLTAGE DRAW. FOUND BATTERIES AT FULL CHARGE. RECHECKED ALL CONNECTIONS AND PARKED TRUCK.

Parts	Quantity
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
HP-31DBATTERY 950CCA HP-31D	4

Workorder: V65829

In Date: 04/19/2014
Close Date: 04/21/2014

Meter Reading:

Problem?

Drivers window closed but completely seperated from regulator. Unable to open without it being falling into door and being permantly open. E91

Task performed:

WORK DONE ON V65843.

Parts	Quantity
NO PARTS USED	

Workorder: V65427

In Date: 04/03/2014
Close Date: 04/25/2014

Meter Reading: 86,856.70

Problem?

E91 no power to battery stud in cabinet behind console. Causing MDT not to work

Task performed:

RECONNECTED POWER TO SWITCH.

Parts	Quantity
NO PARTS USED	



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V66267

In Date: 05/06/2014

Meter Reading:

Close Date: 05/13/2014

Problem?

No emergency lights or any other lights that work off control panel.

Task performed:

Parts

Quantity

DRIVE TO ST-91 CHECK FOR LIGHTS NOT WORKING FOUND.
BATTERIES WERE LOOSE ON POSITIVE CABLES TIGHT ON AND CHECK POWER SWITCH, TEST IS GOOD NOW.

NO PARTS USED

Workorder: V66276

In Date: 05/06/2014

Meter Reading:

Close Date: 05/13/2014

Problem?

Engine is not going into pump gear. In addition, almost all emergency lights are not working. Lastly, if possible, the gas cap for the gas powered fan needs repair/ fixing to prevent gas from leaking.

Task performed:

Parts

Quantity

PINCHED NODES. ALL NOT REPLYING EXCEPT SCREEN. UNPLUG NODES ON BACK BUMPER FOUND NODE 2 FAULTY PROGRAM NEW NODE AND INSTALL ALL OK AT THIS TIME.

600000003NODE HERCULES V-MUX

1

Workorder: V66217

In Date: 05/04/2014

Meter Reading:

Close Date: 05/14/2014

Problem?

No emergency lights. no scene lights. no taillights. turned truck and batteries on and off several times no help. E91

Task performed:

Parts

Quantity

TRACED OUT PROBLEM FOUND NODE BAD REPROGRAMMED NODE AND TESTED.

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V65647

In Date: 04/11/2014

Meter Reading:

Close Date: 05/21/2014

Problem?

passenger side window will roll up. Glass appears to have fallen off of track.

Task performed:

REMOVED DOOR PANEL AND PUT WINDOW BACK IN TRACK REMOVED WINDOW HANDLE SO WINDOW WILL NOT ROLL DOWN.

Parts

Quantity

6807200353GUIDE METAL	1
6807200446WINDOW REGULATOR	1
6809870055SEAL CAB WINDOW	1
DS60609-2BOTTOM CHANNEL GLASS	1

Workorder: V66202

In Date: 05/03/2014

Meter Reading:

Close Date: 05/21/2014

Problem?

Driver's window inoperable and in the DOWN position E91

Task performed:

DRIVE TO STA-91 REMOVED DRIVER SIDE FOUND WINDOW AND TRACK FOUND OUT WE ORDERED WRONG PARTS. PARTS ARE FOR PASSENGER SIDE, NEED TO REORDER PARTS AGAIN.

Parts

Quantity

6807200146REGULATOR	1
6807200253GUIDE METAL	1

Workorder: V66395

In Date: 07/21/2014

Meter Reading: 87,533.00

Close Date: 07/29/2014

Problem?

A inspection SE5

Task performed:

- 1.Work on"A" Inspection
- 2.Work on "A" Inspection and repairs. Replace hood latch catsher. Repair wires to rear deck lights. Repair LR tire valve steems and adjust to specs.
- 3.Complete repair on rear light wire harness. Replace left rear light bulb. Adjust brackets to lights. Test for operation its good now.
- 4.Install driver door window regulator. Window track and seal. Modify seal frame to make it work on the door.
- 5.Clean up driver door window. Removed tint it was too damage. Also removed logos from rear doors.

Parts

Quantity

17-14781-000PLASTIC HOOD LATCH	1
4435HEADLIGHT	1
44364436 BULB	1
60A00TARLED TURN SIGNAL LAMP	1
6807200253GUIDE METAL	1
6807250001CHANNEL GLASS	1
6807250121CUSHION	1
68118358130600 SER OPTIC CLEAR	1
68318358750600 NON OPTIC RED LENS	2
S777COUPLING NIPPLE	1
S986AIR GAUGE 160 PSI	1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V65843

In Date: 04/21/2014

Meter Reading:

Close Date: 08/06/2014

Problem?

drivers side window came off track, turn over from previous D/O advised may need new track due to rust. E91 (SEE NOTES)

Task performed:

see notes.
WORK WAS COMPLETE ON SER, AT SHOP ON W/O
V66395

Parts	Quantity
23-12982-712COVER SCREW	2
A1818557002HANDLE-WINDOW	1
DS60609-2BOTTOM CHANNEL GLASS	1

Workorder: V69267

In Date: 09/10/2014

Meter Reading: 87,533.00

Close Date: 10/27/2014

Problem?

A-inspection Smells like a fuel leak Check front tires

Task performed:

1. A Inspection and check for fuel leak.

Parts	Quantity
NO PARTS USED	

Workorder: V69972

In Date: 10/07/2014

Meter Reading: 87,533.00

Close Date: 11/04/2014

Problem?

check engine light, throttle stutters

Task performed:

1. Check engine light on. Jump start vehicle. Stone dead. Test batteries after charging - no good. Replace batteries. Also noticed that all electrical connections on frame mounting gang studs were corroded and dirty. Disassemble and clean 4 positive and 2 negative gang studs and cable wiring. Road test to check out throttle stutter. Check engine light was not on. On road test, throttle stuttered only once. Came back to shop and changed fuel filter. Check for engine codes. Only code was for low voltage but new batteries fixed that. Road test again and only stuttered once. Recheck for codes and again, no codes. Will start up cold next day and road test. This time only one stutter but put check engine light on also. Check codes. Had code for bad accumulator pressure switch. Replace pressure switch. Also replaced throttle pedal switch.

Parts	Quantity
4025130FUEL PRESS SENSOR	1
78R536078R5360M 2PK FILTER AIR COND	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	4
R90PFILTER FUEL 33231	1
RAIRK30880N122WSKL4000 SENSOR WATER IN FUEL	1
RK211131311FUEL BOWL KIT NON-HEATED	1
WIL-131973TPS SENSOR	1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V69278

In Date: 09/10/2014

Meter Reading: 87,533.00

Close Date: 01/08/2015

Problem?

tempurature gauge on Class 1 control not working SE 5 AT TRAINING

Task performed:

Parts

Quantity

1. Diagnose no tmeq showing on class 1 engine status center on pump panel.
2. Continued diagnosis of no temp showing-see above
3. Cont. above repair-now fixed

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V71705

In Date: 12/17/2014

Meter Reading: 87,906.00

Close Date: 01/20/2015

Problem?

C inspection SE5

Task performed:

- 1-2. C inspection
3. Air up all tires to correct PSI
4. Replace front suction screen-have to cut to size
5. Service pump transmission and oil change etc
6. Replace missing air filter housing hardware
7. Clean, lube and adjust latches for pump panel access
8. Troubleshoot and repair compartment open warning system. Remove center and R/S overheated consoles to access wiring. Repair wiring to buzzer and light.
9. R/R lens, R/R bulbs clean contacts 4f fender marker ll
10. R/R 4R side marker light assy. clean ground wire and contact area
11. Tighten comp R-1 hold open, mounting hardware
12. R/R 2 of 3 tailboard marker lts
13. R/R mid body marker lt-clean connections-threads stripped had to use another type of fastener.
14. R/R lens, R/R bulb in rear tag lt
15. Deckgun raised warning system diag and repair
16. R/R booster reel swivel assy
17. Service P/S system, R/R oil, filter and gasket
18. AD-9 drier service and check valve
19. R/R u joint in drive shaft
20. Lube primer pump assy
21. Start diagnosis of foam pump not working
22. R/R foam pump assy separator pump for motor. R/R motor with rebuilt one.
23. Remove hose bed cover for repair
24. Drain cooling system, R/R coolant filter hedder. R/R coolant shut off valve assy and all o-rings.
25. R/R cab hovrmeter
26. Dry vac test and look for leaks
27. Repair bracket for deck gun-discharge pipe.
28. R/R overhaul deck gun disch valve
29. Reinstall hose bed cover and replace 2 broken female buckles at rear crossbar
30. Test foam system operation after foam pump repair-flowed foam out booster reel and flush system.
31. Road test veh to heat trans fluid to check dipstick against electronic fluid level(says 2 qts low) fluid is low add 2 qts.

Parts	Quantity
045-0770-00108494-00 MOTOR ELECT HALE FOAM PUMP	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
35200-RLIGHT MARKER LED RED	3
35200-YLIGHT MARKER LEDAMBER	1
3818885O-RING WATER SHUT OFF	2
3920773WASHER DRAIN PLUG	1
3937367GASKET 4942874	1
39437394940547 SHAFT SHUT-OFF VALVE	1
3943740SHAFT SHUT-OFF VALVE	1
39438574989614 SEAL O-RING SHUT-OFF VALVE	1
39444543977737 SCREW SHUTOFF VALVE	1
5-280XU-JOINT	1
6809880678STUD DZ	1
800405PURGE VALVE KIT	1
8534203HRS METER 85342-03	1
91398907 VALVE KIT 3 IN AKRON	1
BD5501516160BD55015-1616-01 SWIVEL	1
CA8193AIR FILTER 46744 WIX	1
EXO3AH00015SPLUG RAD. DRAIN	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
PR338324070 WIX FILTER WATER	1
WAT61403STRAINER 6 IN	1
R90PFILTER FUEL 33231	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V72916

In Date: 02/05/2015
Close Date: 02/06/2015

Meter Reading: 87,940.00

Problem?

replace rear tires

Task performed:

REPAIRS AS REQUESTED.

Parts

Quantity

NO PARTS USED

Vendor?: BLVD TIRE CENTER

Workorder: V73008

In Date: 02/09/2015
Close Date: 02/23/2015

Meter Reading: 88,022.00

Problem?

A INSPECTION

Task performed:

1. A Inspection. a. Windshield b.Top off coolant level 3. Top off washer fluid bottle.
2. 2 streamlight charging stations in cab damaged. Remove and install 2 new charging stations.
3. Pump compartment light inop. Check for voltage. Supply line good. Check light assembly good. Check ground. Found poor ground. Remove light ground. Clean contacts and reassemble.

Parts

Quantity

NO PARTS USED

Workorder: V74130

In Date: 03/24/2015
Close Date: 03/24/2015

Meter Reading: 88,682.30

Problem?

passenger headlight out @ ST41

Task performed:

replace r/side headlight

Parts

Quantity

H6054BLH6054CVC1 HEADLIGHT EXTRA BRIGHT

1

Workorder: V71593

In Date: 12/11/2014
Close Date: 06/30/2015

Meter Reading: 87,533.00

Problem?

engine stumbles

Task performed:

Parts

Quantity

NO PARTS USED



4/27/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10152028

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V73762

In Date: 03/09/2015

Meter Reading:

Close Date: 06/30/2015

Problem?

Spare engine is having hesitation during acceleration E41

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V74667

In Date: 04/15/2015

Meter Reading: 89,302.50

Close Date: 07/07/2015

Problem?

fuel leak

Task performed:

Parts

Quantity

NO PARTS USED



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10152028) 2003 - FERRARA FL80 1250 Gpm Pumper

10152028

CSHOP-2015-1562

Comments: A INSPECTION RED MARKER ON HOOD FALLING OFF E 20 SAFETY PAD DOES NOT CHARGE WHEN BATTERIES ARE OFF

Date Opened: 7-6-2015 Date Finished: 7-15-2015 Meter 1 Reading: 91,504

TASKS PERFORMED

Q PARTS

A INSPECTION	1	LIGHT; MARKER LIGHT
WIPER BLADES	1	9IP; 600 NON OPTIC RED LENS
OIL	1	FILTER; 78R5360M 2PK FILTER AIR COND
LIGHTING SYSTEM	2	WIPER; WIPER BLADES ANCO 24
ELECTRICAL		
VALVE STEM		
TIRES ALL		
SEAT FRONT		
A/C FILTER SCREENS		

CSHOP-2015-2077

Comments: CIGARETTE ADAPTER SE@21

Date Opened: 8-3-2015 Date Finished: 8-4-2015 Meter 1 Reading: 91,504

TASKS PERFORMED

Q PARTS

WAIT TIME TO BE CHARGED TO WORK ORDER	1	SWITCH; CIG. LIGHTER ACCES.
TRAVEL TO BE CHARGED TO WORK ORDER		
ELECTRICAL		

CSHOP-2015-2124

Comments: REPAIR FLAT

Date Opened: 8-4-2015 Date Finished: 8-4-2015 Meter 1 Reading: 91,504

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? EARL COLVARD BOULEVARD TIRE

CSHOP-2015-2136

Comments: A INSPECTION FOAM SYSTEM INOP SE@21

Date Opened: 8-4-2015 Date Finished: 9-15-2015 Meter 1 Reading: 92,409

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	1	SWITCH; 82-2106 TOGGLE GUARD
A INSPECTION	1	SWITCH; 82-2111 GROTE ON-OFF WEATHERPROOF
FOAM SYSTEM		
HOSE BED BODY		

Asset Work Order History 10152028

CSHOP-2015-310

Comments: **E57 ALTERNATOR NOT CHARGING**

Date Opened: 4-27-2015 Date Finished 4-28-2015 Meter 1 Reading: 89,102

TASKS PERFORMED

Q PARTS

ALTERNATOR-GENERATOR

1 ALTERNATOR; 320 UPGRADE ALTERNATOR

CSHOP-2015-3778

Comments: **EMERGENCY LIGHTS INOP SPARE E19**

Date Opened: 11-4-2015 Date Finished 11-5-2015 Meter 1 Reading: 92,596

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 9IP; NODE MINI V-MUX 6010-0000-00

CSHOP-2015-4095

Comments: **A INSPECTION**

Date Opened: 11-23-2015 Date Finished 12-2-2015 Meter 1 Reading: 93,718

TASKS PERFORMED

Q PARTS

A INSPECTION
EQUIPMENT MOUNTING BRACKETS
OIL
PARK-CLEARANCE LIGHTS
TIRE

1 LIGHT; LIGHT MARKER LEDAMBER
1 LIGHT; MARKER LIGHT

Service Requests:

11/22/2015 ENGINE / 44: WORN / INSTALLED NEW STRAP
NEED NEW STRAP FOR CONES ON BACK OF ENGINE.

CSHOP-2015-4369

Comments: **SPARE ENGINE @ 53 DECK GUN LEAKING FROM PRESSURE GAUGE**

Date Opened: 12-8-2015 Date Finished 12-24-2015 Meter 1 Reading: 90,350

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM

Service Requests:

12/08/2015 LIGHTS / 19: LOOSE / OVERHAUL
DRIVER SIDE REAR SCENE LIGHT NOT WORKING-STATION 53 SPARE

12/11/2015 SERVICE REQUEST / 19: LOOSE / REPAIR
DECK GUN LEAKING FROM PRESSURE GAUGE

Asset Work Order History 10152028

CSHOP-2015-487

Comments: **E-57 SLOW STARTING**

Date Opened: 5-6-2015 Date Finished 5-12-2015 Meter 1 Reading: 89,202

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
STARTER
STROBE LIGHTS
AIR CONDITIONING

CSHOP-2015-568

Comments: **L/F TIRE LOW TREAD**

Date Opened: 5-11-2015 Date Finished 5-12-2015 Meter 1 Reading: 89,302

TASKS PERFORMED

NO PARTS USED

FRONT TIRES

CSHOP-2015-642

Comments: **REPLACED FRONT TIRES**

Date Opened: 5-14-2015 Date Finished 5-14-2015 Meter 1 Reading: 90,186

TASKS PERFORMED

NO PARTS USED

FRONT TIRES

VENDOR? EARL COLVARD BOULEVARD TIRE

CSHOP-2016-1071

Comments: **ON-CALL E34 NO REAR LIGHTS**

Date Opened: 3-7-2016 Date Finished 3-8-2016 Meter 1 Reading: 96,405

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

CSHOP-2016-1420

Comments: **CHECK ENGINE LIGHT WHEN ACCELERATING REPAIRED BY CUMMINS 3-25-16**

Date Opened: 3-24-2016 Date Finished 4-8-2016 Meter 1 Reading: 96,692

TASKS PERFORMED

NO PARTS USED

A INSPECTION

Asset Work Order History 10152028

CSHOP-2016-2255

Comments: **FOAM SYSTEM INOP AT ST20**

Date Opened: 5-10-2016 Date Finished 5-10-2016 Meter 1 Reading: 96,940

TASKS PERFORMED

NO PARTS USED

WAIT TIME TO BE CHARGED TO WORK ORDER
TRAVEL TO BE CHARGED TO WORK ORDER
FOAM SYSTEM

Service Requests:

05/10/2016 SERVICE REQUEST / 23: NOT CONNECTED / INSPECT
HALE FOAM GAUGE ON PUMP PANEL DOES NOT ILLUMINATE. CANNOT TELL IF DISPENSING FOAM OR NOT.

CSHOP-2016-242

Comments: **B INSPECTION SE5**

Date Opened: 1-19-2016 Date Finished 1-19-2016 Meter 1 Reading: 94,996

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FILTER; FILTER FUEL WIX 33422 PS8689 FRAM
1 FILTER; FILTER FUEL 33231
1 FILTER; OIL FILTER 51748

CSHOP-2016-257

Comments: **REPAIRS FROM INSPECTION**

Date Opened: 1-19-2016 Date Finished 1-21-2016 Meter 1 Reading: 94,996

TASKS PERFORMED

Q PARTS

HOSE BED BODY
LIGHTING SYSTEM
BATTERY
ELECTRICAL
SAFTEY-EMERGENCY EQUIPMENT
BODY EXTERIOR
DOOR PANEL
CAB-INTERIOR ACCESSORIES
A/C FILTER SCREENS

1 9IP; NODE HERCULES V-MUX
4 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
4 BATTERY; BATTERY 950CCA HP-31D
1 HORN; HORN HIGH NEW # 06-52125-039
1 HORN; HORN LOW NEW #06-52125-041
1 WINDOW; MOLD L/H
1 FILTER; 78R5360M 2PK FILTER AIR COND

CSHOP-2016-3139

Comments: **A INSPECTION**

Date Opened: 6-30-2016 Date Finished 7-14-2016 Meter 1 Reading: 97,898

TASKS PERFORMED

Q PARTS

A INSPECTION
DOOR PROP CYLINDER
WIPER BLADES
TURN SIGNAL LIGHTS
BATTERY
CRANKING SYSTEM
REAR TIRES
A/C LEAK TEST
A/C FILTER SCREENS

2 STRUT; GSS1783UQ STRUT-LIFT
1 9IP; 1720 DIFFUSER A/C 3.5 IN
2 WIPER; WIPER BLADES ANCO 24
2 STUD; DZ STUD
1 FLASHER; FLASHER ELECTRONIC
2 A/C; FREON LB
2 VALVE; 8915 VALVE CORE A/C 3544706C1
1 FILTER; 78R5360M 2PK FILTER AIR COND

Asset Work Order History 10152028

CSHOP-2016-37

Comments: **SPARE ENGINE @ 53**

Date Opened: 1-5-2016 Date Finished 1-15-2016 Meter 1 Reading: 90,375

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
SAFTEY-EMERGENCY EQUIPMENT

Service Requests:

01/05/2016 ALARMS / 19: LOOSE / REPAIR
SIRENS WORK PERIODICALLY. AIR HORN IS OPERATIONAL THOUGHT

CSHOP-2016-3765

Date Opened: 8-3-2016 Date Finished 10-4-2016 Meter 1 Reading: 99,093

TASKS PERFORMED

Q PARTS

STROBE LIGHTS

1 BULB; BULB
1 LIGHT; 600 SERIES RED LED W/O FLANGE

Service Requests:

08/03/2016 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
THE HEAT SENSORS ON ALL THREE LADDERS ARE OUT OF DATE.

08/28/2016 LIGHTS / 44: WORN NORMAL WEAR / REPLACED BAD PARTS
VEHICLE LIGHTS NOT WORKING, LEFT REAR BEACON NEEDS A BULB AND RIGHT FRONT LED STROBE.

CSHOP-2016-4706

Comments: **MEDICAL COMPARTMENT DOOR LOCK INOP SE @ ST17**

Date Opened: 9-29-2016 Date Finished 10-13-2016 Meter 1 Reading: 99,323

TASKS PERFORMED

Q PARTS

DOOR

1 HANDLE; D PADDLE HANDLE

Service Requests:

10/07/2016 ENGINE / 12: BROKEN / EXCHANGE - NEW
ENGINE PROTECT LIGHT IS ON. CODE ECU 128 APPEARS ON THE DASH.

CSHOP-2016-5775

Comments: **C INSPECTION BY H2**

Date Opened: 12-12-2016 Date Finished 12-21-2016 Meter 1 Reading: 100,635

TASKS PERFORMED

Q PARTS

PM SERVICE C

24 FLUID; SYN OIL BULK QTS
1 FILTER; FILTER FUEL WIX 33422 PS8689 FRAM
1 FILTER; OIL FILTER 51748
1 FILTER; FILTER FUEL 33231

VENDOR? H2 FIRE SERVICES

Asset Work Order History 10152028

CSHOP-2017-1393

Date Opened: 3-6-2017 Date Finished 3-6-2017 Meter 1 Reading: 100,635

TASKS PERFORMED

NO PARTS USED

EQUIPMENT MOUNTING BRACKETS

CSHOP-2017-1481

Date Opened: 3-9-2017 Date Finished 4-17-2017 Meter 1 Reading: 101,573

TASKS PERFORMED

Q PARTS

COOLING SYSTEM
BODY EXTERIOR

2 NCB; MOTHERS POLISH MAG

Service Requests:

04/17/2017 ENGINE / 17: INSUFFICIENT LUBRICANT / INSPECT
ENGINE, LOW COOLANT

CSHOP-2017-1518

Comments: **SPARE ENGINE AT 25**

Date Opened: 3-13-2017 Date Finished 3-29-2017 Meter 1 Reading: 101,269

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE FIGHTING EQUIPMENT
RADIO

Service Requests:

03/12/2017 RADIO / 15: FOREIGN MATERIAL / INSPECT
MIC ON MOBILE RADIO HAS A FRAYED WIRE. ALL OUTER INSULATION IS GONE.

03/12/2017 ENGINE / 23: NOT CONNECTED / REPAIR
NEED A CHARGER MOUNTED FOR THE DRAEGER XAM2500 GAS MONITOR. NOT ONE IN THE SPARE. ENGINE. TRUCK
IS AT STATION 25 LONG TERM.

CSHOP-2017-1574

Comments: **SPARE ENGINE AT 25**

Date Opened: 3-13-2017 Date Finished 3-29-2017 Meter 1 Reading: 101,269

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

Service Requests:

03/13/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST TRUCK HAS AN AIR LEAK. WHEN STARTING TRUCK AFTER IT HAS BEEN OFF A WHILE THE AIR
PRESSURE NEEDS TO BUILD UP AND COULD DELAY RESPONSE.

03/20/2017 SERVICE REQUEST / 23: NOT CONNECTED / REPAIR
SERVICE REQUEST CAN WE PLEASE GET A CHARGER FOR THE SCOUT MONITOR... EITHER HOUSE CHARGER OR
APPARATUS MOUNTED ONE.

Asset Work Order History 10152028

CSHOP-2017-1817

Comments: **SPARE AT E25**

Date Opened: 3-27-2017 Date Finished 3-29-2017 Meter 1 Reading: 101,269

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HEADLIGHTS LOW BEAM

1 LMP; HALOGEN LAMP

Service Requests:

03/24/2017 LIGHTS / 12: BROKEN / EXCHANGE - NEW
OFFICER'S SIDE HEADLIGHT LOW BEAM INOP.

CSHOP-2017-1841

Date Opened: 3-27-2017 Date Finished 3-29-2017 Meter 1 Reading: 101,269

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS
AIR CONDITIONING

Service Requests:

03/27/2017 A/C / 11: BINDS/STICKS / CLEAN
A/C ISSUE AC LEAKING ON OFFICER SIDE OF CAB ON FLOOR BOARD

03/27/2017 ENGINE / 19: LOOSE / REPAIR
ENGINE, MASTER PRESSURE GAUGE ON PUMP PANEL OUT OFF SERVICE

CSHOP-2017-1937

Comments: **SPARE AT 25**

Date Opened: 4-3-2017 Date Finished 4-6-2017 Meter 1 Reading: 101,493

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR CONDITIONING

30 9IP; FREON LB

Service Requests:

04/02/2017 A/C / 43: WEAK / ADJUST
A/C ISSUE AC IN CAB NOT BLOWING COLD AIR.

CSHOP-2017-2258

Date Opened: 4-17-2017 Date Finished 4-17-2017 Meter 1 Reading: 101,573

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM

Asset Work Order History 10152028

CSHOP-2017-2573

Date Opened: 5-2-2017 Date Finished 5-2-2017 Meter 1 Reading: 102,088

TASKS PERFORMED

Q PARTS

HURST TOOL MANIFOLD

1 9IP; HURST HYD. FLUID QT

Service Requests:

05/02/2017 ENGINE / 18: LEAKING / REPAIR
ENGINE REQUESTING HYDRAULIC FLUID FOR THE POWER UNIT ON ENGINE/25. THANK YOU

CSHOP-2017-2604

Date Opened: 5-3-2017 Date Finished 5-8-2017 Meter 1 Reading: 102,148

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
DISCHARGE GAUGE

1 5TN; GAUGE 3.5

Service Requests:

05/03/2017 SERVICE REQUEST / 12: BROKEN / REPAIR
NO. 1 CROSSLAY DISCHARGE GAUGE NOT WORKING ON E25.

CSHOP-2017-2667

Date Opened: 5-6-2017 Date Finished 5-10-2017 Meter 1 Reading: 102,148

TASKS PERFORMED

Q PARTS

FIRE APPARATUS

1 9IP; VALVE KIT SS 546-2270-02-0

CSHOP-2017-2845

Date Opened: 5-15-2017 Date Finished 6-1-2017 Meter 1 Reading: 102,818

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP PLUMBING

2 5SC; ROLLER
1 5SC; JAW
1 5SC; JAW
1 NONSTOCK; FREIGHT CHARGE

Service Requests:

05/14/2017 HAZARD / 12: BROKEN / EXCHANGE - NEW
HAZARDOUS ISSUE . NYLON GUIDE WORN ON DECK GUN ALSO PRESSURE GAUGE ON DECK GUN CRACKED

CSHOP-2017-3004

Date Opened: 5-22-2017 Date Finished 5-22-2017 Meter 1 Reading: 102,656

TASKS PERFORMED

NO PARTS USED

COMMERCIAL WORK - OUTSIDE AGENCY

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10152028

CSHOP-2017-3071

Comments: **SPARE ENGINE AT 25**

Date Opened: 5-25-2017

Date Finished

6-1-2017

Meter 1 Reading:

102,818

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE FIGHTING EQUIPMENT
SEAT BELTS

Service Requests:

05/25/2017 SEATS / 49: CAN NOT DUPLICATE CONCERN / INSPECT
SEAT ISSUE, SEAT BELT IN REAR CAB BEHIND DRIVERS SEAT IS NOT LOCKING IN.

05/25/2017 SERVICE REQUEST / 19: LOOSE / REPAIR
SERVICE REQUEST CHARGING BASE FOR TIC NOT WORKING. (NOT CHARGING TIC OR SPARE BATTERY.)

CSHOP-2017-3135

Date Opened: 5-30-2017

Date Finished

10-3-2017

Meter 1 Reading:

106,210

TASKS PERFORMED

Q PARTS

COMMERCIAL WORK - OUTSIDE AGENCY
WINDOW CHANNEL

1 WINDOW; GUIDE METAL
1 9IP; SEAL CAB WINDOW

VENDOR? REGANS SMALL ENGINE SERVICE

Service Requests:

05/29/2017 BODY / 12: BROKEN / REPAIR
BODY ISSUE WINDOW ON LEFT REAR DOOR NOT WORKING PROPERLY. SEEMS TO BE OUT OF TRACK

CSHOP-2017-3289

Comments: **SPARE ENGINE AT ST25 1. INTERIOR OF DRIVER DOOR WINDOW MOLDING IS LOOSE. 2. AIR LEAKS BELOW 60 PSI OVERNIGHT. SERVICE REQUEST NEED NEW HOSE BED COVER FOR E25**

Date Opened: 6-5-2017

Date Finished

7-14-2017

Meter 1 Reading:

104,389

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
CAB-INTERIOR ACCESSORIES
AIR CONDITIONING

1 9IP; MOLD L/H

Service Requests:

06/05/2017 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
1. INTERIOR OF DRIVER DOOR WINDOW MOLDING IS LOOSE. 2. AIR LEAKS BELOW 60 PSI OVERNIGHT.

06/07/2017 SERVICE REQUEST / 41: TORN/PUNCTURED / REPAIR
SERVICE REQUEST NEED NEW HOSE BED COVER FOR E25

06/07/2017 A/C / 18: LEAKING / ADJUST
A/C ISSUE FRONT CAB AC NOT BLOWING COLD AIR

Asset Work Order History 10152028

CSHOP-2017-3817

Date Opened: 6-28-2017 Date Finished 8-1-2017 Meter 1 Reading: 104,773

TASKS PERFORMED

Q PARTS

STROBE LIGHTS

1 1WL; 600 SERIES RED LED W/O FLANGE

Service Requests:

06/28/2017 LIGHTS / 38: SHORTED / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING .EMERGRNCY LIGHT OOS ON CAPTAIN SIDE OF ENGINE BELOW MIV VALVE.

CSHOP-2017-4035

Date Opened: 7-10-2017 Date Finished 7-26-2017 Meter 1 Reading: 104,702

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
COMMERCIAL WORK - OUTSIDE AGENCY
SPOT LIGHTS
AIR SYSTEM

1 9IP; SPOT LIGHT REMOTE
1 9IP; 91-8301 85 PSI CLOSED 67 OPEN PREESUR
1 MBI; PRESSURE PROTECT VLV

Service Requests:

07/10/2017 LIGHTS / 12: BROKEN / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING SPOT LIGHT OOS STUCK WILL NOT MOVE

CSHOP-2017-5062

Date Opened: 8-28-2017 Date Finished 8-28-2017 Meter 1 Reading: 105,666

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR CONDITIONING

CSHOP-2017-6203

Date Opened: 10-27-2017 Date Finished 11-1-2017 Meter 1 Reading: 106,809

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD AIR FILTER
1 FIL; FUEL WATER SEPARATOR
-24 9OC; SYN 15W40
24 9OC; SYN 15W40

Asset Work Order History 10152028

CSHOP-2017-6365

Comments: **REPAIRS FROM PM**

Date Opened: 11-3-2017

Date Finished 12-12-2017

Meter 1 Reading: 106,817

TASKS PERFORMED

FIRE PUMP PLUMBING
PRIMING PUMP FIRE PUMP
HOSE BED BODY
PRE TRIP INSPECTION
WIPERS-WASHER
FUEL INJECTOR
EXHAUST PIPE
EXHAUST MANIFOLD
LIGHTING SYSTEM
BATTERY TRAY
TRANSFER CASE
REPAIR FROM PM - BELTS
AIR DRIER
WINDOW CHANNEL
AIR HORN
DOOR
UPHOLSTERY
AIR CONDITIONING

Q PARTS

1	9HY; PIPE
1	9IP; TEE PLASTIC
1	1ED; TUBE
1	1ED; TUBE
6	1ED; CONNECTOR
1	1ED; TUBE
1	MAC; CARB-CHOKE CLNR 13OZ
1	1ED; TUBE
1	1ED; TUBE
6	1ED; INJECTOR
1	1ED; TUBE
6	2FL; ORING
32	9OC; COOLANT
4	2FL; NUT
2	FIL; NAPA COOLANT FILTER
1	2FL; MANIFOLD
1	2FL; MANIFOLD
1	9HY; ORING
1	2FL; GASKET
32	FLUID; COOLANT ANTIFREEZE GAL
-32	9OC; COOLANT
1	2FL; GASKET
6	2FL; GASKET
4	2FL; STUD
2	9IP; BULB 12 VOLT
6	GEAR; GEAR OIL SYN QT
6	9OC; GEAR OIL BULK
-6	9OC; GEAR OIL BULK
1	NBH; SERPENTINE BELT
1	BRG; ALTERNATOR BEARING
1	NBH; TENSIONER-HEAVY DUTY
1	NBH; V-BELT
1	NBH; V-BELT
1	TWD; AD-9KIT MINOR
1	2FL; CHANNEL
1	2FL; LH WINDOW REGULATOR
1	2FL; HANDLE
1	2FL; CUSHION
1	2FL; MOLDING LH
1	2FL; LATCH L/H
3	9XX; AC FREON 10199801

Asset Work Order History 10152028

CSHOP-2017-693

Comments: **REPAIRS FROM PM**

Date Opened: 2-1-2017

Date Finished

2-3-2017

Meter 1 Reading:

100,635

TASKS PERFORMED

Q PARTS

COMPARTMENT LIGHT BODY

1

COVER; MANSAYER COVER

FOAM SYSTEM

1

COVER; MANSAYER COVER

FIRE PUMP

2

9IP; 9IP

FIRE APPARATUS

1

9IP; 41032-3 RED REFLECTOR OVAL REFLECTOR

REPAIR FROM PM - GROUND LADDERS

1

9IP; 41032-3 RED REFLECTOR OVAL REFLECTOR

LIGHTING SYSTEM

1

LIGHT; MAP LIGHT LED 18 IN

BATTERY

4

1AD; BATTERY 31 SERIES

RESERVOIR

1

9IP; 9IP

BODY EXTERIOR

1

9OC; BULK TRANS SYN

ALARM-BUZZER-WARNING LIGHT

CSHOP-2018-1126

Date Opened: 2-26-2018

Date Finished

2-28-2018

Meter 1 Reading:

107,713

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2018-1147

Date Opened: 2-26-2018

Date Finished

2-26-2018

Meter 1 Reading:

107,713

TASKS PERFORMED

NO PARTS USED

REAR WINDOW

Service Requests:

02/26/2018

WINDOW / 18: LEAKING / REPAIR

UNIT LOCATED AT ST43 WINDOW/GLASS OFFICERS SIDE BACK WINDOW ROLLED DOWN AND CAME OFF TRACK. WINDOW IS OPEN AND UNABLE TO BRING IT BACK UP. THE ROLLERS CAME UP BUT WITHOUT GLASS ATTACHED.

CSHOP-2018-1503

Comments: **SPARE ENGINE AT 43**

Date Opened: 3-14-2018

Date Finished

3-14-2018

Meter 1 Reading:

108,189

TASKS PERFORMED

Q PARTS

STARTER

1

2IH; STARTER 37MT

Service Requests:

03/14/2018

STARTER / 12: BROKEN / REMOVE INSTALL NEW ONE

SOMETIMES IT WILL TAKE 5-10 TIMES OF STARTING ATTEMPTS TO GET THE ENGINE RUNNING

Asset Work Order History 10152028

CSHOP-2018-1540

Comments: **E43**

Date Opened: 3-15-2018

Date Finished

4-12-2018

Meter 1 Reading:

109,126

TASKS PERFORMED

Q PARTS

SIREN

1 5EF; KYS LT BOARD

1 NONSTOCK; FREIGHT CHARGE

Service Requests:

03/15/2018

ALARMS / 12: BROKEN / REPAIRED

AUDIBLE SIRENS NOT WORKING. LED LIGHTS NOT DISPLAYING WHEN TOGGLE SWITCH IS SET TO "ON" POSITION

CSHOP-2018-1755

Date Opened: 3-28-2018

Date Finished

4-3-2018

Meter 1 Reading:

108,878

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

Service Requests:

03/28/2018

SERVICE REQUEST / 18: LEAKING / REPAIR

THE MASTER INTAKE TO THE DRIVER SIDE HAS A SMALL LEAK WHILE COMPLETELY SHUT OFF (STYLE 7000 PISTON INTAKE VALVE). ALSO WHILE BEING ON THE PUMP PANEL AND HAVING THE TANK TO PUMP ON AND TANK REFILL ON IN LESS THAN 2 MINUTES A BURNING SMELL OCCURS BUT THE ENGINE GAUGES DOES NOT INDICATE OVER HEATING.

CSHOP-2018-1953

Comments: **ON-CALL E43 HOSE REEL CHAIN FELL OFF**

Date Opened: 4-9-2018

Date Finished

4-9-2018

Meter 1 Reading:

109,065

HOSE REEL INOP.

TASKS PERFORMED

NO PARTS USED

HOSE REEL

CSHOP-2018-2076

Date Opened: 4-13-2018

Date Finished

4-23-2018

Meter 1 Reading:

109,518

TASKS PERFORMED

NO PARTS USED

FIRE PUMP CONTROLS

Asset Work Order History 10152028

CSHOP-2018-2101

Date Opened: 4-16-2018

Date Finished

5-14-2018

Meter 1 Reading:

110,152

TASKS PERFORMED

Q PARTS

PRE TRIP INSPECTION	1	5TN; GAUGE
LIGHTING SYSTEM	1	9IP; DECK LIGHT ROUND BASE
DIAGNOSE ELECTRICAL	3	LMP; LAMP
DOOR LOCKS	2	9IP; BREAKER 30 AMP
	1	9IP; NODE MINI V-MUX 6010-0000-00
	2	9IP; 434 LATCH TRIGGER S/O
	1	5AH; GAS SPRING

Service Requests:

04/14/2018 SERVICE REQUEST / 12: BROKEN / #1 DISCHARGE VALVE GAGE IN-OP
DISCHARGE PRESSURE GAGE NOT WORKING. DISCHARGE #1

04/14/2018 SERVICE REQUEST / 12: BROKEN / ADJUST
TYPE PROBLEM INTO DESCRIPTION

CSHOP-2018-2484

Comments: **SPARE ENGINE AT 43**

Date Opened: 5-7-2018

Date Finished

8-22-2018

Meter 1 Reading:

110,152

TASKS PERFORMED

Q PARTS

REAR DOOR LATCH ASSEMBLY	1	2FL; WEATHERSTRIP
LIGHTING SYSTEM	4	5SC; BUCKLEASSYWSTRAPS
BODY EXTERIOR		

Service Requests:

05/04/2018 DOOR / 19: LOOSE / REPAIR
VEHICLE DOORS BOTH LATCHES FOR DOOR OF TRASH AND SUPPLY LINES COMPARTMENT BROKEN AND DOOR
NOW IS DUCT TAPED SHUT.

05/04/2018 LIGHTS / 19: LOOSE / REPAIR
VEHICLE LIGHTS NOT WORKING PROPERLY EMERGENCY LIGHT INTERMITTENTLY WILL NOT TURN ON OR SHUT
OFF.

05/04/2018 DOOR / 12: BROKEN / REPAIR
VEHICLE DOOR ON ENGINEERS COMPARTMENT DOES NOT OPEN PROPERLY.

CSHOP-2018-2506

Comments: **SPARE ENGINE AT 41**

Date Opened: 5-7-2018

Date Finished

5-14-2018

Meter 1 Reading:

110,152

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES

Service Requests:

05/07/2018 OIL / 18: LEAKING / REPAIR
LOW ENGINE OIL ENGINE HAS OIL LEAK AND WE ARE OUT OF OIL TO REFILL IT.

Asset Work Order History 10152028

CSHOP-2018-335

Date Opened: 1-16-2018 Date Finished 2-21-2018 Meter 1 Reading: 107,485

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

-
- 01/14/2018 TIRES / 49: CAN NOT DUPLICATE CONCERN / REPAIR
BAD TIRES- LEFT FRONT TIRE NEEDS TO BE REPLACED ON SPARE ENGINE 74-DRIVER LEFT FRONT
 - 01/16/2018 BRAKES / 18: LEAKING / REPAIRED AIR LEAK
BRAKE ISSUES: SIGNIFICANT AIR LEAK. AIR COMPRESSOR CAN NOT KEEP UP WITH LEAK. NEED REPAIR ASAP
-

CSHOP-2018-4308

Date Opened: 8-1-2018 Date Finished 8-1-2018 Meter 1 Reading: 110,152

TASKS PERFORMED

NO PARTS USED

HOSE BED BODY

VENDOR? CENTRAL AUTO TRIM CO.

CSHOP-2018-5004

Date Opened: 9-4-2018 Date Finished 9-5-2018 Meter 1 Reading: 110,177

TASKS PERFORMED

Q PARTS

PM SERVICE C

- 1 FIL; NAPAGOLD FUEL FILTER
 - 1 MAC; MAC WITE LITHIUM GRES
 - 1 FIL; NAPAGOLD OIL FILTER
 - 1 FIL; NAPA COOLANT FILTER
 - 25 4PC; 15W40 PREMIUM BLUE OIL
 - 1 FIL; FUEL WATER SEPARATOR
-

CSHOP-2018-5036

Comments: **REPAIRS FROM PM**

Date Opened: 9-5-2018 Date Finished 9-7-2018 Meter 1 Reading: 110,177

TASKS PERFORMED

Q PARTS

FAULT CODE
PARK-CLEARANCE LIGHTS
BATTERY
TRANSMISSION
A/C FILTER SCREENS

- 2 2CU; SENSOR
 - 2 9PH; LED 35 SERIES
 - 4 1AD; BATTERY 31 SERIES
 - 1 FIL; NAPA TRANS FILTER
 - 23 9OC; BULK TRANS SYN
 - 23 9OC; BULK TRANS SYN
 - 23 9IP; ALLISON TRANS FLUID GAL
 - 6 9IP; ALLISON TRANS FLUID GAL
 - 23 9IP; ALLISON TRANS FLUID GAL
 - 1 2TK; FILTER
-

Asset Work Order History 10152028

CSHOP-2018-6085

Date Opened: 10-26-2018 Date Finished 10-26-2018 Meter 1 Reading: 110,177

TASKS PERFORMED

NO PARTS USED

REAR WINDOW

CSHOP-2018-6139

Date Opened: 10-29-2018 Date Finished 11-6-2018 Meter 1 Reading: 110,517

TASKS PERFORMED

NO PARTS USED

CHARGING SYSTEM

Service Requests:

10/29/2018 SERVICE REQUEST / 35: RUSTED/CORRODED / REPAIR
VOLTAGE METER READING WHEN TRUCK IS AT IDLE READS 12V, WHEN THE PRIMER IS PULLED THE VOLTAGE READING DROPS TO LOW AND AN ALARM IS SOUNDED. CONCERN IF PULLING A PRIME IS NEEDED THE TRUCK MIGHT LOOSE POWER.

CSHOP-2018-6228

Comments: **REPAIR FOAM SYSTEM**

Date Opened: 11-1-2018 Date Finished 11-15-2018 Meter 1 Reading: 110,520

TASKS PERFORMED

Q PARTS

FOAM SYSTEM		
PUMP PANEL	1	9HY; FITTING
RELIEF VALVE FIRE PUMP	1	GRO; TOGGLE SWITCH 20 AMP
FIRE PUMP	1	GRO; SWITCH, BOOT
	1	5HP; KNOB
	2	9IP; STRAINER

CSHOP-2018-6692

Comments: **PRE TRIP PUMP TEST FOLLOW-UP MASTER DRAIN VALVE STUCK CLOSE RIGHT REAR DISCHARGE GAUGE AND TRASHLINE GAUGE LOW ON OIL OR NO OIL, RECOMMEND REPLACING VALVES DIFFICULT TO OPEN AND CLOSE, RECOMMEND LUBING OR REBUILDING EXTERNAL RELIEF VALVE LEAKING DURING VACUUM TEST, PUSHED**

Date Opened: 11-27-2018 Date Finished 12-5-2018 Meter 1 Reading: 110,553

TASKS PERFORMED

Q PARTS

FIRE APPARATUS		
PRE TRIP INSPECTION	1	9IP; GASKET
BODY EXTERIOR	1	9IP; MASTER DRAIN VALVE
	2	5TN; GAUGE 35
	2	7CF; LETTERING, ENGINE

Asset Work Order History 10152028

CSHOP-2018-7383

Date Opened: 12-29-2018 Date Finished 1-14-2019 Meter 1 Reading: 111,067

TASKS PERFORMED

Q PARTS

BRAKES

1 2FL; NORM CLSD 2 WIRE PRES SW
1 2DD; ALLISON PRESSURE SWITCH

Service Requests:

12/29/2018 BRAKES / 18: LEAKING / REPAIR
BRAKE ISSUES. LOUD AIR LEAK WHEN BRAKES APPLIED.

CSHOP-2019-1211

Comments: **SPARE ENGINE AT 31**

Date Opened: 3-6-2019 Date Finished 3-8-2019 Meter 1 Reading: 111,290

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM
BODY EXTERIOR

Service Requests:

03/06/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
PUMP IS ACTIVELY LEAKING

CSHOP-2019-1428

Comments: **SPARE ENGINE AT 31**

Date Opened: 3-18-2019 Date Finished 3-19-2019 Meter 1 Reading: 111,861

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
STROBE LIGHTS

Service Requests:

03/18/2019 LIGHTS / 38: SHORTED / INSPECT
EMERGENCY LIGHTS NOT ACTIVATING CORRECTLY. SOMETIMES THEY DO SOMETIMES THE DONT, SOMETIMES HITTING A BUMP CAUSES THEM TO STOP.

CSHOP-2019-1892

Date Opened: 4-11-2019 Date Finished 4-18-2019 Meter 1 Reading: 111,905

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; NAPAGOLD FUEL FILTER
1 9AP; HAND SOAP PUM (TOTAL TRK)
4 9OC; BULK TRANS SYN
2 9OC; BULK TRANS SYN
1 FIL; NAPAGOLD OIL FILTER
1 FIL; FUEL WATER SEPARATOR
4 4PC; 15W40 PREMIUM BLUE OIL

Asset Work Order History 10152028

CSHOP-2019-1919

Date Opened: 4-12-2019 Date Finished 4-23-2019 Meter 1 Reading: 111,905

E-LIGHT INTERMENT

TASKS PERFORMED

Q PARTS

TURN SIGNAL LIGHTS	9	LMP; LAMP
FLUID	4	4PC; GEAR OIL-SYN BULK (DELO)
OIL COOLER-HEAT EXCHANGER	3	2FL; LOWERRADHOSE
AIR DRIER	1	9IP; COOLER14032
LIGHT BAR	1	9IP; HOSELOWERRADIATOR
	1	TWD; AD-9KIT MINOR
	-1	TWD; KIT
	1	TWD; CHKVLV
	1	TWD; KIT
	1	TWD; AD-9KIT
	2	1WL; SPOTLIGHT, LED

CSHOP-2019-2553

Date Opened: 5-15-2019 Date Finished 5-17-2019 Meter 1 Reading: 114,895

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP

CSHOP-2019-2581

Comments: **SPARE ENGINE AT 14**

Date Opened: 5-16-2019 Date Finished 5-17-2019 Meter 1 Reading: 114,895

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR CONDITIONING

Service Requests:

05/16/2019	A/C / 18: LEAKING / CLEAN A/C ISSUE ON SPARE E14 WATER FROM A/C IS GOING INTO THE FLOOR ON CAPTAINS SIDE WHILE ENGINE IS RUNNING
------------	---

CSHOP-2019-2848

Comments: **SPARE ENGINE AT 14**

Date Opened: 6-3-2019 Date Finished 7-3-2019 Meter 1 Reading: 114,895

TASKS PERFORMED

NO PARTS USED

FIRE PUMP

Service Requests:

05/31/2019	LIGHTS / 12: BROKEN / REPAIR FLOOD LIGHT IN REAR OF TUCK OUT AND ALSO LED LIGHT ON PUMP PANEL FOR H2O LEVEL IS OFF
------------	---

Asset Work Order History 10152028

CSHOP-2019-3217

Date Opened: 6-21-2019 Date Finished 6-21-2019 Meter 1 Reading: 114,895

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
CRANKING SYSTEM

1 2IH; STARTER37MT

Service Requests:

06/21/2019 STARTER / 13: CHIPPED / REPAIR
VEHICLE WILL NOT START

CSHOP-2019-3402

Date Opened: 7-1-2019 Date Finished 7-3-2019 Meter 1 Reading: 114,895

TASKS PERFORMED

NO PARTS USED

QUALITY CHECK-REPAIRS
STORAGE CABINET EMERGENCY VEH

CSHOP-2019-3685

Comments: **DAMAGE BEING CHARGED TO THIS UNIT BECAUSE WE DAMAGED TEQUESTA # T2040**

Date Opened: 7-15-2019 Date Finished 7-15-2019 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

BODY DAMAGE ACCIDENT

VENDOR? MURPHY'S PAINT & BODY SHOP LLC

CSHOP-2019-3869

Date Opened: 7-25-2019 Date Finished 8-12-2019 Meter 1 Reading: 114,895

TASKS PERFORMED

Q PARTS

DOOR STRIKER PLATE

1 5SC; STRIKER PIN

Service Requests:

07/25/2019 BODY / 14: CRACKED / REPLACED REAR HOSE REEL DOOR STRIKER
BODY ISSUE

CSHOP-2019-4223

Date Opened: 8-12-2019 Date Finished 10-3-2019 Meter 1 Reading: 114,678

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
FIRE APPARATUS
CONTROL VALVE

1 5HP; 3 SVS LEVEL 2 KIT
1 8GR; GREASE FOOD GRADE

Service Requests:

08/09/2019 ENGINE / 12: BROKEN / REPAIR
ENGINE WILL NOT DRAFT

Asset Work Order History 10152028

CSHOP-2019-6279

Date Opened: 12-3-2019 Date Finished 12-4-2019 Meter 1 Reading: 115,081

TASKS PERFORMED

Q PARTS

SAFTEY-EMERGENCY EQUIPMENT

1 9IP; NODE MINI V MUX 6010 0000 00

CSHOP-2019-828

Comments: **PRE TRIP**

Date Opened: 2-11-2019 Date Finished 3-22-2019 Meter 1 Reading: 114,895

TASKS PERFORMED

Q PARTS

A INSPECTION
SIDE COMPARTMENT BODY
FAN
TURBOCHARGER
AIR SYSTEM
AIR CONDITIONING

4 5AH; SAFETY CLIP FOR 16298, 10MM
2 5AH; DOOR CHECK 1256
4 2FL; SCREW
1 2FL; FAN
1 2FL; CLUTCH
1 2FL; AIR BAG
1 2FL; AIR BAG
1 2FL; CAB LEVEL VALVE
1 9HY; FITTINGS
1 TWD; AIR SLEEVE
3 9XX; AC FREON 10174676
1 2FL; RECEIVER
1 TEM; EXPANSION VALVE
-1 SVP; EXPVLVE
1 SVP; EXPVLVE
1 2FL; RECEIVER DRIER
1 2FL; HOSE
1 9IP; FILTER DRYER AC

CSHOP-2020-1593

Date Opened: 3-19-2020 Date Finished 4-13-2020 Meter 1 Reading: 116,483

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
BATTERY
CHARGING SYSTEM

4 1AD; BATTERY GROUP 31
1 TWD; STARTER

Asset Work Order History 10152028

CSHOP-2020-2052

Date Opened: 4-17-2020 Date Finished 1-13-2021 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
LIGHTING SYSTEM
VENDOR TIRE REPAIR/CHANGE

1 2FL; LAMP ASSY W/STUDS

Service Requests:

04/17/2020 TIRES / 18: LEAKING / REPAIR
THE DRIVER REAR OUTSIDE TIRE THREAD IS WORN OUT AND THE PASSENGER REAR OUTSIDE TIRE THREAD IS WORN OUT. NEED 2 TIRES TO BE REPLACE.

04/17/2020 LIGHTS / 12: BROKEN / INSPECT
THE FRONT DRIVER'S TURN SIGNAL LIGHT IS OUT. NEED A BULB REPLACEMENT.

CSHOP-2020-2335

Comments: **AT ST44 WE NEED TO INSPECT AS SOON AS POSSIBLE INSPECTION WAS COMPLETED**

Date Opened: 5-2-2020 Date Finished 5-5-2020 Meter 1 Reading: 117,603

TASKS PERFORMED

NO PARTS USED

PM SERVICE C

CSHOP-2020-2345

Date Opened: 5-4-2020 Date Finished 5-5-2020 Meter 1 Reading: 117,638

TASKS PERFORMED

Q PARTS

BRAKES
AIR SYSTEM

2 MBI; SERVICE AIR CHAMBER

Service Requests:

05/02/2020 SERVICE REQUEST / 12: BROKEN / REPLACED LEFT REAR SERVICE BRAKE CHAMBER DIAPHRA
AIR LEAK NOISE CAUSING A DELAY TO DRIVE THE UNIT FROM THE BAY.

CSHOP-2020-2395

Comments: **SEE FILES FOR FOLLOW UPS**

Date Opened: 5-5-2020 Date Finished 5-26-2020 Meter 1 Reading: 117,638

TASKS PERFORMED

Q PARTS

FOAM SYSTEM
DISCHARGE GAUGE
WIPER BLADES
COOLING SYSTEM
ENGINE AND ACCESSORIES
UNIVERSAL JOINT
BRAKE CHAMBER
AIR SYSTEM
SAFTEY-EMERGENCY EQUIPMENT

2 5CS; 5CS
-2 5CS; GAUGE 600 PSI 4 5 IN WHITE
2 5CS; GAUGE 600 PSI 4 5 IN WHITE
2 1AN; WIPER BLADE 24 IN
1 BK; SWITCH
1 TWD; PP DCVALVE DASH

Asset Work Order History 10152028

CSHOP-2020-3878

Date Opened: 7-27-2020 Date Finished 12-1-2020 Meter 1 Reading: 117,638

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
ELECTRICAL
RETARDER
AIR HORN

2 9AP; HORN KIT PAI 3390 1094
1 2FL; VALVE ENGINE BRAKE AIR
1 2FL; 2FL

CSHOP-2020-42

Date Opened: 1-4-2020 Date Finished 1-7-2020 Meter 1 Reading: 115,184

TASKS PERFORMED

NO PARTS USED

SEAT BELTS

Service Requests:

01/03/2020 SEATS / 12: BROKEN / REPLACED
DRIVER SEAT BELT IS BROKEN AND UNABLE TO USE

CSHOP-2020-774

Comments: **SPARE ENGINE AT ST17**

Date Opened: 2-10-2020 Date Finished 3-10-2020 Meter 1 Reading: 116,483

TASKS PERFORMED

NO PARTS USED

RELIEF VALVE FIRE PUMP
ELECTRICAL

Service Requests:

02/10/2020 SERVICE REQUEST / 18: LEAKING / INSPECTED
TYPE PROBLEM INTO DESCRIPTION THERE IS A WATER LEAK AT THE DRAIN FOR THE PRESSURE RELIEF VALVE.

02/10/2020 SERVICE REQUEST / 12: BROKEN / INSPECTED
TYPE PROBLEM INTO DESCRIPTION LEFT SIDE REAR SCENE LIGHT IS NOT WORKING

RADIO-2017-575

Comments: **REPLACED SHOULDER MIC**

Date Opened: 9-9-2017 Date Finished 9-9-2017 Meter 1 Reading: 105,722

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

09/08/2017 RADIO / /
MIC FOR OFFICERS RADIO ON E25 CHIRPS WHEN SQUEEZING BUTTON. CUTS OFF RADIO COMMUNICATIONS.

Asset Work Order History 10152028

RADIO-2018-317

Comments: **REMOVAL OF 10141692, INSTALL OF 10205593 INTO SE5 - 10152028**

Date Opened: 4-17-2018 Date Finished 4-17-2018 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

04/17/2018 RADIO / /
REMOVAL & INSTALL OF NEW MOTOROLA MOBILE RADIO IN SPARE ENGINE 5

SSHOP-2019-83

Date Opened: 3-19-2019 Date Finished 3-21-2019 Meter 1 Reading: 111,861

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
LIGHTING SYSTEM

2	CRC; QD ELECTRONIC CLEANER
3	9ME; STRAP 25"-44"
