Hours: 3.00

Comm: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10189463 2013 TOYOTA PRIUS Car, Mid Size, Hybrid

Total Hours: 81.75 Labor: 5,170.40		Parts: 4,019.85	Comm: 5,488.58		Charged	: 14678.83		
Work Order: Problem:	1300321 1061 - Pre Delivery Insp	Meter: pection	116		In Date:	01/09/2013	Closed:	01/09/2013
Work Com	pleted							
- Pre Deliv	ery Inspection							
- Wash Vel	nicle							
	Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 0.0	0	Total:	180.00
Work Order: Problem:	1300849 1 - Wash ticket(s) issued	Meter:	470		In Date:	01/24/2013	Closed:	01/24/2013
Work Com	pleted							
- 1 - Wash	ticket(s) issued							
	Hours: 0.00		Comm: 8.51	Labor: 0.00	Parts: 0.0	0	Total:	8.51
Work Order: Problem:	1306298 P.M. Service.	Meter:	3591		In Date:	06/24/2013	Closed:	07/05/2013
Work Com	pleted			Parts Issued			Qı	uantity
- P.m. Serv	ice.			Syn0w20				5.00
- Rotate ar	nd balance all tires.			Napagold Oil Filter				1.00
- Shop Sup	plies			Shop Supplies				1.00
	Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 36.	32	Total:	216.32
Work Order: Problem:	1312675 Pm service and washer	Meter: fluid	7095		In Date:	12/19/2013	Closed:	01/08/2014
Work Com	pleted			Parts Issued			Qı	uantity
- Perform _I	om service.			Napagold Oil Filter				1.00
	d balance all four tires.			Syn0w20				5.00
- Shop Sup	plies			Exact Fit Blade				1.00
				Wiper Blade				1.00
				Washer Fluid Conce	ntr			1.00

Labor: 180.00

Parts: 55.00

Total: 235.00

Palm Beach County Fleet Management Asset Maintenance History 10189463 2013 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1406812 Meter: 11334 In Date: 07/10/2014 Closed: 07/28/2014

Problem: Pm service.

Work Completed		Parts Issued		Quantity
- Perform pm service.		Napagold Oil Filte	r	1.00
- Rotate and balance all four tires.		Syn0w20		5.00
- Repair and balance left rear tire.		Washer Fluid Cond	centr	1.00
- Shop Supplies		Wd40 16oz Steering Wheel Cover Cap Sub Assy		1.00
				1.00
				1.00
		Shop Supplies		1.00
Hours: 4.00	Comm: 0.00	Labor: 240.00	Parts: 159.67	Total: 399.67

Work Order: 1412500 Meter: 14260 In Date: 12/09/2014 Closed: 12/15/2014

Problem: Flat tire on L/F

Work Completed

- Tire Service 800 Clematis (health Dept) - Flat tire on L/f

Hours: 0.00 Comm: 66.34 Labor: 0.00 Parts: 0.00 Total: 66.34

Work Order: 1412858 Meter: 14623 In Date: 12/29/2014 Closed: 02/05/2015

Problem: P.M. Service.Tow in,dead battery(reading light on)Recall.

Work Completed	Parts Issued		Quantity
- P.m. Service.	Syn0w20		4.00
- Recharge battery and test battery and charging system.okay,reading light	Napagold Oil Filter		1.00
left on.	Exact Fit Blade		1.00
- Rotate and balance all tires.	Wiper Blade		1.00
- Replace broken left side dash vent.	Accufit Rear		1.00
- Transport vehicle to dealer for software update.	Cabin Air Filter		1.00
- Shop Supplies	register inst		1.00
	Shop Supplies		1.00
Hours: 5.75 Comm: 0.00	Labor: 345.00	Parts: 218.17	Total: 563.17

Palm Beach County Fleet Management Asset Maintenance History 10189463 2013 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1412934 Meter: 14463 In Date: 12/29/2014 Closed: 12/31/2014

Problem: NO start

Work Completed

- Tow From: 800 Clematis Ave (health Dept) To: Lv Shop

Hours: 0.00 Comm: 104.15 Labor: 0.00 Parts: 0.00 Total: 104.15

Work Order: 1506636 Meter: 19396 In Date: 07/01/2015 Closed: 07/21/2015

Problem: Pm service.

Work Completed		Parts Issued		Quantity
- Pm service.	Syn0w20		5.00	
- Rotate and balance all four wheels.	Napagold Oil Filter	1.00		
- Shop Supplies		Wiper Blade		1.00
		Exact Fit Blade		1.00
		Accufit Rear		1.00
		Washer Fluid Concentr Accufit Rear		1.00
				1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 67.25	Total: 247.25

Work Order: 1510541 Meter: 23041 In Date: 10/19/2015 Closed: 10/27/2015

Problem: Left front tire road on flat .spare on car.

Work Completed		Parts Issued		Quantity
- Replace and balance two tires.	738274571 195-6	55r15 A	2.00	
- Shop Supplies		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 249.81	Total: 309.81

Work Order: 1510612 Meter: 22835 In Date: 10/15/2015 Closed: 10/20/2015

Problem: Flat tire

Work Completed

- Tire Service Pbia Cell phone Waiting - Flat tire

Hours: 0.00 Comm: 66.34 Labor: 0.00 Parts: 0.00 Total: 66.34

Palm Beach County Fleet Management Asset Maintenance History 10189463 2013 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: Problem:	1512346 Pm service.Wiper blades.	Meter:	24303		In Date:	12/07/2015	Closed:	12/16/2015
Work Com	pleted			Parts Issued			Qı	ıantity
- Pm servic	ce.			Syn0w20				5.00
- Rotate ar	nd balance all four tires.			Napagold Oil Filter				1.00
- Shop Sup	pplies			Wiper Blade				1.00
' '	•			Wiper Blade				1.00
				Accufit Rear				1.00
				Accufit Hybrid				1.00
				Accufit Hybrid				1.00
				Accufit Rear				1.00
				Shop Supplies				1.00
	Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 92.	11	Total:	272.11
	1601446 damage to bumpers & rear hatch	Meter:	24533		In Date:	12/23/2015	Closed:	02/10/2016
Work Com	pleted							
- damage	to bumpers & rear hatch							
	Hours: 0.00		Comm: 4,249.85	Labor: 0.00	Parts: 0.0)	Total:	4,249.85
Work Order:	1603466	Meter:	25644		In Date:	04/01/2016	Closed:	04/06/2016
Problem:	Towed in for no start.							
Work Com	pleted							
- Recharge	and test battery,good.map light le	eft on.						
	Hours: 0.50		Comm: 0.00	Labor: 30.00	Parts: 0.0)	Total:	30.00
Work Order: Problem:		Meter:	25644		In Date:	04/01/2016	Closed:	04/01/2016
Work Com	pleted							
- Tow Fron	n: 800 Clematis St To: Lv Shop Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00

Palm Beach County Fleet Management Asset Maintenance History 10189463 2013 TOYOTA PRIUS Car, Mid Size, Hybrid

9.17.38 AIVI	10189463	2013 TOYOTA PRIUS	Gar, Mid Size, Hybrid			
Work Order: 1605531		Meter: 26519		In Date:	05/27/2016 Closed:	06/09/2016
Problem: P.M. Service	ce.Cracked windshield.					
Work Completed			Parts Issued		Q	uantity
- P.m. Service.			Cap Sub Assy			1.00
- Replace two tires,rota	ate and balance all four.		Syn0w20			4.00
- Replace tag lamp bul	lbs.		Napagold Oil Filter			1.00
- Complete wheel aligr	nment.test drive.		738274571 195-65r1	5 A		2.00
- Shop Supplies			Bulb			2.00

Work Order: 1605776 Meter: 26492 In Date: 06/06/2016 Closed: 06/13/2016

Comm: 0.00

Comm: 312.90

Shop Supplies

Labor: 420.00

Labor: 60.00

Tire Disposal Fee

Parts: 366.83

Parts: 2.00

1.00

2.00

Total: 786.83

Total: 374.90

Problem: replace cracked windsheild

Work CompletedParts IssuedQuantity- Set up repairs and assetShop Supplies1.00- Shop Supplies

Work Order: 1612972 Meter: 29148 In Date: 12/20/2016 Closed: 01/03/2017

Problem: P.M. service and towed in for no start.

Hours: 1.00

Hours: 7.00

Work Completed	Parts Issued	Quantity
- P.m. Service.	Syn0w20	5.00
- Recahrge battery and test charging system, battery fail load test.re	eplace Napagold Oil Filter	1.00
defective battery.	Accufit Hybrid	1.00
- Rotate and balance all tires.	Accufit Hybrid	1.00
- Shop Supplies	Accufit Rear	1.00
	Cabin Air Filter	1.00
	Agm Battery	1.00
	Shop Supplies	1.00
Hours: 4.00 Comm: 0	.00 Labor: 240.00 Parts: 292.64	Total: 532.64

Palm Beach County Fleet Management Asset Maintenance History 10189463 2013 TOYOTA PRIUS Car, Mid Size, Hybrid

Meter: 29140 In Date: 12/19/2016 Closed: 12/21/2016

Problem: No start

Work Order: 1613012

Work Completed

- Tow From: Wpb Police Garge (600 Banyan Blvd) To: Lv shop

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1701895 Meter: 30202 In Date: 02/23/2017 Closed: 02/27/2017

Problem: replace front fairing

Work CompletedParts IssuedQuantity- Replace Rf Plastic Inner wheel housing coversLiner Fr Fender1.00- Shop SuppliesShop Supplies1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 137.38 Total: 197.38

Work Order: 1704158 Meter: 31502 In Date: 04/25/2017 Closed: 04/28/2017

Problem: Towed in for no start.

Work Completed

- Charge battery fully.test battery and charging system .perform draw test

found dome light left on.

Hours: 0.80 Comm: 0.00 Labor: 48.00 Parts: 0.00 Total: 48.00

Work Order: 1704162 Meter: 31502 In Date: 04/25/2017 Closed: 04/25/2017

Problem: No start

Work Completed

- Tow From: 600 Clematis Garage To: Lv shop

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Palm Beach County Fleet Management Asset Maintenance History 10189463 2013 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order:		Meter:	31923		In Date:	05/30/2017	Closed:	06/02/2017
Problem:	P.M. service and towed in for r	no start.						
Work Com	pleted			Parts Issued			Qı	uantity
- P.m. serv	rice.			Syn0w20				5.00
- Balance a	and rotate all four tires.			Napagold Oil Filter	r			1.00
- Check ba	attery and charging system .fully	charge battery	recheck ,passed /	Accufit Rear				1.00
load test.fo	ound headlight switch left on.			Accufit Hybrid				1.00
- Shop Sup	oplies			Accufit Hybrid				1.00
				Wiper Blade - Accu	ufit - Rear - O	e Style		1.00
				Shop Supplies				1.00
	Hours: 3.50		Comm: 0.00	Labor: 210.00	Parts: 82.	16	Total:	292.16
Work Order: Problem:		Meter:	31836		In Date:	05/30/2017	Closed:	05/31/2017
Work Com	pleted							
- Tow Fron	m: 600 Clematis (police Garage)	To: Lv shop						
	Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00
Work Order:		Meter:	32199		In Date:	06/27/2017	Closed:	06/27/2017
Problem:	1 - Wash ticket(s) issued							
Work Com	pleted							
- 1 - Wash	ticket(s) issued							
	Hours: 0.00		Comm: 8.51	Labor: 0.00	Parts: 0.0	0	Total:	8.51
Work Order: Problem:	1710074 Towed in, No start.	Meter:	34292		In Date:	10/13/2017	Closed:	10/19/2017
Work Com	pleted			Parts Issued			Qı	uantity
_	pattery fully.test battery and char dome light switch left on .	rging system, a	ll ok. Perform draw	Shop Supplies				1.00
- Fabricate	e and replace missing rear asset	number.						
- Shop Sup	oplies							
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00

Palm Beach County Fleet Management Asset Maintenance History 10189463 2013 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1710108 Meter: 34126 In Date: 10/13/2017 Closed: 10/16/2017

Problem: No Start

Work Completed

- Tow From: 600 Clematis (police Garage 3rd Floor) To: He shop

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1800186 Meter: 35672 In Date: 01/04/2018 Closed: 01/16/2018

Problem: P.M. Service. Tire light on.

Work Completed		Parts Issued		Quantity
- P.m. service.		Syn0w20		5.00
- Rotate and high speed balance all four tires.	Napagold Oil Filte	r	1.00	
- Shop Supplies	Wiper Bleade Anco		1.00	
		Wiper Blade Anco		1.00
		14in Exactfit-rear Shop Supplies		1.00
				1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 47.92	Total: 227.92

Work Order: 1803940 Meter: 38145 In Date: 04/16/2018 Closed: 04/18/2018

Problem: Towed in for right front tire flat.

Work Completed		Parts Issued		Quantity
- Mount and balance one new tire on right fro	ont .due to side wall damage.	738274571 195-6	55r15 A	1.00
- Shop Supplies	Shop Supplies		1.00	
		Tire Disposal Fee		1.00
Hours: 0.50	Comm: 0.00	Labor: 30.00	Parts: 124.38	Total: 154.38

Work Order: 1804239 Meter: 38217 In Date: 04/16/2018 Closed: 04/24/2018

Problem: Flat tire on F/P

Work Completed

- Tire Service 345 S Congress Ave - Flat tire on F/p

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Palm Beach County Fleet Management Asset Maintenance History 10189463 2013 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1807350 Meter: 39812 In Date: 07/19/2018 Closed: 07/26/2018

Problem: P.M. service.

Work Completed	Parts Issued	Quantity
- P.m. service.	Syn0w20	5.00
- Resurface front rotors and replace brake pads .service calipers. Test di	ive. Napagold Oil Filter	1.00
- Replace three tires and balance all four . Nitrofill tires and reset Tpms.	16in Exactfit-rear	1.00
- Perform four wheel alignment. Road test.	Wiper Blade Anco	1.00
- Shop Supplies	Wiper Bleade Anco	1.00
	Non-chlor Brake Clnr	1.00
	Brake Pad	1.00
	738274571 195-65r15 A	3.00
	Ceramic Brake Lube	1.00
	Front Brake Pad	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	3.00
Hours: 9.50 Comm: 0.00	Labor: 570.00 Parts: 608.65	Total: 1,178.65

Work Order: 1900078 Meter: 42350 In Date: 01/02/2019 Closed: 01/07/2019

Problem: P.M. service and tire light on .

Work Completed		Parts Issued		Quantity	
P.m. service.Rotate and high speed balance all four wheels . Nitrofill and reset Tpms.		Napagold Oil Filter		1.00	
		Syn0w20		5.00	
- Shop Supplies		Wiper Blade Anco Wiper Bleade Anco 16in Exactfit-rear		1.00	
				1.00	
				1.00	
		Washer Fluid Concentr		1.00	
		Shop Supplies		1.00	
Hours: 3.00 Comn	n: 0.00	Labor: 201.00	Parts: 53.39	Total: 254.39	

Palm Beach County Fleet Management Asset Maintenance History 10189463 2013 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1906727 Meter: 44646 In Date: 06/26/2019 Closed: 07/16/2019

Problem: P.M. service, missing hub cap and recall 18V-684.

Work Completed	Parts Issued		Quantity
- P.m. service.	Syn0w20		5.00
- Rotate and balance all four tires . Nitrofill all and replace missing hub	ap . Napagold Oil Filte	r	1.00
- Transport to and from dealer for recall 18v-684 Pcm reprogram .	16in Exactfit-rear	16in Exactfit-rear Wiper Blade Anco Wiper Bleade Anco Cabin Air Filter	
- Shop Supplies	Wiper Blade Anco		
	Wiper Bleade Anco		
	Cabin Air Filter		
	Cap Sub Assy		1.00
	Shop Supplies		1.00
Hours: 5.00 Comm: 0.00	Labor: 335.00	Parts: 183.24	Total: 518.24

Work Order: 1907816 Meter: 44701 In Date: 07/29/2019 Closed: 07/31/2019

Problem: Replace key FOB battery.

 Work Completed
 Parts Issued
 Quantity

 - Replace key fob battery.
 Lithium Coin Cell
 1.00

 Hours: 0.20
 Comm: 0.00
 Labor: 13.40
 Parts: 5.42
 Total: 18.82

Work Order: 2000568 Meter: 47248 In Date: 01/16/2020 Closed: 01/27/2020

Problem: PM Service.

Work Completed	Parts Issued		Quantity	
- Pm Service.	Syn0w20		5.00	
- Rotate and balance tires.reset Tpms Correct all N2 levels.replace front right	Napagold Oil Filter	1.00		
hubcap.	Cap Sub Assy		1.00	
- Vacume debris from under hood.wash exterior.	Shop Supplies	1.00		
- Shop Supplies				
Hours: 4.00 Comm: 0.00	Labor: 292.00	Parts: 157.23	Total: 449.23	

Palm Beach County Fleet Management Asset Maintenance History 10189463 2013 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2002026 Meter: 47979 In Date: 02/27/2020 Closed: 03/05/2020

Problem: Towed in right rear tire flat .

Work CompletedParts IssuedQuantity- Repair right rear tire and balance . Nitrofill all.Shop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 4.00 Total: 77.00

Work Order: 2002169 Meter: 47776 In Date: 02/27/2020 Closed: 03/02/2020

Problem: Flat tire

Work Completed

- Tow From: Pinewood Lake Ct. 1140 13th rd South To: Lv shop

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2002860 Meter: 48335 In Date: 03/20/2020 Closed: 03/23/2020

Problem: Nail in tire.

Work CompletedParts IssuedQuantity- Repair left front tire and balance . Nitrofill all.Shop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 4.00 Total: 77.00

Palm Beach County Fleet Management Asset Maintenance History 10189463 2013 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2006970 Meter: 50005 In Date: 07/16/2020 Closed: 07/31/2020

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Pm Service.		Napagold Oil Filter		1.00
Replace damage right front rim and both right side hub caps.replace both front tiresand balance all four.Vacume debris from under hood.	ub caps.replace both	Syn0w20		5.00
		Washer Fluid Conc	entr	1.00
	16in Exactfit-rear		1.00	
- Shop Supplies		Wiper Bleade Anco)	1.00
		Wiper Blade Anco		1.00
		Air Filter (gold)		1.00
		Cabin Air Filter		1.00
		Tire Mic 195/65/15	2.00	
		Cap Sub Assy		2.00
		Wheel Tire		1.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 5.00	Comm: 0.00	Labor: 365.00	Parts: 1,023.23	Total: 1,388.2

Work Order: 2100513 Meter: 53325 In Date: 01/14/2021 Closed: 01/22/2021

Problem: P.M. service.

Work Completed		Parts Issued	Quantity
- Preventive Maint. Service- Rotate and balance all four tires . Nitro fill all.		Napagold Oil Filter	1.00
		Syn0w20	5.00
- Shop Supplies		Washer Fluid Concentr	1.00
		Wiper Blade Anco	1.00
		Wiper Bleade Anco	1.00
		Shop Supplies	1.00
Hours: 3.00	Comm: 0.00	Labor: 219.00 Parts: 47.11	Total: 266.11

Palm Beach County Fleet Management Asset Maintenance History 10189463 2013 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2106597 Meter: 55290 In Date: 06/17/2021 Closed: 06/17/2021

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 81.75 Total Labor: 5,170.40 Total Comm: 5,488.58 Total Parts: 4,019.85