



10/27/2022

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10194778

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V63431

In Date: 01/15/2014 Meter Reading:
Close Date: 01/17/2014

Problem?
AC vents missing on Lt side and new R33 placacards that fit

Task performed:	Parts	Quantity
TRAVEL TO ST. 33 TO INSTALL DASH A/C VENTS AND REPLACE NUMBER PLACARDS.	S PLACARD INSERTFRONT AND BACK INSERT CARD	1

Workorder: V62481

In Date: 12/04/2013 Meter Reading: 1,046.00
Close Date: 01/21/2014

Problem?
B INSPECTION NEW UNIT IN SERVICE R33

Task performed:	Parts	Quantity
1. REMOVE AND REPLACE REAR LIGHTS FOR DECALS.	101-124-000CRASH RESTRAINT STRAPS	4
2. FOUND BATT DEAD- BUT CHARGER ON BATT.	14-7014HGR-1 HELMET HOOK	2
3. B SERVICE AND INSPECTION.	5269LPVM-5 SM MOUNT	4
4. B SERVICE INSPECTION.	6092036018J HOOK STRYKER	1
5. FOUND TIRE MONITORS INOP- DISASSEMBLED SENSORS- CLEANED CONTACTS- INSTALLED AND SET- CHK OK.	680-10LAMERICAN FLAG W UV CLEAR LEFT	1
6. REMOVE STAR WASHERS FROM GROUND ON PAT BOX- REMOVED ALL GROUNDS AND WASHERS AND WASHERS- CLEANED CONTACTS- REASSEMBLED AND CHK OK.	680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
7. FOUND RT FRONT PAT BOX RUBBING ON EXH PIPE REMOVED CORNER PLATE AND TRIMMED PAT BOX- CHK OK.	FHLP-6TANK CLIP	8
8. INSTALL EQUIPMENT L-2.	KD-UN-6-SFBRACKET	4
9. MT TOOL HOLDERS IN L-2 MOVE O2 WRENCH AND GRIND O2 RATTLE SLIDE AND LATCH.	LPVM-7LG MOUNT	2
10. MT AN DINSTALL EQUIPMENT.	S PLACARDFRONT AND BACK PLACARD	1
11. MT SCBA BRKTS- REMOVED REAR LFT SPRING STRAPS REDRILLED AND MOUNTED.	UMVS162511STRAP	3
12. INSTALL AIR TANKS. BRACKETS AND ALL STRAPS. MOUNT SIDE DOOR AIR TANK ALSO INSTALL 3 LED LIGHT STATIONS ON L1 COMPARTMENT.		
13. FINISH CLEANING UP COMPARMENTS INSTALL STREAMER BRACKET CHANGE THE PATENT ON LIGHTS.		



10/27/2022

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10194778

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V63454

In Date: 01/16/2014

Meter Reading: 1,352.00

Close Date: 01/21/2014

Problem?

install glove box holders and stryker covers r33

Task performed:

1. TRAVEL TO STA 33, INSTALL GLOVE BOXES. NO DRILL TAP OR TAPS ON TRUCK. TRAVEL TO BACK TO SHOP FOR TOOLS. DRILL OUT NADAR COVER FOR BOLTS AT SHOP. TRAVEL TO 33, RESCUE ON CALL. DRILLED HOLES FOR NADAR PIN COVER TAP 2 HOLES. RESCUE CALLED OUT. TRAVEL BACK TO SHOP.

2. TRAVEL TO STA 33. TAP OUT NEW THREADS IN REAR AREA AND MOUNT NADAR PIN COVERS, FILL TOP OF COVERS FOR CLEARANCE ON BOTTOM OF REAR DOOR, DRILL AND TAP THREADS AND MOUNT RADIO HEADSET HOOKS. TRAVEL BACK TO SHOP.

Parts

Quantity

LPVM-7LG MOUNT

1

Q1500T3/CLLB-M15 240 V BULB

1

Workorder: V63761

In Date: 01/27/2014

Meter Reading: 2,548.00

Close Date: 01/31/2014

Problem?

R33 check engine light

Task performed:

TRACED OUT PROBLEM FOUND DIRTY SENSORS ON EXHAUST REGEN SYSTEM.

Parts

Quantity

NO PARTS USED

Workorder: V63607

In Date: 01/22/2014

Meter Reading:

Close Date: 02/07/2014

Problem?

The driver side air inlet is leaking air from behind the step. r33

Task performed:

CHECK OUT AIR LEAK ON STEP SPRAY W/ SOAP UNFOUNDED.

Parts

Quantity

NO PARTS USED



10/27/2022

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10194778

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V63455

In Date: 01/16/2014

Meter Reading: 1,352.00

Close Date: 02/13/2014

Problem?

move ny hook to rt rear compt. r33

Task performed:

MOVE BRKTS AND REMOUNT NY HOOK ON L-4 DOOR.

Parts

14-7014HGR-1 HELMET HOOK

Quantity

3

Workorder: V64148

In Date: 02/12/2014

Meter Reading:

Close Date: 02/13/2014

Problem?

The check engine light is on with an upside down triangle over it.

Task performed:

1. TRAVEL TO ST-33 CHECK TRUCK W/ READER NEEDS FORCE PARK REGEN TRY TO GET LAPTOP TO WORK NO LUCK SEND TO SHOP FPR REPAIR.
2. REPAIR TOOL HOLDER STRAP MOUNT BROKEN TAP AND REDRILL.

Parts

NO PARTS USED

Quantity

Workorder: V64164

In Date: 02/12/2014

Meter Reading: 4,652.00

Close Date: 02/18/2014

Problem?

Check enging light

Task performed:

1. CHK OIL AND COOLANT LEAKS- ADDED COOLANT- FOUND DIF PRESSURE CODE-CHK AND REPAIR CONNECTION OF SENSORS- RUN ENG RUN TESTS RAN REGAN- CHK OK.
2. CHK CODES- D.P.F SENSOR BIAS- REMOVED TUBES AND SENSOR- BLEW OUT TUBES- R&R SENSOR- TEST DROVE- CHECK CODES- CHK OK.

Parts

3626432C1SENSOR DPF PRESSURE DIFFERENTIAL

Quantity

1



10/27/2022

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10194778

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V64174

In Date: 02/12/2014

Meter Reading:

Close Date: 02/19/2014

Problem?

Amber upside down triangle on dash, with "warn engine" on the digital screen, with decrease in power to truck. Happens intermittently, once truck is shut down and restarted warnings go away and power is restored.

Task performed:

Parts

Quantity

REPAIRED AT SHOP.

NO PARTS USED

Workorder: V64185

In Date: 02/13/2014

Meter Reading:

Close Date: 02/25/2014

Problem?

Issue continuing through the night, happening more frequently, engine light staying on now. Warning lights and power reduction occurring upon acceleration.

Task performed:

Parts

Quantity

VEHICLE SENT TO DEALER.

NO PARTS USED

Workorder: V64239

In Date: 02/15/2014

Meter Reading:

Close Date: 02/25/2014

Problem?

Check engine light, on new R33 still on.

Task performed:

Parts

Quantity

VEHICLE SENT TO DEALER.

3536182C1RESET BREAKERS NEW HORTONS

1

Workorder: V64256

In Date: 02/16/2014

Meter Reading:

Close Date: 02/25/2014

Problem?

The engine light and the up side down triangle are lit on the dash. When they light up the truck has less power. R33

Task performed:

Parts

Quantity

VEHICLE SENT TO DEALER.

NO PARTS USED



10/27/2022

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10194778

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V64306

In Date: 02/18/2014

Meter Reading:

Close Date: 02/25/2014

Problem?

R33 problems continue; Check engine light Losing power strong exhaust odor in cab

Task performed:

Parts

Quantity

VEHICLE SENT TO DEALER.

NO PARTS USED

Workorder: V64915

In Date: 03/13/2014

Meter Reading: 5,556.00

Close Date: 03/17/2014

Problem?

C inspection R33

Task performed:

Parts

Quantity

1. PERFORM C INSPECTION.
2. ASSIST LUIS WITH C-INSPECTION.

15W40BSYN OIL BULK QTS

30

1884207C92FUEL FILTER MAXFORCE 7

1

1899332C91OIL FILTER MAXFORCE 7

1

2602212C1PRIMARY AIR FILTER 4300M7

1

3839141C1FILTER CAB AIR

1

Workorder: V63427

In Date: 01/15/2014

Meter Reading:

Close Date: 03/20/2014

Problem?

need 2 NEW number plates for side and 1 NEW small number plate for rear for new rescue. Current plates do not fit .

Task performed:

Parts

Quantity

REPAIRED ON ANOTHER WORK ORDER.

NO PARTS USED

Workorder: V65119

In Date: 03/22/2014

Meter Reading: 6,823.00

Close Date: 03/24/2014

Problem?

on call check engine light on r33

Task performed:

Parts

Quantity

CHECK ENGINE LIGHT CAME ON FOR AFTER AFTER TREATMENT I PARTICULATE TRAP CLEARED CODES

NO PARTS USED



10/27/2022

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10194778

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V65384

In Date: 04/01/2014

Meter Reading:

Close Date: 04/08/2014

Problem?

Strong exhaust smell in cab. Hot exhaust light on for short period during smell. Now solid check engine light on continuously r33

Task performed:

Parts

Quantity

UNIT SENT TO RECHTIEN FOR REPAIRS.

NO PARTS USED

Workorder: V65192

In Date: 03/25/2014

Meter Reading:

Close Date: 04/09/2014

Problem?

Door locks dont work..

Task performed:

Parts

Quantity

TRAVEL TO H.Q CHECK DOOR LOCKS INOP, CHECK SYST. FOUND BAD FUSE ON CKT BOARD AND REPLACE.

NO PARTS USED

Workorder: V65241

In Date: 03/26/2014

Meter Reading:

Close Date: 04/09/2014

Problem?

Dash light of a wrench, change oil light.

Task performed:

Parts

Quantity

RESET SERVICE LIGHT ON DASH.

NO PARTS USED

Workorder: V65771

In Date: 04/17/2014

Meter Reading: 8,014.00

Close Date: 04/18/2014

Problem?

Drivers seat loose cushion

Task performed:

Parts

Quantity

1. INSTALL DRIVERS SEATR CUSHION.
2. AS PER JOH MURRAY, DISABLE BAACKING UP WARNING SYSTEM (NOT BACKUP ALARM).

NO PARTS USED



10/27/2022

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10194778

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V63978

In Date: 02/04/2014

Meter Reading:

Close Date: 04/21/2014

Problem?

Please tint windows on next schedule B service. Thanks

Task performed:

Please tint windows on next schedule B service.

Parts

NO PARTS USED

Quantity

Workorder: V65823

In Date: 04/19/2014

Meter Reading: 8,305.00

Close Date: 04/21/2014

Problem?

c/e light on

Task performed:

WENT TO SHOP FOR SPARE, SPARE BROKE BEFORE IT GOT TO STATION. MET UNIT BACK SHOP, R&R TURBO CLAMP WENT TO ST-5.

Parts

15W40QSYN OIL QT

Quantity

1

Workorder: V66397

In Date: 05/12/2014

Meter Reading: 8,959.00

Close Date: 05/13/2014

Problem?

engine throttle surging at idle

Task performed:

ENGINE SURGING LESS OF POWER- NO PROBLEM FOUND NO CODES COULD NOT DUPLICATE PROBLEM.

Parts

NO PARTS USED

Quantity

Workorder: V66583

In Date: 05/19/2014

Meter Reading: 9,828.00

Close Date: 05/22/2014

Problem?

PAT a/c inop

Task performed:

PAT A/C INOP-LOSS OF POWER AT CONDENSOR PANS TRACED WIRE BACK UP FRONT INTO CAB AND FOUND BRAKER SHORTED OUT REPLACED BRAKER AND CONNECTION.

Parts

1261A/C RELAY

54-53030055-30BX CIRCUIT BREAKER

Quantity

1

1



10/27/2022

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10194778

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V66603

In Date: 05/20/2014

Meter Reading:

Close Date: 05/23/2014

Problem?

Boot torn connecting front cab to rear patient compartment, rain water leaking into both areas. R33

Task performed:

Parts

Quantity

LET FORMAN KNOW TO CALL HORTON FOR REPLACEMENT.

NO PARTS USED

Workorder: V66379

In Date: 05/10/2014

Meter Reading:

Close Date: 06/13/2014

Problem?

1. SRS Fault warning 2. Box light not functioning R33

Task performed:

Parts

Quantity

replaced light box with new style,
call horton for warrant on srs system waiting for call.

NO PARTS USED

Workorder: V66744

In Date: 05/25/2014

Meter Reading:

Close Date: 07/08/2014

Problem?

Window tint for front cab.

Task performed:

Parts

Quantity

Window tint for front cab.

NO PARTS USED

Vendor?: 60 MINUTE AUTO TINT

Workorder: V65363

In Date: 04/01/2014

Meter Reading:

Close Date: 07/17/2014

Problem?

(1)Strong exhaust smell intermittently in cab! (2)Door lock buttons not functioning. (3)Change oil, wrench light on dash. R33

Task performed:

Parts

Quantity

REPAIRS COMPLETE ON TWO TICKETS
V65192/65384.OUT SIDE REPAIRS

NO PARTS USED



10/27/2022

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10194778

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V68009

In Date: 07/18/2014

Meter Reading: 11,288.00

Close Date: 07/23/2014

Problem?

pat a/c inop

Task performed:

1. Checked patient A/C cleaned condensor. Installed gauges. Remove and replace air filters. Added 8 oz of freon. 64 dgreees vent, 23 degrees intake ran and check ok.

Parts

Quantity

0775145PANEL FILTER

2

Workorder: V67915

In Date: 07/14/2014

Meter Reading:

Close Date: 07/30/2014

Problem?

Comp 7 door "open alarm" is coming on with the door closed. Rubber gasket between cab and box is ripped. r33

Task performed:

travel to sta 33 ck,out d.o.w. unhook untill horton tech repairs, boot ect,.

Parts

Quantity

NO PARTS USED

Workorder: V68360

In Date: 08/02/2014

Meter Reading:

Close Date: 08/07/2014

Problem?

Valve extension with blinking light broke off. Tire valve appears to be ok.

Task performed:

TRAVEL TO STA,33 CK, OUT TIRE VALUE INOP, FOUND EXTENTION BAD INATALLED GATOR VALUE AND FILLED TIRES.

Parts

Quantity

NO PARTS USED

Workorder: V66404

In Date: 05/12/2014

Meter Reading:

Close Date: 08/20/2014

Problem?

R33 had power reduction problem occur last night while on emergency call. A 2nd rescue had to be called to trans a priority 2 patient. On call mechanic notified- could not duplicate problem.

Task performed:

WENT TO INTERNATIONAL FOR REPAIRS.

Parts

Quantity

NO PARTS USED



10/27/2022

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10194778

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V66521

In Date: 05/16/2014

Meter Reading:

Close Date: 08/20/2014

Problem?

Multiple ocurrences last night when turning on the engine while leaving the hospital. The engine light with a triangle over it comes on and a message that says "electicle faulty", and when accelerating the engine sputters.

Task performed:

Parts

Quantity

WENT TO INTERNATIONAL FOR REPAIRS (WARRANT!!!) MAYBE.

NO PARTS USED

Workorder: V67934

In Date: 07/15/2014

Meter Reading:

Close Date: 08/20/2014

Problem?

Door ajar alarm sounding, warning light for rear storage compartment. Exposed wires near door sensor. Rubber jacket between cab and pt compt. cracked, leaks inside pt compt when raining

Task performed:

Parts

Quantity

AT SHOP BUT CALLED FOR WARRANT WORK AND REPAIRS FOR HORTON.

NO PARTS USED

Workorder: V68586

In Date: 08/11/2014

Meter Reading:

Close Date: 08/21/2014

Problem?

Check engine light Inverted triangle light De-powering

Task performed:

Parts

Quantity

unit sent to Rechten
reprogrammed fuel pressure adaption reset feature
they clamied code was cleared and no check engine light on
unit came back, check engine light on - same code
unit serviced on B ticket and then sent back to Rechten

NO PARTS USED

Vendor?: RECHTIEN

Workorder: V65850

In Date: 04/21/2014

Meter Reading: 8,305.00

Close Date: 08/25/2014

Problem?

c/e light

Task performed:

Parts

Quantity

WENT TO INTERNATTIONAL FOR REPAIRS.

NO PARTS USED



10/27/2022

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10194778

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V68628

In Date: 08/12/2014

Meter Reading: 14,003.00

Close Date: 10/09/2014

Problem?

B inspection R33, check engine light - low power

Task performed:

1. Work o "B" inspection.
2. Work on "B" Inspection and repairs. Top of antifreeze. Rpelace wuiper blades. Replace air filter.
3. Work on repairs. Adjust and tighten L3 door shock bracket, relocate. Left rear cab door weather seal.
4. Remove drive line U joint cap. Clean and reinstall back with lock tight. Torque to specifactions.

Parts

Quantity

1884207C92FUEL FILTER MAXFORCE 7	1
1899332C91OIL FILTER MAXFORCE 7	1
2602212C1PRIMARY AIR FILTER 4300M7	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	3
HP-31DBATTERY 950CCA HP-31D	3

Workorder: V70022

In Date: 10/09/2014

Meter Reading: 14,003.00

Close Date: 10/29/2014

Problem?

prep for R37, QA

Task performed:

1. Detail R37 interior and patient compartment for delivery and QA for any problems and test drive.
2. Ensure R37 QA

Parts

Quantity

0775145PANEL FILTER	2
211-2BULB	2

Workorder: V70331

In Date: 10/09/2014

Meter Reading: 14,003.00

Close Date: 10/31/2014

Problem?

prep for R37, QA

Task performed:

1. Check engine codes. Check engine and body codes. Check OK.
2. Removed fire monitors. Removed front axle monitors. Check and adjust front tire air pressure. R & R all monitors.
3. Found patient box leaning to one side. Adjusted air bags. Check OK.
4. Quality Assessment Inspection. Found inside door won't lock. Replaced screws and adjusted lock. Check OK.

Parts

Quantity

NO PARTS USED



10/27/2022

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10194778

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V70476

In Date: 10/27/2014

Meter Reading: 14,619.00

Close Date: 11/03/2014

Problem?

High Temp Exhaust Light Lit On Dash And Engine Is Running Erraticly.Engine RPM's are jumping around and shaking the truck. Attempted rejen of engine and rejen will not start, rejen light flashes and just turns off

Task performed:

Parts

Quantity

1. Repaired on 10/27/14.

NO PARTS USED

Workorder: V70477

In Date: 10/27/2014

Meter Reading: 14,619.00

Close Date: 11/03/2014

Problem?

When vehicle is parked in neutral with brake on the front light bar and flashing headlights shut down completly. This allows for n advanced warning lights toward oncoming head on vehicles when parked in roadway.

Task performed:

Parts

Quantity

1. Travel to station 37. Check out front light bar going off in secondary mode. Reprogram Intelliplex to hold light bar on, on secondary mode.

NO PARTS USED

Workorder: V70478

In Date: 10/27/2014

Meter Reading: 14,619.00

Close Date: 11/03/2014

Problem?

Ground light to the right of side entry door is hanging by one screw, remaining screws from bracket are not present, and light is danging under truck

Task performed:

Parts

Quantity

1. Re-install ground light on passenger side of truck falling off.

NO PARTS USED

Workorder: V70491

In Date: 10/28/2014

Meter Reading: 14,704.00

Close Date: 11/03/2014

Problem?

R37 went into Exhaust Temp Hot mode while transporting pt to JFK again tonight and did the same eratic engine idling and shakir of the truck as it did earlier today before it was serviced/rejen this afternoon.

Task performed:

Parts

Quantity

1. Will bring truck to shop for repairs.

NO PARTS USED



10/27/2022

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10194778

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V70539

In Date: 10/29/2014
Close Date: 11/03/2014

Meter Reading: 14,767.00

Problem?

Parked regen having to be done twice a shift at station 37, for rescue 37.

Task performed:

Repaired on 10/27/14.

Parts

Quantity

NO PARTS USED

Workorder: V70390

In Date: 10/23/2014
Close Date: 11/05/2014

Meter Reading: 14,003.00

Problem?

Check a/c compressor mounting bolts

Task performed:

Travel from station 35 to station 37
Inspect and retorque patient A/C compressor bracket

Parts

Quantity

NO PARTS USED

Workorder: V70590

In Date: 10/30/2014
Close Date: 11/06/2014

Meter Reading: 14,848.00

Problem?

Fuel gauge not working properly on truck.

Task performed:

Repaired on W/O#70575.

Parts

Quantity

3864392C92FUEL SENDER

1

Workorder: V70575

In Date: 10/30/2014
Close Date: 11/12/2014

Meter Reading:

Problem?

Fuel gauge not reading properly. Gauge was showing less than 1/4 tank but only took 13 gallons.

Task performed:

Check out fuel gauge inop will order new sender.

Parts

Quantity

NO PARTS USED



10/27/2022

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10194778

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V70702

In Date: 11/04/2014

Meter Reading:

Close Date: 11/12/2014

Problem?

Rear compartment door latch not holding.

Task performed:

Parts

Quantity

Travel to station 37, check out rear door inop adjust latch and striker, lube and tets ok.

NO PARTS USED

Workorder: V70921

In Date: 11/14/2014

Meter Reading: 15,865.00

Close Date: 11/18/2014

Problem?

clicking sound heard when plugging in shore line

Task performed:

Parts

Quantity

Travel to station 37, check out shoreline inop. Found brake air compressor inop call for warranty they are going to repair another problem next week.

NO PARTS USED

Workorder: V70986

In Date: 11/17/2014

Meter Reading:

Close Date: 11/18/2014

Problem?

fuel gauge is not working and constantly sounds low fuel alarm.

Task performed:

Parts

Quantity

Repaired at international warranty

NO PARTS USED

Workorder: V70985

In Date: 11/17/2014

Meter Reading: 16,139.00

Close Date: 11/20/2014

Problem?

Passenger rear window and door locking buttons inopperable.

Task performed:

Parts

Quantity

SENT TO DEALER FOR REPAIR.

NO PARTS USED



10/27/2022

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10194778

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V70988

In Date: 11/17/2014

Meter Reading: 16,139.00

Close Date: 11/20/2014

Problem?

When the truck is driven at a higher speed on I95 for a distance such as from 37 to HQ the yellow high temp exhaust light comes on the dash and truck starts to run erratic at speed and an idle with no regen available

Task performed:

SENT TO DEALER FOR REPAIR.

Parts

NO PARTS USED

Quantity

Workorder: V71989

In Date: 01/01/2015

Meter Reading:

Close Date: 01/05/2015

Problem?

12 volt outlets are not working throughout the cab and patient compartment R37

Task performed:

Travel to station 37-check cab 12v outlet inop-found blown breaker on dash. Repair check out rear body 12v outlet-found blown fuse on rear circuit board, R/R fuse

Parts

NO PARTS USED

Quantity

Workorder: V72595

In Date: 01/26/2015

Meter Reading: 19,089.00

Close Date: 01/27/2015

Problem?

Check engine light

Task performed:

V engine light on. Code 3251. Reset codes and road tested. Code did not come back.

Parts

NO PARTS USED

Quantity

Workorder: V72430

In Date: 01/19/2015

Meter Reading:

Close Date: 02/03/2015

Problem?

Interior cab lights will not turn off. Set as high priority because the bright light obstructs vision of roadway while driving at night.

Task performed:

- Travel to ST 37. Check dome lights inoperable. Found switch covers off. Adjust door for now. Will return to replace.
- Travel to ST 37. R & R cab door switches. Boots missing. Rewire test OK.

Parts

14-7014HGR-1 HELMET HOOK
3579984C1DOOR SWITCH

Quantity

4
4



10/27/2022

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10194778

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V72890

In Date: 02/05/2015

Meter Reading:

Close Date: 02/13/2015

Problem?

Check engine light turned on during a call, also little wrech icon for oil change turned on. Duriing morning checkout none of the light were turned on.

Task performed:

Parts

Quantity

Travel to ST 37. Check out Check Engine light. Exhaust DPF code -will repair at shop on next PM. Reset oil service light.

NO PARTS USED

Workorder: V73581

In Date: 03/03/2015

Meter Reading: 21,907.00

Close Date: 03/09/2015

Problem?

involved in MVA

Task performed:

Parts

Quantity

REPAIED R/S CAB STOP THAT WAS DAMAGED IN ACCIDENT

NO PARTS USED

Workorder: V73832

In Date: 03/12/2015

Meter Reading: 22,731.00

Close Date: 04/06/2015

Problem?

C inspection R37

Task performed:

Parts

Quantity

1. C-Inspection.
2. Air bags suspension damage- Remove air bags and install new ones.
3. Air dryer service.
4. L/Rear frame rail chassie suspension mount bolts loose. Retorque and check night side and retorque.
5. Torque front and rear U-bols.
6. A/C filter cab rear- Remove serviceable filter- Wash and blow out- Reinstall.
7. Coolant low pressure, test system- found engine to cab fitting leaking and hose pinch- Tighten fitting - Remove damage hose- Install new section of hose- All reservoir and pressure system no leaks.
8. Engine code DPF3251 and 629- Outside vender repair.

065624AD-IP DRIER

1

1884207C92FUEL FILTER MAXFORCE 7

1

1899332C91OIL FILTER MAXFORCE 7

1

3839141C1FILTER CAB AIR

1

GUI1R11216GY1R11216 AIR BAG INT.

2

K022105PURGE VALVE AD-IP-IS

1



10/27/2022

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10194778

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V74679

In Date: 04/11/2015
Close Date: 04/27/2015

Meter Reading: 23,865.00

Problem?

Air leak

Task performed:

Parts

Quantity

1. Removed and replaced leaking valve and tested.

NO PARTS USED

Workorder: V74336

In Date: 03/31/2015
Close Date: 05/05/2015

Meter Reading: 22,731.00

Problem?

quality check

Task performed:

Parts

Quantity

1. Perform Q.C. inspection on unit. Remove cab edge seals and adjust rear patient compartment door latch, is good.

NO PARTS USED

Workorder: V74433

In Date: 04/05/2015
Close Date: 05/11/2015

Meter Reading:

Problem?

Pressure gauge on water can is broken. R37

Task performed:

Parts

Quantity

1. Check out water can gauge, give crew new water can

NO PARTS USED

Workorder: V73525

In Date: 02/28/2015
Close Date: 06/04/2015

Meter Reading:

Problem?

Driver side front tire thread is low.

Task performed:

Parts

Quantity

replace front tires

NO PARTS USED

Vendor?: ELPEX



Palm Beach County Fire Rescue

Fleet Maintenance Asset History

Asset: (10194778) 2014 - INTERNATIONAL HORTON Advanced Life Support Vehicle R273

10194778

CSHOP-2015-1014

Comments: SEAT BELT RETAINING PIN THAT KEEPS BELT BUCKLE ELEVATED ON STRAP HAS FALLEN OUT DIFFICULT TO REACH SAFELY WHEN GOING ON CALLS R37

Date Opened: 6-5-2015 Date Finished 6-17-2015 Meter 1 Reading: 25,572

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
SEAT BELTS

CSHOP-2015-1207

Comments: BACK PATIENT AC LEAKING WATER AT THE BASE CAUSING DAMAGE TO SOME MEDICAL EQUIPMENT R37 UNIT NEEDED 4 REGENS 6/17 - POSSIBLE ISSUE STARTING

Date Opened: 6-16-2015 Date Finished 6-19-2015 Meter 1 Reading: 25,572

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES
HVAC SYSTEM

CSHOP-2015-1454

Comments: TRUCK IS SAYING PARKED REGEN AVAILABLE, BUT WILL NOT ALLOW REGEN WHEN TRIED R37

Date Opened: 6-29-2015 Date Finished 6-29-2015 Meter 1 Reading: 25,572

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

CSHOP-2015-1949

Comments: R37 STEP LOOSE

Date Opened: 7-24-2015 Date Finished 7-24-2015 Meter 1 Reading: 25,572

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BODY & HOPPER

Asset Work Order History 10194778

CSHOP-2015-2006

Comments: CAB AC FRONT AND REAR INOP R37

Date Opened: 7-28-2015 Date Finished 8-3-2015 Meter 1 Reading: 25,572

AC HOSE BROKE

TASKS PERFORMED

Q PARTS

WAIT TIME TO BE CHARGED TO WORK ORDER
TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

1 9IP; AIR COMPRESSOR CAB V8
1 FILTER; FILTER DRYER A/C V8 CAB
1 SWITCH; SWITCH A/C PRESSURE INT.
1 SWITCH LOW PRESSURE
1 HOSE A/C COMPRESSOR TO CONDENSOR
1 VALVE; EXP VALVE
1 FILTER; CAB FILTER RED DOT

CSHOP-2015-221

Date Opened: 4-22-2015 Date Finished 4-28-2015 Meter 1 Reading: 24,284

TASKS PERFORMED

Q PARTS

EMISSIONS SYSTEM
A/C FILTER
HVAC SYSTEM

2 FILTER; FILTER CAB A/C SIDE INTERNAL BOX
1 PROBE; FREEZE PROBE

CSHOP-2015-2310

Comments: B SERVICE R37 BY OCS

Date Opened: 8-13-2015 Date Finished 9-28-2015 Meter 1 Reading: 33,210

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FILTER; FILTER CAB AIR
1 FILTER; OIL FILTER MAXFORCE 7
1 FILTER; FUEL FILTER MAXFORCE 7

CSHOP-2015-2524

Comments: REPLACE REAR TIRES

Date Opened: 8-25-2015 Date Finished 8-25-2015 Meter 1 Reading: 25,572

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? ELPEX TIRE TIRESOLES

CSHOP-2015-2605

Comments: CALL OUT R37 NO START

Date Opened: 8-29-2015 Date Finished 9-4-2015 Meter 1 Reading: 31,635

TASKS PERFORMED

Q PARTS

FUEL PRIMING PUMP

1 9IP; FUEL PUMP KIT

Asset Work Order History 10194778

CSHOP-2015-2749

Comments: **ON-CALL LOW VOLTAGE**

Date Opened: 9-8-2015 Date Finished 9-8-2015 Meter 1 Reading: 32,489

TASKS PERFORMED

NO PARTS USED

BATTERY CABLE

CSHOP-2015-2892

Comments: **ON-CALL R37 OIL ON BACK OF UNIT**

Date Opened: 9-14-2015 Date Finished 9-14-2015 Meter 1 Reading: 32,970

TASKS PERFORMED

NO PARTS USED

OIL

CSHOP-2015-2910

Comments: **R37 NO PAT A/C**

Date Opened: 9-15-2015 Date Finished 9-16-2015 Meter 1 Reading: 33,210

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

CSHOP-2015-3257

Date Opened: 10-6-2015 Date Finished 10-19-2015 Meter 1 Reading: 167,719

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
HVAC SYSTEM

1 BULB; H9007 BULB ASSY

Service Requests:

10/06/2015 LIGHTS / 19: LOOSE / REPAIR
OFFICER SIDE HEAD LIGHT IS OUT. NEEDS REPLACEMENT.

10/09/2015 LIGHTS / 19: LOOSE / REPAIR
LED FLASH LIGHT NOT TURNING ON R37. LIGHT PLACED IN CAPTAIN'S OFFICE FOR PICK UP.

CSHOP-2015-3341

Comments: **R37 CHECK ENGINE OIL PRESSURE**

Date Opened: 10-9-2015 Date Finished 10-15-2015 Meter 1 Reading: 167,719

TASKS PERFORMED

NO PARTS USED

TOWING HITCH
OIL
ENGINE AND ACCESSORIES

VENDOR? WESTWAY TOWING

Asset Work Order History 10194778

CSHOP-2015-3652

Comments: **R37 QUALITY CHECK, BACK FROM RECHTIEN**

Date Opened: 10-28-2015 Date Finished 10-29-2015 Meter 1 Reading: 35,087

TASKS PERFORMED

NO PARTS USED

STROBE LIGHTS
AIR HORN
QUALITY CHECK-REPAIRS

CSHOP-2015-3810

Comments: **R37 AIR LEAK ALSO**

Date Opened: 11-6-2015 Date Finished 11-9-2015 Meter 1 Reading: 35,771

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
AIR SYSTEM

1 BULB; H9007 BULB ASSY

Service Requests:

11/05/2015 LIGHTS / 12: BROKEN / REPAIR
DRIVERS SIDE HEAD LIGHT NOT WORKING

CSHOP-2015-3864

Comments: **R37 TURBOCHARGER FAILURE**

Date Opened: 11-9-2015 Date Finished 11-19-2015 Meter 1 Reading: 35,892

SMOKING AND OIL LEAKING FROM EXHAUST

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES

1 FILTER; PRIMARY AIR FILTER 4300M7
1 NEWPART; TURBO KIT V8 INT.
1 NEWPART; DPF 5010847R1
1 TUBE; TUBE ASSY RELIEF TO DUCT
1 NEWPART; RING EXHAUST
1 NEWPART; SEAL
1 NEWPART; MOUNTING KIT TURBO
1 GASKET; DPF GASKET
4 NEWPART; SEAL ORING
1 NEWPART; KIT HOSE
1 NONSTOCK; CORE CHARGE
1 NONSTOCK; CORE CHARGE
1 NEWPART; OIL FEED LINE TURBOCHARGER V8 INT.
1 NEWPART; KIT TURBO MOUNT
1 NEWPART; STUD TURBO V8 INT.
1 NEWPART; TURBOCHARGER V8 INT.
2 9IP; GASKET TURBO V8
1 GASKET; DPF GASKET
1 SOLENOID; TUBE ASSY BOOST TO SOLENOID
1 NONSTOCK; FREIGHT CHARGE

Asset Work Order History 10194778

CSHOP-2015-4305

Comments: **R37 INSTALL OIL DIPSTICK TUBE GROMMET**

Date Opened: 12-4-2015 Date Finished 12-7-2015 Meter 1 Reading: 35,895

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES

1 9IP; DIPSTICK TUBE SEAL V8

CSHOP-2015-4491

Date Opened: 12-15-2015 Date Finished 12-15-2015 Meter 1 Reading: 36,049

TASKS PERFORMED

NO PARTS USED

HOSE UPPER

CSHOP-2015-614

Comments: **R-37 DRIVER SIDE REAR SEAT BELT BROKEN.**

Date Opened: 5-13-2015 Date Finished 6-2-2015 Meter 1 Reading: 25,572

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SEAT BELTS

1 9IP; BELT RECIEVER
1 BELT; SEAT BELT

CSHOP-2015-675

Comments: **R37 PAT A/C COMPRESSOR LOCKED UP**

Date Opened: 5-18-2015 Date Finished 5-16-2015 Meter 1 Reading: 25,572

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

CSHOP-2015-735

Comments: **A/C COMPRESSOR LOCKED UP R37**

Date Opened: 5-20-2015 Date Finished 6-8-2015 Meter 1 Reading: 25,572

TASKS PERFORMED

Q PARTS

DIAGNOSE ELECTRICAL
HVAC SYSTEM

1 ROTARY THERMOSTAT
1 RELAY; RY48 RELAY
1 9IP; AIR COMPRESSOR CAB V8
1 PULLEY GROOVED V8
1 BELT; K060764 BELT A/C M7
1 BELT; FAN BELT V8 INT DUAL AIR COMPRESSOR

Asset Work Order History 10194778

CSHOP-2016-1036

Comments: **R37 HEADLIGHT**

Date Opened: 3-4-2016

Date Finished

3-14-2016

Meter 1 Reading:

36,506

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HEADLIGHTS LOW BEAM

1 9IP; 9005XS HIGH BEAM BULB
-1 BULB; H9007 BULB ASSY
1 BULB; H9007 BULB ASSY

Service Requests:

03/03/2016

LIGHTS / 12: BROKEN / REPAIR
DRIVER SIDE HEADLIGHT IS OUT OF SERVICE.

CSHOP-2016-1181

Date Opened: 3-11-2016

Date Finished

3-15-2016

Meter 1 Reading:

36,781

TASKS PERFORMED

NO PARTS USED

BUMPER FRONT

CSHOP-2016-1299

Date Opened: 3-17-2016

Date Finished

3-17-2016

Meter 1 Reading:

36,927

TASKS PERFORMED

Q PARTS

STRETCHER

1 NEWPART; STRIKER BAR/RAIL ASSY

CSHOP-2016-1348

Comments: **10194778 AT 23 CHECK ENGINE LIGHT ON. O2 SYSTEM LEAKS**

Date Opened: 3-21-2016

Date Finished

3-22-2016

Meter 1 Reading:

37,469

TASKS PERFORMED

Q PARTS

EMISSIONS SYSTEM
REPAIR FROM PM - O2 SYSTEM

1 GASKET; DPF GASKET
1 GASKET; DPF GASKET
1 9IP; CLEANED UNIT

Service Requests:

03/20/2016

SERVICE REQUEST / 14: CRACKED / CHECK ENGINE LAMP ON AND BLOWING BLACK SMOKE. PF
CHECK ENGINE LIGHT HAS APPEARED.

Asset Work Order History 10194778

CSHOP-2016-1398

Comments: **R37**

Date Opened: 3-23-2016

Date Finished

3-24-2016

Meter 1 Reading:

37,469

TASKS PERFORMED

NO PARTS USED

WAIT TIME TO BE CHARGED TO WORK ORDER
TRAVEL TO BE CHARGED TO WORK ORDER
BRAKES

Service Requests:

03/23/2016

BRAKES / 12: BROKEN / REPAIR

WHEN SLOWING, WHILE PUSHING ON THE BREAK PEDAL, THERE IS A "CLUNK" SOUND THEN THE BREAKS GRAB HARD W/ THE SAME AMOUNT OF PRESSURE BEING APPLIED.

CSHOP-2016-1681

Comments: **R37**

Date Opened: 4-11-2016

Date Finished

4-14-2016

Meter 1 Reading:

38,510

CAB AC LOW ON FREON

TASKS PERFORMED

Q PARTS

WIPER BLADES
A/C LOW FREON

2	WIPER; WIPER BLADE
2	ORING; ORING A/C
1	FILTER; FILTER DRYER A/C V8 CAB
1	SWITCH; SWITCH A/C LOW PRESSURE
1	A/C; 17-3428 ESTER OIL E7
1	VALVE; EXP VALVE
2	SEAL; SEAL PLATE A/C

Service Requests:

04/09/2016

W/S WIPER / 12: BROKEN / EXCHANGE - NEW
BOTH WIPER BLADES TORN

04/13/2016

A/C / 19: LOOSE / EXCHANGE - NEW
FRONT CAB

CSHOP-2016-2081

Comments: **R41**

Date Opened: 5-2-2016

Date Finished

5-17-2016

Meter 1 Reading:

41,385

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM
HVAC SYSTEM

Service Requests:

04/30/2016

A/C / 18: LEAKING / S
FRONT CAB REAR THIRD PERSON A/C IS LEAKING FROM TUBE

Asset Work Order History 10194778

CSHOP-2016-213

Date Opened: 1-15-2016 Date Finished 1-27-2016 Meter 1 Reading: 36,280

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

VENDOR? RECHTIEN INTERNATIONAL TRUCKS

CSHOP-2016-2270

Comments: **R37**

Date Opened: 5-11-2016 Date Finished 6-3-2016 Meter 1 Reading: 42,698

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM
HVAC SYSTEM

Service Requests:

05/10/2016 A/C / 12: BROKEN / REPAIR
REAR CAB AC WORKS INTERMITTENTLY

CSHOP-2016-2374

Comments: **PM FOLLOW UPS OLD R37**

Date Opened: 5-17-2016 Date Finished 5-26-2016 Meter 1 Reading: 41,993

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SEAL
FRONT TIRES

1 9IP; 370023A SEAL
2 FILTER; PANEL FILTER
1 FILTER; AF27958 FILTER CAB AIR

Service Requests:

05/17/2016 ENGINE / 12: BROKEN / ADJUST
(2) DASHBOARD LIGHTS ARE ON: ONE CHECK ENGINE LIGHT IS ON AND THE OTHER IS A WRENCH SHAPED LIGHT.

CSHOP-2016-2399

Date Opened: 5-18-2016 Date Finished 5-20-2016 Meter 1 Reading: 41,552

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

30 FLUID; SYN OIL BULK QTS
1 FILTER; OIL FILTER MAXFORCE 7
1 FILTER; FUEL FILTER MAXFORCE 7

Asset Work Order History 10194778

CSHOP-2016-2475

Comments: **R41**

Date Opened: 5-23-2016

Date Finished

6-3-2016

Meter 1 Reading:

42,698

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
INSTRUMENTS-GAUGES-METERS

Service Requests:

05/23/2016

ENGINE / 19: LOOSE / S
CHECK ENGINE LIGHT IS ON

CSHOP-2016-2637

Comments: **SR @ ST43 TIRES WERE INSTALLED BY CALLAGHAN WITH OUR STOCK WO#2374**

Date Opened: 6-2-2016

Date Finished

6-8-2016

Meter 1 Reading:

43,059

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
REAR TIRES

Service Requests:

06/02/2016

LIGHTS / 18: LEAKING / F
EMERGENCY LIGHT ON THE BOTTOM PASSENGER SIDE OF CAB IS FALLING OUT, SCREWS ARE NOT SECURE.

CSHOP-2016-2815

Comments: **NO REPAIRS COMPLETED ON THIS WORK ORDER THEY WERE DONE ON ANOTHER WORK ORDER**

Date Opened: 6-13-2016

Date Finished

8-6-2016

Meter 1 Reading:

47,601

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

3 A/C; FREON LB

CSHOP-2016-3222

Comments: **R41**

Date Opened: 7-5-2016

Date Finished

8-13-2016

Meter 1 Reading:

47,796

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES
HVAC SYSTEM

3 A/C; FREON LB

Service Requests:

07/04/2016

ENGINE / 18: LEAKING / INSPECT
LEAKING OIL

Asset Work Order History 10194778

CSHOP-2016-3582

Comments: **CALLED CALLAGHAN 7-27-16**

Date Opened: 7-27-2016 Date Finished 8-13-2016 Meter 1 Reading: 47,796

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
TIRES & WHEELS

Service Requests:

07/23/2016 TIRES / 44: WORN / EXCHANGE - NEW
REAR TIRES NEED REPLACEMENT

CSHOP-2016-3665

Date Opened: 8-1-2016 Date Finished 8-1-2016 Meter 1 Reading: 47,250

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2016-3855

Comments: **ENGINE NOISE**

Date Opened: 8-8-2016 Date Finished 8-11-2016 Meter 1 Reading: 47,588

TASKS PERFORMED

Q PARTS

STRETCHER	-1	NEWPART; STRIKER BAR/RAIL ASSY
WIPERS-WASHER	1	NEWPART; STRIKER BAR/RAIL ASSY
HANGER-CLAMP	2	WIPER; WIPER BLADE
FAULT CODE	1	FILTER; PRIMARY AIR FILTER 4300M7
ENGINE AND ACCESSORIES	-1	FILTER; AF27958 FILTER CAB AIR
AUTO-EJECT	1	FILTER; AF27958 FILTER CAB AIR
SUSPENSION	-1	FILTER; OIL FILTER MAXFORCE 7
BRAKES	1	FILTER; OIL FILTER MAXFORCE 7
AIR DRIER	-1	FILTER; FUEL FILTER MAXFORCE 7
AIR HORN	1	FILTER; FUEL FILTER MAXFORCE 7
CAB-INTERIOR ACCESSORIES	2	BRAKE; GY1R11216 AIR BAG INT.
A/C FILTER	2	BRAKE; HD SHOE KIT 3/8 BEAM
	2	BRAKE; REAR DRUMS 3757X 3647X
	1	DRYER; AD-IP DRIER
	1	VALVE; PURGE VALVE AD-IP-IS
	1	BRAKE; BRK PEDAL PAD
	1	FILTER; CAB FILTER RED DOT
	-1	FILTER; PANEL FILTER
	3	FILTER; PANEL FILTER
	-1	FILTER; 18-2699 A/C FILTER
	1	FILTER; 18-2699 A/C FILTER

Service Requests:

06/12/2016 ENGINE / 18: LEAKING / INSPECT
LOUD HUMMING NOISE COMING FROM PASSENGER SIDE OF ENGINE COMPARTMENT. NO LIGHTS OR NOTIFICATIONS ON DASH. NO PROBLEMS WITH DRIVING THE TRUCK.

Asset Work Order History 10194778

CSHOP-2016-3856

Comments: **B INSPECTION**

Date Opened: 8-8-2016

Date Finished

8-16-2016

Meter 1 Reading:

47,855

TASKS PERFORMED

Q PARTS

PM SERVICE B

30 FLUID; SYN OIL BULK QTS
1 FILTER; OIL FILTER MAXFORCE 7
1 FILTER; FUEL FILTER MAXFORCE 7

CSHOP-2016-4522

Comments: **R41 QUALITY CHECK REPAIRS MADE AT RECHTIEN**

Date Opened: 9-17-2016

Date Finished

9-19-2016

Meter 1 Reading:

47,947

TASKS PERFORMED

Q PARTS

STORAGE CABINET EMERGENCY VEH
WIPERS-WASHER
OIL
DOME LIGHTS
BATTERY
QUALITY CHECK-REPAIRS

3 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
3 BATTERY; BATTERY 950CCA HP-31D

CSHOP-2016-4637

Date Opened: 9-24-2016

Date Finished

9-24-2016

Meter 1 Reading:

48,233

TASKS PERFORMED

Q PARTS

STRETCHER

1 NEWPART; STRIKER BAR/RAIL ASSY

CSHOP-2016-4769

Date Opened: 10-3-2016

Date Finished

10-4-2016

Meter 1 Reading:

48,986

TASKS PERFORMED

NO PARTS USED

TRANSMISSION

CSHOP-2016-5702

Comments: **E41**

Date Opened: 12-7-2016

Date Finished

12-9-2016

Meter 1 Reading:

54,142

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS

Service Requests:

12/07/2016

SERVICE REQUEST / 19: LOOSE / REPAIR

SERVICE REQUEST CHANGE ENGINE OIL LIGHT ON TEMPERATURE LIGHT ON PARTS REGEN AVAILABLE WRENCH
LIGHT ON

Asset Work Order History 10194778

CSHOP-2016-5765

Date Opened: 12-9-2016 Date Finished 12-15-2016 Meter 1 Reading: 54,856

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

12/09/2016 STEERING / 19: LOOSE / REPAIR
POWER STEERING PUMP IS LEAKING. ADDED POWER STEERING FLUID TO FULL MARK.

12/09/2016 ENGINE / 19: LOOSE / REPAIR
ENGINE HAS TO MUCH OIL, ALSO LEAKING OIL

CSHOP-2016-5857

Date Opened: 12-15-2016 Date Finished 12-15-2016 Meter 1 Reading: 54,642

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FILTER; AF27958 FILTER CAB AIR
2 FILTER; FILTER CAB A/C SIDE INTERNAL BOX
1 FILTER; OIL FILTER MAXFORCE 7
1 FILTER; FUEL FILTER MAXFORCE 7

CSHOP-2016-5861

Date Opened: 12-15-2016 Date Finished 3-16-2017 Meter 1 Reading: 56,001

TASKS PERFORMED

Q PARTS

A INSPECTION
STRETCHER
EMISSIONS SYSTEM
COOLING SYSTEM
ENGINE AND ACCESSORIES
GEAR BOX
BODY DAMAGE ACCIDENT

1 NEWPART; MAGNET STRETCHER STRYKER
1 BREATHER; 7085773C92 BREATHER M7
1 FILTER; 2503221C1 FILTER POWER STEERING
-1 GEAR; STEERING GEAR NAV 3554373C91
1 GEAR; STEERING GEAR NAV 3554373C91
3 FLUID; P/S FLUID
1 MEDIC MASTER; RUBBER EXTRUSION
2 CAP; END CAP

CSHOP-2017-1106

Comments: **R41 FUEL LEAKING**

Date Opened: 2-22-2017 Date Finished 2-23-2017 Meter 1 Reading: 55,061

TASKS PERFORMED

NO PARTS USED

FUEL SYSTEM

Asset Work Order History 10194778

CSHOP-2017-1634

Date Opened: 3-16-2017 Date Finished 3-23-2017 Meter 1 Reading: 56,001

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS

Service Requests:

03/15/2017 A/C / 18: LEAKING / REPAIR
A/C ISSUE - FRONT CAB AC NOT BLOWING COLD

03/16/2017 ALARMS / 18: LEAKING / REPAIR
ALARM SIGNALS.. WARNING TRIANGLE LIGHT/ CHECK ENGINE LIGHT

CSHOP-2017-1807

Date Opened: 3-27-2017 Date Finished 5-2-2017 Meter 1 Reading: 61,924

TASKS PERFORMED

Q PARTS

SEAT BELTS

1 2IH; BELT
1 2IH; SEAT BELT, RETRACTOR
1 NONSTOCK; FREIGHT CHARGE

Service Requests:

03/26/2017 SEATS / 18: LEAKING / REPAIR
THE PLASTIC COVER FOR THE SEATBELT MECHANISM IS BROKEN. THE SEATBELT ITSELF APPEARS TO WORK NORMALLY, BUT THE PLASTIC COVER FOR THE FEMALE END IS MISSING.

CSHOP-2017-1883

Date Opened: 3-29-2017 Date Finished 4-20-2017 Meter 1 Reading: 60,437

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

03/29/2017 AIR RIDE / 18: LEAKING / REPAIR
AIR RIDE ISSUE. IT SOUNDS LIKE THERE IS AN AIR LEAK WHEN THE TRUCK IS RUNNING.

CSHOP-2017-1891

Date Opened: 3-30-2017 Date Finished 4-5-2017 Meter 1 Reading: 59,717

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

03/29/2017 TIRES / 18: LEAKING / REPAIR
BAD TIRES. DRIVER'S SIDE FRONT TIRE TREAD APPEARS WORN OUT

Asset Work Order History 10194778

CSHOP-2017-2113

Date Opened: 4-11-2017 Date Finished 4-20-2017 Meter 1 Reading: 60,437

TASKS PERFORMED

Q PARTS

REPAIR FROM PM - AIR INTAKE SYS	1	2IH; 2IH
FRONT TIRES	1	2IH; COMPRESSOR
A/C HOSES/FITTINGS	3	9XX; 134A 10194654

CSHOP-2017-2196

Comments: **ENGINE REPAIRED UNDER WARRANTY STEERING CUSTOMER PAY INVOICE SCANNED TO SERVICE REQUEST**

Date Opened: 4-15-2017 Date Finished 4-15-2017 Meter 1 Reading: 54,963

TASKS PERFORMED

NO PARTS USED

STEERING

VENDOR? RECHTIEN INTERNATIONAL TRUCKS

Service Requests:

04/15/2017 ENGINE / 44: WORN / REPAIR

CSHOP-2017-2271

Date Opened: 4-18-2017 Date Finished 5-5-2017 Meter 1 Reading: 62,158

TASKS PERFORMED

Q PARTS

WIPER BLADES	2	1AN; WIPERS
COOLING SYSTEM		
INSTRUMENTS-GAUGES-METERS		
HVAC SYSTEM		

Service Requests:

04/18/2017 SEATS / 18: LEAKING / REPAIR
SEAT ISSUE THE BACK REAR RIGHT SEAT IN THE CAB IS MISSING A SEATBELT

04/18/2017 A/C / 18: LEAKING / REPAIR
A/C ISSUE REAR AC IN THE CAB IS NOT WORKING

CSHOP-2017-2509

Date Opened: 4-28-2017 Date Finished 5-3-2017 Meter 1 Reading: 62,022

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS

Service Requests:

04/28/2017 OIL / 18: LEAKING / REPAIR
CHANGE ENGINE OIL LIGHT IS ON

Asset Work Order History 10194778

CSHOP-2017-2654

Date Opened: 5-5-2017

Date Finished

5-8-2017

Meter 1 Reading:

62,419

TASKS PERFORMED

NO PARTS USED

CAB-INTERIOR ACCESSORIES

Service Requests:

05/04/2017

BODY / 18: LEAKING / REPAIR

THE RUBBER TUNNEL BETWEEN THE CAB AND THE PATIENT COMPARTMENT OF R41 LEAKS A LOT WHEN IT RAINS.
THE RUBBER TUNNEL NEEDS TO BE RESEALED / REPAIRED. THANK YOU.

CSHOP-2017-2754

Comments: **REPAIRS FROM PM**

Date Opened: 5-10-2017

Date Finished

6-2-2017

Meter 1 Reading:

63,106

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS

1

9AP; DOOR #11 GLASS

FUEL SYSTEM

1

2TP; RED DOT A/C FILTER

OIL FILTER

1

2IH; LIGHT, DOME

REPAIR FROM PM - PATIENT COMPT

4

MAC; NON-CHLOR BRAKE CLNR

LIGHTING SYSTEM

2

MBI; GRIP/KIT

REAR TIRES

2

TWD; BRAKE DRUM

REPAIR FROM PM - BELTS

1

2IH; DRAG LINK

REPAIR FROM PM - TRANSMISSION

REPAIR FROM PM - BRAKES

GLASS

REPAIR FROM PM - STEERING

BODY EXTERIOR

SEAT FRONT

INSTRUMENTS-GAUGES-METERS

CABIN AIR FILTER

HVAC SYSTEM

Service Requests:

05/10/2017

LIGHTS / 12: BROKEN / REPAIR

THE PLASTIC BRACKET FOR THE PASSENGER SIDE B-POST LIGHTHEAD (RUNNING BOARD ON PASSENGER SIDE OF CAB) IS CRACKED AND NEEDS TO BE REPLACED. WHELEN TIR6 LIGHTHEAD FLANGE. ONLY THE BRACKET NEEDS TO BE REPLACED (THE LIGHTHEAD ITSELF WORKS), BECAUSE THE LIGHTHEAD IS ONLY HOLDING ON BY 1 SCREW

Asset Work Order History 10194778

CSHOP-2017-2775

Date Opened: 5-11-2017

Date Finished

5-30-2017

Meter 1 Reading:

63,106

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1 FIL; NAPA GOLD FUEL FILTER
2 1AN; WIPERS
-1 2IH; BELT
1 2IH; BELT
15 9OC; BULK TRANS SYN
1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPA TRANS FILTER
22 9OC; SYN 15W40
1 NBH; SERPENTINE BELT
1 2IH; BELT
2 8GR; FILTER
1 FIL; POWER STEERING FILTER

Service Requests:

05/10/2017

SERVICE REQUEST / 20: LUBE/OIL SOAKED / LUBRICATE

OIL CHANGE NEEDED. CHECK ENGINE LIGHT ON INDICATING THAT VEHICLE IS DUE FOR AN OIL CHANGE.

CSHOP-2017-3339

Comments: **CK TRANSMISSION SHIFTING**

Date Opened: 6-6-2017

Date Finished

6-8-2017

Meter 1 Reading:

63,237

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
ALTERNATOR-GENERATOR
TCU - PCM
U-BOLTS
AIR SYSTEM

1 1AD; ALTERNATOR, 320A

Asset Work Order History 10194778

CSHOP-2017-3505

Date Opened: 6-13-2017

Date Finished

7-10-2017

Meter 1 Reading:

63,273

TASKS PERFORMED

Q PARTS

FUEL SYSTEM
SERPENTINE BELT
BATTERY
ELECTRICAL
AIR SYSTEM

1 2AW; T RING, ASSETWORKS
1 2AW; VIB, ASSETWORKS
1 2IH; BELT TENSIONER V8
1 NBH; SERPENTINE BELT
1 BRG; ALTERNATOR BEARING
1 NBH; V-RIBBED BELT
2 NBH; IDLER PULLEY
1 9IP; BEARING PULLEY
1 NBH; TENSIONER-HEAVY DUTY
-1 NBH; PULLEY
1 NBH; PULLEY
3 1AD; BATTERY 31 SERIES
1 2IH; BODY CONTROL MODUAL
-1 2IH; ECM CONTROL MODULE
1 2IH; ECM CONTROL MODULE
3 9HY; 9HY
1 9HY; 9HY

CSHOP-2017-3993

Date Opened: 7-6-2017

Date Finished

7-6-2017

Meter 1 Reading:

63,237

TASKS PERFORMED

NO PARTS USED

CRANKING SYSTEM

CSHOP-2017-4693

Comments: **BODY WORK COMPLETED FROM SIDE DAMAGE TO PAT BOX**

Date Opened: 8-12-2017

Date Finished

12-3-2017

Meter 1 Reading:

68,090

TASKS PERFORMED

NO PARTS USED

BODY DAMAGE ACCIDENT

VENDOR? SOUTHEAST TRUCK

CSHOP-2017-4694

Comments: **FINAL QUALITY CHECK UNIT WAS SERVICED THEN BODY WORK COMPLETED TO RIGHT REAR OF PAT BOX**

Date Opened: 8-12-2017

Date Finished

8-15-2017

Meter 1 Reading:

63,334

TASKS PERFORMED

NO PARTS USED

QUALITY CHECK-REPAIRS
LIGHTING SYSTEM
HVAC SYSTEM

Asset Work Order History 10194778

CSHOP-2017-4839

Date Opened: 8-18-2017 Date Finished 8-22-2017 Meter 1 Reading: 63,536

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
EQUIPMENT MOUNTING BRACKETS
BATTERY

CSHOP-2017-4980

Date Opened: 8-24-2017 Date Finished 8-30-2017 Meter 1 Reading: 63,787

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

- 08/24/2017 ENGINE / 21: MISADJUSTED / REPAIR
ENGINE TRUCK NOT GOING INTO TRUCK REGEN MODE. ITS IN PARK AND YOU HIT THE BUTTON BUT IT DOESN'T HIGH IDEAL
 - 08/30/2017 MUFFLER / 21: MISADJUSTED / INSPECT
MUFFLER BAD- WONT GO INTO REGEN
 - 08/30/2017 BRAKES / 49: CAN NOT DUPLICATE CONCERN / INSPECT
BRAKE ISSUES. AIR PRESSURE ON R273 TAKES ABOUT A MINUTE TO BUILD ENOUGH PRESSURE TO MOVE.
-

CSHOP-2017-5127

Date Opened: 8-31-2017 Date Finished 10-26-2017 Meter 1 Reading: 66,672

TASKS PERFORMED

Q PARTS

AIR SYSTEM
BLOWER MOTOR

1	2IH; VALVE HIGH-CAB
1	TEM; BLOWER MOTOR

Service Requests:

- 08/31/2017 AIR RIDE / 18: LEAKING / INSPECT
AIR RIDE ISSUE. R273 TAKES ABOUT A MINUTE TO BUILD ENOUGH AIR PRESSURE TO MOVE VEHICLE.
-

CSHOP-2017-5196

Date Opened: 9-5-2017 Date Finished 9-15-2017 Meter 1 Reading: 64,489

TASKS PERFORMED

NO PARTS USED

DOOR HANDLES INSIDE-OUTSIDE

Service Requests:

- 09/04/2017 DOOR / 12: BROKEN / REPAIR
REAR DOOR HANDLE TO GET INTO PATIENT COMPARTMENT IS NOT OPENING CORRECTLY. HANDLE IS GETTING STUCK AND NOT LETTING THE DOOR OPEN CORRECTLY. SEEMS LIKE THE ASSEMBLY IS LOOSE.
-

Asset Work Order History 10194778

CSHOP-2017-5597

Date Opened: 9-26-2017 Date Finished 10-1-2017 Meter 1 Reading: 65,446

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR HORN
DOOR ALARM OR OTHER WARNING

Service Requests:

09/26/2017 ALARMS / 12: BROKEN / EXCHANGE - NEW
ALARM SIGNALS. AIR HORN NOT FUNCTION PROPERLY.

CSHOP-2017-5638

Date Opened: 9-28-2017 Date Finished 10-13-2017 Meter 1 Reading: 65,867

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

Service Requests:

09/28/2017 WINDOW / 18: LEAKING / REPAIR
HEAVY WATER LEAK IN GASKET THAT DIVIDES CAB AND PATIENT COMPARTMENT WHEN RAINING

CSHOP-2017-6166

Date Opened: 10-26-2017 Date Finished 11-6-2017 Meter 1 Reading: 67,152

TASKS PERFORMED

Q PARTS

DPFE SENSOR	1	2IH; DPF PRESSURE SENSOR
EXHAUST SYSTEM	1	2IH; DPF NEW 4 DOOR
	1	2IH; DPF GASKET
	1	2IH; DPF GASKET

CSHOP-2017-6896

Date Opened: 12-3-2017 Date Finished 12-8-2017 Meter 1 Reading: 68,286

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BRAKE LIGHTS

Service Requests:

12/01/2017 ALARMS / 12: BROKEN / REPAIR
ALARM SIGNALS REAR BRAKE FLASHERS NOT WORKING

Asset Work Order History 10194778

CSHOP-2017-7364

Date Opened: 12-27-2017 Date Finished 3-19-2018 Meter 1 Reading: 71,992

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
BELT

1 ECH; RELAY
-1 ECH; RELAY
1 ECH; RELAY
2 5TN; LIGHT, MINI BROW 9" LNG
2 5TN; MNT, BLACK
1 BK; FUSE HOLDER
-1 BK; FUSE HOLDER
1 BK; FUSE HOLDER

Service Requests:

12/25/2017 ALARMS / 23: NOT CONNECTED / EXCHANGE - NEW
ALARM SIGNALS. REQUEST FOR LED FOG LIGHTS DUE TO HEAVY FOG, WHICH STANDARD LIGHTS ARE NOT ADEQUATE.

12/25/2017 ENGINE / 19: LOOSE / ADJUST
ENGINE. LOUD BELT SQUEAL WHILE ACCELERATING.

CSHOP-2017-7385

Date Opened: 12-28-2017 Date Finished 1-19-2018 Meter 1 Reading: 69,851

TASKS PERFORMED

NO PARTS USED

DOOR PROP CYLINDER

Service Requests:

12/28/2017 BODY / 12: BROKEN / INSPECT
BODY ISSUE- DOOR HOLDER IN BACK OF THE RESCUE STRIPPED AND NEEDS TO BE RE ATTACHED

CSHOP-2017-855

Comments: **REAR CAB A/C VENTS BROKEN**

Date Opened: 2-10-2017 Date Finished 4-12-2017 Meter 1 Reading: 60,340

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

3 2TP; LOUVER

CSHOP-2018-15

Date Opened: 1-2-2018 Date Finished 5-8-2018 Meter 1 Reading: 74,121

TASKS PERFORMED

NO PARTS USED

FAULT CODE

Service Requests:

01/01/2018 ENGINE / 18: LEAKING / REPAIR
ENGINE, IN THE FRONT AND REAR CAB THERE IS A LARGE AMOUNT OF EXHAUST FUMES.

01/01/2018 ENGINE / 17: INSUFFICIENT LUBRICANT / EXCHANGE - NEW
ENGINE, CHANGE (ENGINE OIL) LIGHT IS ON.

Asset Work Order History 10194778

CSHOP-2018-2117

Comments: **BROKE DOWN**

Date Opened: 4-16-2018

Date Finished

4-17-2018

Meter 1 Reading:

72,865

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
EMISSIONS SYSTEM

CSHOP-2018-2133

Date Opened: 4-17-2018

Date Finished

4-24-2018

Meter 1 Reading:

73,482

TASKS PERFORMED

Q PARTS

FUEL SYSTEM
OIL FILTER
REPAIR FROM PM - AIR INTAKE SYS
FAULT CODE

1	FIL; NAPA GOLD FUEL FILTER
22	4PC; 15W40 PREMIUM BLUE OIL
1	FIL; NAPAGOLD OIL FILTER
2	2IH; CLAMP, AIR
1	2IH; HOSE , FLEX
1	2IH; HOSE , FLEX
2	2IH; CLAMP

CSHOP-2018-2272

Date Opened: 4-25-2018

Date Finished

5-15-2018

Meter 1 Reading:

74,121

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES
LIGHTING SYSTEM
DRIVE BELT

1	2IH; HOSE , FLEX
1	2IH; HOSE , FLEX
1	2IH; MAN INT SENSOR
1	9IP; MOUNT 500 TIR SER CHROME
1	9IP; ULTRA VIOLET LIGHT SHORT
2	BRG; ALTERNATOR BEARING
3	NBH; IDLER PULLEY

CSHOP-2018-2303

Comments: **C INSPECTION USE FORM OIL AND FILTERS WERE REPLACE ON PREVIOUS REPAIR**

Date Opened: 4-26-2018

Date Finished

4-27-2018

Meter 1 Reading:

74,121

TASKS PERFORMED

NO PARTS USED

PM SERVICE C RESCUE

CSHOP-2018-2450

Date Opened: 5-3-2018

Date Finished

5-3-2018

Meter 1 Reading:

74,121

TASKS PERFORMED

NO PARTS USED

DPFE SENSOR

Asset Work Order History 10194778

CSHOP-2018-2669

Date Opened: 5-15-2018 Date Finished 5-17-2018 Meter 1 Reading: 74,898

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FAULT CODE

Service Requests:

05/15/2018 SERVICE REQUEST / 33: REGISTERS WRONG / INSPECT
R273: CHECK ENGINE LIGHT ON DASH. NO SYMPTOMS

CSHOP-2018-2934

Date Opened: 5-29-2018 Date Finished 5-31-2018 Meter 1 Reading: 75,391

TASKS PERFORMED

NO PARTS USED

THERMOSTAT
REPAIR FROM PM - AIR INTAKE SYS

Service Requests:

05/26/2018 ENGINE / 11: BINDS/STICKS / ADJUST
CHECK ENGINE LIGHT ON

CSHOP-2018-3378

Date Opened: 6-15-2018 Date Finished 6-19-2018 Meter 1 Reading: 75,482

TASKS PERFORMED

Q PARTS

REPAIRS BY RECHTIEN
QUALITY CHECK-REPAIRS

1 4AH; 12INCHSLIDES
1 2IH; AIR FILTER-CAN ORDER-500804
2 8GR; FILTER
1 MMM; WTHRSTRPADHBLK5OZ

VENDOR? RECHTIEN INTERNATIONAL TRUCKS

CSHOP-2018-3640

Date Opened: 6-28-2018 Date Finished 6-28-2018 Meter 1 Reading: 75,830

TASKS PERFORMED

NO PARTS USED

DOOR

Service Requests:

06/28/2018 DOOR / 49: CAN NOT DUPLICATE CONCERN / INSPECT
VEHICLE DOORS- DRIVER SIDE COMPARTMENT DOOR (EXTINGUISHER COMPARTMENT LEFT DOOR) MECHANISM IS
BROKEN.

Asset Work Order History 10194778

CSHOP-2018-3690

Date Opened: 7-2-2018

Date Finished

7-5-2018

Meter 1 Reading:

76,015

TASKS PERFORMED

NO PARTS USED

FAULT CODE

Service Requests:

07/02/2018

ENGINE / 20: LUBE/OIL SOAKED / REPAIR

CHECK ENGINE LIGHT ON WITH UPSIDE DOWN TRIANGLE AND WRENCH SYMBOL

CSHOP-2018-4006

Date Opened: 7-16-2018

Date Finished

7-20-2018

Meter 1 Reading:

76,777

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

Service Requests:

07/14/2018

A/C / 18: LEAKING / REPAIR

A/C ISSUE. AC LEAKING IN THE CAB.

CSHOP-2018-4191

Comments: **R73 A/C INOP**

Date Opened: 7-26-2018

Date Finished

7-27-2018

Meter 1 Reading:

77,120

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

Service Requests:

07/26/2018

A/C / 48: LOW PRESSURE / ADJUST

A/C ISSUE

Asset Work Order History 10194778

CSHOP-2018-4304

Date Opened: 8-1-2018

Date Finished

8-2-2018

Meter 1 Reading:

77,327

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BODY - WORK COMPARTMENT EMER
OXYGEN SENSOR
DASH PAD

Service Requests:

07/31/2018 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
NOISE COMING OFF DASHBOARD IN THE PASSENGER'S SIDE.

07/31/2018 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
O2 PORT DOES NOT WORK WHEN O2 TREE IS PLUGGED IN ON SIDE OF ACTION AREA.

07/31/2018 SERVICE REQUEST / 21: MISADJUSTED / ADJUST
TOP SUPPLY DRAWER NOT OPENING TO ACCESS EMS SUPPLIES

CSHOP-2018-44

Date Opened: 1-2-2018

Date Finished

1-3-2018

Meter 1 Reading:

69,459

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; NAPA GOLD FUEL FILTER
1 FIL; NAPAGOLD OIL FILTER
22 FLUID; SYN OIL BULK QTS
-22 90C; SYN 15W40
22 90C; SYN 15W40

CSHOP-2018-4517

Date Opened: 8-13-2018

Date Finished

8-20-2018

Meter 1 Reading:

77,898

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

08/13/2018 TIRES / 18: LEAKING / REPAIR
BAD TIRES. DRIVER OUTSIDE REAR TIRE HAS A CUT IN THE TREAD.

CSHOP-2018-4953

Date Opened: 8-31-2018

Date Finished

8-31-2018

Meter 1 Reading:

78,319

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FAULT CODE

Service Requests:

08/30/2018 ENGINE / 15: FOREIGN MATERIAL / INSPECT
CHECK ENGINE LIGHT IS ON

Asset Work Order History 10194778

CSHOP-2018-5038

Date Opened: 9-5-2018

Date Finished

9-6-2018

Meter 1 Reading:

78,633

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
STRETCHER

Service Requests:

09/05/2018

SERVICE REQUEST / 23: NOT CONNECTED / INSPECT

R273'S STRETCHER HAS A POWER SUPPLY ISSUE. IT DOES NOT GET ANY POWER FROM THE BATTERY.

CSHOP-2018-6030

Date Opened: 10-23-2018

Date Finished

10-26-2018

Meter 1 Reading:

80,349

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; NAPA TRANS FILTER
1 FIL; NAPA GOLD FUEL FILTER
1 FIL; NAPAGOLD OIL FILTER
22 4PC; 15W40 PREMIUM BLUE OIL

CSHOP-2018-6038

Date Opened: 10-24-2018

Date Finished

10-26-2018

Meter 1 Reading:

80,349

TASKS PERFORMED

Q PARTS

WIPERS-WASHER

REPAIR FROM PM - PATIENT COMPT

REPAIR FROM PM - COOLING SYSTEM

REPAIR FROM PM - DIFFERENTIALS

REPAIR FROM PM - ENGINE

REPAIR FROM PM - CAB

REPAIR FROM PM - A/C

5 5EF; BELLOWS GASKET FT
1 BK; PTEX ULTRA BLACK 30Z
1 BK; RADIATOR CAP
1 2IH; THERMOSTAT KIT
15 4PC; GEAR OIL-SYN BULK (DELO)
2 1AN; 22" WIPER BLADE
2 BK; HI-AMP FLUSH MOUNT
2 2IH; FILTER, CAB A/C INT BX, BLUE

Asset Work Order History 10194778

CSHOP-2018-63

Comments: **PM FOLLOW UPS ATTACHED**

Date Opened: 1-3-2018

Date Finished

1-11-2018

Meter 1 Reading:

69,527

TASKS PERFORMED

Q PARTS

REAR DOOR SEAL
WIPERS-WASHER
EXHAUST SYSTEM
REPAIR FROM PM - O2 SYSTEM
REPAIR FROM PM - AIR INTAKE SYS
AIR DRIER
AIR SYSTEM
DOOR LOCKS ELECTRIC
CABIN AIR FILTER

1 CRC; CLEAN-R-CARB 200Z
1 MBI; PURG/VLV
1 TWD; REP/CART
2 1AN; 22" WIPER BLADE
1 SVP; DPF GSKT (2601233C1)
1 2IH; CLAMP EXHUAST
1 SVP; DPF GSKT (2593986C1)
3 9ME; ZICO RATCHET STRAPS
1 5EF; DOOR GRABBER CHROME
5 5EF; BELLOWS GASKET FT
1 2IH; VALVE HIGH-CAB
2 8GR; FILTER
2 2IH; FILTER, CAB A/C INT BX, BLUE
1 FIL; NAPA CABIN AIR FILTER

CSHOP-2018-6406

Date Opened: 11-10-2018

Date Finished

11-10-2018

Meter 1 Reading:

81,003

TASKS PERFORMED

NO PARTS USED

FRONT TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10194778

CSHOP-2018-6775

Date Opened: 11-30-2018 Date Finished 12-27-2018 Meter 1 Reading: 82,010

TASKS PERFORMED

	Q	PARTS
WIPER BLADES	1	NCB; SUPER K WASH CONCNTRT
OXYGEN SENSOR	2	1AN; 22" WIPER BLADE
COOLING SYSTEM	1	9AP; O2 GAUGE, 0-3000PSI
ENGINE AND ACCESSORIES	5	2IH; SPACER
REPAIR FROM PM - O2 SYSTEM	4	2IH; STUD
SPOT LIGHTS	5	2IH; BOLT
LIGHTING SYSTEM	4	LMP; BULB
REPAIR FROM PM - POWER STEERING	1	FIL; POWER STEERING FILTER
REPAIR FROM PM - 110 A/C	1	2IH; POWER STEERING FLUID 32OZ
BATTERY	1	2IH; POWER STEERING FLUID 32OZ
SWITCH-ELECTRICAL	1	9AP; SORBENT PAD
DIAGNOSE ELECTRICAL	1	2TK; UNIV INSIDE
MOUNT	3	1AD; BATTERY 31 SERIES
POWER BOOSTER-HYDRO BOOST	1	NSE; DISPGLV
AIR SYSTEM	1	BK; ATC FUSEHOLDER-CARD
FAULT CODE	1	TWD; E8PVALVE BRAKE
STROBE LIGHTS	1	2IH; KIT HORN
STEPS	2	2IH; KIT
FENDER	1	2IH; VALVE CHECK
DOOR PANEL	1	2IH; MAN INT SENSOR
CAB-INTERIOR ACCESSORIES	1	1WL; LIGHT LED RED TIR6
HEATING AND VENTILATION	4	5EF; BELLOWS GASKET FT
A/C FILTER	1	5SC; LOUVER LARGE
HVAC SYSTEM	1	2TK; BRISK 2

Service Requests:

- 11/29/2018 ALARMS / 49: CAN NOT DUPLICATE COMPLAIN / SPOT LIGHT WORKING
ALARM SIGNALS SPOT LIGHT NOT WORKING
- 11/29/2018 SERVICE REQUEST / 48: LOW PRESSURE / MANUAL RESET
TYPE PROBLEM INTO DESCRIPTION 02 ALARM CONTINUES TO SOUND.

CSHOP-2018-6808

Date Opened: 12-2-2018 Date Finished 12-3-2018 Meter 1 Reading: 81,970

TASKS PERFORMED

	Q	PARTS
TRAVEL TO BE CHARGED TO WORK ORDER SIREN	2	5EF; SPEAKER DRIVER

CSHOP-2018-6865

Date Opened: 12-3-2018 Date Finished 12-6-2018 Meter 1 Reading: 82,010

TASKS PERFORMED

	Q	PARTS
PM SERVICE C RESCUE	1	FIL; NAPA GOLD FUEL FILTER
	22	4PC; 15W40 PREMIUM BLUE OIL
	1	FIL; NAPA CABIN AIR FILTER
	1	FIL; NAPAGOLD OIL FILTER
	1	2IH; AIR FILTER-CAN ORDER-500804

Asset Work Order History 10194778

CSHOP-2019-1081

Date Opened: 2-27-2019 Date Finished 3-13-2019 Meter 1 Reading: 85,917

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM
FAULT CODE
CAB-INTERIOR ACCESSORIES

2 9IP; 5FLANGEC FLANGE CHROME

Service Requests:

02/26/2019 BODY / 12: BROKEN / EXCHANGE - NEW
BODY ISSUE, OFFICER SIDE STEP LIGHT BENEATH DOOR IS DETACHING FROM FRAME OF RESCUE.

03/03/2019 ENGINE / 49: CAN NOT DUPLICATE CONCERN / INSPECT
ENGINE CHECK ENGINE LIGHT ON WITHOUT DESCRIPTION OF THE ISSUE. RESCUE IS OPERATING NORMALLY.

CSHOP-2019-1272

Date Opened: 3-10-2019 Date Finished 3-11-2019 Meter 1 Reading: 85,397

TASKS PERFORMED

Q PARTS

FAULT CODE

4 2IH; 50/50 COOLANT, FLEETGUARD

CSHOP-2019-1328

Date Opened: 3-12-2019 Date Finished 3-13-2019 Meter 1 Reading: 85,917

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

03/11/2019 A/C / 43: WEAK / ADJUST
A/C ISSUE ALSO CAB TO PATIENT COMPARTMENT WINDOW SEAL IS BROKEN

CSHOP-2019-1548

Date Opened: 3-25-2019 Date Finished 4-1-2019 Meter 1 Reading: 85,967

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
EGR VALVE
TURBOCHARGER
ENGINE AND ACCESSORIES
FAULT CODE

1 BK; PTEX ANAEROBIC GASKT
1 2IH; EGR VALVE
1 2IH; TURBO KIT
1 2IH; TURBO MOUNTING KIT
1 2IH; TURBO KIT
1 NCB; HI-TACKSTICK

Service Requests:

03/24/2019 ENGINE / 18: LEAKING / REPLACED LEAKING TURBOS` AND CLOGGED EGR VALVE TESTED FOU
ENGINE CHECK ENGINE LIGHT ON. TRUCK STALLED ONCE THIS MORNING AT A TRAFFIC LIGHT STOP DURING A
TRANSPORT, BUT WAS ABLE TO RESTART ENGINE.

Asset Work Order History 10194778

CSHOP-2019-1675

Date Opened: 4-1-2019

Date Finished

4-11-2019

Meter 1 Reading:

85,967

TASKS PERFORMED

Q PARTS

PM SERVICE B

2 2IH; FILTER, CAB A/C INT BX, BLUE
1 FIL; NAPAGOLD OIL FILTER
1 2IH; AIR FILTER-CAN ORDER-500804
26 4PC; 15W40 PREMIUM BLUE OIL
1 FIL; NAPA CABIN AIR FILTER
1 2RD; FILTER, 6.45X7.75 BLK FOAM
2 1AN; 22" WIPER BLADE
1 9AP; OIL SAMPLE TEST KIT (PETRO-CANADA)
2 8GR; FILTER

CSHOP-2019-1697

Date Opened: 4-2-2019

Date Finished

4-11-2019

Meter 1 Reading:

85,967

TASKS PERFORMED

Q PARTS

TURBOCHARGER
REPAIR FROM PM - REAR SUSPENSION
HVAC SYSTEM

1 2IH; DUCT ASSY
1 2IH; CLAMP
2 2IH; SPRING AIR
1 9AP; AC REAR UNIT

CSHOP-2019-2357

Date Opened: 5-3-2019

Date Finished

5-6-2019

Meter 1 Reading:

85,967

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
REAR DOOR SEAL
LIGHTING SYSTEM
HVAC SYSTEM

1 9OC; R134 30LB

CSHOP-2019-2649

Comments: **PARTS ONLY**

Date Opened: 5-22-2019

Date Finished

6-3-2019

Meter 1 Reading:

86,971

TASKS PERFORMED

Q PARTS

BODY EXTERIOR

1 9PB; LARGE PLACARD HOLDER
1 9PB; SMALL PLACARD HOLDER

CSHOP-2019-2684

Date Opened: 5-25-2019

Date Finished

5-28-2019

Meter 1 Reading:

86,819

BRACKET FALLING OFF

TASKS PERFORMED

NO PARTS USED

BODY EXTERIOR

Asset Work Order History 10194778

CSHOP-2019-2723

Date Opened: 5-28-2019 Date Finished 6-6-2019 Meter 1 Reading: 87,068

TASKS PERFORMED

NO PARTS USED

HANDLIGHT

Service Requests:

05/24/2019 ELECTRICAL / 12: BROKEN / EXCHANGE - REBUILT
THE CHARGING STATION IN RESCUE 73 IS NOT CHARGING THE BOX LIGHTS

CSHOP-2019-3137

Date Opened: 6-18-2019 Date Finished 6-18-2019 Meter 1 Reading: 87,512

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

CSHOP-2019-3272

Date Opened: 6-24-2019 Date Finished 6-28-2019 Meter 1 Reading: 87,832

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FAULT CODE
HVAC SYSTEM

Service Requests:

06/22/2019 A/C / 49: CAN NOT DUPLICATE CONCERN / INSPECT
A/C ISSUE DRIVER COMPARTMENT AC NOT COOLING PROPERLY. CHECK ENGINE LIGHT ON.

CSHOP-2019-3509

Date Opened: 7-6-2019 Date Finished 7-25-2019 Meter 1 Reading: 88,745

TASKS PERFORMED

Q PARTS

BRAKES

1 TWD; PURGE VALVE ASSY KIT

CSHOP-2019-3756

Date Opened: 7-19-2019 Date Finished 7-25-2019 Meter 1 Reading: 88,745

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
EQUIPMENT MOUNTING BRACKETS

Service Requests:

07/19/2019 SERVICE REQUEST / 23: NOT CONNECTED / EXCHANGE - NEW
NEW PORTABLE SUCTION NEEDS INSTALLED IN R273.

Asset Work Order History 10194778

CSHOP-2019-3926

Date Opened: 7-29-2019

Date Finished

8-1-2019

Meter 1 Reading:

88,970

TASKS PERFORMED

NO PARTS USED

FAULT CODE

Service Requests:

07/27/2019 ENGINE / 44: WORN / INSPECT
ENGINE LIGHT IS ON

CSHOP-2019-4149

Date Opened: 8-7-2019

Date Finished

10-3-2019

Meter 1 Reading:

91,273

TASKS PERFORMED

Q PARTS

FAULT CODE

HEADLIGHTS HIGH BEAM

LIGHTING SYSTEM

AUTO-EJECT

STEERING

1 NAF; BLUEDEF25GAL
1 2IH; STEERINGSHAFT

Service Requests:

08/06/2019 SERVICE REQUEST / 12: BROKEN / DIAGNOSTIC TEST
CHECK ENGINE LIGHT ON

08/07/2019 BODY / 12: BROKEN / EXCHANGE - NEW
BODY ISSUE - AUTO EJECT BATTERY LID COVER FOR E55 IS BROKEN. DRIVERS SIDE.

08/07/2019 ENGINE / 15: FOREIGN MATERIAL / REPAIR
CHECK ENGINE LIGHT IS ON R273

08/07/2019 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
HIGHT BEAM LIGHTS TURN ON ANYTIME YOU HIT A BUMP IN THE ROAD.

08/07/2019 STEERING / 12: BROKEN / REPLACED WITH NEW
STEERING ON 273 FEELS STIFF. ON OCCASIONS IT TAKES PHYSICAL FORCE TO TURN THE STEERING WHEEL AND OTHER TIMES THE STEERING WHEEL MOVES FINE.

CSHOP-2019-4253

Date Opened: 8-13-2019

Date Finished

8-13-2019

Meter 1 Reading:

85,988

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

VENDOR? RECHTIEN INTERNATIONAL TRUCKS

Asset Work Order History 10194778

CSHOP-2019-4413

Comments: **PM REPAIRS**

Date Opened: 8-20-2019

Date Finished

11-27-2019

Meter 1 Reading:

92,736

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	1	2IH; LAMP
WIPER BLADES	1	2IH; LIGHT, TURN SIGNAL
FAULT CODE	-1	2IH; LIGHT, TURN SIGNAL
HEADLIGHTS HIGH BEAM	2	1AN; WIPERS
HEADLIGHTS LOW BEAM	2	2IH; RETAINER NUT HL BULB
INDICATOR LIGHT	1	9ES; BULB LED SUPER BRIGHT
UNIVERSAL JOINT	1	2IH; STRAPKIT
REAR BRAKE PADS-SHOES	1	2IH; U JOINT
FRONT BRAKE PADS-SHOES	2	2GU; DRUM GUNITE
REPAIR FROM PM - DECALS/CLEANLINESS	2	MBI; GRIP KIT
AIR DRIER	2	TWD; BRAKE SHOE KITS NEW
CAB-INTERIOR ACCESSORIES	2	9IP; BRAKE DRUM 85 123382002
A/C FILTER	1	9PB; LARGE PLACARD
	1	9PB; SMALL PLACARD
	1	TWD; PURGE VALVE ASSY KIT
	1	TWD; REP CART
	-1	1CH; BRAKE CLEANER MOPAR
	12	1CH; BRAKE CLEANER MOPAR
	1	1CH; BRAKE CLEANER MOPAR
	1	PTX; PERMATEX
	1	2IH; DOORSEALREAR
	4	5HA; BELLOWS GASKET FT
	1	2IH; SEAL
	4	9IP; BEZEL AC
	2	9HD; FILTER CABIN 7 75X14 5

CSHOP-2019-4875

Date Opened: 9-16-2019

Date Finished

9-24-2019

Meter 1 Reading:

91,052

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

09/14/2019

A/C / 18: LEAKING / ADJUST

A/C ISSUE. THE FRONT CREW COMPARTMENT AC BLOWS COOL BUT NO COLD AS NORMAL. REAR PT AC COMPARTMENT HAS NO PROBLEMS

Asset Work Order History 10194778

CSHOP-2019-4907

Date Opened: 9-17-2019

Date Finished

11-1-2019

Meter 1 Reading:

92,563

TASKS PERFORMED

Q PARTS

AIR SYSTEM
HVAC SYSTEM

1 TWD; BENDIX D 2 GOV
1 2IH; HOSE OIL FEED COMPRESSOR
-1 2IH; HOSE OIL FEED COMPRESSOR
1 2IH; HOSE OIL FEED COMPRESSOR
1 2IH; AIR COMPRESSOR
-1 2IH; AIR COMPRESSOR
1 2IH; AIR COMPRESSOR
1 2IH; HOSE RETURN
-1 2IH; HOSE RETURN
1 2IH; HOSE RETURN
1 2IH; VALVE A C
1 2IH; FILTER/DRIER
3 9XX; AC FREON 10174676
3 9XX; AC FREON 10174676

Service Requests:

09/16/2019 A/C / 18: LEAKING / REPAIR
RESCUE 273 CAB AC BLOWING HOT AIR

CSHOP-2019-5022

Date Opened: 9-23-2019

Date Finished

10-3-2019

Meter 1 Reading:

91,273

TASKS PERFORMED

NO PARTS USED

FAULT CODE
HVAC SYSTEM

Service Requests:

09/20/2019 SERVICE REQUEST / 15: FOREIGN MATERIAL / REPAIR
CHECK ENGINE LIGHT ON *TRANS OIL FILTER* SHOWING ON DISPLAY

09/20/2019 A/C / 49: CAN NOT DUPLICATE CONCERN / INSPECT
A/C ISSUE DRIVER CAB AC WORKING INTERMITTENTLY

CSHOP-2019-5047

Date Opened: 9-25-2019

Date Finished

10-3-2019

Meter 1 Reading:

91,273

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR HINGE-PINS-BUSHINGS

Service Requests:

09/25/2019 BODY / 10: BENT / REPAIR
DRIVERS GEAR STORAGE COMPARTMENT DOOR HAS A WARPED HINGE THAT SHIFTED THE DOOR SLIGHTLY TO WHERE IT CATCHES ON THE LATCH AND PIN WHEN YOU OPEN IT. DOOR FRAME IS FREE OF ANY VISIBLE DAMAGE, ONLY HINGE AREA SEEMS TO BE AFFECTED.

Asset Work Order History 10194778

CSHOP-2019-5048

Date Opened: 9-25-2019 Date Finished 10-24-2019 Meter 1 Reading: 92,074

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

Service Requests:

09/25/2019 LIGHTS / 49: CAN NOT DUPLICATE CONCERN / INSPECT
VEHICLE UNDER CARRIAGE LIGHTS NOT WORKING.

CSHOP-2019-515

Date Opened: 1-27-2019 Date Finished 1-27-2019 Meter 1 Reading: 83,361

TASKS PERFORMED

NO PARTS USED

VEHICLE RECOVERY OPERATION

CSHOP-2019-5537

Date Opened: 10-21-2019 Date Finished 11-1-2019 Meter 1 Reading: 92,653

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 LIT; GROMMET
1 5G; LED LIGHT

Service Requests:

10/19/2019 LIGHTS / 12: BROKEN / EXCHANGE - NEW
THE REAR LOADING GROUND LIGHT FELL OUT. IT WAS DISCONNECTED AND PLACED IN THE DRIVERS DOOR.
HOUSING THAT HOLDS THE LIGHT IS MISSING

CSHOP-2019-5663

Date Opened: 10-28-2019 Date Finished 11-14-2019 Meter 1 Reading: 92,653

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
WIPER BLADES
OIL
OIL FILTER
UNIVERSAL JOINT
REPAIR FROM PM - AIR COMPRESSOR
HVAC SYSTEM

4 1AN; WIPERS
2 1AN; WIPER BLADE
22 4PC; 15W40 PREMIUM BLUE OIL
1 FIL; NAPAGOLD OIL FILTER
1 2IH; AIR COMPRESSOR
1 TEM; EXPVALV
3 9XX; 134A 10194654
1 TEM; STEEL FILTER DRIER
1 2IH; COMPRESSOR A/C

Service Requests:

10/28/2019 A/C / 44: WORN / INSPECT
PATIENT COMPARTMENT AC IS NOT BLOWING COLD

10/28/2019 MISCELLANEOUS / 19: LOOSE / REPAIR
ON RESCUE 273 DRIVER SIDE WINDSHIELD WIPER LOOSE

Asset Work Order History 10194778

CSHOP-2019-5717

Date Opened: 10-31-2019 Date Finished 11-6-2019 Meter 1 Reading: 92,603

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1 FIL; NAPA GOLD FUEL FILTER
24 4PC; 15W40 PREMIUM BLUE OIL
1 FIL; NAPA CABIN AIR FILTER
1 FIL; NAPAGOLD OIL FILTER
1 2IH; AIR FILTER CAN ORDER 500804

CSHOP-2019-6213

Comments: **LOW VOLTAGE POSSIBLE ALTERNATOR TROUBLE**

Date Opened: 11-29-2019 Date Finished 12-12-2019 Meter 1 Reading: 93,525

TASKS PERFORMED

NO PARTS USED

CHARGING SYSTEM

Service Requests:

11/29/2019 ENGINE / 23: NOT CONNECTED / REPAIR
LOW BATTERY VOLTAGE- CRANKS LONGER THAN SHOULD- VOLTAGE WHILE RUNNING APPROX 11.3V

CSHOP-2019-6482

Date Opened: 12-16-2019 Date Finished 1-2-2020 Meter 1 Reading: 94,420

TASKS PERFORMED

NO PARTS USED

FAN BELT

Service Requests:

12/13/2019 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
R273 ENGINE BELT IS RATTLING

CSHOP-2019-6557

Date Opened: 12-19-2019 Date Finished 1-2-2020 Meter 1 Reading: 94,420

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

12/19/2019 AIR RIDE / 18: LEAKING / REPAIR
R273 HAS A HOSE THAT IS LOSE THAT IS CONSTANTLY LEAKING AND REQUIRING THE AIR BREAK COMPRESSOR TO RUN CONTINUOUSLY WHEN BATTERY ID ON AND VEHICLE IS RUNNING. MAKES LOUD NOISE CONTINUOUSLY.

Asset Work Order History 10194778

CSHOP-2019-677

Date Opened: 2-4-2019 Date Finished 3-13-2019 Meter 1 Reading: 85,917

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
BODY EXTERIOR

1 5EF; RUBRAIL
1 5EF; RUBRAIL END CAPS
1 RUB RAIL

Service Requests:

02/03/2019 BODY / 12: BROKEN / EXCHANGE - NEW
BODY ISSUE: RUB RAIL UNDER DRIVERS COMPARTMENT FELL OFF.

CSHOP-2019-879

Date Opened: 2-15-2019 Date Finished 2-20-2019 Meter 1 Reading: 84,472

TASKS PERFORMED

Q PARTS

EXHAUST SYSTEM

2 SVP; DPF GSKT (2601233C1)
2 SVP; DPF GSKT (2593986C1)

Service Requests:

02/14/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
EXHAUST SEPARATED AT FLANGE UNDERNEATH THE TRUCK

CSHOP-2019-908

Date Opened: 2-19-2019 Date Finished 3-13-2019 Meter 1 Reading: 85,917

TASKS PERFORMED

NO PARTS USED

FAULT CODE

Service Requests:

02/19/2019 ENGINE / 49: CAN NOT DUPLICATE CONCERN / INSPECT
"CHECK ENGINE LIGHT" IS ILLUMINATED. TRUCK SEEMS TO BE RUNNING FINE EXCEPT IT SMOKES OUT OF THE
EXHAUST PRETTY GOOD FROM IDLE TO CRUISE.

CSHOP-2020-1270

Comments: **OIL AND FUEL FILTERS CHANGED AT DEALER**

Date Opened: 3-4-2020 Date Finished 3-4-2020 Meter 1 Reading: 95,641

TASKS PERFORMED

NO PARTS USED

PM SERVICE B

CSHOP-2020-1390

Date Opened: 3-9-2020 Date Finished 3-9-2020 Meter 1 Reading: 95,754

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

VENDOR? RECHTIEN INTERNATIONAL TRUCKS

Asset Work Order History 10194778

CSHOP-2020-1723

Date Opened: 3-26-2020 Date Finished 3-30-2020 Meter 1 Reading: 96,542

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
EMERGENCY EQUIPMENT

CSHOP-2020-1927

Date Opened: 4-10-2020 Date Finished 4-13-2020 Meter 1 Reading: 97,365

TASKS PERFORMED

NO PARTS USED

STRETCHER

Service Requests:

04/09/2020 SERVICE REQUEST / 12: BROKEN / REPAIR
STRECHER LOCK IS NOT LOCKING IN PLACE.

CSHOP-2020-2279

Date Opened: 4-29-2020 Date Finished 5-12-2020 Meter 1 Reading: 97,836

TASKS PERFORMED

Q PARTS

ELECTRICAL

1 6KU; COVER ROUND YELLOW

Service Requests:

04/29/2020 SERVICE REQUEST / 12: BROKEN / REPAIR
SHORELINE COVER BROKE OFF OF 273

CSHOP-2020-2537

Date Opened: 5-13-2020 Date Finished 5-19-2020 Meter 1 Reading: 97,836

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FAULT CODE

Service Requests:

05/12/2020 ENGINE / 12: BROKEN / REPAIR
ENGINE, CHECK ENGINE LIGHT IS ON.

Asset Work Order History 10194778

CSHOP-2020-2685

Date Opened: 5-20-2020

Date Finished

6-4-2020

Meter 1 Reading:

98,866

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES

2 NBH; IDLER PULLEY
1 NBH; TENSIONER HEAVY DUTY
1 NBH; NBH
1 NBH; V RIBBED BELT
2 MAC; SILICONE SPRAY 10OZ
1 2IH; BELT TENSIONER V8

Service Requests:

-
- 05/20/2020 SERVICE REQUEST / 19: LOOSE / REPAIR ON ANOTHER TICKET REMT
TYPE PROBLEM INTO DESCRIPTION RESCUE DRIVER COMPARTMENT SCBA MOUNTING BRACKET LOOSE
 - 05/20/2020 ENGINE / 12: BROKEN / REPAIR
ENGINE WAS MAKING INTERMITTENT LOUD NOISE. CRUISE THROTTLE WAS LOCKING ON WHILE IDLE.
 - 05/26/2020 SERVICE REQUEST / 12: BROKEN / REPAIR
ENGINE IS MAKING A TERRIBLE NOISE. SENT VIDEO TO JOHN MURRAY
-

CSHOP-2020-274

Date Opened: 1-17-2020

Date Finished

3-8-2020

Meter 1 Reading:

95,754

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

1 2IH; SENSOR EVAP TEMP
1 2CU; SEAT BELT

Service Requests:

-
- 01/16/2020 ENGINE / 15: FOREIGN MATERIAL / LUBRICATE.
ENGINE. THE BELT IS MAKING A NOISE. WE THINK IS THE BELT BUT NOT 100% SURE.
-

CSHOP-2020-2824

Date Opened: 5-28-2020

Date Finished

6-11-2020

Meter 1 Reading:

99,317

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM

Service Requests:

-
- 05/27/2020 SERVICE REQUEST / 12: BROKEN / REPAIR
DRIVER SIDE STEP LIGHT IS MISSING WASHER WHICH DOESNT ALLOW THE LIGHT TO PROPERLY TIGHTEN. HELD ON BY ONE SCREW
 - 05/27/2020 SERVICE REQUEST / 12: BROKEN / REPAIR
DISREGARD PREVIOUS POST NOT AN OOS ISSUE (DRIVER SIDE STEP LIGHT IS HELD ON BY ONE SCREW. MISSING A WASHER WHICH ALLOWS IT TO SEAT PROPERLY
-

Asset Work Order History 10194778

CSHOP-2020-2887

Date Opened: 6-2-2020

Date Finished

6-11-2020

Meter 1 Reading:

99,317

TASKS PERFORMED

Q PARTS

WASHER RESERVOIR
CRANKING SYSTEM

1 2IH; CAP
1 NCB; SUPER K WASH CONCNTRT

Service Requests:

06/01/2020 SERVICE REQUEST / 12: BROKEN / REPAIR
THE CAP TO THE WINDSHIELD WASHER FLUID CONTAINER IS BROKEN. THE PLASTIC HAS BROKEN OFF WHERE THE THREADS MEET THE TOP OF THE CAP. IT IS STILL SCREWED ON BECAUSE THE TOP HAS NOT COMPLETELY BROKEN ALL THE WAY OFF, BUT IS RELEASING FLUID ANYTIME THE RESCUE HITS A BUMP.

CSHOP-2020-3015

Date Opened: 6-8-2020

Date Finished

6-15-2020

Meter 1 Reading:

99,393

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FAULT CODE
ENGINE AND ACCESSORIES

Service Requests:

06/08/2020 ENGINE / 12: BROKEN / REPAIR
ENGINE R273 IS NOT PROPERLY REGENING AND WILL NOT GO OVER 55MPH. APPEARS TO NEED A FORCE REGEN

06/11/2020 ENGINE / 12: BROKEN / REPAIR
ENGINE SPINS OVER FINE TAKES LONG TIME TO FIRE UP

CSHOP-2020-3110

Date Opened: 6-14-2020

Date Finished

6-16-2020

Meter 1 Reading:

99,393

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

06/14/2020 ALARMS / 12: BROKEN / REPAIRED
ALARM SIGNALS CHECK ENGINE SAME THING IT DID LAST TIME. DIDN'T SEEM TO WANT TO GO OVER 55 MPH

CSHOP-2020-493

Date Opened: 1-29-2020

Date Finished

2-24-2020

Meter 1 Reading:

95,528

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DIAGNOSTIC TEST

Service Requests:

01/29/2020 SERVICE REQUEST / 12: BROKEN / INSPECT

Asset Work Order History 10194778

CSHOP-2020-5562

Date Opened: 10-21-2020 Date Finished 11-3-2020 Meter 1 Reading: 99,393

TASKS PERFORMED

NO PARTS USED

QUALITY CHECK-REPAIRS

RADIO-2016-588

Comments: **CREW WAS USING A SETCOM HEADSET ON A FIRECOM SYSTEM.**

Date Opened: 9-23-2016 Date Finished 9-23-2016 Meter 1 Reading: 48,148

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

09/23/2016 RADIO / /
RADIO ISSUES WHEN RADIO IS ON, IT IS CONTINUOUSLY KEYED ON FOR BOTH FRONT AND REAR RADIOS.

RADIO-2017-534

Date Opened: 8-23-2017 Date Finished 8-24-2017 Meter 1 Reading: 63,639

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

08/18/2017 SERVICE REQUEST / /
MDT WILL NOT CHARGE. BLOWS 30 AMP FUSE WHERE THE LAPTOP CONNECTS TO A POWER SOURCE.

RADIO-2018-1245

Comments: **RETROFIT VEHICLE WITH WIRELESS HEADSET SYSTEM 10194778 R273 FIR-UHW-505 RADIO TRANSMIT \ WIRELESS HEADSET QTY4 FIR-WB505R FIRECOM WIRELESS BASE STATION QTY1 FIR-5200D 5200D DIGITAL INTERCOM QTY1**

Date Opened: 12-10-2018 Date Finished 12-11-2018 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

RADIO

1 9ES; DIGITAL INTERCOM
4 9ES; RADIO TRANSMIT UNDER HELMET
1 9ES; FIRECOM WIRELESS BASE STATION

Service Requests:

12/10/2018 RADIO / /
RETROFIT VEHICLE WITH WIRELESS HEADSET SYSTEM

Asset Work Order History 10194778

RADIO-2018-1259

Comments: **RETRO WIRELESS HEADSETS INTO RESCUE - 273**

Date Opened: 12-17-2018 Date Finished 12-17-2018 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

RADIO-2018-1260

Comments: **RETRO WIRELESS HEADSETS INTO RESCUE - 273**

Date Opened: 12-17-2018 Date Finished 12-17-2018 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

12/11/2018 RADIO / /
RETROFIT WIRELESS HEADSET SYSTEM INTO R273

RADIO-2020-429

Date Opened: 5-6-2020 Date Finished 5-6-2020 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

05/06/2020 RADIO / /
RADIO ISSUES TRUCK RADIO ON BUT INOPERABLE. RADIO HAS A CONTINUOUS TONE SOUNDING OVER THE
SPEAKER. REPLACED 2 HEADSET BATTERIES AND REPAIRED PM HEADSET (PTT WAS THE PROBLEM).
