

10/25/2024  
2:50:31 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10185507 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4**

---

**Total Hours: 202.50    Labor: 13,323.05    Parts: 11,628.37    Comm: 1,236.41    Charged: 26187.83**

---

**Work Order:** 1107635      **Meter:** 14      **In Date:** 07/20/2011    **Closed:** 07/25/2011  
**Problem:** install 6 prong trailer plug

**Work Completed**

- Remove factory trailer plug, install 6 prong plug wire and test Ok
- Shop Supplies

**Parts Issued**

Shop Supplies	1.00
5404 Female Connector	1.00

**Quantity**

Hours: 1.00      Comm: 0.00      Labor: 60.00      Parts: 12.10      Total: 72.10

---

**Work Order:** 1107656      **Meter:** 0      **In Date:** 07/21/2011    **Closed:** 07/21/2011  
**Problem:** Pre Delivery Inspection

**Work Completed**

- Pre Delivery Inspection

Hours: 2.00      Comm: 0.00      Labor: 120.00      Parts: 0.00      Total: 120.00

---

**Work Order:** 1110016      **Meter:** 2603      **In Date:** 09/20/2011    **Closed:** 09/20/2011  
**Problem:** 3 - Wash ticket(s) issued

**Work Completed**

- 3 - Wash ticket(s) issued

Hours: 0.00      Comm: 29.20      Labor: 0.00      Parts: 0.00      Total: 29.20

---

**Work Order:** 1112339      **Meter:** 5238      **In Date:** 11/18/2011    **Closed:** 11/21/2011  
**Problem:** Pm service.

**Work Completed**

- Perform pm service.
- Rotate and balance all four tires.
- Shop Supplies

**Parts Issued**

Shop Supplies	1.00
Ph10575 Oil Filter Mtc FI500s Wix 57502	1.00
5w20 Engine Oil	6.00

**Quantity**

Hours: 3.75      Comm: 0.00      Labor: 225.00      Parts: 21.11      Total: 246.11











10/25/2024  
2:50:31 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10185507 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4**

---

**Work Order:** 1508351      **Meter:** 41260      **In Date:** 08/20/2015      **Closed:** 08/20/2015  
**Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

**Work Completed**

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00      Comm: 96.00      Labor: 0.00      Parts: 0.00      Total: 96.00

---

**Work Order:** 1509661      **Meter:** 42006      **In Date:** 09/24/2015      **Closed:** 09/24/2015  
**Problem:** 2 - Wash ticket(s) issued

**Work Completed**

- 2 - Wash ticket(s) issued

Hours: 0.00      Comm: 19.08      Labor: 0.00      Parts: 0.00      Total: 19.08

---

**Work Order:** 1601777      **Meter:** 44532      **In Date:** 02/19/2016      **Closed:** 02/24/2016  
**Problem:** Pm service.

**Work Completed**

- P.m. Service.
- Flush and refill transmission,
- Replace left and right side weatherstrip/moulding assembly.(cracked)
- Rotate and balance all tires.
- Shop Supplies

**Parts Issued**

**Quantity**

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Accufit Beam	1.00
Accufit Beam	1.00
Blade	1.00
Washer Fluid Concentr	1.00
Syn-atf Trans Fluid S	12.00
Moulding	1.00
Moulding	1.00
Moulding	1.00
Moulding	1.00
Shop Supplies	1.00

Hours: 6.25      Comm: 0.00      Labor: 375.00      Parts: 587.68      Total: 962.68





10/25/2024  
2:50:31 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10185507 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4**

---

**Work Order:** 1712083      **Meter:** 53346      **In Date:** 12/08/2017      **Closed:** 12/18/2017  
**Problem:** PM Service, Detail

**Work Completed**

- P.m. service.
- Resurface both front rotors on car .replace worn front brake pads with new.flush and bleed brake system and road test.
- Replace four worn tires and valve stems with new.high speed balance all .
- Complete front and rear alignment and road test.
- Shop Supplies

**Parts Issued**

**Quantity**

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
26in Exactfit-beam	1.00
22in Exactfit-beam	1.00
11in Exactfit-rear	1.00
Washer Fluid Concentr	1.00
B Fluid Dot 3-32oz	1.00
Non-chlor Brake Clnr	1.00
P245 65 Sr17	4.00
Tire Pressure Monitoring System Sensor (	4.00
Air Filter	1.00
Front Brake Pad	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 11.25

Comm: 0.00

Labor: 675.00

Parts: 965.62

Total: 1,640.62

---

**Work Order:** 1712175      **Meter:** 53222      **In Date:** 12/12/2017      **Closed:** 12/12/2017  
**Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

**Work Completed**

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

---

**Work Order:** 1801800      **Meter:** 54603      **In Date:** 02/15/2018      **Closed:** 02/15/2018  
**Problem:** 2 - Wash ticket(s) issued

**Work Completed**

- 2 - Wash ticket(s) issued

Hours: 0.00

Comm: 19.08

Labor: 0.00

Parts: 0.00

Total: 19.08

10/25/2024  
2:50:31 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10185507 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4**

---

**Work Order:** 1804686                      **Meter:** 56298                      **In Date:** 05/04/2018   **Closed:** 05/04/2018  
**Problem:** 2 - Wash ticket(s) issued

**Work Completed**

- 2 - Wash ticket(s) issued

Hours: 0.00                                      Comm: 19.08                      Labor: 0.00                      Parts: 0.00                      Total: 19.08

---

**Work Order:** 1805893                      **Meter:** 57173                      **In Date:** 06/08/2018   **Closed:** 06/12/2018  
**Problem:** PM Service

**Work Completed**

- P.m. Service.
- Replace rear brake pads and rotors.service and lube calipers.flush and bleed system.
- Rotate and balance tires.
- Shop Supplies

**Parts Issued**

**Quantity**

Brake Pad	1.00
Rear Brake Rotor	2.00
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Non-chlor Brake Clnr	2.00
Mac Wite Lithium Gres	1.00
11in Exactfit-rear	1.00
26in Exactfit-beam	1.00
22in Exactfit-beam	1.00
B Fluid Dot 3-32oz	1.00
Shop Supplies	1.00

Hours: 7.75                                      Comm: 0.00                      Labor: 465.00                      Parts: 225.31                      Total: 690.31

---

**Work Order:** 1809212                      **Meter:** 59202                      **In Date:** 09/07/2018   **Closed:** 09/07/2018  
**Problem:** 2 - Wash ticket(s) issued

**Work Completed**

- 2 - Wash ticket(s) issued

Hours: 0.00                                      Comm: 19.08                      Labor: 0.00                      Parts: 0.00                      Total: 19.08

---

**Work Order:** 1810952                      **Meter:** 60531                      **In Date:** 10/24/2018   **Closed:** 10/24/2018  
**Problem:** 2 - Wash ticket(s) issued

**Work Completed**

- 2 - Wash ticket(s) issued

Hours: 0.00                                      Comm: 19.08                      Labor: 0.00                      Parts: 0.00                      Total: 19.08









10/25/2024  
2:50:31 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10185507 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4**

**Work Order:** 2100164      **Meter:** 73185      **In Date:** 01/07/2021      **Closed:** 01/26/2021  
**Problem:** pm service

**Work Completed**

- Preventive Maint. Service
- check engine n abs light on diagnose - no brakes - multiple codes for abs -u3000,c0004,c0020,c1boo,u3oo0 - test abs system remove battery air intake system replace abs pump n abs module - reprogram n bleed system
- test n replace battery

**Parts Issued**

**Quantity**

Napa Quart 5w20	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
26in Exactfit-beam	1.00
22in Exactfit-beam	1.00
Non-chlor Brake Clnr	1.00
Abs Module	1.00
Abs Pump	1.00
Napagold Air Filter	1.00
Battery	1.00
Non-chlor Brake Clnr	2.00
B Fluid Dot 3-12oz	1.00
Qd Electronic Cleaner	1.00

Hours: 11.75

Comm: 0.00

Labor: 857.75

Parts: 1,738.52

Total: 2,596.27

**Work Order:** 2101377      **Meter:** 73401      **In Date:** 02/05/2021      **Closed:** 02/11/2021  
**Problem:** brake pedal went to floor

**Work Completed**

- test - use ids to bleed abs system then manually bleed brakes - road test
- no problems found

**Parts Issued**

**Quantity**

B Fluid Dot 3-32oz	1.00
--------------------	------

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 7.07

Total: 153.07

**Work Order:** 2102202      **Meter:** 73753      **In Date:** 02/25/2021      **Closed:** 03/09/2021  
**Problem:** tire pressure sensor fault light

**Work Completed**

- Check Tire Pressure Fault,replaced Faulty Left Rear Tire Sensor, Relearn All Tire Pressure Sensors

**Parts Issued**

**Quantity**

Tpms12 Sensor Tire Pr	1.00
-----------------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 80.45

Total: 153.45



10/25/2024  
2:50:31 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10185507 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4**

---

**Work Order:** 2200041      **Meter:** 77664      **In Date:** 01/03/2022      **Closed:** 01/13/2022

**Problem:** condensation water on dash

**Work Completed**

**Parts Issued**

**Quantity**

- Performed Water Test, Found Leak Coming From Clogged Cowl Do To Broken Cowl Seals. Replaced Cowl

Grille 1.00

Hours: 5.00

Comm: 0.00

Labor: 365.00

Parts: 154.84

Total: 519.84

---

**Work Order:** 2203149      **Meter:** 78714      **In Date:** 03/23/2022      **Closed:** 03/28/2022

**Problem:** pm service

**Work Completed**

**Parts Issued**

**Quantity**

- Preventive Maint. Service

Napa Quart 5w20 6.00

- Rotate & Balance Tires, Nitro Fill, And Replace Valve Caps

Napagold Oil Filter 1.00

26in Exactfit-beam 1.00

22in Exactfit-beam 1.00

11in Exactfit-rear 1.00

Air Freshener 1.00

Non-chlor Brake Clnr 1.00

High Gloss Coating 1.00

Hours: 3.75

Comm: 0.00

Labor: 273.75

Parts: 72.39

Total: 346.14

---

**Work Order:** 2206359      **Meter:** 80070      **In Date:** 06/15/2022      **Closed:** 06/15/2022

**Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued to: Bill for Fleet

**Work Completed**

- 1 - Detail Vehicle Wash Ticket(s) Issued to: Bill for Fleet

Hours: 0.00

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40





10/25/2024  
2:50:31 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10185507 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4**

**Work Order:** 2310352

**Meter:** 90766

**In Date:** 10/12/2023 **Closed:** 10/24/2023

**Problem:** PM Service.

**Work Completed**

- Preventive Maint. Service
- Rotate and speed balance, nitro fill
- Inspect all brakes, R & i new rear brakes, R & i new rear rotors, service Caliper slide pins, bleed brakes, road test
- Check drivers window switch, R & i new switch broken
- Check circuit to right side head light inoperative, R & i new bulb
- Shop Supplies

**Parts Issued**

**Quantity**

Napa Quart 5w20	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
11in Exactfit-rear	1.00
26in Exactfit-beam	1.00
22in Exactfit-beam	1.00
Non-chlor Brake Clnr	1.00
Boxed Capsules	1.00
Rotor	2.00
Brake Pad	1.00
Window Switch Asm	1.00
Shop Supplies	1.00

Hours: 8.25

Comm: 0.00

Labor: 602.25

Parts: 386.42

Total: 988.67

10/25/2024  
2:50:31 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10185507 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4**

**Work Order:** 2405958

**Meter:** 95919

**In Date:** 06/17/2024 **Closed:** 07/08/2024

**Problem:** PM Service.

**Work Completed**

- Preventive Maint. Service
- Recall: Safety recall # 24s02/24v031 A-pillar trim loose (improper assembly) No part available yet
- Wiper comes on intermittently. Diagnose with scan tool wiper control switch and pinpoint test. R&r faulty wiper control switch and verify repair. Replace broken section of windshield wash hose.
- Load test battery failed due to age and normal wear. R&r battery, check charging system and verify repair complete.
- R&r six worn spark plugs, Pcv valve and upper intake gasket. Power balance test ignition system with scan tool and road test to verify repair.
- Perform fuel injection, upper intake system service and clean throttle body.
- Low engine oil pressure light on. Diagnose with scan tool oil pressure switch showing low while engine is running. Check oil pressure with gage and found pressure within specification. R&r faulty oil pressure switch and verify repair complete.
- Rotate and balance four tires. Relearn tire sensors.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
11in Exactfit-rear	1.00
21in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Napagold Air Filter	1.00
Wiper Switch	1.00
Battery	1.00
Gasket	1.00
Spark Plug	6.00
Pcv Elbow	1.00
Pcv Valve	1.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Throttle Cleaner	1.00
Switch Asy	1.00
Switch Assy	1.00
Gasket	1.00
Pcv Valve	1.00
Pcv Elbow	1.00
Shop Supplies	1.00

Hours: 14.85

Comm: 0.00

Labor: 1,084.05

Parts: 601.72

Total: 1,685.77

10/25/2024  
2:50:31 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10185507 2011 FORD EXPLORER Suv, Lg Mid Size, 4X4**

---

**Work Order:** 2407082      **Meter:** 96218      **In Date:** 07/23/2024      **Closed:** 07/26/2024  
**Problem:** Transition Prep Charge

**Work Completed**

**Parts Issued**

**Quantity**

- Transition Prep Charge
- Shop Supplies

Shop Supplies

1.00

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 2.65

Total: 148.65

**Total Hours: 202.50**

**Total Labor: 13,323.05**

**Total Comm: 1,236.41**

**Total Parts: 11,628.37**