

10/25/2024
3:08:19 PM

Palm Beach County Fleet Management Asset Maintenance History
10198282 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Total Hours: 142.20 Labor: 9,748.60 Parts: 6,530.60 Comm: 923.05 Charged: 17202.25

Work Order: 1511692 **Meter:** 330 **In Date:** 11/16/2015 **Closed:** 11/16/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1605135 **Meter:** 4512 **In Date:** 05/17/2016 **Closed:** 05/26/2016
Problem: P.M. Service.

Work Completed

- P.m. Service.

- Test and replace defective right rear tire pressure sensor.rotate and balance all tires.reprogram sensor.

- Shop Supplies

Parts Issued

Quantity

Tpms12 Sensor Tire Pr 1.00

5w20 Engine Oil 6.00

Napagold Oil Filter 1.00

Floor Mat 1.00

Stg Wheel Cov - Ford 1.00

Mac Wite Lithium Gres 1.00

Washer Fluid Concentr 1.00

Shop Supplies 1.00

Hours: 6.00 Comm: 0.00 Labor: 360.00 Parts: 154.01 Total: 514.01

Work Order: 1611804 **Meter:** 9220 **In Date:** 11/16/2016 **Closed:** 11/29/2016
Problem: P.M. service and detail.

Work Completed

- P.m. Service.

- Rotate and balance all tires.

- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil 6.00

Napagold Oil Filter 1.00

Used Fire X Refurbished 1.00

Shop Supplies 1.00

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 34.36 Total: 334.36

10/25/2024
3:08:19 PM

Palm Beach County Fleet Management Asset Maintenance History
10198282 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 1806585 **Meter:** 20397 **In Date:** 06/27/2018 **Closed:** 07/18/2018
Problem: P.M. service and recalls 17S34 , 17S15 .

Work Completed

- P.m. service. Replace battery in remote key fob.
- Replace rear brake pads .resurface rear rotors and service rear calipers .
Flush and bleed brake system .test drive.
- Replace four tires. Balance and nitrogen fill tires.
- Perform complete front alignment .road test.
- Transport to and from dealer for recalls 17s34 and 17s15 .
- Shop Supplies

Parts Issued

Quantity

Brk Fluid Dot 4-12oz	2.00
Lithium Coin Cell	1.00
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Brake Pad	1.00
235/65/16 Tire Hankook	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 14.00

Comm: 0.00

Labor: 840.00 Parts: 1,007.53 Total: 1,847.53

Work Order: 1901376 **Meter:** 24346 **In Date:** 02/05/2019 **Closed:** 02/20/2019
Problem: P.M. service.

Work Completed

- P.m. service.
- Test and replace trailer plug connector and rewire as needed.
- Rotate and balance all four tires . Nitrogen fill all tires .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	1.00
Wiper Blade	2.00
trailer plug	1.00
Bp Fmx-lp F Mx Fuse	1.00
Fuse	1.00
Shop Supplies	1.00

Hours: 6.00

Comm: 0.00

Labor: 402.00 Parts: 99.20 Total: 501.20

10/25/2024
3:08:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10198282 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 1903143 **Meter:** 25201 **In Date:** 03/21/2019 **Closed:** 04/03/2019
Problem: Runs rough & stalls, Runs fine after restart.

Work Completed

- Computer diagnose wrench light , code P2195 ,p2197 . Replace air box top per Tsb 17-0014 and seal vacuum port . Clear codes and retest .
- Computer diagnose check engine light , code P0122,p0223 . Replace defective throttle body . Clear codes and test drive .
- Shop Supplies

Parts Issued

Quantity

Throttle Body	1.00
Cover	1.00
Gasket	1.00
Air Filter	1.00
Shop Supplies	1.00

Hours: 3.50 Comm: 0.00 Labor: 234.50 Parts: 228.81 Total: 463.31

Work Order: 1907562 **Meter:** 26876 **In Date:** 07/18/2019 **Closed:** 07/22/2019
Problem: FLAT TIRE REPAIR

Work Completed

- Tire Service 8130 Jog Rd - Flat Tire Repair

Hours: 0.00 Comm: 70.25 Labor: 0.00 Parts: 0.00 Total: 70.25

Work Order: 1909320 **Meter:** 29350 **In Date:** 09/10/2019 **Closed:** 09/23/2019
Problem: P.M. service and at times cranks but no start.

Work Completed

- P.m. service.
- Computer diagnose no start at times . Perform evap test . R&r defective purge valve . Retest .
- Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	1.00
Wiper Blade	1.00
Purge Valve	1.00
Shop Supplies	1.00

Hours: 7.00 Comm: 0.00 Labor: 469.00 Parts: 112.89 Total: 581.89

Work Order: 1909673 **Meter:** 29198 **In Date:** 09/19/2019 **Closed:** 09/19/2019
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

10/25/2024
3:08:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10198282 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 2302552

Meter: 64309

In Date: 03/14/2023 **Closed:** 03/30/2023

Problem: PM Service and recall 19S38 .

Work Completed

- Preventive Maint. Service
- Rotate and speed balance,nitro fill
- Check all brakes, R & I new front brakes, Resurface both rotors, R & I both front calipers, service caliper slide pins, Bleed and flush brake fluid Burnish brake rotors, Road test
- Transport to and from dealer for recall #19s38
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	6.00
Washer Fluid Concentr	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Non-chlor Brake Clnr	1.00
Brake Fl-dot 3-4 32oz	1.00
Brake Caliper	1.00
Brake Caliper	1.00
Brake Pad	1.00
Shop Supplies	1.00

Hours: 11.00

Comm: 0.00

Labor: 803.00

Parts: 306.50

Total: 1,109.50

10/25/2024
3:08:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10198282 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 2309309 **Meter:** 69628 **In Date:** 09/13/2023 **Closed:** 09/25/2023

Problem: PM Service. had to jump start .

Work Completed

Parts Issued

Quantity

- Performed P.m. Service & Inspection.
- Mount 2 Tires Then Balance & Rotate All 4 Wheels, Add Nitro Fill Reset Tpms.
- Performed Front Wheel Alignment Test Drove Vehicle & Test Drove.
- Load Test Battery, Battery Test Recommend Charge, Charged Battery & Retest. Test Recommend Battery Replacement. Removed Left Front Seat To Replace Battery. Reset To Basic Settings And Check.
- Driver Side Rear Tail Lamp Assembly Has Water Damage Due To Seal Broken. Removed & Rplaced Then Check.
- Perform Engine Decarb Service & Fuel Injection Cleaning Service. Removed Throttle Body And Clean.
- Diagnose Engine Misfire Performed Tune -up, Removed & Replaced All 6 Spark Plugs Test Drove Vehicle & Check.
- Shop Supplies

Oil Filter	1.00
5w20 Engine Oil	6.00
Used Fire X Refurbished	1.00
235/65/16 Tire Gooyer	2.00
Battry Motorcraft	1.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Plenum Gskt Set	1.00
Spark Plug	6.00
Lamp Assy	1.00
Ignition Coil	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 16.90

Comm: 0.00

Labor: 1,233.70

Parts: 960.63

Total: 2,194.33

10/25/2024
3:08:20 PM

Palm Beach County Fleet Management Asset Maintenance History
10198282 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 2402572 **Meter:** 70951 **In Date:** 03/12/2024 **Closed:** 03/27/2024
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- R&r right slide door lock switch and contact broken. Had to drill out rivets and replace. Readjust slide door striker loose and retorque.
- Mount two tires, rotate and balance four tires. Relearn tire sensors.
- R&r worn front sway bar links.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Wiper Blade	1.00
Wiper Blade	1.00
235/65/16 Tire Gooyer	2.00
Nut	2.00
l\link	2.00
Terminal	1.00
Terminal	1.00
Rivet	4.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 8.10

Comm: 0.00

Labor: 591.30

Parts: 500.09

Total: 1,091.39

Work Order: 2406849 **Meter:** 71088 **In Date:** 07/16/2024 **Closed:** 07/17/2024
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 142.20

Total Labor: 9,748.60

Total Comm: 923.05

Total Parts: 6,530.60