

10/25/2024
6:46:47 PM

Palm Beach County Fleet Management Asset Maintenance History
10196046 2014 LEOBY 400T Roller, Vibratory, 2.5 - 5 Ton

Total Hours: 291.00 Labor: 19,341.50 Parts: 20,056.83 Comm: 1,262.99 Charged: 40661.32

Work Order: 1408688 **Meter:** 6 **In Date:** 08/28/2014 **Closed:** 08/28/2014
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1408892 **Meter:** 6 **In Date:** 09/03/2014 **Closed:** 09/22/2014
Problem: keys

Work Completed

- order keys

- Shop Supplies

Parts Issued

Quantity

Ignition Key 16.00

Shop Supplies 1.00

Freight Charge 1.00

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 370.24 Total: 400.24

Work Order: 1409646 **Meter:** 6 **In Date:** 09/25/2014 **Closed:** 09/29/2014
Problem: Keys

Work Completed

- order keys

- Shop Supplies

Parts Issued

Quantity

Leeboy Key 16.00

Shop Supplies 1.00

Freight Charge 1.00

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 576.40 Total: 606.40

10/25/2024
6:46:47 PM

Palm Beach County Fleet Management Asset Maintenance History
10196046 2014 LEBOY 400T Roller, Vibratory, 2.5 - 5 Ton

Work Order: 1412947 **Meter:** 85 **In Date:** 12/31/2014 **Closed:** 01/20/2015
Problem: List

Work Completed

- Rebuild intire drum assembly
- Replace brake plug
- Shop Supplies

Parts Issued

Quantity

Axle Nut	1.00
Front Axle	1.00
Seal	4.00
Bearing Cone	4.00
Bearing Cup	4.00
Front Spacer	2.00
Brake Cleaner	2.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 10.50

Comm: 0.00

Labor: 630.00 Parts: 1,032.21 Total: 1,662.21

Work Order: 1501826 **Meter:** 109 **In Date:** 02/20/2015 **Closed:** 03/06/2015
Problem: PM

Work Completed

- Pm
- To Jpp
- Rd Test
- Shop Supplies

Parts Issued

Quantity

15w40 serv truck	6.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Fuel Fil	1.00
Hyd/fil	1.00
Aw68 Serv Truck	3.00
Shop Supplies	1.00

Hours: 6.50

Comm: 0.00

Labor: 390.00 Parts: 69.58 Total: 459.58

Work Order: 1507166 **Meter:** 109 **In Date:** 07/15/2015 **Closed:** 07/17/2015
Problem: replace pass side bald tire

Work Completed

- Tire Service Jpp polebarn compound - replace pass side bald tire

Hours: 0.00

Comm: 150.64

Labor: 0.00 Parts: 0.00 Total: 150.64

10/25/2024
6:46:47 PM

Palm Beach County Fleet Management Asset Maintenance History
10196046 2014 LEBOY 400T Roller, Vibratory, 2.5 - 5 Ton

Work Order: 1702692 **Meter:** 456 **In Date:** 03/16/2017 **Closed:** 04/06/2017
Problem: pm service

Work Completed

- Pm
- Service hydraulic sys
- Replace left and right brake assy. fab and replace breakaway cable, repair ground right side brakes
- Diag and replace reverse alarm switch
- Replace trailer plug
- Test battery replace faulty battery
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	6.00
Fuel Fil	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	1.00
Hyd/fil	1.00
Aw68 Hydro Fluid Hydr	3.00
Backing Plate Assm	1.00
Backing Plate Assm	1.00
Seal 2.250x3.371x.375	2.00
Male Trailer Connector	1.00
Peak Global Antifrz	1.00
Back Up Actuator	1.00
Battery	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 13.00 Comm: 0.00 Labor: 780.00 Parts: 462.93 Total: 1,242.93

Work Order: 1707322 **Meter:** 510 **In Date:** 07/26/2017 **Closed:** 07/27/2017
Problem: wont start

Work Completed

- test battery, test for parasidic draw. found alternator belt loose and tighten
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.50 Comm: 0.00 Labor: 90.00 Parts: 2.00 Total: 92.00

10/25/2024
6:46:47 PM

Palm Beach County Fleet Management Asset Maintenance History
10196046 2014 LEBOY 400T Roller, Vibratory, 2.5 - 5 Ton

Work Order: 1707647 **Meter:** 512 **In Date:** 08/04/2017 **Closed:** 08/09/2017
Problem: brakes locked up

Work Completed

- Replace breakaway switch. replace left and right brake assy
- Shop Supplies

Parts Issued

Quantity

Backing Plate Assm	1.00
Backing Plate Assm	1.00
Seal 2.250x3.371x.375	2.00
Breakaway Switch	1.00
Non-chlor Brake Clnr	1.00
Shop Supplies	1.00

Hours: 3.50

Comm: 0.00

Labor: 210.00

Parts: 218.08

Total: 428.08

Work Order: 1707734 **Meter:** 510 **In Date:** 08/04/2017 **Closed:** 08/08/2017
Problem: brake has locked on up on this roller

Work Completed

- Tow From: 441 1/2 from Pinewood Park To: Se shop

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

Work Order: 1709471 **Meter:** 524 **In Date:** 09/28/2017 **Closed:** 10/10/2017
Problem: pm/ roof bracket weld broken

Work Completed

- Pm
- Replace trailer plug
- Reweld hold down brackets to the roof
- Ck for battery draw, replace Shorted out breakaway switch
- Free up seized E-brake lever
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	6.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Fuel Fil	1.00
Non-chlor Brake Clnr	2.00
Male Trailer Connector	1.00
Glos Blk	1.00
Breakaway Switch	1.00
Blaster Penetrant	1.00
Shop Supplies	1.00

Hours: 11.50

Comm: 0.00

Labor: 690.00

Parts: 86.78

Total: 776.78

10/25/2024
6:46:47 PM

Palm Beach County Fleet Management Asset Maintenance History
10196046 2014 LEBOY 400T Roller, Vibratory, 2.5 - 5 Ton

Work Order: 1910462 **Meter:** 777 **In Date:** 10/09/2019 **Closed:** 10/25/2019

Problem: overheating/ breakaway/ brake wire/ work light fixture

Work Completed

- Check overheating-radiator is leaking; replace radiator & hoses and thermostat
- Replace left and right brake assy's; repl. left and right brake drums, seals and bearings
- Fabricate new breakaway cable; rewire all burn up breakaway switch wires & repl. breakaway switch
- Repl. rear work light and rewire
- Repl. worn tow ring
- Wash off red dirt from around radiator shroud & engine compartment
- Shop Supplies

Parts Issued

Quantity

Hub & Drum Assembly	2.00
brake 12x2 rh	1.00
brake 12x2 lh	1.00
Breakaway Switch	1.00
Lamp	1.00
Lunette Tow Ring	1.00
Radiator Assy	1.00
Thermostat Gasket	1.00
Radiator Cap	1.00
Peak Global Antifrz	2.00
Lower Hose	1.00
Upper Hose	1.00
Thermostat	1.00
Hose Clamp	1.00
Aw68 Hydro Fluid Hydr	4.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 17.00

Comm: 0.00

Labor: 1,241.00 Parts: 3,464.44 Total: 4,705.44

10/25/2024
6:46:47 PM

Palm Beach County Fleet Management Asset Maintenance History
10196046 2014 LEBOY 400T Roller, Vibratory, 2.5 - 5 Ton

Work Order: 1912869 **Meter:** 803 **In Date:** 12/17/2019 **Closed:** 12/26/2019
Problem: pm service

Work Completed

- pm service
- replace trailer plug
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Napagold Oil Filter	1.00
Fuel Fil	1.00
15-40 Oil	6.00
Hyd/fil	1.00
Aw68 Hydro Fluid Hydr	2.00
Seal 2.250x3.371x.375	2.00
Male Trailer Connector	1.00
Shop Supplies	1.00

Hours: 6.50

Comm: 0.00

Labor: 474.50

Parts: 82.84

Total: 557.34

Work Order: 2006677 **Meter:** 848 **In Date:** 07/07/2020 **Closed:** 07/22/2020
Problem: pm service, breakaway cable frayed, back up alarm goes off when parked

Work Completed

- pm service
- service brakes
- replace trailer plug
- test and replace backup alarm switch
- replace right side tire
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Napagold Oil Filter	1.00
15-40 Oil	6.00
Fuel Fil	1.00
Seal 2.250x3.371x.375	2.00
Male Trailer Connector	1.00
Lt225/75r16e Elpex Special.	1.00
Ecco Switch	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 9.50

Comm: 0.00

Labor: 693.50

Parts: 321.77

Total: 1,015.27

10/25/2024
6:46:47 PM

Palm Beach County Fleet Management Asset Maintenance History
10196046 2014 LEBOY 400T Roller, Vibratory, 2.5 - 5 Ton

Work Order: 2101145 **Meter:** 909 **In Date:** 01/29/2021 **Closed:** 03/31/2021
Problem: PM Service/ muffler broke

Work Completed

- Preventive Maint. Service
- replace damaged beacon light rewire - replace trailer plug
- replace damaged exhaust - remove heat shield n replace exhaust - gaskets n hardware / Repair & Weld Broken Exhaust, Paint
- flush fuel system - water in tank
- replace v belt
- Shop Supplies

Parts Issued

Quantity

Heat Spr	1.00
Px Red Rtv Silicone 3	1.00
U-bolt	2.00
Exhaust Pipe	1.00
Exhaust Manifold Gasket	1.00
Fan Belt	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Napa Qt 15w40	6.00
Napagold Oil Filter	1.00
Fuel Fil	1.00
Grease Cap	2.00
Non-chlor Brake Clnr	2.00
Male Trailer Connector	1.00
Strobe Lp Led	1.00
Blaster Penetrant	1.00
Pm-22-a Additive Dies	1.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 17.00

Comm: 0.00

Labor: 1,241.00

Parts: 531.71

Total: 1,772.71

10/25/2024
6:46:47 PM

Palm Beach County Fleet Management Asset Maintenance History
10196046 2014 LEBOY 400T Roller, Vibratory, 2.5 - 5 Ton

Work Order: 2110034

Meter: 962

In Date: 09/16/2021 **Closed:** 10/22/2021

Problem: PM Service.

Work Completed

- Preventive Maint. Service
- replace both tires
- replace trailer light bulbs n trailer plug
- replace hitch o ring
- fabricate new hold down mount
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	6.00
Pm-22-a Additive Dies	1.00
Non-chlor Brake Clnr	2.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Fuel Fil	1.00
Seal 2.250x3.371x.375	2.00
Grease Cap	2.00
Male Trailer Connector	1.00
Lt225/75r16/10 Iron All Country A/t	2.00
Napagold Oil Filter	1.00
Boxed Miniatures	2.00
Tow Ring	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 9.50

Comm: 0.00

Labor: 693.50

Parts: 350.15

Total: 1,043.65

10/25/2024
6:46:47 PM

Palm Beach County Fleet Management Asset Maintenance History
10196046 2014 LEBOY 400T Roller, Vibratory, 2.5 - 5 Ton

Work Order: 2203493 **Meter:** 1027 **In Date:** 03/30/2022 **Closed:** 06/23/2022

Problem: pm/ Leaking fluid from the bearings in the front wheel and front wheel is making clanging noise. Will bring in.

Work Completed

- pm service
- Replaced Male Trailer Plug
- Replaced Front Roller Bearing, disassy axle, shaft & replace all bearings
- Load Tested Battery, Replaced Battery
- Shop Supplies

Parts Issued

Quantity

Seal	4.00
Bearing Cup	4.00
Bearing Cone	4.00
Axle	1.00
Permatex	1.00
Battery	1.00
Seal 2.250x3.371x.375	2.00
Qt Hd40w	6.00
Napagold Oil Filter	1.00
Fuel Fil	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Grease Cap	2.00
Male Trailer Connector	1.00
Non-chlor Brake Clnr	4.00
Axle Machined Nut	1.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 21.00

Comm: 0.00

Labor: 1,533.00

Parts: 1,677.39

Total: 3,210.39

10/25/2024
6:46:48 PM

Palm Beach County Fleet Management Asset Maintenance History
10196046 2014 LEBOY 400T Roller, Vibratory, 2.5 - 5 Ton

Work Order: 2207821 **Meter:** 1047 **In Date:** 07/27/2022 **Closed:** 09/02/2022

Problem: Brakes/ tires locked up. Smoking when you try to move. Located at South County Regional Compound.

Work Completed

Parts Issued

Quantity

- Check Brakes Locked Up, Replaced Worn Brake Assemblies, Replaced
Burned Up Breakaway Wires And Breakaway Switch

Breakaway Switch

1.00

- Charged Battery, Load Test Failed, Replaced Battery, Checked Charging
System

brake 12x2 rh

1.00

brake 12x2 lh

1.00

Battery

1.00

- Shop Supplies

Shop Supplies

1.00

Hours: 6.00

Comm: 0.00

Labor: 438.00

Parts: 233.61

Total: 671.61

Work Order: 2209560 **Meter:** 1047 **In Date:** 09/14/2022 **Closed:** 09/21/2022

Problem: Please order a new locking fuel cap for this asset. The one on it isn't sealing properly...

Work Completed

Parts Issued

Quantity

- secure fuel cap for dept

Fuel Cap

1.00

- Shop Supplies

Shop Supplies

1.00

Hours: 0.50

Comm: 0.00

Labor: 36.50

Parts: 46.03

Total: 82.53

10/25/2024
6:46:48 PM

Palm Beach County Fleet Management Asset Maintenance History
10196046 2014 LEBOY 400T Roller, Vibratory, 2.5 - 5 Ton

Work Order: 2301566

Meter: 1107

In Date: 02/16/2023 **Closed:** 03/16/2023

Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Hydraulic Service
- Replace Trailer Plug And Strobe Light, Cut Seized Mounting Bolts
- Test Electrical System, Replace Battery
- Wash Roller
- Flush Lines And Clean Tips For Water System
- Shop Supplies

Parts Issued

Quantity

Napa Qt 15w40	6.00
Napagold Oil Filter	1.00
Fuel Fil	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Seal 2.250x3.371x.375	2.00
Corrosion-x Inhibitor 16oz	1.00
High Gloss Coating	1.00
Non-chlor Brake Clnr	3.00
Hyd/fil	1.00
Aw68 Hydro Fluid Hydr	10.00
Male Trailer Connector	1.00
Battery	1.00
strobe light	1.00
Permatex	1.00
Shop Supplies	1.00

Hours: 11.50

Comm: 0.00

Labor: 839.50

Parts: 431.54

Total: 1,271.04

10/25/2024
6:46:48 PM

Palm Beach County Fleet Management Asset Maintenance History
10196046 2014 LEBOY 400T Roller, Vibratory, 2.5 - 5 Ton

Work Order: 2310513 **Meter:** 1142 **In Date:** 10/18/2023 **Closed:** 10/31/2023
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Replaced Trailer Plug
- Replaced Missing Spraying Tips
- Replaced Breakaway Switch
- Replaced Seat Bottom
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Fuel Fil	1.00
Non-chlor Brake Clnr	3.00
Napa Qt 15w40	6.00
Seal 2.250x3.371x.375	2.00
Grease Cap	2.00
Trailer Wiring Connector	1.00
Breakaway Switch	1.00
Filter	1.00
Teejet Cap	2.00
Bottom Seat Cushion	1.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 8.50

Comm: 0.00

Labor: 620.50

Parts: 481.18

Total: 1,101.68

Work Order: 2400129 **Meter:** 1158 **In Date:** 01/05/2024 **Closed:** 01/26/2024
Problem: Cannot be started without having someone to press a button underneath of accelerator./ comments

Work Completed

- diagnose no start condition - replace neutral safety switch
- replace damaged toing parts
- Repair And Weld Cracked Towing Bar Pivots
- Shop Supplies

Parts Issued

Quantity

Neutral Safety Switch	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 5.50

Comm: 0.00

Labor: 401.50

Parts: 73.89

Total: 475.39

10/25/2024
6:46:48 PM

Palm Beach County Fleet Management Asset Maintenance History
10196046 2014 LEBOY 400T Roller, Vibratory, 2.5 - 5 Ton

Work Order: 2407845 **Meter:** 1169 **In Date:** 08/14/2024 **Closed:** 08/14/2024
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 291.00

Total Labor: 19,341.50

Total Comm: 1,262.99

Total Parts: 20,056.83