

5/8/2025  
4:12:52 PM

L00956

**Palm Beach County Fleet Management Asset Maintenance History**  
**2016 TORO GRNDSMASTR 7200 Mower, Zero Turn Radius (Ztr), 72in**

---

**Total Hours: 80.50    Labor: 5,550.00    Parts: 5,430.17    Comm: 0.00    Charged: 10980.17**

---

**Work Order:** 1600716      **Meter:** 1      **In Date:** 01/22/2016    **Closed:** 01/22/2016  
**Problem:** 1061 - Pre Delivery Inspection

**Work Completed**

- Pre Delivery Inspection

Hours: 2.00      Comm: 0.00      Labor: 120.00      Parts: 0.00      Total: 120.00

---

**Work Order:** 1608922      **Meter:** 309      **In Date:** 08/26/2016    **Closed:** 09/12/2016  
**Problem:** replace dmaged tire (tire only)

**Work Completed**

- Repair Tire  
- Shop Supplies

**Parts Issued**

**Quantity**

24x12x12 6 Ply Kenda	1.00
24x12.00-12 Turf Trac 6p Tire	1.00
Shop Supplies	1.00
Tire Disposal Fee	0.00

Hours: 1.00      Comm: 0.00      Labor: 60.00      Parts: 393.34      Total: 453.34

---

**Work Order:** 1612940      **Meter:** 460      **In Date:** 12/19/2016    **Closed:** 12/28/2016  
**Problem:** pm/ alternator belt came

**Work Completed**

- Pm  
- Hyd Service  
- R/r right caster tire to change out bent rim and plug tire  
- Reinstall fan belt and test run  
- Disassemble r/tail lamp o reistall loose wires  
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Air Filter	1.00
Napagold Oil Filter	1.00
15-40 Oil	4.00
Napa Hydraulic Filtr	1.00
Spin On Filter	1.00
Service Wheel	1.00
Shop Supplies	1.00

Hours: 7.50      Comm: 0.00      Labor: 450.00      Parts: 240.91      Total: 690.91

5/8/2025  
4:12:52 PM

L00956

**Palm Beach County Fleet Management Asset Maintenance History**  
**2016 TORO GRNDSMASTR 7200 Mower, Zero Turn Radius (Ztr), 72in**

---

**Work Order:** 1710021      **Meter:** 691      **In Date:** 10/12/2017      **Closed:** 10/24/2017

**Problem:** struck object and cut wires/ no start

**Work Completed**

- Build new wir harness and repair cables to battery
- Shop Supplies

Hours: 3.00

Comm: 0.00

**Parts Issued**

	<b>Quantity</b>
Primary Wire	1.00
Shop Supplies	1.00
Labor: 180.00	Parts: 8.48
Total: 188.48	

---

**Work Order:** 1803582      **Meter:** 766      **In Date:** 04/04/2018      **Closed:** 04/17/2018

**Problem:** pm service

**Work Completed**

- pm service
- hydraulic service
- replace blown fuse and 4 bulbs, repair broken ground wire
- Shop Supplies

Hours: 6.00

Comm: 0.00

**Parts Issued**

	<b>Quantity</b>
Napagold Air Filter	1.00
Napagold Oil Filter	1.00
15-40 Oil	4.00
Spin On Filter	1.00
Pm-22-a Additive Dies	1.00
Non-chlor Brake Clnr	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	3.00
Bulb	2.00
Bulb	2.00
Shop Supplies	1.00
Labor: 360.00	Parts: 92.59
Total: 452.59	

---

**Work Order:** 1808947      **Meter:** 900      **In Date:** 08/29/2018      **Closed:** 08/31/2018

**Problem:** flat tire (tire only)

**Work Completed**

- replace 1 tire
- Shop Supplies

Hours: 1.00

Comm: 0.00

**Parts Issued**

	<b>Quantity</b>
15-600-6 Nhs Str Rib 04	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00
Labor: 60.00	Parts: 40.39
Total: 100.39	



5/8/2025  
4:12:52 PM

L00956

**Palm Beach County Fleet Management Asset Maintenance History**  
**2016 TORO GRNDSMASTR 7200 Mower, Zero Turn Radius (Ztr), 72in**

---

**Work Order:** 1906607      **Meter:** 1021      **In Date:** 06/24/2019      **Closed:** 06/28/2019

**Problem:** dead battery/ hydraulic leak

**Work Completed**

- test and replace battery
- wash equipment
- replace hydraulic line add fluid and test run
- Shop Supplies

**Parts Issued**

**Quantity**

Battery	1.00
Aw68 Hydro Fluid Hydr	3.00
Mako Hose & Fittings	1.00
Non-chlor Brake Clnr	1.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 268.00

Parts: 217.20

Total: 485.20

---

**Work Order:** 2005599      **Meter:** 1146      **In Date:** 06/04/2020      **Closed:** 06/23/2020

**Problem:** pm/ deck adjustment/ see note

**Work Completed**

- pm service
- replace left front tire
- replace 2 bulbs, repair tangs in light housings
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Air Filter	1.00
Napagold Oil Filter	1.00
Spin On Filter	1.00
15-40 Oil	4.00
Boxed Miniatures	2.00
15x6.00-6	1.00
Shop Supplies	1.00

Hours: 6.00

Comm: 0.00

Labor: 438.00

Parts: 98.65

Total: 536.65

---

**Work Order:** 2103835      **Meter:** 1171      **In Date:** 04/05/2021      **Closed:** 04/06/2021

**Problem:** Replace tire (Tire Only)

**Work Completed**

- Replace Tire
- Shop Supplies

**Parts Issued**

**Quantity**

15x6.00-6	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 41.46

Total: 114.46

5/8/2025  
4:12:52 PM

L00956

**Palm Beach County Fleet Management Asset Maintenance History**  
**2016 TORO GRNDSMASTR 7200 Mower, Zero Turn Radius (Ztr), 72in**

---

**Work Order:** 2103838      **Meter:** 0      **In Date:** 04/05/2021      **Closed:** 04/07/2021  
**Problem:** Hour meter isn't working.

**Work Completed**

- Inspect Hour Meter, Test Circuit And Replace Faulty Hour Meter
- Shop Supplies

Hours: 1.00

Comm: 0.00

**Parts Issued**

	<b>Quantity</b>
Hour Meter	1.00
Shop Supplies	1.00

Labor: 73.00      Parts: 102.18      Total: 175.18

---

**Work Order:** 2107688      **Meter:** 38      **In Date:** 07/14/2021      **Closed:** 08/10/2021  
**Problem:** PM Service. plus spare tire on machine

**Work Completed**

- Preventive Maint. Service
- replace 2 spare tires on rims. Replace left rear tire
- Tire And Wheel Assembly For Customer Request.
- Replace Right Side Light Bulb.
- Shop Supplies

Hours: 7.50

Comm: 0.00

**Parts Issued**

	<b>Quantity</b>
Napa Qt 15w40	4.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	2.00
Spacer	2.00
Seal	6.00
Bearing	6.00
24x12.00-12 Toro 6 Ply	1.00
1cart Palladium 2 Grs	1.00
Tire & Wheel Assy	2.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Labor: 547.50      Parts: 741.66      Total: 1,289.16

5/8/2025  
4:12:52 PM

L00956

**Palm Beach County Fleet Management Asset Maintenance History**  
**2016 TORO GRNDSMASTR 7200 Mower, Zero Turn Radius (Ztr), 72in**

---

**Work Order:** 2109932      **Meter:** 61      **In Date:** 09/14/2021      **Closed:** 10/19/2021

**Problem:** PTO Gear Box Bushings are wore out so gear box shakes bad when PTO is engaged

**Work Completed**

- Replace Three Mounts And Carriage Bolts
- Replace Both Belt Tensioners And Belts
- Shop Supplies

**Parts Issued**

**Quantity**

Bolt	3.00
Rubber Mount	3.00
Belt	1.00
Belt	1.00
Torsion Spring	2.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 219.00

Parts: 235.91

Total: 454.91

---

**Work Order:** 2112349      **Meter:** 94      **In Date:** 11/18/2021      **Closed:** 11/19/2021

**Problem:** Tire needs to be repaired, wont hold air and rim has small dent by beading area.

**Work Completed**

- Repair Tire
- Shop Supplies

**Parts Issued**

**Quantity**

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

5/8/2025  
4:12:52 PM

L00956

**Palm Beach County Fleet Management Asset Maintenance History**  
**2016 TORO GRNDSMASTR 7200 Mower, Zero Turn Radius (Ztr), 72in**

**Work Order:** 2207518

**Meter:** 313

**In Date:** 07/19/2022 **Closed:** 09/13/2022

**Problem:** pm/ Hydraulic leak and "other issue" under deck related to the blades.

**Work Completed**

- Preventive Maint. Service
- Replace Front Tires
- Service Hydraulic
- Fuel Leak From Filter Housing
- Cutting Blade Bolt Loose. Replace Lower Driven Spindle Assy And Bolts
- Replace Gear Box Mounting Bushing
- Replace Deck Belts
- Replace Left Side 1157 And 1156 Bulb
- Shop Supplies

**Parts Issued**

**Quantity**

Napa Qt 15w40	4.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	2.00
15-600-6 Nhs Str Rib 04	2.00
Caster Wheel Bearing Kit	4.00
Aw68 Hydro Fluid Hydr	4.00
Napa Hydraulic Filtr	1.00
Blade Bolt	3.00
Fuel Seperator/housing	1.00
Rubber Mount	3.00
Belt	1.00
Belt	1.00
Gearbox Bracket Rh	1.00
Gearbox Bracket Lh	1.00
Low Driven Spindle Asm	1.00
Fitting	2.00
Boxed Miniatures	1.00
Boxed Miniatures	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00
Freight Charge	1.00

Hours: 16.00

Comm: 0.00

Labor: 1,168.00

Parts: 1,393.05

Total: 2,561.05

5/8/2025  
4:12:52 PM

L00956

**Palm Beach County Fleet Management Asset Maintenance History**  
**2016 TORO GRNDSMASTR 7200 Mower, Zero Turn Radius (Ztr), 72in**

---

**Work Order:** 2304444      **Meter:** 337      **In Date:** 05/03/2023      **Closed:** 05/04/2023

**Problem:** Rear tire needs to be replaced, worn and has holes in side wall. Dropping off today.

**Work Completed**

**Parts Issued**

**Quantity**

- replace tire (tire only)
- Shop Supplies

24x12x12 6 Ply Kenda	1.00
Shop Supplies	1.00

Hours: 1.00      Comm: 0.00      Labor: 73.00      Parts: 178.67      Total: 251.67

---

**Work Order:** 2306634      **Meter:** 337      **In Date:** 07/06/2023      **Closed:** 07/07/2023

**Problem:** TIRE ONLY replace tire, check bearings, install missing valve stem.

**Work Completed**

**Parts Issued**

**Quantity**

- Replaced Bearings, Races, And Seals
- Replaced Tire
- Shop Supplies

Seal	2.00
Bearing - Race	2.00
Bearing	2.00
15-600-6 Nhs Str Rib 04	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 2.00      Comm: 0.00      Labor: 146.00      Parts: 103.96      Total: 249.96

---

**Work Order:** 2306875      **Meter:** 337      **In Date:** 07/12/2023      **Closed:** 07/12/2023

**Problem:** tire only

**Work Completed**

**Parts Issued**

**Quantity**

- Repaired Leaking Tire
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00      Comm: 0.00      Labor: 73.00      Parts: 2.65      Total: 75.65

5/8/2025  
4:12:52 PM

**L00956 Palm Beach County Fleet Management Asset Maintenance History  
2016 TORO GRNDSMASTR 7200 Mower, Zero Turn Radius (Ztr), 72in**

**Work Order:** 2312189      **Meter:** 407      **In Date:** 12/07/2023      **Closed:** 01/08/2024  
**Problem:** PM Service. Inspect all tires and rims, inspect bearings in front wheels, right hydraulic arm felt jumpy when using.

**Work Completed**

**Parts Issued**

**Quantity**

- Preventive Maint. Service
- Test Electrical System, Replace Battery
- Ck Blades Do Not Engauge. Replace Pto Switch, Seat Switch Was Bypassed, Reconnect Harness To Switch
- Replace Front Tire And Wheel Assembly, Bearings, And Seals
- Wash Mower
- Shop Supplies

Prem Blue 15w40 1 Gal	1.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Pm-22-a Additive Dies	1.00
Non-chlor Brake Clnr	2.00
Battery	1.00
Pto Switch	1.00
15-6.00x6 Ribbed Tire	2.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 9.00

Comm: 0.00

Labor: 657.00

Parts: 1,092.32

Total: 1,749.32

**Work Order:** 2402859      **Meter:** 442      **In Date:** 03/20/2024      **Closed:** 04/04/2024  
**Problem:** PTO works intermittently. Also fix seat sensor had to bypass to load on trailer.

**Work Completed**

**Parts Issued**

**Quantity**

- Replace Pto Switch, And Reconnect Seat Switch Connector, Lube Mower
- Shop Supplies

Pto Switch	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 1.50

Comm: 0.00

Labor: 109.50

Parts: 54.01

Total: 163.51

**Total Hours: 80.50**

**Total Labor: 5,550.00**

**Total Comm: 0.00**

**Total Parts: 5,430.17**