

5/8/2025
4:13:19 PM

L00957

Palm Beach County Fleet Management Asset Maintenance History
2016 TORO GRNDSMASTR 7200 Mower, Zero Turn Radius (Ztr), 72in

Total Hours: 98.00 Labor: 6,788.50 Parts: 14,080.20 Comm: 0.00 Charged: 20868.70

Work Order: 1600717 **Meter:** 1 **In Date:** 01/22/2016 **Closed:** 01/22/2016
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1612584 **Meter:** 125 **In Date:** 12/08/2016 **Closed:** 12/20/2016
Problem: flat tire (tire Only)

Work Completed

- Repair Tire
- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1701274 **Meter:** 144 **In Date:** 02/07/2017 **Closed:** 02/22/2017
Problem: pm/ noise in left spindle

Work Completed

- Pm
- Hyd Service
- Replace damaged spindle assembly
- Clean and adjust rear brakes
- Disassemble left tail lamp and reinstall loose wires
- Shop Supplies

Parts Issued	Quantity
Napagold Oil Filter	1.00
15-40 Oil	4.00
Napagold Air Filter	1.00
Spin On Filter	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	3.00
Spindle Shaft Assy	1.00
Spacer,spindle Shaft	1.00
Nut	1.00
Spindle Housing Assy	1.00
Washer	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 8.00 Comm: 0.00 Labor: 480.00 Parts: 493.73 Total: 973.73

5/8/2025
4:13:19 PM

L00957

Palm Beach County Fleet Management Asset Maintenance History
2016 TORO GRNDSMASTR 7200 Mower, Zero Turn Radius (Ztr), 72in

Work Order: 1704157 **Meter:** 164 **In Date:** 04/25/2017 **Closed:** 04/28/2017
Problem: adjust deck / replace front roller

Work Completed

Parts Issued

Quantity

- Replace front roller and shaft
- Adjust and Level deck and test run
- Shop Supplies

Roller	1.00
Shaft,roller	1.00
Shop Supplies	1.00

Hours: 2.50

Comm: 0.00

Labor: 150.00

Parts: 107.72

Total: 257.72

Work Order: 1802077 **Meter:** 298 **In Date:** 02/23/2018 **Closed:** 02/28/2018
Problem: replace tire (tire only)

Work Completed

Parts Issued

Quantity

- R&r Tire
- Shop Supplies

24x12x12 6 Ply Kenda	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 224.72

Total: 284.72

5/8/2025
4:13:19 PM

L00957

Palm Beach County Fleet Management Asset Maintenance History
2016 TORO GRNDSMASTR 7200 Mower, Zero Turn Radius (Ztr), 72in

Work Order: 1803672 **Meter:** 318 **In Date:** 04/06/2018 **Closed:** 04/23/2018

Problem: pm/ canopy bolts

Work Completed

- pm service
- hydraulic service
- replace all turn signal bulbs
- replace u bolts on canopy
- replace left rear tire
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Oil Filter	1.00
15-40 Oil	4.00
Napagold Fuel Filter	1.00
Pm-22-a Additive Dies	1.00
Non-chlor Brake Clnr	1.00
Atf Plus 4	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	3.00
Boxed Miniatures	2.00
Boxed Miniatures	2.00
U Bolts	2.00
Flange Nut Ni	2.00
24x12x12 6 Ply Kenda	1.00
Shop Supplies	1.00

Hours: 8.00

Comm: 0.00

Labor: 480.00

Parts: 323.59

Total: 803.59

Work Order: 1807344

Meter: 377

In Date: 07/19/2018 **Closed:** 07/23/2018

Problem: replace tire (tire only)

Work Completed

- replace tire
- Shop Supplies

Parts Issued

Quantity

Tir-000	1.00
24x12x12 6 Ply Kenda	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 238.29

Total: 298.29

5/8/2025
4:13:19 PM

L00957

Palm Beach County Fleet Management Asset Maintenance History
2016 TORO GRNDSMASTR 7200 Mower, Zero Turn Radius (Ztr), 72in

Work Order: 2006042 **Meter:** 693 **In Date:** 06/17/2020 **Closed:** 07/07/2020
Problem: pm/ left spindle/ P brake/ AF housing/ RR tire leak

Work Completed

- pm service
- replace 2 deck belts
- replace damaged air box assy
- replace left and right spindle assy
- Replace r/r tire
- hydraulic service
- wash grass and dirt from engine bay and unit
- clean and adjust brakes
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	4.00
Napagold Fuel Filter	1.00
Atf Plus 4	1.00
Pm-22-a Additive Dies	1.00
Non-chlor Brake Clnr	2.00
Fhp Bladerunner Belt	1.00
Air Cleaner Assy	1.00
24x12.00-12 Toro 6 Ply	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	4.00
Bladerunner Belt	1.00
Low Driven Spindle Assy	1.00
High Driven Spindle Assy	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 13.50

Comm: 0.00

Labor: 985.50

Parts: 2,028.51

Total: 3,014.01

Work Order: 2011115 **Meter:** 794 **In Date:** 11/03/2020 **Closed:** 11/18/2020
Problem: Will not run Had a melted fuse inside the fuse box/ see comments

Work Completed

- Fabricate Mounting Brackets, Install Pedestal Lamp Assemblies, Rewire Harness And Mount Spot Light.
- Check Wont Start. Replace Battery, And Test Charging System.
- Clean And Check Connections On Fuse Panel, Replace All Fuses, Ck Grounds And Connections
- Shop Supplies

Parts Issued

Quantity

Ss Led Sf Ped Lamp	2.00
Ss Led Df Ped Lamp	2.00
Battery	1.00
Fab Loom-split Poly	3.00
Electrical Tape	1.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 657.00

Parts: 330.76

Total: 987.76

5/8/2025
4:13:19 PM

L00957

Palm Beach County Fleet Management Asset Maintenance History
2016 TORO GRNDSMASTR 7200 Mower, Zero Turn Radius (Ztr), 72in

Work Order: 2108650

Meter: 866

In Date: 08/10/2021 **Closed:** 09/13/2021

Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Replace left rear tire
- Replace alternator belt
- Replace missing throttle knob,seat hardware
- Replace both front caster tire/wheel asm.
- Replace broken air cleaner cover
- Shop Supplies

Parts Issued

Quantity

Napa Qt 15w40	4.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Pm-22-a Additive Dies	1.00
24x12.00-12 Toro 6 Ply	1.00
15-6.00x6 Ribbed Tire	2.00
V-belt	1.00
Knob	1.00
Pin Hair	1.00
Clevis Pin	1.00
Air Cleaner Cover Assy	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00
Freight Charge	1.00

Hours: 9.00

Comm: 0.00

Labor: 657.00

Parts: 942.89

Total: 1,599.89

5/8/2025
4:13:19 PM

L00957

Palm Beach County Fleet Management Asset Maintenance History
2016 TORO GRNDSMASTR 7200 Mower, Zero Turn Radius (Ztr), 72in

Work Order: 2204593

Meter: 941

In Date: 04/28/2022 **Closed:** 07/11/2022

Problem: PTO gear box came undone and broke parts needs repair.

Work Completed

Parts Issued

Quantity

- Remove Driveshaft, Try To Free Up Slip Yoke (frozen Beyond Repair), Install New Driveshaft And Grease.

Idler Pulley 1.00

Pulley 1.00

- Replace Gearbox, Pulley, Keeper, Bracket, And Mounts

Belt 1.00

- Replace Damaged Deck Belts

Pulley 1.00

- Replace Both Damaged Tensioner Pulleys

set screw 2.00

- Shop Supplies

Bushing 1.00

Gearbox 1.00

Screw 4.00

Bolt 3.00

Gearbox Bracket Lh 1.00

Rubber Mount 3.00

Roll Pin 1.00

Belt 1.00

Driveshaft 1.00

Shop Supplies 1.00

Freight Charge 1.00

Freight Charge 1.00

Hours: 6.50

Comm: 0.00

Labor: 474.50

Parts: 2,360.77

Total: 2,835.27

5/8/2025
4:13:19 PM

L00957

Palm Beach County Fleet Management Asset Maintenance History
2016 TORO GRNDSMASTR 7200 Mower, Zero Turn Radius (Ztr), 72in

Work Order: 2207664

Meter: 982

In Date: 07/22/2022 **Closed:** 09/27/2022

Problem: Broken wheel bearing in front tire/ pm

Work Completed

- Broken Wheel Bearing In Front Tire, Replaced Worn Caster Bearings And Seals On Both Sides, Replaced Both Tire/wheel Assemblies With Bearings And Seals
- Diagnos Won't Stay Running After Start, Test All Safety Switch Circuits, Test Inputs And Outputs To Scm Module, Replaced Faulty Scm Module
- Pm Service
- Shop Supplies

Parts Issued

Quantity

Control Module Assy	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	1.00
1cart Palladium 2 Grs	1.00
15-40 Oil	4.00
Napagold Oil Filter	1.00
Bearing Cup	4.00
Bearing	4.00
15-6.00x6 Ribbed Tire	2.00
Caster Fork	1.00
Seal	2.00
Washer - Belleville	6.00
Nut	2.00
Grease Cap	2.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 9.50

Comm: 0.00

Labor: 693.50

Parts: 1,767.06

Total: 2,460.56

5/8/2025
4:13:19 PM

L00957

Palm Beach County Fleet Management Asset Maintenance History
2016 TORO GRNDSMASTR 7200 Mower, Zero Turn Radius (Ztr), 72in

Work Order: 2312191

Meter: 1111

In Date: 12/07/2023 **Closed:** 01/10/2024

Problem: PM Service. Inspect all rims and tires , FR & RR & LR tires were all flat.

Work Completed

- Preventive Maint. Service
- Replace Left Rear Tire
- Replace Both Front Caster Wheel Assemblies
- Replace Weak Battery
- Replace 3 Blades
- Install New Pto Gearbox With Mounts
- Shop Supplies

Parts Issued

Quantity

Napa Qt 15w40	4.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
24x12.00-12 Toro 6 Ply	1.00
Seal	4.00
Spacer	4.00
Bearing	4.00
Battery	1.00
Front Caster Spacer	2.00
15-6.00x6 Ribbed Tire	2.00
Blade-flat	3.00
Rubber Mount	3.00
Screw	4.00
Gearbox	1.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 11.00

Comm: 0.00

Labor: 803.00

Parts: 2,562.81

Total: 3,365.81

Work Order: 2401124

Meter: 1111

In Date: 01/31/2024 **Closed:** 02/02/2024

Problem: * TIRE ONLY * 1 Rear tire needs to be replaced.

Work Completed

- Replace Tire
- Shop Supplies

Parts Issued

Quantity

Turf Tread 24x12x12	1.00
Shop Supplies	1.00

5/8/2025
4:13:19 PM

L00957

Palm Beach County Fleet Management Asset Maintenance History
2016 TORO GRNDSMASTR 7200 Mower, Zero Turn Radius (Ztr), 72in

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 231.95

Total: 304.95

Total Hours: 98.00

Total Labor: 6,788.50

Total Comm: 0.00

Total Parts: 14,080.20