



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10196874

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V69299

In Date: 09/11/2014
Close Date: 10/16/2014

Meter Reading: 1,377.00

Problem?

B inspection R37, setup new vehicle

Task performed:

1. B Inspection.
2. Finish B inspection. Had to move vehicle to another bay. No hoists.
3. Repair and replace R/S exhaust manifold heatshield in order to reposition cooling system water pipe, causing heater hose to rub on chassis.
4. New vehicle set up.
5. New vehicle set up and mount equipment.
6. New vehicle set up and mount equipment.
7. New vehicle set up and mount equipment.
8. New vehicle set up and mount equipment.
9. Install 3 number frames. Install OOS decals.

Parts	Quantity
5269LPVM-5 SM MOUNT	6
LPVM-7LG MOUNT	6
6092036018J HOOK STRYKER	1
FHLP-6TANK CLIP	6
56415CIG. LIGHTER ACCES.	2
1884207C92FUEL FILTER MAXFORCE 7	1
UMVS162511STRAP	3
UMVS111611STRAP	1
SAHSVS2510STRAP	1
14-7014HGR-1 HELMET HOOK	6
L PLACARDLARGE SIDE PLACARD	2
S PLACARDFRONT AND BACK PLACARD	1

Workorder: V70511

In Date: 10/28/2014
Close Date: 11/06/2014

Meter Reading: 1,377.00

Problem?

adjust rear suspension

Task performed:

1. Remove stop to air dump on rear suspension and redrill hole to make it drop further.

Parts	Quantity
NO PARTS USED	



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10196874

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V71045

In Date: 11/18/2014
Close Date: 11/19/2014

Meter Reading: 3,041.00

Problem?
no power

Task performed:

Parts

Quantity

Preformed regen and road tested truck

NO PARTS USED

Workorder: V71461

In Date: 12/07/2014
Close Date: 12/24/2014

Meter Reading: 4,576.00

Problem?
check engine light is on also when driving gears do not shift until high rpm is reach.

Task performed:

Parts

Quantity

1. Check engine light is on and will need to go to International for repairs.

NO PARTS USED

2. Road tested to check shifting and shifted OK at this time (normal).

Workorder: V71702

In Date: 12/16/2014
Close Date: 01/07/2015

Meter Reading: 5,449.00

Problem?
R54 regen needed

Task performed:

Parts

Quantity

Performed forced regen and road tested

NO PARTS USED

Workorder: V71723

In Date: 12/17/2014
Close Date: 01/07/2015

Meter Reading: 5,449.00

Problem?
check engine light is on and stays on.

Task performed:

Parts

Quantity

Truck will need to go to international for repairs due to code

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10196874

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V71763

In Date: 12/19/2014
Close Date: 01/07/2015

Meter Reading: 5,099.50

Problem?

Truck check light engine came in. Attempted to do 'park regen' and was unable to accomplish. Tommy came into the station to complete the process.

Task performed:

Parts

Quantity

1. Performed forced regen and road tested
2. Repaired air leak in rear

NO PARTS USED

Workorder: V72025

In Date: 01/04/2015
Close Date: 01/20/2015

Meter Reading:

Problem?

check engine light on

Task performed:

Parts

Quantity

Truck needs to go to International for repair.

NO PARTS USED

Workorder: V72575

In Date: 01/24/2015
Close Date: 01/27/2015

Meter Reading:

Problem?

Siren not working on R54

Task performed:

Parts

Quantity

1. Siren inoperable. Connector loose. Repaired connector.
2. L-2 compartment won't open. Rod came off. Repaired L-2 compartment.

NO PARTS USED

Workorder: V72510

In Date: 01/21/2015
Close Date: 02/05/2015

Meter Reading:

Problem?

Driver's Compartment Door (#2) is stuck closed. Door sensor is also giving a false reading (Compartment #2 Open). There is limit access to the equipment compartment which can cause a delay on scene

Task performed:

Parts

Quantity

Readjusted door latch and tested.

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10196874

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V72659

In Date: 01/27/2015
Close Date: 02/11/2015

Meter Reading:

Problem?

L2 compartment door was fixed but sensor needs replaced as it keeps going off.t

Task performed:

Parts

Quantity

Removed and repaired door sensor.

NO PARTS USED

Workorder: V72668

In Date: 01/28/2015
Close Date: 02/11/2015

Meter Reading:

Problem?

3 engine lights are on. upside down triangle, engine, wrench

Task performed:

Parts

Quantity

Performed regen and road tested.

NO PARTS USED

Workorder: V71722

In Date: 12/17/2014
Close Date: 02/18/2015

Meter Reading:

Problem?

SCBA bracket on the Driver's side compartment.

Task performed:

Parts

Quantity

1. Mounted bracket for trip tic.
2. Installed air packbracket on L-1 door.

NO PARTS USED

Workorder: V72974

In Date: 02/09/2015
Close Date: 02/18/2015

Meter Reading: 10,290.00

Problem?

regin needed

Task performed:

Parts

Quantity

Performed regen and road tested.

NO PARTS USED



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10196874

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V73200

In Date: 02/17/2015
Close Date: 02/23/2015

Meter Reading: 11,164.00

Problem?

check engine light on

Task performed:

Performed regen and road tested.

Parts

NO PARTS USED

Quantity

Workorder: V73556

In Date: 03/02/2015
Close Date: 04/02/2015

Meter Reading: 12,364.00

Problem?

C inspection R54

Task performed:

1. C Inspection.
2. C inspection and repairs. Remove and replace wheel valve estentions. Remove and clean up engine air filter housing.
3. Remove and repair rear camara mounting braket. Service air dryer.
4. Q& A Inspection.
5. Tighten all cap brab handles. R&R all mounting bolts to apply lock tite.

Parts

- 1884207C92FUEL FILTER MAXFORCE 7
- 3839141C1FILTER CAB AIR
- 1899332C91OIL FILTER MAXFORCE 7
- 2602212C1PRIMARY AIR FILTER 4300M7
- 065624AD-IP DRIER
- K022105PURGE VALVE AD-IP-IS

Quantity

- 1
- 1
- 1
- 1
- 1
- 1

Workorder: V74215

In Date: 03/26/2015
Close Date: 04/22/2015

Meter Reading:

Problem?

MAIN O2 PRESSURE GAGE IS BROKEN.

Task performed:

1. Replace gauge.

Parts

MG-C23SPMGC23 GAUGE

Quantity

- 1

Workorder: V73528

In Date: 02/28/2015
Close Date: 04/24/2015

Meter Reading:

Problem?

Interior of cab is leaking water when it rains from the molding near the door open light. Assumption is light bar was not properly sealed and water is leaking through gaskets. into the interior of the cab.

Task performed:

1. Resealed top off roof.

Parts

NO PARTS USED

Quantity



10/17/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10196874

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V74056

In Date: 03/20/2015

Meter Reading: 13,367.00

Close Date: 04/24/2015

Problem?

Check engine light on

Task performed:

Parts

Quantity

1. Trouble shot check engine light on. Found code for DPF 3154-21. Went through trouble shoot procedure outlined in ISIS. Truck passed all laptop and visual test. Cleared code and road tested. Code did not return.

NO PARTS USED



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10196874) 2014 - INTERNATIONAL HORTON Advanced Life Support Vehicle Ssr5

10196874

CSHOP-2015-1020

Date Opened 6-5-2015 Date Finished 6-8-2015 Meter 1 Reading: 18,920

TASKS PERFORMED

NO PARTS USED

FAULT CODE

CSHOP-2015-1080

Date Opened 6-8-2015 Date Finished 6-16-2015 Meter 1 Reading: 18,930

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES

CSHOP-2015-1195

Comments: SHORELINE GETTING HOT AND SMOKES WHEN PLUGGED IN R54

Date Opened 6-15-2015 Date Finished 6-22-2015 Meter 1 Reading: 18,950

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FAULT CODE
CHARGING SYSTEM

4 CONNECTOR; 1PGK4 CONNECTOR 120V 20A FEMALE

CSHOP-2015-1219

Comments: FRONT TIRES BALD R54

Date Opened 6-16-2015 Date Finished 6-22-2015 Meter 1 Reading: 18,940

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FRONT TIRES
INSTRUMENTS-GAUGES-METERS
HVAC SYSTEM

CSHOP-2015-1341

Comments: FRONT TIRES WORN PLEASE INSPECT R54

Date Opened 6-23-2015 Date Finished 7-27-2015 Meter 1 Reading: 18,950

TASKS PERFORMED

NO PARTS USED

FRONT TIRES
SUSPENSION

Asset Work Order History 10196874

CSHOP-2015-1564

Comments: **R54 ELECTRONIC DOOR LOCKS NOT WORKING AND SHORE A/C INOP**
Date Opened 7-6-2015 Date Finished 7-30-2015 Meter 1 Reading: 18,950

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FAULT CODE
DOOR LOCKS
HVAC SYSTEM

CSHOP-2015-2160

Comments: **REPLACE TIRE**
Date Opened 8-5-2015 Date Finished 8-5-2015 Meter 1 Reading: 18,950

TASKS PERFORMED

NO PARTS USED

TIRE
VENDOR? ELPEX TIRE TIRESOLES

CSHOP-2015-2207

Comments: **AC PROBLEM R54 SHORELINE AC NOT COLD**
Date Opened 8-7-2015 Date Finished 9-30-2015 Meter 1 Reading: 24,762

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
TOWING HITCH
CATALYTIC CONVERTER
LIGHTING SYSTEM
DIAGNOSE ELECTRICAL
HOSE-LINES & FITTINGS
HVAC SYSTEM

1	EXHAUST; 2594131C91 DPF V8
1	HANDLE; HANDLE LH HORTON

CSHOP-2015-2643

Comments: **CHECK ENG LT ON NO POWER R 54**
Date Opened 9-1-2015 Date Finished 9-2-2015 Meter 1 Reading: 18,950

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES

CSHOP-2015-3072

Comments: **R54 B INSPECTION**
Date Opened 9-24-2015 Date Finished 9-29-2015 Meter 1 Reading: 24,762

TASKS PERFORMED

Q PARTS

PM SERVICE B

1	FILTER; OIL FILTER MAXFORCE 7
22	FLUID; SYN OIL BULK QTS
1	FILTER; FILTER CAB AIR
1	FILTER; FUEL FILTER MAXFORCE 7

Asset Work Order History 10196874

CSHOP-2015-3073

Comments: **REPAIRS FROM PM**

Date Opened 9-24-2015 Date Finished 10-6-2015 Meter 1 Reading: 25,169

PUMP DOWN LEAK TEST AND CHARGE SYSTEM AND TEST.

TASKS PERFORMED

Q PARTS

BATTERY	3	BATTERY; BATTERY 950CCA HP-31D
WIRING	3	BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
TIRE	1	FILTER; CAB FILTER RED DOT
HEAD LINER	1	DRYER; 07-0602A DRIER A/C 7118
SEAT FRONT		
CABIN AIR FILTER		
HOSE-LINES & FITTINGS		
DRYER-ACCUMULATOR		
CONDENSER		
EVACUATE AND RECHARGE		

CSHOP-2015-3203

Comments: **R54 CHECK REAR TIRES**

Date Opened 10-2-2015 Date Finished 10-6-2015 Meter 1 Reading: 25,169

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? EARL COLVARD BOULEVARD TIRE

Service Requests:

10/02/2015 TIRES / 44: WORN / EXCHANGE - NEW
REAR EXTERNAL TIRES DOWN TO THE WEAR BAR

CSHOP-2015-3302

Comments: **R54 DRIVERS SIDE SCENE LIGHT OUT EMSAR WILL GET THERE MONDAY 10-12**

Date Opened 10-8-2015 Date Finished 10-28-2015 Meter 1 Reading: 26,900

TASKS PERFORMED

NO PARTS USED

CAB-INTERIOR ACCESSORIES

Service Requests:

10/25/2015 LIGHTS / 19: LOOSE / REPAIR
THE DRIVER SIDE REAR SCENE LIGHT IS NOT WORKING.

10/07/2015 SERVICE REQUEST / 19: LOOSE / REPAIR
R54 STRETCHER (ASSET NUMBER 10195334) IS DRAINING THE BATTERY WHEN IT IS NOT BEING USED. WHILE THE STRETCHER IS IN THE TRUCK THE BATTERY REMAINS ON.

Asset Work Order History 10196874

CSHOP-2015-3358

Comments: **R54**

Date Opened 10-13-2015 Date Finished 10-14-2015 Meter 1 Reading: 25,976

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

10/11/2015 AIR RIDE / 18: LEAKING / REPAIR
AIR DUMP VALVE HAS A EAR PIERCING HIGH PITCHED BLOOD CURDLING SOUND WHEN IT DUMPS.

CSHOP-2015-3534

Comments: **R54 CAB BOOT LEAKING**

Date Opened 10-21-2015 Date Finished 10-21-2015 Meter 1 Reading: 26,431

TASKS PERFORMED

NO PARTS USED

CAB-INTERIOR ACCESSORIES

Service Requests:

10/21/2015 BODY / 19: LOOSE / ADJUST
RUBBER SEAL BETWEEN CAB AND PATIENT COMPARTMENT BROKEN (LEAKING)

CSHOP-2015-3756

Comments: **R54 REAR LEFT DOME LIGHT IS OUT**

Date Opened 11-3-2015 Date Finished 11-18-2015 Meter 1 Reading: 28,940

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

CSHOP-2015-4035

Comments: **R54 CHECK ENGINE LIGHT**

Date Opened 11-18-2015 Date Finished 12-8-2015 Meter 1 Reading: 30,024

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM

Service Requests:

11/03/2015 LIGHTS / 18: LEAKING / REPAIR
REAR LEFT DOME LIGHT IS OUT.

CSHOP-2015-4330

Comments: **R54**

Date Opened 12-7-2015 Date Finished 12-14-2015 Meter 1 Reading: 30,585

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Asset Work Order History 10196874

CSHOP-2015-4472

Comments: **R54 PAT A/C BLOWER MAKING NOISE AND EMER LIGHTS OUT**

Date Opened 12-14-2015 Date Finished 12-15-2015 Meter 1 Reading: 30,696

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

12/06/2015 A/C / 19: LOOSE / REPAIR
THE AIR CONDITIONER IN THE PATIENT CARE AREA IS MAKING A RATTLING NOISE.

12/11/2015 LIGHTS / 19: LOOSE / REPAIR
HALF OF THE RED EMERGENCY LIGHT ABOVE THE DRIVERS SIDE REAR TIRE NOT WORKING

CSHOP-2015-518

Comments: **CHECK ENGINE LIGHT ON R54**

Date Opened 5-8-2015 Date Finished 5-19-2015 Meter 1 Reading: 15,930

TASKS PERFORMED

NO PARTS USED

FAULT CODE
HVAC SYSTEM

CSHOP-2015-780

Comments: **R-54 ENGINE WARNING LIGHTS ON SLOW TAKE OFF WITH SPATTERING**

Date Opened 5-26-2015 Date Finished 6-2-2015 Meter 1 Reading: 18,916

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR ALARM OR OTHER WARNING

1	GASKET; DPF GASKET
1	GASKET; DPF GASKET
1	9IP; CLEANED UNIT

CSHOP-2015-894

Comments: **GEAR SHIFTER STICKING AND RELEASE BUTTON DOES NOT DEPRESS R54**

Date Opened 6-1-2015 Date Finished 6-2-2015 Meter 1 Reading: 15,950

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
TRANSMISSION

CSHOP-2015-909

Comments: **R54 DRIVERS SIDE FRONT TIRE LOW ON TREAD**

Date Opened 6-1-2015 Date Finished 6-2-2015 Meter 1 Reading: 15,940

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
TIRES & WHEELS

Asset Work Order History 10196874

CSHOP-2016-1316

Date Opened 3-18-2016 Date Finished 3-18-2016 Meter 1 Reading: 37,630

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

CSHOP-2016-135

Comments: **REPAIRS FROM PM**

Date Opened 1-11-2016 Date Finished 1-29-2016 Meter 1 Reading: 33,465

TASKS PERFORMED

Q PARTS

OVERFLOW TANK	1	LENS; 68-1963428-30 LENS CLR
HOSE LOWER	1	LIGHT; 700 SERIES SCENE
HOSE UPPER	1	BULB; BULB
LENS	3	FILTER; PANEL FILTER
TORQUE ROD-ARM		
STEPS		
DOOR HANDLES INSIDE-OUTSIDE		
A/C FILTER		

Service Requests:

01/11/2016 SERVICE REQUEST / 48: LOW PRESSURE / LUBRICATE
SERVICE ENGINE OIL

CSHOP-2016-1501

Date Opened 3-30-2016 Date Finished 4-4-2016 Meter 1 Reading: 38,928

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM

CSHOP-2016-1850

Comments: **PM FOLLOW UPS**

Date Opened 4-20-2016 Date Finished 6-15-2016 Meter 1 Reading: 40,310

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	1	CLAMP; CLAMP EXH SHIELD
WIPER BLADES	2	WIPER; WIPER BLADE
EXHAUST PIPE	1	FLUID; P/S FLUID
OIL	1	VALVE; PURGE VALVE AD-IP-IS
ECU-ECM	1	DRYER; AD-IP DRIER
DOME LIGHTS	1	SEAL; DOOR SEAL F
FLUID	2	FILTER; PANEL FILTER
TIRES ALL	1	PANEL; PANEL DOMELIGHT
FRONT TIRES	1	LIGHT; LOUVER AC HORTON UV LIGHT
AIR DRIER		
SIREN		
DOOR WEATHER MOLDING		
HVAC SYSTEM		

Asset Work Order History 10196874

CSHOP-2016-1855

Comments: **B-INSP R54**

Date Opened 4-20-2016 Date Finished 4-27-2016 Meter 1 Reading: 40,310

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FILTER; AF27958 FILTER CAB AIR
1 FILTER; OIL FILTER MAXFORCE 7
1 FILTER; FUEL FILTER MAXFORCE 7

CSHOP-2016-209

Comments: **PLEASE CHECK THIS WORK ORDER AND CLOSE**

Date Opened 1-15-2016 Date Finished 1-27-2016 Meter 1 Reading: 33,299

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1 FILTER; AF27958 FILTER CAB AIR
1 FILTER; FUEL FILTER 2008 HORTON
1 FILTER; 24316 WIX CAB A/C FILTER
22 FLUID; SYN OIL BULK QTS
1 FILTER; PRIMARY AIR FILTER 4300M7
1 FILTER; 57744XD OIL FILTER
1 FILTER; OIL FILTER MAXFORCE 7
1 FILTER; FUEL FILTER MAXFORCE 7
1 FILTER; AIR FILTER

CSHOP-2016-2194

Date Opened 5-6-2016 Date Finished 5-17-2016 Meter 1 Reading: 41,357

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM
ENGINE AND ACCESSORIES

CSHOP-2016-2384

Date Opened 5-18-2016 Date Finished 5-26-2016 Meter 1 Reading: 41,905

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
INSTRUMENTS-GAUGES-METERS
HVAC SYSTEM

Asset Work Order History 10196874

CSHOP-2016-2692

Comments: **R54**

Date Opened 6-6-2016

Date Finished

6-9-2016

Meter 1 Reading:

42,763

TASKS PERFORMED

NO PARTS USED

TRANSMISSION
HVAC SYSTEM

Service Requests:

06/05/2016

ENGINE / 18: LEAKING / S

TRUCK WON'T SHIFT INTO GEAR OCCASIONALLY THROUGHOUT SHIFT. TRUCK IS ALSO TAKING A LONG TIME FOR AIR TO BUILD UP FOR BACK SUSPENSION.

CSHOP-2016-3

Comments: **R54 DASH LIGHT COMING ON FOR TEMP**

Date Opened 1-4-2016

Date Finished

1-4-2016

Meter 1 Reading:

32,180

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM

Service Requests:

01/01/2016

SERVICE REQUEST / 18: LEAKING / REPAIR

TEMPERATURE DASH LIGHT COMES ON INTERMITTENTLY WHILE OPERATING THE VEHICLE. THE TEMPERATURE GAUGE READING IS NOTED AT 200°F WHILE AT IDLE. THE LIGHT GOES OFF ONCE THE VEHICLE BEGINS TO DRIVE.

CSHOP-2016-3437

Date Opened 7-18-2016

Date Finished

7-18-2016

Meter 1 Reading:

45,355

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES

Service Requests:

07/18/2016

ENGINE / 19: LOOSE / REPAIR

CHECK ENGINE LIGHT IS ON AND DARK SMOKE COMING FROM EXHAUST WHEN ACCELERATING

CSHOP-2016-3726

Comments: **R54 DOOR INOP**

Date Opened 8-1-2016

Date Finished

8-5-2016

Meter 1 Reading:

46,395

TASKS PERFORMED

NO PARTS USED

DOOR

Service Requests:

07/29/2016

DOOR / 19: LOOSE / REPAIR

PT COMPARTMENT OFFICERS SIDE INTERIOR DOOR HANDLE NOT OPERATING THE DOOR, CAN ONLY BE OPERATED FROM THE EXTERIOR.

Asset Work Order History 10196874

CSHOP-2016-3980

Comments: **R54**

Date Opened 8-13-2016 Date Finished 8-13-2016 Meter 1 Reading: 46,855

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE APPARATUS
ENGINE AND ACCESSORIES

Service Requests:

08/10/2016 ENGINE / 19: LOOSE / REPAIR
WRENCH ON DASHBOARD ON, CHANGE ENGINE OIL LIGHT ON

CSHOP-2016-4106

Comments: **E54**

Date Opened 8-20-2016 Date Finished 8-29-2016 Meter 1 Reading: 48,130

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES
LIGHTING SYSTEM

1 BULB; H9007 BULB ASSY

Service Requests:

08/20/2016 SERVICE REQUEST / 19: LOOSE / REPAIR

08/22/2016 ENGINE / 18: LEAKING / REPAIR
CHECK ENGINE LIGHT IS NOW ON, IN ADDITION TO THE WRENCH SYMBOL FOR CHANGE ENGINE OIL WHICH WAS PREVIOUSLY REPORTED.

08/25/2016 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST PELICAN FLASHLIGHT NOT WORKING OR CHARGING

CSHOP-2016-425

Date Opened 1-28-2016 Date Finished 2-5-2016 Meter 1 Reading: 33,935

TASKS PERFORMED

Q PARTS

BODY EXTERIOR

11 WINDOW; 10002439 WINDOW BELLOWS 6 IN

Service Requests:

01/28/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
WATER LEAKING IN TO THE CAB FROM THE ROOF LOCATED AT THE FRONT OF THE CAB BY THE BACK-UP CAMERA MONITOR.

CSHOP-2016-4272

Date Opened 8-30-2016 Date Finished 9-7-2016 Meter 1 Reading: 48,885

ROOF LEAK

TASKS PERFORMED

Q PARTS

SIREN
BODY EXTERIOR

1 SIREN; SIREN

Asset Work Order History 10196874

CSHOP-2016-4295

Date Opened 9-1-2016 Date Finished 9-1-2016 Meter 1 Reading: 48,485

TASKS PERFORMED

NO PARTS USED

CAB-INTERIOR ACCESSORIES
INSTRUMENTS-GAUGES-METERS

Service Requests:

08/30/2016 BODY / 19: LOOSE / REPAIR
BODY ISSUE. WATER IS LEAKING THROUGH ROOF IN CAB WHERE THE REAR VIEW CAMERA IS MOUNTED.

CSHOP-2016-4346

Date Opened 9-6-2016 Date Finished 9-6-2016 Meter 1 Reading: 48,800

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
INSTRUMENTS-GAUGES-METERS

Service Requests:

09/02/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
SHORELINE POWER IS NOT WORKING WHEN PLUGGED IN

09/05/2016 A/C / 19: LOOSE / REPAIR
ON BOARD AC BREAKER WITHIN THE DRIVER COMPARTMENT TRIPS WHEN AC IS PLACED ON "COOL HIGH" WHILE CONNECTED TO SHORE LINE ELECTRICITY, BUT WORKS FINE WHEN PLACED ON "COOL LOW". CREWS HAVE BEEN INFORMED TO NOT PLACE ON TO "COOL HIGH"

CSHOP-2016-4411

Date Opened 9-9-2016 Date Finished 9-14-2016 Meter 1 Reading: 49,394

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS
HVAC SYSTEM

Service Requests:

09/09/2016 A/C / 19: LOOSE / REPAIR
A/C ISSUE/ REAR AC UNIT IN CAB LEAKING WATER.

Asset Work Order History 10196874

CSHOP-2016-4584

Date Opened 9-20-2016 Date Finished 10-21-2016 Meter 1 Reading: 52,126

TASKS PERFORMED

NO PARTS USED

INVERTER
INSTRUMENTS-GAUGES-METERS

-1 INVERTER; SPS-20-1050-CUL-DC INVERTER VANNER
1 INVERTER; SPS-20-1050-CUL-DC INVERTER VANNER

Service Requests:

09/20/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
INVERTER DOES NOT WORK AND WILL NOT CHARGE THE STRETCHER BATTERIES. WHEN VEHICLE IS TURNED OFF AND PLUGGED IN THE CHARGER WORKS FINE.

09/21/2016 ENGINE / 19: LOOSE / REPAIR
CHECK ENGINE LIGHT IS ON AND LARGE AMOUNTS OF BLACK SMOKE COMING OUT OF THE STACK WITH ACCELERATION

CSHOP-2016-4648

Date Opened 9-26-2016 Date Finished 10-3-2016 Meter 1 Reading: 50,807

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL
REAR TIRES

Service Requests:

09/25/2016 TIRES / 19: LOOSE / REPAIR
BAD TIRES, TREAD DEPTH INDICATOR LOW, USING QUARTER TECHNIQUE, ALL FOUR REAR TIRES NEED REPLACEMENT, FRONT TWO TIRES ARE SATISFACTORY.

CSHOP-2016-5031

Date Opened 10-24-2016 Date Finished 10-24-2016 Meter 1 Reading: 52,442

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS

CSHOP-2016-5093

Date Opened 10-25-2016 Date Finished 10-26-2016 Meter 1 Reading: 52,488

TASKS PERFORMED

NO PARTS USED

SUSPENSION
SIREN

Asset Work Order History 10196874

CSHOP-2016-5195

Date Opened 11-1-2016 Date Finished 11-2-2016 Meter 1 Reading: 52,970

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

11/01/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
VEHICLE PLUGGED INTO SHORE LINE AND WILL NOT CHARGE. VEHICLE IS IDLING VERY ROUGH AND ATTEMPTED TO SHUT OFF ON RETURN TRIP FROM LAST CALL.

CSHOP-2016-5342

Date Opened 11-15-2016 Date Finished 11-16-2016 Meter 1 Reading: 52,970

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS

CSHOP-2016-5367

Comments: **R54 C INSPECTION BY H2**

Date Opened 11-16-2016 Date Finished 11-21-2016 Meter 1 Reading: 53,568

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

26 FLUID; SYN OIL BULK QTS
3 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
2 FILTER; PANEL FILTER
1 FILTER; FUEL FILTER MAXFORCE 7
1 FILTER; AF27958 FILTER CAB AIR
3 BATTERY; BATTERY 950CCA HP-31D
1 FILTER; OIL FILTER MAXFORCE 7

VENDOR? H2 FIRE SERVICES

CSHOP-2016-5451

Comments: **REPAIRS FROM PM**

Date Opened 11-21-2016 Date Finished 11-23-2016 Meter 1 Reading: 53,084

TASKS PERFORMED

Q PARTS

EXHAUST SYSTEM
ECU-ECM
CRANKING SYSTEM
HVAC SYSTEM

4 NEWPART; LOUVER REAR A/C HORTON

Asset Work Order History 10196874

CSHOP-2016-5992

Comments: **R-54 CHECK ENGINE AND WRENCH LIGHT ON**

Date Opened 12-27-2016 Date Finished 12-27-2016 Meter 1 Reading: 55,056

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM
INSTRUMENTS-GAUGES-METERS

Service Requests:

12/26/2016 ENGINE / 19: LOOSE / REPAIR
ENGINE- CHECK ENGINE LIGHT AND WRENCH LIGHT ON DASHBOARD, STATES CHANGE ENGINE OIL LARGE AMOUNTS OF BLACK SMOKE COMING FROM SMOKE STACK

CSHOP-2016-6114

Comments: **R-54 CHANGE OIL LIGHT ON**

Date Opened 12-30-2016 Date Finished 1-12-2017 Meter 1 Reading: 56,226

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM
ENGINE AND ACCESSORIES
AIR SYSTEM
HVAC SYSTEM

Service Requests:

12/29/2016 ENGINE / 19: LOOSE / REPAIR
CHANGE ENGINE OIL LIGHT AND MESSAGE ON DASH SCREEN

CSHOP-2016-64

Date Opened 1-6-2016 Date Finished 1-6-2016 Meter 1 Reading: 32,428

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS

CSHOP-2017-104

Comments: **R-54 CHECK ENGINE LIGHT ON**

Date Opened 1-5-2017 Date Finished 1-5-2017 Meter 1 Reading: 55,901

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

01/05/2017 ENGINE / 19: LOOSE / REPAIR
ENGINE CHECK ENGINE LIGHT AND WRENCH LIGHT ON DASH STATES CHANGE ENGINE OIL

Asset Work Order History 10196874

CSHOP-2017-1454

Date Opened 3-8-2017 Date Finished 3-9-2017 Meter 1 Reading: 60,848

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS

CSHOP-2017-1591

Date Opened 3-14-2017 Date Finished 3-28-2017 Meter 1 Reading: 62,129

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM
LIGHTING SYSTEM
DIAGNOSE ELECTRICAL

Service Requests:

03/14/2017 LIGHTS / 18: LEAKING / REPAIR
RUNNING GROUND LIGHTS X3 ON OFFICER/RIGHT SIDE OF VEHICLE NOT WORKING

CSHOP-2017-1643

Date Opened 3-17-2017 Date Finished 4-7-2017 Meter 1 Reading: 63,010

TASKS PERFORMED

NO PARTS USED

FRONT TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

03/17/2017 TIRES / 12: BROKEN / EXCHANGE - NEW
FRONT DRIVER SIDE TIRE WORN DOWN TO WEAR BAR ON OUTSIDE OF TIRE. SIZE 255/70/22.5

CSHOP-2017-1748

Comments: **CHECKING ON TIRE CONDITION**

Date Opened 3-22-2017 Date Finished 3-22-2017 Meter 1 Reading: 61,630

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM
HVAC SYSTEM

Service Requests:

03/22/2017 TIRES / 18: LEAKING / REPAIR
BAD TIRES. LEFT FRONT TIRE IS BALD.

Asset Work Order History 10196874

CSHOP-2017-1949

Date Opened 4-3-2017 Date Finished 4-4-2017 Meter 1 Reading: 62,836

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

04/02/2017 A/C / 18: LEAKING / REPAIR
A/C ISSUE AC BLOWS WARMER AIR DURING THE DAY. THE WARMER IT IS OUTSIDE THE HARDER THE AC WORKS TO STAY COLD.

CSHOP-2017-2364

Date Opened 4-21-2017 Date Finished 5-2-2017 Meter 1 Reading: 63,254

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; NAPA GOLD FUEL FILTER
1 FIL; NAPAGOLD OIL FILTER
1 2IH; AIR FILTER
2 1AN; WIPERS

CSHOP-2017-2365

Comments: **REPAIRS FROM PM**

Date Opened 4-21-2017 Date Finished 5-2-2017 Meter 1 Reading: 63,254

TASKS PERFORMED

Q PARTS

WIPERS-WASHER 3 8GR; FILTER
FUEL SYSTEM 1 BREATHER; 7085773C92 BREATHER M7
OIL FILTER 1 2IH; LIGHT, DOOR
REPAIR FROM PM - PATIENT COMPT 1 LIGHT; LIGHT LED RED TIR 6
REPAIR FROM PM - AIR INTAKE SYS 1 TWD; REP/CART
LIGHTING SYSTEM 1 9IP; 9C3Z8101B RADIATOR CAP 10238 STANT
REPAIR FROM PM - AIR SYSTEM 1 TWD; AD-IP AD-IS PURGE VLV
REPAIR FROM PM - EXHAUST SYSTEM 2 MAC; NON-CHLOR BRAKE CLNR
REPAIR FROM PM - ENGINE 1 2IH; AIR COMPRESSOR
REPAIR FROM PM - BRAKES 1 1RA; CLEANED DPF 2IH
HVAC SYSTEM 1 NCB; PURPLE POWER 40 OZ
1 2IH; DPF GASKET
1 2IH; DPF GASKET
1 NONSTOCK; FREIGHT CHARGE
3 MAC; NON-CHLOR BRAKE CLNR
2 TWD; BRAKE DRUM
2 MBI; GRIP/KIT

Asset Work Order History 10196874

CSHOP-2017-2636

Date Opened 5-5-2017 Date Finished 5-10-2017 Meter 1 Reading: 64,571

TASKS PERFORMED

Q PARTS

COOLING SYSTEM
INSTRUMENTS-GAUGES-METERS

1 AVB; CAPSULE

Service Requests:

05/05/2017 LIGHTS / 18: LEAKING / REPAIR
AFTER TRANSPORTING TO HOSPITAL FOUND DRIVER SIDE HEADLIGHT NOT FUNCTIONING, LIGHT WILL WORK ONLY ON HIGH BEAM, LOW BEAM NOT FUNCTIONAL

CSHOP-2017-2672

Date Opened 5-8-2017 Date Finished 5-13-2017 Meter 1 Reading: 64,853

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

05/07/2017 SERVICE REQUEST / 17: INSUFFICIENT LUBRICANT / REPAIR
R54 SAFETY PAD CHARGER (PLUGS INTO CIGARETTE LIGHTER) NOT CHARGING SAFETYPAD, R54 SAFETY PAD NEEDS TO BE BROUGHT INTO STATION TO BE CHARGED.

CSHOP-2017-2790

Date Opened 5-11-2017 Date Finished 5-13-2017 Meter 1 Reading: 64,853

TASKS PERFORMED

NO PARTS USED

BODY EXTERIOR

Service Requests:

05/11/2017 DOOR / 18: LEAKING / REPAIR
VEHICLE DOORS COMPARTMENT 7 WILL NOT CLOSE PROPERLY AND OPENS WHILE DRIVING OVER BUMPS IN THE ROAD.

CSHOP-2017-2947

Date Opened 5-18-2017 Date Finished 6-8-2017 Meter 1 Reading: 65,496

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
ENGINE AND ACCESSORIES
CABIN AIR FILTER

2 SVP; CNDSRFAN
1 9AP; HAND SOAP PUM (TOTAL TRK)
2 9IP; FILTER CAB A/C SIDE INTERNAL BOX

Service Requests:

05/18/2017 SERVICE REQUEST / 12: BROKEN / REPAIR
AC FILTER MAKING LOUD NOISE.

Asset Work Order History 10196874

CSHOP-2017-2970

Date Opened 5-19-2017 Date Finished 5-19-2017 Meter 1 Reading: 65,257

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM

Service Requests:

05/19/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
VEHICLE MAKING LOUD SOUND AND FUMES ARE SMELLED THROUGHOUT CAB OF RESCUE.

CSHOP-2017-341

Date Opened 1-17-2017 Date Finished 1-17-2017 Meter 1 Reading: 56,700

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES
HVAC SYSTEM

CSHOP-2017-3735

Date Opened 6-23-2017 Date Finished 6-23-2017 Meter 1 Reading: 65,330

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

VENDOR? RECHTIEN INTERNATIONAL TRUCKS

CSHOP-2017-4046

Date Opened 7-10-2017 Date Finished 7-10-2017 Meter 1 Reading: 68,009

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS

Service Requests:

07/09/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
EXHAUST SYSTEM IS DEPOSITING BLACK SOOT THROUGHOUT THE BAY. REGEN DOES NOT SEEM TO BE WORKING
PROPERLY.

Asset Work Order History 10196874

CSHOP-2017-4193

Date Opened 7-18-2017

Date Finished

9-1-2017

Meter 1 Reading:

70,821

TASKS PERFORMED

Q PARTS

BODY - WORK COMPARTMENT EMER	1	NBH; V-RIBBED BELT
PUMP ENGINE BELTS	1	NBH; SERPENTINE BELT
WIPERS-WASHER	2	1AN; 22" WIPER BLADE
ENGINE AND ACCESSORIES	1	9IP; SENSOR DPF PRESSURE DIFFERENTIAL
LIGHTING SYSTEM	1	1RA; 4DOOR DPF
ELECTRICAL	1	2IH; DPF GASKET
FILTER	1	2IH; DPF GASKET
TRANSMISSION	1	2IH; SENSOR
REPAIR FROM PM - REAR SUSPENSION	1	2IH; MAN INT SENSOR
AIR HORN	5	LMP; BULB
HVAC SYSTEM	3	5SC; RELAY 40A/30A 5PIN
	1	FIL; NAPA CABIN AIR FILTER
	1	2IH; BREATHER
	3	8GR; FILTER
	1	FIL; NAPA TRANS FILTER
	5	2IH; TRANSYND
	1	FIL; NAPA TRANS FILTER
	2	2IH; SPRING AIR
	1	2IH; THERMISTORS
	1	2TK; AC REAR UNIT
	1	2IH; EXHAUST SENSOR

Service Requests:

07/18/2017 MUFFLER / 12: BROKEN / EXCHANGE - NEW
MUFFLER BAD. EXCESSIVE EXHAUST .

CSHOP-2017-4202

Date Opened 7-18-2017

Date Finished

8-7-2017

Meter 1 Reading:

68,951

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE	4	2TP; RED N TACKY GREASE
	1	FIL; NAPA GOLD FUEL FILTER
	1	FIL; NAPAGOLD OIL FILTER
	1	2IH; AIR FILTER-CAN ORDER-500804

CSHOP-2017-425

Comments: **R54 POWER STEERING LOW AND NONE AT STATION**

Date Opened 1-19-2017

Date Finished

1-31-2017

Meter 1 Reading:

57,716

TASKS PERFORMED

NO PARTS USED

POWER STEERING PUMP
INSTRUMENTS-GAUGES-METERS

Service Requests:

01/19/2017 SERVICE REQUEST / 19: LOOSE / REPAIR
POWER STEERING FLUID LOW, IN THE "ADD" SECTION OF THE DIPSTICK. NO POWER STEERING FLUID AT THE STATION.

Asset Work Order History 10196874

CSHOP-2017-4786

Date Opened 8-16-2017 Date Finished 8-16-2017 Meter 1 Reading: 69,440

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
INSTRUMENTS-GAUGES-METERS

Service Requests:

08/15/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST - R54 - HEAVY SMOKE COMING FROM EXHAUST

CSHOP-2017-4970

Date Opened 8-24-2017 Date Finished 8-29-2017 Meter 1 Reading: 70,624

TASKS PERFORMED

Q PARTS

DIAGNOSE ELECTRICAL
BODY EXTERIOR

2 NAF; BLUE DEF 2.5 GAL

Service Requests:

08/23/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
ELECTRICAL PANEL ON DRIVER SIDE WINDOW DOES NOT WORK. DOORS WILL NOT LOCK AND WINDOWS WILL NOT GO UP USING DRIVER SIDE CONTROL PANEL. AS PER OIC, PLEASE FIX AS IT IS A HAZARD. THANK YOU

CSHOP-2017-5093

Date Opened 8-29-2017 Date Finished 9-19-2017 Meter 1 Reading: 72,504

TASKS PERFORMED

Q PARTS

WIPERS-WASHER
ENGINE AND ACCESSORIES
HEADLIGHTS LOW BEAM
HOOD HINGE
HVAC SYSTEM

2 1AN; 22" WIPER BLADE
1 LMP; HALOGEN CAPSULE
2 2IH; DOOR HINGE
1 2IH; COMPRESSOR

Service Requests:

08/29/2017 ENGINE / 12: BROKEN / EXCHANGE - NEW
WHEN R54 IS STARTED IN THE STATION BAY BLACK SMOKE AND SOOT AND PARTICLES SPEW FROM THE EXHAUST IN LARGE AMOUNTS. THE REMNANTS OF THE PARTICLES EXPELLED FROM THE EXHAUST LAND ON TOP OF OUR BRUSH TRUCK, WASHER, DRYER AND ALL OVER OUR BUNKER GEAR LOCKERS AND ALL OVER THE FLOOR

Asset Work Order History 10196874

CSHOP-2017-5206

Date Opened 9-5-2017 Date Finished 9-6-2017 Meter 1 Reading: 71,364

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DIAGNOSE ELECTRICAL
INSTRUMENTS-GAUGES-METERS

Service Requests:

-
- 09/03/2017 ENGINE / 18: LEAKING / REPAIR
CHECK ENGINE LIGHT IS ON OIL CHANGE LIGHT IS ON BACK TIRES NEED TO BE CHANGED SOON
 - 09/03/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST DOOR LOCKS ARE 10-7
-

CSHOP-2017-5322

Comments: **OIL WAS CHANGED RECENTLY JUST NEED TO RESET OIL LIGHT.**
Date Opened 9-14-2017 Date Finished 9-15-2017 Meter 1 Reading: 72,319

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES
HVAC SYSTEM

Service Requests:

-
- 09/12/2017 A/C / 12: BROKEN / INSPECT
A/C ISSUE. THE A/C IN THE CAB ON THE BACK SEAT TURNS ON WHENEVER IT WANTS.
 - 09/13/2017 SERVICE REQUEST / 33: REGISTERS WRONG / INSPECT
CHANGE ENGINE OIL MESSAGE DISPLAYED ON DASH WITH WARNING LIGHT/ICON.
 - 09/14/2017 A/C / 18: LEAKING / INSPECT
A/C IN CAB ON THE DASH NOT BLOWING AS COLD AS NORMAL, A/C IN REAR OF CAB NOT BLOWING AT ALL.
-

CSHOP-2017-5374

Date Opened 9-15-2017 Date Finished 9-15-2017 Meter 1 Reading: 72,319

TASKS PERFORMED

NO PARTS USED

HEADLIGHTS LOW BEAM

Service Requests:

-
- 09/15/2017 LIGHTS / 12: BROKEN / INSPECT
VEHICLE LIGHTS NOT WORKING. RESCUE 54 FRONT LEFT HEADLIGHT IS OUT.
-

CSHOP-2017-5582

Date Opened 9-26-2017 Date Finished 9-26-2017 Meter 1 Reading: 72,923

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10196874

CSHOP-2017-6354

Date Opened 11-3-2017 Date Finished 11-21-2017 Meter 1 Reading: 76,044

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPA GOLD FUEL FILTER

CSHOP-2017-6355

Date Opened 11-3-2017 Date Finished 11-8-2017 Meter 1 Reading: 75,341

TASKS PERFORMED

Q PARTS

WIPER BLADES
RADIATOR
ENGINE AND ACCESSORIES
FILTER
BODY EXTERIOR
SEAT BELTS

2 1AN; 22" WIPER BLADE
2 BK; RADIATOR CAP
2 8GR; FILTER
1 2TP; RED DOT A/C FILTER

CSHOP-2017-6689

Date Opened 11-20-2017 Date Finished 12-14-2017 Meter 1 Reading: 78,298

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES

1 2IH; PIPE, AIR
1 2IH; CLAMP
1 2IH; CLAMP

Service Requests:

11/20/2017 ENGINE / 12: BROKEN / EXCHANGE - NEW
LEAKING OIL

11/20/2017 ALARMS / 12: BROKEN / REPAIR
ALARM SIGNALS, BACK UP ALARM ON THE CAMERA IN THE CAB IS GOING OFF THE WHOLE TIME WHEN IN REVERSE.

11/21/2017 WINDOW / 12: BROKEN / EXCHANGE - NEW
WINDOW THAT CONNECTS CAB TO THE BACK OF THE TRUCK NEEDS NEW WEATHER STRIPPING.

CSHOP-2017-6860

Date Opened 12-1-2017 Date Finished 12-1-2017 Meter 1 Reading: 77,227

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DIAGNOSE ELECTRICAL
INSTRUMENTS-GAUGES-METERS

Service Requests:

11/30/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST. CHECK ENGINE LIGHT CAME ON WHILE DRIVING TODAY.

Asset Work Order History 10196874

CSHOP-2017-6971

Date Opened 12-6-2017 Date Finished 12-12-2017 Meter 1 Reading: 78,172

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

Service Requests:

12/06/2017 AIR RIDE / 18: LEAKING / REPAIR
AIR RIDE ISSUE. AIR LEAK. IN DUMP WHEN WE FIRST START VEHICLE.

CSHOP-2017-7082

Date Opened 12-12-2017 Date Finished 12-15-2017 Meter 1 Reading: 78,298

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES	2	2IH; KT SOLND
DIAGNOSE ELECTRICAL	1	2IH; VALVE CHECK
AIR SYSTEM	2	2IH; KIT
BODY EXTERIOR	1	9IP; SPMGC23 GAUGE

Service Requests:

12/12/2017 ENGINE / 18: LEAKING / REPAIR
ENGINE MAKING LOUD SUCKING SOUND WHEN YOU ACCELERATE ABOVE 1500RPM, ALMOST LIKE VACUUM LEAK.

12/12/2017 AIR RIDE / 18: LEAKING / REPAIR
AIR RIDE ISSUE. AIR LEAK.

12/12/2017 BODY / 18: LEAKING / REPAIR
BODY ISSUE. CENTER CAB BOOT BROKEN, LEAKING BADLY WHEN ITS RAINING.

CSHOP-2017-7243

Date Opened 12-19-2017 Date Finished 12-21-2017 Meter 1 Reading: 78,700

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS
HVAC SYSTEM

Service Requests:

12/19/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST - MAIN OXYGEN LINE OUTSIDE THREAD STRIPPED, NEEDS REPLACED.

CSHOP-2017-938

Date Opened 2-15-2017 Date Finished 2-24-2017 Meter 1 Reading: 59,890

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS

Service Requests:

02/14/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
1 OF THE 3 PORTABLE HAND LIGHTS IN DRIVER SIDE COMPARTMENT IS NOT WORKING/

Asset Work Order History 10196874

CSHOP-2018-103

Date Opened 1-5-2018 Date Finished 1-8-2018 Meter 1 Reading: 80,317

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
INSTRUMENTS-GAUGES-METERS

Service Requests:

01/05/2018 ENGINE / 18: LEAKING / REPAIR
CHECK ENGINE LIGHT IS ON, DISPLAY STATES CHANGE ENGINE OIL

01/08/2018 ENGINE / 18: LEAKING / REPAIR
ENGINE- DISPLAY STATES CHANGE ENGINE OIL, WRENCH AND ENGINE LIGHT ARE ON

CSHOP-2018-1091

Date Opened 2-22-2018 Date Finished 2-22-2018 Meter 1 Reading: 80,630

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

VENDOR? RECHTIEN INTERNATIONAL TRUCKS

CSHOP-2018-1183

Date Opened 2-27-2018 Date Finished 2-27-2018 Meter 1 Reading: 80,630

TASKS PERFORMED

NO PARTS USED

PM SERVICE C RESCUE

CSHOP-2018-1188

Date Opened 2-27-2018 Date Finished 2-27-2018 Meter 1 Reading: 80,630

TASKS PERFORMED

Q PARTS

BATTERY
3 1AD; BATTERY 31 SERIES

Service Requests:

02/27/2018 SERVICE REQUEST / 43: WEAK / EXCHANGE - NEW

CSHOP-2018-1230

Comments: **USE FOR PM FOLLOW UPS**

Date Opened 2-28-2018 Date Finished 3-13-2018 Meter 1 Reading: 81,130

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM
REPAIR FROM PM - POWER STEERING
REPAIR FROM PM - AIR SYSTEM
ELECTRICAL
REPAIR FROM PM - COOLING SYSTEM
REPAIR FROM PM - REAR SUSPENSION

1 9AP; LIGHT
1 LIT; GROMMET
2 2IH; POWER STEERING FLUID 32OZ
2 TWD; BENDIX AD-9KIT
1 2IH; RADIATOR DRAIN COCK

Asset Work Order History 10196874

CSHOP-2018-1368

Date Opened 3-7-2018 Date Finished 3-8-2018 Meter 1 Reading: 80,660

TASKS PERFORMED

Q PARTS

WIPER BLADES
AIR SYSTEM
BODY EXTERIOR

2 1AN; 22" WIPER BLADE
1 2IH; VALVE HIGH-CAB
1 BK; PTEX ULTRA BLACK 30Z
5 5EF; BELLOWS GASKET FT

CSHOP-2018-1445

Date Opened 3-12-2018 Date Finished 3-15-2018 Meter 1 Reading: 81,294

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES
HOSES-LINES & FITTINGS
AIR SYSTEM
CAB-INTERIOR ACCESSORIES

1 2IH; CONTROL SWITCHES

Service Requests:

- 03/11/2018 DOOR / 18: LEAKING / REPAIR
VEHICLE DOORS DRIVER SIDE DOOR PANEL IS LOOSE BY THE WINDOW/LOCK SWITCH THE DOOR LOCK BUTTON DOES NOT WORK MOST OF THE TIME AND SOMETIMES THE WINDOW SWITCHES STOP WORKING.
- 03/11/2018 STEERING / 18: LEAKING / REPAIR
STEERING/ALIGNMENT POWER STEERING FLUID IS ON LOW LINE OF COLD WHEN COLD.
- 03/11/2018 ENGINE / 18: LEAKING / REPAIR
ENGINE CHECK ENGINE LIGHT CAME ON, ALSO THE FERNO HOLDER FOR THE LIFEPAK IN THE REAR PATIENT COMPARTMENT THE HANDLE HAS BROKE ON ONE SIDE.
-

CSHOP-2018-1496

Date Opened 3-13-2018 Date Finished 3-21-2018 Meter 1 Reading: 81,793

TASKS PERFORMED

Q PARTS

COOLING SYSTEM

1 BK; RADIATOR CAP
12 PAF; ANTIFRZ

CSHOP-2018-1596

Date Opened 3-19-2018 Date Finished 3-19-2018 Meter 1 Reading: 81,588

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10196874

CSHOP-2018-1634

Date Opened 3-21-2018 Date Finished 4-18-2018 Meter 1 Reading: 83,653

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES

1 2IH; DPF PRESSURE SENSOR

Service Requests:

03/21/2018 ENGINE / 12: BROKEN / EXCHANGE - NEW
ENGINE, CHECK ENGINE LIGHT ON. CRUISE THROTTLE SELF ENGAGING WHEN TRUCK IS IN PARK.

CSHOP-2018-1683

Date Opened 3-26-2018 Date Finished 3-27-2018 Meter 1 Reading: 82,164

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
CAB-INTERIOR ACCESSORIES

1 9IP; RY-30T RELAY 5 PIN 12V
-1 9IP; RY-30T RELAY 5 PIN 12V
1 9IP; RY-30T RELAY 5 PIN 12V
1 9IP; RELAY RY48T (AR204/AR462)

Service Requests:

03/24/2018 DOOR / 18: LEAKING / REPAIR
VEHICLE DOORS DO NOT LOCK WHEN BUTTON IS PRESSED

CSHOP-2018-2081

Date Opened 4-16-2018 Date Finished 4-17-2018 Meter 1 Reading: 83,653

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
WIPERS-WASHER
EMERGENCY EQUIPMENT
INSTRUMENTS-GAUGES-METERS

2 1AN; WIPERS

Service Requests:

04/17/2018 HAZARD / 18: LEAKING / REPAIR
HAZARDOUS ISSUE- AIR HORNS ARE NOT WORKING PROPERLY, DRIVERS SIDE NOT WORKING AT ALL, OFFICERS
SIDE IS NOT SHARP SOUNDING

CSHOP-2018-223

Date Opened 1-10-2018 Date Finished 1-11-2018 Meter 1 Reading: 80,567

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

01/10/2018 ENGINE / 12: BROKEN / REPAIR
LOW ENGINE OIL LIGHT, AND ENGINE WARNING LIGHT IS ON DISPLAY.

Asset Work Order History 10196874

CSHOP-2018-2372

Date Opened 5-1-2018 Date Finished 5-1-2018 Meter 1 Reading: 85,089

TASKS PERFORMED

NO PARTS USED

BODY EXTERIOR

CSHOP-2018-2400

Date Opened 5-2-2018 Date Finished 5-3-2018 Meter 1 Reading: 85,089

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
INSTRUMENTS-GAUGES-METERS

Service Requests:

05/02/2018 ENGINE / 18: LEAKING / REPAIR
SERVICE ENGINE LIGHT ON. OFFICER ADVISED.

CSHOP-2018-250

Date Opened 1-11-2018 Date Finished 1-11-2018 Meter 1 Reading: 80,567

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

CSHOP-2018-2727

Date Opened 5-16-2018 Date Finished 5-17-2018 Meter 1 Reading: 86,105

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM
ENGINE AND ACCESSORIES

Service Requests:

05/16/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
TYPE PROBLEM INTO DESCRIPTION DIESEL SMELL IN CAB

CSHOP-2018-280

Date Opened 1-12-2018 Date Finished 2-20-2018 Meter 1 Reading: 80,630

TASKS PERFORMED

Q PARTS

FUEL SYSTEM	1	2AW; VIB, ASSETWORKS
ENGINE AND ACCESSORIES	1	2AW; T RING, ASSETWORKS
HOOD	1	2IH; MAN INT SENSOR

Asset Work Order History 10196874

CSHOP-2018-2855

Date Opened 5-23-2018 Date Finished 5-25-2018 Meter 1 Reading: 86,565

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
INSTRUMENTS-GAUGES-METERS

Service Requests:

05/23/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
2 PLASTIC GLOVE STORAGE CONTAINERS FOR THE BACK OF THE RESCUE TO MATCH THE ONES IN THE CAB

CSHOP-2018-2927

Date Opened 5-29-2018 Date Finished 5-29-2018 Meter 1 Reading: 86,626

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BODY EXTERIOR

Service Requests:

05/29/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
ENGINE LIGHT ON. NOT SURE OF THE PROBLEM.

CSHOP-2018-3087

Date Opened 6-4-2018 Date Finished 6-8-2018 Meter 1 Reading: 87,409

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BODY EXTERIOR
INSTRUMENTS-GAUGES-METERS

Service Requests:

06/03/2018 ENGINE / 18: LEAKING / REPAIR
ENGINE LIGHT IS ON AND ALSO CHANGE OIL LIGHT IS ON. (YELLOW WRENCH LIGHT). OIL WAS ASSESSED AND
NORMAL OIL LEVEL AND NORMAL TRANSMISSION LEVEL.

CSHOP-2018-3224

Comments: **CALL BACK CHECK ENGINE LIGHT AND LOW POWER**

Date Opened 6-9-2018 Date Finished 6-9-2018 Meter 1 Reading: 87,700

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

06/09/2018 ENGINE / 12: BROKEN / INSPECT
ENGINE RESCUE LOST SOME POWER WHILE DRIVING AND WAS ALSO MAKING A WINING NOISE. THE TRIANGLE
LIGHT ALSO COME ON ON THE DASH.

Asset Work Order History 10196874

CSHOP-2018-3235

Date Opened 6-11-2018 Date Finished 6-15-2018 Meter 1 Reading: 88,137

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

06/11/2018 ENGINE / 18: LEAKING / REPAIR
ENGINE- CHECK ENGINE LIGHT IS ON

CSHOP-2018-3288

Date Opened 6-12-2018 Date Finished 6-18-2018 Meter 1 Reading: 88,242

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

06/12/2018 BRAKES / 18: LEAKING / REPAIR
AIR BRAKE ISSUES. AIR LEAKING INITIALLY EVEN WITH PUSHING ON THE GAS, COULDN'T REACH 90 AND NOW IT FILLS UP NORMALLY AFTER OPENING AND CLOSING THE REAR DOOR AND TURNING OFF AND ON THE RESCUE.

CSHOP-2018-3293

Comments: **TOMMY, NEEDS BLOWER MOTOR AND RESISTOR MODULE, THE PARTS HAVE BEEN REQUESTED. BRAKE ISSUE REPORTED IS JUST A LOW AIR ALARM GOING OFF DURING THE DAY BUT THE AIR TANKS ARE FULL.**

Date Opened 6-12-2018 Date Finished 6-18-2018 Meter 1 Reading: 88,242

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	1	2IH; BLOWER MOTOR RESISTOR
AIR SYSTEM	1	2IH; BLOWER CAB REAR
COMPRESSOR		

Service Requests:

06/12/2018 A/C / 18: LEAKING / REPAIR
A/C ISSUE -CAB A/C IS WORKING INTERMITTENT WHILE DRIVING. -REAR BUMPER NEED BOLT FOR BLACK RUBBER BUMPER

06/13/2018 BRAKES / 18: LEAKING / REPAIR
BRAKE ISSUES

CSHOP-2018-3554

Date Opened 6-25-2018 Date Finished 6-25-2018 Meter 1 Reading: 88,959

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

Service Requests:

06/24/2018 BRAKES / 18: LEAKING / REPAIR
BRAKE ISSUES. AIR BREAK CONTINUES TO LEAK. IT EVENTUALLY FILLED UP BUT STILL HAVING ISSUES.

Asset Work Order History 10196874

CSHOP-2018-3588

Date Opened 6-26-2018 Date Finished 6-27-2018 Meter 1 Reading: 88,959

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

Service Requests:

06/26/2018 BRAKES / 18: LEAKING / REPAIR
BRAKE ISSUES- AIR BRAKES STILL HAVE A LEAK AFTER TRUCK SITS FOR A PERIOD OF TIME, CAN HEAR UP BY THE FRONT AXLE AREA

CSHOP-2018-3721

Date Opened 7-2-2018 Date Finished 7-19-2018 Meter 1 Reading: 90,564

TASKS PERFORMED

Q PARTS

SIDE COMPARTMENT BODY	1	TWD; BENDIX D-2 GOV
WIPERS-WASHER	2	1AN; 22" WIPER BLADE
ENGINE AND ACCESSORIES	2	2IH; FILTER, CAB A/C INT BX, BLUE
FILTER	1	FIL; NAPA CABIN AIR FILTER
REAR TIRES	1	2IH; AIR FILTER-CAN ORDER-500804
SUSPENSION	1	FIL; AIR FILTER
BRAKES	2	2IH; SPRINGAIRBAG
AIR SYSTEM	2	TWD; BRAKEDRUM15X4
CAB-INTERIOR ACCESSORIES	2	MBI; GRIP/KIT
BACK UP CAMERA-MONITOR	2	TWD; BRAKE DRUM
	2	TWD; BRAKESHOEKITSNEW
	1	2IH; BRACKET
	1	TWD; ADIPADISPURGEVLV
	1	2IH; KITHORN
	2	2IH; KIT
	1	2IH; VALVE CHECK
	2	2IH; VALVE, LEVELING
	1	TWD; REP/CART

CSHOP-2018-3736

Date Opened 7-3-2018 Date Finished 7-11-2018 Meter 1 Reading: 89,579

TASKS PERFORMED

Q PARTS

PM SERVICE B	1	FIL; NAPAGOLD OIL FILTER
	1	FIL; NAPA GOLD FUEL FILTER

Asset Work Order History 10196874

CSHOP-2018-4327

Date Opened 8-2-2018 Date Finished 8-3-2018 Meter 1 Reading: 91,553

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HEADLIGHTS LOW BEAM

1 AVB; CAPSULE

Service Requests:

08/02/2018 LIGHTS / 18: LEAKING / REPAIR
FRONT DRIVER SIDE HEADLIGHT OUT/NOT WORKING

CSHOP-2018-4461

Date Opened 8-10-2018 Date Finished 8-14-2018 Meter 1 Reading: 92,488

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
INSTRUMENTS-GAUGES-METERS

1 LMP; LAMP
1 LMP; LAMP
2 ECH; SOCKET

Service Requests:

08/10/2018 LIGHTS / 18: LEAKING / REPAIR
VEHICLE LIGHTS NOT WORKING- DRIVERS SIDE HEADLIGHT IS OUT

CSHOP-2018-4486

Date Opened 8-12-2018 Date Finished 8-17-2018 Meter 1 Reading: 92,656

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
EMERGENCY EQUIPMENT

Service Requests:

08/11/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
THE GAUGE THAT MEASURES THE MAIN O2 ON THE RESCUE IS BROKEN AND ALWAYS SHOWS A LOW PSI EVEN ON
BOTTLES THAT ARE COMPLETELY FILLED.

08/12/2018 LIGHTS / 18: LEAKING / REPAIR
VEHICLE LIGHTS NOT WORKING DRIVER SIDE HEAD LIGHT IS NOT FUNCTIONING THE CONNECTOR IS BURNT

Asset Work Order History 10196874

CSHOP-2018-4550

Date Opened 8-14-2018 Date Finished 8-28-2018 Meter 1 Reading: 93,485

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER AIR SYSTEM	1	9AP; O2 GAUGE, 0-3000PSI
INSTRUMENTS-GAUGES-METERS	2	9AP; RD LOUVER
HVAC SYSTEM	1	TEM; BLOWER MOTOR

Service Requests:

08/13/2018 AIR RIDE / 18: LEAKING / REPAIR
AIR RIDE ISSUE

08/13/2018 A/C / 18: LEAKING / REPAIR
A/C DOES NOT BLOW COLD AND COOL THE PATIENT COMPARTMENT.

CSHOP-2018-4657

Date Opened 8-20-2018 Date Finished 8-21-2018 Meter 1 Reading: 92,996

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

08/17/2018 A/C / 18: LEAKING / REPAIR
A/C ISSUE. PT COMP AC. UNABLE TO ADJUST AC FAN SPEED.

08/18/2018 A/C / 18: LEAKING / REPAIR
A/C ISSUE- SMELL OF EXHAUST IN FRONT CAB AND PT COMPARTMENT. ALSO AC IN FRONT CAB IS SURGING INTERMITTENTLY

CSHOP-2018-5087

Date Opened 9-7-2018 Date Finished 9-16-2018 Meter 1 Reading: 94,821

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER LIGHTING SYSTEM	2	ECH; SOCKET
	1	2IH; LIGHT CAP

Service Requests:

09/07/2018 LIGHTS / 18: LEAKING / REPAIR
VEHICLE LIGHTS NOT WORKING. FRONT RIGHT HEADLIGHT COMES OFF AND ON. IT TURNS OFF THEN WHEN YOU OPEN THE CAB AND MOVE IT AROUND IT TURNS BACK ON.

09/07/2018 ENGINE / 18: LEAKING / REPAIR
ENGINE OIL PRESENTS TO BE OVER FULL. LAST TIME THIS HAPPENED R54 HAD TO GO TO STATION 42 AT THE MECHANIC SHOP TO DRAIN ALL THE OIL AND REFILL. THERE COULD BE A POSSIBLE LEAKAGE GOING INTO THE OIL TANK.

Asset Work Order History 10196874

CSHOP-2018-5125

Date Opened 9-10-2018 Date Finished 9-11-2018 Meter 1 Reading: 94,511

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
CAB-INTERIOR ACCESSORIES
INSTRUMENTS-GAUGES-METERS

Service Requests:

09/10/2018 LIGHTS / 18: LEAKING / REPAIR
ALREADY INPUTTED THIS ISSUE BUT THIS IS AN UPDATE ON THE PROBLEM. VEHICLE RIGHT HEADLIGHT NOT WORKING. RIGHT HEADLIGHT WIRE HARNESS SEEMS TO BE DAMAGED NOT THE BULB ITSELF.

CSHOP-2018-5251

Date Opened 9-14-2018 Date Finished 9-28-2018 Meter 1 Reading: 95,914

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM
AIR SYSTEM
INSTRUMENTS-GAUGES-METERS

Service Requests:

09/14/2018 ENGINE / 18: LEAKING / REPAIR
ENGINE- CHECK ENGINE LIGHT IS ON, ALSO MESSAGE STATES CHANGE ENGINE OIL

09/19/2018 BRAKES / 18: LEAKING / REPAIR
SLOW AIR LEAK CAN BE HEARD WHEN TRUCK SHUTS OFF. LEAK CAN BE HEARD COMING FROM FRONT ENGINE COMPARTMENT.

CSHOP-2018-5258

Date Opened 9-15-2018 Date Finished 9-17-2018 Meter 1 Reading: 94,954

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

2 SVP; CNDSRFAN

Service Requests:

09/15/2018 A/C / 18: LEAKING / REPAIR
A/C ISSUE. NO AC IN THE PATIENT CAB WORKING AFTER TRIED MULTIPLE ATTEMPTS.

Asset Work Order History 10196874

CSHOP-2018-5274

Date Opened 9-17-2018 Date Finished 9-18-2018 Meter 1 Reading: 95,112

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS

Service Requests:

09/16/2018 ENGINE / 18: LEAKING / REPAIR
"ENGINE OIL CHANGE" LIGHT TURNED ON. ENGINE OIL LEVELS ON THE DIP STICK SHOWS HIGH.

09/17/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
ENGINE COOLANT LOW, FOUND A POSSIBLE LEAK

CSHOP-2018-5440

Date Opened 9-24-2018 Date Finished 9-25-2018 Meter 1 Reading: 95,599

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

1 ECH; SOCKET
2 LMP; LAMP

Service Requests:

09/22/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
CHANGE ENGINE OIL LIGHT TURNED ON. OIL LEVELS ARE HIGH AND A LIGHT REQUESTING TO CHANGE OIL HAS TURNED ON.

09/22/2018 LIGHTS / 18: LEAKING / REPAIR
VEHICLE LIGHTS NOT WORKING PROPERLY. RIGHT HEAD LIGHT TURNS OFF AND ON. THE RIGHT HEADLIGHT WIRE HARNESS WAS REPLACED NOT TO LONG AGO. SAME PROBLEM IS HAPPENING THE WIRE HARNESS SHOWS BLACK BURNT MARKS AND LOOKS MELTED.

CSHOP-2018-5592

Date Opened 10-1-2018 Date Finished 10-2-2018 Meter 1 Reading: 95,914

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
CAB-INTERIOR ACCESSORIES
INSTRUMENTS-GAUGES-METERS

Service Requests:

09/29/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
ENGINE ICON AND WRENCH ICON ILLUMINATED ON DASH. MESSAGE STATING THAT OIL CHANGE DUE ALSO DISPLAYED.

Asset Work Order History 10196874

CSHOP-2018-5706

Comments: **USE FOR PM FOLLOW UPS**

Date Opened 10-9-2018 Date Finished 10-24-2018 Meter 1 Reading: 96,629

TASKS PERFORMED

STORAGE CABINET EMERGENCY VEH
COOLING SYSTEM
DIAGNOSE ELECTRICAL
AIR SYSTEM

NO PARTS USED

-2 8GR; FILTER
-1 2IH; AIR FILTER-CAN ORDER-500804
-26 4PC; 15W40 PREMIUM BLUE OIL
2 8GR; FILTER
1 2IH; AIR FILTER-CAN ORDER-500804
26 4PC; 15W40 PREMIUM BLUE OIL
-2 2IH; FILTER, CAB A/C INT BX, BLUE
2 2IH; FILTER, CAB A/C INT BX, BLUE
-1 FIL; NAPA GOLD FUEL FILTER
1 FIL; NAPA GOLD FUEL FILTER
-1 FIL; NAPA CABIN AIR FILTER
-1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPA CABIN AIR FILTER
1 FIL; NAPAGOLD OIL FILTER

Service Requests:

10/07/2018 SERVICE REQUEST / 15: FOREIGN MATERIAL / RESET SERVICE OIL LIGHT
YELLOW WRENCH LIGHT TURNED ON. ON TOP OF THE YELLOW WRENCH LIGHT TURNING ON RECENTLY THE
"CHANGE THE ENGINE OIL" LIGHT IS STILL ON.

CSHOP-2018-5775

Date Opened 10-12-2018 Date Finished 10-12-2018 Meter 1 Reading: 96,256

TASKS PERFORMED

PM SERVICE C RESCUE

Q PARTS

1 FIL; NAPA CABIN AIR FILTER
2 2IH; FILTER, CAB A/C INT BX, BLUE
2 1AN; 22" WIPER BLADE
1 FIL; NAPA GOLD FUEL FILTER
1 2IH; AIR FILTER-CAN ORDER-500804
26 4PC; 15W40 PREMIUM BLUE OIL
2 8GR; FILTER
1 FIL; NAPAGOLD OIL FILTER

CSHOP-2018-5796

Date Opened 10-15-2018 Date Finished 10-15-2018 Meter 1 Reading: 96,629

TASKS PERFORMED

PM SERVICE B

NO PARTS USED

CSHOP-2018-5967

Date Opened 10-19-2018 Date Finished 10-19-2018 Meter 1 Reading: 96,629

TASKS PERFORMED

FRONT TIRES

NO PARTS USED

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10196874

CSHOP-2018-6059

Date Opened 10-24-2018 Date Finished 11-6-2018 Meter 1 Reading: 97,276

TASKS PERFORMED

Q PARTS

DIAGNOSE ELECTRICAL
SIREN

2 9IP; 54-525 CIRCUIT BREAKER

Service Requests:

10/24/2018 ALARMS / 35: RUSTED/CORRODED / REPAIR
ALARM SIGNALS SIREN NOT WORKING. SIREN, AM/FM RADIO, AND CAB A/C CUTTING OUT

CSHOP-2018-6094

Date Opened 10-26-2018 Date Finished 11-1-2018 Meter 1 Reading: 97,185

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL
EMERGENCY EQUIPMENT

Service Requests:

10/25/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
REVERSE CAMERA AND BEEPING SOUND DOESNT WORK WHEN R54 IS ENGAGED INTO THE REVERSE GEAR.

10/27/2018 LIGHTS / 18: LEAKING / REPAIR
VEHICLE LIGHTS NOT WORKING- WHEN PARKING AT THE ER, WHEN ENGINE IS TURNED OFF THE LIGHTS IN THE PT
COMPARTMENT TURN OFF AND VEHICLE DOES NOT DUMP, POSSIBLE TIED IN TO ON GOING ELECTRICAL ISSUE
FROM C-SHIFT

CSHOP-2018-6156

Date Opened 10-29-2018 Date Finished 10-29-2018 Meter 1 Reading: 97,185

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

10/28/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
THE AIR DUMP ON THE RESCUE DOESNT ENGAGE UNLESS THE ENGINE IS RUNNING. TYPICALLY THE RESCUE WILL
DUMP AS LONG AS THE BATTERY IS LEFT ON. THE ENGINE IS TURNED OFF TO PREVENT THE EXHAUST FUMES TO BE
INHALED BY THE PATIENTS, FIREFIGHTERS, AND HOSPITAL PERSONNEL.

CSHOP-2018-6568

Date Opened 11-19-2018 Date Finished 11-30-2018 Meter 1 Reading: 99,939

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL
INSTRUMENTS-GAUGES-METERS

Service Requests:

11/19/2018 ENGINE / 18: LEAKING / REPAIR
ENGINE- TRANSMISSION OIL MESSAGE IS ON AS WELL AS UPSIDE DOWN TRIANGLE

Asset Work Order History 10196874

CSHOP-2018-6630

Date Opened 11-24-2018 Date Finished 11-26-2018 Meter 1 Reading: 99,131

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES
HVAC SYSTEM

CSHOP-2018-6635

Date Opened 11-25-2018 Date Finished 11-27-2018 Meter 1 Reading: 99,204

TASKS PERFORMED

Q PARTS

SIDE COMPARTMENT BODY
HVAC SYSTEM

1 2TK; BLOWER

CSHOP-2018-7163

Date Opened 12-18-2018 Date Finished 12-18-2018 Meter 1 Reading: 100,846

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

CSHOP-2018-7184

Date Opened 12-19-2018 Date Finished 1-8-2019 Meter 1 Reading: 100,846

TASKS PERFORMED

Q PARTS

WIPER BLADES
ENGINE AND ACCESSORIES
FILTER
AIR SYSTEM

1 2IH; DPF NEW 4 DOOR
1 2IH; MAN INT SENSOR
1 2IH; EXHAUST SENSOR
1 2IH; TURBO KIT
1 SVP; DPF GSKT (2593986C1)
1 2IH; TURBO KIT
1 2IH; OIL PAN GASKET DT466
1 SVP; DPF GSKT (2601233C1)
1 9HY; TUBING

CSHOP-2018-75

Date Opened 1-4-2018 Date Finished 1-9-2018 Meter 1 Reading: 80,380

TASKS PERFORMED

Q PARTS

CAB-INTERIOR ACCESSORIES

9 5EF; BELLOWS GASKET FT

Service Requests:

01/04/2018 BODY / 18: LEAKING / REPAIR
BODY ISSUE RUBBER BOOT FOR WINDOW BETWEEN CAB AND BOX NEED TO BE REPLACED.

Asset Work Order History 10196874

CSHOP-2019-1002

Date Opened 2-22-2019 Date Finished 3-11-2019 Meter 1 Reading: 106,268

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

02/22/2019 TIRES / 19: LOOSE / EXCHANGE - NEW
REAR, PASSENGER, OUTSIDE TIRE IS LOW

CSHOP-2019-1065

Date Opened 2-26-2019 Date Finished 3-7-2019 Meter 1 Reading: 105,961

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM
HVAC SYSTEM

Service Requests:

02/26/2019 A/C / 18: LEAKING / REPAIR
A/C ISSUE FRONT CAB BLOWER MOTOR NOT WORKING

CSHOP-2019-1239

Date Opened 3-7-2019 Date Finished 3-8-2019 Meter 1 Reading: 106,050

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS

Service Requests:

03/07/2019 ENGINE / 18: LEAKING / REPAIR
ENGINE- CHECK ENGINE LIGHT IS ON

CSHOP-2019-1331

Date Opened 3-12-2019 Date Finished 3-14-2019 Meter 1 Reading: 106,504

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

03/11/2019 A/C / 18: LEAKING / REPAIR
A/C ISSUE

Asset Work Order History 10196874

CSHOP-2019-1629

Date Opened 3-29-2019 Date Finished 4-18-2019 Meter 1 Reading: 108,154

TASKS PERFORMED

NO PARTS USED

REPAIR FROM PM - O2 SYSTEM
CAB-INTERIOR ACCESSORIES
INSTRUMENTS-GAUGES-METERS
HVAC SYSTEM

Service Requests:

03/29/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
MAIN O2 LEAKING.

CSHOP-2019-1664

Date Opened 4-1-2019 Date Finished 4-17-2019 Meter 1 Reading: 108,154

TASKS PERFORMED

NO PARTS USED

SUSPENSION
SIREN

Service Requests:

03/30/2019 ALARMS / 19: LOOSE / INSPECT
ALARM SIGNALS- SIREN CONTROL PANEL, SIREN DOES NOT WORK THEN IT DOES WORK AND SHUTS OFF AGAIN,
MIGHT BE A SHORT IN THE FUSE

CSHOP-2019-1799

Date Opened 4-8-2019 Date Finished 4-9-2019 Meter 1 Reading: 107,825

TASKS PERFORMED

NO PARTS USED

SIREN

Service Requests:

04/06/2019 SERVICE REQUEST / 12: BROKEN / INSPECT
SIRENS NOT WORKING INTERMITTENTLY

CSHOP-2019-1870

Date Opened 4-10-2019 Date Finished 4-23-2019 Meter 1 Reading: 108,154

TASKS PERFORMED

Q PARTS

DIAGNOSE ELECTRICAL
AIR SYSTEM

1	8HD; CORD PLG, M,15A,125V
4	9ME; TANK CLIP

Service Requests:

04/10/2019 ALARMS / 18: LEAKING / REPAIR
ALARM SIGNALS SIREN PANEL DID NOT WORK. RESTART FIXED ISSUE

Asset Work Order History 10196874

CSHOP-2019-1925

Date Opened 4-13-2019 Date Finished 4-15-2019 Meter 1 Reading: 107,649

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

04/13/2019 A/C / 18: LEAKING / INSPECT
A/C ISSUE PATIENT COMPARTMENT A/C NOT WORKING

CSHOP-2019-2739

Date Opened 5-29-2019 Date Finished 6-4-2019 Meter 1 Reading: 108,481

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
BACK-UP ALARM
INSTRUMENTS-GAUGES-METERS

1 BK; BACK-UP ALARM

Service Requests:

05/28/2019 ALARMS / 18: LEAKING / REPAIR
ALARM SIGNALS BACK UP ALARM NOT SOUNDING.

CSHOP-2019-2893

Date Opened 6-4-2019 Date Finished 6-4-2019 Meter 1 Reading: 108,481

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

Service Requests:

06/04/2019 ENGINE / 18: LEAKING / REPAIR
ENGINE- COOLANT WAS ADDED ON 6/3/19

CSHOP-2019-2977

Date Opened 6-10-2019 Date Finished 6-22-2019 Meter 1 Reading: 109,679

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

06/06/2019 RADIATOR / 18: LEAKING / REPAIR
RADIATOR HAS MINOR LEAK

06/09/2019 ENGINE / 18: LEAKING / REPAIR
CHECK ENGINE LIGHT

Asset Work Order History 10196874

CSHOP-2019-31

Date Opened 1-2-2019 Date Finished 1-8-2019 Meter 1 Reading: 100,846

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

CSHOP-2019-3159

Date Opened 6-19-2019 Date Finished 6-22-2019 Meter 1 Reading: 109,679

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

4 LMP; LAMP
4 TEE; HEADLIGHT HARNESS
4 ECH; SOCKET

Service Requests:

06/19/2019 LIGHTS / 18: LEAKING / REPAIR
VEHICLE FRONT LEFT HEADLIGHT NOT WORKING

CSHOP-2019-3220

Date Opened 6-21-2019 Date Finished 7-2-2019 Meter 1 Reading: 110,272

TASKS PERFORMED

NO PARTS USED

EMERGENCY EQUIPMENT

Service Requests:

06/21/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
AIR HORNS NOT WORKING ON RIGHT SIDE AND LEFT SIDE NOT SOUNDING PROPERLY RUMBLER SIREN NOT WORKING AT ALL

CSHOP-2019-3355

Date Opened 6-26-2019 Date Finished 7-1-2019 Meter 1 Reading: 110,272

TASKS PERFORMED

Q PARTS

CAB-INTERIOR ACCESSORIES
INSTRUMENTS-GAUGES-METERS

1 2IH; PANEL

Service Requests:

06/26/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
TYPE PROBLEM INTO DESCRIPTION

06/26/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
DASH IN FRONT OF OFFICER SEAT IS NOT SECURED AND TENDS TO DISCONNECT AND FALLS OFF.

Asset Work Order History 10196874

CSHOP-2019-3525

Date Opened 7-8-2019 Date Finished 7-9-2019 Meter 1 Reading: 111,062

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

07/05/2019 ENGINE / 18: LEAKING / REPAIR
ENGINE LIGHT IS ON. RESCUE SEEMS TO BE RUNNING FINE NO NOTICEABLE ISSUES.

CSHOP-2019-3551

Date Opened 7-9-2019 Date Finished 7-11-2019 Meter 1 Reading: 111,062

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

07/08/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
AIR HORNS NOT WORKING AT ALL

07/08/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
RUMBLER SIREN NOT WORKING AT ALL

CSHOP-2019-3805

Date Opened 7-23-2019 Date Finished 7-30-2019 Meter 1 Reading: 111,458

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

CSHOP-2019-3824

Date Opened 7-23-2019 Date Finished 8-8-2019 Meter 1 Reading: 111,791

TASKS PERFORMED

Q PARTS

DIAGNOSTIC TEST
COOLING SYSTEM

1 FREIGHT
1 2IH; PIPECOOLANT
1 2IH; THERMOSTAT KIT

CSHOP-2019-4263

Date Opened 8-14-2019 Date Finished 12-6-2019 Meter 1 Reading: 111,583

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

24 4PC; 15W40 PREMIUM BLUE OIL
1 FIL; NAPAGOLDFUELFILTER
1 FIL; NAPAGOLDOILFILTER
26 4PC; 4PC

Asset Work Order History 10196874

CSHOP-2019-4268

Date Opened 8-14-2019

Date Finished

9-26-2019

Meter 1 Reading:

112,763

TASKS PERFORMED

QUALITY CHECK-REPAIRS
BODY - WORK COMPARTMENT EMER
STRETCHER
DOOR PROP CYLINDER
WIPER BLADES
AIR FILTER
REPAIR FROM PM - O2 SYSTEM
BATTERY
ELECTRICAL
TRANSMISSION
STEERING
AIR DRIER
AIR SYSTEM
DOOR HINGE-PINS-BUSHINGS
CABIN AIR FILTER
HVAC SYSTEM

Q

PARTS

1 4AH; SLIDE12PR
1 9AP; STYRKERMAGNETSWITCH
4 4AH; GASSPRING7518LBS
2 1AN; 22WIPERBLADE
1 2IH; AIRFILTERCANORDER500804
1 5EF; O23WRENCH
1 1AD; BATTERYSEVEREDUTY
1 6KU; DYNAMICDISCONNECT
1 2DD; TCM
1 FIL; POWERSTEERINGFILTER
-1 FIL; NAPATRANSFILTER
1 FIL; NAPATRANSFILTER
1 TWD; KITMINOR
1 TWD; VALVEPURGEWABCO
1 FIL; NAPACABINAIRFILTER
2 2IH; FILTERCABACINTBXBLUE
1 2RD; FILTER645X775BLKFOAM
2 9HD; FILTERCABIN775X145
1 5EF; HORTONUVLOUVER

CSHOP-2019-4607

Date Opened 8-28-2019

Date Finished

9-25-2019

Meter 1 Reading:

112,763

WILL NOT SHIFT

TASKS PERFORMED

ENGINE AND ACCESSORIES
COMPUTER CONTROLS

Q

PARTS

1 9PB; LARGE PLACARD HOLDER
1 2IH; TURBOKIT
8 2IH; BOLT
2 2IH; 2IH
2 2IH; 2IH
1 2IH; GASKET
1 NBH; SERPENTINE BELT
1 2IH; TURBOKIT
1 2IH; BELT
8 2IH; SPACER
1 2IH; EGR GASKET
2 2IH; 2IH
7 2IH; STUD
6 2IH; 2IH

Service Requests:

08/28/2019

ENGINE / 19: LOOSE / INSPECT

VEHICLE WILL NOT SWITCH GEARS AND WILL NOT GO OVER 15MPH

Asset Work Order History 10196874

CSHOP-2019-4620

Date Opened 8-29-2019

Date Finished

10-1-2019

Meter 1 Reading:

113,046

TASKS PERFORMED

EXHAUST MANIFOLD
HEAD GASKETS
ENGINE AND ACCESSORIES
TRANSMISSION
HEATER CORE
HVAC SYSTEM

Q PARTS

1	2IH; KIT HEAD GASKETS BOLTS
2	2IH; GASKET
4	2IH; GASKET
4	2IH; O RING HS FUEL PUMP
4	2IH; O RING HS FUEL PUMP
10	2IH; CLIP FUEL RETURN 25
2	2IH; O-RING
4	2IH; ORING
2	2IH; O RING COOLANT
-1	TEM; STEEL FILTER DRIER
2	2IH; CLAMP INJECTOR HOLD DOWN
6	2IH; STUD
5	2IH; SEAL KIT INJECTOR
2	2IH; GASKET HS FUEL PUMP
1	2IH; GASKET KIT
-1	TEM; EXPANSION VALVE
1	TEM; EXPANSION VALVE
4	2IH; BOLTS, EXHAUST TO MANIFOLD
3	9XX; AC FREON 10174676
1	2IH; TUBE FUEL HP
4	2IH; BOLT
1	2IH; EXHAUST MANIFOLD
1	PTX; PERMATEx
-1	2IH; TUBE ASSEMBLY
1	2IH; TUBE ASSEMBLY
2	2IH; GASKET
1	2IH; BREATHER
10	2IH; CLIP ROCKER ARM
1	2IH; TUBE ASSM
1	TEM; STEEL FILTER DRIER
4	2IH; EGR GASKET
4	2IH; GASKET TURBO
4	2IH; GASKET
8	2IH; BOLT
1	2IH; TUBE GASKET
1	2IH; TUBE, GASKET
1	2IH; HEATER CORE
2	BK; CBC 30 CIR BRKR
1	BK; FUSE HOLDER
1	2IH; BLOWER MOTOR RESISTOR
1	2IH; BLOWER CAB REAR
2	2IH; O RING
3	NBH; QUALITY HTR HOSE
1	2IH; VALVE A C
1	SVP; DRIER
3	NBH; HD HEATER HOSE

Asset Work Order History 10196874

CSHOP-2019-54

Date Opened 1-3-2019 Date Finished 1-8-2019 Meter 1 Reading: 100,846

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

-24 90C; 15W40 OIL VAL DRUM S SHOP
24 90C; 15W40 OIL VAL DRUM S SHOP
1 FIL; NAPA GOLD FUEL FILTER
24 FLUID; SYN OIL BULK QTS
1 FIL; NAPAGOLD OIL FILTER

CSHOP-2019-6207

Date Opened 11-28-2019 Date Finished 11-28-2019 Meter 1 Reading: 117,274

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS

CSHOP-2019-6335

Date Opened 12-6-2019 Date Finished 12-6-2019 Meter 1 Reading: 117,500

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS

Service Requests:

12/05/2019 ENGINE / 18: LEAKING / REPAIR
CHECK ENGINE LIGHT ON AND CHANGE ENGINE OIL MESSAGE ON

CSHOP-2019-6343

Date Opened 12-6-2019 Date Finished 12-26-2019 Meter 1 Reading: 117,643

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; NAPA TRANS FILTER
1 FIL; NAPAGOLD OIL FILTER
1 2IH; AIR FILTER CAN ORDER 500804
22 4PC; 15W40 PREMIUM BLUE OIL
1 FIL; NAPA GOLD FUEL FILTER

CSHOP-2019-6351

Date Opened 12-9-2019 Date Finished 12-10-2019 Meter 1 Reading: 118,132

TASKS PERFORMED

Q PARTS

DIAGNOSE ELECTRICAL

3 NAF; BLUE DEF 2 5 GAL

Service Requests:

12/08/2019 LIGHTS / 18: LEAKING / REPAIR
VEHICLE LIGHTS NOT WORKING- HIGH BEAMS NOT ILLUMINATING

Asset Work Order History 10196874

CSHOP-2019-6460

Date Opened 12-13-2019 Date Finished 12-18-2019 Meter 1 Reading: 117,653

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	2	1AN; 22 WIPER BLADE
WIPER BLADES	1	2IH; HOSE COOLANT M7
CAP	1	BK; RADIATOR CAP
COOLING SYSTEM	1	2IH; HOSE RADIATOR
FAULT CODE	1	SVP; SVP
ENGINE AND ACCESSORIES	1	2IH; COVER AIR
HEADLIGHTS LOW BEAM	1	2IH; DPF NEW 4 DOOR
STEPS	1	SVP; DPF GSKT 2601233C1
GLOVE BOX	1	9ES; BULB LED SUPER BRIGHT
A/C FILTER	2	9HD; FILTER CABIN 7 75X14 5
COMPRESSOR	1	2RD; FILTER 6 45X7 75 BLK FOAM
	1	2IH; CONTROL
	1	2IH; BLOWER CAB REAR
	1	2IH; BLOWER MOTOR RESISTOR

CSHOP-2019-864

Date Opened 2-14-2019 Date Finished 2-14-2019 Meter 1 Reading: 104,146

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES
TIRES & WHEELS

Service Requests:

02/14/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
FRONT TIRES 85 AND 90 PSI

CSHOP-2019-998

Date Opened 2-22-2019 Date Finished 3-8-2019 Meter 1 Reading: 106,050

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

02/21/2019 A/C / 18: LEAKING / REPAIR
A/C BREAKER FLIPS WHEN PLUGGED INTO SHORELINE & ONE OF THE SHORE LINE CABLES DOES NOT WORK

Asset Work Order History 10196874

CSHOP-2020-2907

Date Opened 6-3-2020 Date Finished 6-26-2020 Meter 1 Reading: 129,425

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR HORN
A/C HOSES/FITTINGS

Service Requests:

06/02/2020 ALARMS / 12: BROKEN / EXCHANGE - NEW
DRIVER SIDE AIR HORN BRACKET IS BROKEN

06/04/2020 A/C / 18: LEAKING / REPAIR
A/C COMPRESSOR WAS REPLACED BUT IS STILL BLOWING WARM INSIDE CAB

CSHOP-2020-3805

Date Opened 7-22-2020 Date Finished 7-22-2020 Meter 1 Reading: 131,584

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2020-4266

Date Opened 8-17-2020 Date Finished 8-18-2020 Meter 1 Reading: 133,733

TASKS PERFORMED

NO PARTS USED

SIDE COMPARTMENT BODY

CSHOP-2020-4314

Comments: **SPARE RESCUE AT 41**

Date Opened 8-20-2020 Date Finished 9-4-2020 Meter 1 Reading: 135,024

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES
DIAGNOSE ELECTRICAL
DOOR PANEL

1 2IH; DOOR HANDLE CUP

Service Requests:

08/20/2020 ENGINE / 49: CAN NOT DUPLICATE CONCERN / INSPECT
CHECK ENGINE LIGHT CAME ON

CSHOP-2020-4630

Date Opened 9-5-2020 Date Finished 9-24-2020 Meter 1 Reading: 135,902

TASKS PERFORMED

NO PARTS USED

PM SERVICE C RESCUE

Asset Work Order History 10196874

CSHOP-2020-4687

Date Opened 9-9-2020 Date Finished 9-14-2020 Meter 1 Reading: 135,796

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

Service Requests:

09/08/2020 SERVICE REQUEST / 18: LEAKING / REPAIR
REAR DRIVER'S SIDE BRAKE LIGHT IS OUT.

CSHOP-2020-5027

Comments: **REPAIR FROM PM INSPECTION**

Date Opened 9-24-2020 Date Finished 9-24-2020 Meter 1 Reading: 136,170

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES

20 4PC; 15W40 PREMIUM BLUE OIL
1 FIL; NAPA GOLD FUEL FILTER
1 FIL; NAPAGOLD OIL FILTER

CSHOP-2020-5128

Date Opened 9-30-2020 Date Finished 10-23-2020 Meter 1 Reading: 139,327

TASKS PERFORMED

NO PARTS USED

EMERGENCY EQUIPMENT

Service Requests:

09/30/2020 SERVICE REQUEST / 18: LEAKING / REPAIR
TRUCK APPEARS TO BE LEAKING OIL, ALSO LEFT REAR FLOOD LIGHT OUT

CSHOP-2020-5320

Date Opened 10-9-2020 Date Finished 5-24-2021 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

REPAIR FROM PM - REAR A/C

1 5EF; AMBIENTTEMPSENSORHORTON

Service Requests:

10/09/2020 A/C / 12: BROKEN / INSPECT
A/C ISSUE PATIENT COMPARTMENT AC WILL NOT COME ON AUTOMATICALLY. THE MODE HAS TO BE SET TO MANUAL AND THE FAN SPEED HAS TO BE TURNED UP IN ORDER FOR THE AC TO WORK. THE TEMPERATURE SHOWN ON THE DIGITAL DISPLAY IS "-466.00 F" THE TRUCK ALSO HAS AN OIL LEAK.

Asset Work Order History 10196874

CSHOP-2020-5444

Date Opened 10-15-2020 Date Finished 10-17-2020 Meter 1 Reading: 138,765

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

Service Requests:

10/14/2020 LIGHTS / 18: LEAKING / REPAIR
SCENE LIGHT ON DRIVERS SIDE REAR NOT WORKING ON R 241

10/14/2020 LIGHTS / 18: LEAKING / REPAIR
CHECK OUT LIGHTS NOT WORKING IN PATIENT COMPARTMENT OF R 241

CSHOP-2020-5936

Date Opened 11-10-2020 Date Finished 11-10-2020 Meter 1 Reading: 140,385

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

11/07/2020 OIL / 18: LEAKING / REPAIR
LOW ENGINE OIL - NEEDS TO BE TOPPED OFF OR OIL CHANGED.

CSHOP-2020-6204

Date Opened 11-30-2020 Date Finished 12-9-2020 Meter 1 Reading: 142,207

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
EMERGENCY EQUIPMENT

2 1WL; 900 SERIES REFLECTOR

Service Requests:

11/22/2020 LIGHTS / 18: LEAKING / REPAIR
DRIVER SIDE REAR FLOOD LIGHT OUT

CSHOP-2020-6335

Date Opened 12-5-2020 Date Finished 12-5-2020 Meter 1 Reading: 142,207

TASKS PERFORMED

NO PARTS USED

PM SERVICE B

Asset Work Order History 10196874

CSHOP-2020-6336

Comments: **LUBE OIL FILTER AND PM FOLLOW UPS**

Date Opened 12-5-2020

Date Finished

1-4-2021

Meter 1 Reading:

142,207

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR FILTER
FUEL SYSTEM
OIL
TRANSMISSION
REPAIR FROM PM - BATTERIES
STEERING
COMPRESSOR

1 2IH; AIR FILTER
1 2IH; SENSOR
1 FIL; NAPAGOLD OIL FILTER
1 2IH; OIL PRESSURE SENSOR
26 4PC; 15W40 PB OIL DRM QT
1 2IH; TUBE KIT
1 2IH; FILTER TRANS SPIN ON
3 1AD; 1000 CCA 31 SERIES BATTERY

CSHOP-2020-723

Date Opened 2-7-2020

Date Finished

3-3-2020

Meter 1 Reading:

124,711

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM
EMERGENCY EQUIPMENT

Service Requests:

02/07/2020 ENGINE / 18: LEAKING / REPAIR
CHECK ENGINE LIGHT IS ON

CSHOP-2020-89

Date Opened 1-7-2020

Date Finished

1-8-2020

Meter 1 Reading:

119,790

TASKS PERFORMED

NO PARTS USED

BODY EXTERIOR

CSHOP-2021-1104

Date Opened 2-27-2021

Date Finished

3-9-2021

Meter 1 Reading:

143,431

TASKS PERFORMED

Q PARTS

BATTERY
HVAC SYSTEM

3 1AD; 1000 CCA 31 SERIES BATTERY
1 BK; PAG 46 W UV DYE 8OZ
1 SVP; COMPRESOR

Service Requests:

02/26/2021 A/C / 12: BROKEN / REPAIRED
A/C ISSUE-NOT BLOWING COLD

Asset Work Order History 10196874

CSHOP-2021-1235

Comments: **SPARE RESCUE AT 56**

Date Opened 3-7-2021

Date Finished

4-20-2021

Meter 1 Reading:

147,621

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

4 1WL; LIGHT LED RED TIR6

INSTRUMENTS-GAUGES-METERS

1 FREIGHT

4 1WL; 1WL

1 2IH; MASS AIR FLOW SENSOR

Service Requests:

02/26/2021

LIGHTS / 18: LEAKING / REPAIR

VEHICLE LIGHTS NOT WORKING-DRIVER SIDE BOTTOM FLASHER NOT WORKING WHEN BRAKING.

03/04/2021

ENGINE / 18: LEAKING / REPAIR

ENGINE CHECK ENGINE LIGHT WRENCH LIGHT

03/05/2021

OIL / 18: LEAKING / REPAIR

"ENGINE OIL NEED TO BE CHANGED" NOTIFICATION CAME ON. RESCUE IS AT STATION 56

CSHOP-2021-1626

Date Opened 3-26-2021

Date Finished

3-30-2021

Meter 1 Reading:

147,621

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES

-1 9HD; 2 DOOR FILTER DPF RW 5010850R1

1 9HD; 2 DOOR FILTER DPF RW 5010850R1

1 2IH; FAN CLUTCH

1 9HD; DPF FILTER RW 5010847R1

CSHOP-2021-2221

Date Opened 4-24-2021

Date Finished

4-28-2021

Meter 1 Reading:

147,621

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

CSHOP-2021-2364

Date Opened 4-29-2021

Date Finished

5-7-2021

Meter 1 Reading:

150,048

TASKS PERFORMED

NO PARTS USED

PM SERVICE C RESCUE

Asset Work Order History 10196874

CSHOP-2021-2365

Comments: **LUBE OIL FILTER AND PM FOLLOW UPS**

Date Opened 4-29-2021

Date Finished

7-10-2021

Meter 1 Reading:

0

TASKS PERFORMED

SIDE COMPARTMENT BODY
CAB
WIPER BLADES
OIL
ENGINE AND ACCESSORIES
LIGHTING SYSTEM
BATTERY
CRANKING SYSTEM
AUTO-EJECT
AIR SYSTEM
GRILLE
SEAT REAR
HVAC SYSTEM

Q PARTS

2 4AH; GAS SPRING 12 087 34LB
1 MMM; SUPER WTHRSTRP ADHV
2 1AN; 22 WIPER BLADE
1 2IH; FAN BLADE
1 2IH; FAN CLUTCH
-1 2IH; FAN CLUTCH
1 FREIGHT
1 FIL; NAPAGOLD OIL FILTER
1 2IH; FANCLUTCH
1 FIL; NAPA GOLD FUEL FILTER
1 2IH; MASS AIR FLOW SENSOR
28 4PC; 15W40 PB OIL DRM QT
1 2IH; OIL FILL CAP
1 2IH; LIGHT CLEARANCE
1 1AD; STARTER 29 MT 10T
2 6KU; COVER ROUND WHITE AUTO EJECT
1 2IH; VALVE CHECK
1 2RD; FILTER 6 45X7 75 BLK FOAM
1 FIL; NAPA CABIN AIR FILTER
1 CRC; FOAMING COIL CLEANER
2 9HD; FILTER CABIN 7 75X14 5

CSHOP-2021-2410

Date Opened 5-2-2021

Date Finished

5-5-2021

Meter 1 Reading:

149,774

TASKS PERFORMED

HVAC SYSTEM

Q PARTS

1 2IH; BLOWER CAB REAR
1 2IH; BLOWER MOTOR RESISTOR

Service Requests:

05/02/2021 A/C / 12: BROKEN / EXCHANGE - NEW
AC IN THE CAB IS BARELY BLOWING AT ALL AND THE AIR IS WARM

CSHOP-2021-2424

Date Opened 5-3-2021

Date Finished

6-10-2021

Meter 1 Reading:

152,027

TASKS PERFORMED

BODY DAMAGE ACCIDENT

Q PARTS

3 1WL; 600 SERIES CLEAR LENS

Service Requests:

05/02/2021 SERVICE REQUEST / 18: LEAKING / REPAIR
STROBE LIGHT COVER IS CRACKED ON THE PASSENGER SIDE DOOR WAY ON THE STEP.

05/02/2021 SERVICE REQUEST / 18: LEAKING / REPAIR
SHORELINE OUTLET COVER ON THE RESCUE IS BROKEN.

Asset Work Order History 10196874

CSHOP-2021-2828

Comments: **SPARE RESCUE AT 56**

Date Opened 5-24-2021

Date Finished

5-26-2021

Meter 1 Reading:

150,618

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM
EMERGENCY EQUIPMENT

Service Requests:

05/23/2021 LIGHTS / 18: LEAKING / REPAIR
VEHICLE LIGHTS NOT WORKING - DRIVER READ FLOOD LIGHT IS OUT.

CSHOP-2021-3180

Date Opened 6-10-2021

Date Finished

6-11-2021

Meter 1 Reading:

152,027

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

Service Requests:

06/08/2021 SERVICE REQUEST / 18: LEAKING / REPAIR
AUTO EJECT A/C ELECTRICAL INLET STUCK AND NOT WORKING

CSHOP-2021-3905

Date Opened 7-13-2021

Date Finished

7-16-2021

Meter 1 Reading:

152,410

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES
SEAT REAR
HVAC SYSTEM

1 2IH; GASKET RIGHT VALVE COVER
1 2IH; BREATHER
1 2IH; SENSOR FUEL PRESSURE
1 CRC; QD ELECTRONIC CLEANER
3 2RD; LOUVER
1 2IH; ORING KIT

CSHOP-2021-4482

Date Opened 8-9-2021

Date Finished

8-11-2021

Meter 1 Reading:

152,497

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
COOLING SYSTEM
ELECTRICAL

2 FLUID; COOLANT ANTIFREEZE GAL
1 BK; RADIATOR CAP
-2 9OC; COOLANT
2 9OC; COOLANT
1 1WL; BULB 35 WATT 12V SNAP IN
1 1WL; 900 SERIES REFLECTOR

Asset Work Order History 10196874

CSHOP-2021-5190

Comments: **INSTALL POWER LOAD**

Date Opened 9-15-2021

Date Finished 10-25-2021

Meter 1 Reading: 153,443

TASKS PERFORMED

Q PARTS

POWERLOAD SYSTEM
HEADLIGHTS LOW BEAM
LIGHTING SYSTEM
DOOR
BODY EXTERIOR
SEAT FRONT

1 NW; FUSE HOLDER
2 PTX; PERMATEX
1 9ES; BULB LED SUPER BRIGHT
1 9ES; BULB LED SUPER BRIGHT
1 2IH; HEADLAMP ASSY LEFT
1 2IH; HEADLAMP ASSY RIGHT
1 2IH; O RING
1 2IH; LIGHT CLEARANCE
1 9ES; GO LIGHT LED BULB
2 1WL; LED FLOOD SCENE LIGHT
4 1WL; LED FLOOD SCENE LIGHT
1 5EF; HANDLE LH W LOCK
1 4AH; GAS SPRING 12 087 34LB
1 SF; BUGS-B-GONE 16 OZ

CSHOP-2021-5938

Date Opened 10-22-2021

Date Finished 2-15-2022

Meter 1 Reading: 157,560

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM
BODY EXTERIOR

1 FREIGHT
1 5EF; SWITCH PANEL 3 BUTTON
-1 5HA; SWITCH 3 POSITION REMOTE I4G W MINI
1 5HA; SWITCH 3 POSITION REMOTE I4G W MINI
1 9PB; LARGE PLACARD HOLDER

CSHOP-2021-5950

Date Opened 10-24-2021

Date Finished 10-25-2021

Meter 1 Reading: 153,443

TASKS PERFORMED

Q PARTS

REGULATOR

1 9ME; REGULATOR 540 MEDICAL O2

Service Requests:

10/23/2021

SERVICE REQUEST / 12: BROKEN / REPAIR

MAIN OXYGEN IS NON-OPERATIONAL. TANK IS FULL. WILL NOT FLOW OXYGEN IN THE WALL MOUNT FLOW METER.

Asset Work Order History 10196874

CSHOP-2021-6117

Date Opened 11-1-2021 Date Finished 3-2-2022 Meter 1 Reading: 157,560

TASKS PERFORMED

Q PARTS

EQUIPMENT MOUNTING BRACKETS
HANDLIGHT
ELECTRICAL

4 NTH; ADAPTER
1 5FS; LIGHT INTERIOR WARNING

Service Requests:

-
- 10/29/2021 LIGHTS / 12: BROKEN / REPAIRED
DOME LIGHTS NOT WORKING WITH BACK DOOR SWITCH
 - 10/29/2021 LIGHTS / 12: BROKEN / INSTALL
MAP/REPORT LIGHT IN CAB, OFFICER SIDE NEEDS REPLACED
 - 10/29/2021 SERVICE REQUEST / 10: BENT / REPAIR
MOUNT BOTTLE HOLDER TO SQUAD BENCH FORWARD WALL

CSHOP-2021-6580

Comments: **CALLAGHAN TIRE INVOICE**

Date Opened 12-1-2021 Date Finished 12-3-2021 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

-
- 11/28/2021 TIRES / 12: BROKEN / EXCHANGE - NEW
DRIVER'S OUTSIDE REAR TIRE HAS A NAIL AND IS LEAKING.

CSHOP-2021-6601

Date Opened 12-1-2021 Date Finished 1-14-2022 Meter 1 Reading: 156,047

TASKS PERFORMED

Q PARTS

CHECK ENGINE LIGHT

2 WD; WD40 12OZ SPRAY

Service Requests:

-
- 11/22/2021 ENGINE / 21: MISADJUSTED / INSPECT
ENGINE - CHANGE ENGINE OIL WARNING AND CHECK ENGINE WARNING LIGHT IS ON

Asset Work Order History 10196874

CSHOP-2021-928

Date Opened 2-17-2021 Date Finished 3-8-2021 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

02/17/2021 TIRES / 18: LEAKING / EXCHANGE - NEW
BAD TIRES ALL 6 TIRES ARE WORN DOWN AND WERE REQUESTED BY CHIEF VALDES TO BE REPLACED.

CSHOP-2022-1108

Comments: **BATTERIES DEAD**
Date Opened 2-26-2022 Date Finished 3-21-2022 Meter 1 Reading: 158,230

TASKS PERFORMED

Q PARTS

BATTERY
3 1AD; 1000 CCA 31 SERIES BATTERY

CSHOP-2022-1781

Comments: **CHECK ENGINE**
Date Opened 3-31-2022 Date Finished 4-1-2022 Meter 1 Reading: 158,943

TASKS PERFORMED

Q PARTS

CHECK ENGINE LIGHT
20 4PC; 15W40 PB OIL DRM QT
1 FIL; NAPAGOLD OIL FILTER

CSHOP-2022-233

Comments: **INSPECT ONLY**
Date Opened 1-13-2022 Date Finished 1-21-2022 Meter 1 Reading: 156,122

TASKS PERFORMED

NO PARTS USED

INSPECTION

Asset Work Order History 10196874

CSHOP-2022-234

Comments: **NOTED IN PM FOLLOW UP REPAIRS LUBE OIL AND FILTERS**

Date Opened 1-13-2022 Date Finished 3-4-2022 Meter 1 Reading: 157,560

TASKS PERFORMED

	Q	PARTS
WIPERS-WASHER	2	1AN; 22 WIPER BLADE
DPF FILTER	1	9HD; DPF FILTER RW 5010847R1
AIR FILTER	1	2IH; AIR FILTER
FUEL SYSTEM	1	9AP; PF9914KIT 600066
OIL FILTER	1	FIL; NAPAGOLD OIL FILTER
TRANSMISSION	1	9OC; OIL MAXXFORCE 7 25QTS
DIFFERENTIAL	1	2IH; FILTER TRANS SPIN ON
POWER STEERING PUMP	1	PTX; PERMATEX
AIR DRIER	1	2CU; FILTER P S 7191
AIR SYSTEM	1	2TP; 2TP
DOOR HANDLES INSIDE-OUTSIDE	1	2TP; CARTRIDGE
	1	TWD; PURGE VALVE ASSY KIT

CSHOP-2022-3042

Comments: **CHECK WITH STEVE**

Date Opened 6-6-2022 Date Finished 6-14-2022 Meter 1 Reading: 0

TASKS PERFORMED

	Q	PARTS
ROOF EXHAUST SYSTEM	1	9HD; DPF FILTER RW 5010847R1

CSHOP-2022-3090

Comments: **ENGINE PROBLEMS. DPF HAS BEEN REPLACED, EGR COOLER HAS BEEN REPLACED. DURING TEST DRIVE CHECK ENGINE LIGHT ON, ENGINE SURGES. ENGINE NEEDS TO BE EVALUATED/IT MAY BE MORE COST EFFECTIVE TO SWAP ENGINES WITH A 2 DOOR RESCUE THAT IS SLATED FOR SURPLUS IF ENGINE NEEDS MAJOR WORK. PER**

Date Opened 6-7-2022 Date Finished 6-27-2022 Meter 1 Reading: 160,973

TASKS PERFORMED

	Q	PARTS
QUALITY CHECK-REPAIRS	1	2IH; FUEL FILTER MAXFORCE 7
OIL	22	4PC; 15W40 PREMIUM BLUE OIL
ENGINE AND ACCESSORIES	1	FIL; NAPAGOLD OIL FILTER
LIGHTING SYSTEM	1	FIL; NAPA CABIN AIR FILTER
BATTERY	1	2IH; TURBO MOUNTING KIT
HVAC SYSTEM	2	2IH; GASKET TURBO
	1	2IH; OIL PRESSURE SENSOR
	4	2IH; BOLT
	4	2IH; RING O SEAL
	2	2IH; TUBE GASKET
	1	5HA; MODULE OUTPUT HORTON
	1	LIT; RIGHT ANGLE S T PGTL
	1	LIT; 4 BACK UP LAMP
	3	2IH; LIGHT DOOR
	1	1AD; 1000 CCA 31 SERIES BATTERY
	2	9HD; FILTER CABIN 7 75X14 5
	1	2RD; LOUVER

Asset Work Order History 10196874

CSHOP-2022-3268

Date Opened 6-14-2022 Date Finished 6-16-2022 Meter 1 Reading: 160,973

TASKS PERFORMED

NO PARTS USED

INSPECTION

CSHOP-2022-3514

Comments: **ON CALL**

Date Opened 6-29-2022 Date Finished 7-11-2022 Meter 1 Reading: 161,125

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

CSHOP-2022-4830

Comments: **SSR5 PM FOLLOW UP REPAIRS LEFT FRONT STEER TIRE NEEDS REPLACED WITH USED FROM BUILDING 3**

Date Opened 9-7-2022 Date Finished 9-13-2022 Meter 1 Reading: 162,615

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
PARK-CLEARANCE LIGHTS
BATTERY
A/C FILTER

1 2IH; LIGHT CLEARANCE
3 1AD; 1000 CCA 31 SERIES BATTERY
2 2IH; FILTER CAB A C INT BX BLUE
1 FIL; NAPA CABIN AIR FILTER
2 9HD; FILTER CABIN 7 75X14 5

CSHOP-2022-4904

Comments: **SSR5 TRUCK DIED IN PARKING LOT**

Date Opened 9-12-2022 Date Finished 10-3-2022 Meter 1 Reading: 161,956

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES

1 2IH; HIGH PRESS FUEL PUMP
1 2IH; CORE DEPOSIT
1 2IH; TURBO MOUNTING KIT
1 2IH; PMP KIT FUEL
1 2IH; FUEL FILTER MAXFORCE 7
1 2IH; VALVE KIT
1 2IH; MAN INT SENSOR
3 2IH; 2IH
1 2IH; CROSSOVER TUBE

CSHOP-2022-5255

Comments: **PRE-TRIP**

Date Opened 9-28-2022 Date Finished 10-4-2022 Meter 1 Reading: 161,956

TASKS PERFORMED

Q PARTS

PRE TRIP INSPECTION
WIPER BLADES

2 WIP; BEAM WIPER BLADE

Asset Work Order History 10196874

CSHOP-2022-5571

Date Opened 10-17-2022 Date Finished 10-19-2022 Meter 1 Reading: 162,265

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

1 ECH; SWITCH

Service Requests:

10/17/2022 LIGHTS / 12: BROKEN / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING

CSHOP-2022-5606

Comments: LIGHTS NOT WORKING SPARE RESCUE AT 33

Date Opened 10-18-2022 Date Finished 12-1-2022 Meter 1 Reading: 163,370

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DIAGNOSE ELECTRICAL

Service Requests:

10/18/2022 LIGHTS / 38: SHORTED / REPAIR
VEHICLE LIGHTS NOT WORKING

CSHOP-2022-5648

Date Opened 10-19-2022 Date Finished 10-24-2022 Meter 1 Reading: 162,311

TASKS PERFORMED

NO PARTS USED

QUALITY CHECK-REPAIRS

CSHOP-2022-5655

Date Opened 10-20-2022 Date Finished 10-24-2022 Meter 1 Reading: 162,265

TASKS PERFORMED

Q PARTS

INSPECTION

2 WIP; BEAM WIPER BLADE
1 FIL; NAPA GOLD FUEL FILTER
1 FIL; NAPAGOLD OIL FILTER
1 2IH; AIR FILTER
21 4PC; 15W40 PREMIUM BLUE OIL

Asset Work Order History 10196874

CSHOP-2022-5671

Comments: **PM SERVICE REPAIRS**

Date Opened 10-20-2022

Date Finished

12-28-2022

Meter 1 Reading:

163,482

TASKS PERFORMED

Q PARTS

EXHAUST SYSTEM
TIRES & WHEELS
EMERGENCY EQUIPMENT
DOOR

1 2IH; TUBE ASM
1 2IH; GASKET
1 2IH; 2IH
1 2IH; EGR GASKET
3 2IH; BOLTS EXHAUST TO MANIFOLD
2 BK; CLAMP
1 FREIGHT
1 9AP; SILKOLENE 762 HI TEMP COMPOUND
2 2IH; HINGE DOOR NON THREAD FRONT
2 2IH; HINGE DOOR THREADED REAR

CSHOP-2022-574

Date Opened 1-31-2022

Date Finished

2-2-2022

Meter 1 Reading:

156,987

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

CSHOP-2022-6460

Date Opened 12-12-2022

Date Finished

12-12-2022

Meter 1 Reading:

163,370

TASKS PERFORMED

NO PARTS USED

BATTERY

CSHOP-2022-6595

Comments: **PILOT PROGRAM**

Date Opened 12-20-2022

Date Finished

1-13-2023

Meter 1 Reading:

163,708

TASKS PERFORMED

Q PARTS

EMERGENCY EQUIPMENT
CAB-INTERIOR ACCESSORIES

1 6ZA; STRAP 16 25
2 6ZA; STRAP ZICO 8 11IN
2 6ZA; TOOL HOLDER SMALL

CSHOP-2022-860

Date Opened 2-14-2022

Date Finished

2-22-2022

Meter 1 Reading:

157,560

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
STEP
SUSPENSION
BRAKES

2 9HD; AIRBAG REAR
2 2IH; 4707 MERITOR REAR
2 2IH; LOCK WHEEL
2 TWD; USE 56353F
2 NTL; OIL SEAL
2 NTL; AXL GSKT

Asset Work Order History 10196874

CSHOP-2023-1099

Date Opened 3-2-2023 Date Finished 3-7-2023 Meter 1 Reading: 167,094

TASKS PERFORMED

Q PARTS

SAFETY INSPECTION
PARK-CLEARANCE LIGHTS

2 GRO; CLR MKR LAMP

CSHOP-2023-1499

Comments: **CHECK ENGINE LIGHT**

Date Opened 3-22-2023 Date Finished 3-22-2023 Meter 1 Reading: 167,714

TASKS PERFORMED

NO PARTS USED

CHECK ENGINE LIGHT

CSHOP-2023-1737

Comments: **AIR HORN**

Date Opened 4-3-2023 Date Finished 4-12-2023 Meter 1 Reading: 168,714

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM
AIR HORN

Service Requests:

03/28/2023 SERVICE REQUEST / 21: MISADJUSTED / ADJUST
AIR HORN NOT WORKING PROPERLY

CSHOP-2023-1738

Comments: **COOLANT LEAK**

Date Opened 4-3-2023 Date Finished 4-12-2023 Meter 1 Reading: 168,714

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

Service Requests:

03/29/2023 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / OPERATE AND INSPECT FOR LEAK
Fluid observed on floor of bay. Moderate amount radiator fluid; noticed approximately 3 x throughout the day during running calls and coming back to station.

03/30/2023 RADIATOR / 49: CAN NOT DUPLICATE CONCERN / ADJUST
Small coolant leak. Shop contacted on 3/29 told to document in assestworks. On 3/30 about 1/2 a gallon of coolant was replaced still a small leak.

CSHOP-2023-1850

Comments: **INSPECTION ONLY**

Date Opened 4-6-2023 Date Finished 4-10-2023 Meter 1 Reading: 168,714

TASKS PERFORMED

NO PARTS USED

INSPECTION

Asset Work Order History 10196874

CSHOP-2023-1851

Comments: **PM REPAIR TICKET**

Date Opened 4-6-2023

Date Finished

5-23-2023

Meter 1 Reading:

0

TASKS PERFORMED

COOLING SYSTEM
OIL
LIGHTING SYSTEM
FAULT CODE
TRANSMISSION
BRAKES
AIR SYSTEM
BUMPER REAR
DOOR LOCKS
SEAT FRONT
A/C FILTER

Q PARTS

1 BK; RADIATOR CAP
1 9AP; OIL ANALYSIS TEST
1 FIL; NAPAGOLD OIL FILTER
1 2IH; FUEL FILTER MAXFORCE 7
22 4PC; 15W40 PREMIUM BLUE OIL
1 1WL; LIGHT INTERIOR
1 1WL; LIGHT LED RED TIR6
9 9OC; BULK TRANS SYN
1 2IH; FILTER TRANS SPIN ON
2 9AP; KIT SOLOINOID
1 2IH; VALVE CHECK
1 5HA; BUMPER GUARD RUBBER
1 2AD; SENSOR SEAT SWITCH KIT
2 9HD; FILTER CABIN 7 75X14 5
1 2RD; FILTER 6 45X7 75 BLK FOAM
1 FIL; NAPA CABIN AIR FILTER

CSHOP-2023-2055

Comments: **COOLANT**

Date Opened 4-17-2023

Date Finished

4-26-2023

Meter 1 Reading:

169,604

TASKS PERFORMED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR FILTER
COOLING SYSTEM
SERPENTINE BELT
AIR SYSTEM

Q PARTS

1 2IH; AIR FILTER
1 2IH; RADIATOR
-1 2IH; RADIATOR
1 2IH; THERMOSTAT KIT
1 2IH; BELT TENSIONER
1 2IH; PUMP WATER
1 2CU; TENSIONER 38702
1 NBH; V RIBBED BELT 1889037C2
1 2IH; BOLT
1 2IH; BELT TENSIONER V8
1 2IH; BELT A C
2 NBH; IDLER PULLEY
1 8HD; STRAP RATCHET 4 PACK
-1 2IH; BELT 25 081047HD
1 2IH; BELT 25 081047HD
1 2IH; PULLEY
1 2IH; IDLER BOLT
1 2IH; BOLT HEX
1 2IH; CORE DEPOSIT
1 2IH; BRAKE AIR COMP ASSEM
2 2IH; BOLT SHOULDERED
1 8HY; CUSTOM HOSE
1 TWD; BENDIX D 2 GOV

Asset Work Order History 10196874

CSHOP-2023-2199

Comments: **ADVANCED LIFE SUPPORT VEHICLE SSR5: TRANSMISSION BAD**

Date Opened 4-24-2023 Date Finished 4-25-2023 Meter 1 Reading: 169,500

TASKS PERFORMED

NO PARTS USED

TRANSMISSION

Service Requests:

04/21/2023 TRANSMISSION / 10: BENT / INSPECT
TRANSMISSION BAD: possible issue, check transmission code on dash

CSHOP-2023-2394

Date Opened 5-3-2023 Date Finished 5-4-2023 Meter 1 Reading: 169,818

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR HORN 2 9AP; HORN KIT PAI 3390 1094

CSHOP-2023-2584

Date Opened 5-13-2023 Date Finished 6-9-2023 Meter 1 Reading: 171,038

TASKS PERFORMED

Q PARTS

DPF FILTER 1 2IH; CORE DEPOSIT
OIL FILTER 1 2IH; DPF FILTER
CHECK ENGINE LIGHT 1 FIL; NAPAGOLD OIL FILTER
20 4PC; 15W40 PREMIUM BLUE OIL

CSHOP-2023-2629

Comments: **BRAKE PEDAL VALVE**

Date Opened 5-15-2023 Date Finished 5-24-2023 Meter 1 Reading: 170,550

TASKS PERFORMED

Q PARTS

BRAKES 1 2IH; BRAKE VALVE TREADLE

Asset Work Order History 10196874

CSHOP-2023-319

Comments: **R46**

Date Opened 1-19-2023

Date Finished

2-17-2023

Meter 1 Reading:

166,414

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES

1	2IH; GASKET
1	2IH; TUBE ASSY
1	2IH; PLUG OIL DRAIN
2	2IH; EGR GASKET
1	2IH; CORE DEPOSIT
1	9HD; DPF FILTER RW 5010847R1
2	2IH; GASKET TURBO
1	2IH; CORE DEPOSIT
1	2IH; TURBO KIT
1	2IH; TURBOCHARGER LOW PRESS
1	FIL; FIL
1	9OC; OIL MAXXFORCE 7 25QTS
1	2IH; TURBO MOUNTING KIT
1	2IH; TUBE ASSY

Service Requests:

01/15/2023

ENGINE / 18: LEAKING / VERIFIED LOSS OF POWER AND MULTIPLE DTC`S. PREFORMED DIAGNC FOR THE RESCUE TO PICKUP SPEED THE RPMS HAVE TO GO HIGHER THEN NORMAL FOR THE RESCUE TO SHIFT INTO THE PROPER GEAR.

CSHOP-2023-3411

Comments: **R55 AIR HORN NOT WORKING**

Date Opened 6-26-2023

Date Finished

6-27-2023

Meter 1 Reading:

172,139

TASKS PERFORMED

NO PARTS USED

AIR HORN

Service Requests:

06/26/2023

LIGHTS / 49: CAN NOT DUPLICATE CONCERN / INSPECT
Air horn not working.

CSHOP-2023-4488

Comments: **UNIT WITH MULTIPLE LIGHTS ON AND DERATE**

Date Opened 8-24-2023

Date Finished

10-4-2023

Meter 1 Reading:

173,305

TASKS PERFORMED

Q PARTS

OIL FILTER
CHECK ENGINE LIGHT

1	FIL; NAPAGOLD OIL FILTER
---	--------------------------

Asset Work Order History 10196874

CSHOP-2023-4794

Comments: **COMPARTMENT DOOR**

Date Opened 9-13-2023 Date Finished 1-9-2024 Meter 1 Reading: 17,722

TASKS PERFORMED

Q PARTS

WIPER BLADES	2	WIP; WIPER
FUEL SYSTEM	1	2IH; FUEL FILTER MAXFORCE 7
OIL	1	MBI; CORE DEPOSIT
REPAIR FROM PM - POWER STEERING	1	TWD; BENDIX D 2 GOV
AIR SYSTEM	1	MBI; REMAN AIR DRYER
DOOR ALARM OR OTHER WARNING	2	2IH; BLEND DOOR MOTOR
HVAC SYSTEM	1	2IH; COMPRESSOR A C
	1	2IH; HOSE A C
	1	2IH; HVAC ASM

Service Requests:

09/12/2023 SERVICE REQUEST / 12: BROKEN / REPAIR
Cab open door alarm keeps going off even when all doors are closed. Alarm is also extremely loud making hard to hear radio communications and is harmful to firefighters hearing.

CSHOP-2023-5639

Comments: **R39 SUC UNIT**

Date Opened 11-1-2023 Date Finished 11-1-2023 Meter 1 Reading: 174,069

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE FIGHTING EQUIPMENT

CSHOP-2023-5684

Comments: **ON CALL CAB AC**

Date Opened 11-5-2023 Date Finished 11-28-2023 Meter 1 Reading: 176,856

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

CSHOP-2023-6113

Comments: **DOOR OPEN HOLDER spare rescue at 33**

Date Opened 12-5-2023 Date Finished 12-8-2023 Meter 1 Reading: 176,722

TASKS PERFORMED

Q PARTS

DOOR	1	4AH; ADJ DOOR GRABBER 4 5
	1	4AH; ADJ DOOR GRABBER 4 5

Service Requests:

12/01/2023 DOOR / 12: BROKEN / Replaced right rear door retainer
R Side rear exterior door pin holder broken therefore when opening rear doors to load and unload patients door doesn't stay. Open and closes freely with door pin unable to be secured in holder.

Asset Work Order History 10196874

CSHOP-2023-6179

Date Opened 12-8-2023 Date Finished 1-9-2024 Meter 1 Reading: 176,729

TASKS PERFORMED

NO PARTS USED

INSPECTION

CSHOP-2023-6265

Comments: **AFTER INSPECTION REPAIRS**

Date Opened 12-13-2023 Date Finished 1-13-2024 Meter 1 Reading: 177,171

TASKS PERFORMED

Q PARTS

WIPERS-WASHER	2	WIP; WIPER
THERMOSTAT	1	1FG; FILTER UREA
OIL	1	2IH; THERMOSTAT KIT
REPAIR FROM PM - POWER STEERING	1	2IH; PLUG OIL DRAIN
REPAIR FROM PM - EXHAUST SYSTEM	1	9AP; OIL ANALYSIS TEST
REAR AXLE	1	9OC; OIL MAXXFORCE 7 25QTS
AXLES-HUBS-AND BEARINGS	1	FIL; NAPAGOLD OIL FILTER
SWAY BAR LINKS	1	1FG; FILTER P S 7191
BRAKES	6	2IH; FLUID POWER STEERING 32OZ
AIR SYSTEM	1	2IH; TUBE ASM
AIR HORN	1	2IH; GASKET
	1	2IH; EGR GASKET
	1	2IH; CORE DEPOSIT
	1	2IH; DPF GASKET
	1	2IH; DPF GASKET
	1	2IH; DPF FILTER
	1	1AM; UNI ROD MERITOR
	2	NPP; SHOP TOWELS
	2	TWD; DRUM BRAKE 3753X FRONT
	2	NTL; TEF SEAL
	2	1AM; 4703 SHOES RSD GG RATED
	6	9AP; 80W90 GEAR OIL
	2	CR; HUB CAP
	1	NCB; THL 271 HD 36ML
	2	9AP; HORN KIT PAI 3390 1094
	1	9AP; 21 1 2 AIR HORN
	1	TWD; KIT MINOR
	2	1GY; SPRING AIR

Asset Work Order History 10196874

CSHOP-2023-984

Comments: **R91 CHECK ENGINE LIGHT AND BLOWING SMOKE**

Date Opened 2-23-2023 Date Finished 2-28-2023 Meter 1 Reading: 166,953

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES
HVAC SYSTEM

1 2IH; DPF GASKET
1 2IH; CORE DEPOSIT
1 2IH; DPF FILTER
1 FIL; NAPAGOLD OIL FILTER
1 SVP; DPF GSKT 2593986C1
20 4PC; 15W40 PREMIUM BLUE OIL
1 2TK; UNIV INSIDE
1 2TK; BRISK 2

Service Requests:

02/23/2023 ALARMS / 12: BROKEN / DIAGNOSE
ALARM SIGNALS WHITE SMOKE LIMP MODE

CSHOP-2024-1032

Comments: **QC**

Date Opened 2-23-2024 Date Finished 4-22-2024 Meter 1 Reading: 180,692

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS

2 1AN; 22 WIPER BLADE

CSHOP-2024-1246

Comments: **CALLAGHAN TIRE**

Date Opened 3-6-2024 Date Finished 3-6-2024 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2024-1314

Date Opened 3-10-2024 Date Finished 3-10-2024 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

CSHOP-2024-1419

Date Opened 3-15-2024 Date Finished 3-22-2024 Meter 1 Reading: 179,867

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES

1 9OC; OIL MAXXFORCE 7 25QTS
1 FIL; NAPAGOLD OIL FILTER
7 NOL; NAPA QT 15W40 CJ4

Asset Work Order History 10196874

CSHOP-2024-1425

Comments: **ticket not used**

Date Opened 3-16-2024

Date Finished

4-22-2024

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

INSPECTION

CSHOP-2024-1426

Comments: **ON CALL LR DOOR WOULD NOT OPEN**

Date Opened 3-16-2024

Date Finished

3-16-2024

Meter 1 Reading:

179,578

TASKS PERFORMED

NO PARTS USED

DOOR HANDLES INSIDE-OUTSIDE

CSHOP-2024-1922

Comments: **AIR LEAK WHEN BRAKES APPLIED**

Date Opened 4-17-2024

Date Finished

5-9-2024

Meter 1 Reading:

180,692

TASKS PERFORMED

Q PARTS

BRAKES

2 9AP; BRAKE ACTUATOR T20 LONG STROKE
2 2IH; HOSE FRONT BRAKE CHAMBER

CSHOP-2024-2094

Date Opened 4-26-2024

Date Finished

5-10-2024

Meter 1 Reading:

180,692

TASKS PERFORMED

Q PARTS

BATTERY

3 1AD; 1000 CCA 31 SERIES BATTERY

CSHOP-2024-2514

Date Opened 5-20-2024

Date Finished

5-20-2024

Meter 1 Reading:

180,692

TASKS PERFORMED

NO PARTS USED

QUALITY CHECK-REPAIRS

CSHOP-2024-2605

Comments: **ON CALL**

Date Opened 5-27-2024

Date Finished

6-24-2024

Meter 1 Reading:

181,897

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES
AIR SYSTEM

Service Requests:

05/27/2024

LIGHTS / 12: BROKEN / REPAIR

VEHICLE LIGHTS NOT WORKING Drivers side headlight is not working. The vehicle is currently at Station 22.

Asset Work Order History 10196874

CSHOP-2024-265

Comments: **REPAIRS AFTER QC**

Date Opened 1-16-2024

Date Finished

1-17-2024

Meter 1 Reading:

177,171

TASKS PERFORMED

Q PARTS

AIR FILTER
ELECTRICAL
CAB-INTERIOR ACCESSORIES
CABIN AIR FILTER

1 2IH; AIR FILTER
1 2RD; LOUVER
2 4AH; GAS SPRING 7 5 18LBS
1 4AH; SLIDE 12 PR
2 9HD; FILTER CABIN 7 75X14 5
2 2IH; FILTER CAB A C INT BX BLUE
1 2RD; FILTER 6 45X7 75 BLK FOAM

CSHOP-2024-2813

Date Opened 6-7-2024

Date Finished

6-10-2024

Meter 1 Reading:

181,897

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

CSHOP-2024-518

Date Opened 1-26-2024

Date Finished

1-26-2024

Meter 1 Reading:

177,403

TASKS PERFORMED

NO PARTS USED

SAFETY INSPECTION

CSHOP-2024-594

Date Opened 1-30-2024

Date Finished

1-31-2024

Meter 1 Reading:

177,403

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES

1 2IH; DPF PRESSURE SENSOR 4921730

CSHOP-2024-843

Date Opened 2-12-2024

Date Finished

2-23-2024

Meter 1 Reading:

178,071

TASKS PERFORMED

Q PARTS

ELECTRICAL

4 9WE; FUSE BLADE 100A

CSHOP-2025-4364

Date Opened 10-6-2025

Date Finished

10-14-2025

Meter 1 Reading:

181,897

TASKS PERFORMED

NO PARTS USED

SURPLUS PREP

Asset Work Order History 10196874

RADIO-2018-1265

Comments: **RETRO WIRELESS HEADSETS INTO RESCUE - 54**
Date Opened 12-17-2018 Date Finished 12-17-2018 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

12/17/2018 RADIO / /
RETROFIT WIRELESS HEADSET INTO R54

RADIO-2019-507

Comments: **BC 57**
Date Opened 6-11-2019 Date Finished 6-11-2019 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

PORTABLE RELATED

Service Requests:

06/08/2019 RADIO / /
RESCUE 54- PM RADIO LAPEL MIC HAVING ISSUES CUTTING IN AND OUT, TALKED TO BC57 HE LOANED R54 A MIC FOR THE DAY. WILL REPLACE MONDAY - ED

RADIO-2019-860

Comments: **CHECKED RADIO AND HEADSETS. NO TROUBLE FOUND.**
Date Opened 11-8-2019 Date Finished 11-8-2019 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

RADIO

RADIO-2020-430

Comments: **HEADSET REPLACED**
Date Opened 5-6-2020 Date Finished 5-6-2020 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

05/05/2020 RADIO / /
RADIO ISSUES. RESCUE RADIO REMAINS KEYED UP WITHOUT BUTTON DEPRESSED. SMALL RED LIGHT ILLUMINATED ON RIGHT SIDE OF RADIO DISPLAY. BOTH RADIOS IN FRONT AND PATIENT COMPARTMENT SAME ISSUE. STATION 41, R241, 10196874.

Asset Work Order History 10196874

RADIO-2020-697

Comments: **REPAIRED**
Date Opened 8-17-2020 Date Finished 8-17-2020 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

08/03/2020 RADIO / /
ON THE VHS RADIO WE CAN HEAR THE INCOMING BUT OUTCOMING CANNOT BE HEARD. R241

RADIO-2020-793

Comments: **REPLACED**
Date Opened 9-22-2020 Date Finished 9-22-2020 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

PORTABLE RELATED

Service Requests:

09/20/2020 RADIO / /
THE TOP HOUSING OF 245 DRIVER RADIO IS CRACKED (PLASTIC AREA NEAR THE SCREEN)

RADIO-2020-922

Comments: **10196874**
Date Opened 10-30-2020 Date Finished 10-30-2020 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

RADIO-2020-923

Comments: **PAGER REPLACED**
Date Opened 10-30-2020 Date Finished 10-30-2020 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

PORTABLE RELATED

Service Requests:

10/29/2020 RADIO / /
PAGER ON RESCUE 241-DO APPEARS TO BE WORKING PERFECTLY BUT DOES NOT RECEIVE PAGES. BATTERY TAKEN OUT MULTIPLE TIMES. DISPATCH SENT OUT MULTIPLE TEST PAGES.

Asset Work Order History 10196874

RADIO-2020-931

Date Opened 11-2-2020 Date Finished 11-2-2020 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

11/02/2020 RADIO / /
THE PAGER ID# ANNP00A589 RECEIVES CALLS BUT DOES NOT ALERT USER OF INCOMING CALL. PAGER DOES NOT VIBRATE OR MAKE NOISE.

RADIO-2021-1148

Comments: **REPLACED**
Date Opened 12-30-2021 Date Finished 12-30-2021 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

12/30/2021 RADIO / /
REPLACE WB505R & 3X UHW505 HEADSETS

RADIO-2021-326

Date Opened 4-6-2021 Date Finished 4-6-2021 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

04/02/2021 SERVICE REQUEST / /
R-56 ONE OF THE WIRELESS HEAD SET IS NOT WORKING. THE MIC IS NOT WORKING.

SCBA-2020-358

Comments: **(2) SHOULDER TO WAIST STRAPS/ L & R SHOULDER PADS/ REG COVER/ M & F WAIST BELTS/ RELIEF VALVE**
Date Opened 4-15-2020 Date Finished 4-15-2020 Meter 1 Reading: 126,260

TASKS PERFORMED

Q PARTS

AIR SYSTEM

- 1 SCOTT SCBA SUPP; SHOULDER PAD LEFT
- 1 SCOTT SCBA SUPP; REGULATOR COVER
- 1 SCOTT SCBA SUPP; SHOULDER PAD RIGHT
- 2 SCOTT SCBA SUPP; SHOULDER TO WAIST STRAP.
- 1 SCOTT SCBA SUPP; WAIST BELT W/CONNEC
- 1 SCOTT SCBA SUPP; WAIST BELT FEMALE

Service Requests:

04/11/2020 SERVICE REQUEST / /
AIR PACK #387 LEAKING FROM THE PRESSURE RELIEF VALVE

Asset Work Order History 10196874

SSHOP-2015-22

Comments: **R54 PAT A/C COMPRESSOR FAULTY CHECK ENGINE LITE ON**

Date Opened 4-23-2015 Date Finished 4-23-2015 Meter 1 Reading: 15,928

PAT. A/C COMPRESSOR SIZED UP, REPLACE COMPRESSOR AND DRYER

TASKS PERFORMED

Q PARTS

EXHAUST SYSTEM	1	DRYER; 07-0602A DRIER A/C 7118
INSTRUMENTS-GAUGES-METERS	1	9IP; 3615169C3 A/C COMPRESSOR 4382 SANDEN
HVAC SYSTEM		

SSHOP-2019-113

Date Opened 4-16-2019 Date Finished 5-31-2019 Meter 1 Reading: 108,418

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	2	2IH; CLAMP EXHUAST
HURST TOOL CUTTERS	1	2IH; LIGHTCAP
EXHAUST SYSTEM	3	1AD; BATTERY 31 SERIES
COOLING SYSTEM	1	2IH; REGULATOR
HEADLIGHTS LOW BEAM	4	5EF; HOLD DOWN REAR STEP
BATTERY	2	2IH; DOOR HINGE
DRIVESHAFT	1	2TK; CONDENSER
REAR WINDOW	1	TEM; STEEL FILTER DRIER
SIREN		
BUMPER REAR		
DOOR HINGE-PINS-BUSHINGS		
BACK UP CAMERA-MONITOR		
HVAC SYSTEM		

SSHOP-2019-157

Date Opened 5-28-2019 Date Finished 5-31-2019 Meter 1 Reading: 108,418

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
QUALITY CHECK-REPAIRS
REAR WINDOW
AIR HORN
BACK-UP ALARM

SSHOP-2019-180

Date Opened 6-9-2019 Date Finished 6-12-2019 Meter 1 Reading: 109,029

TASKS PERFORMED

NO PARTS USED

BRAKES

Service Requests:

06/09/2019 BRAKES / 18: LEAKING / EXCHANGE - NEW
BRAKE ISSUES RED WARNING LIGHT COMES ON WHEN BRAKING. BRAKE LINE 1 PRESSURE DROPS BELOW 100

Asset Work Order History 10196874

SSHOP-2019-182

Date Opened 6-11-2019 Date Finished 6-12-2019 Meter 1 Reading: 109,029

TASKS PERFORMED

Q PARTS

HEADLIGHTS LOW BEAM

2 TEE; HEADLIGHT HARNESS
2 TEE; HEADLIGHT HARNESS
2 LMP; LAMP

SSHOP-2019-211

Date Opened 7-6-2019 Date Finished 7-24-2019 Meter 1 Reading: 111,791

TASKS PERFORMED

Q PARTS

SHORELINE CHARGER

4 8GR; CONNECTOR
4 8GR; PLUG
1 9HW; 50103EXTENSIONCORD

SSHOP-2019-216

Date Opened 7-7-2019 Date Finished 7-9-2019 Meter 1 Reading: 111,062

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES
AIR HORN

2 9AP; HORN KIT, PAI, 3390-1094

Service Requests:

07/07/2019 ENGINE / 12: BROKEN / REPAIR
ENGINE-ENGINE LIGHT ON AIR HORN NOT WORKING PROPERLY

SSHOP-2019-59

Date Opened 2-28-2019 Date Finished 2-28-2019 Meter 1 Reading: 105,446

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM

SSHOP-2019-76

Date Opened 3-15-2019 Date Finished 3-21-2019 Meter 1 Reading: 106,647

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; NAPAGOLD OIL FILTER
22 4PC; 15W40 PB OIL DRM/QT
1 FIL; NAPA GOLD FUEL FILTER

Asset Work Order History 10196874

SSHOP-2019-77

Date Opened 3-15-2019 Date Finished 3-27-2019 Meter 1 Reading: 106,647

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	2	1AN; 22" WIPER BLADE
WIPERS-WASHER	1	BK; RADIATOR CAP
ENGINE COOLANT TEMPERATURE SE	1	NHD; FLUID RESERVOIR
HANDLIGHT	2	9AP; FILTER, REAR AC (TOTAL TRUCK)
ELECTRICAL	1	FIL; NAPA CABIN AIR FILTER
FILTER	4	8GR; FILTER
TRANSMISSION	1	FIL; NAPA TRANS FILTER
SUSPENSION	1	FIL; NAPA TRANS FILTER
AIR SYSTEM	2	2IH; TRANSYND
HVAC SYSTEM	4	2IH; VALVE, LEVELING
	2	2IH; SPRING AIR

SSHOP-2020-101

Comments: **OXYGEN SYSTEM AND SRS LIGHT**

Date Opened 3-31-2020 Date Finished 3-31-2020 Meter 1 Reading: 125,362

TASKS PERFORMED

Q PARTS

OXYGEN SENSOR	1	5EF; TRANSDUCER REPL 10004858
GLASS		
AIR BAG WARNING LIGHT		

Asset Work Order History 10196874

SSHOP-2020-173

Date Opened 6-4-2020

Date Finished

6-19-2020

Meter 1 Reading:

129,419

TASKS PERFORMED

WIPER BLADES
EXHAUST MANIFOLD
SERPENTINE BELT TENSIONER
ENGINE AND ACCESSORIES
AIR SYSTEM
FAULT CODE
HVAC SYSTEM

Q PARTS

2 1AN; 22 WIPER BLADE
1 2IH; 2IH
1 2IH; EXHAUST MANIFOLD
3 2IH; 2IH
3 2IH; 2IH
4 2IH; 2IH
4 2IH; BOLT
1 NBH; HD TENSIONER CUM 5270678
1 NBH; V RIBBED BELT
1 2IH; BELT
1 2IH; OIL PRESSURE SENSOR
1 2IH; SENSOR
1 FIL; NAPAGOLD OIL FILTER
1 2IH; PIPE AIR
22 4PC; 15W40 PB OIL DRM QT
1 2IH; CLAMP
1 2IH; CLAMP HEAT
2 2IH; CONNECTOR, SENSOR
10 TEM; TEM
1 ROB; FILTER
-3 9XX; 10177987 AC RECYCLER
1 2IH; SWITCH A C LOW PRESSURE
3 9XX; 10177987 AC RECYCLER
10 TEM; TEM
10 TEM; ORING
10 TEM; O RING
1 2IH; VALVE A C
10 TEM; O RINGS GREEN ROUND
3 9IP; FREON LB
1 SVP; COMPRESOR
2 TEM; PAG 100 OIL
10 TEM; ORING
1 SVP; DRIER

SSHOP-2020-194

Comments: **MISSING HORN BRACKET**

Date Opened 6-19-2020

Date Finished

6-22-2020

Meter 1 Reading:

129,425

TASKS PERFORMED

ENGINE AND ACCESSORIES
REPAIR FROM PM - A/C

Q PARTS

1 TWD; BRACKET AIR HORN GROVER
1 2IH; BLEND DOOR MOTOR
1 2IH; FILTER DRIER
1 2IH; VALVE A C

Asset Work Order History 10196874

SSHOP-2020-195

Date Opened 6-19-2020 Date Finished 6-22-2020 Meter 1 Reading: 129,425

TASKS PERFORMED

NO PARTS USED

PM SERVICE B

SSHOP-2020-221

Comments: **RIPE IN TIRE SIDE WALL**

Date Opened 7-2-2020 Date Finished 7-2-2020 Meter 1 Reading: 130,125

TASKS PERFORMED

NO PARTS USED

TIRES & WHEELS

Service Requests:

07/02/2020 TIRES / 12: BROKEN / INSPECTED TIRE CUT INTO SIDE WALL OF DRIVER. SENT PICTURES TO SC DRIVER SIDE TIRE. EXTERIOR SIDE WALL. PARTIAL TEAR.

SSHOP-2020-364

Comments: **POWER STEERING ROAD CALL**

Date Opened 11-5-2020 Date Finished 12-8-2020 Meter 1 Reading: 142,207

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	1	2IH; DPF NEW 4 DOOR
EXHAUST SYSTEM	1	2IH; 2IH
OIL	1	SVP; SVP
POWER STEERING PUMP	1	2IH; CORE DEPOSIT
	30	4PC; 15W40 PB OIL DRM QT
	1	FIL; NAPAGOLD OIL FILTER
	1	2IH; STEERING SHAFT
	1	2IH; PUMPPOWER

Service Requests:

11/04/2020 STEERING / /
POWER STEERING NO LONGER SMOOTH. STEERING VEHICLE IS INCONSISTENT.

SSHOP-2020-408

Date Opened 12-9-2020 Date Finished 12-9-2020 Meter 1 Reading: 142,207

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

Asset Work Order History 10196874

SSHOP-2020-83

Date Opened 3-11-2020 Date Finished 3-25-2020 Meter 1 Reading: 125,362

TASKS PERFORMED

PM SERVICE C RESCUE

<u>Q</u>	<u>PARTS</u>
1	2IH; AIR FILTER CAN ORDER 500804
22	4PC; 15W40 PB OIL DRM QT
1	FIL; NAPA GOLD FUEL FILTER
1	FIL; NAPAGOLD OIL FILTER

SSHOP-2020-84

Date Opened 3-11-2020 Date Finished 3-25-2020 Meter 1 Reading: 125,362

TASKS PERFORMED

WIPER BLADES
SERPENTINE BELT
ENGINE AND ACCESSORIES
BATTERY
TRANSMISSION
VENDOR TIRE REPAIR/CHANGE
SUSPENSION
POWER STEERING PUMP
BRAKES
BODY EXTERIOR
SEAT BELTS
HVAC SYSTEM

<u>Q</u>	<u>PARTS</u>
2	1AN; 22 WIPER BLADE
1	2IH; BELT A C
1	2IH; IDLER PULLEY
1	2IH; BELT TENSIONER V8
1	SVP; SVP
1	2IH; DPF NEW 4 DOOR
1	SVP; DPF GSKT 2601233C1
3	1AD; BATTERY GROUP 31
1	2DD; FILTER TRANS SPIN ON
2	1GY; SPRING AIR
2	2IH; POWER STEERING FLUID 32OZ
1	FIL; POWER STEERING FILTER
12	CRC; CLEANRCARB16OZ
1	2IH; BRAKE PEDAL PAD
2	TWD; BRAKE DRUM
-2	TWD; BRAKE DRUM
2	MBI; GRIP KIT
2	TWD; SLACK ADJUSTER KIT
2	MBI; GRIP KIT
2	TWD; BRAKEDRUM
2	2GU; BRAKE DRUM 15 X 4
2	9HD; FILTER CABIN 7 75X14 5
2	2IH; FILTER CAB A C INT BX BLUE
1	2RD; FILTER 6 45X7 75 BLK FOAM
1	FIL; NAPA CABIN AIR FILTER

SSHOP-2021-121

Comments: **ON CALL REPAIR RF HEADLAMP OUT**

Date Opened 3-23-2021 Date Finished 4-1-2021 Meter 1 Reading: 147,621

TASKS PERFORMED

HEADLIGHTS LOW BEAM

<u>Q</u>	<u>PARTS</u>
1	9ES; BULB LED SUPER BRIGHT

Asset Work Order History 10196874

SSHOP-2021-2

Comments: **NEEDS DRIVE BELTS AN SMALL AIR LEAK CAN BE USED IF NEEDED**

Date Opened 1-4-2021 Date Finished 1-6-2021 Meter 1 Reading: 142,207

TASKS PERFORMED

Q PARTS

COOLANT 1 2IH; BELT A C
DRIVE BELT 1 2IH; BELT

SSHOP-2021-9

Comments: **AIR HORNS NOT WORKING. REAR NOT DUMPING. LOCK FOR STRETCHER**

Date Opened 1-7-2021 Date Finished 1-12-2021 Meter 1 Reading: 142,207

TASKS PERFORMED

Q PARTS

STRETCHER 2 5HA; MODULE NEO CONTROL KNEEL MOD
AIR BAG SYSTEM 1 FREIGHT
AIR HORN 2 9AP; HORN KIT PAI 3390 1094

SSHOP-2022-138

Comments: **INSPECTION**

Date Opened 4-18-2022 Date Finished 5-10-2022 Meter 1 Reading: 159,688

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER 2 2IH; CLAMP INJECTOR HOLD DOWN
QUALITY CHECK-REPAIRS 1 2CU; EGR ELBOW
EXHAUST SYSTEM 1 2CU; CORE DEPOSIT
EGR COOLER 1 2CU; EGR COOLER KIT
LIGHTING SYSTEM 1 2IH; EGR TUBE HOSE
HVAC SYSTEM 1 2IH; SEAL
1 9HD; DPF FILTER RW 5010847R1
8 2IH; O RING

SSHOP-2022-249

Date Opened 5-19-2022 Date Finished 6-7-2022 Meter 1 Reading: 161,546

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
QUALITY CHECK-REPAIRS

SSHOP-2022-376

Date Opened 7-7-2022 Date Finished 7-11-2022 Meter 1 Reading: 161,890

TASKS PERFORMED

NO PARTS USED

PRE TRIP INSPECTION

Asset Work Order History 10196874

SSHOP-2022-381

Comments: **EXHAUST LEAK / LOW OIL PRESSURE WARNING - MULTIPLE REPAIRS ATTEMPTED / OIL LEAKS**

Date Opened 7-8-2022 Date Finished 10-24-2022 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

VENDOR? RECHTIEN INTERNATIONAL TRUCKS

SSHOP-2022-928

Comments: **DPF FILTER AND OIL CHANGE**

Date Opened 11-15-2022 Date Finished 11-15-2022 Meter 1 Reading: 163,370

TASKS PERFORMED

Q PARTS

DPF FILTER
OIL

1 90C; OIL CUMMINS 6 7 18QTS
1 FIL; NAPAGOLD OIL FILTER

SSHOP-2023-1060

Comments: **ON CALL**

Date Opened 9-10-2023 Date Finished 9-13-2023 Meter 1 Reading: 173,305

TASKS PERFORMED

Q PARTS

DPF FILTER
OIL
CHECK ENGINE LIGHT

1 2IH; DPF GASKET
1 2IH; DPF GASKET
1 2IH; CORE DEPOSIT
1 2IH; DPF FILTER
22 4PC; 15W40 PB OIL DRM QT
1 FIL; NAPAGOLD OIL FILTER

SSHOP-2023-1080

Comments: **PAT HVAC**

Date Opened 9-13-2023 Date Finished 12-8-2023 Meter 1 Reading: 176,856

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

-1 TEM; STEEL FILTER DRIER
1 TEM; STEEL FILTER DRIER
1 2IH; COMPRESSOR A C
1 2IH; SENSOR EVAP TEMP
1 TEM; STEEL FILTER DRIER

SSHOP-2023-462

Date Opened 5-2-2023 Date Finished 5-2-2023 Meter 1 Reading: 169,818

TASKS PERFORMED

NO PARTS USED

QUALITY CHECK-REPAIRS

Asset Work Order History 10196874

SSHOP-2023-534

Date Opened 5-19-2023 Date Finished 7-31-2023 Meter 1 Reading: 172,623

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	1	2IH; AIR FILTER
NARCS BOX ELECTRONIC LOCK INSTALL -	1	9AP; O2 WRENCH
RESCUES	1	5EF; CHEVRON 12 LED RED
KNOX UPGRADE PROJECT	1	9ES; PIEZO BUZZERS AMP AUDIO INDICATORS 88 DBA
A INSPECTION		
AIR FILTER		
REPAIR FROM PM - O2 SYSTEM		
LIGHTING SYSTEM		
DOOR ALARM OR OTHER WARNING		
HVAC SYSTEM		

SSHOP-2023-722

Comments: **CHECK ENGINE LIGHT**
Date Opened 6-27-2023 Date Finished 8-2-2023 Meter 1 Reading: 172,623

TASKS PERFORMED

NO PARTS USED

FAULT CODE

SSHOP-2023-817

Comments: **UNIT WITH MULTIPLE LIGHTS ON AND DERATE**
Date Opened 7-17-2023 Date Finished 7-17-2023 Meter 1 Reading: 172,623

TASKS PERFORMED

NO PARTS USED

SWAP UNIT INTO SPARE
FAULT CODE
