

6/3/2026
1:51:29 PM

Palm Beach County Fleet Management Asset Maintenance History
10193017 2014 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, 4X4

Total Hours: 245.90		Labor: 16,755.20		Parts: 14,144.41		Comm: 9,400.23		Charged: 40299.83	
Work Order: 1312202		Meter: 312				In Date: 12/06/2013		Closed: 12/18/2013	
Problem: fill def fluid									
Work Completed				Parts Issued		Quantity			
- Parts Only				Def Quart		1.00			
Hours: 0.00		Comm: 0.00		Labor: 0.00		Parts: 1.55		Total: 1.55	
Work Order: 1312664		Meter: 313				In Date: 12/19/2013		Closed: 12/19/2013	
Problem: 1061 - Pre Delivery Inspection									
Work Completed									
- Pre Delivery Inspection									
Hours: 5.00		Comm: 0.00		Labor: 300.00		Parts: 0.00		Total: 300.00	
Work Order: 1400673		Meter: 332				In Date: 01/21/2014		Closed: 02/28/2014	
Problem: Install strobe lights on utility body.Remove water cooler rack and rear window guard per request.									
Work Completed				Parts Issued		Quantity			
- Fabricate and install strobe light on body per request.remove water cooler rack and headache rack per dept request.				M4 Series Led Surface Mount Light		2.00			
				M4 Series Chrome Flange		2.00			
- Shop Supplies				Shop Supplies		1.00			
				Freight Charge		1.00			
Hours: 4.00		Comm: 0.00		Labor: 240.00		Parts: 407.58		Total: 647.58	

6/3/2026
1:51:29 PM

Palm Beach County Fleet Management Asset Maintenance History
10193017 2014 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, 4X4

Work Order: 1403136 **Meter:** 908 **In Date:** 03/31/2014 **Closed:** 04/24/2014
Problem: Install additional light per request.

Work Completed

- Fabricate and mount four new additional Led flashing lights and two other lights to the front.make up wiring harness and spliced into strobe lights power ststem.install fuse holder.

- Fabricate and install two auxiliary power outlets in front comparment of bed.make up and install wire harness for power and ground.install fuse holder.install sun pass and bracket.

- Shop Supplies

Parts Issued

Quantity

Pwr Outl	2.00
Fuse Holder	2.00
bracket	1.00
M4 Series Led Surface Mount Light	4.00
M4 Series Chrome Flange	4.00
Fab Loom-split Poly	5.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 10.00

Comm: 0.00

Labor: 600.00 Parts: 858.04 Total: 1,458.04

Work Order: 1405789 **Meter:** 996 **In Date:** 06/12/2014 **Closed:** 06/25/2014
Problem: P.M. Service.Tail gate not closing.Driver side rear body damage,rear bumper rust.

Work Completed

- Perform pm service.

- Rotate and balance all six tires.

- Inspect and service power winch.

- Shop Supplies

Parts Issued

Quantity

15-40 Oil	13.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Used Fire X Refurbished	1.00
Floor Mat-2pc Rub Bk	1.00
Def Quart	2.00
Shop Supplies	1.00

Hours: 6.50

Comm: 0.00

Labor: 390.00 Parts: 138.94 Total: 528.94

Work Order: 1406768 **Meter:** 996 **In Date:** 06/19/2014 **Closed:** 07/09/2014
Problem: damage to lft side of body & repaint rear bumper

Work Completed

- damage to lft side of body & repaint rear bumper

Hours: 0.00

Comm: 912.00

Labor: 0.00

Parts: 0.00

Total: 912.00

6/3/2026
1:51:29 PM

Palm Beach County Fleet Management Asset Maintenance History
10193017 2014 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, 4X4

Work Order: 1410695 **Meter:** 1444 **In Date:** 09/24/2014 **Closed:** 10/27/2014
Problem: damage to left side of bed & bin doors

Work Completed

- damage to left side of bed & bin doors

Hours: 0.00 Comm: 736.80 Labor: 0.00 Parts: 0.00 Total: 736.80

Work Order: 1500229 **Meter:** 1973 **In Date:** 01/07/2015 **Closed:** 02/26/2015
Problem: P.M. service.

Work Completed

- P.m. Service.
- Rotate and balance six tires.
- Inspect and service winch.
- Inspect and replace four defective red horizontal Led strobe lamps.r&r grill
for access.fabricate wiring as needed.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	13.00
Napagold Oil Filter	1.00
Fuel Filter Kit	1.00
Wiper Blade	2.00
Cap	1.00
Floor Mat-2pc Rub Bk	1.00
Horz Red Led Lightheads	4.00
Shop Supplies	1.00

Hours: 8.50 Comm: 0.00 Labor: 510.00 Parts: 587.74 Total: 1,097.74

Work Order: 1508230 **Meter:** 2572 **In Date:** 08/17/2015 **Closed:** 08/31/2015
Problem: Pm service.Mount sunpass on front bumper.

Work Completed

- Pm service.
- Inspect and service winch.
- Rotate and balance all six wheels.
- Fabricate and install sun pass on front bumper.

Parts Issued

Quantity

15-40 Oil	13.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Wiper Blade	2.00
Def Quart	4.00
Shop Supplies	1.00

Hours: 6.80 Comm: 0.00 Labor: 408.00 Parts: 110.27 Total: 518.27

6/3/2026
1:51:29 PM

Palm Beach County Fleet Management Asset Maintenance History
10193017 2014 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, 4X4

Work Order: 1601716 **Meter:** 3053 **In Date:** 02/18/2016 **Closed:** 02/29/2016
Problem: Pm service.

Work Completed

- Pm service.
- Rotate and balance all six tires.
- Service winch.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	13.00
22" Wiper Blade	2.00
Macs Chain Cable Lube	1.00
Fuel Filter Kit	1.00
Def Quart	1.00
Shop Supplies	1.00

Hours: 6.50

Comm: 0.00

Labor: 390.00 Parts: 162.56 Total: 552.56

Work Order: 1608719 **Meter:** 3466 **In Date:** 08/22/2016 **Closed:** 09/28/2016
Problem: P.M. service and had to jump start and recall 14e03.

Work Completed

- P.m. Service.
- Rotate and balance all tires.
- Test batteries and charging system.replace both bad batteries.
- Replace bent left bin door hinges.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	13.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Fuel Filter Kit	1.00
Used Fire X Refurbished	1.00
Battery 65	2.00
Cargo Door Hinge	4.00
Def Bulk Qts	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 9.50

Comm: 0.00

Labor: 570.00 Parts: 720.61 Total: 1,290.61

6/3/2026
1:51:29 PM

Palm Beach County Fleet Management Asset Maintenance History
10193017 2014 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, 4X4

Work Order: 1703042 **Meter:** 4397 **In Date:** 03/27/2017 **Closed:** 04/10/2017
Problem: P.M. Seervice.

Work Completed

- P.m. Service.
- Replace two tires,rotate and balance all four.
- Inspect and service winch.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	13.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Air Filter (gold), Air Panel	1.00
Def Bulk Qts	3.00
Tire	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 7.00

Comm: 0.00

Labor: 420.00

Parts: 660.11

Total: 1,080.11

Work Order: 1703133 **Meter:** 4256 **In Date:** 03/29/2017 **Closed:** 03/29/2017
Problem: rear bed cover latch broken

Work Completed

- Fab locking rod and adjust latch for rear bed cover door
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 2.50

Comm: 0.00

Labor: 150.00

Parts: 2.00

Total: 152.00

Work Order: 1704819 **Meter:** 4539 **In Date:** 05/15/2017 **Closed:** 05/24/2017
Problem: Missing front tank fuel cap.

Work Completed

- Replace missing fuel cap for front tank.

Parts Issued

Quantity

Fuel Cap	1.00
----------	------

Hours: 0.20

Comm: 0.00

Labor: 12.00

Parts: 20.04

Total: 32.04

Work Order: 1704919 **Meter:** 4525 **In Date:** 05/17/2017 **Closed:** 05/17/2017
Problem: 10 - Wash ticket(s) issued

Work Completed

- 10 - Wash ticket(s) issued

Hours: 0.00

Comm: 95.40

Labor: 0.00

Parts: 0.00

Total: 95.40

6/3/2026
1:51:29 PM

Palm Beach County Fleet Management Asset Maintenance History
10193017 2014 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, 4X4

Work Order: 1709439 **Meter:** 5607 **In Date:** 09/27/2017 **Closed:** 10/31/2017
Problem: P.M. service and check engine light.

Work Completed

- P.m. service.
- Inspect and service power winch.
- Rotate and balance six tires.
- Transport to and from dealer for check engine light P1552, P2002.replace particulate filter and # two injector.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	13.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Blue Df	1.00
Shop Supplies	1.00

Hours: 8.50

Comm: 0.00

Labor: 510.00	Parts: 116.42	Total: 626.42
---------------	---------------	---------------

Work Order: 1712707 **Meter:** 5845 **In Date:** 12/27/2017 **Closed:** 01/19/2018
Problem: Locking inop on bed cover.

Work Completed

- Fabricate and install sliding bed cover lock rod.
- Shop Supplies

Parts Issued

Quantity

Lock Rod	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 0.50

Comm: 0.00

Labor: 30.00	Parts: 78.60	Total: 108.60
--------------	--------------	---------------

6/3/2026
1:51:29 PM

Palm Beach County Fleet Management Asset Maintenance History
10193017 2014 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, 4X4

Work Order: 1805030 **Meter:** 6081 **In Date:** 05/15/2018 **Closed:** 05/21/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Replace four tires . Rotate and high speed balance all six tires. Nitrofill tires.
- Inspect and service winch.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	13.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Slip Plate Spray 12oz	1.00
Napagold Fuel Filter	1.00
Used Fire X Refurbished	1.00
Blue Df	1.00
Tire	4.00
Tr416 Valve Stem	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 8.00

Comm: 0.00

Labor: 480.00

Parts: 1,097.32

Total: 1,577.32

Work Order: 1808848 **Meter:** 6436 **In Date:** 08/27/2018 **Closed:** 08/27/2018
Problem: NO START

Work Completed

- Tow From: 20 Military Trail (eoc) To: Lv Shop

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

Work Order: 1808857 **Meter:** 6500 **In Date:** 08/28/2018 **Closed:** 09/04/2018
Problem: Towed in for no start.

Work Completed

- Test both batteries .both failed load test after charge . Replace both defective batteries. Retest staring and charging systems .check for draws .
- Shop Supplies

Parts Issued

Quantity

Battery 65	2.00
Shop Supplies	1.00

Hours: 2.00

Comm: 0.00

Labor: 120.00

Parts: 334.94

Total: 454.94

6/3/2026
1:51:29 PM

Palm Beach County Fleet Management Asset Maintenance History
10193017 2014 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, 4X4

Work Order: 1810810 **Meter:** 6708 **In Date:** 10/19/2018 **Closed:** 10/24/2018
Problem: Request to carry DEF for travel.

Work Completed

- Fill request for exhaust fluid For travel to pan handle.
- Shop Supplies

Hours: 0.50

Comm: 0.00

Parts Issued

Quantity

Blue Df	2.00
Shop Supplies	1.00
Labor: 33.50	Parts: 32.07
Total: 65.57	

Work Order: 1811661 **Meter:** 8310 **In Date:** 11/14/2018 **Closed:** 11/29/2018
Problem: P.M. Service.

Work Completed

- P.m. service.
- Rotate and high speed balance all six tires. Nitrofill all.
- Inspect and service winch.
- Shop Supplies

Hours: 6.50

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	13.00
22" Wiper Blade	2.00
Napagold Fuel Filter	1.00
Blue Df	1.00
Pintle Pin W/clip	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00
Labor: 435.50	Parts: 135.26
Total: 570.76	

Work Order: 1905419 **Meter:** 8985 **In Date:** 05/20/2019 **Closed:** 05/29/2019
Problem: P.M. SAervice.

Work Completed

- P.m. service. Install steering wheel cover .
- Inspect and service winch .
- Rotate and high speed balance all four tires . Nitrofill all.
- Shop Supplies

Hours: 6.50

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	13.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Blue Df	1.00
Napagold Fuel Filter	1.00
Ford Triton Pvc Swc	1.00
Shop Supplies	1.00
Labor: 435.50	Parts: 141.47
Total: 576.97	

6/3/2026
1:51:29 PM

Palm Beach County Fleet Management Asset Maintenance History
10193017 2014 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, 4X4

Work Order: 1906888 **Meter:** 9527 **In Date:** 07/01/2019 **Closed:** 07/03/2019
Problem: Whining noise from under hood.Check tire pressures.

Work Completed

- Test drive and started several times ,could not duplicate concern . Check tire pressure all the way around vehicle . 75 psi in front tires and 65 psi in rear tires .

Hours: 0.50 Comm: 0.00 Labor: 33.50 Parts: 0.00 Total: 33.50

Work Order: 1911771 **Meter:** 9929 **In Date:** 11/13/2019 **Closed:** 11/25/2019
Problem: P.M. Service.Check engine light on,screw missing from camera bracket.

Work Completed

- P.m. service.
- Computer diagnose check engine light , code P20c1 and P20c2 . Perform pinpoint test . Remove reductant tank to replace defective reductant heater sender assembly . Clear codes and retest .
- Extract broken screw from rear camera bracket and replace with rivet .
- Inspect and service winch .
- Rotate and balance all six tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	13.00
Napagold Fuel Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Blue Df	1.00
Def Pump	1.00
Shop Supplies	1.00

Hours: 10.80 Comm: 0.00 Labor: 788.40 Parts: 549.58 Total: 1,337.98

Work Order: 1912046 **Meter:** 9905 **In Date:** 11/20/2019 **Closed:** 11/20/2019
Problem: 5 - Wash ticket(s) issued

Work Completed

- 5 - Wash ticket(s) issued

Hours: 0.00 Comm: 47.70 Labor: 0.00 Parts: 0.00 Total: 47.70

6/3/2026
1:51:29 PM

Palm Beach County Fleet Management Asset Maintenance History
10193017 2014 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, 4X4

Work Order: 1912578 **Meter:** 10135 **In Date:** 12/09/2019 **Closed:** 12/18/2019
Problem: Check engine light and left front utility box lock inop.

Work Completed

Parts Issued

Quantity

- Computer diagnose check engine light , code P20c1 ,p20c2 . Remove Def tank to replace defective heater assembly . Clear codes and retest .
Recalibrate Sccr .

Px Blue Threadlocker	1.00
Reservoir	1.00
Shop Supplies	1.00

- Drill hole in center box to access latch assembly in front box . Reattach lock rod and bolt to latch assembly . Retest operation .

- Shop Supplies

Hours: 4.00

Comm: 0.00

Labor: 292.00

Parts: 386.31

Total: 678.31

Work Order: 2001394 **Meter:** 10308 **In Date:** 02/10/2020 **Closed:** 02/18/2020
Problem: Check engine light on .

Work Completed

Parts Issued

Quantity

- Computer diagnose check engine light , P2001 ,b0090 . Perform pinpoint test . Replace defective power relay for glow plug module . Perform self test . and clear codes .

Relay	1.00
Shop Supplies	1.00

- Shop Supplies

Hours: 1.50

Comm: 0.00

Labor: 109.50

Parts: 24.60

Total: 134.10

Work Order: 2004705 **Meter:** 10407 **In Date:** 05/11/2020 **Closed:** 05/21/2020
Problem: P.M. service.

Work Completed

Parts Issued

Quantity

- P.m. service.

Napagold Oil Filter	3.00
---------------------	------

- Diagnose fuel pump erratic noise . R&r defective fuel pump assembly . Bleed fuel system . Retest .

15-40 Oil	13.00
-----------	-------

- Fabricate and replace front faded asset number .

Napagold Fuel Filter	1.00
----------------------	------

- Inspect and service winch .

22" Wiper Blade	2.00
-----------------	------

- Rotate and balance all six tires . Nitrofill all .

Washer Fluid Concentr	1.00
-----------------------	------

- Shop Supplies

Blue Df	1.00
---------	------

pump asy	1.00
----------	------

Shop Supplies	1.00
---------------	------

Hours: 10.00

Comm: 0.00

Labor: 730.00

Parts: 769.77

Total: 1,499.77

6/3/2026
1:51:29 PM

Palm Beach County Fleet Management Asset Maintenance History
10193017 2014 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, 4X4

Work Order: 2006873 **Meter:** 10603 **In Date:** 07/14/2020 **Closed:** 07/14/2020
Problem: 5 - Wash ticket(s) issued

Work Completed

- 5 - Wash ticket(s) issued

Hours: 0.00 Comm: 47.70 Labor: 0.00 Parts: 0.00 Total: 47.70

Work Order: 2011833 **Meter:** 10974 **In Date:** 11/30/2020 **Closed:** 12/09/2020
Problem: Due for PM. Loud noise then no power .

Work Completed

- Preventive Maint. Service

- loud noise engine lose power diagnose with computer air charge hose broken R/r with new code poo8a low pressure fuel system or mass volume flow . Clear codes and retest .

-

test batteries and charging system battery failed Replace both battery

- Rotate and hi speed balance all six tires . Nitro fill all.

- broken pintle install new

- inspect and service winch

- diagnose camera system . camera f ailed . R&r defective camera system and fabricate mounts . Retest operation .

diagnose camera system camera failed remove and replace camera system with new

- Shop Supplies

Hours: 15.70 Comm: 0.00 Labor: 1,146.10 Parts: 868.45 Total: 2,014.55

Parts Issued

Quantity

Napagold Fuel Filter	1.00
15-40 Oil	13.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Blue Df	1.00
22" Wiper Blade	2.00
Mac Wite Lithium Gres	1.00
Air Filter (gold), Air Panel	1.00
Tube - Outlet	1.00
Battery 65	2.00
Pintle Pin W/clip	1.00
Backup Cam Kit w/mirror	1.00
Shop Supplies	1.00

6/3/2026
1:51:29 PM

Palm Beach County Fleet Management Asset Maintenance History
10193017 2014 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, 4X4

Work Order: 2102912 **Meter:** 11150 **In Date:** 03/16/2021 **Closed:** 04/07/2021
Problem: Screw/ bolt in drivers rear outside tire Check engine light on . Asset will be on location by 09:00am. 03/16.

Work Completed

- Computer diagnose check engine light , code P1557 . Perform pinpoint test . Perform complete fuel injector flush and cleaning . Retest and clear code . Road test .
- Repair left rear tire and balance . Nitro fill all.
- Transport to and from dealer for repair . Check engine light on
- Shop Supplies

Parts Issued

Quantity

Kq22932df Diesel Inje	1.00
Sta-bil Fuel Stabilzr	1.00
Napagold Fuel Filter	1.00
Big G Degreaser 1 Gal	1.00
Shop Supplies	1.00

Hours: 5.50 Comm: 858.79 Labor: 401.50 Parts: 151.44 Total: 1,411.73

Work Order: 2106383 **Meter:** 11352 **In Date:** 06/11/2021 **Closed:** 06/17/2021
Problem: PM Service. Back up camera not working. Rear- bed mounted emergency lights not working.

Work Completed

- Preventive Maint. Service
- Pin Point Check Back Up Camera And Rear Strobe Lamp Circuits Not Working. Repaired Ground Wire For Shared Circuit And Verify Repair Complete.
- Rotate And Balance Six Tires. Nitro fill all.
- Inspect And Service Power Winch.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	13.00
Blue Df	2.00
Fuel Fil	1.00
22" Wiper Blade	2.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00

Hours: 7.50 Comm: 0.00 Labor: 547.50 Parts: 191.22 Total: 738.72

Work Order: 2106945 **Meter:** 11352 **In Date:** 06/24/2021 **Closed:** 06/24/2021
Problem: 5 - Wash ticket(s) issued

Work Completed

- 5 - Wash ticket(s) issued

Hours: 0.00 Comm: 47.70 Labor: 0.00 Parts: 0.00 Total: 47.70

6/3/2026
1:51:29 PM

Palm Beach County Fleet Management Asset Maintenance History
10193017 2014 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, 4X4

Work Order: 2108572 **Meter:** 11420 **In Date:** 08/09/2021 **Closed:** 08/11/2021
Problem: Front passenger window will not close. It is stuck opened.

Work Completed

Parts Issued

Quantity

- Diagnose right front window stuck down .remove right front door panel to replace broken window regulator . Adjust and retest .
- Shop Supplies

Window Regulator	1.00
Shop Supplies	1.00

Hours: 2.10 Comm: 0.00 Labor: 153.30 Parts: 128.49 Total: 281.79

Work Order: 2112674 **Meter:** 11601 **In Date:** 11/30/2021 **Closed:** 12/15/2021
Problem: PM Service. noise under hood and slow to crack

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Rotated and balanced all 6 tires. Nitrogen filled all tires.
- Charged both batteries fully. Tested starting and charging system and all is ok at this time. Tested for system draw and nothing found
- Replaced all 8 dry rotted cab mounts.
- Inspect and serviced winch
- Shop Supplies

Napagold Fuel Filter	1.00
22" Wiper Blade	2.00
15-40 Oil	13.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Blue Def 2.5 Gallon	1.00
Body Mount Kit	6.00
Body Mount Kit	2.00
Filler Breather	1.00
Shop Supplies	1.00

Hours: 15.50 Comm: 0.00 Labor: 1,131.50 Parts: 792.13 Total: 1,923.63

Work Order: 2200920 **Meter:** 11730 **In Date:** 01/26/2022 **Closed:** 01/27/2022
Problem: Loud clunking noise from front tire area on turns or over bumps. Possible cab mounts.

Work Completed

Parts Issued

Quantity

- Road test for noise , hook up chassis ears . Replace missing mounting bolt and nut for right side front of bed . Road test
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.50 Comm: 0.00 Labor: 109.50 Parts: 2.65 Total: 112.15

6/3/2026
1:51:29 PM

Palm Beach County Fleet Management Asset Maintenance History
10193017 2014 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, 4X4

Work Order: 2207084 **Meter:** 12083 **In Date:** 07/06/2022 **Closed:** 07/14/2022
Problem: PM Service. locking rods on camper top bent and white strobe on left visor light out .

Work Completed

- Preventive Maint. Service Straightened lock rod for topper.
- Rotated and balanced all 6 tires. Nitrogen filled all tires.
- Inspect and serviced winch
- Diagnose visor strobe inop. Found to have bad bulb. Replaced Bulb.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Qt 15w40	1.00
Prem Blue 15w40 1 Gal	3.00
22" Wiper Blade	2.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00

Hours: 8.00

Comm: 0.00

Labor: 584.00 Parts: 140.33 Total: 724.33

Work Order: 2208523 **Meter:** 12303 **In Date:** 08/16/2022 **Closed:** 10/06/2022
Problem: Check engine light on.

Work Completed

- Scan computer P0087, Inspect vehicle fuel system, remove primary fuel filter. No fuel supply system issues found. Transport to and from dealer for repair .
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 6,549.55

Labor: 73.00 Parts: 2.65 Total: 6,625.20

Work Order: 2212710 **Meter:** 12435 **In Date:** 12/19/2022 **Closed:** 01/04/2023
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- rotate and balance all 6 tires nitro fill all
- lube and service winch
- batteries failed load test during inspection replace batteries and retest charge system operating at manufacture specs
- Shop Supplies

Parts Issued

Quantity

Napagold Fuel Filter	1.00
Mac Wite Lithium Gres	1.00
22" Wiper Blade	2.00
15-40 Oil	13.00
Napagold Oil Filter	1.00
Battery	2.00
Shop Supplies	1.00

Hours: 8.50

Comm: 0.00

Labor: 620.50 Parts: 449.14 Total: 1,069.64

6/3/2026
1:51:29 PM

Palm Beach County Fleet Management Asset Maintenance History
10193017 2014 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, 4X4

Work Order: 2306776 **Meter:** 13479 **In Date:** 07/10/2023 **Closed:** 07/17/2023
Problem: PM Service and bent rear door locking rod.

Work Completed

- Preventive Maint. Service
- Rotate and speed balance all six, nitro fill
- Inspect and service winches
- Straighten Bent rear door locking rod,
- Left rear brake light water intrusion, R & L new lamp
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Qt 15w40	13.00
Fuel Filter	1.00
Used Fire X Refurbished	1.00
Tire Crayon	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Blue Df	1.00
Cabin Air Filter	1.00
Led Mdl 45 S T T 12v	1.00
Shop Supplies	1.00

Hours: 7.30

Comm: 0.00

Labor: 532.90 Parts: 183.41 Total: 716.31

Work Order: 2308360 **Meter:** 13750 **In Date:** 08/21/2023 **Closed:** 08/28/2023
Problem: Front Passenger tire seems dry rotted/ worn.

Work Completed

- Mount, balance and nitro service 6 tires
- Perform front wheel alignment
- Shop Supplies

Parts Issued

Quantity

Lt 245/75/17titr Mic	6.00
Tr416 Valve Stem	6.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 5.50

Comm: 0.00

Labor: 401.50 Parts: 1,612.31 Total: 2,013.81

Work Order: 2310620 **Meter:** 13773 **In Date:** 10/20/2023 **Closed:** 10/23/2023
Problem: (2) nails/ screws in passenger rear outside tire. Will wait at shop for repair.

Work Completed

- nail did not puncture tire,so repair performed

Hours: 0.20

Comm: 0.00

Labor: 14.60 Parts: 0.00 Total: 14.60

6/3/2026
1:51:30 PM

Palm Beach County Fleet Management Asset Maintenance History
10193017 2014 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, 4X4

Work Order: 2312178 **Meter:** 13893 **In Date:** 12/07/2023 **Closed:** 12/15/2023
Problem: Check engine light on.

Work Completed

Parts Issued

Quantity

- Perform battery recovery charge. Both batteries low, Test batteries, pass.
- Scan diagnose code, P06e5, P2a01. All codes caused from low battery state of charge. Perform glow plug module tests all Ok.
- Replace wiper blades.
- Shop Supplies

Wiper Blade	2.00
Shop Supplies	1.00

Hours: 2.30 Comm: 0.00 Labor: 167.90 Parts: 10.90 Total: 178.80

Work Order: 2400512 **Meter:** 13988 **In Date:** 01/17/2024 **Closed:** 01/29/2024
Problem: PM Service and check engine light on

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Rotated and balanced all 6 tires. Nitrogen filled all tires.
- Computer diagnose check engine light. Code-p2a01. Found to have bad Nox sensor. R&r faulty sensor. Cleared code and test drove
- Diagnose noise going over bumps Found one cab mount to be collapsed behind drives front wheel. R&r faulty cab mount
- Shop Supplies

Napagold Oil Filter	1.00
Napa Qt 15w40	13.00
Wiper Blade	2.00
Fuel Filter	1.00
Body Mount Kit	1.00
Sensor	1.00
Shop Supplies	1.00

Hours: 9.50 Comm: 0.00 Labor: 693.50 Parts: 428.28 Total: 1,121.78

Work Order: 2404286 **Meter:** 14200 **In Date:** 04/30/2024 **Closed:** 05/16/2024
Problem: will start up fine and then not start later, and then start up fine again. Water leak , check clucking on turns

Work Completed

Parts Issued

Quantity

- Both batteries tested below 50% charge. Charge and retest, failed load test, Replace batteries.
- Seal roof marker lights, Id bar lights out. Replace rear Id bar light.
- Starter amp draw high, perform oscilloscope test, one partially open winding. Replace starter.
- Spray lube and grease suspension.
- Shop Supplies

6 Inch Id Bar Kit	1.00
Starter Motor Assy	1.00
Battery	2.00
Shop Supplies	1.00

Hours: 5.00 Comm: 0.00 Labor: 365.00 Parts: 772.56 Total: 1,137.56

6/3/2026
1:51:30 PM

Palm Beach County Fleet Management Asset Maintenance History
10193017 2014 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, 4X4

Work Order: 2406599 **Meter:** 14548 **In Date:** 07/09/2024 **Closed:** 07/17/2024
Problem: PM Service

Work Completed

- Preventive Maint. Service
- rotate and balance all 6 tires nitro fill all
- inspect winch and cable lube all moving parts verify electrical connections
- customer states Rear bed hatch difficult to lock/ secure. latch wound to be binding found pivot point to be bent lube and re bend backing plate .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Qt 15w40	13.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Fuel Filter	1.00
Blue Df	1.00
Big G Degreaser 1 Gal	1.00
White Lithium Grease	1.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 511.00

Parts: 174.40

Total: 685.40

Work Order: 2407996 **Meter:** 14580 **In Date:** 08/19/2024 **Closed:** 08/27/2024
Problem: battery died. jumped to get it to fleet. Check engine light is on.

Work Completed

- Test batteries, secondary battery low, recharge both batteries, retest starting and charging system, Good. Normal draw indicated. no codes.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

Work Order: 2409623 **Meter:** 15250 **In Date:** 10/03/2024 **Closed:** 10/09/2024
Problem: Check engine light is on

Work Completed

- Diagnose check engine light. Codes- P2201 and P1557. pinpoint test and found to have faulty. B1s1 Nox sensor. R&r bad sensor and added fuel system cleaner. Cleared codes and test drove.
- Shop Supplies

Parts Issued

Quantity

Diesel Cond Clnr 32oz	1.00
Nox Sensor	1.00
Shop Supplies	1.00

Hours: 2.50

Comm: 0.00

Labor: 182.50

Parts: 320.20

Total: 502.70

6/3/2026
1:51:30 PM

Palm Beach County Fleet Management Asset Maintenance History
10193017 2014 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, 4X4

Work Order: 2501068 **Meter:** 15436 **In Date:** 02/03/2025 **Closed:** 02/19/2025
Problem: PM Service

Work Completed

- Preventive Maint. Service
- Check Engine Light On Diagnose And Scan P245a Egr Bypass Valve Stuck Open & P0278 Cylinder 7 Injector Performance Omed Out Injector And Over Spec Replace Injector Code To Ecm 05a0a7e028 And Retest
- Balance And Rotate All 6 Tires With Nitro Fill
- Right Front Yellow Running Light Blown Test For Power And Ground Replace And Wire In New Light Retest
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Qt 15w40	13.00
Wiper Blade	2.00
Fuel Filter	1.00
Blue Df	1.00
Lamp Kit	1.00
Valve Assy	1.00
Kit Injector	1.00
Shop Supplies	1.00

Hours: 11.50

Comm: 0.00

Labor: 839.50

Parts: 577.47

Total: 1,416.97

Work Order: 2501985 **Meter:** 15445 **In Date:** 02/19/2025 **Closed:** 02/27/2025
Problem: 1 - Wash ticket(s) Issued to: Justin Klosenberg

Work Completed

- 1 - Wash ticket(s) Issued to: Justin Klosenberg

Hours: 0.00

Comm: 8.59

Labor: 0.00

Parts: 0.00

Total: 8.59

Work Order: 2506779 **Meter:** 15545 **In Date:** 07/23/2025 **Closed:** 07/24/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 3.00

Comm: 0.00

Labor: 219.00

Parts: 0.00

Total: 219.00

Total Hours: 245.90

Total Labor: 16,755.20

Total Comm: 9,400.23

Total Parts: 14,144.41