

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10198039    2015 POLARIS SPORTSMAN ETX Atv, 4X4**

**Workorder:** 1502583    **Meter:** 1    **In Date:** 03/11/2015    **Closed:** 04/27/2015

**Problem:** install brush guards & luggage racks

- Installed frt and rear brush grounds installed frt rear luggage racks undercoat vehicle. Install surf board rack and fabricate brackets	<b>Parts List</b>	<b>Qty</b>
	Rear Rack Extender	1.00
	Front Rack Extender	1.00
- Wire and install beacon light	Rear Brush Guard	1.00
- Shop Supplies	Front Brush Guard	1.00
	Rubberized Undercoat	1.00
	Class 2 Strobe Beacon	1.00
	Rubberized Undercoat	1.00
	Shop Supplies	1.00
Hours 7.00	Labor: 420.00	Parts: 658.78
:		Total: 1,078.78

**Workorder:** 1502840    **Meter:** 1    **In Date:** 03/19/2015    **Closed:** 03/19/2015

**Problem:** 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00	Labor: 120.00	Parts: 0.00	Total: 120.00
:			

**Workorder:** 1509463    **Meter:** 264    **In Date:** 09/18/2015    **Closed:** 09/24/2015

**Problem:** pm service

- Pm	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Napa Gold Oil Filter	1.00
	Spark Plug	1.00
	Qt 5w50 Edge W Syn	2.00
	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 38.27
:		Total: 278.27

**Workorder:** 1512402    **Meter:** 392    **In Date:** 12/08/2015    **Closed:** 12/16/2015

**Problem:** lack of power/ see notes

- Diagnose lack of power found some water in fuel tank drain tank and added fuel stabilizer	<b>Parts List</b>	<b>Qty</b>
	Startron 8oz Fuel Trt	1.00
- Wash	Shop Supplies	1.00
- Shop Supplies		
Hours 2.50	Labor: 150.00	Parts: 11.45
:		Total: 161.45

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1603470      **Meter:** 392      **In Date:** 04/01/2016      **Closed:** 04/13/2016  
**Problem:** pm service

	<b>Parts List</b>	<b>Qty</b>
- Pm		
- Wash vehicle and undercoat undercarriage	Napa Gold Oil Filter	1.00
- Front Differential service	Spark Plug	1.00
- Shop Supplies	Air Filter	1.00
	Qt 5w50 Edge W Syn	2.00
	Rubberized Undercoat	1.00
	Demand Hub Drive Fluid	1.00
	Shop Supplies	1.00
Hours 6.00	Labor: 360.00	Parts: 89.15
:		Total: 449.15

**Workorder:** 1605309      **Meter:** 124      **In Date:** 05/23/2016      **Closed:** 06/24/2016  
**Problem:** steering is tight/ exhaust noise

	<b>Parts List</b>	<b>Qty</b>
- Remove and clean steering shaft and all steering components	Spring	2.00
- Repair exhaust leak replace gasket and springs and mid pipe	Exhaust Seal	1.00
- Shop Supplies	Exhaust	1.00
	Shop Supplies	1.00
Hours 5.00	Labor: 300.00	Parts: 185.89
:		Total: 485.89

**Workorder:** 1609528      **Meter:** 0      **In Date:** 09/13/2016      **Closed:** 09/23/2016  
**Problem:** pm/ wont start

	<b>Parts List</b>	<b>Qty</b>
- Pm		
- Ck for no start r&r front fenders to access wiring and clean rusted wiring connections at junction block and fuse block ck dash cluster inop repl cluster	Qt 5w50 Edge W Syn	2.00
	Rubberized Undercoat	1.00
- Wash and undercoat veh	Napa Gold Oil Filter	1.00
- Shop Supplies	Spark Plug	1.00
	Cluster Assy	1.00
	Shop Supplies	1.00
Hours 7.50	Labor: 450.00	Parts: 450.79
:		Total: 900.79

**Workorder:** 1610840      **Meter:** 11      **In Date:** 10/20/2016      **Closed:** 10/31/2016  
**Problem:** bogs down when throttled/ see notes

	<b>Parts List</b>	<b>Qty</b>
- Diag bagging down found codes 520194-2-signal out of range throttle body assembly and clear code test ride for 30 min no codes found	Throttle Body	1.00
- Wash Eqpt	Qd Electronic Cleaner	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 376.70
:		Total: 556.70

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1611671      **Meter:** 14      **In Date:** 11/14/2016      **Closed:** 11/29/2016  
**Problem:** wont accellorate/ see notes

- Diag not accelerating and check enging light on found      **Parts List**      **Qty**  
throttle control cable out of adj readjust cable clear codes and      Shop Supplies      1.00  
test drive multiple times

- Shop Supplies

Hours 2.00      Labor: 120.00      Parts: 2.00      Total: 122.00  
:

---

**Workorder:** 1612258      **Meter:** 17      **In Date:** 11/30/2016      **Closed:** 12/14/2016  
**Problem:** bogs down when wet out

- Diagnose bogging down issue when wet. Remove all      **Parts List**      **Qty**  
plastics spray water on all electrical connections found no      Shop Supplies      1.00  
water intrusion in connectos, clean main electrical grounds  
and apply diaelectric grease, secure main harness for Ecm  
and Test run

- Shop Supplies

Hours 3.00      Labor: 180.00      Parts: 2.00      Total: 182.00  
:

---

**Workorder:** 1701278      **Meter:** 41      **In Date:** 02/07/2017      **Closed:** 02/27/2017  
**Problem:** pm/ wont start/ brakes or bearings?/ see notes

- Pm      **Parts List**      **Qty**  
- Brakes frozen -replac frt calipers and pads and service rear      Napa Gold Oil Filter      1.00  
caliper and pads and bleed sys      Spark Plug      1.00  
- Recharge battery and load test Ok ck charging sys ok      Qt 5w50 Edge W Syn      2.00  
- Shop Supplies      Lh Brake Caliper W/pads      1.00  
Rh Brake Calipers W/pads      1.00  
Brake FI      1.00  
Shop Supplies      1.00

Hours 9.00      Labor: 540.00      Parts: 584.12      Total: 1,124.12  
:

---

**Workorder:** 1703722      **Meter:** 53      **In Date:** 04/12/2017      **Closed:** 04/25/2017  
**Problem:** wont start/ check battery

- R/r weak battery      **Parts List**      **Qty**  
- Shop Supplies      Battery M C Specialty      1.00  
Shop Supplies      1.00

Hours 1.00      Labor: 60.00      Parts: 67.99      Total: 127.99  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1706635      **Meter:** 73      **In Date:** 07/06/2017      **Closed:** 07/24/2017  
**Problem:** pm/ exhaust problem

- pm service	<b>Parts List</b>	<b>Qty</b>
- replace rear muffler, gasket and springs	Qt 5w50 Edge W Syn	2.00
- clean weld and paint broken rear bumper brackets	Napa Gold Oil Filter	1.00
- Shop Supplies	Spark Plug	1.00
	Air Filter	1.00
	Spring	1.00
	Muffler	1.00
	Exhaust Seal	1.00
	Spring	2.00
	Shop Supplies	1.00
Hours 6.50	Labor: 390.00	Parts: 345.85
:		Total: 735.85

---

**Workorder:** 1709718      **Meter:** 73      **In Date:** 10/04/2017      **Closed:** 10/16/2017  
**Problem:** bogs down/ wont move/ bent axle? see notes

- Rust Issues not cost effective to repair	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

---

**Workorder:** 1800088      **Meter:** 73      **In Date:** 01/03/2018      **Closed:** 01/03/2018  
**Problem:** Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 120.00	Parts: 0.00
:		Total: 120.00