Workorder: Problem:	936563 PRE-DELI	Meter: VERY INSPE	0 CTION			In Date:	04/16/2009	Closed:	04/16/20	009
- Pre-delivery	Inspection									
	· H(ours 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	944178 P.M. Servio	Meter: ce. Need ano	1398 ther key made			In Date:	10/05/2009	Closed:	10/13/20	09
- P.m. Service	Э.				Parts Li	st				Qty
- Order and c	ut duplicate	key.program	key.		Shop Su	upplies				1.00
- Shop Suppli	es				Ch9018	Oil Filter Ad	d Pf457g Wix	57082		1.00
					10w30 N	/lotor Oil				6.00
					31-16 W	/iper Blades	16" Wiper Bla	ade		1.00
					31-24 V	Viper Blades	s 24" Blade			1.00
					Key					1.00
	H(:	ours 3.00		Labor:	180.00	Parts:	77.12	Total:	257.12	
Workorder: Problem:	1004459 P.M service	Meter: e.	2014			In Date:	04/29/2010	Closed:	05/03/20)10
- P.m service.					Parts Li	st				Qty
- Shop Suppli	es				Shop Su	upplies				1.00
					Ch9018	Oil Filter Ad	d Pf457g Wix	57082		1.00
					10w30 N	/lotor Oil				6.00
					31-16 W	/iper Blades	16" Wiper Bla	ade		1.00
					31-24 V	Viper Blades	s 24" Blade			1.00
	H(:	ours 2.00		Labor:	120.00	Parts:	33.05	Total:	153.05	
Workorder: Problem:	1009243 Check eng	Meter: ine light on.	2495			In Date:	08/26/2010	Closed:	09/03/20)10
- Transport ve battery.)	hicle to dea	ler for recall	#v2243(hybrib		Parts Li					Qty
- Shop Suppli	es				Shop Su	ipplies				1.00
		ours 2.00		Labor:	120.00	Parts:	2.00	Total:	122.00	
	. 1009633	Meter:	2509			In Date:	09/02/2010	Closed:	09/07/20)10
Workorder: Problem:		eiver spot # 1	88							
Problem:	flash cance		88		Parts I i	st				Qtv
	flash cance ceiver and i		88		Parts Li Shop Su					Qty 1.00

Workorder: 10 [°] Problem: Pm	12145 n service	Meter:	2704		Ir	n Date:	10/29/2010	Closed:	11/03/20	010
- Perform pm serv	vice.				Parts List					Qty
- Rotate and bala		tires.			Shop Supp	olies				1.00
- Shop Supplies							cd Pf457g Wix	¢ 57082		1.00
					09997 Bra		-			1.00
					1066 Whit	e Lithium	n (crc 05037)			1.00
					5w30 Oil					6.00
					31-16 Wipe	er Blades	s 16" Wiper Bl	ade		1.00
					31-24 Wip	er Blade	s 24" Blade			1.00
					96624648	Rear Wip	per Blade			1.00
	Hour :	s 3.00		Labor:	180.00	Parts:	67.51	Total:	247.51	
Workorder: 110 Problem: Pm	06390 n service.	Meter:	3520		Ir	Date:	06/17/2011	Closed:	06/29/20	011
- P.m. Service.					Parts List					Qty
- Rotate and bala	ance all tires	S.			Shop Supp	olies				1.00
- Transport vehicl	le to dealer	for check	engine light(pcm			cd Pf457g Wix	c 57082		1.00
Relay) and defecti	tive hood lat	tch.			5w30 Oil		-			6.00
- Shop Supplies					31-24 Wip	er Blade	s 24" Blade			1.00
					04 40 14/					1.00
					31-16 WIP	er Blades	s 16" Wiper Bl	ade		1.00
					96624648		•	ade		
	Hour :	s 5.00		Labor:		Rear Wip	•		344.49	
	: 00525	Meter:	4101 he light on an		96624648 300.00	Rear Wip	ber Blade		344.49 01/25/20	1.00
Workorder: 120 Problem: Pm - P.m. Service.	: 00525	Meter:			96624648 300.00	Rear Wip Parts:	ber Blade 44.49	Total:		1.00 012
Problem: Pm - P.m. Service.	: 00525 n service.Cł	Meter: heck engir	e light on an	d has to ju	96624648 300.00 Ir Imp start. Parts List	Rear Wiµ Parts: • Date:	ber Blade 44.49	Total:		1.00 012 Qty
Problem: Pm - P.m. Service. - Diagnose check battery and chargi	: 00525 n service.Cl c engine ligh ing system.	Meter: heck engir ht,low volta	e light on an	d has to ju ent.test	96624648 300.00 Ir Imp start. Parts List Shop Supp	Rear Wip Parts: Date:	oer Blade 44.49 01/17/2012	Total: Closed:		1.00 012 Qty 1.00
Problem: Pm - P.m. Service. - Diagnose check battery and chargi load test.replace of	: 00525 n service.Cl c engine ligh ing system. defective ba	Meter: heck engir ht,low volta charge an attery.	e light on an	d has to ju ent.test	96624648 300.00 Ir Imp start. Parts List Shop Supp	Rear Wip Parts: Date:	ber Blade 44.49	Total: Closed:		1.00 012 Qty 1.00 1.00
Problem: Pm - P.m. Service. - Diagnose check battery and chargi load test.replace c - Rortate and bala	: 00525 n service.Cl c engine ligh ing system. defective ba	Meter: heck engir ht,low volta charge an attery.	e light on an	d has to ju ent.test	96624648 300.00 Ir Imp start. Parts List Shop Supp Ch9018 Oi 5w30 Oil	Rear Wip Parts: Date: Dies I Filter A	oer Blade 44.49 01/17/2012 cd Pf457g Wix	Total: Closed:		1.00 012 Qty 1.00 6.00
Problem: Pm - P.m. Service. - Diagnose check battery and chargi load test.replace of	: 00525 n service.Cl c engine ligh ing system. defective ba	Meter: heck engir ht,low volta charge an attery.	e light on an	d has to ju ent.test	96624648 300.00 Irr Imp start. Parts List Shop Supp Ch9018 Oi 5w30 Oil 31-24 Wip	Rear Wip Parts: Date: Dies I Filter Au er Blade	oer Blade 44.49 01/17/2012	Total: Closed: 57082		1.00 012 Qty 1.00 1.00 6.00 1.00
Problem: Pm - P.m. Service. - Diagnose check battery and chargi load test.replace c - Rortate and bala	: 00525 n service.Cl c engine ligh ing system. defective ba	Meter: heck engir ht,low volta charge an attery.	e light on an	d has to ju ent.test	96624648 300.00 Irr Imp start. Parts List Shop Supp Ch9018 Oi 5w30 Oil 31-24 Wip	Rear Wip Parts: Date: I Date: I Filter An er Blades	ber Blade 44.49 01/17/2012 cd Pf457g Wix s 24" Blade s 16" Wiper Bl	Total: Closed: 57082		1.00 012 Qty 1.00 1.00 1.00 1.00
Problem: Pm - P.m. Service. - Diagnose check battery and chargi load test.replace c - Rortate and bala	: 00525 n service.Cl c engine ligh ing system. defective ba	Meter: heck engir ht,low volta charge an attery.	e light on an	d has to ju ent.test	96624648 300.00 Ir Imp start. Parts List Shop Supp Ch9018 Oi 5w30 Oil 31-24 Wip 31-16 Wipe	Rear Wip Parts: Date: I Date: I Filter An er Blades	ber Blade 44.49 01/17/2012 cd Pf457g Wix s 24" Blade s 16" Wiper Bl	Total: Closed: 57082		1.00
Problem: Pm - P.m. Service. - Diagnose check battery and chargi load test.replace c - Rortate and bala	: 00525 n service.Cl c engine ligh ing system. defective ba ance all tire	Meter: heck engir ht,low volta charge an attery.	e light on an	d has to ju ent.test ery,fail	96624648 300.00 Irr Imp start. Parts List Shop Supp Ch9018 Oi 5w30 Oil 31-24 Wip 31-16 Wipe 96624648	Rear Wip Parts: Date: I Filter An er Blades Rear Wip	ber Blade 44.49 01/17/2012 cd Pf457g Wix s 24" Blade s 16" Wiper Bl	Total: Closed: 57082		1.00 012 Qty 1.00 1.00 1.00 1.00
Problem: Pm - P.m. Service. - Diagnose check battery and chargi load test.replace of - Rortate and bala - Shop Supplies	: 00525 n service.Cl c engine ligh ing system. defective ba ance all tire Hour : 06700	Meter: heck engir ht,low volta charge an attery. s.	e light on an	d has to ju ent.test ery,fail	96624648 300.00 Ir Imp start. Parts List Shop Supp Ch9018 Oi 5w30 Oil 31-24 Wip 31-16 Wipe 96624648 Battery 240.00	Rear Wip Parts: Date: I Filter An er Blades Rear Wip	oer Blade 44.49 01/17/2012 cd Pf457g Wix s 24" Blade s 16" Wiper Bl oer Blade	Total: Closed: 57082	01/25/20	1.00 012 Qty 1.00 1.00 1.00 1.00 1.00
Problem: Pm - P.m. Service. - Diagnose check battery and chargi load test.replace of - Rortate and bala - Shop Supplies Workorder: 120	: 00525 n service.Cl c engine ligh ing system. defective ba ance all tire Hour : 06700 n service.	Meter: heck engin ht,low volta charge an attery. es.	age Dtc prese d retest batte	d has to ju ent.test ery,fail	96624648 300.00 Ir Imp start. Parts List Shop Supp Ch9018 Oi 5w30 Oil 31-24 Wip 31-16 Wipe 96624648 Battery 240.00	Rear Wip Parts: Date: Date: Date: Date: Date: Date: Date: Parts:	ber Blade 44.49 01/17/2012 cd Pf457g Wix s 24" Blade s 16" Wiper Bl ber Blade 165.28	Total: Closed: 57082 ade Total:	01/25/20	1.00 012 Qty 1.00 1.00 1.00 1.00 1.00
Problem: Pm - P.m. Service. - Diagnose check battery and chargi load test.replace of - Rortate and bala - Shop Supplies Workorder: 120 Problem: Pm	: 00525 n service.Cl c engine ligh ing system. defective ba ance all tire Hour : 06700 n service.	Meter: heck engin ht,low volta charge an attery. es. s.	age Dtc prese d retest batte	d has to ju ent.test ery,fail	96624648 300.00 Ir Imp start. Parts List Shop Supp Ch9018 Oi 5w30 Oil 31-24 Wip 31-16 Wipe 96624648 Battery 240.00 Ir	Rear Wip Parts: Date: Date: Dies I Filter Ad er Blades Rear Wip Parts: Date:	ber Blade 44.49 01/17/2012 cd Pf457g Wix s 24" Blade s 16" Wiper Bl ber Blade 165.28	Total: Closed: 57082 ade Total:	01/25/20	1.00 012 Qty 1.00 1.00 1.00 1.00 1.00 012 Qty
Problem: Pm - P.m. Service. - Diagnose check battery and chargi load test.replace of - Rortate and bala - Shop Supplies Workorder: 120 Problem: Pm - Perform pm serv	: 00525 n service.Cl c engine ligh ing system. defective ba ance all tire Hour : 06700 n service.	Meter: heck engin ht,low volta charge an attery. es. s.	age Dtc prese d retest batte	d has to ju ent.test ery,fail	96624648 300.00 Ir Imp start. Parts List Shop Supp Ch9018 Oi 5w30 Oil 31-24 Wip 31-16 Wipe 96624648 Battery 240.00 Ir Parts List Shop Supp	Rear Wip Parts: Date: Date: Dies I Filter Ad er Blades Rear Wip Parts: Date: Date:	ber Blade 44.49 01/17/2012 cd Pf457g Wix s 24" Blade s 16" Wiper Bl ber Blade 165.28	Total: Closed: 57082 ade Total: Closed:	01/25/20	1.00 012 Qty 1.00 1.00 1.00 1.00 1.00 012 Qty 1.00
Problem: Pm - P.m. Service. - Diagnose check battery and chargi load test.replace of - Rortate and bala - Shop Supplies Workorder: 120 Problem: Pm - Perform pm serv - Rotate and bala	: 00525 n service.Cl c engine ligh ing system. defective ba ance all tire Hour : 06700 n service.	Meter: heck engin ht,low volta charge an attery. es. s.	age Dtc prese d retest batte	d has to ju ent.test ery,fail	96624648 300.00 Ir Imp start. Parts List Shop Supp Ch9018 Oi 5w30 Oil 31-24 Wip 31-16 Wipe 96624648 Battery 240.00 Ir Parts List Shop Supp	Rear Wip Parts: Date: Date: Dies I Filter Ad er Blades Rear Wip Parts: Date: Date:	ber Blade 44.49 01/17/2012 cd Pf457g Wix s 24" Blade s 16" Wiper Bl ber Blade 165.28 07/18/2012	Total: Closed: 57082 ade Total: Closed:	01/25/20	1.00 012 Qty 1.00 1.00 1.00 1.00 1.00

Workorder: Problem:	1207198 need ignition I	Meter: key	4805		In	Date:	08/01/2012	Closed:	08/21/20)12
- Make And P	rogram 1 Extra	Kev			Parts List					Qty
- Shop Suppli		,			Shop Supp	olies				1.00
					Ignition Key					1.00
	Hour :	s 1.00		Labor:	60.00	Parts:	29.80	Total:	89.80	
Workorder: Problem:	1301710 P.M. service.	Meter:	5528		In	Date:	02/19/2013	Closed:	03/05/20)13
- P.m. Service).				Parts List					Qty
- Rotate and b	alance all tires	5.			Napa Quar	t 5w30				6.00
- Shop Suppli	es				Oil Filter					1.00
					Shop Supp	olies				1.00
	Hour	s 3.00		Labor:	180.00	Parts:	29.15	Total:	209.15	
Workorder: Problem:	1302320 20 - Wash tick	Meter: tet(s) issue	5528 ed		In	Date:	03/07/2013	Closed:	03/07/20)13
- 20 - Wash ti	cket(s) issued									
		s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1308247 Pm service.	Meter:	8806		In	Date:	08/15/2013	Closed:	08/27/20)13
- Perform pm	service.				Parts List					Qty
- Rotate and b	alance all four	tires.			Napa Quar	t 5w30				6.00
- Shop Suppli	es				Napagold (Dil Filter				1.00
					31-24 Wip	er Blade	s 2			1.00
					31-16 Wipe	er Blades	s 16			1.00
					Shop Supp	lies				1.00
	Hour :	s 3.00		Labor:	180.00	Parts:	39.71	Total:	219.71	
Workorder: Problem:	1403806 Pm service	Meter:	8806		In	Date:	03/18/2014	Closed:	04/30/20)14
- P.m. Service).				Parts List					Qty
	eck engine ligh	nt.replace	defective pow	er train	Napa Quar	t 5w30				6.00
control relay.cl	ear codes. Dalance all tires				Napagold (1.00
		».			31-24 Wip		s 2			2.00
- Shop Suppli	53				Wiper Blad	е				1.00
					Washer Fl					1.00
					Wiper Blad	е				1.00
					filter					1.00
					relay					1.00
										4 00
		s 5.00			Shop Supp 300.00	olies			395.20	1.00

Workorder: Problem:	1410317 Pm service	Meter:	9443		l	n Date:	10/15/2014	Closed:	10/31/20)14
- Pm service.					Parts List					Qty
	al system.bat	tery failed lo	ad .replace b	bad	Napa Qua	rt 5w30				6.00
battery.		P 1 4			Napagold	Oil Filter				1.00
- Diagnose to P1682.pin poi	or check engine nt test.trace ci			connector	Napagold	Air Filter				1.00
in power distri					Washer Fl	uid Conc	entr			1.00
- Rotate and	balance all fou	ur tires.			Battery					1.00
- Shop Suppl	ies				Shop Sup	plies				1.00
	Hou :	urs 6.00		Labor:	360.00	Parts:	155.36	Total:	515.36	
Workorder:	1504247	Meter:	9796		l	n Date:	04/24/2015	Closed:	05/07/20)15
Problem:	Pm service.0	Check engin	e light on.							
- Pm service.					Parts List					Qty
	iagnose for ch				Napa Qua	rt 5w30				6.00
P1682.test all and test batte					Napagold	Oil Filter				1.00
	balance all fou			01001.01	Wiper Blac	de				1.00
- Shop Suppl					31-24 Wip	per Blade	s 2			1.00
					Washer Fl		entr			1.00
					Wiper Blac					1.00
					Shop Sup					1.00
	Hou :	urs 5.50		Labor:	330.00	Parts:	52.58	Total:	382.58	
Workorder: Problem:	1601962 Pm service.	Meter:	10524		l	n Date:	02/25/2016	Closed:	03/07/20)16
										_
- Pm service.					Parts List					Qty
	ing and chargi	ng system.t	battery failed l	loadtest	Parts List Battery					Qty 1.00
	ing and chargi			loadtest	_					-
- Check starti after recharge - Rotate and	ing and chargi preplace defect balance all fou	ctive battery		loadtest	Battery	rt 5w30				1.00
- Check starti after recharge	ing and chargi preplace defect balance all fou	ctive battery		loadtest	Battery Napa Qua	rt 5w30 Oil Filter)			1.00 6.00
- Check starti after recharge - Rotate and	ing and chargi preplace defect balance all fou	ctive battery		loadtest	Battery Napa Qua Napagold	rt 5w30 Oil Filter de Delco)			1.00 6.00 1.00
- Check starti after recharge - Rotate and	ing and chargi preplace defect balance all fou	ctive battery		loadtest	Battery Napa Qua Napagold Wiper Blac	rt 5w30 Oil Filter de Delco des 24")			1.00 6.00 1.00
- Check starti after recharge - Rotate and	ing and chargi preplace defect balance all fou	ctive battery		loadtest	Battery Napa Qua Napagold Wiper Blac Wiper Blac	rt 5w30 Oil Filter de Delco des 24" de)			1.00 6.00 1.00 1.00
- Check starti after recharge - Rotate and	ing and chargi preplace defea balance all fou ies	ctive battery			Battery Napa Qua Napagold Wiper Blac Wiper Blac Wiper Blac	rt 5w30 Oil Filter de Delcc des 24" de plies	165.40	Total:	405.40	1.00 6.00 1.00 1.00 1.00
- Check starti after recharge - Rotate and - Shop Suppli	ing and chargi preplace defea balance all fou ies	ur tires. urs 4.00 Meter:	10616	Labor:	Battery Napa Qua Napagold Wiper Blac Wiper Blac Shop Sup 240.00	rt 5w30 Oil Filter de Delcc des 24" de plies		Total: Closed:	405.40 05/19/20	1.00 6.00 1.00 1.00 1.00 1.00
 Check starti after recharge Rotate and Shop Suppli Workorder: Problem:	ing and chargi preplace defect balance all fou ies Hou : 1604150	ur tires. urs 4.00 Meter: and check e	10616	Labor:	Battery Napa Qua Napagold Wiper Blac Wiper Blac Shop Sup 240.00	rt 5w30 Oil Filter de Delcc des 24" de plies Parts: n Date:	165.40			1.00 6.00 1.00 1.00 1.00 1.00
 Check starti after recharge Rotate and Shop Suppli Workorder: Problem: Replace and 	ing and chargi preplace defect balance all fou ies Hou : 1604150 Check tires a	urs 4.00 Meter: and check e	10616 ngine light on	Labor:	Battery Napa Qua Napagold Wiper Blac Wiper Blac Shop Sup 240.00	rt 5w30 Oil Filter de Delco des 24" de Delies Parts: n Date:	165.40 04/20/2016			1.00 6.00 1.00 1.00 1.00 1.00
 Check starti after recharge Rotate and Shop Suppli Workorder: Problem: Replace and Diagnose Alsensor/hub as 	ing and chargi preplace defect balance all fou- ies Hou- : 1604150 Check tires a d balance four bs light.replac ssemble.	urs 4.00 Meter: and check e new tires. e right front	10616 ngine light on wheel speed	Labor:	Battery Napa Qua Napagold Wiper Blac Wiper Blac Shop Sup 240.00	rt 5w30 Oil Filter de Delco des 24" de plies Parts: n Date: 1 225-60	165.40 04/20/2016			1.00 6.00 1.00 1.00 1.00 1.00 1.00
 Check starti after recharge Rotate and Shop Suppli Workorder: Problem: Replace and Diagnose Alsensor/hub as Diagnose ch 	ing and chargi preplace defect balance all fou- ies Hou : 1604150 Check tires a d balance four bs light.replac semble. neck engine lig	urs 4.00 Meter: and check e new tires. e right front ght,p1682p	10616 ngine light on wheel speed perform pin po	Labor:	Battery Napa Qua Napagold Wiper Blac Wiper Blac Shop Sup 240.00	rt 5w30 Oil Filter de Delco des 24" de polies Parts: n Date: 1 225-60 or	165.40 04/20/2016			1.00 6.00 1.00 1.00 1.00 1.00 016 Qty 4.00 1.00
 Check starti after recharge Rotate and Shop Suppli Shop Suppli Workorder: Problem: Replace and sensor/hub as Diagnose ch trest.replace g 	ing and chargi e.replace defect balance all fou- ies Hou- : 1604150 Check tires a d balance four bs light.replac ssemble. neck engine lig ground harnes	urs 4.00 Meter: and check e new tires. e right front ght,p1682p	10616 ngine light on wheel speed perform pin po	Labor:	Battery Napa Qua Napagold Wiper Blac Wiper Blac Shop Sup 240.00	rt 5w30 Oil Filter de Delco des 24" de plies Parts: n Date: 1 225-60 or	165.40 04/20/2016 r17			1.00 6.00 1.00 1.00 1.00 1.00 1.00 1.00
 Check starti after recharge Rotate and Shop Suppli Shop Suppli Workorder: Problem: Replace and Diagnose Alsensor/hub as Diagnose ch trest.replace g engine.clear of 	ing and chargi e.replace defect balance all fou- ies Hou- : 1604150 Check tires a d balance four bs light.replac ssemble. heck engine lig ground harnes code.	urs 4.00 Meter: and check e new tires. e right front ght,p1682p	10616 ngine light on wheel speed perform pin po	Labor:	Battery Napa Qua Napagold Wiper Blac Wiper Blac Shop Sup 240.00	rt 5w30 Oil Filter de Delco des 24" de Parts: n Date: 1 225-60 or ng tery Grou	165.40 04/20/2016 r17			1.00 6.00 1.00 1.00 1.00 1.00 1.00 016 Qty 4.00
 Check starti after recharge Rotate and Shop Suppli Shop Suppli Workorder: Problem: Replace and sensor/hub as Diagnose ch trest.replace g 	ing and chargi e.replace defect balance all fou- ies Hou- : 1604150 Check tires a d balance four bs light.replac ssemble. heck engine lig ground harnes code.	urs 4.00 Meter: and check e new tires. e right front ght,p1682p	10616 ngine light on wheel speed perform pin po	Labor:	Battery Napa Qua Napagold Wiper Blac Wiper Blac Shop Sup 240.00	rt 5w30 Oil Filter de Delco des 24" de plies Parts: n Date: 1 225-60 or ng tery Grou	165.40 04/20/2016 r17			1.00 6.00 1.00 1.00 1.00 1.00 016 Qty 4.00 1.00 1.00
 Check startiafter recharge Rotate and Shop Suppli Shop Suppli Workorder: Problem: Replace and Diagnose charges Diagnose charges Diagnose charges 	ing and chargi e.replace defect balance all fou- ies Hou : 1604150 Check tires a d balance four bs light.replac ssemble. heck engine lig ground harnes code. ies	urs 4.00 Meter: and check e new tires. e right front ght,p1682p	10616 ngine light on wheel speed perform pin po	Labor:	Battery Napa Qua Napagold Wiper Blac Wiper Blac Shop Sup 240.00	rt 5w30 Oil Filter de Delco des 24" de polies Parts: n Date: 1 225-60 or ng tery Grou polies sal Fee	165.40 04/20/2016 r17	Closed:		1.00 6.00 1.00 1.00 1.00 1.00 1.00 1.00

:

Workorder: 16104 Problem: P.M. s	66 Meter: ervice and check	10852 engine light on.			In Date:	10/11/2016	Closed:	11/30/2016
- P.m. Service.				Parts Li	st			Qty
- Diagnose Abs light.		n poit test.replac	e left	Napa S	yn 5w30 Qt			6.00
front wheel speed ser				Napago	ld Oil Filter			1.00
- Replaced one strip	-			Wiper B	lades 24"			1.00
- Diagnose check en pin point test.replace			form	Wiper				1.00
sensors.program batt				Wiper B	lade			1.00
- Rotate and and bal	ance tires.				Fluid Conce	entr		1.00
- Shop Supplies				Abs Ser	isor			1.00
				Nut				1.00
				•	Battery Sens			1.00
					Hy Bbrid A/o	c Delco		1.00
				Shop Su	• •			1.00
	Hours 11.25 :	l	_abor:	675.00	Parts:	1,598.45	Total:	2,273.45
Workorder: 17007	16 Meter:	10872			In Date:	01/24/2017	Closed:	01/31/2017
Problem: Towed	d in for no start and	d recall IPC repr	ogram.					
- Recharge battery.te system for draw,withi often.		ed to be driven		30.00	Parts:	0.00	Total:	30.00
Workorder: 17007 Problem: Will no		10852			In Date:	01/24/2017	Closed:	01/25/2017
- Tow From: 3700 Be Parkway	elvedere Road, Blo	dg E To: 2601 V	′ista					
	Hours 0.00 :	l	_abor:	0.00	Parts:	0.00	Total:	0.00
Workorder: 17029 Problem: Towed		10912			In Date:	03/22/2017	Closed:	04/13/2017
- Recharge battery a	nd test for draw,no	pe found at this t	ime.	Parts Li	st			Qty
 Diagnose check en loose connector at hy 			ir	Shop Su	upplies			1.00
- Shop Supplies								
	Hours 1.50 :	I	_abor:	90.00	Parts:	2.00	Total:	92.00
Workorder: 17029 Problem: no sta		10872			In Date:	03/22/2017	Closed:	03/22/2017
- Tow From: Pbia								
	Hours 0.00 :	I	_abor:	0.00	Parts:	0.00	Total:	0.00

Workorder: Problem:	1705275 P.M. service	Meter: e and right side	10990 de visor broke	n.	I	In Date:	05/30/2017	Closed:	06/06/20	17
- P.m. service	Э.				Parts Lis	t				Qty
- Replace bot	th left and rigl	ht broken vis	ors with new.		Napa Syr	n 5w30 Qt				6.00
- Rotate and I	high speed b	alance all fou	ır tires.		Napagold	Oil Filter				1.00
- Shop Suppli	ies				Wiper Bla	des 24"				1.00
					Wiper					1.00
					Wiper Bla	de				1.00
					Sunshade	e				1.00
					Sunshade	e				1.00
					Shop Sup	plies				1.00
	Ho	urs 3.80		Labor:	228.00	Parts:	445.91	Total:	673.91	
Workorder: Problem:	1706654 wont fuel	Meter:	11022			In Date:	07/07/2017	Closed:	07/10/20	17
- Test and Re	emove Cance	iver/ Issue F	uel card/clear	Eniane	Parts Lis	t				Qty
Light				5	Shop Sup	plies				1.00
- Shop Suppli	ies									
	Ho	urs 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
	1711904 P.M. service	Meter: e and ABS lig	11301 ht on.			In Date:	12/05/2017	Closed:	01/16/20	18
Problem:	P.M. service	e and ABS lig	ht on.	.	Parts Lis		12/05/2017	Closed:	01/16/20	
	P.M. service .replace two	e and ABS lig	ht on. crome peeling] .		t	12/05/2017	Closed:	01/16/20	18 Qty 6.00
Problem: - P.m. service - Perform con C0201.test ,r8	P.M. service e .replace two nputer diagno	e and ABS lig lug nuts for bise for Abs l	ht on. crome peeling ght on code	-	Parts Lis	t art 5w30	12/05/2017	Closed:	01/16/20	Qty
Problem: - P.m. service - Perform con C0201.test ,r8 programing.	P.M. service e .replace two nputer diagno ki new Abs m	e and ABS lig lug nuts for bise for Abs l odule and se	ht on. crome peeling ght on code nd to dealer fo	or	Parts Lis Napa Qua	t art 5w30 Oil Filter		Closed:	01/16/20	Qty 6.00
Problem: - P.m. service - Perform con C0201.test ,r8 programing. - Rotate and I	P.M. service e .replace two nputer diagno & new Abs m high speed b	e and ABS lig lug nuts for bise for Abs l odule and se	ht on. crome peeling ght on code nd to dealer fo	or	Parts Lis Napa Qua Napagold	t art 5w30 Oil Filter Iuid Conc		Closed:	01/16/20	Qty 6.00 1.00
Problem: - P.m. service - Perform con C0201.test ,r8 programing.	P.M. service e .replace two nputer diagno & new Abs m high speed b	e and ABS lig lug nuts for bise for Abs l odule and se	ht on. crome peeling ght on code nd to dealer fo	or	Parts Lis Napa Qua Napagold Washer F	t art 5w30 Oil Filter Iuid Conc		Closed:	01/16/20	Qty 6.00 1.00 1.00
Problem: - P.m. service - Perform con C0201.test ,r8 programing. - Rotate and I	P.M. service e .replace two nputer diagno & new Abs m high speed b	e and ABS lig lug nuts for bise for Abs l odule and se	ht on. crome peeling ght on code nd to dealer fo	or	Parts Lis Napa Qua Napagold Washer F Wiper Bla	t art 5w30 Oil Filter Iuid Conc des 24"		Closed:	01/16/20	Qty 6.00 1.00 1.00 1.00
Problem: - P.m. service - Perform con C0201.test ,r8 programing. - Rotate and I	P.M. service e .replace two nputer diagno & new Abs m high speed b	e and ABS lig lug nuts for bise for Abs l odule and se	ht on. crome peeling ght on code nd to dealer fo	or	Parts Lis Napa Qua Napagold Washer F Wiper Bla Wiper	t art 5w30 Oil Filter Iuid Conc des 24"		Closed:	01/16/20	Qty 6.00 1.00 1.00 1.00
Problem: - P.m. service - Perform con C0201.test ,r8 programing. - Rotate and I	P.M. service e .replace two nputer diagno & new Abs m high speed b	e and ABS lig lug nuts for bise for Abs l odule and se	ht on. crome peeling ght on code nd to dealer fo	or	Parts Lis Napa Qua Napagold Washer F Wiper Bla Wiper Wiper Bla	t art 5w30 Oil Filter Iuid Conc Ides 24" Ide	entr	Closed:	01/16/20	Qty 6.00 1.00 1.00 1.00 1.00
Problem: - P.m. service - Perform con C0201.test ,r8 programing. - Rotate and I	P.M. service e .replace two nputer diagno & new Abs m high speed b	e and ABS lig lug nuts for bise for Abs l odule and se	ht on. crome peeling ght on code nd to dealer fo	or	Parts Lis Napa Qua Napagold Washer F Wiper Bla Wiper Wiper Bla Lug Nut	t art 5w30 Oil Filter Juid Conc Ides 24" Ide	entr	Closed:	01/16/20	Qty 6.00 1.00 1.00 1.00 1.00 2.00
 P.m. service Perform con C0201.test ,r8 programing. Rotate and I 	P.M. service e .replace two nputer diagno & new Abs m high speed b	e and ABS lig lug nuts for bise for Abs l odule and se	ht on. crome peeling ght on code nd to dealer fo	or	Parts Lis Napa Qua Napagold Washer F Wiper Bla Wiper Wiper Bla Lug Nut Brake Co	t art 5w30 Oil Filter Iuid Conce des 24" de de ntrol Modu	entr	Closed:	01/16/20	Qty 6.00 1.00 1.00 1.00 1.00 2.00 1.00