10169495 2007 FORD E350 Van, 1 Ton, Cargo

						•				
Workorder: Problem:	741251 PRE-DE	<b>Meter:</b> ELIVERY INSPE	0 CTION			In Date:	07/11/2007	Closed:	07/11/20	007
- Pre-delivery	Inspection	on								
		Hours 2.00 :		Labor:	110.00	Parts:	0.00	Total:	110.00	
Workorder: Problem:	834636 P.M SE	Meter: RVICE,CHECK	5000 STROBES			In Date:	02/26/2008	Closed:	02/29/20	800
- Pm Service					Parts Li	ist				Qty
	/rear Bull	b Failed Replace	Bulb,repair		Shop Su	upplies				1.00
Connector.					Ca8039	Air Filter Lb	of Af1615 Wix	46418		1.00
- Shop Suppli	ies				1372 O	il Filter Frm	Ph2 Wix 513	372		1.00
					G8018 F	Fuel Filter LI	bf G6593 Wix	33595		1.00
					10020 Ir	njector Clea	ner Don't Red	order		1.00
					5w20 Er	ngine Oil				7.00
					S30hac	p Strobe Bu	lb For Kit S66	Осссс		1.00
		Hours 4.80		Labor:	288.00	Parts:	69.35	Total:	357.35	
Workorder:	840644	Meter:	7912			In Date:	06/27/2008	Closed:	07/09/20	008
Problem:	TRANS	SLIPPING,CHE	CK SIDE DO	OR						
- Inspect & Ro	oad Test	For Slipping Tra	ns.no 3rd Ge	ar.setup	Parts Li	ist				Qty
		To Tow To Deale		•	Shop Su	upplies				1.00
Door Handle		er Warranty Tran	s Overhaul &	Side	•					
- Shop Suppli	ies				400.00	5 (	0.00	<b>+</b>	400.00	
		Hours 2.00 :		Labor:	120.00	Parts:	2.00	i otai:	122.00	
Workorder: Problem:	841060 001 KE	Meter: Y ISSUED OUT	0 07/08/0	08		In Date:	07/08/2008	Closed:	07/08/20	800
- 001 Key Iss	ued Out	07/08/08			Parts Li	ist				Qty
·					Duplicat	e Vehicle K	eys			1.00
		Hours 0.20 :		Labor:	-	Parts:	-	Total:	3.00	
Workorder: Problem:	842800 RIGHT	Meter: FRONT TIRE FL	8781 _AT			In Date:	08/13/2008	Closed:	08/18/20	800
- Repair Righ	t Front Ti	re.			Parts Li	ist				Qty
- Shop Suppli					Shop Su					1.00
		Hours 1.00		Labor:		Parts:	2.00	Total:	62.00	
		:								
Workorder: Problem:	842962 NAIL IN	<b>Meter:</b> R/F TIRE.	8907			In Date:	08/18/2008	Closed:	08/21/20	800
- Repair Righ	t Front Ti	re And High Spe	ed Balance.		Parts Li	ist				Qty
- Shop Suppli		3 °F-			Shop Su					1.00
1 1										

- Pm Service Parts List	<b>d:</b> 09/29/2008
	Qty
- Repair 1 Tire.rotate And High Speed Balance All 4 Tires. Shop Supplies	1.00
Nitro Fill Tires. 1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies G8018 Fuel Filter Lbf G6593 Wix 33595	1.00
5w20 Engine Oil	7.00
31-20 Wiper Blades 20" Blade	2.00
Used Firex Refurbed Fire Extingshers	1.00
•	tal: 407.95
Workorder: 935226 Meter: 13638 In Date: 03/16/2009 Closed Problem: PM SERVICE.	<b>d</b> : 03/24/2009
- Pm Service Parts List	Qty
- Check Trailer Hitch.replace Broken Hitch Pin. Shop Supplies	1.00
- Mount 2 Tires, Hi Speed Balanc & Nitro Fill 4 Tires Put New 1372 Oil Filter Frm Ph2 Wix 51372	1.00
Tires On Front. 5w20 Engine Oil	7.00
- Shop Supplies Tire Disposal Fee	2.00
Tr416 Valve Stem	2.00
749353434 245/75r16 Wrangler Rt/s E	2.00
18410 Pintle Pin	1.00
Hours 6.25 Labor: 375.00 Parts: 330.12 To	tal: 705.12
Workorder:         936402         Meter:         14139         In Date:         04/13/2009         Close           Problem:         L/R TIRE FLAT	<b>d:</b> 04/14/2009
Problem: L/R TIRE FLAT  - Mount & Hi Speed Balance Two New Tires On Rear Of Parts List	d: 04/14/2009 Qty
Problem: L/R TIRE FLAT  - Mount & Hi Speed Balance Two New Tires On Rear Of Vehicle. Nitro Fill To Specs.  Parts List Shop Supplies	
Problem: L/R TIRE FLAT  - Mount & Hi Speed Balance Two New Tires On Rear Of Value Nitro Fill To Speed	Qty
Problem: L/R TIRE FLAT  - Mount & Hi Speed Balance Two New Tires On Rear Of Vehicle. Nitro Fill To Specs.  Shop Supplies	<b>Qty</b> 1.00
Problem: L/R TIRE FLAT  - Mount & Hi Speed Balance Two New Tires On Rear Of Vehicle. Nitro Fill To Specs Shop Supplies  Tr416 Valve Stem 749353434 245/75r16 Wrangler Rt/s E	<b>Qty</b> 1.00 2.00
Problem: L/R TIRE FLAT  - Mount & Hi Speed Balance Two New Tires On Rear Of Vehicle. Nitro Fill To Specs Shop Supplies  Tr416 Valve Stem 749353434 245/75r16 Wrangler Rt/s E	Qty 1.00 2.00 2.00 tal: 394.74
Problem: L/R TIRE FLAT  - Mount & Hi Speed Balance Two New Tires On Rear Of Vehicle. Nitro Fill To Specs.  - Shop Supplies  Tr416 Valve Stem 749353434 245/75r16 Wrangler Rt/s E Hours 1.50 Hours 1.50 Hours 18900  In Date: 09/24/2009 Close	Qty 1.00 2.00 2.00 tal: 394.74
Problem: L/R TIRE FLAT  - Mount & Hi Speed Balance Two New Tires On Rear Of Vehicle. Nitro Fill To Specs.  - Shop Supplies  Tr416 Valve Stem 749353434 245/75r16 Wrangler Rt/s E Hours 1.50 Edbor: 90.00 Parts: 304.74 To:  Workorder: 943719 Meter: 18900 In Date: 09/24/2009 Closed Problem: P.M service	Qty 1.00 2.00 2.00 tal: 394.74 d: 09/30/2009
Problem: L/R TIRE FLAT  - Mount & Hi Speed Balance Two New Tires On Rear Of Vehicle. Nitro Fill To Specs Shop Supplies  - Shop Supplies  Tr416 Valve Stem 749353434 245/75r16 Wrangler Rt/s E  Hours 1.50 :  Workorder: 943719 Meter: 18900 In Date: 09/24/2009 Closed Problem: P.M service  - P.m. Service.  Parts List  Parts List  Parts List	Qty 1.00 2.00 2.00 tal: 394.74 d: 09/30/2009
Problem: L/R TIRE FLAT  - Mount & Hi Speed Balance Two New Tires On Rear Of Vehicle. Nitro Fill To Specs Shop Supplies  - Shop Supplies  - Shop Supplies  Tr416 Valve Stem  749353434 245/75r16 Wrangler Rt/s E  Hours 1.50  Labor: 90.00 Parts: 304.74 To  Workorder: 943719 Meter: 18900 In Date: 09/24/2009 Closed Problem: P.M service  - P.m. Service Perts List - Replace broken pintle pin on hitch.	Qty 1.00 2.00 2.00 tal: 394.74 d: 09/30/2009 Qty 1.00
Problem: L/R TIRE FLAT  - Mount & Hi Speed Balance Two New Tires On Rear Of Vehicle. Nitro Fill To Specs Shop Supplies  - Shop Supplies  Tr416 Valve Stem  749353434 245/75r16 Wrangler Rt/s E  Hours 1.50 :  Workorder: 943719 Meter: 18900 In Date: 09/24/2009 Closed Problem: P.M service  - P.m. Service Replace broken pintle pin on hitch Repair L/f tire.rotate and balance all four tires.  Parts List Shop Supplies  1372 Oil Filter Frm Ph2 Wix 51372	Qty 1.00 2.00 2.00 tal: 394.74 d: 09/30/2009  Qty 1.00 1.00
Problem: L/R TIRE FLAT  - Mount & Hi Speed Balance Two New Tires On Rear Of Vehicle. Nitro Fill To Specs Shop Supplies  - Shop Supplies  - Shop Supplies  - Tr416 Valve Stem  - 749353434 245/75r16 Wrangler Rt/s E  - Hours 1.50 - Labor: 90.00 - Parts: 304.74  - To  - Workorder: 943719 - Meter: 18900 - Problem: P.M service  - P.m. Service Replace broken pintle pin on hitch Repair L/f tire.rotate and balance all four tires Shop Supplies  - Ca8039 Air Filter Lbf Af1615 Wix 46418	Qty 1.00 2.00 2.00 tal: 394.74  d: 09/30/2009  Qty 1.00 1.00 1.00
Problem: L/R TIRE FLAT  - Mount & Hi Speed Balance Two New Tires On Rear Of Vehicle. Nitro Fill To Specs Shop Supplies  - Shop Supplies  Tr416 Valve Stem 749353434 245/75r16 Wrangler Rt/s E  Hours 1.50 Labor: 90.00 Parts: 304.74 To  :  Workorder: 943719 Meter: 18900 Problem: P.M service  - P.m. Service Replace broken pintle pin on hitch Repair L/f tire.rotate and balance all four tires Shop Supplies  Ca8039 Air Filter Lbf Af1615 Wix 46418 G8018 Fuel Filter Lbf G6593 Wix 33595	Qty 1.00 2.00 2.00 tal: 394.74 d: 09/30/2009  Qty 1.00 1.00 1.00 1.00
Problem: L/R TIRE FLAT  - Mount & Hi Speed Balance Two New Tires On Rear Of Vehicle. Nitro Fill To Specs Shop Supplies  - Shop Supplies  - Shop Supplies  Tr416 Valve Stem 749353434 245/75r16 Wrangler Rt/s E  Hours 1.50  Labor: 90.00 Parts: 304.74 To  :  Workorder: 943719 Meter: 18900 In Date: 09/24/2009 Closed Problem: P.M service  - P.m. Service Replace broken pintle pin on hitch Repair L/f tire.rotate and balance all four tires Shop Supplies  Ca8039 Air Filter Lbf Af1615 Wix 46418  G8018 Fuel Filter Lbf G6593 Wix 33595 5w20 Engine Oil	Qty 1.00 2.00 2.00 tal: 394.74  d: 09/30/2009  Qty 1.00 1.00 1.00 7.00
Problem: L/R TIRE FLAT  - Mount & Hi Speed Balance Two New Tires On Rear Of Vehicle. Nitro Fill To Specs Shop Supplies  - Shop Supplies  Tr416 Valve Stem 749353434 245/75r16 Wrangler Rt/s E  Hours 1.50 Labor: 90.00 Parts: 304.74 To  :  Workorder: 943719 Meter: 18900 In Date: 09/24/2009 Closer  Problem: P.M service  - P.m. Service Replace broken pintle pin on hitch Repair L/f tire.rotate and balance all four tires Shop Supplies  Ca8039 Air Filter Lbf Af1615 Wix 46418 G8018 Fuel Filter Lbf G6593 Wix 33595 5w20 Engine Oil Used Firex Refurbed Fire Extingshers	Qty 1.00 2.00 2.00 tal: 394.74 d: 09/30/2009  Qty 1.00 1.00 7.00 1.00

Workorder: Problem:	947287 WONT COME	Meter: OUT OF	20206 LOW			In Date:	12/23/2009	Closed:	12/28/20	009
- From: 3680	Lake Worth Rd	To: Lv	Shop							
		s 0.00	·	Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	947304 Towed in,stucl	<b>Meter:</b> k in low ge	20388 ear.			In Date:	12/28/2009	Closed:	01/06/20	010
- To/from dea	ler for warrenty	internal tr	ans repair.		Parts Lis	st				Qty
- Shop Suppli	es				Shop Su	pplies				1.00
	Hours	s 2.00		Labor:	120.00	Parts:	2.00	Total:	122.00	
Workorder: Problem:	1002614 P.M service, c	Meter: heck tires	21859 for nails.			In Date:	03/15/2010	Closed:	03/19/20	010
- P.m service	<u>.</u>				Parts Li	st				Qty
- Repair two t	ires, rotate & ba	alance all	four tires.		Shop Su	pplies				1.00
- Shop Suppli	es				1372 Oi	Filter Frm	Ph2 Wix 513	372		1.00
					5w20 En	_				7.00
						iper Blades				2.00
	Hours :	s 6.00		Labor:	360.00	Parts:	26.87	Total:	386.87	
Workorder: Problem:	1005720 No start, @ wa	Meter: arehouse	23391 oading dock.			In Date:	06/01/2010	Closed:	06/01/20	010
- To/from war	ehouse to jump	start van	& bring to flee	et.	Parts Lis	st				Qty
_	g & charging sys	stem, test	& replace fail	ed	Shop Su	pplies				1.00
<ul><li>battery.</li><li>Shop Suppli</li></ul>	inc				Group 6	5 Battery (n	ntc Bxt-65-850	))		1.00
- эпор заррп		s 2.00		Labor:	120.00	Parts:	136.01	Total:	256.01	
Workorder: Problem:	1007905 Check power s	Meter:	24821 Dise and front			In Date:	07/26/2010	Closed:	08/04/20	010
- Install new f	·			wneels s	kake whe	n braking.				
- Install new front brake pads and resurface front and rear brake rotors.repack front wheel bearings.service all four										Qtv
	epack front whe	el bearing	s.service all f	d rear our	Parts Lis	st				<b>Qty</b> 1.00
calipers and b		el bearing	s.service all f	d rear our	Parts Lis	<b>st</b> pplies	Ray Pgd655n	1		<b>Qty</b> 1.00 1.00
calipers and b scan tool.	epack front whe	el bearing perform a	s.service all f utomated blee	d rear our ed with	Parts Lis Shop Su Mx655 B	<b>st</b> pplies	, ,	า		1.00
calipers and b scan tool.  - Install two n	epack front whe rake fluid flush.	el bearing perform a ront whee	s.service all futomated blee	d rear our ed with e all four.	Parts Lis Shop Su Mx655 B 09997 B	st pplies rake Pads	1	n		1.00 1.00
calipers and b scan tool.  - Install two n  - Perform who correct cambe	epack front whe rake fluid flush.  ew tires to the feel alignment corr.	el bearing perform a ront whee	s.service all futomated blee	d rear our ed with e all four.	Parts Lis Shop Su Mx655 B 09997 B Bl1 Brak	st pplies rake Pads rake Clean	endix)	1		1.00 1.00 1.00
calipers and b scan tool.  - Install two notes are reform when	epack front whe rake fluid flush.  ew tires to the feel alignment corr.	el bearing perform a ront whee	s.service all futomated blee	d rear our ed with e all four.	Parts Lis Shop Su Mx655 B 09997 B Bl1 Brak 61a P/ste 1401 Br	st pplies rake Pads rake Clean e Lube (be eering Fluid ake Fluid B	endix) I rake Fluid			1.00 1.00 1.00 1.00 1.00 1.00
calipers and b scan tool.  - Install two n  - Perform who correct cambe	epack front whe rake fluid flush.  ew tires to the feel alignment corr.	el bearing perform a ront whee	s.service all futomated blee	d rear our ed with e all four.	Parts Lis Shop Su Mx655 B 09997 B Bl1 Brak 61a P/sto 1401 Br 5068 Pe	pplies  rake Pads  rake Clean e Lube (be eering Fluid ake Fluid B	endix)			1.00 1.00 1.00 1.00 1.00 1.00
calipers and b scan tool.  - Install two n  - Perform who correct cambe	epack front whe rake fluid flush.  ew tires to the feel alignment corr.	el bearing perform a ront whee	s.service all futomated blee	d rear our ed with e all four.	Parts Lis Shop Su Mx655 B 09997 B Bl1 Brak 61a P/stc 1401 Br 5068 Pe Front Wh	pplies brake Pads brake Clean e Lube (be beering Fluid ake Fluid B netrant Lub	endix) I rake Fluid			1.00 1.00 1.00 1.00 1.00 1.00 1.00 2.00
calipers and b scan tool.  - Install two n  - Perform who correct cambe	epack front whe rake fluid flush.  ew tires to the feel alignment corr.	el bearing perform a ront whee	s.service all futomated blee	d rear our ed with e all four.	Parts List Shop Sur Mx655 B 09997 B Bl1 Brak 61a P/str 1401 Br 5068 Pe Front Wh Camber	pplies brake Pads brake Clean e Lube (be eering Fluid ake Fluid B netrant Lub neel Seals Adjuster	endix) I rake Fluid e Pentron (ma	antek)		1.00 1.00 1.00 1.00 1.00 1.00 2.00 1.00
calipers and b scan tool.  - Install two n  - Perform who correct cambe	epack front whe rake fluid flush.  ew tires to the feel alignment corr.	el bearing perform a ront whee	s.service all futomated blee	d rear our ed with e all four.	Parts Lis Shop Su Mx655 B 09997 B Bl1 Brak 61a P/stc 1401 Br 5068 Pe Front Wh Camber 1797474	pplies brake Pads brake Clean e Lube (be beering Fluid ake Fluid B netrant Lub neel Seals Adjuster 92 Lt245/75	endix) I rake Fluid	antek)		1.00 1.00 1.00 1.00 1.00 1.00 2.00 1.00 2.00
calipers and b scan tool.  - Install two n  - Perform who correct cambe	epack front whe rake fluid flush.  ew tires to the feel alignment corr.	el bearing perform a ront whee	s.service all futomated blee	d rear our ed with e all four.	Parts List Shop Su Mx655 B 09997 B Bl1 Brak 61a P/st 1401 Br 5068 Pe Front Wh Camber 1797474 Tire Disp	pplies pplies prake Pads prake Clean pe Lube (be peering Fluid pake Fluid B petrant Lub peel Seals Adjuster 92 Lt245/75 posal Fee	endix) I rake Fluid e Pentron (ma	antek)		1.00 1.00 1.00 1.00 1.00 1.00 2.00 2.00
calipers and b scan tool.  - Install two n  - Perform who correct cambe	epack front whe rake fluid flush.  ew tires to the feel alignment coer.  es	el bearing perform a ront whee	s.service all futomated blee	d rear our ed with e all four. as to	Parts List Shop Su Mx655 B 09997 B Bl1 Brak 61a P/st 1401 Br 5068 Pe Front Wh Camber 1797474 Tire Disp	pplies prake Pads rake Clean e Lube (be eering Fluid ake Fluid B netrant Lub neel Seals Adjuster 92 Lt245/75 posal Fee alve Stem	endix) I rake Fluid e Pentron (ma	antek) · Sr-a E	1,108.6	1.00 1.00 1.00 1.00 1.00 1.00 2.00 2.00

Perform pm service.   Parts List   Shop Supplies   1.00   - Shop Supplies   Ca8039 Air Fitter Lbf Af1615 Wix 46418   1.00   - Shop Supplies   Ca8039 Air Fitter Lbf Af1615 Wix 46418   1.00   - Shop Supplies   Ca8039 Air Fitter Lbf Af1615 Wix 46418   1.00   - Shop Supplies   Ca8039 Air Fitter Lbf Af1615 Wix 46418   1.00   - Shop Supplies   Ca8039 Air Fitter Lbf Af1615 Wix 46418   1.00   - Sw20 Engine Oil	Workorder: Problem:	1009629 P.M. service.	Meter:	25544			In Date:	09/02/2010	Closed:	09/14/20	010
- Rotate and balance all four tires. Shop Supplies						Parts Li	st				Qty
1372   Oil Filter Frm Ph2   Wix 51372   1.00	- Rotate and I	balance all four	tires.			Shop Su	upplies				1.00
Company   Comp	- Shop Suppli	es				Ca8039	Air Filter Lb	of Af1615 Wix	46418		1.00
Sw20 Engine Oil   Sw20 Engi						1372 O	il Filter Frm	n Ph2 Wix 513	372		1.00
Used Firex Refurbed Fire Extingshers   1.00						G8018 F	Fuel Filter L	bf G6593 Wix	33595		1.00
Norkorder: 1107853   Meter: 32350   Meter: 32350						5w20 Er	ngine Oil				7.00
Hours   5.00   Ealor:   301-20 Wiper Blades   20" Blade   20" Blade   20" Blade   305-15						Used Fi	rex Refurbe	d Fire Extings	hers		1.00
Hours 5.00						D3tz245	7b Brake P	edal Pad			1.00
Section   Sect						31-20 W	iper Blades	20" Blade			2.00
Problem: Pm service Perform pm service.		Hour :	s 5.00		Labor:	300.00	Parts:	59.15	Total:	359.15	
- Install two new tires to the front wheels.nitrogen fill and balance all four Shop Supplies - Shop Suppli			Meter:	28630			In Date:	02/03/2011	Closed:	02/09/20	011
balance all four 1372   Oil Filter Frm Ph2   Wix 51372   1.00   - Shop Supplies   5w20   Engine Oil   7.00   7	- Perform pm	service.				Parts Li	st				Qty
- Shop Supplies	- Install two n	ew tires to the f	front whee	ls.nitrogen fil	l and	Shop Su	upplies				1.00
Tire Disposal Fee Tr416 Valve Stem 179747492 Lt245/75r16 Wrangler Sr-a E 2.00 Parts: 346.44 Total: 706.44  Workorder: 1107853 Meter: 32350 In Date: 07/26/2011 Closed: 08/15/2011 Problem: P.M. service and missing round lock on side doors.  - P.m. Service. Replace hitch pintle pin Check transmission leak.replace leaking dipstick tube and o'r ring.top off fluid Rotate and balance all tires Shop Supplies - Shop Supplies - G8018 Fuel Filter Lbf G6593 Wix 33595 - 1.00 - Sw20 Engine Oil - Syn/atf Trans Fluid Synthetic - Used Firex Refurbed Fire Extingshers - 1.00 - 31-20 Wiper Blades 20" Blade - 2.00 - 18410 Pintle Pin - 1.00						1372 O	il Filter Frm	n Ph2 Wix 513	372		1.00
Tr416 Valve Stem   179747492 Lt245/75r16 Wrangler Sr-a   E   2.00	- Shop Suppli	es				5w20 Er	ngine Oil				7.00
Hours 6.00						Tire Disp	posal Fee				2.00
Hours 6.00   Labor: 360.00   Parts: 346.44   Total: 706.44						Tr416 V	alve Stem				2.00
Workorder:   1107853   Meter:   32350   In Date:   07/26/2011   Closed:   08/15/2011   Problem:   P.M. service and missing round lock on side doors.						1797474	492 Lt245/7	5r16 Wrangle	r Sr-a E		2.00
Problem: P.M. service and missing round lock on side dors.  - P.m. Service		Hour	s 6.00		Labor:	360.00	Parts:	346.44	Total:	706.44	
Print Service					on side do	oors	In Date:	07/26/2011	Closed:	08/15/20	011
- Replace hitch pintle pin Check transmission leak.replace leaking dipstick tube and 'o' ring.top off fluid Rotate and balance all tires Shop Supplies  - Shop Supplies				9			st				Qtv
- Check transmission leak.replace leaking dipstick tube and 'o' ring.top off fluid.  - Rotate and balance all tires Shop Supplies  - Shop S						Big G D		-			
'o' ring.top off fluid.       1372 Oil Filter Frm Ph2 Wix 51372       1.00         - Rotate and balance all tires.       G8018 Fuel Filter Lbf G6593 Wix 33595       1.00         - Shop Supplies       09997 Brake Clean       1.00         5w20 Engine Oil       7.00         Syn/atf Trans Fluid Synthetic       4.00         Used Firex Refurbed Fire Extingshers       1.00         31-20 Wiper Blades 20" Blade       2.00         18410 Pintle Pin       1.00         Trans Dipstick Tube       1.00         Dipstick Tube Seal       1.00         Hours 6.75       Labor: 405.00 Parts: 130.33 Total: 535.33         Workorder: 1111724 Meter: 33923 Problem: Screw in right rear tire.       In Date: 11/01/2011 Closed: 11/03/2011         - Repair and balance right rear tire.       Parts List       Qty         - Shop Supplies       5hop Supplies       1.00	•		place leak	ina dipstick t	ube and	-					
- Rotate and balance all tires Shop Supplies  09997 Brake Clean 1.00  5w20 Engine Oil 5w20 Engine Oil 5w20 Firex Refurbed Fire Extingshers 1.00  1.						•		1.00			
- Shop Supplies	- Rotate and I	balance all tires	S.					1.00			
Syn/atf Trans Fluid Synthetic   4.00	- Shop Suppli	es									1.00
Used Firex Refurbed Fire Extingshers   1.00   31-20 Wiper Blades 20" Blade   2.00   18410 Pintle Pin   1.00   Trans Dipstick Tube   1.00   Dipstick Tube Seal   1.00   Dipstick Tube Seal   1.00   Parts: 130.33   Total: 535.33   Total: 535.33   Total: 535.33   Total: 535.33   Problem: Screw in right rear tire.   Parts List   Qty   Shop Supplies   Shop Supplies   Shop Supplies   1.00   Supplies   State						5w20 Er	ngine Oil				7.00
31-20 Wiper Blades 20" Blade   2.00   18410 Pintle Pin   1.00   1.00   Trans Dipstick Tube   500   Dipstick Tube   Dipst							J	Synthetic			4.00
Hours 6.75 Labor: 405.00 Parts: 130.33 Total: 535.33  Workorder: 1111724 Meter: 33923 In Date: 11/01/2011 Closed: 11/03/2011 Problem: Screw in right rear tire.  - Repair and balance right rear tire Shop Supplies Shop Supplies 1.00						•		•	hers		1.00
Trans Dipstick Tube Seal 1.00 Dipstick Tube Seal 1.00 Hours 6.75 Eabor: 405.00 Parts: 130.33 Total: 535.33  Workorder: 1111724 Meter: 33923 Problem: Screw in right rear tire.  - Repair and balance right rear tire.  Parts List Qty - Shop Supplies Shop Supplies 1.00						31-20 W	/iper Blades	20" Blade			2.00
Hours 6.75 Labor: 405.00 Parts: 130.33 Total: 535.33  Workorder: 1111724 Meter: 33923 In Date: 11/01/2011 Closed: 11/03/2011 Problem: Screw in right rear tire.  - Repair and balance right rear tire.  - Shop Supplies Shop Supplies 1.00						18410 P	intle Pin				1.00
Hours 6.75 Labor: 405.00 Parts: 130.33 Total: 535.33  Workorder: 1111724 Meter: 33923 In Date: 11/01/2011 Closed: 11/03/2011 Problem: Screw in right rear tire.  - Repair and balance right rear tire.  - Shop Supplies Shop Supplies 1.00						Trans D	ipstick Tube	e			1.00
: Workorder: 1111724 Meter: 33923 In Date: 11/01/2011 Closed: 11/03/2011 Problem: Screw in right rear tire.  - Repair and balance right rear tire.  - Shop Supplies Shop Supplies 1.00							-				1.00
Problem: Screw in right rear tire.  - Repair and balance right rear tire.  - Shop Supplies  Shop Supplies  Qty - 1.00		Hour	s 6.75		Labor:	405.00	Parts:	130.33	Total:	535.33	
- Shop Supplies Shop Supplies 1.00				33923			In Date:	11/01/2011	Closed:	11/03/20	011
- Shop Supplies Shop Supplies 1.00	- Repair and I	balance right re	ar tire			Parts I i	st				Qtv
	•	•	.a								-
	опор оцррп		s 1.00		Labor:		• •	2.00	Total:	62.00	1.00

Workorder: Problem:	1112623 Transmission	Meter: won't go i	34121 nto gear.			In Date:	11/29/2011	Closed:	12/07/20	011
<ul><li>Transport ve drivetrain warr</li><li>Shop Suppli</li></ul>	•	for transm	nission repail	r under	Parts Li Shop Su					<b>Qty</b> 1.00
	Hour :	s 2.00		Labor:	120.00	Parts:	2.00	Total:	122.00	
Workorder: Problem:	1200770 Pm service.	Meter:	34811			In Date:	01/25/2012	Closed:	02/03/20	012
- Perform pm	service.				Parts Li	st				Qty
	ower motor thir			replace	Shop Su	ıpplies				1.00
	failed blower motor switch and resistor with new Rotate and balance all four tires.						Ph2 Wix 51	372		1.00
		tires.					of Af1615 Wix	46418		1.00
- Shop Suppli	<del>6</del> 2				5w20 Er	•				7.00
						ver Resistor				1.00
	l la	a C 50		l abaw		ver Switch	CO 22	Total	450.00	1.00
	□0ui :	s 6.50		Labor.	390.00	Parts:	00.32	Total.	458.32	
Workorder: Problem:	1205080 Screw in right	Meter: rear tire.	36430			In Date:	05/31/2012	Closed:	05/31/20	012
- Repair and b	palance right re	ar tire.			Parts Li	st				Qty
- Shop Suppli	es				Shop Su	ıpplies				1.00
	Hour :	s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1206604 Pm service ar	Meter: nd rear bur	37211 nper sil.See	notes.		In Date:	07/16/2012	Closed:	07/25/20	012
- P.m. Service	į				Parts Li	st				Qty
	tires,rotate an	d balance	all four.		Shop Supplies					1.00
	neel alignment				1372 Oil Filter Frm Ph2 Wix 51372					1.00
- Fabricate an	d secure rear l	oumper tri	m.		G8018 F	Fuel Filter Lt	of G6593 Wix	33595		1.00
- Shop Suppli	es				5w20 Er	ngine Oil				7.00
					31-20 W	/iper Blades	20" Blade			2.00
					Used Fir	rex Refurbe	d Fire Extings	shers		1.00
					1797474	192 Lt245/7	5r16 Wrangle	r Sr-a E		2.00
					•	oosal Fee				2.00
	Hour :	s 9.00		Labor:	540.00	Parts:	433.30	Total:	973.30	
Workorder:	1209179	Meter:	38378			In Date:	09/25/2012	Closed:		
Problem:	No crank on the	ne road ha	nd to jump sta	art.						
-	Hour	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	

Problem:	1302007 P.M. service	Meter: e and check s	40871 seat belt and rea	ar dome		Date:	02/27/2013	Closed:	03/12/2013	3
- P.m. Service	<b>e</b> .				Parts List				(	Qty
- Replace mis		n.			5w20 Engine	e Oil				7.00
•	•		ace bad battery	<i>1</i> .	1372 Oil Filt				1.00	
- Replace two				•	Napagold Fu		r			.00
- Replace driv					Stg Wheel C					.00
- Shop Suppli		711 dotor dooo!	11515.		31-20 Wiper					2.00
спор сарра	00				18410 Pintle		20			.00 1.00
					Battery 65	, , ,,,				.00
					179747492	l t245-7	5r16			2.00
					seat belt	L12-10 7	0110			.00
					Shop Suppli	<b></b>				.00
					Tire Disposa					2.00
	Нο	urs 8.25	1	l abor	495.00		843.56	Total·	1,338.56	00
	:	uio 0.20			400.00	i dito.	040.00	Total.	1,000.00	
Workorder:	1308528		43563 and driver seat b	nelt inor		Date:	08/23/2013	Closed:	09/12/2013	3
- P.m. Service		oriook tiroo d	na anvoi ocai c	7011 IIIOF	Parts List					<b>0</b> 4v
		shar braakat				o Oil				<b>Qty</b> 7.00
- Replace bro	_		raka pada aani	aa aad	5w20 Engine					.00. 00.1
			rake pads.servion and test drive				20			
- Repair right		•			31-20 Wiper					2.00
- Shop Suppli					Used Fire X					.00
					Napagold Fu					00. ا 00. ا
					Custom Brad	cket File	e Ex			.00
					Brake Pad					.00
	11-	44 00	ı	l = b =	Shop Suppli		474.40	Tatal		.00
	Ho:	urs 11.00	l	_abor:	660.00	Parts:	174.13	ı otai:	834.13	
Workorder:	1402764	Meter:	46695		In	Date:	03/21/2014	Closed:	04/10/2014	4
Problem:	P.M. Service	e.Siliit iliulca	tor mop.							
		e.oriiit iiidica	ю тор.		Parts List				(	Qty
- Perform pm - Pressure tes	service. st and inspect		em.reverse flus	h and	Parts List 5w20 Engine	e Oil				<b>Qty</b> 7.00
- Perform pm - Pressure tes renew engine	service. st and inspect coolant.	t cooling syst	em.reverse flus	h and					7	•
- Perform pm - Pressure tes renew engine - Remove stereplace failed	service. st and inspect coolant. eering colum a steering shaf	t cooling syst and dismantle t with new.als	em.reverse fluse to acess and so replace failed		5w20 Engine	il Filter			7 1 1	7.00
- Perform pm - Pressure tes renew engine - Remove ster replace failed shifter indicato	service. st and inspect coolant. sering colum a steering shafor and steering	t cooling syst and dismantle it with new.als g dampner w	em.reverse fluse to acess and so replace failed		5w20 Engine Napagold O Napagold Ai	il Filter ir Filter			7 1 1 1	7.00 1.00 1.00
- Perform pm - Pressure testenew engine - Remove stereplace failed shifter indicated	service. st and inspect coolant. eering colum a steering shaf- or and steerin balance all fo	t cooling syst and dismantle it with new.als g dampner w	em.reverse fluse to acess and so replace failed		5w20 Engine Napagold O Napagold Ai Wd40 16oz	il Filter ir Filter			7 1 1 1 2	7.00 1.00 1.00
- Perform pm - Pressure testenew engine - Remove stereplace failed shifter indicate - Rotate and b	service. st and inspect coolant. eering colum a steering shaf- or and steerin balance all fo	t cooling syst and dismantle it with new.als g dampner w	em.reverse fluse to acess and so replace failed		5w20 Engine Napagold O Napagold Ai Wd40 16oz Wiper Blade Peak Global	il Filter ir Filter	ı Sh		7 1 1 1 2 2	7.00 1.00 1.00 1.00 2.00
- Perform pm - Pressure testenew engine - Remove stereplace failed shifter indicate - Rotate and b	service. st and inspect coolant. eering colum a steering shaf- or and steerin balance all fo	t cooling syst and dismantle it with new.als g dampner w	em.reverse fluse to acess and so replace failed		5w20 Engine Napagold O Napagold Ai Wd40 16oz Wiper Blade Peak Global F3tz7l278a I	il Filter r Filter	ı Sh		7 1 1 1 2 2 2	7.00 1.00 1.00 2.00 2.00 2.00
- Perform pm - Pressure testenew engine - Remove stereplace failed shifter indicate - Rotate and b	service. st and inspect coolant. eering colum a steering shaf- or and steerin balance all fo	t cooling syst and dismantle it with new.als g dampner w	em.reverse fluse to acess and so replace failed		5w20 Engine Napagold O Napagold Ai Wd40 16oz Wiper Blade Peak Global F3tz7l278a I Gear Lunger	il Filter ir Filter Bushing	ı Sh		7 1 1 1 2 2 2 1	7.00 1.00 1.00 2.00 2.00 2.00
- Perform pm - Pressure testenew engine - Remove stereplace failed shifter indicated	service. st and inspect coolant. eering colum a steering shaf- or and steerin balance all fo	t cooling syst and dismantle it with new.als g dampner w	em.reverse fluse to acess and so replace failed		5w20 Engine Napagold O Napagold Ai Wd40 16oz Wiper Blade Peak Global F3tz7l278a I Gear Lunger Damper Asy	il Filter r Filter Bushing	ı Sh		7 1 1 2 2 2 1 1	7.00 1.00 1.00 1.00 2.00 2.00 1.00
- Perform pm - Pressure testenew engine - Remove stereplace failed shifter indicated.	service. st and inspect coolant. eering colum a steering shaf- or and steerin balance all fo	t cooling syst and dismantle it with new.als g dampner w	em.reverse fluse to acess and so replace failed		5w20 Engine Napagold O Napagold Ai Wd40 16oz Wiper Blade Peak Global F3tz7l278a I Gear Lunger Damper Asy Damper Ass	il Filter r Filter Bushing	ı Sh		7 1 1 2 2 2 2 1 1	7.00 1.00 1.00 1.00 2.00 2.00 1.00 1.00
- Perform pm - Pressure tes renew engine - Remove ste	service. st and inspect coolant. eering colum a steering shaf- or and steerin balance all fo	t cooling syst and dismantle it with new.als g dampner w	em.reverse fluse to acess and so replace failed		5w20 Engine Napagold O Napagold Ai Wd40 16oz Wiper Blade Peak Global F3tz7l278a I Gear Lunger Damper Asy	il Filter ir Filter Bushing r y	ı Sh		7 1 1 2 2 2 1 1 1	7.00 1.00 1.00 1.00 2.00 2.00 1.00

.

Workorder: 1410187 Meter: 49425 Problem: P.M, Service.	In Date: 10/09/2014 Closed: 10/27/201	4			
- Pm service.	Parts List	Qty			
- Check battery and charging system.battery failed	5w20 Engine Oil	7.00			
loadtest.replace bad battery.	Napagold Oil Filter	1.00			
- Replace and balance all four tires.	Napagold Fuel Filter	1.00			
- Complete front end alignment and test drive.	Battery	1.00			
- Shop Supplies	179747492 Lt245-75r16	4.00			
	Used Fire X Refurbished	1.00			
	Stg Wheel Cov - Ford	1.00			
	Shop Supplies	1.00			
	Tire Disposal Fee	4.00			
Hours 9.50 Labo	570.00 Parts: 1,133.91 Total: 1,703.91				
Workorder: 1503914 Meter: 52178 Problem: Pm service.Brake pulsates.Power outlet inop	In Date: 04/15/2015 Closed: 05/07/201	5			
- Pm service.	Parts List	Qty			
- Remove and replace driver seat for upholstery repairs.	Ball Joint Lower	2.00			
- Replace front brake pads and both front brake	5w20 Engine Oil	7.00			
calipers.resurface both front brake rotors.flush and bleed brake system.roadtest.	Napagold Oil Filter	1.00			
- Complete front end alignment and road test	Wiper Blade 2	2.00			
- Replace both worn left and right side upper and lower bal	Washer Fluid Concentr	1.00			
joints.	Reman Brake Caliper	1.00			
- Inspect power outlet and cigarette lighter inop.test and replace open 20 amps. fuse.	Reman Brake Caliper 1401 Brake Fluid Bra				
- Rotate and balance all four tires.					
- Shop Supplies	•	2.00 2.00			
- Shop Supplies	• • • • • • • • • • • • • • • • • • • •	2.00 1.00			
		1.00 1.00			
Hours 17.00 Labo	Shop Supplies 7,020.0 Parts: 766.94 Total: 1,786.94	1.00			
Workorder: 1506522 Meter: 53768 Problem: Check engine light on.	In Date: 06/29/2015 Closed: 07/09/201	5			
- Computer diagnose for check engine light on.code	Parts List	Qty			
P0748.pinpoint test Pca solenoid and circuit.all test ok.several road test and transmission shifts ok through all gears.		1.00			
- Shop Supplies					
Hours 2.00 Labo	120.00 Parts: 2.00 Total: 122.00				

Workorder:	1510191	Meter:	55144			In Date:	10/07/2015	Closed:	10/28/2015
Problem:	Pm service.Tr	ansmissio	n light on.Fron	t end noi	sy.Driver	visor and a	ırm rest brokeı	า.	
- Pm service.					Parts Lis	st			Qty
- Replace bro	ken left sun vis	or and tigh	nten arm rest.		Transmis	sion Filter	Oe		1.00
- Replace botl	h defective fron	t shocks d	lue to worn bu	shings.	Visor				1.00
	agnose for che				Solenoid	/a			1.00
	point test and i				Connecto	or			1.00
flush fluid.clea	e connectors.re r codes and roa		smission iller	anu	Connecto	or			1.00
<ul><li>Rotate and balance all four tires.</li><li>Shop Supplies</li></ul>						gine Oil			7.00
						d Oil Filter			1.00
					Used Fire	e X Refurbi	shed		1.00
					Wiper Bla	ade			2.00
					Napagolo	d Fuel Filter	r		1.00
					Shock - 0	Gas Grande	e Fleet - Front		2.00
					Platinum	Filter Kit			1.00
					Syn-atf T	rans Fluid	S		16.00
					Trans Sc	lenoid			1.00
					Trans Sc	lenoid			1.00
					Shop Su	pplies			1.00
	Hours	s 12.50		Labor:	750.00	Parts:	751.82	Total:	1,501.82
Workorder:	1605993	Meter:	59987			In Date:	06/10/2016	Closed:	07/29/2016
	P.M. service a			and A/C	feels wa		00/10/2010	Giocou.	0172072010
- P.m. Service	)				Parts Lis	st			Qty
	r transmission				5w20 En	gine Oil			7.00
	ing seen.replac	e transmis	sion assemble	install	Napagolo	d Oil Filter			1.00
new oil cooler.		d halanaa	all four		20" Wipe		2.00		
•	tires,rotate and				Washer I		1.00		
•	stem.test for le	eaks.crieck	c pressures.		Lt245 75		2.00		
- Shop Suppli	62				Stg Whe	el Cov - Fo	rd		1.00
					Transmis	sion			1.00
					Speed S	ensor			1.00
					Cooler				1.00
					Syn-atf T	rans Fluid	S		5.00
					Shop Su	pplies			1.00
					Tire Disp	osal Fee			2.00
	Hours	s 14.00		Labor:	840.00	Parts:	3,251.55	Total:	4,091.55
Workorder:	1611088	Meter:	62170			In Date:	10/26/2016	Closed:	10/31/2016
Problem:	Rear cargo do	or inop.							
- Diagnose an	d replace defe	ctive rear	door latch asse	emble.	Parts Lis	st			Qty
- Shop Suppli	es				Remote				1.00
					Shop Su	pplies			1.00
	Hours :	s 1.25		Labor:	75.00	Parts:	100.43	Total:	175.43

Workorder: Problem:	1613075 Side door inc	Meter:	63374		I	n Date:	12/27/2016	Closed:	01/03/2017
- Replace rig	ht cargo door l	atch assem	ıble.		Parts List G				
- Shop Suppl	ies				door latch	remote c	ontrol		1.00
					Shop Sup	plies			1.00
	Hou	ırs 1.25		Labor:	75.00	Parts:	99.46	Total:	174.46
Workorder: Problem:	1700588 P.M. service	Meter: and transm	63724 hission slippi	ng and det		n Date:	01/19/2017	Closed:	02/06/2017
- P.m. Servic	- P.m. Service.								Qty
- Replace two	Napagold	Oil Filter			1.00				
- Complete w		5w20 Eng	ine Oil			6.00			
- Inspect and		Washer F	1.00						
	etap broken bo	It for center	brake lamp	.replace	20" Wiper	2.00			
lamp assemb					Napagold		1.00		
- Adjust both front wheel bearings.					Lt245 75r	16			2.00
	ehicle to deale	r for warran	nty transmiss	sion	Friction M	odifier			2.00
repairs.	nd install new	brooket for	driver eide r	00"	75w140 F	ord Axle I	_ube		3.00
- rabilicate at cabinets.	iu iristali riew i	Diacket ioi (	unver side re	<del>J</del> ai	Non-chlor	Brake Cli	nr		1.00
- Shop Suppl	ies				Used Fire	X Refurb	ished		1.00
					Lamp Ass	embly			1.00
					Shop Sup	plies			1.00
					Tire Dispo	sal Fee			2.00
	Hou :	ırs 14.50		Labor:	870.00	Parts:	708.53	Total:	1,578.53
Workorder: Problem:	1707643 P.M. service.	Meter:	67982		I	n Date:	08/04/2017	Closed:	08/21/2017
- P.m. Servic	e.				Parts List	t			Qty
- Diagnose si	de cargo door	won't open	.replace upp	er and	5w20 Eng	ine Oil			6.00
	ch assemblies				Napagold	Oil Filter			1.00
	balance tires.				Washer F	luid Conc	entr		1.00
- Shop Suppl	ies				22" Wiper	Blade			2.00
					latch				1.00
					latch				1.00

Labor: 420.00 Parts: 209.42

Total: 629.42

Hours 7.00

Workorder: 1800584 Meter: 71665	In Date: 01/18/2018	Closed: 01/29/2018
Problem: P.M. service and blower switch inop and burning	ng smell.	
- P.m. service.	Parts List	Qty
- Diagnoise A/c inop.fabericate and install new pigtail for	5w20 Engine Oil	7.00
switch and new switch ,blower motor , blower resistor.retest.	Napagold Oil Filter	1.00
- Rotate and high speed balance all four tires.	20" Wiper Blade	2.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Used Fire X Refurbished	1.00
	Knob	1.00
	Switch	1.00
	Resistor	1.00
	Wire Asy	1.00
	Blower Motor	1.00
	Shop Supplies	1.00
Hours 8.90 Labor:	534.00 Parts: 248.03	Total: 782.03
Workorder: 1804908 Meter: 72064	In Date: 05/10/2018	<b>Closed:</b> 05/10/2018
Problem: Transition Prep Charge		
- Transition Prep Charge		
Hours 2.00 Labor:	120.00 Parts: 0.00	Total: 120.00

: